

1/13/2025
9:35:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10195557 2015 FORD EXPLORER Suv, Lg Mid Size, 4X4

Total Hours: 130.00 Labor: 8,713.50 Parts: 5,127.63 Comm: 732.90 Charged: 14574.03

Work Order: 1500346 **Meter:** 581 **In Date:** 01/12/2015 **Closed:** 01/12/2015
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1504694 **Meter:** 5358 **In Date:** 05/08/2015 **Closed:** 05/12/2015
Problem: P.M. Service.

Work Completed

- Pm service.

- Rotate and balance all four tires.

- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil 6.00

Napagold Oil Filter 1.00

Shop Supplies 1.00

Hours: 3.75 Comm: 0.00 Labor: 225.00 Parts: 21.19 Total: 246.19

Work Order: 1508181 **Meter:** 10477 **In Date:** 08/14/2015 **Closed:** 08/19/2015
Problem: Pm service.

Work Completed

- Pm service.

- Rotate and balance all four tires.

- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil 6.00

Napagold Oil Filter 1.00

Shop Supplies 1.00

Hours: 3.75 Comm: 0.00 Labor: 225.00 Parts: 21.19 Total: 246.19

Work Order: 1510127 **Meter:** 12182 **In Date:** 10/06/2015 **Closed:** 10/06/2015
Problem: 2 - Wash ticket(s) issued

Work Completed

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 19.08 Labor: 0.00 Parts: 0.00 Total: 19.08

1/13/2025
9:35:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10195557 2015 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1512947 **Meter:** 15891 **In Date:** 12/23/2015 **Closed:** 12/31/2015
Problem: Pm service.

Work Completed

- Pm service.
- Rotate and balance all four tires.
- Shop Supplies

Hours: 3.75

Comm: 0.00

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Shop Supplies	1.00

Labor: 225.00 Parts: 18.50 Total: 243.50

Work Order: 1604531 **Meter:** 21355 **In Date:** 04/29/2016 **Closed:** 05/05/2016
Problem: P.M. Service.

Work Completed

- P.m. Service.
- Rotate and balance all tires.
- Shop Supplies

Hours: 3.75

Comm: 0.00

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Accufit Beam	1.00
Accufit Beam	1.00
Blade	1.00
Shop Supplies	1.00

Labor: 225.00 Parts: 69.98 Total: 294.98

Work Order: 1608648 **Meter:** 26480 **In Date:** 08/19/2016 **Closed:** 08/30/2016
Problem: P.M. service and check wipers smearing and detail.

Work Completed

- P.m. Service.
- Rotate and balance all tires.
- Shop Supplies

Hours: 3.75

Comm: 0.00

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Blade	1.00
Blade	1.00
Washer Fluid Concentr	1.00
Blade	1.00
Shop Supplies	1.00

Labor: 225.00 Parts: 76.21 Total: 301.21

1/13/2025
9:35:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10195557 2015 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1608716 **Meter:** 26172 **In Date:** 08/22/2016 **Closed:** 08/22/2016
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 1611218 **Meter:** 28795 **In Date:** 10/28/2016 **Closed:** 10/28/2016
Problem: 3 - Wash ticket(s) issued

Work Completed

- 3 - Wash ticket(s) issued

Hours: 0.00 Comm: 28.62 Labor: 0.00 Parts: 0.00 Total: 28.62

Work Order: 1612988 **Meter:** 31837 **In Date:** 12/21/2016 **Closed:** 01/02/2017
Problem: P.M. service.

Work Completed

- P.m. Service.
- Battery corroded around positive terminal.replace leaking battery.clean terminal and tray.
- Flush and refill transmission.
- Rotate and balance tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Accufit Beam	1.00
Accufit Beam	1.00
Washer Fluid Concentr	1.00
Battery	1.00
Syn-atf Trans Fluid S	10.00
Shop Supplies	1.00

Hours: 6.25 Comm: 0.00 Labor: 375.00 Parts: 248.77 Total: 623.77

1/13/2025
9:35:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10195557 2015 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1703822 **Meter:** 37424 **In Date:** 04/14/2017 **Closed:** 05/02/2017
Problem: P.M. service.

Work Completed

- P.m. Service.
- Rotate and balance tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Accufit Beam	1.00
Accufit Beam	1.00
Wpr/blde	1.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00

Hours: 3.75

Comm: 0.00

Labor: 225.00 Parts: 58.46 Total: 283.46

Work Order: 1708035 **Meter:** 42387 **In Date:** 08/16/2017 **Closed:** 08/31/2017
Problem: Inspect for exhaust fumes entering cab.

Work Completed

- Inspect and perform Tsb 16-0166 procedure 1.inspect body seams and plugs for leaks.reseal rear A/c lines and left body seam.reprogram Hvac to latest calibration..
- P.m. service.
- Complete reverse coolant flush to system.
- Rotate and balance four tires.
- Shop Supplies

Parts Issued

Quantity

Rubberized Undercoat	1.00
Seam Sealer	1.00
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Napa Cabin Air Filter	1.00
Anti Freeze Motorcraft	2.00
Shop Supplies	1.00

Hours: 6.75

Comm: 0.00

Labor: 405.00 Parts: 135.73 Total: 540.73

Work Order: 1710587 **Meter:** 44143 **In Date:** 10/26/2017 **Closed:** 10/26/2017
Problem: 2 - Wash ticket(s) issued

Work Completed

- 2 - Wash ticket(s) issued

Hours: 0.00

Comm: 19.08

Labor: 0.00 Parts: 0.00 Total: 19.08

1/13/2025
9:35:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10195557 2015 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1800985 **Meter:** 47986 **In Date:** 01/26/2018 **Closed:** 02/05/2018
Problem: P.M. service.

Work Completed

- P.m. service.
- Rotate and balance four tires.
- Transport to and from dealer for recalls 17n03 and 17n04.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
26in Exactfit-beam	1.00
22in Exactfit-beam	1.00
11in Exactfit-rear	1.00
Shop Supplies	1.00

Hours: 5.75

Comm: 0.00

Labor: 345.00 Parts: 58.54 Total: 403.54

Work Order: 1806141 **Meter:** 53166 **In Date:** 06/15/2018 **Closed:** 06/25/2018
Problem: PM Service

Work Completed

- P.m. Service.
- Replace two tires,rotate and balance all four.
- Horns inop.diagnose and replace defective horns.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22in Exactfit-beam	1.00
26in Exactfit-beam	1.00
P245/60/18 Tire Mic	2.00
Horn Assy	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 5.75

Comm: 0.00

Labor: 345.00 Parts: 711.83 Total: 1,056.83

1/13/2025
9:35:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10195557 2015 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1810226 **Meter:** 57515 **In Date:** 10/02/2018 **Closed:** 10/11/2018
Problem: Weather stripping on windshield flapping around.

Work Completed

- Replace both side windshield molding and mounts .
- Shop Supplies

Parts Issued

Quantity

Moulding	2.00
Moulding	1.00
Moulding	1.00
Moulding	1.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 67.00 Parts: 594.59 Total: 661.59

Work Order: 1811056 **Meter:** 58214 **In Date:** 10/26/2018 **Closed:** 11/01/2018
Problem: PM Service.

Work Completed

- P.m. service.
- Replace two worn tires . Rotate and balance all four tires. Nitrofill.
- Load test battery . Battery failed load test . R&r defective battery and replace positive battery terminal. Retest.
- Transport to and from dealer for Ptu pinion seal leaking .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
245/60/18 Tire Gdy	2.00
Battery	1.00
Battery Terminal Assy	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 7.75 Comm: 0.00 Labor: 519.25 Parts: 616.24 Total: 1,135.49

Work Order: 1812577 **Meter:** 59343 **In Date:** 12/11/2018 **Closed:** 12/11/2018
Problem: 2 - Wash ticket(s) issued

Work Completed

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 19.08 Labor: 0.00 Parts: 0.00 Total: 19.08

1/13/2025
9:35:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10195557 2015 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 1909742 **Meter:** 70150 **In Date:** 09/20/2019 **Closed:** 09/27/2019
Problem: PM Service, Recall 19S17

Work Completed

- P.m. service.
- Rotate and balance all four tires . Nitrofill all.
- Transport to and from dealer for recall 19s17 .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
11in Exactfit-rear	1.00
20in Exactfit-beam	1.00
26in Exactfit-beam	1.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00

Hours: 5.75 Comm: 0.00 Labor: 385.25 Parts: 64.22 Total: 449.47

Work Order: 1909885 **Meter:** 69854 **In Date:** 09/25/2019 **Closed:** 09/25/2019
Problem: 2 - Wash ticket(s) issued

Work Completed

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 19.08 Labor: 0.00 Parts: 0.00 Total: 19.08

Work Order: 2004673 **Meter:** 75503 **In Date:** 05/08/2020 **Closed:** 05/12/2020
Problem: PM Service

Work Completed

- P.m. service.
- Rotate and balance all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
11in Exactfit-rear	1.00
20in Exactfit-beam	1.00
26in Exactfit-beam	1.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00

Hours: 3.75 Comm: 0.00 Labor: 273.75 Parts: 65.23 Total: 338.98

1/13/2025
9:35:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10195557 2015 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 2005401 **Meter:** 75503 **In Date:** 05/29/2020 **Closed:** 05/29/2020
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 2010631 **Meter:** 78086 **In Date:** 10/23/2020 **Closed:** 10/26/2020
Problem: Roads Tom, truck Lt. tire needs replacing will bring down this morning

Work Completed

- Tire Repair. Lr tire flat. Spare installed on vehicle. Remove tire from spare compartment and repair hole in tire. Remount and rebalance. Remove spare installed in vehicle and reinstall spare in truck spare tire compartment.reinstall tire. Reset Tpms

Parts Issued	Quantity
Shop Supplies	1.00

- Shop Supplies

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 4.00 Total: 77.00

Work Order: 2010751 **Meter:** 78086 **In Date:** 10/23/2020 **Closed:** 10/26/2020
Problem: L/R SPARE MOUNT

Work Completed

- Tire Service: El Paso Dr Lake Worth Problem: L/r Spare Mount

Hours: 0.00 Comm: 70.25 Labor: 0.00 Parts: 0.00 Total: 70.25

Work Order: 2011880 **Meter:** 78751 **In Date:** 12/01/2020 **Closed:** 12/01/2020
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

1/13/2025
9:35:35 AM

Palm Beach County Fleet Management Asset Maintenance History
10195557 2015 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 2100168 **Meter:** 78751 **In Date:** 01/07/2021 **Closed:** 01/11/2021
Problem: pm service, get ready for freassign

Work Completed

- Preventive Maint. Service
- Install New Asset Numbers

Parts Issued

	Quantity
Napagold Oil Filter	1.00
Napa Quart 5w20	6.00
26in Exactfit-beam	1.00
20in Exactfit-beam	1.00

Hours: 3.75 Comm: 0.00 Labor: 273.75 Parts: 56.13 Total: 329.88

Work Order: 2100206 **Meter:** 78751 **In Date:** 01/07/2021 **Closed:** 01/07/2021
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours: 0.00 Comm: 96.00 Labor: 0.00 Parts: 0.00 Total: 96.00

Work Order: 2106664 **Meter:** 82774 **In Date:** 06/18/2021 **Closed:** 06/22/2021
Problem: pm service

Work Completed

- Preventive Maint. Service
- Clear Blocked Washer Fluid Nozzle And Line
- Load Test And Replace Bad Battery, Check Charging System

Parts Issued

	Quantity
Napa Quart 5w20	6.00
Napagold Oil Filter	1.00
Battery	1.00

Hours: 4.25 Comm: 0.00 Labor: 310.25 Parts: 159.59 Total: 469.84

Work Order: 2106937 **Meter:** 82849 **In Date:** 06/24/2021 **Closed:** 06/24/2021
Problem: 2 - Wash ticket(s) issued

Work Completed

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 19.08 Labor: 0.00 Parts: 0.00 Total: 19.08

Work Order: 2109276 **Meter:** 85317 **In Date:** 08/26/2021 **Closed:** 08/30/2021
Problem: Tire light on

Work Completed

- Performed Flat Repair On L/r Tire And Balance . Nitro Fill All.

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 0.00 Total: 73.00

1/13/2025
9:35:35 AM

Palm Beach County Fleet Management Asset Maintenance History
10195557 2015 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 2110919 **Meter:** 87811 **In Date:** 09/29/2021 **Closed:** 10/08/2021
Problem: 2 - Wash ticket(s) issued

Work Completed

- 2 - Wash ticket(s) issued

Hours: 0.00 Comm: 17.97 Labor: 0.00 Parts: 0.00 Total: 17.97

Work Order: 2111272 **Meter:** 88594 **In Date:** 10/20/2021 **Closed:** 10/22/2021
Problem: pm service

Work Completed

- Preventive Maint. Service

Parts Issued

Quantity

Napa Quart 5w20	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
26in Exactfit-beam	1.00
20in Exactfit-beam	1.00
Mac Wite Lithium Gres	1.00

Hours: 2.75 Comm: 0.00 Labor: 200.75 Parts: 49.42 Total: 250.17

Work Order: 2112501 **Meter:** 90127 **In Date:** 11/23/2021 **Closed:** 11/24/2021
Problem: Left Front tire going flat .

Work Completed

- Repair left front tire and balance . Nitro fill all.

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 0.00 Total: 73.00

Work Order: 2201060 **Meter:** 91354 **In Date:** 01/28/2022 **Closed:** 01/31/2022
Problem: TPMS light on.

Work Completed

- Repair left front tire, balance and nitro service

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 0.00 Total: 73.00

1/13/2025
9:35:35 AM

Palm Beach County Fleet Management Asset Maintenance History
10195557 2015 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 2212371 **Meter:** 98511 **In Date:** 12/09/2022 **Closed:** 12/14/2022
Problem: tire light on

Work Completed

Parts Issued

Quantity

- Replaced And Balanced Both Front Tires

245/60/18 Tire Mic

2.00

Tire Disposal Fee

2.00

Hours: 1.50

Comm: 0.00

Labor: 109.50

Parts: 404.44

Total: 513.94

Work Order: 2302803 **Meter:** 99766 **In Date:** 03/20/2023 **Closed:** 03/31/2023
Problem: pm service

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service

Napa Quart 5w20

6.00

- Diag Horn Innop, Checked Fuse And Pinpoint Test Circuit, Found Factory
Horn Bypassed, Repaired Wires Near Horn Connector.

Napagold Oil Filter

1.00

26in Exactfit-beam

1.00

- Cleaned Corrosion On Battery Hold Down

20in Exactfit-beam

1.00

Washer Fluid Concentr

1.00

Hours: 4.75

Comm: 0.00

Labor: 346.75

Parts: 54.34

Total: 401.09

Work Order: 2303397 **Meter:** 99766 **In Date:** 03/31/2023 **Closed:** 04/05/2023
Problem: 1 - Wash ticket(s) Issued to: FLEET-DJ

Work Completed

- 1 - Wash ticket(s) Issued to: Fleet-dj

Hours: 0.00

Comm: 8.98

Labor: 0.00

Parts: 0.00

Total: 8.98

Work Order: 2308794 **Meter:** 101983 **In Date:** 08/30/2023 **Closed:** 08/30/2023
Problem: low tire light

Work Completed

- Repaired Driver Front Tire

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 0.00

Total: 73.00

1/13/2025
9:35:35 AM

Palm Beach County Fleet Management Asset Maintenance History
10195557 2015 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 2310211 **Meter:** 102569 **In Date:** 10/06/2023 **Closed:** 10/10/2023
Problem: dead battery/ pm spot 318

Work Completed

- Preventive Maint. Service
- Battery Failed Load Test, Replaced Battery

Parts Issued

Quantity

Oil Filter	1.00
Napa Quart 5w20	6.00
Washer Fluid Concentr	1.00
Non-chlor Brake Clnr	1.00
Battery	1.00

Hours: 3.75

Comm: 0.00

Labor: 273.75

Parts: 224.26

Total: 498.01

Work Order: 2310503 **Meter:** 102874 **In Date:** 10/06/2023 **Closed:** 10/17/2023
Problem: on 5th parking garage see steph for key and to let you in

Work Completed

- Tow From: 301 North Olive Ave To: 2601 Vista Pkwy, West Palm Beach 33411

Hours: 0.00

Comm: 124.30

Labor: 0.00

Parts: 0.00

Total: 124.30

Work Order: 2403133 **Meter:** 106922 **In Date:** 03/28/2024 **Closed:** 04/02/2024
Problem: pm service

Work Completed

- Preventive Maint. Service
- Install New Front Brake Pads, Rotors, And Service Calipers

Parts Issued

Quantity

Washer Fluid Concentr	1.00
22in Exactfit-beam	1.00
26in Exactfit-beam	1.00
Blade	1.00
Napa Quart 5w20	6.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Non-chlor Brake Clnr	1.00
Brake Rotor	2.00
Brake Pad	1.00

Hours: 6.25

Comm: 0.00

Labor: 456.25

Parts: 363.81

Total: 820.06

1/13/2025
9:35:35 AM

Palm Beach County Fleet Management Asset Maintenance History
10195557 2015 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 2404323 **Meter:** 108190 **In Date:** 05/01/2024 **Closed:** 05/03/2024
Problem: terrain mgmt system fault

Work Completed

- C/s Terrain Mgmt System Fault, Rd Test Asset, Did Not Verify Concern, Scanned No Codes Found, No Repairs Recomendated At This Time

- Recall: Safety recall # 24s02/24v031 A-pillar trim loose (improper assembly) no repair procedure at this time as per S. Thomas

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 0.00 Total: 73.00

Work Order: 2405460 **Meter:** 109032 **In Date:** 06/04/2024 **Closed:** 06/06/2024
Problem: STALLED ON DRIVER 3 TIMES

Work Completed

- Diag Stalling, Monitor Engine, R/r Throttle Body And Relearn Computer

- Recall: Safety recall # 24s02/24v031 A-pillar trim loose (improper assembly) no repair procedure at this time per S. Thomas

Parts Issued	Quantity
Gasket	1.00
Throttle Body	1.00

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 176.01 Total: 322.01

Work Order: 2405610 **Meter:** 109040 **In Date:** 06/06/2024 **Closed:** 06/11/2024
Problem: ac blows hot

Work Completed

- C/s A/c Not Cold. Replace High & Low Side Shrader Valves, Evacuate & Recharge A/c System.

- Recall: Safety recall # 24s02/24v031 A-pillar trim loose (improper assembly) repair procedure not available per S. Thomas

Parts Issued	Quantity
Cap And Valve Kit	1.00
Freon Lv Shop 1	1.00

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 25.56 Total: 171.56

1/13/2025
9:35:35 AM

Palm Beach County Fleet Management Asset Maintenance History
10195557 2015 FORD EXPLORER Suv, Lg Mid Size, 4X4

Work Order: 2408204 **Meter:** 111112 **In Date:** 08/26/2024 **Closed:** 08/29/2024
Problem: multiple lights on dash

Work Completed

Parts Issued

Quantity

- C/s Abs, Brake Lights Are On, U3000:49 Control Module Code, Cleared
Dtc's Performed Abs Module Self Test, Test Drove Vehicle Codes Returned,
Would Need To Replace Abs Traction Module, Not Cost Effective To Repair
At This Time

Battery

1.00

- Recall: Safety recall # 24s02/24v031 A-pillar trim loose (improper
assembly) parts not available per S. Thomas

- Load Test And Replaced Bad Battery

Hours: 3.00

Comm: 0.00

Labor: 219.00

Parts: 174.53

Total: 393.53

Work Order: 2408382 **Meter:** 111112 **In Date:** 08/29/2024 **Closed:** 08/29/2024
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

Total Hours: 130.00

Total Labor: 8,713.50

Total Comm: 732.90

Total Parts: 5,127.63