1/13/2025 9:38:38 AI			Palm		nagement Asset Maintenar FORD F150 Pickup, 1/2 Ton				
Total Hours:	126.35	Labor: 8,783	.45	Parts: 6,720.28	Comm: 3,781.28		Charged	: 19285.00	
Work Order: Problem:		5 Pre Delivery Ins	Meter: spection	293		In Date:	01/07/2016	Closed:	01/07/2016
Work Com	npleted								
- Pre Deliv	very Inspe	ection							
		Hours: 2.00		Comm: 0.00	Labor: 120.00	Parts: 0.0	0	Total:	120.00
Work Order: Problem:			Meter:	867		In Date:	03/02/2016	Closed:	03/02/2016
Work Con	npleted								
- Tow Fror	m: Semin	ole Palms Park	To: Lv sł	пор					
		Hours: 0.00		Comm: 96.00	Labor: 0.00	Parts: 0.0	0	Total:	96.00
Work Order: Problem:		4 in for noise in f	Meter: ront whe			In Date:	03/02/2016	Closed:	03/07/2016
Work Com	npleted								
- Test driv this time.	e.remove	all four wheels	s to inspe	ect brakes.no problem fou	nd at				
		Hours: 0.50		Comm: 0.00	Labor: 30.00	Parts: 0.0	0	Total:	30.00
Work Order: Problem:			Meter:	2445		In Date:	06/02/2016	Closed:	06/13/2016
Work Com	npleted				Parts Issued			Qı	antity
- P.m. Serv	vice.				5w20 Engine Oil				7.00
- Rotate a	nd baland	ce all.tires.			Napagold Oil Filter				1.00
- Inspect a	and servic	e winch.			Washer Fluid Concer	ntr			1.00
- Shop Su	pplies				Shop Supplies				1.00
		Hours: 4.00		Comm: 0.00	Labor: 240.00	Parts: 21.	.89	Total:	261.89

Palm Beach County Fleet Management Asset Maintenance History 10199086 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1612504 Meter: 7397 12/06/2016 Closed: 12/27/2016 In Date: Problem: P.m. service and recall 16b32. **Work Completed** Parts Issued Quantity 22" Wiper Blade 4.00 - P.m. Service. Used Fire X Refurbished 1.00 - Inspect and service winch. Stg Wheel Cov - Ford 2.00 - Rotate and balance tires. 5w20 Engine Oil 14.00 - Repair trailer wiring. Napagold Oil Filter 2.00 - Transport vehicle to dealer for recall 16b32.(throttle body). Washer Fluid Concentr 2.00 - Shop Supplies Used Fire X Refurbished 1.00 Shop Supplies 1.00 Hours: 7.00 Comm: 0.00 Parts: 121.34 Total: 541.34 Labor: 420.00 Work Order: 1707810 08/09/2017 Closed: 08/22/2017 Meter: 12218 In Date: Problem: PM Service Parts Issued Quantity **Work Completed** 5w20 Engine Oil 6.00 - P.m. service. Napagold Oil Filter 1.00 - Replace missing pull handle trim left side upper on A-pillar. 22" Wiper Blade 2.00 - Inspect and service front winch. Washer Fluid Concentr 1.00 - Check and repair ,nail in tire Rotate and high speed balance all four.nitro fill all. Cover 1.00 - Shop Supplies Shop Supplies 1.00 Parts: 29.99 Hours: 5.20 Comm: 0.00 Labor: 312.00 Total: 341.99

Palm Beach County Fleet Management Asset Maintenance History101990862016 FORD F150 Pickup, 1/2 Ton

Nork Order: Problem:	1801217 P.M. service.	Meter:	14421		In Date:	01/31/2018	Closed:	02/06/2018
Work Com	pleted			Parts Issued			Qı	uantity
- P.m. serv	ice.			5w20 Engine Oil				6.00
- Rotate ar	nd high speed balance all four tires.			Napagold Oil Filter				1.00
- Inspect a	nd service winch.			22" Wiper Blade				2.00
- Shop Sup	oplies			Used Fire X Refurbis	hed			1.00
				Floor Mat-2pc Rub B	3k			1.00
				Shop Supplies				1.00
	Hours: 4.00		Comm: 0.00	Labor: 240.00	Parts: 68.	47	Total:	308.47
Vork Order: Problem:	1807176 Right front tire going flat.	Meter:	18866		In Date:	07/16/2018	Closed:	07/18/2018
Work Com	pleted			Parts Issued			Qı	uantity
- Replace t	wo front tires .balance and nitroger	n fill tires.		183114470 P245-70)r17			2.00
- Shop Sup	oplies			Shop Supplies				1.00
				Tire Disposal Fee				2.00
	Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 418	5.44	Total:	475.44
Vork Order: Problem:	1808043 P.M. service.	Meter:	19502		In Date:	08/06/2018	Closed:	08/15/2018
Work Com	pleted			Parts Issued			Qı	antity
- P.m. serv	ice.			Napagold Oil Filter				1.00
- Replace t	wo tires on front . High speed balar	nce all four	tires and nitrogen	5w20 Engine Oil				6.00
fill all tires.			5	Washer Fluid Concer	ntr			1.00
- Complete	e front end alignment. Road test.			22" Wiper Blade				2.00
- Inspect a	nd service winch.			Macs Chain Cable Lu	ıbe			1.00
- Shop Sup	oplies			183114470 P245-70)r17			2.00
				Shop Supplies				1.00
				Tire Disposal Fee				2.00
	Hours: 7.50		Comm: 0.00	Labor: 450.00	Parts: 446	6.45	Total:	896.45

Palm Beach County Fleet Management Asset Maintenance History101990862016 FORD F150 Pickup, 1/2 Ton

Work Order: 1902790 Problem: P.M. service.	Meter: 24726		In Date:	03/13/2019	Closed:	03/22/2019
Work Completed		Parts Issued			Qı	uantity
- P.m. Service.		Napagold Oil Filter	r			1.00
- Test battery and charging system.r	5w20 Engine Oil				6.00	
test.replace bad battery.		Washer Fluid Conc	entr			1.00
- Inspect and service winch.		22" Wiper Blade				2.00
- Rotate and balance tires.		Used Fire X Refurb	ished			1.00
- Shop Supplies	Battry Motorcraf	t			1.00	
		Shop Supplies				1.00
Hours: 5.75	Comm: 0.00	Labor: 385.25	Parts: 219	9.89	Total:	605.14
Work Order: 1909956 Problem: FLat tire	Meter: 28458		In Date:	06/03/2019	010000	09/26/201
Work Completed - Tire Service Okeeheelee Park Main	t Compound - Flat tire					
•	t Compound - Flat tire Comm: 70.25	Labor: 0.00	Parts: 0.0	00	Total:	70.25
- Tire Service Okeeheelee Park Main Hours: 0.00 Work Order: 1911712 Problem: P.M. service and recalls	Comm: 70.25 Meter: 29634		Parts: 0.0 In Date:	00 11/12/2019	Closed:	11/25/201
- Tire Service Okeeheelee Park Main Hours: 0.00 Work Order: 1911712 Problem: P.M. service and recalls Work Completed	Comm: 70.25 Meter: 29634	Parts Issued			Closed:	11/25/201 Jantity
- Tire Service Okeeheelee Park Main Hours: 0.00 Work Order: 1911712 Problem: P.M. service and recalls Work Completed - P.m. service.	Comm: 70.25 Meter: 29634 17S33 and 18S27 .	Parts Issued 22" Wiper Blade	In Date:		Closed:	11/25/201 Jantity 2.00
- Tire Service Okeeheelee Park Main Hours: 0.00 Work Order: 1911712 Problem: P.M. service and recalls Work Completed	Comm: 70.25 Meter: 29634 17S33 and 18S27 .	Parts Issued 22" Wiper Blade Washer Fluid Conc	In Date:		Closed:	11/25/201 Jantity 2.00 1.00
- Tire Service Okeeheelee Park Main Hours: 0.00 Work Order: 1911712 Problem: P.M. service and recalls Work Completed - P.m. service.	Comm: 70.25 Meter: 29634 17S33 and 18S27 .	Parts Issued 22" Wiper Blade Washer Fluid Conc Napagold Oil Filter	In Date:		Closed:	11/25/201 Jantity 2.00 1.00 1.00
 Tire Service Okeeheelee Park Main Hours: 0.00 Work Order: 1911712 Problem: P.M. service and recalls Work Completed P.m. service. Test and repair tool box strut mou 	Comm: 70.25 Meter: 29634 17S33 and 18S27 . nt and replace missing strut .	Parts Issued 22" Wiper Blade Washer Fluid Conc Napagold Oil Filter 5w20 Engine Oil	In Date:		Closed:	11/25/201 Jantity 2.00 1.00 1.00 6.00
 Tire Service Okeeheelee Park Main Hours: 0.00 Work Order: 1911712 Problem: P.M. service and recalls Work Completed P.m. service. Test and repair tool box strut mouting of the service winch in the service winch is service winch in the service winch in the service winch in the service winch is service winch in the service winch	Comm: 70.25 Meter: 29634 17S33 and 18S27 . nt and replace missing strut . four tires . Nitrofill all.	Parts Issued 22" Wiper Blade Washer Fluid Conc Napagold Oil Filter	In Date:		Closed:	11/25/2013 Jantity 2.00 1.00 1.00 6.00 1.00
 Tire Service Okeeheelee Park Main Hours: 0.00 Work Order: 1911712 Problem: P.M. service and recalls Work Completed P.m. service. Test and repair tool box strut mou Inspect and service winch . Rotate and high speed balance all 	Comm: 70.25 Meter: 29634 17S33 and 18S27 . nt and replace missing strut . four tires . Nitrofill all.	Parts Issued 22" Wiper Blade Washer Fluid Conc Napagold Oil Filter 5w20 Engine Oil	In Date:		Closed:	11/25/2013 Jantity 2.00 1.00 1.00 6.00
 Tire Service Okeeheelee Park Main Hours: 0.00 Work Order: 1911712 Problem: P.M. service and recalls Work Completed P.m. service. Test and repair tool box strut mou Inspect and service winch . Rotate and high speed balance all Transport to and from dealer for rest 	Comm: 70.25 Meter: 29634 17S33 and 18S27 . nt and replace missing strut . four tires . Nitrofill all.	Parts Issued 22" Wiper Blade Washer Fluid Conc Napagold Oil Filter 5w20 Engine Oil Wd40 Spr	In Date:	11/12/2019	Closed: Qu	11/25/2019 Jantity 2.00 1.00 1.00 6.00 1.00

Work Order: 2004554

In Date: 05/06/2020 **Closed:** 05/14/2020

Problem: P.M. Service.Idles rough after fueling.

Work Completed		Parts Issued			Qı	uantity
- P.m. service.	Napagold Oil Filter				1.00	
- Computer diagnose check engine and rough i	dle after fueling , code	5w20 Engine Oil			7.00	
P1450 . Perfom evap test . R&r defective stuck o	22" Wiper Blade			2.00 1.00		
and retest .	Washer Fluid Conce	ntr				
- Replace all four tires and balance . Nitrofill all	·	Used Fire X Refurbis	hed		1.00	
- Perform complete front end alignment and ro	Purge Valve			1.00 4.00		
- Inspect and service winch .	245/70/17 Tire Mich					
- Shop Supplies		Shop Supplies			1.00	
		Tire Disposal Fee				4.00
Hours: 10.00	Comm: 0.00	Labor: 730.00	Parts: 1,0	40.07	Total:	1,770.07
rk Order: 2011141 Problem: P.M. service and needs pintle hitch	Meter: 38300	Parts Issued	In Date:	11/04/2020		
		Parts Issued	In Date:	11/04/2020		11/24/20: Jantity
Problem: P.M. service and needs pintle hitch		Parts Issued 5w20 Engine Oil	In Date:	11/04/2020		
 Problem: P.M. service and needs pintle hitch Work Completed Preventive Maint. Service Cabin A/c filter replacement. Remove and rep 			In Date:	11/04/2020		uantity
Problem: P.M. service and needs pintle hitchWork CompletedPreventive Maint. Service		5w20 Engine Oil	In Date:	11/04/2020		antity 7.00
 Problem: P.M. service and needs pintle hitch Work Completed Preventive Maint. Service Cabin A/c filter replacement. Remove and rep glove box. Clean outside air pick up vents. Rotate and Balance all four wheels and tires. Note: Note	lace cabin A/c filter behind	5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade		11/04/2020		7.00
 Problem: P.M. service and needs pintle hitch Work Completed Preventive Maint. Service Cabin A/c filter replacement. Remove and rep glove box. Clean outside air pick up vents. Rotate and Balance all four wheels and tires. N Tpms. 	lace cabin A/c filter behind litrogen fill all tires and reset	5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade		11/04/2020		7.00 1.00 2.00
 Problem: P.M. service and needs pintle hitch Work Completed Preventive Maint. Service Cabin A/c filter replacement. Remove and rep glove box. Clean outside air pick up vents. Rotate and Balance all four wheels and tires. N Tpms. Install new Pintle style Hitch. Install new hitch 	lace cabin A/c filter behind litrogen fill all tires and reset pin.	5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade Washer Fluid Conce		11/04/2020		antity 7.00 1.00 2.00 1.00
 Problem: P.M. service and needs pintle hitch Work Completed Preventive Maint. Service Cabin A/c filter replacement. Remove and rep glove box. Clean outside air pick up vents. Rotate and Balance all four wheels and tires. N Tpms. Install new Pintle style Hitch. Install new hitch Service winch mounted on front bumper. Win 	lace cabin A/c filter behind Nitrogen fill all tires and reset pin. ch will not retract cable with	5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade Washer Fluid Conce Cabin Filter		11/04/2020		Jantity 7.00 1.00 2.00 1.00 1.00
 Problem: P.M. service and needs pintle hitch Work Completed Preventive Maint. Service Cabin A/c filter replacement. Remove and rep glove box. Clean outside air pick up vents. Rotate and Balance all four wheels and tires. N Tpms. Install new Pintle style Hitch. Install new hitch Service winch mounted on front bumper. Win remote. Remove winch cover and determine bac 	lace cabin A/c filter behind litrogen fill all tires and reset pin. ch will not retract cable with d connection at solenoid.	5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade Washer Fluid Conce Cabin Filter Hitch Lock Cls V	ntr	11/04/2020		Jantity 7.00 1.00 2.00 1.00 1.00 1.00 1.00
 Problem: P.M. service and needs pintle hitch Work Completed Preventive Maint. Service Cabin A/c filter replacement. Remove and rep glove box. Clean outside air pick up vents. Rotate and Balance all four wheels and tires. N Tpms. Install new Pintle style Hitch. Install new hitch Service winch mounted on front bumper. Win remote. Remove winch cover and determine bac Remove all cables from winch solenoids. Clean service winch cover and determine bac provide the style style style winch solenoids. Clean service winch solenoids. Clean service winch solenoids. Clean service winch solenoids. 	lace cabin A/c filter behind litrogen fill all tires and reset pin. ch will not retract cable with d connection at solenoid.	5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade Washer Fluid Conce Cabin Filter Hitch Lock Cls V Pintle Hook Mount	ntr	11/04/2020		Jantity 7.00 1.00 2.00 1.00 1.00 1.00 1.00 1.00
 Problem: P.M. service and needs pintle hitch Work Completed Preventive Maint. Service Cabin A/c filter replacement. Remove and rep glove box. Clean outside air pick up vents. Rotate and Balance all four wheels and tires. N Tpms. Install new Pintle style Hitch. Install new hitch Service winch mounted on front bumper. Win 	lace cabin A/c filter behind litrogen fill all tires and reset pin. ch will not retract cable with d connection at solenoid.	5w20 Engine Oil Napagold Oil Filter 22" Wiper Blade Washer Fluid Conce Cabin Filter Hitch Lock Cls V Pintle Hook Mount Pintle Hook With Ba	ntr	11/04/2020		Jantity 7.00 1.00 2.00 1.00 1.00 1.00 1.00 1.00 1.00

Work Order: 2109526

In Date: 08/31/2021 **Closed:** 09/21/2021

Problem: PM Service. Thank you! and over heating .

Work Completed		Parts Issued			Qı	uantity
- Preventive Maint. Service		22" Wiper Blade				2.00
- Inspect and serviced winch		Napagold Oil Filter				1.00
- Rotated and balanced all 4 tires. Nitrogen filled	5w20 Engine Oil				7.00	
- Diagnose over heating. Found upper and lower	radiator hoses to be	Steering Wheel Co	over Large			1.00
leaking. Replaced both radiator hoses and thermo	ostat. Flushed cooling	Anti Freeze Motor	craft			2.00
system. Test drove		Brake Pad				1.00
- Resurfaced rear rotors and replaced rear pads. test drove.	Serviced rear calipers and	Hose Clamp				3.00
		Hose Clamp				2.00
- Shop Supplies	Thermostat Gasket				1.00	
		Hose				1.00
		Thermotat Assy Hose				1.00
						1.00
		Used Fire X Refurb	bished			1.00
		Non-chlor Brake C	Inr			2.00
		Shop Supplies				1.00
Hours: 11.50	Comm: 0.00	Labor: 839.50	Parts: 308.81		Total:	1,148.31
Problem: 2112547 Problem: windshied wiper dont tun off	Meter: 45259		In Date:	11/24/2021	Closed:	11/30/202
Work Completed		Parts Issued			Qu	uantity
- Computer diagnose wipers on , monitor pids . I	Wiper Switch				1.00	
setting on wiper switch . Retest .		Shop Supplies				1.00
- Shop Supplies						
Hours: 1.50	Comm: 0.00	Labor: 109.50	Parts: 60.	57	Total:	170.07

Work Order: 2203996

In Date: 04/13/2022 **Closed:** 04/21/2022

Problem: P.M. service and tire sensor fault light on .

Work Completed			Parts Issued	Quantity		
- Performed P.m.	Performed P.m. Service & Inspection.			5w20 Engine Oil		
- Check Custome	er Concern, Performed Diag 8	& Scan For Faults, Found R/f	Napagold Oil Filte	r	1.00	0
	sor Defective, Removed & Re		Used Fire X Refurk	bished	1.00	0
Balance And Rotate, Reset Tpms Test Drove Vehicle And Check. Working As Design.			Washer Fluid Con	centr	1.00	0
0	ery, Battery Test Recommend	Charge Charged Battery &	22" Wiper Blade		2.00	0
		placed, Reset Bms And Check.	245/70/17 Tire Mi	ch	2.00	0
Working As Desig		•	Battry Motorcrat	ft	1.00	0
- Performed Service & Inspection On Winch.			Universal Switch		1.00	0
- Removed & Replaced Cabin Air Filter, Clean A/c Vents And Check.			Cabin Filter		1.00	0
- Strobe Lights Ir	nop Aswell As Right Rear Stro	be. Check Power & Ground To	Support		1.00	0
	ower And Ground Was Ok. Str	,	Kit Tpms Sensor	1.00	0	
	aced Then Check, Found R/r robe. Strobe Defective R & R	Strobe Inop, Performed Diag	Mnt Conc Led Cle	1.00	0	
	nt Wheel Alignment & Test D	rove Vehicle Working As	Universal Switch	1.00	0	
Design.		Tove vehicle. Working 75	Shop Supplies	1.00		
- Removed & Re	placed Leaking Tool Box Sho	ck Strut Also Rescure & Rivot	Tire Disposal Fee		2.00	0
Hinge For Shock S	Strut.					
- Shop Supplies						
	Hours: 11.80	Comm: 0.00	Labor: 861.40	Parts: 782.52	Total: 1,643	3.92
ork Order: 22040 Problem: Dama		Meter: 47026 oor & mirror, left side of bed & le	eft step	In Date: 03/09/2022	2 Closed: 04/19	9/202
Work Completed	d					
- Damage to left	front fender, left door & mir	ror, left side of bed & left step				
	Hours: 0.00	Comm: 3,524.63	Labor: 0.00	Parts: 0.00	Total: 3,524	1 62

Work Order: 2212235

In Date: 12/06/2022 Closed: 12/19/2022

Problem: PM Service just came from body shop

Work Completed	Parts Issued			Quantity		
- Preventive Maint. Service					1.00	
- Rear View Camera Not Working Verify Power				5w20 Engine Oil		
					1.00	
Plug, Corroded Causing Trailer Plug Connected All The Time, Replace Trailer Plug And Retest Adjust L/f Door.		22" Wiper Blade Napagold Air Filter			2.00	
- Replace 4 Tires And Front Right Tpms Sensor					1.00	
- Service And Inspect Winche, Replace Winche	Backup Cam Kit w/m	irror		1.00		
- Test Drive And Perform Front End Alignment	,	Tpms Sens Kit 245/70/17 Tire Mich Fab Loom-split Poly			1.00 4.00 30.00	
- Inspect Lights Left Rear Tail Light Cracked R8						
Faborcate Strobe Light						
- Shop Supplies		Primary Wire			20.00	
		Clevis Slip Hk W Ltch	I		1.00	
		Winche Cable			1.00	
		Lamp Assy			1.00	
		Lamp Assy			1.00	
		trailer plug			1.00	
		Shop Supplies			1.00	
		Tire Disposal Fee			4.00	
Hours: 15.30	Comm: 0.00	Labor: 1,116.90	Parts: 1,4	45.27	Total: 2,562.17	
York Order:2300298Problem:tire blow out	Meter: 53105		In Date:	01/11/2023	Closed: 01/12/202	
Work Completed		Parts Issued			Quantity	

- Replace left rear tire and balance due to sidewall damage .

- Shop Supplies

Comm: 0.00

Parts Issued		Quantity
245/70/17 Tire Mich		1.00
Shop Supplies		1.00
Tire Disposal Fee		1.00
Labor: 36.50	Parts: 197.39	Total: 233.89

/ork Order: 2301220 Problem: Loose water pump pulley. Also,	Meter: 52721 a driver-side arm rest cover cam	e off. Thanks.	In Date:	02/07/2023	Closed:	02/16/2023
Work Completed		Parts Issued			Qı	uantity
- Replace water pump, thermostat, belts and	Coolent				1.00	
bleed and pressure test system.	V Belt				1.00	
- Remove drivers door panel, plastic weld re	Connection Assy				1.00	
- Install right front factory rim and tire.		Water Pump Asy				1.00
- Shop Supplies		V Belt				1.00
		Shop Supplies				1.00
Hours: 7.60	Comm: 0.00	Labor: 554.80	Parts: 255	5.21	Total:	810.01
Vork Order: 2308408 Problem: PM Service. Send for Detail.	Meter: 57110		In Date:	08/22/2023	Closed:	09/06/2023
Work Completed		Parts Issued			Qı	uantity
- Performed P.m. Service & Inspection.		Napagold Oil Filter				1.00
- Performed Tire Rotation Balance On All 4	Wheels, Add Nitrofill Reset Tpms.	5. 5w20 Engine Oil				7.00
		Washer Fluid Concentr			1.00	
- Performed Service & Inpection On Winch.						2.00
·		22" Wiper Blade				2.00
 Performed Service & Inpection On Winch. Rear Toolbox Lid Is Seperating, Removed ⁻ Then Install New Toolbox And Check. 		22" Wiper Blade Used Fire X Refurbis	hed			1.00
- Rear Toolbox Lid Is Seperating, Removed ⁻ Then Install New Toolbox And Check. - Driver Side Seat Cushion Worn And Hole I	Tools And Transfer Into New n Seat. Removed Drive Side Seat	•				
 Rear Toolbox Lid Is Seperating, Removed Then Install New Toolbox And Check. Driver Side Seat Cushion Worn And Hole I Removed And Replaced Seat Cushion With I 	Tools And Transfer Into New n Seat. Removed Drive Side Seat nterior Then Check.	Used Fire X Refurbis				1.00
 Rear Toolbox Lid Is Seperating, Removed Then Install New Toolbox And Check. Driver Side Seat Cushion Worn And Hole I Removed And Replaced Seat Cushion With I Removed & Replaced Cabin Air Filter, Clear 	Tools And Transfer Into New n Seat. Removed Drive Side Seat nterior Then Check. an A/c Vents And Check.	Used Fire X Refurbish Macs Chain Cable Lu				1.00 1.00
 Rear Toolbox Lid Is Seperating, Removed Then Install New Toolbox And Check. Driver Side Seat Cushion Worn And Hole I Removed And Replaced Seat Cushion With I Removed & Replaced Cabin Air Filter, Cleat Rear Back Up Camera Inop, Check Signal T 	Tools And Transfer Into New n Seat. Removed Drive Side Seat nterior Then Check. an A/c Vents And Check. To Back Up Camera. Signal Ok,	Used Fire X Refurbish Macs Chain Cable Lu Seat Cover Assy				1.00 1.00 1.00
 Rear Toolbox Lid Is Seperating, Removed Then Install New Toolbox And Check. Driver Side Seat Cushion Worn And Hole I Removed And Replaced Seat Cushion With I Removed & Replaced Cabin Air Filter, Cleater Back Up Camera Inop, Check Signal T Camera Defective. Removed And Replaced Cabin Air Filter Cleater Camera Defective. Removed And Replacer Cabin Air Filter Cleater Camera Defective. Removed And Replacer Cabin Air Filter Cleater Camera Air Filter Cleater Cabin Air Filter Cleater Camera Air Filter Cleater Cabin Air Filter Cleater Camera Air F	Tools And Transfer Into New n Seat. Removed Drive Side Seat nterior Then Check. an A/c Vents And Check. To Back Up Camera. Signal Ok, Camera With Known Good One	Used Fire X Refurbish Macs Chain Cable Lu Seat Cover Assy Pad Seat				1.00 1.00 1.00 1.00
 Rear Toolbox Lid Is Seperating, Removed Then Install New Toolbox And Check. Driver Side Seat Cushion Worn And Hole I Removed And Replaced Seat Cushion With I Removed & Replaced Cabin Air Filter, Cleat Rear Back Up Camera Inop, Check Signal T 	Tools And Transfer Into New n Seat. Removed Drive Side Seat nterior Then Check. an A/c Vents And Check. To Back Up Camera. Signal Ok, Camera With Known Good One	Used Fire X Refurbish Macs Chain Cable Lu Seat Cover Assy Pad Seat Cabin Air Filter				1.00 1.00 1.00 1.00 1.00

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2308408 for: Courtney Hanson

Work Order: 2401310 Problem: P.M. serv		59297 ing charge. Issues with starting. W	ill bring in today .Tire f	In Date: fault light on	02/05/2024	Closed:	02/13/2024	
Work Completed			Parts Issued			Quantity		
- Pm Service			Wiper Blade				2.00	
- Replace Tpms sense	or in right front and r	ear wheels . rotate and balance	Washer Fluid Concen	ıtr			1.00	
tires nitro fill all Reset Tpms			5w20 Engine Oil				6.00	
- customer states ba	Napagold Oil Filter				1.00			
	load test battery was charged but failed load test . Remove and replace			ned		1.00		
battery .hook up lds to reset Bsm - lube and inspect winch.			Tpms Sens Kit				2.00	
			Battry Motorcraft				1.00	
- Shop Supplies			Shop Supplies				1.00	
I	Hours: 6.50	Comm: 0.00	Labor: 474.50	Parts: 343	8.80	Total:	818.30	
Problem: Dead Bat Work Completed	tery. Stan will bring to	o shop today.	Parts Issued			Qı	lantity	
- Recover charge bat for draw. Ok.	tery, lights were left o	on. Charge and retest, Pass. Check	Shop Supplies				1.00	
- Shop Supplies								
	Hours: 0.70	Comm: 0.00	Labor: 51.10	Parts: 2.6	5	Total:	53.75	
Work Order: 2409403 Problem: Transition		61776		In Date:	09/26/2024	Closed:	10/01/2024	
Work Completed								
- Transition Prep Cha	rge							
•	-Jours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 0.0	0	Total:	146.00	