Palm Beach County Fleet Management Asset Maintenance History 10199098 2016 FORD F150 Pickup, 1/2 Ton

Total Hours: 115.60	Parts: 6,631.16	Comm: 96.00	Charge	d: 14780.46
Work Order: 1606214 M Problem: 1061 - Pre Delivery Inspe	leter: 307		In Date: 06/16/2016	6 Closed: 06/16/2016
Work Completed				
- Pre Delivery Inspection				
Hours: 2.00	Comm: 0.00	Labor: 120.00	Parts: 0.00	Total: 120.00
Work Order: 1612174 M Problem: P.M. service.	leter: 2146		In Date: 11/29/2016	6 Closed : 12/12/2016
Work Completed		Parts Issued		Quantity
- P.m. Service.		Napagold Oil Filter		1.00
- Rotate and balance tires.		5w20 Engine Oil		6.00
- Shop Supplies		Used Fire X Refurbi	shed	1.00
		22" Wiper Blade		2.00
		Washer Fluid Conce	entr	1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 42.98	Total: 222.98
Work Order: 1702889 M Problem: Check engine light and re	leter: 3579 ecall 16B32.		In Date: 03/22/2017	Closed: 04/13/2017
Work Completed		Parts Issued		Quantity
- Transport vehicle to dealer for reca	II #16b32.	Shop Supplies		1.00
- Shop Supplies				
Hours: 2.00	Comm: 0.00	Labor: 120.00	Parts: 2.00	Total: 122.00
Work Order: 1702923 M Problem: No start	leter: 3516		In Date: 03/22/2017	Closed: 03/22/2017
Work Completed				
- Tow From: Okeeheelee Park Maint	Compound To: Lv shop			
Hours: 0.00	Comm: 96.00	Labor: 0.00	Parts: 0.00	Total: 96.00

Palm Beach County Fleet Management Asset Maintenance History 10199098 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1707618 Meter: 5574 In Date: 08/03/2017 Closed: 08/14/2017

Problem: P.M. Service.

Work Completed		Parts Issued		Quantity
- P.m. service.		5w20 Engine Oil		6.00
- Rotate and high speed balance all four tires.		Napagold Oil Filte	r	1.00
- Shop Supplies		22" Wiper Blade		2.00
		Used Fire X Refurb	pished	1.00
		Floor Mat-2pc Rub	o Bk	1.00
		Stg Wheel Cov - Fe	ord	1.00
		Shop Supplies		1.00
Hours: 3.00	Comm: 0.00	Labor: 180.00	Parts: 83.42	Total: 263.42

Work Order: 1800803 Meter: 7920 In Date: 01/23/2018 Closed: 02/01/2018

Problem: P.M. service and tool box above fuel tank.

Work Completed		Parts Issued		Quantity
- P.m. service.		5w20 Engine Oil		6.00
- Fabricate and install tool box.		Napagold Oil Filter		1.00
- No filter on auxiliary fuel tank .fabericate ans install filter k	rit on pump	Washer Fluid Concentr 22" Wiper Blade		1.00
inspect and service auxiliary fuel tank and replace worn hos	e.			2.00
- Rotate and high speed balance all four wheels.nitro fill all.		Filter Kit		1.00
- Shop Supplies		Hose 3/4x12' Hard	wall	1.00
		Bright Alum Crosso	over	1.00
		Napagold Fuel Filter		1.00
		3/4 Pipe		2.00
		Shop Supplies		1.00
Hours: 7.50 C	omm: 0.00	Labor: 450.00	Parts: 493.70	Total: 943.70

Palm Beach County Fleet Management Asset Maintenance History 10199098 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1808245 Meter: 10584 In Date: 08/10/2018 Closed: 08/20/2018

Problem: PM Service, Trailer battery warning coming on.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filter		1.00
- Inspect and service auxilary fuel tank.		5w20 Engine Oil		6.00
- Inspect and replace trailer plug connector and rewire as	needed.	22" Wiper Blade		2.00
- Rotate and high speed balance all four wheels . Nitrofill	all.	Washer Fluid Concentr		1.00
- Shop Supplies		Used Fire X Refurb	oished	1.00
		Napagold Fuel Filt	er	1.00
		trailer plug		1.00
		Shop Supplies		1.00
Hours: 5.00	Comm: 0.00	Labor: 300.00	Parts: 53.53	Total: 353.53

Work Order: 1901219 Meter: 12628 In Date: 01/31/2019 Closed: 02/13/2019

Problem: P.M. service.

Work Completed	Parts Issued	Quantity
- P.m. service.	Napagold Oil Filter	1.00
- Replace two tires . Rotate and high speed balance all four tires . Nitr	ofill all. 5w20 Engine Oil	6.00
- Inspect and service aux fuel tank.	22" Wiper Blade	2.00
- Perform complete front end alignment and road test.	Used Fire X Refurbished	1.00
- Shop Supplies	Ford Triton Pvc Swc	1.00
	Napagold Fuel Filter	1.00
	245/70/17 Tire Mich	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours: 7.50 Comm: 0.00	Labor: 502.50 Parts: 554.01	Total: 1,056.51

Palm Beach County Fleet Management Asset Maintenance History 10199098 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 1907875 Meter: 15248 In Date: 07/30/2019 Closed: 08/07/2019

Problem: PM Service

Work Completed		Parts Issued		Quantity
- P.m. Service.		Napagold Oil Filte	er	1.00
- Inspect and service aux. fuel system.		5w20 Engine Oil		7.00
- Test battery and charging system.recharge an	d retest battery,fail load	22" Wiper Blade		2.00
test.replace defective battery.	·	Washer Fluid Con-	centr	1.00
- Replace two tires,rotateand balance all four.		Napagold Fuel Fil	ter	1.00
- Replace corroded trailer plug and rewire.		Battry Motorcra	ft	1.00
- Repair bent toolbox lid hinge.drill and secure	hinges with pop rivets.	245/70/17 Tire Mi	ch	2.00
- Shop Supplies		Permatex		1.00
		trailer plug		1.00
		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 8.00	Comm: 0.00	Labor: 536.00	Parts: 703.24	Total: 1,239.24

Work Order: 1911328 Meter: 16509 In Date: 10/31/2019 Closed: 11/06/2019

Problem: Aibag light on.Check wiper blades.

Work Completed		Parts Issued		Quantity
 Test and replace defective wiper blades . Computer diagnose airbag light , code B1404 . Perform pinpoint test . Remove left front seat asembly to replace open defective airbag harness . 		Wire Asy		1.00
		22" Wiper Blade		2.00
		Shop Supplies		1.00
- Shop Supplies				
Hours: 2.70	Comm: 0.00	Labor: 197.10	Parts: 49.08	Total: 246.18

Palm Beach County Fleet Management Asset Maintenance History 10199098 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2007362 Meter: 21848 In Date: 07/28/2020 Closed: 08/06/2020

Problem: P.M. service.and recalls 17S33 and 18S27.

Work Completed		Parts Issued		Quantity
- P.m. service.		Napagold Oil Filter		1.00
- Replace one worn out tire . Rotate and balance	ce all four tires . Nitrofill all.	5w20 Engine Oil		6.00
- Resurface both rear brake rotors and service	calipers . Replace brake pads	. Washer Fluid Cond	centr	1.00
Flush and bleed brake system . Road test .		22" Wiper Blade		2.00
- Inspect and service auxiliary fuel tank .		Napagold Air Filte	er	1.00
		Mac Wite Lithium Gres Used Fire X Refurbished		1.00
		Brake Pad		1.00
		Napagold Fuel Filt	er	1.00
		Cabin Air Filter		1.00
		Shop Supplies		1.00
		Tire Disposal Fee		1.00
Hours: 11.00	Comm: 0.00	Labor: 803.00	Parts: 389.28	Total: 1,192.28

Work Order: 2012249 Meter: 25866 In Date: 12/09/2020 Closed: 12/14/2020

Problem: Plug in tire and auxiliary fuel nozzle leaking .

Work Completed		Parts Issued		Quantity
- Diagnose leaking nozzle . R&r defective nozzle . (Clean and retest .	Green Diesel Nozzle Hld Open Clip		1.00
- Repair left rear tire that was plugged and balance . Nitro fill all		Filter Kit		1.00
- Shop Supplies		Nozzle		1.00
		Shop Supplies		1.00
Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 264.70	Total: 410.70

Palm Beach County Fleet Management Asset Maintenance History 10199098 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2102930 Meter: 28126 In Date: 03/16/2021 Closed: 03/24/2021

Problem: P.M. service and cabin filter and air freshener.

Work Completed	Parts Issued		Quantity
- Preventive Maint. Service	Napagold Oil Filter	r	1.00
- Check all tires R & I two new on front, rotate and speed balance all four,	5w20 Engine Oil		6.00
nitro fill	22" Wiper Blade		2.00
- Perform complete front end alignment Road test .	Washer Fluid Cond	entr	1.00
- R & I new cabin filter and clean fresh air intake .	Tpms Sens Kit		1.00
- Inspect and Service Aps fuel system	245/70/17 Tire Mid	ch	2.00
- Shop Supplies	Air Freshener		1.00
	Cabin Air Filter		1.00
	Napagold Fuel Filt	er	1.00
	Shop Supplies		1.00
	Tire Disposal Fee		2.00
Hours: 8.00 Comm: 0.00	Labor: 584.00	Parts: 702.32	Total: 1,286.32

Work Order: 2106075 Meter: 29450 In Date: 06/03/2021 Closed: 06/09/2021

Problem: The "trailer battery not charging" warning light keeps coming on when it is not hooked to any trailer.

Work Completed		Parts Issued		Quantity
- Replace trailer plug, Reprogram trailer module.		trailer plug		1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 1.50	Comm: 0.00	Labor: 109.50	Parts: 15.10	Total: 124.60

Work Order: 2109180 Meter: 31022 In Date: 08/24/2021 Closed: 08/25/2021

Problem: Fire Extinguisher Used, Need replacement

Work Completed		Parts Issued		Quantity
- Replace spent fire extinguisher		Used Fire X Refur	bished	1.00
Hours: 0.20	Comm: 0.00	Labor: 14.60	Parts: 9.86	Total: 24.46

Palm Beach County Fleet Management Asset Maintenance History 10199098 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2110221 Meter: 31803 In Date: 09/21/2021 Closed: 09/30/2021

Problem: PM Service.

Work Completed		Parts Issued	Quantity
- Preventive Maint. Service		5w20 Engine Oil	6.00
- Inspect and service Aps fuel system		Napagold Oil Filter	1.00
- Rotate and speed balance, nitro fill		Washer Fluid Concentr	1.00
- Shop Supplies		22" Wiper Blade	2.00
		Steering Wheel Cover Large	1.00
		Yellow Markal Crayon	1.00
		Napagold Fuel Filter	1.00
		Mac Wite Lithium Gres	1.00
		Shop Supplies	1.00
Hours: 4.00	Comm: 0.00	Labor: 292.00 Parts: 55.75	Total: 347.75

Work Order: 2112992 Meter: 33325 In Date: 12/08/2021 Closed: 12/09/2021

Problem: right passenger tire going flat

Hours: 1.00

Work Completed	Parts Issued	Quantity
- Repair right front tire and balance . Nitro fill all.	Shop Supplies	1.00
- Shop Supplies		

Labor: 73.00

Parts: 2.65

Total: 75.65

Comm: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10199098 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2202828 Meter: 35548 In Date: 03/15/2022 Closed: 03/21/2022

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service - inspect and service auxiliary fuel system		Napagold Oil Filter		1.00
		Napa Quart 5w20		6.00
- replaced two tires ,balance all 4 Nitro fill all.		22" Wiper Blade		2.00
- completed front end alignment and road test		Used Fire X Refurbis	shed	1.00
- Shop Supplies		Napagold Fuel Filte	r	1.00
		245/70/17 Tire Mich	1	2.00
		Shop Supplies		1.00
		Tire Disposal Fee		2.00
Hours: 7.50	Comm: 0.00	Labor: 547.50	Parts: 502.49	Total: 1,049.99

Work Order: 2209783 Meter: 38975 In Date: 09/20/2022 Closed: 09/30/2022

Problem: PM Service.

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Napagold Oil Filter	1.00
- Rotated and balanced all 4 tires. Nitrogen filled all tires.	5w20 Engine Oil	6.00
- Battery tested bad. Charged battery fully and retested bad. Replaced	bad Washer Fluid Concentr	1.00
battery and reset Bms.	22" Wiper Blade	2.00
- Inspect and serviced aux fuel system	Battry Motorcraft	1.00
- Shop Supplies	Napagold Fuel Filter	1.00
	Shop Supplies	1.00
Hours: 5.50 Comm: 0.00	Labor: 401.50 Parts: 189.83	Total: 591.33

Palm Beach County Fleet Management Asset Maintenance History 10199098 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2302869 Meter: 41761 In Date: 03/21/2023 Closed: 03/28/2023

Problem: PM Service.

Work Completed		Parts Issued		Quantity					
 Preventive Maint. Service completed inspect and service auxiliary fuel system balance and rotate all 4 tires . Nitro fill all. check,and replaced cabin a/c filter and clean fresh air intake Shop Supplies 		Napagold Oil Filte	Napagold Oil Filter						
		Napa Quart 5w20		6.00					
		22" Wiper Blade Used Fire X Refurbished Napagold Fuel Filter		2.00 1.00 1.00					
							Cabin Filter		1.00
							Shop Supplies		1.00
Hours: 4.50	Comm: 0.00	Labor: 328.50	Parts: 100.00	Total: 428.50					

Work Order: 2306152 Meter: 43295 In Date: 06/22/2023 Closed: 06/22/2023

Problem: left front tire needs repair

Work Completed		Parts Issued		Quantity
- Repair left front tire, balance and nitro service		Shop Supplies		1.00
- Shop Supplies				
Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 2.65	Total: 75.65

Palm Beach County Fleet Management Asset Maintenance History 10199098 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2308821 Meter: 44603 In Date: 08/30/2023 Closed: 09/13/2023

Problem: PM Service and right front tire going flat

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Filter	1.00
- Repaired Rf tire. Replaced 2 tires. Rotated and balanced all 4 tires. Nitrogen filed all tires.	5w20 Engine Oil	6.00
	Washer Fluid Concentr	1.00
- Inspect and serviced aux fuel system.	22" Wiper Blade	2.00
- Replaced rear brake pads and rotors. Serviced calipers. Flushed brake fluid.	. 245/70/17 Tire Mich	2.00
Test drove to burnish new pads and rotors.	Napagold Fuel Filter	1.00
- Diagnose transmission fluid leak. Found to have leaking tail shaft seal. R&	Brake Pad Set	1.00
tail shaft seal. Cleaned oil spray from leak. Performed transmission fluid flush. Topped off fluid and test drove.	Rear Rotor	2.00
- Shop Supplies	Brake Fl-dot 3-4 32oz	1.00
	Non-chlor Brake Clnr	2.00
	Seal	1.00
	Nut Tram	1.00
	Non-chlor Brake Clnr	2.00
	Flange	1.00
	oil auto	15.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours: 11.70 Comm: 0.00	Labor: 854.10 Parts:	968.01 Total: 1,822.11

Palm Beach County Fleet Management Asset Maintenance History 10199098 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2404701 Meter: 48258 In Date: 05/10/2024 Closed: 05/29/2024

Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Inspect all, R & i two new on front, Rotate and speed balance, nitro fill
- Perform Ids Diagnostic engine light on, Code #p1450, Perform evap system test , Purge failed R & i new
- Perform Aps fuel service
- Seat trim damages, Cushion worn
- Inspect all, R & i new front brakes, Resurface both rotors, service caliper slide pins, bleed bakes, Road test
- Check & replace strobe light switch inop.
- Check & repair broken latch cable, repair door trim arm rest loose
- Shop Supplies

Parts Issued	Quantity
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
245/70r17 Gy Wrkhrse Ht	2.00
Tpms Sens Kit	1.00
Valve Asm	1.00
Napagold Fuel Filter	1.00
Seat Cover Assy	1.00
Seat Cover Assy	1.00
Pad Seat	1.00
Pad Seat	1.00
Non-chlor Brake Clnr	1.00
Brake Pad	1.00
Brk Fluid Dot 4-12oz	1.00
Led Rocker Switch Round	1.00
Uv Liq Plastic Adhesv	1.00
Cable Assy	1.00
Duramix	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00
Labor: 1,095.00 Parts: 1,446.59	Total: 2,541.59

Hours: 15.00 Comm: 0.00

Palm Beach County Fleet Management Asset Maintenance History

10199098 2016 FORD F150 Pickup, 1/2 Ton

Work Order: 2408716 Meter: 49545 In Date: 09/10/2024 Closed: 09/19/2024

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 115.60 Total Labor: 8,053.30 Total Comm: 96.00 Total Parts: 6,631.16