- Shop Supplies

Hours: 1.00

Comm: 0.00

# Palm Beach County Fleet Management Asset Maintenance History 10199492 2016 CAROLINA SKIFF 218 DLV Boat, < 21 Ft

Total Hours: 1	33.50 Labor: 9,376.	50 Parts: 7,506.18	Comm: 96.00		Charged	: 16978.68	
Work Order: Problem:	1512616 1061 - Pre Delivery Insp	Meter: 1		In Date:	12/14/2015	Closed:	12/14/2015
Work Com	pleted						
- Pre Delive	ery Inspection						
	Hours: 2.00	Comm: 0.00	Labor: 120.00	Parts: 0.0	00	Total:	120.00
Work Order: Problem:	1604296 pm service	Meter: 19		In Date:	04/25/2016	Closed:	04/29/2016
Work Com	pleted		Parts Issued			Qı	uantity
- Pm			Napagold Fuel Filter				1.00
- Replace v	varranty hatch latch		Center Pin Coax				1.00
- Remount	Vhf in radio box and rep	pair antenna connector	10-24 Screws Ph Ova	al			10.00
- Shop Sup	plies		10flat Washer Ss				10.00
			10-24lockwashss				10.00
			10cup Washer Ss				10.00
			Shop Supplies				1.00
			Freight Charge				1.00
	Hours: 4.00	Comm: 0.00	Labor: 240.00	Parts: 48.	.50	Total:	288.50
	1608451 GPS FELL OFF/ SEE N	<b>Meter:</b> 53 IOTES		In Date:	08/16/2016	Closed:	08/24/2016
Work Com	pleted		Parts Issued			Qı	uantity
- Reinstall ı	mount		Shop Supplies				1.00

Labor: 60.00

Parts: 2.00

Total: 62.00

## Palm Beach County Fleet Management Asset Maintenance History 10199492 2016 CAROLINA SKIFF 218 DLV Boat, < 21 Ft

Work Order: 1611281 Meter: 60 In Date: 11/01/2016 Closed: 11/15/2016

Problem: pm service

Work Completed		Parts Issued		Quantity
- Pm		Napagold Fuel Filte	er	1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 2.00	Comm: 0.00	Labor: 120.00	Parts: 19.25	Total: 139.25

Work Order: 1701393 Meter: 68 In Date: 02/09/2017 Closed: 02/16/2017

Problem: depth finder not working

Work Completed	Parts Issued	Quantity
- Diag depth finder not working called garmin tech support dowload newest	32 G micro chip	1.00
software to unit	Shop Supplies	1.00

- Shop Supplies

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 23.26 Total: 143.26

Work Order: 1704883 Meter: 79 In Date: 05/16/2017 Closed: 05/22/2017

Problem: pm service

Work Completed		Parts Issued		Quantity
- pm service		Napagold Fuel Fil	ter	1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 2.00	Comm: 0.00	Labor: 120.00	Parts: 21.04	Total: 141.04

Work Order: 1709676 Meter: 116 In Date: 10/03/2017 Closed: 10/10/2017

Problem: guard rail needs reattached

Work Completed		Parts Issued		Quantity
- Reattach and secure starboard side rub rail		Clr Rtv Silcn Seala	ant	1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 1.50	Comm: 0.00	Labor: 90.00	Parts: 8.39	Total: 98.39

#### **Palm Beach County Fleet Management Asset Maintenance History** 2016 CAROLINA SKIFF 218 DLV Boat, < 21 Ft 10199492

Work Order: 1711286 Meter: 127 11/15/2017 **Closed:** 12/08/2017 In Date:

Problem: pm service

Work Completed		Parts Issued		Quantity
- Pm	Napagold Fuel Fil	1.00		
- Check charging sys batteries failed lo	ad test replace both batteries	Battery		2.00
- Shop Supplies		Shop Supplies		1.00
Hours: 3.50	Comm: 0.00	Labor: 210.00	Parts: 300.94	Total: 510.94
Work Order: 1804005	Meter: 151		In Date: 04/18/201	8 <b>Closed:</b> 04/23/2018

**Problem:** anchor?

**Work Completed** Quantity **Parts Issued Shop Supplies** 1.00 - replace broken power pole spike anchor

- Shop Supplies

Work Order: 1809102

Comm: 0.00 Hours: 1.50 Labor: 90.00 Parts: 2.00 Total: 92.00

In Date:

09/05/2018 **Closed**: 09/19/2018

Work Order: 1805874 **Meter: 164** 06/08/2018 Closed: 06/15/2018 In Date:

Problem: pm service

Work Completed			Parts Issued		Quantity
- pm service			Napagold Fuel Filter		1.00
- Shop Supplies			Shop Supplies		1.00
Но	urs: 2.00	Comm: 0.00	Labor: 120.00	Parts: 20.60	Total: 140.60

Problem: pm service, light on t top broken, seat foot rst clip broke, depth sounder not working, comp latch

**Meter:** 186

Work Completed	Parts Issued	Quantity
- pm service	Napagold Fuel Filter	1.00
- replace courtesy light on T top	Oval Courtesy Light	1.00
- update fish finder to newest software, clean corrosion on harness	Qd Electronic Cleaner	1.00
- repair handle on anchor latch	Clip	1.00
- replace spring clamp for foot rest	Shop Supplies	1.00
- Shop Supplies		

Hours: 5.50 Comm: 0.00 Labor: 330.00 Parts: 61.27 Total: 391.27

# Palm Beach County Fleet Management Asset Maintenance History 10199492 2016 CAROLINA SKIFF 218 DLV Boat, < 21 Ft

Work Order: 1902777 Meter: 213 In Date: 03/13/2019 Closed: 03/22/2019

Problem: pm service

Work CompletedParts IssuedQuantity- Pm ServiceNapagold Fuel Filter1.00- Rep. loose connection on Uhf radioShop Supplies1.00

- Shop Supplies

Hours: 3.00 Comm: 0.00 Labor: 201.00 Parts: 22.02 Total: 223.02

Work Order: 1910552 Meter: 271 In Date: 10/11/2019 Closed: 10/21/2019

Problem: pm service

 Work Completed
 Parts Issued
 Quantity

 - Pm Service
 Napagold Fuel Filter
 1.00

 - Shop Supplies
 Shop Supplies
 1.00

 Hours: 2.00
 Comm: 0.00
 Labor: 146.00
 Parts: 23.41
 Total: 169.41

Work Order: 1912764 Meter: 281 In Date: 12/13/2019 Closed: 12/26/2019

Problem: power pole/ see notes

Work Completed		Parts Issued	Quantity	
- diagnose poer pole. repair wiring, replace control	Green Marine Hyd	1.00		
reprogram. bleed hydraulics		Circuit Board	1.00	
- Shop Supplies		Shop Supplies		1.00
				1.00
Hours: 4.00	Comm: 0.00	Labor: 292.00	Parts: 369.04	Total: 661.04

# Palm Beach County Fleet Management Asset Maintenance History 10199492 2016 CAROLINA SKIFF 218 DLV Boat, < 21 Ft

Work Order: 2	2000855	Meter:	295		In Date:	01/27/2020	Closed:	02/12/2020
Problem:	GPs & depth finder not working	ıg						
Work Comp	pleted			Parts Issued			Qı	uantity
- replace in	op Garmin unit. wire in and re	pair wiring, inst	all newest software	32gb Sd Card				1.00
update				Garmin Transducer				1.00
- travel to w	vater to check and calibrate se	ttings on Garmi	in unit	Garmin 1042xsv Gps				1.00
- replace sti	icking gas gauge			Marine Adh Fast Cure	9			1.00
- Shop Supp	plies			Fuel Level Gauge				1.00
				Shop Supplies				1.00
				Freight Charge				1.00
	Hours: 19.00		Comm: 0.00	Labor: 1,387.00	Parts: 2,3	77.46	Total:	3,764.46
Work Order: 2		Meter:	302		In Date:	03/10/2020	Closed:	03/13/2020
Work Comp	oleted							
- Tow From	: Jog Rd s of Turnpike							
	Hours: 0.00		Comm: 96.00	Labor: 0.00	Parts: 0.0	0	Total:	96.00
Work Order: 2 Problem:		Meter:	310		In Date:	04/20/2020	Closed:	04/24/2020
Work Comp	pleted			Parts Issued			Qı	uantity
- pm service	е			Napagold Fuel Filter				1.00
- Shop Supp				Shop Supplies				1.00
-	Hours: 2.00		Comm: 0.00	Labor: 146.00	Parts: 23.	41	Total:	169.41
Work Order: 2	2006827 customer says is infested with	Meter: a black widow sp			In Date:	07/14/2020	Closed:	08/17/2020
Work Comp	pleted			Parts Issued			Qı	uantity
monk comb				Llulott				1.00
-	naly treat boat for spiders by I	Hulett		Hulett				1.00
•		Hulett		Shop Supplies				1.00

### Palm Beach County Fleet Management Asset Maintenance History 10199492 2016 CAROLINA SKIFF 218 DLV Boat, < 21 Ft

 Work Order:
 2009595
 Meter:
 362
 In Date:
 09/23/2020
 Closed:
 09/30/2020

 Problem:
 GPS not working

Work Completed	Parts Issued	Quantity
- repair damaged pins on unit, replace transducer. download and install	Garmin Transducer	1.00
latest update	Shop Supplies	1.00

- travel to water. test and recalibrate settings on garmin unit

- Shop Supplies

Hours: 8.00 Comm: 0.00 Labor: 584.00 Parts: 428.94 Total: 1,012.94

Work Order: 2012973 Meter: 387 In Date: 12/30/2020 Closed: 01/16/2021

Problem: PM Service. boat

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Napagold Fuel Filter	1.00
- Repair horn wiring	Marine Fire Evtinguisher	1.00
- Replace fire x	Shop Supplies	1.00
- Repair port side rub rail		
- Shop Supplies		

Hours: 4.00 Comm: 0.00 Labor: 292.00 Parts: 61.18 Total: 353.18

Work Order: 2102323 Meter: 410 In Date: 03/01/2021 Closed: 04/07/2021

Problem: The T-Top on the skiff (10199492) it is broken/ hatch latches. Two bars have fallen off of it

Work Completed		Parts Issued	Quantity		
<ul> <li>Replace Latches Lid Latches, Installwater Container Brackets, Repair &amp;</li> <li>Weld Broken T-top Frame, Secure Mounting Bolts</li> <li>Shop Supplies</li> </ul>		T-handle Latch		5.00	
		S/s Hook Shop Supplies		2.00	
Hours: 13.00	Comm: 0.00	Labor: 949.00	Parts: 258.31	Total: 1,207.31	

Work Order: 2104609 Meter: 414 In Date: 04/26/2021 Closed:

**Problem:** T top broke/ power pole remote/ rub rail/ marine radio

**Work Completed** 

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

# Palm Beach County Fleet Management Asset Maintenance History 10199492 2016 CAROLINA SKIFF 218 DLV Boat, < 21 Ft

Work Order: 2104835 Meter: 417 In Date: 04/29/2021 Closed: 05/20/2021

Problem: VHF Radio not working/ power pole remote inop/ T top welds broke/ rub rail

Nork Completed		<b>Parts Issued</b>	Quantity		
- Repair T-top, Fabricate And Weld More Supp	pair T-top, Fabricate And Weld More Supports		Threaded Rod		
<ul><li>Reprogram power pole remote control.</li><li>Repair loose wiring, replace, and secure new fuse holder.</li><li>Remove excess rub rail and reattach.</li></ul>		Cap Nut	6.00 1.00 1.00		
		Fuse Holder			
		Shop Supplies			
- Shop Supplies					
Hours: 13.00	Comm: 0.00	Labor: 949.00	Parts: 129.46	Total: 1,078.46	

Work Order: 2106454 Meter: 432 In Date: 06/15/2021 Closed: 08/10/2021

Problem: The power pole doesn't work, the rub rail is coming off on the other side now/ see comments

Work Completed	Parts Issued	Quantity
- Repair rub rail	Green Marine Hydraulic Fluid	2.00
- Flush hydraulic control unit	Napagold Fuel Filter	1.00
- Pm Service	Battery	2.00
- Test and replace both batteries	Bulk Battery Cable	2.00
- Replace battery switch, positive battery and negative battery cable	es for Battery Cable Lug	9.00
batteries.	Bulk Battery Cable	9.00
- Replace power cables and main breaker for instrument panel/mai	n feed to Selector Switch	1.00
console	Fuse Holder	1.00
- Shop Supplies	40a Circuit Breaker	1.00
	Shop Supplies	1.00
	Freight Charge	1.00
Hours: 10.00 Comm: 0.	00 Labor: 730.00 Parts: 449.64	Total: 1,179.64

Hours: 2.50

# Palm Beach County Fleet Management Asset Maintenance History 10199492 2016 CAROLINA SKIFF 218 DLV Boat, < 21 Ft

Work Order: Problem:	2108576 power pole	Meter:	432		In Date:	08/09/2021	Closed:	08/25/2021
Work Com	pleted			Parts Issued			Qı	uantity
- Install ne	w power pole, bleed and test run			Power Pole Pro Ii S	eries			1.00
- Shop Sup				Shop Supplies				1.00
				Freight Charge				1.00
	Hours: 7.00		Comm: 0.00	Labor: 511.00	Parts: 1,9	47.63	Total:	2,458.63
Work Order: Problem:	2112431 pm,Trailer Lights, Fender well ca	Meter: arpet floated of		er I beam cracked wher	In Date: re guide posts	11/22/2021 s are attached		12/22/2021
Work Com	pleted			Parts Issued			Qı	uantity
- Preventiv	re Maint. Service			Napagold Fuel Filte	er			1.00
- Repair Ru	ub Rail			Shop Supplies				1.00
- Shop Sup	oplies							
	Hours: 3.00		Comm: 0.00	Labor: 219.00	Parts: 19.	30	Total:	238.30
Work Order: Problem:	2204934 load boat onto Parks trailer for E	Meter: RM inspection			In Date:	05/06/2022	Closed:	05/10/2022
Work Com	pleted			Parts Issued			Qı	uantity
- load boa	t onto Parks trailer for Erm inspec	tion		Shop Supplies				1.00
- Run Engi	ne On Water Hose To Verify Runr	ning Conditio	n					
- Shop Sup	•	3						
	Hours: 4.00		Comm: 0.00	Labor: 292.00	Parts: 2.6	5	Total:	294.65
Work Order: Problem:	2205255 remove ERM boat from Parks tr	Meter: ailer	473		In Date:	05/17/2022	Closed:	05/18/2022
Work Com	pleted			Parts Issued			Qı	uantity
- Remove	Boat From Trailer			Shop Supplies				1.00
- Shop Sup	1.							

Comm: 0.00

Labor: 182.50

Parts: 2.65

Total: 185.15

# Palm Beach County Fleet Management Asset Maintenance History 10199492 2016 CAROLINA SKIFF 218 DLV Boat, < 21 Ft

Work Order: 2206242 Meter: 496 In Date: 06/13/2022 Closed: 07/28/2022

**Problem:** PM Service. boat/ power pole & T top broken/ box on T top loose

Work CompletedParts IssuedQuantity- Preventive Maint. ServiceNapagold Fuel Filter1.00- Replace Broken Power Pole AnchorShop Supplies1.00

- Secure Radio Box

- Shop Supplies

Hours: 4.50 Comm: 0.00 Labor: 328.50 Parts: 22.64 Total: 351.14

Work Order: 2300230 Meter: 549 In Date: 01/09/2023 Closed: 02/09/2023

Problem: PM Service, boat w/ Z205177

Work Completed	Parts Issued	Quantity	
- Preventive Maint. Service	Napagold Fuel Filter	1.00	
- Replaced Broken Stern Navigation Light, Drilled And Tapped New	Used Fire X Refurbished	1.00	
Mounting Holes, Rewired Light	Stern Nav Light	1.00	
- Remove Bench Seat To Send To Get Re-upolstered, Re-installed Seat	Attwood Navigation Light	1.00 1.00 1.00	
- Applied Clear Epoxy To Repair Live Well Lid	Gorilla Epoxy		
- Shop Supplies	Primer Bulb-3 8		
	Seat Repair	1.00	
	Hose Clamp	1.00	
	Shop Supplies	1.00	
Hours: 5.50 Comm: 0.00	Labor: 401.50 Parts: 465.17	Total: 866.67	

Work Order: 2303445 Meter: 560 In Date: 04/05/2023 Closed:

**Problem:** It has a crack in the bottom of the hull.

**Work Completed** 

Hours: 0.0

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

### Palm Beach County Fleet Management Asset Maintenance History 10199492 2016 CAROLINA SKIFF 218 DLV Boat, < 21 Ft

Work Order: 2409418 Meter: 560 In Date: 09/26/2024 Closed: 10/04/2024

Problem: Transition Prep Charge

Work CompletedParts IssuedQuantity- Transition Prep ChargeShop Supplies1.00

- Shop Supplies

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 2.65 Total: 148.65

Total Hours: 133.50 Total Labor: 9,376.50 Total Comm: 96.00 Total Parts: 7,506.18