

1/13/2025
9:48:51 AM

Palm Beach County Fleet Management Asset Maintenance History
10199493 2016 YAMAHA F150XB Boat Motor, > 50 HP, 150 HP

Total Hours: 84.00 Labor: 5,698.00 Parts: 6,826.39 Comm: 0.00 Charged: 12524.39

Work Order: 1512617 **Meter:** 0 **In Date:** 12/14/2015 **Closed:** 12/14/2015
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1604297 **Meter:** 19 **In Date:** 04/25/2016 **Closed:** 04/29/2016
Problem: first service/ pm

Work Completed

- Pm Service
- Shop Supplies

Parts Issued

Quantity

Spark Plug	4.00
Fuel Filter Element	1.00
Oil Filter	1.00
10w30 Motor Oil	5.00
Oil Filter	1.00
Shop Supplies	1.00
Labor: 180.00 Parts: 106.51 Total: 286.51	

Hours: 3.00 Comm: 0.00

1/13/2025
9:48:51 AM

Palm Beach County Fleet Management Asset Maintenance History
10199493 2016 YAMAHA F150XB Boat Motor, > 50 HP, 150 HP

Work Order: 2012974 **Meter:** 312 **In Date:** 12/30/2020 **Closed:** 01/16/2021
Problem: PM Service. motor

Work Completed

- Preventive Maint. Service
- Cooling system service
- Lower unit service
- Shop Supplies

Parts Issued

Quantity

Napa 10w30 Qt	5.00
Fuel Filter Element	1.00
Spark Plug	4.00
Thermostat Cover Gasket	1.00
Thermostat Assy	1.00
Yamaha Gear Lube Qt	1.00
Oil Filter	1.00
Water Pump Repair Kit	1.00
Gasket Vent Plug	2.00
O-ring - Shift Rod	1.00
Nipple	1.00
Shop Supplies	1.00

Hours: 7.00

Comm: 0.00

Labor: 511.00

Parts: 328.24

Total: 839.24

Work Order: 2103897 **Meter:** 410 **In Date:** 04/07/2021 **Closed:** 04/12/2021
Problem: motor making a squealing noise

Work Completed

- Drop gearcase, replace water pump kit, tighten spacers on drive shaft and install new trim tab anode with bolt.
- Water test and no problems found
- Shop Supplies

Parts Issued

Quantity

Water Pump Repair Kit	1.00
Trim Tab Anode	1.00
Bolt	1.00
Shop Supplies	1.00

Hours: 5.00

Comm: 0.00

Labor: 365.00

Parts: 160.29

Total: 525.29

1/13/2025
9:48:51 AM

Palm Beach County Fleet Management Asset Maintenance History
10199493 2016 YAMAHA F150XB Boat Motor, > 50 HP, 150 HP

Work Order: 2106902 **Meter:** 432 **In Date:** 06/24/2021 **Closed:** 07/16/2021

Problem: trim an tilt doesn't work

Work Completed

- Replace trim and tilt unit
- Pm Service
- Lower unit service
- Replace thermostat
- Shop Supplies

Parts Issued

Quantity

Power Trim & Tilt Fluid 32oz	1.00
Power Trim & Tilt Assy	1.00
Napa 10w30 Qt	5.00
Oil Filter	1.00
Fuel Filter Element	1.00
Spark Plug	4.00
Yamaha Gear Lube Qt	1.00
Gasket Vent Plug	2.00
Thermostat Cover Gasket	1.00
Thermostat Assy	1.00
Shop Supplies	1.00

Hours: 7.50

Comm: 0.00

Labor: 547.50 Parts: 4,037.00 Total: 4,584.50

Work Order: 2112434 **Meter:** 471 **In Date:** 11/22/2021 **Closed:** 12/22/2021

Problem: pm,Trailer Lights, Fender well carpet floated off at ramp, Trailer I beam cracked where guide posts are attached on both

Work Completed

- Preventive Maint. Service
- Cooling System Service
- Lower Unit Service
- Shop Supplies

Parts Issued

Quantity

Napa 10w30 Qt	5.00
Oil Filter	1.00
Fuel Filter	1.00
Thermostat Cover Gasket	1.00
Thermostat Assy	1.00
Yamaha Gear Lube Qt	1.00
Gasket Vent Plug	2.00
Water Pump Repair Kit	1.00
Spark Plug	4.00
Shop Supplies	1.00

Hours: 7.00

Comm: 0.00

Labor: 511.00 Parts: 223.86 Total: 734.86

1/13/2025
9:48:51 AM

Palm Beach County Fleet Management Asset Maintenance History
10199493 2016 YAMAHA F150XB Boat Motor, > 50 HP, 150 HP

Work Order: 2409419 **Meter:** 540 **In Date:** 09/26/2024 **Closed:** 10/04/2024
Problem: Transition Prep Charge

Work Completed

Parts Issued

Quantity

- Transition Prep Charge
- Shop Supplies

Shop Supplies

1.00

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 2.65

Total: 148.65

Total Hours: 84.00

Total Labor: 5,698.00

Total Comm: 0.00

Total Parts: 6,826.39