1/13/2025 9:45:12 AM <b>10183</b>	Palm Beach County Fleet Ma 704 2011 FORD F350 Utili	nagement Asset Maintena ty Body, 13,300 Gvwr, Med		
Total Hours: 354.50 Labor: 23,314.7	5 Parts: 17,642.88	Comm: 2,585.27	Charged: 43542.	90
Work Order:1106320MProblem:fill def fluid	eter: 332		In Date: 06/15/2011 Closed	l: 06/16/2011
Work Completed		Parts Issued		Quantity
- Fill Defrost fluid		Def Diesel Exh Fluic 55)	l (mtc Pm27jug 2.5, Pm27d	3.00
Hours: 0.00	Comm: 0.00	Labor: 0.00	Parts: 4.24 Tot	al: 4.24
Work Order: 1106541 M	eter: 332		In Date: 06/21/2011 Closed	<b>I:</b> 06/21/2011

Work Completed

Problem: Pre Delivery Inspection

Pre Delivery Inspection

- Pre Delivery I	Inspection				
	Hours: 4.00	Comm: 0.00	Labor: 240.00	Parts: 0.00	Total: 240.00
Vork Order: 111 Problem: PT	11901 Me O SWITCH & LIGHT B	e <b>ter:</b> 1059 Ar Light Inop.		In Date: 11/04/20	011 <b>Closed:</b> 11/15/2017
Work Complet	ted		Parts Issued		Quantity
	ch & light bar light inop ts for warranty repair.	. Verified concern. Send vehicle to	Shop Supplies		1.00
- Transport &   defective).	pick up vehicle at deale	r for warranty repair. (p.t.o. switch			
- Shop Supplie	25				
	Hours: 2.75	Comm: 0.00	Labor: 165.00	Parts: 2.00	Total: 167.00
Iork Order: 120 Problem: P.1		eter: 1274		In Date: 01/24/20	012 <b>Closed:</b> 01/31/2012
Work Complet	ted		Parts Issued		Quantity
- P. M. Service.			Shop Supplies		1.00
- Service Def s	ystem. Add Def fluid.		Fuel Filter		1.00
- Service crane	e & outriggers.		Oil Filter		1.00
- Shop Supplie			15/40 Oil		14.00

Labor: 360.00

Parts: 129.92

Total: 489.92

Comm: 0.00 Hours: 6.00

1/13/2025					
9:45:12 AM					

	1205457 damage to frt bumper, frt f	Meter: enders. frt headligh			In Date:	05/22/2012	Closed:	06/11/2012
Work Com								
	to frt bumper, frt fenders, fr	t boodlights & grill	2					
- uanage	Hours: 0.00	t neadiights & grin	- Comm: 2,088.60	Labor: 0.00	Parts: 0.0	0	Total:	2,088.60
Nork Order: Problem:	1207302 P.M.SERVICE	Meter:			In Date:	08/03/2012		08/17/2012
Work Com	pleted			Parts Issued			Qı	antity
- pm				Shop Supplies				1.00
- crane svo				Ph10890 Oil Filter	Mtc FI2051 W	/ix 57151		1.00
- unsiezed	hook and lubed installed n	ew pin unsiezed an	d lubed vise	3615 Fuel Filter F	rm K10826 W	ix 33615		1.00
- def svc				1259 Hydr Filter L	bf Frm P1653a	Wix 51259		1.00
- retighten	ed body hold downs			L0135-063 Lubrip	late Chain&cal	ole		1.00
•	ground for rear triple light a	assv		Lube,03050crc				
	d load recharged and retest	-		6y648 Graphite Lu	ıbe (imperial 6	590)		1.00
	and lubed outriggers pins a	·	sions	15/40 Oil				14.00
	dealer and back for recall #			18411 Pintal Pin, 2	2 3/4" New # 6	6063		1.00
	perform recall 12b34 pcm							
- Shop Sup								
Such and	Hours: 13.50		Comm: 0.00	Labor: 810.00	Parts: 147	7.73	Total <sup>.</sup>	957.73

Problem: pm	<b>Meter:</b> 3001	1		In Date:	03/08/2013	Closed:	03/22/2013
Work Completed			Parts Issued			Qı	uantity
- pm			Napagold Oil Filte	r			1.00
- crane svc			Napagold Fuel Filt	er			1.00
- dep svc			15w40 Bulk South	Reg			14.00
- unsiezed and lubed vise			Air Filter (gold), Ai	r Panel			1.00
- retightened body hold downs			Hydraulic Filter P1	653a			1.00
- unsiezed and lubed out riggers pi	ins and leg extentions		Aw68 Bulk Sr				2.00
- removed valve and polished spoo	ol and reinstalled		Shop Supplies				1.00
- Shop Supplies							
Hours: 12.00	Corr	nm: 0.00	Labor: 720.00	Parts: 130	).27	Total:	850.27
Work Completed			<b>Parts Issued</b> Air Filter (gold) Ai	r Panel		Qı	uantity
			Deute leave d			•	
- pm			Air Filter (gold), Ai	r Panel			1.00
- crane pm			Napagold Fuel Filt	er			1.00
- def svc			Napagold Oil Filte	r			1.00
- repaired grounds to body lights r	r clip light bulb		15w40 Bulk South	Reg			14.00
- disassembled ligth bar repaired co	onnection to take down ligi	ht and	Used Fire X Refurb	ished			1.00
- disassembled ligth bar repaired co reassembled	onnection to take down lig	ht and	Used Fire X Refurb Mac Wite Lithium				1.00 1.00
<b>.</b> .		ht and					
reassembled	is and leg extentions	ht and	Mac Wite Lithium				1.00
reassembled - unsiezed and lubed outrigger pin - removed m switch and lever asse - removed pulley assembly cleaned	as and leg extentions emble on boom		Mac Wite Lithium Napa Trans Filter	Gres			1.00 1.00
reassembled - unsiezed and lubed outrigger pin - removed m switch and lever asse - removed pulley assembly cleaned reinsatlled	as and leg extentions emble on boom d and polished rusted shaft		Mac Wite Lithium Napa Trans Filter Def Fluid 2.5	Gres			1.00 1.00 1.00
reassembled - unsiezed and lubed outrigger pin - removed m switch and lever asse - removed pulley assembly cleaned reinsatlled - unsiezed and lubed vise and hool	as and leg extentions emble on boom d and polished rusted shaft		Mac Wite Lithium Napa Trans Filter Def Fluid 2.5 179636492 Lt245-	Gres			1.00 1.00 1.00 4.00
reassembled - unsiezed and lubed outrigger pin - removed m switch and lever asse - removed pulley assembly cleaned reinsatlled - unsiezed and lubed vise and hook - rr 4 tires and balanced	as and leg extentions emble on boom d and polished rusted shaft		Mac Wite Lithium Napa Trans Filter Def Fluid 2.5 179636492 Lt245- Shop Supplies	Gres			1.00 1.00 1.00 4.00 1.00
reassembled - unsiezed and lubed outrigger pin - removed m switch and lever asse - removed pulley assembly cleaned reinsatlled - unsiezed and lubed vise and hool	as and leg extentions emble on boom d and polished rusted shaft		Mac Wite Lithium Napa Trans Filter Def Fluid 2.5 179636492 Lt245- Shop Supplies	Gres			1.00 1.00 1.00 4.00 1.00

Work Order: Problem:	1405104 needs front tires	Meter:	4249		In Date:	05/27/2014	Closed:	05/30/2014
Work Com	pleted			Parts Issued			Qı	uantity
- ck front t	tires replace front tires mount	balance add n2		179636492 Lt245-75	r17			2.00
- Shop Sup	oplies			Shop Supplies				1.00
				Tire Disposal Fee				2.00
	Hours: 1.50		Comm: 0.00	Labor: 90.00	Parts: 493	3.53	Total:	583.53
Work Order: Problem:		Meter:	4737		In Date:	08/26/2014	Closed:	09/08/2014
Work Com	pleted			Parts Issued			Qı	uantity
- pm				Napagold Oil Filter				1.00
- crane svo	-			Napagold Fuel Filter				1.00
- def avc				15w40 Bulk South Re	eg			14.00
- repaired	ground for triple light assy			Wiper Blade				2.00
- disassem	bled light bar repaired conne	ction to light		Napa Trans Filter				1.00
- rr pintal	pin and unseized and lube vis	e		Pintle Pin W/chain				1.00
- repaired				Lock Pin				1.00
- loosen ta	ank and moved forward repair	ed filters on plun	nbing	Shop Supplies				1.00
- unsiezed	and lubed outriggers pins an	d leg extensions	-					
- Shop Sup	oplies	-						
	Hours: 16.50		Comm: 0.00	Labor: 990.00	Parts: 114	1.08	Total:	1,104.08

# Work Order:1502195Meter:5573In Date:03/02/2015Closed:03/09/2015Problem:PM, DRIVER SIDE TOOL BOX COMPARTMENT DOOR NEAREST DRIVER DOOR NEEDS PIN REPLACED FOR LATCH TO LOCK

Work Completed			Parts Issued		Quantity			
<ul> <li>pm</li> <li>crane service</li> <li>def svc</li> <li>repaired open in cabinet for running light</li> <li>alley light out ck for power to light followed load from light thru cab and repaired connection just before the switch</li> </ul>			Napagold Oil Filter Napagold Fuel Filter		1.00			
							Air Filter (gold), Air	Panel
			15w40 Bulk South R	leg				
			Used Fire X Refurbis	shed			1.00	
			Wiper Blade				2.00	
			- unsiezed and lubed v	ise and hook			Napa Trans Filter	
- repaired rr tire				Slip Plate Spray 12c	Z			
- unsiezed and lubed o	out rigger pin and leg	exentions		Shop Supplies		1.00		
- adj boom swing end	play							
- repaired cabinet latch	n and striker assy							
- Shop Supplies								
	ours: 15.50	(	Comm: 0.00	Labor: 930.00	Parts: 15	5.86	Total:	1,085.86
	ours: 15.50	Meter: 6		Labor: 930.00	Parts: 158	5.86 08/25/2015		
Нс				Labor: 930.00				
Ho ork Order: 1508496				Labor: 930.00 Parts Issued			Closed:	
Hc ork Order: 1508496 Problem: pm, turbo re Work Completed							Closed:	09/08/201
Hc ork Order: 1508496 Problem: pm, turbo re				Parts Issued	In Date:		Closed:	09/08/201
Ho ork Order: 1508496 Problem: pm, turbo re Work Completed - pm - crane svc				<b>Parts Issued</b> Napagold Oil Filter	In Date:		Closed:	09/08/201 Jantity 1.00
Ho ork Order: 1508496 Problem: pm, turbo re Work Completed - pm	epair needed			<b>Parts Issued</b> Napagold Oil Filter Napagold Fuel Filte	In Date:		Closed:	09/08/201 Jantity 1.00 1.00
Ho ork Order: 1508496 Problem: pm, turbo re Work Completed - pm - crane svc - svc def sys	epair needed e filter and test sys	Meter: (	6206	<b>Parts Issued</b> Napagold Oil Filter Napagold Fuel Filte 15w40 Bulk South R	In Date:		Closed:	09/08/201 Jantity 1.00 1.00 14.00
Ho ork Order: 1508496 Problem: pm, turbo re Work Completed - pm - crane svc - svc def sys - clean siesel particulat	epair needed e filter and test sys verify concern inspect	Meter: (	6206	<b>Parts Issued</b> Napagold Oil Filter Napagold Fuel Filte 15w40 Bulk South R Washer Fluid Conce	In Date:		Closed:	09/08/201 Jantity 1.00 1.00 14.00 1.00
Ho ork Order: 1508496 Problem: pm, turbo re Work Completed - pm - crane svc - svc def sys - clean siesel particulat - ck turbo need repair	epair needed e filter and test sys verify concern inspect	Meter: (	6206	Parts Issued Napagold Oil Filter Napagold Fuel Filte 15w40 Bulk South R Washer Fluid Conce Napa Trans Filter	In Date:		Closed:	09/08/201 <b>Jantity</b> 1.00 1.00 14.00 1.00 1.00

1/13/2025 9:45:12 AM

## Palm Beach County Fleet Management Asset Maintenance History 10183704 2011 FORD F350 Utility Body, 13,300 Gvwr, Medium Duty Crane

Work Order: 7 Problem: t	1508522 turbo blew , needs pm	Meter:	5980		In Date:	08/24/2015	Closed:	08/25/2015
Work Comp	pleted							
- Tow From:	: 22438 sw 7 st boca To: sr sh	ор						
	Hours: 0.00		Comm: 134.77	Labor: 0.00	Parts: 0.00	0	Total:	134.77
Nork Order: 7 Problem: F		Meter:	6401		In Date:	02/23/2016	Closed:	03/07/2016
Work Comp	pleted			Parts Issued			Qı	antity
- Pm service	e.			15-40 Oil				14.00
- Test startir	ng and charging system.both	batteries failed	loadtest after	Napagold Oil Filte	r			1.00
recharge.rep	place both defective batteries.			Napagold Fuel Filt	ter			1.00
- Inspect an	nd service crane.			22" Wiper Blade				2.00
- Perform co	omplete wheel alignment.inst	all adjustable ca	m on left side to	Used Fire X Refur	pished			1.00
specs.				Floor Mat-2pc Rul	b Bk			1.00
	d balance all six tires.			Bp Fmx-lp F Mx Fi	use			1.00
•	vehicle to and from dealer for	r replacing wate	r pump and	Battery				2.00
reprogram P				Napa Trans Filter				1.00
- Shop Supp	plies			Aw68 Hydro Fluid	Hydr			8.00
				Caster-camber Bu	shing			1.00
				Def Quart				2.00
				Shop Supplies				1.00
	Hours: 13.50		Comm: 0.00	Labor: 810.00	Parts: 453	3.26	Total:	1,263.26
Nork Order: 1 Problem: 1	1606362 Engine RPM increase by self.	Meter:	7085		In Date:	06/22/2016	Closed:	06/29/2016
Work Comp	pleted			Parts Issued			Qı	antity
	diagnose for engine Rpm inc rm Dpf regen. with scan tool a	,	oncern.no	Shop Supplies				1.00
- Shop Supp								
	Hours: 1.50		Comm: 0.00	Labor: 90.00	Parts: 2.00	n	Total:	92.00

**Meter:** 7459

#### Work Order: 1610217 Problem: Pm service.Recall.

#### In Date: 09/29/2016 Closed: 10/28/2016

Work Completed		Parts Issued	Quantity	
- P.m.service		Napagold Oil Filter		1.00
- Service Crane And Out Riggers.		Napagold Fuel Filt	ter	1.00
- Service Def System		15w40 Bulk South	14.00	
- R/r Pintle Pin, Tighten Tailgate Assy.		Washer Fluid Cond	centr	1.00
- Repair Rear Brake Light Assy.		22" Wiper Blade		2.00
- Transport Veh. To And From Dealer For Sa	ifety Recall#16b24.	Napa Trans Filter	1.00	
- Shop Supplies				3.00
		Slip Plate Spray 12	1.00	
		Def Fluid 2.5		1.00
		Pintle Pin W/clip Led Sup Mdl 44 42 Dio Shop Supplies		1.00
				1.00
				1.00
Hours: 10.75	Comm: 0.00	Labor: 645.00	Parts: 208.94	Total: 853.94
ork Order: 1705010 Problem: P.M.SERVICE	Meter: 8551		In Date: 05/19/201	7 <b>Closed:</b> 05/30/201
Work Completed		Parts Issued		Quantity
- Pm service		Napagold Oil Filte	r	1.00
- Service crane and outriggers		Napagold Fuel Filt	ter	1.00

- Service Def system
- Repair light switch utility bed lights and third brake light
- Rotate and balance tires.
- Shop Supplies

Parts Issued	Quantity	
Napagold Oil Filter	1.00	
Napagold Fuel Filter		1.00
15w40 Bulk South Re	g	14.00
Washer Fluid Concer	tr	1.00
22" Wiper Blade		2.00
Used Fire X Refurbish	ned	1.00
Napa Trans Filter		1.00
Aw68 Bulk Sr		5.00
Def Fluid 2.5		1.00
Universal Switch		1.00
Shop Supplies		1.00
Labor: 660.00	Parts: 163.21	Total: 823.21

Meter: 10810

## Work Order: 1711387

#### In Date: 11/17/2017 Closed: 12/11/2017

Problem: PM Service Flat, Nail in tire.

Work Completed	Parts Issue	d	Quantity
- Pm Service	Napagold C	bil Filter	1.00
- Service crane and outriggers.	15w40 Bulk	South Reg	14.00
- Replace left brake and three piece cargo light bar.	Napagold F	uel Filter	1.00
- Rear brake pads and both rear brake calipers replaced.cut rc	tors.service Air Filter (go	old), Air Panel	1.00
hardware and bleed system.	22" Wiper B	lade	2.00
- Mount and balance six tires.	Washer Flui	d Concentr	1.00
- Replace right front wheel speed sensor, scan and clear codes	Napa Trans	Filter	1.00
- Def Service.	Aw68 Bulk S	Sr	5.00
- Repair leaking transmission line to Pto.top off fluid.	Led Sup Mo	l 44 42 Dio	1.00
- Unseized and service vise	Led Id Bar 6	Ctrs	1.00
- Adjust tailgate to open properly.	Brake Pad		1.00
- Shop Supplies	Reman Brak	e Caliper	1.00
	Reman Brak	e Caliper	1.00
	B Fluid Dot	3-32oz	1.00
	Non-chlor E	rake Clnr	1.00
	179636492	Lt245-75r17	6.00
	Def Fluid 2.	5	1.00
	Syn Atf Bulk	South	3.00
	Abs Sensor		1.00
	Shop Suppl	es	1.00
	Tire Disposa	l Fee	6.00
Hours: 22.50 Con	um: 0.00 Labor: 1,35	0.00 Parts: 1,919.32	Total: 3,269.32

Meter: 13222

## Work Order: 1807034 Problem: PM Service

#### **In Date:** 07/11/2018 **Closed:** 07/30/2018

Work Completed	Parts Issued		Quantity
- Pm Service.	Used Fire X Refurb	bished	1.00
- Service crane and outriggers.	Napagold Oil Filte	r	1.00
- Replace right Led brake lamp.	15w40 Bulk South	Reg	14.00
- Replace 6 way socket and wiring harness.	Napagold Fuel Filt	ter	1.00
- Replace pintle pin.drill hole and tap old bolt out to install pintle pin.	Air Filter (gold), Ai	r Panel	1.00
- Replace defective left rear brake caliper bleed system and clean off residu	22" Wiper Blade Washer Fluid Concentr Napa Trans Filter Aw68 Bulk Sr		2.00
- Realign and adjust tailgate Straighten bent bolts			1.00
- Perform with scan tool regeneration to exhaust filter.reset adaptives and			1.00
clear codes.			5.00
- Shop Supplies	Led Sup Mdl 44 42	2 Dio	1.00
	trailer plug		1.00
	Pintle Pin W/clip		1.00
	Non-chlor Brake C	Inr	1.00
	B Fluid Dot 3-32oz	Ζ	1.00
	Reman Brake Calip	per	1.00
	Shop Supplies		1.00
Hours: 15.25 Comm: 0.00	Labor: 915.00	Parts: 315.10	Total: 1,230.10

Meter: 14820

## Work Order: 1901007 Problem: PM Service.

#### In Date: 01/28/2019 Closed: 02/28/2019

Work Completed	Parts Issued			Quantity			
- Pm Service.		15w40 Bulk South R	eg			14.00	
- Service crane and outriggers.		Napagold Oil Filter Napagold Fuel Filter			1.00		
- Service Def system.							
- Repair wiring harness.	- Repair wiring harness.				1.00		
- Clean hydraulic system and check for leaks.f	22" Wiper Blade				2.00		
tank.need fabrication and welding.	Napa Trans Filter				1.00		
- Check engine light on.scan found code P20	Def Fluid 2.5			2.00			
- Transport vehicle to and from dealer for rep	Sd Butt Connector Y	ellow/		1.00			
to entended warranty.	Aw68 Bulk Sr			5.00			
- Transport vehicle to Vista He Shop for fabric	cation and welding new tank.	Shop Supplies			1.00		
- Shop Supplies Hours: 15.00	Comm: 0.00	Labor: 1,005.00	Parts: 196	6.69	Total:	1,201.69	
ork Order: 1902037 Problem: hydraulic tank repair	<b>Meter:</b> 14876		In Date:	02/22/2019	Closed:	03/19/201	
Work Completed							
work completed		Parts Issued			Qı	antity	
- Replace Hyd. tank		<b>Parts Issued</b> Hose Made Mako			Qı	<b>iantity</b> 1.00	
•			em		Qı	•	
- Replace Hyd. tank		Hose Made Mako	-		Qı	1.00	
- Replace Hyd. tank - To Mako		Hose Made Mako Tank 25 Gal Stl W Te	np			1.00 1.00	
- Replace Hyd. tank - To Mako		Hose Made Mako Tank 25 Gal Stl W Te Ptex Thrd Seal Hiter	np lydr			1.00 1.00 2.00	
- Replace Hyd. tank - To Mako		Hose Made Mako Tank 25 Gal Stl W Te Ptex Thrd Seal Hiten Aw68 Hydro Fluid H	np lydr			1.00 1.00 2.00 100.00	
- Replace Hyd. tank - To Mako		Hose Made Mako Tank 25 Gal Stl W Te Ptex Thrd Seal Hiten Aw68 Hydro Fluid H Napa Hydraulic Filtr	np lydr			1.00 1.00 2.00 100.00 1.00	
- Replace Hyd. tank - To Mako		Hose Made Mako Tank 25 Gal Stl W Te Ptex Thrd Seal Hiter Aw68 Hydro Fluid H Napa Hydraulic Filtr Hose Made Mako	np lydr			1.00 1.00 2.00 100.00 1.00 1.00	
- Replace Hyd. tank - To Mako		Hose Made Mako Tank 25 Gal Stl W Te Ptex Thrd Seal Hiter Aw68 Hydro Fluid H Napa Hydraulic Filtr Hose Made Mako Hose Made Mako	np lydr			1.00       1.00       2.00       100.00       1.00       1.00       1.00	

Work Order: 1 Problem: T	902763 Transport to Vista HE Shop	Meter: for hyd.Tank.	14894		In Date:	03/13/2019	Closed:	03/18/201
Work Comp	leted			Parts Issued			Q	uantity
- Transport v	vehicle to and from Vista He	e Shop for hydrau	llic tank.	Shop Supplies				1.00
- Shop Supp		. ,						
	Hours: 1.50		Comm: 0.00	Labor: 100.50	Parts: 3.0	0	Total:	103.50
Work Order: 1 Problem: F		Meter:	16022		In Date:	09/11/2019	Closed:	09/30/201
Work Comp	leted			Parts Issued			Q	uantity
- Pm Service	۱.			Napagold Oil Filte	r			1.00
- Service cra	ne and outriggers.			15w40 Bulk South	Reg			14.00
- Def Service	2.			Used Fire X Refurb	ished			1.00
- Replace wo	orn floor mats and steering	wheel cover.		Napagold Fuel Filt	er			1.00
- Rotate and	l balance 6 tires.mount one	new tire.		22" Wiper Blade				2.00
- Service bot	th batteries and clean trays.			Washer Fluid Cond	entr			1.00
- Clean engi	ne compartment.			Air Filter (gold), Ai	r Panel			1.00
- Perform ex	haust filter regeneration an	d reset adaptives		Napa Trans Filter				1.00
- Shop Supp	lies			Macs Chain Cable	Lube			1.00
				Def Fluid 2.5				1.00
				Ford Triton Pvc Sw	'C			1.00
				2pc Hd Mat Set Bl	k			1.00
				179636492 Lt245-	75r17			1.00
				Shop Supplies				1.00
				Tire Disposal Fee				1.00
	Hours: 12.75		Comm: 0.00	Labor: 854.25	Parts: 46	7.74	Total:	1,321.99

Meter: 17060

#### Work Order: 2002511

#### In Date: 03/11/2020 Closed: 03/30/2020

Problem: PM Service.ABS light on.Back up alarm inop.

Work Com	pleted	Parts Issued			Quantity		
- Pm Servio	ce.		15w40 Bulk South Reg Napagold Oil Filter			14.00	
- Service cr	rane and outriggers.						1.00
<ul> <li>Service Def system.</li> <li>Check and replace back up alarm.</li> <li>C/s Abs light on.scan,found code#1155.perform pinpoint test and found</li> </ul>			Napagold Fuel Filte	er			1.00
			22" Wiper Blade				2.00
			Washer Fluid Conc	entr			1.00
bad front w	heel speed sensors.replace Ab	s wheel speed sensors and clear	Aw68 Bulk Sr				3.00
codes.		Napa Trans Filter				1.00	
- Perform [	Dpf regeneration with scan too	l and reset system.	Def Fluid 2.5 Alarm Abs Sensor				1.00
- Rotate an	nd balance tires.						1.00
- Shop Sup	oplies						2.00
			Shop Supplies				1.00
	Hours: 14.50	Comm: 0.00	Labor: 1,058.50	Parts: 372	2.97	Total:	1,431.47
/ork Order: Problem:	2008328 Bad batteries	<b>Meter:</b> 17793		In Date:	08/20/2020	Closed:	08/25/2020
Work Com	pleted		Parts Issued			Qı	uantity
- Tset start	ing and charging system.both	batteries failed loadtest.replace	Battery				2.00
both batter	ies.		Shop Supplies				1.00
- Shop Sup	oplies						
	Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 291	1.61	Total:	437.61

Meter: 18155

#### Work Order: 2010356 Problem: PM Service.

## In Date: 10/14/2020 Closed: 11/18/2020

Work Completed		Parts Issued	Quantity
- p.m. service.		Napagold Oil Filter	1.00
- service crane and outriggers.		15w40 Bulk South Reg	14.00
- service Def system.		22" Wiper Blade	2.00
- repair left brake light		Washer Fluid Concentr	1.00
- R & R pintle pin		Napagold Fuel Filter	1.00
- replace 2 tires rotate and balance all 6		Used Fire X Refurbished	1.00
- R & R body mount		Aw68 Bulk Sr	3.00
- repair one tire		Napa Trans Filter	1.00
- perform Dpf regeneration.		Def Fluid 2.5	1.00
- Shop Supplies		Led Sup MdI 44 42 Dio	1.00
		Pintle Pin W/clip	1.00
		Body Mount Kit	4.00
		Body Mount Kit	2.00
		Tire	2.00
		Metal Blades	1.00
		Shop Supplies	1.00
		Tire Disposal Fee	2.00
Hours: 19.75	Comm: 0.00	Labor: 1,441.75 Parts: 1,657.76	Total: 3,099.51

Meter: 18390

#### Work Order: 2105563 Problem: PM Service.

#### In Date: 05/18/2021 Closed: 06/09/2021

Work Com	pleted		Parts Issued			Q	uantity	
- Preventiv	e Maint. Service		22" Wiper Blade			2.00		
- Service C	rane And Out Riggers		Washer Fluid Con	centr		1.00		
- Replaced	Right Side Led Brake Lamp		15w40 Bulk South	Reg		14.00		
- Replaced	<ul> <li>Replaced Broken Pintle Pin</li> <li>Wash Vehicle</li> <li>Rotate Balance 6 Tires</li> <li>Remove And Treat Rust On Rear Bumper.paint Bumper To Match</li> </ul>			r		1.00		
- Wash Vel				ter			1.00	
- Rotate Ba				ir Panel		1.00		
- Remove /								
- Service Se	eized Vice Removed Rust And Pa	int	Aw68 Bulk Sr Napa Trans Filter				10.00	
- Shop Sup	plies						1.00	
			Led Sup Mdl 44 42	2 Dio			1.00	
			Gl Whit				2.00	
			Pintle Pin W/clip				1.00	
			Shop Supplies				1.00	
	Hours: 12.00	Comm: 0.00	Labor: 876.00	Parts: 258	3.27	Total:	1,134.27	
/ork Order: Problem:	2109984 Drivers side tire flat.	Meter: 18782		In Date:	09/15/2021	Closed:	09/29/20	
Work Com	pleted		Parts Issued			Q	uantity	
- Repair an	d balance left rear inside tire.nit	ogen fill all.	Aw68 Bulk Sr				6.00	
- Hyd hose	s for outrigger leaking.replace o	utrigger high pressure	Hyd Hose Assy				1.00	
hoses.clean	up fluid over spray.		Shop Supplies				1.00	
- Shop Sup	plies							
	Hours: 3.50	Comm: 0.00	Labor: 255.50	Parts: 100	).98	Total:	356.48	

Work Order:2111271Meter:18965Problem:Pm Service.Crane boom stuck up in air at Hagen Ranch.

#### **In Date:** 10/20/2021 **Closed:** 01/20/2022

Work Completed	Parts Issued	Quantity
- Diagnose for crane inop.boom left in the air.pin point test and found bac	Napagold Oil Filter	1.00
rotation limit switch.replace rotation limit switch and rewire contact	15w40 Bulk South Reg	14.00
configuration in new limit switch.check all operation Ok.	Napagold Fuel Filter	1.00
- Pm Service	Air Filter	1.00
- pm crane and out riggers. Lube and verify functions.	Aw68 Bulk Sr	10.00
- Shop Supplies	Napa Trans Filter	1.00
	Washer Fluid Concentr	1.00
	22" Wiper Blade	2.00
	Non-chlor Brake Clnr	2.00
	Limit Switch	1.00
	Shop Supplies	1.00
	Freight Charge	1.00
Hours: 8.50 Comm: 0.00	Labor: 620.50 Parts: 648.06	Total: 1,268.56

Meter: 19539

## Work Order: 2207737

#### 07/26/2022 **Closed:** 08/11/2022 In Date:

Problem: PM Service,a/c blow hot air

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		Napagold Fuel Filte	r	1.00
- Service crane, outriggers, replace breather/cap as	sembly,hydraulic filter,	Napagold Oil Filter		1.00
top off hydraulic fluid & verify all hydraulic function	).	15w40 Bulk South F	Reg	14.00
- Service Def system, use Ids to perform Dpf regen	eration & reset adaptive.	Air Filter		1.00
- A/c blows hot air. fully charge system, perform vis	•	Washer Fluid Conce	entr	1.00
found leaking evaporator & Schrader valves. Evacua grill, left front wheel well, replace evaporator, conde		22" Wiper Blade		2.00
recharge & test system.	lisel, Schlader valves,	Used Fire X Refurbis	shed	1.00
- Replace 4 tires, fill all tires with nitrogen, balance	& rotate.	Aw68 Bulk Sr		5.00
- R & R light bar wire harness to remove dashboard		Filler Breather		1.00
light.		Napa Trans Filter		1.00
- Test drive after repair to verify all repair are comp	olete.	Def Fluid 2.5		1.00
- Replace how's my driving decal.		Freon Sr Shop		2.00
- Shop Supplies		Non-chlor Brake Cli	nr	1.00
		A/c Condenser		1.00
		Evaporator Core		1.00
		A/c Valve Core Low	Side	1.00
		High Side Schrader	Valve	1.00
		E8 A/c Oil Univ W D	Ууе	1.00
		Lt245/75r17 Mich D	Defend Ltx	4.00
		Led Sup MdI 44 42	Dio	1.00
		13 Oz Aero Kroil		1.00
		Non-chlor Brake Cli	nr	2.00
		Shop Supplies		1.00
		Tire Disposal Fee		4.00
Hours: 26.00	Comm: 0.00	Labor: 1,898.00	Parts: 1,924.56	Total: 3,822.56

Meter: 19830

#### Work Order: 2302467 Problem: PM Service.

#### In Date: 03/10/2023 Closed: 04/12/2023

Work Completed	Pa	orts Issued		Quantity
- Preventive Maint. Service	N	apagold Oil Filter		1.00
- service crane and out riggers and modify and replaced hook	latch 15	w40 Bulk South R	eg	14.00
- replaced leaking left side out rigger and modify lines to work		ed Fire X Refurbis	hed	1.00
- diagnose and replaced shorted Pto switch	Fu	el Filter Kit		1.00
- mount 2 tires rotate balanced 6 tires	N	on-chlor Brake Clr	ır	3.00
- replaced burned out right side brake led lamp	Av	v68 Bulk Sr		1.00
- Shop Supplies	N	Napa Trans Filter		1.00
	Lt	245/75r17 Mich D	efend Ltx	2.00
	Le	d Sup Mdl 44 42 I	Dio	1.00
	Sa	fety Latch Kit		1.00
	ro	cker switch pto		1.00
	0	utrigger Cylinder		1.00
	Sh	op Supplies		1.00
	Ti	e Disposal Fee		2.00
Hours: 13.50 Com	m: 0.00 La	bor: 985.50	Parts: 2,349.34	Total: 3,334.84

#### Work Order: 2309598 Meter: 21006 **Problem:** crane is leaking fluid. 1 outrigger keeps falling. PM.

#### In Date: 09/21/2023 **Closed:** 10/31/2023

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Proformer Oil Filter	1.00
- Crane leaking at hydraulic hoses r&r hoses send to mako to be made .	15w40 Bulk South Reg	14.00
relaced both lines to crane .clean leaking residue	Fuel Filter Kit	1.00
- service crane and out riggers	Air Filter (gold), Air Panel	1.00
- Rr outrigger leaking down. R&r replaced right side out rigger. Paint new	22" Wiper Blade	1.00
outrigger white. Transfer foot pad from old to new outrigger.	Non-chlor Brake Clnr	3.00
- treat rust and repaint rear bumper	Aw68 Bulk Sr	40.00
- Shop Supplies	Napa Trans Filter	1.00
	Blk/ct	2.00
	2x Flat White	2.00
	New Pig	1.00
	Napa Qt 15w40	14.00
	Hose Assy	2.00
	Outrigger Cylinder	1.00
	Shop Supplies	1.00
Hours: 15.50 Comm: 0.00	Labor: 1,131.50 Parts: 1,871.19	Total: 3,002.69

#### Work Order: 2401173 Meter: 21016 02/01/2024 Closed: 02/16/2024 In Date: Problem: PM Service.Dead Batteries. Parts Issued Quantity **Work Completed** Oil Pan Drain Plug 1.00 - Pm Service. 1.00 Napagold Oil Filter - replaced broken washer nozzles check for other leaks and verified functions 15w40 Bulk South Reg 14.00 - rotate balanced 6 tires Wiper Blade 2.00 - serviced crane and out riggers. Lube cable and check functions. Replace **Fuel Filter** 1.00 hyd filter. Used Fire X Refurbished 1.00 - jump start in wud parking lot. recharged and tested both batteries. Steering Wheel Cover Large 1.00 replaced both failed batteries. Washer Jet 2.00 - Shop Supplies 2.00 Battery Shop Supplies 1.00 Hours: 9.75 Comm: 0.00 Labor: 711.75 Parts: 432.56 Total: 1,144.31 Work Order: 2406285 Meter: 22679 In Date: 06/27/2024 **Closed:** 06/30/2024 Problem: no response from outriggers. Work Completed - Hydraulic & Pressure Sys Hours: 0.50 Comm: 0.00 Labor: 36.50 Parts: 0.00 Total: 36.50 Work Order: 2406506 Meter: 22922 In Date: 07/08/2024 **Closed:** 07/12/2024 Problem: Towed in from Hagen Ranch Road plant for no start. Work Completed Parts Issued Quantity Tube - Outlet 1.00 - Turbo scorpion tube failed.blew off inlet.replace turbo scorpion inlet tube and perform Manual Dpf regen to clean exhaust system. Test drive after to Shop Supplies 1.00 verify fix. - Shop Supplies Hours: 3.00 Comm: 0.00 Labor: 219.00 Parts: 218.47 Total: 437.47

1/13/2025 9:45:12 AM				ient Asset Maintenan y, 13,300 Gvwr, Mediu		ane		
Vork Order: Problem:	2406931 Tow- Transport from Hagen F	Meter: 229 Ranch Road Plant to		urbo leaks / CEL blinki	In Date: ng	07/08/2024	Closed:	07/18/2024
Work Com	pleted							
	n: 12751 Hagen Ranch Rd, Boy Beach 33446	nton Beach 33437 To	o: 13026 S Jog					
	Hours: 0.00	Cor	nm: 124.30	Labor: 0.00	Parts: 0.0	0	Total:	124.30
Vork Order: Problem:	2409686 PM. Broke Down. Rear view r	<b>Meter:</b> 248 mirror. utility box beh		ng latch	In Date:	10/04/2024	Closed:	12/11/2024
Work Com	pleted			Parts Issued			Qı	antity
- Preventiv	ve Maint. Service			sensor				1.00
- Diagnose	e no start, fund fuel pressure re	gulator, remove left	fender well &	Regulador				1.00
replace fue	l pressure regulator.	-		Starter Assy				1.00
- Replace	burnt out starter motor.			Shop Supplies				1.00
- Shop Sup	oplies							
	Hours: 3.50	Cor	nm: 0.00	Labor: 255.50	Parts: 570	).30	Total:	825.80
Vork Order:		<b>Meter:</b> 248	,58		In Date:	10/04/2024	Closed:	11/19/2024
Problem: Work Com	Tow- Transport to SR shop fo	or dreakdown repair						
Work Com	npleted n: 17901 S State Road 7, Boca I	·	26 S Jog Rd,					
Work Com - Tow Fror	npleted n: 17901 S State Road 7, Boca I	Raton 33498 To: 130	26 S Jog Rd, mm: <b>118.80</b>	Labor: 0.00	Parts: 0.00	0	Total:	118.80
Work Com - Tow Fror Delray Bea Vork Order:	npleted n: 17901 S State Road 7, Boca I ch 33446 Hours: 0.00	Raton 33498 To: 130	nm: 118.80	Labor: 0.00	Parts: 0.00	0 12/10/2024		
Work Com - Tow Fror Delray Bea Vork Order:	n: 17901 S State Road 7, Boca I ch 33446 Hours: 0.00 2411662 Transition Prep Charge	Raton 33498 To: 130 Cor	nm: 118.80	Labor: 0.00				
Work Com - Tow Fror Delray Bead Vork Order: Problem: Work Com	n: 17901 S State Road 7, Boca I ch 33446 Hours: 0.00 2411662 Transition Prep Charge	Raton 33498 To: 130 Cor	nm: 118.80	Labor: 0.00				

1/13/2025 9:45:12 AM								
Work Order: Problem:	2411925 Tow-Transport f	Meter: from SR shop to			In Date:	12/04/2024 (	losed:	12/17/2024
Work Com	pleted							
- Tow Fron Palm Beach	5	d, Delray Beach	33446 To: 2601 Vista Pl	xwy, West				
	Hours:	0.00	Comm: 118.80	Labor: 0.00	Parts: 0.00	)	Total:	118.80
Total Hours: 3	354.50	Total Labor: 23	3,314.75	Total Comm: 2,58	5.27	Total Parts: 1	7,642.88	1