Palm Beach County Fleet Management Asset Maintenance History 10203795 2017 FORD F250 Utility Body, 3/4 Ton, Crew Cab

Total Hours:	75.75	Labor: 5,256	.75	Parts: 3,546.49	Comm: 0.00	Charged: 8803.24			
Work Order: Problem:)4 Pre Delivery In:	Meter: spection	331		In Date:	10/20/2017	Closed:	10/20/2017
Work Com	npleted								
- Pre Deliv	very Insp	ection							
		Hours: 3.00		Comm: 0.00	Labor: 180.00	Parts: 0.0	0	Total:	180.00
Work Order: Problem:		33 ce light bar	Meter:	338		In Date:	11/30/2017	Closed:	12/08/2017
Work Com	npleted				Parts Issued			Qı	ıantity
- Fab and	install b	rackes for lifth b	ar being	loose	Clr Rtv Silcn Sealant				1.00
- Shop Su			J		Gray Sea				1.00
					Bumper Black				1.00
					Glos Blk				1.00
					Shop Supplies				1.00
		Hours: 7.50		Comm: 0.00	Labor: 450.00	Parts: 32.	83	Total:	482.83
Work Order: Problem:			Meter: gnition po	339 ower at the fuse box.		In Date:	12/08/2017	Closed:	12/18/2017
Work Com	npleted				Parts Issued			Qı	ıantity
- Install igi	nition ar	nd battery source	e to radi	0.	Micro Add A Circuit				2.00
- Shop Su		,			Shop Supplies				1.00
		Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 44.	21	Total:	104.21
Work Order: Problem:			Meter:	920		In Date:	02/08/2018	Closed:	02/15/2018
Work Com	npleted				Parts Issued			Qı	ıantity
- Battery fa	ailed loa	d test. Replace	battery.		Battery				1.00
- Shop Su		•	•		Shop Supplies				1.00
		Hours: 1.00		Comm: 0.00	Labor: 60.00	Parts: 130	0.64	Total:	190.64

Hours: 5.50

Palm Beach County Fleet Management Asset Maintenance History 10203795 2017 FORD F250 Utility Body, 3/4 Ton, Crew Cab

Work Order: Problem:	1806185 Pm service.	Meter:	2305		In Date:	06/18/2018	Closed:	06/19/2018
Work Com	pleted			Parts Issued			Q	uantity
- Pm servic	ce.			Napagold Oil Filter				1.00
- Rotate ar	nd balance tires.			Napa Quart 5w30				7.00
- Test drive	<u>e</u> .			22" Wiper Blade				2.00
- Shop Sup	pplies			Washer Fluid Concer	ntr			1.00
				Shop Supplies				1.00
	Hours: 5.50		Comm: 0.00	Labor: 330.00	Parts: 42.	.10	Total:	372.10
Work Order: Problem:	1902586 Pm service.	Meter:	5029		In Date:	03/07/2019	Closed:	03/13/2019
Work Com	pleted			Parts Issued			Q	uantity
- Pm servic	ce.			Napa Quart 5w30				7.00
- Wash vel	nicle.			Napagold Oil Filter				1.00
- Rotate ar	nd balance tires.			Washer Fluid Concer	ntr			1.00
- Test drive	<u>.</u>			22" Wiper Blade				2.00
- Shop Sup	oplies			Shop Supplies				1.00
	Hours: 6.50		Comm: 0.00	Labor: 435.50	Parts: 43.	.98	Total:	479.48
Work Order: Problem:	1912299 Pm service.	Meter:	7997		In Date:	12/02/2019	Closed:	12/05/2019
Work Com	pleted			Parts Issued			Q	uantity
- Pm servic	ce.			Napagold Oil Filter				1.00
- Rotate ar	nd balance tires.			Napa Quart 5w30				7.00
- Test drive	e.			Air Fltr				1.00
- Shop Sup	pplies			22" Wiper Blade				2.00
	•			Washer Fluid Concer	ntr			1.00
				Shop Supplies				1.00

Comm: 0.00

Labor: 401.50

Parts: 74.38

Total: 475.88

Palm Beach County Fleet Management Asset Maintenance History 10203795 2017 FORD F250 Utility Body, 3/4 Ton, Crew Cab

Work Order: 2004966 Problem: Pm service.	Meter: 9619	In Date: 05/18/20	020 Closed : 05/19/2020
Work Completed		Parts Issued	Quantity
- Pm service.		Napagold Oil Filter	1.00
- Replace a/c filter.		Napa Quart 5w30	7.00
- Rotate and balance tires.		Air Fltr	1.00
- Test drive.		Washer Fluid Concentr	1.00
- Shop Supplies		22" Wiper Blade	2.00
		Cabin Air Filter	1.00
		Shop Supplies	1.00
Hours: 6.50	Comm: 0.00	Labor: 474.50 Parts: 88.26	Total: 562.76

Work Order: 2006504 Meter: 9977 In Date: 06/30/2020 Closed: 07/06/2020

Problem: Slow crank

Work Completed		Parts Issued		Quantity
- Battery failed load test. Replace battery		Battery		1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 147.81	Total: 220.81

Work Order: 2010704 Meter: 11246 In Date: 10/26/2020 Closed: 11/02/2020

Problem: Fabricate lock hasp for sliding bed cover.

Work Completed		Parts Issued		Qua	antity
- Accessories / Attachments fab lock hasp on rol	ling lock bed cover	Eye Hasp Steel 6in	l		1.00
- rear doo lock knobs missing		Knobs			2.00
- Shop Supplies		Shop Supplies			1.00
Hours: 4.00	Comm: 0.00	Labor: 292.00	Parts: 21.46	Total: 3	313.46

Palm Beach County Fleet Management Asset Maintenance History 10203795 2017 FORD F250 Utility Body, 3/4 Ton, Crew Cab

Work Order: 2012828 Meter: 11879 In Date: 12/28/2020 Closed: 01/07/2021

Problem: pm service

Work Completed		Parts Issued		Quantity
- Preventive Maint. Service		22" Wiper Blade		2.00
- changed a/c filter and inspected evap case		Washer Fluid Cond	centr	1.00
- balance and rotate all 4 tires		Napa Quart 5w30		7.00
- road test		Napagold Oil Filte	r	1.00
- replaced missing vise handle		Air Fltr		1.00
- replaced missing hitch pin		Cabin Filter		1.00
- Shop Supplies		ridgid vise handle		1.00
		Pin W/clip 5/8 For	Hitch	1.00
		Pintle Pin W/clip		1.00
		Shop Supplies		1.00
Hours: 6.25	Comm: 0.00	Labor: 456.25	Parts: 191.23	Total: 647.48

Work Order: 2104819 Meter: 13114 In Date: 04/29/2021 Closed:

Problem: screw in driver side front tire

Work Completed

- Tire Repair

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

Palm Beach County Fleet Management Asset Maintenance History 10203795 2017 FORD F250 Utility Body, 3/4 Ton, Crew Cab

Work Order: 2201630 Meter: 16967 In Date: 02/14/2022 Closed: 02/23/2022

Problem: pm service

Work Completed		Parts Issued	Quantity	
- Preventive Maint. Service- replaced all 4 tires at 4/32nds- replaced cabin filter and cleaned evap		Napa Quart 5w30		7.00
		Napagold Oil Filte	r	1.00
		Washer Fluid Cond	centr	1.00
- test drive	22" Wiper Blade		2.00	
- hood prop shocks bad replaced		Air Filter		1.00
- Shop Supplies		Lt245/75r17 Mich	4.00	
		Cabin Air Filter		1.00
		Tire Sensor		1.00
	Lift Support			1.00
		Lift Support Shop Supplies Tire Disposal Fee		1.00
				1.00
				4.00
Hours: 7.25	Comm: 0.00	Labor: 529.25	Parts: 1,066.65	Total: 1,595.90

Work Order: 2203961 Meter: 17557 In Date: 04/13/2022 Closed: 04/14/2022

Problem: hard to crank

Work Completed		Parts Issued		Quantity
- battery failed load test replaced battery		Battery		1.00
- Shop Supplies		Shop Supplies		1.00
Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 119.98	Total: 192.98

Palm Beach County Fleet Management Asset Maintenance History 10203795 2017 FORD F250 Utility Body, 3/4 Ton, Crew Cab

Work Order: 2303284 Meter: 21808 In Date: 04/03/2023 Closed: 04/17/2023

Problem: PM Service.

Work Completed		Parts Issued		Quantity
- Preventive Maintenance Service		Napagold Oil Filte	r	1.00
- Check engine light on, random miss firers.	Napa Quart 5w30		7.00	
- Replaced shorted rear led tail/brake light assen	22" Wiper Blade		2.00	
- Replaced cabin air filter	Washer Fluid Cond	centr	1.00	
- Rotate tires		Air Fltr		1.00
- Replace missing vise handle		Spark Plug	16.00	
- Patched and balanced left front tire.		Spark Plug Wire		8.00
- Shop Supplies		Coil	4.00	
		Coil Asy		4.00
		Stop/turn/tail Led	Light (red)	2.00
		Cabin Air Filter		1.00
		ridgid vise handle		1.00
		Shop Supplies		1.00
Hours: 9.75	Comm: 0.00	Labor: 711.75	Parts: 1,306.25	Total: 2,018.00

Work Order: 2309579 Meter: 24126 In Date: 09/20/2023 Closed: 10/02/2023

Problem: light bar not flashing.No power.

Work Completed	Parts Issued	Quantity
- Check fuses and wiring. Found individual lights work, but all light do	pes not. Air Fltr	1.00
R/r Cb radio speaker and light control box. Inspect internal control bo	5.10 p cappines	1.00
wiring and found no power coming from switch. R/r switch and clean	switch	
contacts.		

- Air filter warp.wet and folded.r/r air filter.

- Shop Supplies

Hours: 1.50 Comm: 0.00 Labor: 109.50 Parts: 23.64 Total: 133.14

Palm Beach County Fleet Management Asset Maintenance History 10203795 2017 FORD F250 Utility Body, 3/4 Ton, Crew Cab

Work Order: Problem:	2311473 Met o PM Service.Bad battery,has	er: 25219		In Date:	11/16/2023	Closed:	12/14/2023
Work Com	·	to jump dart all the time.	Parts Issued			Oı	ıantity
•	e Maint. Service		Washer Fluid Concer	ntr		4.	1.00
			Wiper Blade				2.00
- replaced	cabin filter		Napa Quart 5w30				7.00
- test drive			· ·				
- rotate and	d balance		Napagold Oil Filter				1.00
- load teste	ed battery passed no probler	n found	Air Fltr				1.00
- Shop Sup	plies		Cabin Air Filter				1.00
			Shop Supplies				1.00
	Hours: 5.50	Comm: 0.00	Labor: 401.50	Parts: 80.	.12	Total:	481.62
Work Order: Problem:	2400303 Met owill not start.	er: 25657		In Date:	01/10/2024	Closed:	01/31/2024
Work Com	pleted		Parts Issued			Qı	ıantity
- Charge ar	nd load test battery, it failed.	Installed new battery and test	Battery				1.00
charging sy	tem.	•	Shop Supplies				1.00
- no work c	done						
- Shop Sup	plies						
	Hours: 1.00	Comm: 0.00	Labor: 73.00	Parts: 132	2.98	Total:	205.98
Work Order: Problem:	2408768 Met o Transition Prep Charge	er: 30053		In Date:	09/11/2024	Closed:	09/11/2024
Work Com	pleted						
- Transition	Prep Charge						
	Hours: 2.00	Comm: 0.00	Labor: 146.00	Parts: 0.0	00	Total:	146.00

Total Hours: 75.75 Total Labor: 5,256.75 Total Comm: 0.00 Total Parts: 3,546.49