

3/27/2017
3:55:10PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171052 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Workorder: 746383

Problem: PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts
In Date: 10/29/2007	Hours	Description
Close Date: 10/29/2007	Quantity	
- Pre-Delivery Inspection	2.00	
Parts Charge: 0.00	Labor Charge: 120.00	

Workorder: 834011

Problem: P.M SERVICE,NAIL IN R/R TIRE

Meter Reading: 4530	Labor	Parts
In Date: 02/11/2008	Hours	Description
Close Date: 02/19/2008	Quantity	
- Pm Service	3.75	SHOP SUPPLIES 1.00
- Repair Nail Hole In FI Tire.		5W20 ENGINE OIL 7.00
- Shop Supplies		FUEL FILTER 1.00
		10003 INJECTOR CLEANER DON'T REORDER 1.00
		1372 OIL FILTER FRM PH2 WIX 51372 1.00
Parts Charge: 45.94	Labor Charge: 60.00	

Workorder: 841567

Problem: P.M SERVICE

Meter Reading: 12845	Labor	Parts
In Date: 07/17/2008	Hours	Description
Close Date: 07/21/2008	Quantity	
- Pm Service	3.75	SHOP SUPPLIES 1.00
- Rotate & High Speed Balance All 4 Tires.Nitro Fill Tires.		1372 OIL FILTER FRM PH2 WIX 51372 1.00
- Shop Supplies		G10166 FUEL FILTER MTC FG1083 WIX 33243 1.00
		CA10262 AIR FILTER MTC FA1883 WIX 49883 1.00
		BIG G DEGREASER STOCK# 485180002 1.00
		5W20 ENGINE OIL 7.00
		31-20 WIPER BLADES 20" BLADE 2.00
Parts Charge: 70.45	Labor Charge: 60.00	

3/27/2017
3:55:10PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171052 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Workorder: 847919

Problem: P.M SERVICE

Meter Reading: 18415	Labor	Parts	
In Date: 12/08/2008	Hours	Description	Quantity
- Pm Service	4.75	G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
- Mount 2 New Front Tires.Balance All 4 Nitro Fill		TIRE DISPOSAL FEE	2.00
- Shop Supplies		TR416 VALVE STEM	2.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		SHOP SUPPLIES	1.00
		TIRE	2.00
		5W20 ENGINE OIL	7.00
		31-20 WIPER BLADES 20" BLADE	2.00
Parts Charge: 457.86	Labor Charge: 120.00		

Workorder: 937881

Problem: INSTALL CUSTOMERS COMP STAND

Meter Reading: 19926	Labor	Parts	
In Date: 05/18/2009	Hours	Description	Quantity
- Fabricate And Install Computer Stand. Wire In Electrical Harness.	4.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00	Labor Charge: 240.00		

Workorder: 943441

Problem: Check brake lights.

Meter Reading: 22842	Labor	Parts	
In Date: 09/18/2009	Hours	Description	Quantity
- Test & Replace R/R Brake Light Bulb.	0.50	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00	Labor Charge: 30.00		

3/27/2017
3:55:10PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171052 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Workorder: 943914

Problem: pm service also see notes on battery and tires

Meter Reading: 23061	Labor	Parts	
In Date: 09/30/2009	Hours	Description	Quantity
- P.M. Service.	6.25	FLOOR MAT SET	1.00
- Install Floor Mats.		SHOP SUPPLIES	1.00
- Test Battery And Charging System.Battery Failed Load		GROUP 65 BATTERY (MTC BXT-65-850)	1.00
- Test After Charge.Replace Defective Battery.		179636492 LT245/75R17 WRANGLER SR-A E	2.00
- Replace Two Tires,Rotate And Balance All Four.Nitro Fill.		TIRE DISPOSAL FEE	2.00
- Shop Supplies		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		5W20 ENGINE OIL	7.00
		CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
		TR416 VALVE STEM	2.00
Parts Charge:	582.83	Labor Charge:	375.00

Workorder: 1003349

Problem: P.M service.

Meter Reading: 27543	Labor	Parts	
In Date: 04/01/2010	Hours	Description	Quantity
- P.M Service.	3.55	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Replace Broken Tail Gate Cap.		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
- Test & Replace R/R Turn Signal Bulb & Third Brake Light		5W20 ENGINE OIL	7.00
- Bulb.		31-20 WIPER BLADES 20" BLADE	2.00
- Shop Supplies		3157 TAIL LIGHT BULBS	1.00
		SHOP SUPPLIES	1.00
		TAILGATE CAP	1.00
Parts Charge:	86.08	Labor Charge:	213.00

3/27/2017
3:55:10PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171052 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Workorder: 1010640

Problem: Pm service,also see notes on tires.

Meter Reading: 33273	Labor	Parts	
In Date: 09/28/2010	Hours	Description	Quantity
- P.M. Service.	7.75	5W20 ENGINE OIL	7.00
- Replace R/R Parking Light Bulb.		CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
- Replace And Balance All Four Tires.		D3TZ2457B BRAKE PEDAL PAD	1.00
- Complete Wheel Alignment.Test Drive.		CUSTOM5LB BRACKET FIREX STOCK #340060300	1.00
- Shop Supplies		3157 TAIL LIGHT BULBS	1.00
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		179636492 LT245/75R17 WRANGLER SR-A E	4.00
		TR416 VALVE STEM	4.00
		1401 BRAKE FLUID BRAKE FLUID	1.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		TIRE DISPOSAL FEE	4.00
		SHOP SUPPLIES	1.00
		31-20 WIPER BLADES 20" BLADE	2.00
Parts Charge:	833.96	Labor Charge:	465.00

Workorder: 1107218

Problem: Pm service and has to jump start in the am

Meter Reading: 39897	Labor	Parts	
In Date: 07/08/2011	Hours	Description	Quantity
- Perform Pm Service.	6.25	LH A/C VENT	1.00
- Remove Driver Door Trim.Inspect And Replace Failed		SHOP SUPPLIES	1.00
Driver Door Stop With New.Also Inspect And Replace		1372 OIL FILTER FRM PH2 WIX 51372	1.00
Failed Left Side Ac Vent Outlet With New.		5W20 ENGINE OIL	7.00
- Test Starting And Charging System.Battery Failed Load		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
Test After Recharge.Replace Failed Battery With New.		LH DOOR CHECK	1.00
- Rotate And Balance All Four Tires.		31-20 WIPER BLADES 20" BLADE	2.00
- Shop Supplies		GROUP 65 BATTERY (MTC BXT-65-850)	1.00
		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
Parts Charge:	258.28	Labor Charge:	375.00

3/27/2017
3:55:10PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171052 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Workorder: 1110449

Problem: PASSENGER BRAKE LIGHT INOP

Meter Reading: 41496	Labor	Parts	
In Date: 09/30/2011	Hours	Description	Quantity
- Repair R/Rear Brake Light.	0.50	3157 TAIL LIGHT BULBS	1.00
Parts Charge: 0.83	Labor Charge: 30.00		

Workorder: 1201425

Problem: P.M. service and low tire pressure light on.

Meter Reading: 45550	Labor	Parts	
In Date: 02/13/2012	Hours	Description	Quantity
- P.M. Service.	11.75	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Replace And Balance Four Tires.		31-20 WIPER BLADES 20" BLADE	2.00
- Resurface Front Rotors,Replace Brake Pads.Service And		5W20 ENGINE OIL	7.00
Lube Calipers.Flush And Bleed System.		TIRE DISPOSAL FEE	4.00
- Complete Wheel Alignment.Test Drive.		179636492 LT245/75R17 WRANGLER SR-A E	4.00
- Shop Supplies		2232 BRAKE FLUID QUART	1.00
		BL1 BRAKE LUBE (BENDIX)	1.00
		SHOP SUPPLIES	1.00
		TR416 VALVE STEM	4.00
		MKD1333 FRONT PADS	1.00
Parts Charge: 862.33	Labor Charge: 705.00		

Workorder: 1201990

Problem: Runing rough,shaking.

Meter Reading: 45579	Labor	Parts	
In Date: 02/28/2012	Hours	Description	Quantity
- Scan Computer System For Codes.P0148,P0191.	5.00	SHOP SUPPLIES	1.00
Perform Fuel Pressure Test.Remove Fuel Tank And		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
Replace Fuel Pump Assemble.Perform Pcm Update With		FUEL PUMP	1.00
New Calibration.		PUMP GASKET	1.00
- Shop Supplies			
Parts Charge: 434.56	Labor Charge: 300.00		

3/27/2017
3:55:10PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171052 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Workorder: 1206810

Problem: pm, aux cig lighter for computer

Meter Reading: 50677	Labor	Parts	
In Date: 07/20/2012	Hours	Description	Quantity
- Pm	9.00	G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
- Ck Engine Light Is On Verify Concern Scan And Found Code Po300, Po316, Po303 Po304 Perform Pinpoint Test And Found Bad Coils Replace Coul #3,7,4, Replace 8 Spark Plug Clear Codes		SHOP SUPPLIES	1.00
		SPARK PLUGS	8.00
		IGN. COIL	3.00
		31-20 WIPER BLADES 20" BLADE	2.00
- Test Drive 50 Miles		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Cs Power Outlet Not Working Perform Pinpoint Test And Found Blown Fuse Replace Fuse		5W20 ENGINE OIL	7.00
- Replace Light Bulb For Utility Bed Light		CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
- Shop Supplies		1372 OIL FILTER FRM PH2 WIX 51372	1.00
Parts Charge: 378.12		Labor Charge: 540.00	

Workorder: 1208136

Problem: engine light , running rough

Meter Reading: 51747	Labor	Parts	
In Date: 08/29/2012	Hours	Description	Quantity
- Ck Engine Ligh Tin On Verify Concern Scan And Found Code Po316, Po303 Perform Pinpoint Test Found Water In Spark Plug Hole #2 & 3 Clean Plug Holes Replace 5 Oil Pack Clear Code And Test Drive	10.00	SL4 DIELECTRIC GREASE	1.00
		IGN. COIL	5.00
		SHOP SUPPLIES	1.00
- After Replacing Coil And Test Drive Engine Still Have Random Misfire On Bank 1 Perform Pinpoint Test And Found Bad Cat. Send To Dealer To Replace Cat Under Warranty			
- Transport Pick Up Vehicle At Dealer For Defective Cat Converter Warranty Replace			
- Shop Supplies			
Parts Charge: 349.63		Labor Charge: 600.00	

3/27/2017
3:55:10PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171052 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Workorder: 1301196

Problem: pm, driver window broken,brake lights out

Meter Reading: 56430		Labor		Parts	
In Date: 02/01/2013	Close Date: 02/21/2013	Hours	Description		Quantity
-	Pm	7.25	SHOP SUPPLIES		1.00
-	Replace Left Rear Brake Light Bulb		31-20 WIPER BLADES 20		2.00
-	Replace 2 Rer Tires And Rotate To The Front		TIRE DISPOSAL FEE		2.00
-	Replace Left Front Window Track		1372 OIL FILTER		1.00
-	Fill New Tires With Nitrogen		MINIATURE BULB		1.00
-	Shop Supplies		179636492 LT245-75R17		2.00
			LF WINDOW TRUCK RUN		1.00
			NAPA QUART 5W20		7.00
Parts Charge: 685.72		Labor Charge: 435.00			

Workorder: 1304264

Problem: winch out

Meter Reading: 58572		Labor		Parts	
In Date: 04/29/2013	Close Date: 04/30/2013	Hours	Description		Quantity
-	Tow From: 2956 Pinehurst Water Plant To: Winch Out				
Parts Charge: 0.00		Labor Charge: 0.00			

Workorder: 1401909

Problem: pm, cargo light out , tires

Meter Reading: 66829		Labor		Parts	
In Date: 02/27/2014	Close Date: 03/11/2014	Hours	Description		Quantity
-	Pm	10.75	BULB		1.00
-	Replace Dome Light Bulb Replace Left Utility Bed Light		179636492 LT245-75R17		2.00
-	Replace Both Rear Tires And Rotate To The Front		BATTERY 65		1.00
-	Ck And Replace Bad Battery		TIRE DISPOSAL FEE		2.00
-	Remove Drive Shaft Resurface Rear Rotors Svc Calipers		SHOP SUPPLIES		1.00
-	And Replace Pads		BRAKE PAD		1.00
-	Shop Supplies		NAPA QUART 5W20		7.00
			NAPAGOLD AIR FILTER		1.00
			NAPAGOLD OIL FILTER		1.00
			WASHER FL		1.00
			NAPAGOLD FUEL FILTER		1.00
Parts Charge: 776.82		Labor Charge: 645.00			

3/27/2017
3:55:10PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171052 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Workorder: 1409412 **Problem:** BATTERY DEAD

Meter Reading: 71944	Labor	Parts
In Date: 09/19/2014	Hours	Description
Close Date: 09/22/2014		Quantity
- Recharge Battery Ck Charging Sys Ck Battery And Found Computer Charger Left On Unplug Charger	0.75	
Parts Charge:	0.00	Labor Charge: 45.00

Workorder: 1409535 **Problem:** PM, CK TIRES , ADJ HEAD LIGHS

Meter Reading: 71983	Labor	Parts
In Date: 09/23/2014	Hours	Description
Close Date: 09/29/2014		Quantity
- Pm	6.75	NAPAGOLD OIL FILTER
- Repair And Adj Both Front Head Lights		USED FIRE X REFURBISHED
- Replace Both Rear Tires And Rotate To The Front		NAPA QUART 5W20
- Shop Supplies		179636492 LT245-75R17
		WIPER BLADE
		HALOGEN LAMP
		WASHER FL
		SHOP SUPPLIES
		TIRE DISPOSAL FEE
Parts Charge:	613.26	Labor Charge: 405.00

Workorder: 1410261 **Problem:** R/REAR BRAKE LIGHT INOP.

Meter Reading: 72405	Labor	Parts
In Date: 10/14/2014	Hours	Description
Close Date: 10/21/2014		Quantity
- Repair Right Rear Brake Light	0.50	BULB
Parts Charge:	0.75	Labor Charge: 30.00

Workorder: 1411988 **Problem:** poassenger rear tire slow leak

Meter Reading: 73545	Labor	Parts
In Date: 12/01/2014	Hours	Description
Close Date: 12/04/2014		Quantity
- Ck Right Rear Tire Flat Dismount Patch Mount Balance Add N2	1.00	SHOP SUPPLIES
- Shop Supplies		
Parts Charge:	2.00	Labor Charge: 60.00

3/27/2017
3:55:10PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171052 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Workorder: 1504163

Problem: p.m.service

Meter Reading: 76747	Labor	Parts	
In Date: 04/22/2015	Hours	Description	Quantity
- Pm	2.75	NAPAGOLD FUEL FILTER	1.00
- Shop Supplies		NAPAGOLD OIL FILTER	1.00
		SHOP SUPPLIES	1.00
		NAPA QUART 5W20	8.00
Parts Charge:	41.67	Labor Charge:	165.00

Workorder: 1510187

Problem: passenger brake light out

Meter Reading: 81098	Labor	Parts	
In Date: 10/07/2015	Hours	Description	Quantity
- Repair Right Rear Light	0.50	BULB	1.00
Parts Charge:	0.75	Labor Charge:	30.00

Workorder: 1512021

Problem: pm, low tire pressure

Meter Reading: 82171	Labor	Parts	
In Date: 11/30/2015	Hours	Description	Quantity
- Pm	5.50	NAPA QUART 5W20	8.00
- Verify Needs W Tires Mount Balance Add N2		WASHER FLUID CONCENTR	1.00
- Ck Tpms Light On Found Nail In Thire Repair Reset Tpms Light		NAPAGOLD AIR FILTER	1.00
		SHOP SUPPLIES	1.00
- Replace 3Rd Brake Light		179636492 LT245-75R17	2.00
- Shop Supplies		NAPAGOLD OIL FILTER	1.00
		TIRE DISPOSAL FEE	2.00
		20" WIPER BLADE	2.00
Parts Charge:	577.54	Labor Charge:	330.00

Workorder: 1602718

Problem: r/rear brake light inop

Meter Reading: 84476	Labor	Parts	
In Date: 03/15/2016	Hours	Description	Quantity
- Rr Bulb	0.50	BULB	1.00
Parts Charge:	0.78	Labor Charge:	30.00

3/27/2017
3:55:10PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171052 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Workorder: 1606861

Problem: Pm service.Has to jump start.

Meter Reading: 86895	Labor	Parts	
In Date: 07/07/2016	Hours	Description	
Close Date: 07/18/2016		Quantity	
- Pm Service	6.25	NAPAGOLD OIL FILTER	1.00
- Replace Bad Battery.		NAPA QUART 5W20	8.00
- Repair Left Rear Tire.Replace Right Rear Tire.Balance And		20" WIPER BLADE	2.00
Rotate All.Reset Tpms.		WASHER FLUID CONCENTR	1.00
- Shop Supplies		NAPAGOLD FUEL FILTER	1.00
		USED FIRE X REFURBISHED	1.00
		SHOP SUPPLIES	1.00
		TIRE DISPOSAL FEE	1.00
		179636492 LT245-75R17	1.00
		BATTERY	1.00
Parts Charge:	440.80	Labor Charge:	375.00

Workorder: 1610472

Problem: Dead battery.Had to jump start in WUD parking lot.TPMS light on.

Meter Reading: 89317	Labor	Parts	
In Date: 10/11/2016	Hours	Description	
Close Date: 10/18/2016		Quantity	
- Test And Replace Defective Left Front Wheel Tire	1.75	SHOP SUPPLIES	1.00
Pressure Sensor And Balance.		SENSOR BAND	1.00
- Jump Start Vehicle In Wud Parking Lot.Fully Recharge		TIRE PRESSURE SENSOR	1.00
And Test Battery,Starting And Charging System.			
- Shop Supplies			
Parts Charge:	172.71	Labor Charge:	105.00

Workorder: 1611523

Problem: Power outlet inop.

Meter Reading: 90089	Labor	Parts	
In Date: 11/08/2016	Hours	Description	
Close Date: 11/21/2016		Quantity	
- Test And Replace Two Open 20 Amp Fuses.	1.00	FMX-20 FUSE	2.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	11.30	Labor Charge:	60.00

3/27/2017
3:55:10PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171052 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

Workorder: 1613198

Problem: Pm Service.Check shock and brake light.

Meter Reading: 91001 In Date: 12/29/2016	Close Date: 01/17/2017	Labor Hours	Description	Parts	Quantity
- Pm Service.		11.00	NAPA QUART 5W20		8.00
- Replace One Tire.Rotate And Balance All.Correct N2 Levels.			179636492 LT245-75R17 brake fluid		1.00 1.00
- Clean Sockets.Replace One Right Tail Light Bulb.			WASHER FLUID CONCENTR		1.00
- Replace Front Brake Pads.Turn Rotors.Service Calipers.			GAS GRANDE SHOCK		2.00
- Replace Rear Shocks.			NAPAGOLD OIL FILTER		1.00
- Shop Supplies			TIRE DISPOSAL FEE		1.00
			PADS		1.00
			SHOP SUPPLIES		1.00
			BULB		1.00
			20" WIPER BLADE		2.00
	Parts Charge: 482.64	Labor Charge: 660.00			

Workorder: 1701623

Problem: Transition Prep Charge

Meter Reading: 91239 In Date: 02/15/2017	Close Date: 02/15/2017	Labor Hours	Description	Parts	Quantity
- Transition Prep Charge		2.00			
	Parts Charge: 0.00	Labor Charge: 0.00			

Total Parts Charges:	8,171.61	Total Labor Charges:	7,608.00	Total Comm. Charges:	0.00
----------------------	-----------------	----------------------	-----------------	----------------------	-------------