

3/28/2025
1:22:40 PM

Palm Beach County Fleet Management Asset Maintenance History
10162806 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

Total Hours: 234.30 Labor: 15,038.75 Parts: 8,932.44 Comm: 2,026.92 Charged: 25998.11

Work Order: 639362 **Meter:** 0 **In Date:** 05/16/2006 **Closed:** 05/16/2006
Problem: PRE-DELIVERY INSPECTION

Work Completed

- Pre-delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 100.00 Parts: 0.00 Total: 100.00

Work Order: 639663 **Meter:** 0 **In Date:** 05/16/2006 **Closed:** 05/22/2006
Problem: 001 WASH TICKET ISSUED OUT 05/16/06

Work Completed

- 001 Wash Ticket Issued Out 05/16/06

Hours: 0.00 Comm: 7.14 Labor: 0.00 Parts: 0.00 Total: 7.14

Work Order: 640792 **Meter:** 192 **In Date:** 06/13/2006 **Closed:** 06/14/2006
Problem: INSTALL COMP. STAND

Work Completed

- Fabricate & Install Computer Stand And Cargo Next.

- Shop Supplies

Parts Issued	Quantity
Shop Supplies	1.00

Hours: 1.50 Comm: 0.00 Labor: 75.00 Parts: 2.00 Total: 77.00

Work Order: 734260 **Meter:** 1552 **In Date:** 02/13/2007 **Closed:** 02/16/2007
Problem: P.M SERVICE

Work Completed

- Perform Pm Service

- Nitrogen Fill All Tires.

- Shop Supplies

Parts Issued	Quantity
Shop Supplies	1.00
Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00
10w30 Motor Oil	5.00

Hours: 3.00 Comm: 0.00 Labor: 165.00 Parts: 16.70 Total: 181.70

Work Order: 739536 **Meter:** 0 **In Date:** 06/05/2007 **Closed:** 06/05/2007
Problem: 002 WASH TICKETS ISSUED OUT 06/05/07

Work Completed

- 002 Wash Tickets Issued Out 06/05/07

Hours: 0.00 Comm: 14.28 Labor: 0.00 Parts: 0.00 Total: 14.28

3/28/2025
1:22:40 PM

Palm Beach County Fleet Management Asset Maintenance History
10162806 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 1202855 **Meter:** 27402 **In Date:** 03/23/2012 **Closed:** 03/23/2012
Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 9.73 Labor: 0.00 Parts: 0.00 Total: 9.73

Work Order: 1208770 **Meter:** 31398 **In Date:** 09/14/2012 **Closed:** 09/27/2012
Problem: Pm service.

Work Completed

- P.m. Service.
- Service and adjust rear brakes.
- Rotate and balance all tires.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
Ph3387a Oil Filter Lbf Ph47 Wix 51040	1.00
10w30 Motor Oil	5.00
Used Firex Refurbed Fire Extingshers	1.00
31-22 Wiper Blades 22" Wiper Blade	2.00

Hours: 4.00 Comm: 0.00 Labor: 240.00 Parts: 40.54 Total: 280.54

Work Order: 1211048 **Meter:** 32574 **In Date:** 11/14/2012 **Closed:** 11/14/2012
Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 9.73 Labor: 0.00 Parts: 0.00 Total: 9.73

Work Order: 1302761 **Meter:** 35726 **In Date:** 03/20/2013 **Closed:** 03/28/2013
Problem: P.M. service.

Work Completed

- Perform pm service.
- Teast starting and charging system.battery failed loadtest after recharge.replace failed battery with new.
- Perform rear drum brake service and adjust brake shoes.
- Rotate and balance all four tires.
- Shop Supplies

Parts Issued

Quantity

10w30 Motor Oil	5.00
Oil Filter	1.00
Used Firex Refurbed F	1.00
31-22 Wiper Blades 22	2.00
Napagold Air Filter	1.00
Group 78 Acd	1.00
Shop Supplies	1.00

Hours: 5.00 Comm: 0.00 Labor: 300.00 Parts: 172.96 Total: 472.96

3/28/2025
1:22:41 PM

Palm Beach County Fleet Management Asset Maintenance History
10162806 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 1500915 **Meter:** 50169 **In Date:** 12/17/2014 **Closed:** 01/27/2015
Problem: damage to lft rear fender & bumper

Work Completed

- damage to lft rear fender & bumper

Hours: 0.00 Comm: 921.60 Labor: 0.00 Parts: 0.00 Total: 921.60

Work Order: 1506223 **Meter:** 52708 **In Date:** 06/22/2015 **Closed:** 07/06/2015
Problem: Pm service.

Work Completed

- Pm service.
- Perform transmission service.replace filter and gasket.flush and refill fluid.
- Perform engine tune up,replace spark plugs,wires,distributor cap and rotor.test drive.
- Rotate and balance four tires.
- Service rear brakes.
- Shop Supplies

Parts Issued

Quantity

Filter Kit	1.00
Wire Set	1.00
Distributor Cap	1.00
Rotor	1.00
10w30 Motor Oil	5.00
Napagold Oil Filter	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Filter Kit	1.00
Syn-atf Trans Fluid S	16.00
Spark Plug Asm	6.00
Shop Supplies	1.00

Hours: 9.50 Comm: 0.00 Labor: 570.00 Parts: 269.17 Total: 839.17

Work Order: 1509811 **Meter:** 53566 **In Date:** 09/28/2015 **Closed:** 09/28/2015
Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 9.54 Labor: 0.00 Parts: 0.00 Total: 9.54

3/28/2025
1:22:41 PM

Palm Beach County Fleet Management Asset Maintenance History
10162806 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 1707066

Meter: 70436

In Date: 07/19/2017 **Closed:** 07/27/2017

Problem: P.M.SERVICE

Work Completed

- Pm Service.
- Mount and balance 4 tires.
- Rear brake job.replace shoes,both wheel cylinders,cut drums,service backing plate, flush and blaad system
- Replace left rear taglamp.assy in bumper.
- Service trailer wire harness 6 way .clean corroded wires and lube connectors.

Parts Issued

Quantity

10w30 Bulk Sr	5.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
183114470 P245-70r17	4.00
Wheel Cylinder	2.00
B Fluid Dot 3-32oz	1.00
Non-chlor Brake Clnr	2.00
Reman Brake Shoes	1.00
Lamp	1.00
Tag Lamp	1.00
Tire Disposal Fee	4.00

Hours: 10.00

Comm: 0.00

Labor: 600.00

Parts: 1,158.28

Total: 1,758.28

3/28/2025
1:22:41 PM

Palm Beach County Fleet Management Asset Maintenance History
10162806 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 1800379 **Meter:** 74074 **In Date:** 01/10/2018 **Closed:** 01/31/2018
Problem: PM Service and check blower motor speeds inop.

Work Completed

- Pm Service.
- Replace ac blower motor,blower resistor and pig tail wiring due to overheated resistor wiring and connector.
- Tailgate handle and trim bezel replaced.
- Replace front brake pads and cut rotors.service calipers,mounts and slides.service rear brakes .flush and bleed system.
- Clean and vacume debris from air cowl.
- Rotate and balance four tires.

Parts Issued

Quantity

10w30 Bulk Sr	5.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Connector	1.00
Resistor	1.00
Blower Motor Assembly	1.00
Tail Gate Handle Bezel	2.00
Disc Brake Pads	1.00
Non-chlor Brake Clnr	1.00
B Fluid Dot 3-32oz	1.00
Blower Motor	1.00
Tailgate Handle	1.00

Hours: 13.75

Comm: 0.00

Labor: 825.00

Parts: 675.63

Total: 1,500.63

Work Order: 1805426 **Meter:** 75562 **In Date:** 05/29/2018 **Closed:** 05/31/2018
Problem: Overheating

Work Completed

- Pressure test and inspect cooling system and fan operation.run and roadtest vehicle,no problems found at this time cannot verify complaint.

Hours: 3.00

Comm: 0.00

Labor: 180.00

Parts: 0.00

Total: 180.00

3/28/2025
1:22:41 PM

Palm Beach County Fleet Management Asset Maintenance History
10162806 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 1808047 **Meter:** 75928 **In Date:** 08/06/2018 **Closed:** 08/27/2018
Problem: PM Service.

Work Completed

- Pm Service.
- Service rear brakes.
- Replace leaking washer bottle and pump.
- Rotate and balance tires.

Parts Issued

Quantity

Napagold Oil Filter	1.00
10w30 Bulk Sr	5.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Air Filter	1.00
Non-chlor Brake Clnr	1.00
Washer Container	1.00
grommet	1.00
Washer Pump	1.00

Hours: 4.75

Comm: 0.00

Labor: 285.00

Parts: 189.83

Total: 474.83

Work Order: 1810866 **Meter:** 76500 **In Date:** 10/22/2018 **Closed:** 10/29/2018
Problem: Tail lights inop.Right rear tire flat.

Work Completed

- Replace both tail lamp bulbs and repair sockets.
- Repair and balance right rear tire.

Parts Issued

Quantity

Boxed Miniatures	2.00
------------------	------

Hours: 1.75

Comm: 0.00

Labor: 117.25

Parts: 1.53

Total: 118.78

3/28/2025
1:22:41 PM

Palm Beach County Fleet Management Asset Maintenance History
10162806 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 1907374 **Meter:** 82843 **In Date:** 07/17/2019 **Closed:** 07/22/2019
Problem: PM Service

Work Completed

- Pm Service.
- Repaired both tail lamp assemblies.mounting tabs broken off.replace all new bulbs..fabricate new mounting tabs.
- Clean and adjust rear brakes.
- Rotate and balance four tires.
- Reattached headliner with spray glue.(falling off)

Hours: 6.50

Comm: 0.00

Parts Issued

	Quantity
Napagold Oil Filter	1.00
10w30 Bulk Sr	5.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Boxed Miniatures	6.00
Non-chlor Brake Clnr	1.00

Labor: 435.50

Parts: 33.30

Total: 468.80

Work Order: 1908980 **Meter:** 83375 **In Date:** 08/27/2019 **Closed:** 08/30/2019
Problem: Check engine light on.

Work Completed

- Check engine light is on.scan found code P0101,0170,p0174.perform pin point test and was unable to duplicate any problem at this time.clear codes.
- Test drive before and after repairs.

Hours: 3.00

Comm: 0.00

Labor: 201.00

Parts: 0.00

Total: 201.00

Work Order: 2001159 **Meter:** 84996 **In Date:** 02/03/2020 **Closed:** 03/23/2020
Problem: PM Service.Check engine light on.

Work Completed

- Pm Service
- Service rear brakes.
- Scan and found code # P0171 and P0174.perform pinpoint and found bad air flow meter.replace air flow meter.clear codes.
- Test drive before and after repair.

Hours: 7.00

Comm: 0.00

Parts Issued

	Quantity
10w30 Bulk Sr	5.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Napagold Air Filter	1.00
Non-chlor Brake Clnr	1.00
Air Flow Sensor Clnr	1.00
Massair Flow Sensor	1.00

Labor: 511.00

Parts: 189.05

Total: 700.05

3/28/2025
1:22:41 PM

Palm Beach County Fleet Management Asset Maintenance History
10162806 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 2009608 **Meter:** 87091 **In Date:** 09/24/2020 **Closed:** 10/21/2020
Problem: PM Service.Dead battery.

Work Completed

- Pm Service.
- Charge and test battery.replace battery.
- Rear brake service.
- Rotate and balance four tires.
- Wash vehicle.

Parts Issued

Quantity

Napagold Oil Filter	1.00
10w30 Bulk Sr	5.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Battery	1.00

Hours: 5.50

Comm: 0.00

Labor: 401.50

Parts: 166.35

Total: 567.85

Work Order: 2012594 **Meter:** 87615 **In Date:** 12/17/2020 **Closed:** 12/23/2020
Problem: Left front tire flat.

Work Completed

- inflate tire in wud parking lot repaired Lf tire patched and balanced

Hours: 1.50

Comm: 0.00

Labor: 109.50

Parts: 0.00

Total: 109.50

Work Order: 2103359 **Meter:** 88726 **In Date:** 03/25/2021 **Closed:** 03/30/2021
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Service rear brakes.
- Scan & found code p0455, perform evap system test & found bad fuel cap. replace fuel cap, clear codes and test drive.
- Repair right rear tire.

Parts Issued

Quantity

Napagold Oil Filter	1.00
10w30 Bulk Sr	5.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
Non-chlor Brake Clnr	1.00
Gas Cap Non-locking	1.00

Hours: 6.00

Comm: 0.00

Labor: 438.00

Parts: 55.02

Total: 493.02

3/28/2025
1:22:41 PM

Palm Beach County Fleet Management Asset Maintenance History
10162806 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 2112732 **Meter:** 89719 **In Date:** 12/01/2021 **Closed:** 12/14/2021
Problem: Rear bumper and left taillamp damage (See incident report)

Work Completed

- replaced rear bumper and transfer trim/parts
- replaced left tail lamp lens assembly

Parts Issued

Quantity

Tag Lamp	2.00
Lamp	1.00
Bumper Assy	1.00
Freight Charge	1.00

Hours: 3.00 Comm: 0.00 Labor: 219.00 Parts: 643.84 Total: 862.84

Work Order: 2203247 **Meter:** 91300 **In Date:** 03/25/2022 **Closed:** 04/07/2022
Problem: PM and Flat RF tire

Work Completed

- Preventive Maint. Service
- repaired right front tire (patched) rotate balanced 4 tires
- clean and adjust rear brakes
- R&r grill to clean and restore headlamps

Parts Issued

Quantity

22" Wiper Blade	2.00
10w30 Bulk Sr	5.00
Napagold Oil Filter	1.00

Hours: 6.50 Comm: 0.00 Labor: 474.50 Parts: 21.69 Total: 496.19

Work Order: 2209907 **Meter:** 91625 **In Date:** 09/23/2022 **Closed:** 09/27/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Service rear brake drums.
- Rotate, balance tires, correct Nitrogen levels to 35 Psi

Parts Issued

Quantity

10w30 Bulk Sr	5.00
Napagold Oil Filter	1.00

Hours: 4.00 Comm: 0.00 Labor: 292.00 Parts: 15.82 Total: 307.82

Work Order: 2210785 **Meter:** 91984 **In Date:** 10/21/2022 **Closed:** 10/25/2022
Problem: Battery

Work Completed

- Battery dead. Fully charge battery and load test. Battery failed load test. Replace battery with new and clean connections.

Parts Issued

Quantity

Battery	1.00
---------	------

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 113.32 Total: 186.32

3/28/2025
1:22:41 PM

Palm Beach County Fleet Management Asset Maintenance History
10162806 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 2310924 **Meter:** 97427 **In Date:** 10/30/2023 **Closed:** 11/08/2023
Problem: PM. Flat Tire. ABS light on

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Replace right rear tire, fill all tires with nitrogen, balance & rotate.
- Abs light was on, scan & found code C0040. Replace right front hub with Abs sensor, Service rear brakes & clear codes.
- Air bag light was on, scan & found code B0104, Replace right front air bag sensor & clear codes.

Napagold Oil Filter	1.00
Napa 10w30 Qt	6.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
245/70r17 Gy Wrkhrse Ht	1.00
Hub Sensor Assy	1.00
Air Bag Sensor	1.00
Tire Disposal Fee	1.00

Hours: 7.00

Comm: 0.00

Labor: 511.00

Parts: 663.93

Total: 1,174.93

Work Order: 2404856 **Meter:** 99355 **In Date:** 05/15/2024 **Closed:** 05/24/2024
Problem: pm service

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- rotate balanced tires
- Replaced left rear door handle On Door Jam

Napagold Oil Filter	1.00
10w30 Bulk Sr	5.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Door Handle	1.00

Hours: 3.50

Comm: 0.00

Labor: 255.50

Parts: 79.45

Total: 334.95

Work Order: 2407971 **Meter:** 100164 **In Date:** 08/19/2024 **Closed:** 08/21/2024
Problem: Overheating.

Work Completed

Parts Issued

Quantity

- Pressure test and inspect cooling system.found heater hose quick disconnect failed.r/r quick disconnect.and fill cooling system.road test and re-check.ok.

Peak Global Antifrz	2.00
Hose Connector	2.00

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 61.34

Total: 207.34

3/28/2025
1:22:41 PM

Palm Beach County Fleet Management Asset Maintenance History
10162806 2006 GMC 1500 Pickup, 1/2 Ton, W/Extended Cab

Work Order: 2410791 **Meter:** 100230 **In Date:** 11/08/2024 **Closed:** 11/22/2024
Problem: PM

Work Completed

- Preventive Maint. Service
- Fill tires with nitrogen, balance & rotate.

Parts Issued

Quantity

Napagold Oil Filter	1.00
10w30 Bulk Sr	5.00
Washer Fluid Concentr	1.00
Wiper Blade	1.00
Napagold Air Filter	1.00

Hours: 3.00 Comm: 0.00

Labor: 219.00 Parts: 34.57 Total: 253.57

Work Order: 2502099 **Meter:** 100230 **In Date:** 03/04/2025 **Closed:** 03/04/2025
Problem: transition

Work Completed

- Transition Charge

Hours: 2.00 Comm: 0.00

Labor: 146.00 Parts: 0.00 Total: 146.00

Work Order: 2502129 **Meter:** 100230 **In Date:** 03/04/2025 **Closed:**
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 0.00 Comm: 0.00

Labor: 0.00 Parts: 0.00 Total: 0.00

Total Hours: 234.30 Total Labor: 15,038.75 Total Comm: 2,026.92 Total Parts: 8,932.44