

3/28/2025
1:27:11 PM

10192682 Palm Beach County Fleet Management Asset Maintenance History
2014 INTERNATIONAL DURASTAR 4300 Wrecker, 38,000 GVWR, 26 Ft Tilt Ramp

Total Hours: 363.00 Labor: 24,987.00 Parts: 40,846.44 Comm: 916.56 Charged: 66750.00

Work Order: 1309967 **Meter:** 1608 **In Date:** 10/02/2013 **Closed:** 10/02/2013
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 6.00 Comm: 0.00 Labor: 360.00 Parts: 0.00 Total: 360.00

Work Order: 1404847 **Meter:** 3231 **In Date:** 05/16/2014 **Closed:** 05/22/2014
Problem: P.M.

Work Completed

- pm
- nitro 6 tires
- test run
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Napagold Oil Filter	1.00
Napagold Fuel Filter	1.00
Wiper Blade	2.00
2602212c1 Air Filter	1.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Mac Wite Lithium Gres	1.00
Shop Supplies	1.00

Hours: 8.00 Comm: 0.00 Labor: 480.00 Parts: 399.50 Total: 879.50

Work Order: 1410328 **Meter:** 4423 **In Date:** 10/03/2014 **Closed:** 10/15/2014
Problem: needs winch out

Work Completed

- Tow From: lox grove fire station

Hours: 0.00 Comm: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

3/28/2025
1:27:12 PM

10192682

Palm Beach County Fleet Management Asset Maintenance History
2014 INTERNATIONAL DURASTAR 4300 Wrecker, 38,000 GVWR, 26 Ft Tilt Ramp

Work Order: 1509748 **Meter:** 6258 **In Date:** 09/25/2015 **Closed:** 09/29/2015
Problem: PM

Work Completed

- pm
- road test
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Napagold Oil Filter	1.00
Fuel Fil	1.00
2602212c1 Air Filter	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 6.50

Comm: 0.00

Labor: 390.00 Parts: 321.35 Total: 711.35

Work Order: 1601297 **Meter:** 7028 **In Date:** 02/05/2016 **Closed:** 02/26/2016
Problem: PM / Winch

Work Completed

- Pm
- Service Ac
- Replace winch cable
- Test drive
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Napagold Oil Filter	1.00
Fuel Fil	1.00
2602212c1 Air Filter	1.00
22" Wiper Blade	2.00
Cabin Air Filter	1.00
7/16 Galv Cable F/rigg	1.00
Cx05-0145 Hook Latch	1.00
Shop Supplies	1.00

Hours: 9.00

Comm: 0.00

Labor: 540.00 Parts: 660.26 Total: 1,200.26

Work Order: 1605597 **Meter:** 7906 **In Date:** 05/31/2016 **Closed:** 06/06/2016
Problem: cable/winch

Work Completed

- connect cable to winch
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 60.00 Parts: 2.00 Total: 62.00

3/28/2025
1:27:12 PM

10192682

Palm Beach County Fleet Management Asset Maintenance History
2014 INTERNATIONAL DURASTAR 4300 Wrecker, 38,000 GVWR, 26 Ft Tilt Ramp

Work Order: 1704723
Problem: pm

Meter: 9750

In Date: 05/11/2017 **Closed:** 05/26/2017

Work Completed

- Pm
- Service air dryer
- Road test
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Napagold Oil Filter	1.00
Fuel Fil	1.00
2602212c1 Air Filter	1.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Wiper Blade	2.00
Ad Ip Dryer Cart	1.00
Shop Supplies	1.00

Hours: 7.50

Comm: 0.00

Labor: 450.00 Parts: 452.30 Total: 902.30

Work Order: 1800680
Problem: PM

Meter: 10925

In Date: 01/19/2018 **Closed:** 02/28/2018

Work Completed

- Pm
- Service winch
- Replace fire extinguisher
- Replace batteries
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Napagold Oil Filter	1.00
Filter	1.00
Wiper Blade	2.00
Macs Chain Cable Lube	1.00
Mac Wite Lithium Gres	1.00
Used Fire X Refurbished	1.00
Group 31 Stud Delco	2.00
hyd filter	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 10.50

Comm: 0.00

Labor: 630.00 Parts: 549.32 Total: 1,179.32

3/28/2025
1:27:12 PM

10192682

Palm Beach County Fleet Management Asset Maintenance History
2014 INTERNATIONAL DURASTAR 4300 Wrecker, 38,000 GVWR, 26 Ft Tilt Ramp

Work Order: 1903508 **Meter:** 13904 **In Date:** 04/01/2019 **Closed:** 04/15/2019
Problem: PM service

Work Completed

- Pm
- Pm Winch
- Replace exsingusher mount
- Service Ac
- Tested for coolant leaks. No leaks found. Erased coolant codes
- Test run
- Shop Supplies

Parts Issued

Quantity

Non-chlor Brake Clnr	3.00
15-40 Oil	30.00
Napagold Oil Filter	1.00
Air Fltr	1.00
Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
hyd filter	1.00
Fire Ext Mount Strap Style	1.00
Used Fire X Refurbished	1.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Shop Supplies	1.00

Hours: 12.50

Comm: 0.00

Labor: 837.50

Parts: 391.73

Total: 1,229.23

Work Order: 1905356 **Meter:** 14390 **In Date:** 05/17/2019 **Closed:** 05/20/2019
Problem: Coolant

Work Completed

- topp off coolant. replace faulty coolant level sensor
- check engine light. check and clear codes
- Shop Supplies

Parts Issued

Quantity

Level Sensor	1.00
Rotell Elc Antifeerze	2.00
Shop Supplies	1.00

Hours: 1.50

Comm: 0.00

Labor: 100.50

Parts: 85.98

Total: 186.48

Work Order: 1908500 **Meter:** 14913 **In Date:** 08/14/2019 **Closed:** 08/21/2019
Problem: Coolant

Work Completed

- add coolant check for leaks
- Shop Supplies

Parts Issued

Quantity

Rotell Elc Antifeerze	3.00
Shop Supplies	1.00

Hours: 1.00

Comm: 0.00

Labor: 67.00

Parts: 48.99

Total: 115.99

3/28/2025
1:27:12 PM

10192682

Palm Beach County Fleet Management Asset Maintenance History
2014 INTERNATIONAL DURASTAR 4300 Wrecker, 38,000 GVWR, 26 Ft Tilt Ramp

Work Order: 1909717
Problem: PM

Meter: 15000

In Date: 09/20/2019 **Closed:** 09/26/2019

Work Completed

- Pm
- Aps Pm
- Service Ac
- Condition fuel
- Test run
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	30.00
Air Fltr	1.00
Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Non-chlor Brake Clnr	3.00
hyd filter	1.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Motor Treatment Gal	1.00
Shop Supplies	1.00

Hours: 12.00

Comm: 0.00

Labor: 804.00

Parts: 444.38

Total: 1,248.38

Work Order: 1911539

Problem: Repair side box

Meter: 15125

In Date: 11/06/2019 **Closed:** 11/07/2019

Work Completed

- Repair side box latch
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 4.00

Total: 77.00

3/28/2025
1:27:12 PM

10192682

Palm Beach County Fleet Management Asset Maintenance History
2014 INTERNATIONAL DURASTAR 4300 Wrecker, 38,000 GVWR, 26 Ft Tilt Ramp

Work Order: 2002568
Problem: pm

Meter: 15615

In Date: 03/12/2020 **Closed:** 04/03/2020

Work Completed

- Pm
- Pm Winch
- Service Ac
- Test run
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Napagold Oil Filter	1.00
Air Fltr	1.00
Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Non-chlor Brake Clnr	3.00
Motor Treatment Gal	1.00
Rotell Elc Antifeerze	2.00
hyd filter	1.00
Aw68 Hydro Fluid Hydr	10.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Shop Supplies	1.00

Hours: 10.00

Comm: 0.00

Labor: 730.00

Parts: 484.69

Total: 1,214.69

Work Order: 2007084
Problem: Low coolant

Meter: 15993

In Date: 07/21/2020 **Closed:** 11/20/2020

Work Completed

- check coolant fill system and bleed
- truck smoking from tail pipe. found bad egr cooler. scan truck for codes
- R&r egr cooler, turbos, intercooler, aftercooler, exhaust brake, evac and charge ac system
- R&r Dpf, dosing module, injector assembly
- R&r belts and pulleys
- to mako 2xs
- to roads 2xs
- to rechtien 2xs
- test run

Parts Issued

Quantity

Distilled Water 1gal	6.00
Rotell Elc Antifeerze	1.00
Fitting	1.00
Fitting	1.00
Tube Assy	1.00
Tube Assy	1.00
Seal Kit	1.00
O Ring	2.00
O Ring	2.00
White Ultra Marker	1.00

3/28/2025
1:27:12 PM

10192682

Palm Beach County Fleet Management Asset Maintenance History
2014 INTERNATIONAL DURASTAR 4300 Wrecker, 38,000 GVWR, 26 Ft Tilt Ramp

- Shop Supplies

Parts Issued	Quantity
Cooler	1.00
Stud	4.00
Turbo Flange Nut	8.00
O Ring	2.00
Ring O	2.00
Stud	4.00
Exhaust Gasket	1.00
Clamp Exha	1.00
Brake Valve	1.00
Dpfe Gasket	6.00
Dpf Filter	1.00
Plug	1.00
Gasket	1.00
Gasket	1.00
Inlet Duct Gasket	1.00
Egr Actuator	1.00
Nuts	3.00
Heat Shield Bolt	3.00
O-ring	6.00
hydrocarbon injector	1.00
Valve Aft Sensor	1.00
Exhaust Brake Valve	1.00
Turbo	1.00
Tubro	1.00
Seal	1.00
O Ring	1.00
O Ring	1.00
Cooler Assy	1.00
Air Charge	1.00
Tensioner	1.00

3/28/2025
1:27:12 PM

10192682

Palm Beach County Fleet Management Asset Maintenance History
2014 INTERNATIONAL DURASTAR 4300 Wrecker, 38,000 GVWR, 26 Ft Tilt Ramp

Parts Issued	Quantity
Drive Belt	1.00
Tensioner	1.00
Idler Pulley	1.00
Napagold Oil Filter	1.00
Rotell Elc Antifeerze	8.00
Sensor	1.00
O Ring	1.00
Clamp V-band	1.00
Elbow	1.00
Hose Made Mako	1.00
Hose	1.00
15-40 Oil	30.00
Shop Supplies	1.00

Hours: 106.50

Comm: 0.00

Labor: 7,774.50

Parts: 26,857.31

Total: 34,631.81

Work Order: 2011557

Meter: 15960

In Date: 11/18/2020 **Closed:** 11/19/2020

Problem: PM

Work Completed

- Preventive Maint. Service
- Pm Winch
- Service a/c system
- Test run
- Shop Supplies

Parts Issued	Quantity
Air Fltr	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Filter	1.00
Non-chlor Brake Clnr	3.00
Used Fire X Refurbished	1.00
hyd filter	1.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Shop Supplies	1.00

Hours: 9.50

Comm: 0.00

Labor: 693.50

Parts: 266.29

Total: 959.79

3/28/2025
1:27:12 PM

**10192682 Palm Beach County Fleet Management Asset Maintenance History
2014 INTERNATIONAL DURASTAR 4300 Wrecker, 38,000 GVWR, 26 Ft Tilt Ramp**

Work Order: 2012319 **Meter:** 16297 **In Date:** 12/11/2020 **Closed:** 12/21/2020
Problem: Roads, truck has a air leak

Work Completed

Parts Issued

Quantity

- Air leak under cab, found dual pressure protection valve internally leaking, Rr valve and reduction lines to air tanks.
- Shop Supplies

Pressure Valve	1.00
1/4x3/8 Standpipe	4.00
Shop Supplies	1.00

Hours: 4.00 Comm: 0.00 Labor: 292.00 Parts: 188.97 Total: 480.97

Work Order: 2101737 **Meter:** 16739 **In Date:** 02/16/2021 **Closed:** 04/16/2021
Problem: Roads, tilt ramp first and third straps need to be replace

Work Completed

Parts Issued

Quantity

- Torn / worn load straps- ordered
- To roads lot and back .
- Shop Supplies

4" X 27' Strap	4.00
Shop Supplies	1.00

Hours: 2.50 Comm: 0.00 Labor: 182.50 Parts: 157.54 Total: 340.04

Work Order: 2104423 **Meter:** 16739 **In Date:** 04/21/2021 **Closed:** 05/03/2021
Problem: 100 foot winch cable replace

Work Completed

Parts Issued

Quantity

- Damaged winch Cable. Remove and replace winch cable.
- Shop Supplies

.50 X 100 Foot Winch Cable W/locking Hoo	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 3.00 Comm: 0.00 Labor: 219.00 Parts: 494.26 Total: 713.26

Work Order: 2104517 **Meter:** 16739 **In Date:** 04/21/2021 **Closed:** 04/22/2021
Problem: RRIO and RF

Work Completed

- Tire Service: vista Problem: Rrio and Rf

Hours: 0.00 Comm: 211.76 Labor: 0.00 Parts: 0.00 Total: 211.76

3/28/2025
1:27:12 PM

10192682 Palm Beach County Fleet Management Asset Maintenance History
2014 INTERNATIONAL DURASTAR 4300 Wrecker, 38,000 GVWR, 26 Ft Tilt Ramp

Work Order: 2107326 **Meter:** 17945 **In Date:** 07/07/2021 **Closed:** 07/12/2021
Problem: PM Service. turning in today.

Work Completed

- Preventive Maint. Service
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Napagold Oil Filter	1.00
Filter	1.00
Air Filter	1.00
Non-chlor Brake Clnr	3.00
Used Fire X Refurbished	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Shop Supplies	1.00

Hours: 6.00 Comm: 0.00 Labor: 438.00 Parts: 381.15 Total: 819.15

Work Order: 2109555 **Meter:** 18249 **In Date:** 09/01/2021 **Closed:** 09/02/2021
Problem: Dist.1 Paul , truck has a head light out

Work Completed

- Operator States Light out. Found Passenger Side Headlight to be in op. replaced bulb and inspected wiring found bulb to be damaged and wiring to test fine.
- Shop Supplies

Parts Issued

Quantity

Boxed Capsules	1.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 10.16 Total: 83.16

Work Order: 2201176 **Meter:** 18586 **In Date:** 02/02/2022 **Closed:** 02/03/2022
Problem: Dist.1 Paul, truck battery is dead it is here in roads yard

Work Completed

- Dead Batteries. Replace 2 batteries.
- Service Call to Roads lot. 2x
- Shop Supplies

Parts Issued

Quantity

Group 31 Stud Delco	2.00
Shop Supplies	1.00

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 271.23 Total: 417.23

3/28/2025
1:27:12 PM

10192682

Palm Beach County Fleet Management Asset Maintenance History
2014 INTERNATIONAL DURASTAR 4300 Wrecker, 38,000 GVWR, 26 Ft Tilt Ramp

Work Order: 2201613

Meter: 18721

In Date: 02/14/2022 **Closed:** 03/04/2022

Problem: pm

Work Completed

- Preventive Maint. Service
- Replace Air Dryer
- Service A/c
- Service Aps Pm Service
- Add Coolant Tested for leaks
- Found lights on flat bed portion of truck to be in op upon testing also found light bar to be defective. checked junction boxes found no corrosion or connection issues only getting 6 volts to wiring, repaired wiring.
- Test Run Road Test
- Replace Winch Cable
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Aw68 Hydro Fluid Hydr	10.00
hyd filter	1.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Ad Ip Dryer Cart	1.00
Used Fire X Refurbished	1.00
Napagold Oil Filter	1.00
Non-chlor Brake Clnr	5.00
Rotell Elc Antifeerze	2.00
Washer Fluid Concentr	1.00
Filter	1.00
Air Fltr	1.00
Wiper Blade	2.00
Led M C 12v Grommet	6.00
Lamp	16.00
1/2x100 Cable	1.00
Macs Chain Cable Lube	1.00
Torx Bits	1.00
Shop Supplies	1.00

Hours: 27.00

Comm: 0.00

Labor: 1,971.00

Parts: 894.44

Total: 2,865.44

3/28/2025
1:27:12 PM

10192682 Palm Beach County Fleet Management Asset Maintenance History
2014 INTERNATIONAL DURASTAR 4300 Wrecker, 38,000 GVWR, 26 Ft Tilt Ramp

Work Order: 2302954 **Meter:** 22226 **In Date:** 03/22/2023 **Closed:** 03/27/2023
Problem: Dist.3 Robert, needs oil and coolant

Work Completed

- add coolant
- add oil
- Shop Supplies

Parts Issued

Quantity

Shop Supplies 1.00

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 2.65 Total: 148.65

Work Order: 2305226 **Meter:** 22565 **In Date:** 05/26/2023 **Closed:** 07/13/2023
Problem: PM Service

Work Completed

- Preventive Maint. Service
- Winch Cable snapped and backlashed on itself. Untangle, free and remove broken winch cable with assistance of heavy equipment. Replace winch cable assy.
- Service Air conditioning Cleaned evaporator and replaced a/c filters also checked pressures for high and low and tested air conditioning via thermostat in ac vent
- Service tilt bed and winch Replace hydraulic filters and grease tilt bed
- power steering service
- Cooling system service
- Extended test run road test due to cooling system service and power steering service to ensure proper levels and topped off
- Shop Supplies

Parts Issued

Quantity

15-40 Oil 30.00
Napagold Oil Filter 1.00
Non-chlor Brake Clnr 5.00
Filter 1.00
Air Fltr 1.00
Wiper Blade 2.00
Washer Fluid Concentr 1.00
Used Fire X Refurbished 1.00
Cabin Air Filter 1.00
Napa Cabin Air Filter 1.00
Aw68 Hydro Fluid Hydr 10.00
Macs Chain Cable Lube 1.00
Power Steering Filter 1.00
hyd filter 1.00
Hose Clamp 6.00
Rotell Elc Antifeerze 10.00
1/2"x100' Steel Cable W/hook 1.00
Shop Supplies 1.00
Freight Charge 1.00

Hours: 20.00 Comm: 0.00 Labor: 1,460.00 Parts: 1,040.25 Total: 2,500.25

3/28/2025
1:27:12 PM

10192682 Palm Beach County Fleet Management Asset Maintenance History
2014 INTERNATIONAL DURASTAR 4300 Wrecker, 38,000 GVWR, 26 Ft Tilt Ramp

Work Order: 2502056 **Meter:** 27137 **In Date:** 02/28/2025 **Closed:** 03/03/2025
Problem: battery is dead it is in our yard

Work Completed

Parts Issued

Quantity

- jump start
- Recall: Safety Recall-15509/linear Power Module-jump start or overload dump event-overheating of Lpm
- Recall: Safety Recall 15509: replace the linear power module (lpm)
- Shop Supplies

Shop Supplies 1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 2.65 Total: 75.65

Work Order: 2502109 **Meter:** 27137 **In Date:** 03/04/2025 **Closed:** 03/12/2025
Problem: air leak

Work Completed

Parts Issued

Quantity

- replace bad air valve
- Recall: Safety Recall-15509/linear Power Module-jump start or overload dump event-overheating of Lpm
- Recall: Safety Recall 15509: replace the linear power module (lpm)
- Shop Supplies

Bleeder Valve 1.00

Shop Supplies 1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 425.62 Total: 498.62

Work Order: 2502661 **Meter:** 27137 **In Date:** 03/19/2025 **Closed:** 03/20/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 363.00 Total Labor: 24,987.00 Total Comm: 916.56 Total Parts: 40,846.44