

3/28/2025  
1:39:58 PM

10206800

**Palm Beach County Fleet Management Asset Maintenance History**  
**2018 CLUB CAR CARRYALL 1700 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)**

---

**Total Hours: 85.00    Labor: 6,127.50    Parts: 5,097.79    Comm: 0.00    Charged: 11225.29**

---

**Work Order:** 1803781      **Meter:** 1      **In Date:** 04/11/2018    **Closed:** 04/16/2018  
**Problem:** pre delivery inspection

**Work Completed**

- pre delivery inspection
- install hitch ext
- Shop Supplies

Hours: 2.50      Comm: 0.00

**Parts Issued**

**Quantity**

Receiver Extension	1.00
Ball Mount 3/4"	1.00
Pin W/clip 5/8 For Hitch	2.00
Shop Supplies	1.00
Labor: 150.00    Parts: 119.48    Total: 269.48	

---

**Work Order:** 1904908      **Meter:** 515      **In Date:** 05/06/2019    **Closed:** 05/29/2019  
**Problem:** PM Service.

**Work Completed**

- Pm Service.
- Verify E.brake inop.replace E.brake caliper Asm.
- Wash equipment.
- Drive train service.change fluid in transaxle,front and rear diffs.
- Shop Supplies

Hours: 7.50      Comm: 0.00

**Parts Issued**

**Quantity**

Napagold Air Filter	1.00
Napagold Air Filter	1.00
Fuel Filter	1.00
Napagold Fuel Filter	1.00
15w40 Bulk South Reg	4.00
Napagold Oil Filter	1.00
Caliper Mech Park Brake	1.00
Shop Supplies	1.00
Labor: 502.50    Parts: 222.63    Total: 725.13	

---

**Work Order:** 1912710      **Meter:** 743      **In Date:** 12/11/2019    **Closed:** 12/16/2019  
**Problem:** Wont start.

**Work Completed**

- Test starting and charging system.battery bad.replace battery and retest all ok.
- Fabricate and repair left tail lamp inop.
- Shop Supplies

Hours: 2.00      Comm: 0.00

**Parts Issued**

**Quantity**

Battery	1.00
Shop Supplies	1.00

Labor: 146.00    Parts: 102.21    Total: 248.21



3/28/2025  
1:39:58 PM

10206800

**Palm Beach County Fleet Management Asset Maintenance History**  
**2018 CLUB CAR CARRYALL 1700 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)**

**Work Order:** 2109473      **Meter:** 1217      **In Date:** 08/30/2021      **Closed:** 09/15/2021  
**Problem:** PM Service.Needs new back tires.Check headlights.

**Work Completed**

- Preventive Maint. Service
- Customers complaint back tires. Verify right rear tire worn, replace right rear tire only. correct all Nitrogen levels to 22 Psi
- Customer complaint check lights, Verify headlight out replace bulb clean rear sockets.
- Wash equipment for service and repairs.
- Verify parking brake wont hold due to worn caliper and broken rotor. Replace brake caliper and rotor on drive shaft for parking brake.
- Replace inner and outer Cv axle boots on front passenger side axle.
- Shop Supplies

Hours: 10.00

Comm: 0.00

**Parts Issued**

**Quantity**

Napagold Air Filter	1.00
Fuel Filter	1.00
15w40 Bulk South Reg	4.00
Napagold Oil Filter	1.00
25 X 11.00 X 12 Tire Kenda	1.00
Blister Pack Capsules	1.00
Caliper Mech Park Brake	1.00
Cv Boot	1.00
Cv Boot	1.00
Rotor Park Brake	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Labor: 730.00

Parts: 441.42

Total: 1,171.42

**Work Order:** 2110242      **Meter:** 1225      **In Date:** 09/21/2021      **Closed:** 09/22/2021  
**Problem:** Crank but wont start.

**Work Completed**

- Customers compliant wont start. trouble shoot fuel injection system, remove fuel line pickup found debris blocking fuel filter inlet. reassemble fuel system purge air and test run.
- Shop Supplies

Hours: 1.50

Comm: 0.00

**Parts Issued**

**Quantity**

Shop Supplies	1.00
---------------	------

Labor: 109.50

Parts: 2.65

Total: 112.15

3/28/2025  
1:39:58 PM

10206800

**Palm Beach County Fleet Management Asset Maintenance History**  
**2018 CLUB CAR CARRYALL 1700 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)**

**Work Order:** 2207691

**Meter:** 1426

**In Date:** 07/25/2022 **Closed:** 08/02/2022

**Problem:** PM service.Need front Right tire, Tire has worn to one side.Check liftgate.

**Work Completed**

- Preventive Maint. Service
- C/c front tires worn. Replace 2 front tires, mount and balance Correct Nitrogen levels to 22 Psi.
- Verify parking brake linkage is fully adjusted, replace caliper assembly on drive shaft parking brake.
- Verify tire is worn uneven. Remove front right cv axle assembly to replace outer boot, reassemble and adjust front end alignment.
- Customers complaint the lift bed is not working. Trouble shoot electrical system, found damage ground wire is causing intermittent operation of the lift bed. repaired ground.
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Air Filter	1.00
Fuel Filter	1.00
15w40 Bulk South Reg	4.00
Napagold Oil Filter	1.00
25 X 11.00 X 12 Tire Kenda	2.00
Caliper Mech Park Brake	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 10.00

Comm: 0.00

Labor: 730.00

Parts: 629.43

Total: 1,359.43

**Work Order:** 2302363

**Meter:** 1600

**In Date:** 03/08/2023 **Closed:** 03/21/2023

**Problem:** Bushings and struts is really bad both front and back

**Work Completed**

- Customers complaint bushings. Verify complaint. Replace front upper and lower bushings and hardware, rear bushings and hardware, front right inner and outer Cv axle boots, test run.
- Verify parking brake is not holding, replace parking brake caliper.
- Customers complaint tail light bulb burned out. Replace right rear tail light bulb. Clean socket
- Shop Supplies

**Parts Issued**

**Quantity**

Cv Boot	1.00
Inner Sleeve	4.00
Lower Arm Sleeve	2.00
Lower Arm Bushing	4.00
Upper Sleeve	4.00
Arm Bushing	16.00
Caliper Mech Park Brake	1.00
Boxed Miniatures	1.00
L/f Inner Cv Boot	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 5.50

Comm: 0.00

Labor: 401.50

Parts: 315.76

Total: 717.26

3/28/2025  
1:39:58 PM

10206800

**Palm Beach County Fleet Management Asset Maintenance History**  
**2018 CLUB CAR CARRYALL 1700 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)**

**Work Order:** 2309379      **Meter:** 1740      **In Date:** 09/14/2023      **Closed:** 09/26/2023  
**Problem:** PM Service. front cv joint check light ahach riioht side molding tiers

**Work Completed**

- Preventive Maint. Service
- C/c tires, Replace two front tires, mount, correct all Nitrogen levels to 18 Psi.
- Replaced inner and outer Cv axle boots on front left axle shaft.
- Verify upper and lower suspension bushings on both front and rear are worn. Replace all.
- C/c side trim pieces are falling off, reattach.
- C/c check lights, Verify both front headlights are out and left rear tail light. Replace 3 bulbs and 1 harness, clean connections.
- Shop Supplies

**Parts Issued**

**Quantity**

air filter	1.00
Fuel Filter	1.00
15w40 Bulk South Reg	4.00
Napagold Oil Filter	1.00
25 X 11.00 X 12 Tire Kenda	2.00
L/f Inner Cv Boot	1.00
L/f Outer Cv Boot	1.00
harness for hd light	1.00
Blister Pack Capsules	1.00
Boxed Miniatures	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 11.75

Comm: 0.00

Labor: 857.75      Parts: 629.76      Total: 1,487.51

**Work Order:** 2405024      **Meter:** 1930      **In Date:** 05/20/2024      **Closed:** 06/21/2024  
**Problem:** Dead battery and check charging system.

**Work Completed**

- Battery failed load test, Clean battery terminals, Replace battery.
- Replace headlight bulb
- Replace inner and outer axle boots.
- Replace clutch on engine side, reassemble belt housing.
- Shop Supplies

**Parts Issued**

**Quantity**

Battery	1.00
Blister Pack Capsules	2.00
L/f Outer Cv Boot	2.00
L/f Inner Cv Boot	2.00
Clutch Drive	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 7.00

Comm: 0.00

Labor: 511.00      Parts: 1,016.09      Total: 1,527.09

3/28/2025  
1:39:59 PM

10206800

**Palm Beach County Fleet Management Asset Maintenance History**  
**2018 CLUB CAR CARRYALL 1700 Utility Cart, All Terrain, 4 Wh (Gator, Mule, Etc)**

**Work Order:** 2409404      **Meter:** 2000      **In Date:** 09/26/2024      **Closed:** 10/04/2024  
**Problem:** p m

**Work Completed**

- Preventive Maint. Service
- Replace front left outer Cv axle boot. Replace suspension bushings on the rear ladder bars.
- Verify needs two tires, replace two tires, mount correct all Nitrogen to 18 Psi.
- C/c coolant reservoir looks contaminated. Verify discoloration is normal from factory coolant type. Drain, flush system, clean reservoir and caps, refill system with green antifreeze and purge air from system.
- Shop Supplies

**Parts Issued**

**Quantity**

Fuel Filter	1.00
15w40 Bulk South Reg	4.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Napagold Air Filter	1.00
L/f Inner Cv Boot	1.00
25 X 11.00 X 12 Tire Kenda	2.00
1gal Rtu Antifreeze	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 9.00      Comm: 0.00

Labor: 657.00      Parts: 603.38      Total: 1,260.38

**Work Order:** 2502545      **Meter:** 2000      **In Date:** 03/17/2025      **Closed:** 03/18/2025  
**Problem:** Transition Prep Charge

**Work Completed**

- Transition Prep Charge

Hours: 2.00      Comm: 0.00

Labor: 146.00      Parts: 0.00      Total: 146.00

**Total Hours: 85.00**

**Total Labor: 6,127.50**

**Total Comm: 0.00**

**Total Parts: 5,097.79**