

3/27/2017
4:32:45PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170986 2007 TORO 687 Aerator, 78", Pull Behind

Workorder: 740809

Problem: PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts	Quantity
In Date: 06/29/2007	Hours	Description	Quantity
- Pre-Delivery Inspection	3.00		
- Minor Weld Repair Or Machining.			
Parts Charge: 0.00	Labor Charge: 55.00		

Workorder: 937824

Problem: 9950

Meter Reading: 0	Labor	Parts	Quantity
In Date: 05/15/2009	Hours	Description	Quantity
- Lubed Complete.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00	Labor Charge: 60.00		

Workorder: 938555

Problem: 9950

Meter Reading: 0	Labor	Parts	Quantity
In Date: 06/02/2009	Hours	Description	Quantity
- Lubed Complete. Attached To 10151793	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00	Labor Charge: 60.00		

Workorder: 1601059

Problem: 9950

Meter Reading: 0	Labor	Parts	Quantity
In Date: 01/29/2016	Hours	Description	Quantity
- Onsite Lube	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00	Labor Charge: 60.00		

3/27/2017
4:32:45PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170986 2007 TORO 687 Aerator, 78", Pull Behind

Workorder: 1700366

Problem: 9950

Meter Reading: 0	Labor	Parts	
In Date: 01/11/2017	Hours	Description	Quantity
- Onsite Lube	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 1702450

Problem: Transition Prep Charge

Meter Reading: 0	Labor	Parts	
In Date: 03/09/2017	Hours	Description	Quantity
- Transition Prep Charge	2.00		
Parts Charge:	0.00	Labor Charge:	0.00

Total Parts Charges: **8.00** Total Labor Charges: **295.00** Total Comm. Charges: **0.00**