

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 04/10/2015 to 03/09/2025 System Code Range: **1100** to **9700**

Print Date: 5/21/2025

Asset# Range: PT1503 to PT1503

| <u>BUS#</u> | <u>SYS Code</u> | <u>SYS Code Description</u> | | | <u>Cause-Reason</u> |
|---------------------|-----------------|-----------------------------|--|--|--------------------------|
| PT1503 | 1100 | INTERIOR CLEAN | Total Line Count for System Code 1100 : | | 1 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>SCHEDULED SERVICE</u> |
| 1808442 | 1 | 04/26/2018 | 656 | INTERIOR CLEAN---COMPLETED | |
| PT1503 | 1200 | COOLING SYSTEM | Total Line Count for System Code 1200 : | | 12 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>SCHEDULED SERVICE</u> |
| 1901819 | 3 | 01/31/2019 | 828 | FASTEN RADIATOR FAN CONTROLLER MODULE | OPERATOR COMPLAINT |
| 1917625 | 1 | 10/21/2019 | 849 | COOLING SYSTEM----FOUND COOLANT HOSE TO TRANSCOOLER LEAKING--POO | OPERATOR COMPLAINT |
| 1917625 | 7 | 10/21/2019 | 849 | RAN FOR (2) HOURS--DID NOT OVERHEAT-OK | OPERATOR COMPLAINT |
| 1822352 | 3 | 10/29/2018 | 828 | remove panel to spot leas found heater hose leaking -wip | OPERATOR COMPLAINT |
| 1822352 | 4 | 10/29/2018 | 828 | drain coolant removeds hose -wip | OPERATOR COMPLAINT |
| 1822352 | 6 | 10/29/2018 | 828 | install hose assembly and wipers arms with panels | OPERATOR COMPLAINT |
| 1907546 | 8 | 04/30/2019 | 828 | REPLCD RESERVIOR TANK CAP--REPAIR COOLANT RETURN LINE TO RESERVIOR--REPLC CLAMP | SCHEDULED SERVICE |
| 2100800 | 3 | 01/24/2021 | 833 | REPLCD TRANS COOLER CONTROL VALVE | OPERATOR COMPLAINT |
| 2100800 | 4 | 01/24/2021 | 833 | REPLCD COOLANT LINR FROM RESERVIOR TO RADIATOR--NO LEAKS | NORMAL WEAR |
| 2210089 | 2 | 04/10/2022 | 823 | replace thermostat and gasket | OPERATOR COMPLAINT |
| 2315831 | 1 | 07/09/2023 | 849 | ran car , added coolant, psi system and no leaks are present. ran for one hour without overheating | OPERATOR COMPLAINT |
| 2424182 | 6 | 10/24/2024 | 833 | install lower rad hose | OPERATOR COMPLAINT |

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 04/10/2015 to 03/09/2025

System Code Range: 1100 to 9700

Print Date: 5/21/2025

Asset# Range: PT1503 to PT1503

| <u>BUS#</u> | <u>SYS Code</u> | <u>SYS Code Description</u> | | | <u>Cause-Reason</u> |
|---------------------|-----------------|----------------------------------|--|---|---------------------|
| PT1503 | 1201 | TROUBLESHOOT COOLING SYS | Total Line Count for System Code 1201 : | | 6 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 2106186 | 1 | 03/26/2021 | 833 | T/S COOLING SYSTEM | OPERATOR COMPLAINT |
| 2100800 | 1 | 01/24/2021 | 849 | TROUBLESHOOT COOLING SYS -----TRAN FLUID HEATER COOLANT CONTROL VALVE | OPERATOR COMPLAINT |
| 2100800 | 2 | 01/24/2021 | 849 | FOUND TRANS FLUID HEATER CONTROL VALVE IS BAD/LEAKING | OPERATOR COMPLAINT |
| 1822352 | 1 | 10/29/2018 | 828 | T/S COOLING SYSTEM | OPERATOR COMPLAINT |
| 1917625 | 3 | 10/21/2019 | 849 | CKD FOR ELAKS--NONE--CAR STARTED OVERHEATING--FOUD FAN NOT TURNING ON--NEEDS COOI | OPERATOR COMPLAINT |
| 2106186 | 3 | 03/26/2021 | 833 | .CHECK FOR LEAKS | OPERATOR COMPLAINT |
| PT1503 | 1204 | FAN MOTOR REPL | Total Line Count for System Code 1204 : | | 2 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 1917625 | 4 | 10/21/2019 | 849 | REMVD RADIATOR, FAN AND CONDENSOR--NEEDS NEW RADIATOR---POO | OPERATOR COMPLAINT |
| 1917625 | 5 | 10/21/2019 | 849 | INSTALLED RADIATOR & FAN--FOUND LWER RADIATOR HOSE LEAKING--NEEDS NEW HOSE | OPERATOR COMPLAINT |
| PT1503 | 1207 | COOLING SYS LEAKS REPAIR | Total Line Count for System Code 1207 : | | 1 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 2210089 | 6 | 04/10/2022 | 823 | replace heater hoses | OPERATOR COMPLAINT |
| PT1503 | 1208 | COOLING SYS LINES/HOSES R | Total Line Count for System Code 1208 : | | 4 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 2106186 | 2 | 03/26/2021 | 833 | REMOVE OLD HEATRER HOSE AND INSTALLED COMBO HEATER HOSE | OPERATOR COMPLAINT |
| 2019725 | 1 | 10/06/2020 | 849 | COLING SYSTEM LINES HOSES R -DRAINED COOLANT REMOVED SKID PLATE REMOVED LOWER RA | SCHEDULED SERVICE |
| 1917625 | 6 | 10/21/2019 | 849 | REPLCD HOSE--FOUD ANOTHER LEAK--REPLCD HOSE/TTOK FROM PC1208 | OPERATOR COMPLAINT |
| 1917625 | 2 | 10/21/2019 | 849 | REPLCD TRAN HOSE TO COOLANT--TOPPED OFF-PSI TESTED--NO LEAKS | OPERATOR COMPLAINT |

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 04/10/2015 to 03/09/2025 System Code Range: **1100** to **9700**

Print Date: 5/21/2025

Asset# Range: PT1503 to PT1503

| <u>BUS#</u> | <u>SYS Code</u> | <u>SYS Code Description</u> | | | <u>Cause-Reason</u> |
|---------------------|-----------------|--------------------------------|--|---|---------------------------|
| PT1503 | 1300 | AIR COND\HEATING SYSTEM | Total Line Count for System Code 1300 : | | 13 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>SCHEDULED SERVICE</u> |
| 1808433 | 3 | 04/26/2018 | 837 | R/R CABIN FILTER | SCHEDULED SERVICE |
| 1907546 | 5 | 04/30/2019 | 828 | INSTALL CONDENSOR, AC LINES, VACUUM, CHARGE, INSTALL WINDSHIELD COWL, PANEL, WIPER AI | SCHEDULED SERVICE |
| 1907546 | 2 | 04/30/2019 | 828 | RECOVER REFRIGERANT--VACUUM--RECHARGE--CK FOR LEAKS--NONE | SCHEDULED SERVICE |
| 1907546 | 3 | 04/30/2019 | 828 | REMV ALL REFRIGERANT--REPLC AIR COMPRESSOR--REMV WIPERS--REPCL EXP VALVE--REMV COI | SCHEDULED SERVICE |
| 2119870 | 2 | 08/03/2021 | 833 | EVACUATE A/C SYSTEM | OPERATOR COMPLAINT |
| 2119870 | 3 | 08/03/2021 | 833 | EVACUATE SYSTEM AND VACUM DOWN | OPERATOR COMPLAINT |
| 2119870 | 4 | 08/03/2021 | 833 | RECHARGE C A/C SYSTEM | OPERATOR COMPLAINT |
| 2120361 | 3 | 08/11/2021 | 853 | ROAD TEST==AC NORMAL | OPERATOR COMPLAINT |
| 2424182 | 7 | 10/24/2024 | 833 | vacuum sys and charge 134 freon | OPERATOR COMPLAINT |
| 2424182 | 3 | 10/24/2024 | 833 | removed ac comp & expansion valve | OPERATOR COMPLAINT |
| 2424182 | 4 | 10/24/2024 | 833 | remove rad fan asy | OPERATOR COMPLAINT |
| 2308352 | 1 | 04/05/2023 | 823 | REFILL A/C 134A | OPERATOR COMPLAINT |
| 2328339 | 2 | 12/11/2023 | 823 | removed old hose but new one is different ----- installed new hose on 12/11 | OPERATOR COMPLAINT |
| PT1503 | 1301 | TROUBLESHOOT AC SYSTEM | Total Line Count for System Code 1301 : | | 5 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>OPERATOR COMPLAINT</u> |
| 2328339 | 1 | 12/11/2023 | 823 | a/c not cold/ a/c line leaking | OPERATOR COMPLAINT |
| 2424182 | 1 | 10/24/2024 | 833 | t/s ac | OPERATOR COMPLAINT |
| 2120361 | 1 | 08/11/2021 | 869 | TROUBLESHOOT AC SYSTEM----SYS LOW--COMP CONNECTOR LOOSE--- | OPERATOR COMPLAINT |
| 2119870 | 1 | 08/03/2021 | 833 | CK AND RESET A/C TEMPS -OUT OF RANGE | OPERATOR COMPLAINT |
| 1916582 | 4 | 09/12/2019 | 849 | RECOVERED VACUUM RECHARGED 1.50POUNDS OF 134 | OPERATOR COMPLAINT |

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 04/10/2015 to 03/09/2025

System Code Range: **1100** to **9700**

Print Date: 5/21/2025

Asset# Range: **PT1503** to **PT1503**

| <u>BUS#</u> | <u>SYS Code</u> | <u>SYS Code Description</u> | | | <u>Cause-Reason</u> |
|---------------------|-----------------|----------------------------------|--|---|---------------------|
| PT1503 | 1307 | BLOWER MOTOR REPL | Total Line Count for System Code 1307 : | | 1 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | SCHEDULED SERVICE |
| 2326455 | 4 | 11/08/2023 | 823 | r/r blower motor | |
| PT1503 | 1318 | A/C SYSTEM RE-CHARGE | Total Line Count for System Code 1318 : | | 3 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | OPERATOR COMPLAINT |
| 2328339 | 4 | 12/11/2023 | 823 | recharge system | OPERATOR COMPLAINT |
| 1817524 | 1 | 08/14/2018 | 752 | RECHARGE AC SYSTEM | OPERATOR COMPLAINT |
| 1916657 | 4 | 09/24/2019 | 849 | RECOVER, VACUUM, RECHARGE AC SYSTEM--CKD TEMP, CKD FAN--ROAD TEST | OPERATOR COMPLAINT |
| PT1503 | 1335 | A/C SYSTEM VACUUM | Total Line Count for System Code 1335 : | | 1 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | OPERATOR COMPLAINT |
| 2328339 | 3 | 12/11/2023 | 823 | vaccum system | |
| PT1503 | 1400 | ELECTRICAL SYSTEM | Total Line Count for System Code 1400 : | | 5 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | OPERATOR COMPLAINT |
| 2300739 | 1 | 01/18/2023 | 823 | ELECTRICAL SYSTEM | OPERATOR COMPLAINT |
| 2430622 | 1 | 12/14/2024 | 833 | repair low beam connection | OPERATOR COMPLAINT |
| 2223634 | 2 | 08/01/2022 | 797 | frabricated a connector for head lifgts | OPERATOR COMPLAINT |
| 1921816 | 2 | 11/23/2019 | 828 | REMV PLUG ON STEERING MOTOR--CLEAN--APPLY GREASE TO PLUG | OPERATOR COMPLAINT |
| 2102801 | 1 | 02/16/2021 | 833 | ELECTRICAL SYSTEM---INSTALL GPS--- | OPERATOR COMPLAINT |
| PT1503 | 1401 | TROUBLESHOOT ELECTRICAL S | Total Line Count for System Code 1401 : | | 4 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | OPERATOR COMPLAINT |
| 1708616 | 1 | 05/18/2017 | 756 | TROUBLESHOOT ELECTRICALS---JUMP SATART--NEEDS BATTERIES | OPERATOR COMPLAINT |
| 1513584 | 1 | 09/30/2015 | 820 | T/S ELEC - CHECKED BATTERY IS OK- CHECK CHARGE SYS IS -OK 14,1VOLTS | OPERATOR COMPLAINT |
| 1810538 | 4 | 07/05/2018 | 783 | TO PICK UP FROM AL PACKER -INSTRUCTED TO FUEL VEHICLE | OPERATOR COMPLAINT |
| 2219299 | 2 | 06/22/2022 | 823 | CHARGING BATTERY AND CHECK ELECTRICAL SYSTEM | OPERATOR COMPLAINT |

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 04/10/2015 to 03/09/2025

System Code Range: 1100 to 9700

Print Date: 5/21/2025

Asset# Range: PT1503 to PT1503

| <u>BUS#</u> | <u>SYS Code</u> | <u>SYS Code Description</u> | | | | | <u>Cause-Reason</u> |
|---------------------|-----------------|-----------------------------|------------------|-------------------------------------|--|--|---------------------|
| PT1503 | 1407 | BATTERIES CHECK | | | Total Line Count for System Code 1407 : | | 2 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | | | |
| 2316981 | 1 | 07/21/2023 | 823 | needs new battery | | | OPERATOR COMPLAINT |
| 2326455 | 2 | 11/08/2023 | 823 | charge battery | | | SCHEDULED SERVICE |
| PT1503 | 1408 | BATTERIES REPLACE | | | Total Line Count for System Code 1408 : | | 4 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | | | |
| 2316981 | 2 | 07/21/2023 | 648 | replace battery and test for lights | | | OPERATOR COMPLAINT |
| 2122171 | 4 | 09/26/2021 | 853 | INSTALL BATTERY--TESTED GOOD | | | OPERATOR COMPLAINT |
| 1810538 | 6 | 07/05/2018 | 746 | BATTIERIES REPLACE | | | OPERATOR COMPLAINT |
| 1708616 | 2 | 05/18/2017 | 753 | R/R BATTERIES | | | OPERATOR COMPLAINT |

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 04/10/2015 to 03/09/2025 System Code Range: **1100** to **9700**

Print Date: 5/21/2025

Asset# Range: PT1503 to PT1503

| <u>BUS#</u> | <u>SYS Code</u> | <u>SYS Code Description</u> | | | <u>Cause-Reason</u> |
|---------------------|-----------------|----------------------------------|--|---|---------------------|
| PT1503 | 1409 | EXTERIOR LIGHTING | Total Line Count for System Code 1409 : | | 14 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 1827646 | 1 | 12/27/2018 | 828 | REPLCD HEADLIGHT LOW BEAM---REPAIR HARNESS | OPERATOR COMPLAINT |
| 1821274 | 1 | 10/02/2018 | 828 | EXTERIOR LIGHTING REPAI FRONT BUMPER AND ATTACH LIGHT PROPERLY | SCHEDULED SERVICE |
| 1821495 | 1 | 10/02/2018 | 752 | EXTERIOR LIGHTING---INSTALL LIGHT BULB | OPERATOR COMPLAINT |
| 1912910 | 2 | 07/15/2019 | 849 | REPLCD LIGHTS | SCHEDULED SERVICE |
| 2123011 | 1 | 09/07/2021 | 836 | EXTERIOR LIGHTING R/R P/S BRAKE LIGHT BULB | OPERATOR COMPLAINT |
| 2008118 | 3 | 05/07/2020 | 849 | CHECKED TAG LIGHT AND REPAIRED BAD CONNECTION | SCHEDULED SERVICE |
| 2016864 | 1 | 09/02/2020 | 849 | REPLCD LF HEAD LIGHT BULB | OPERATOR COMPLAINT |
| 2223634 | 1 | 08/01/2022 | 797 | replace head light bulbs | OPERATOR COMPLAINT |
| 2210089 | 4 | 04/10/2022 | 823 | replace rear tail light | OPERATOR COMPLAINT |
| 2217073 | 1 | 06/02/2022 | 823 | EXTERIOR LIGHT | OPERATOR COMPLAINT |
| 2209443 | 1 | 03/22/2022 | 823 | FRONT RIGHT HEADLIGHT | OPERATOR COMPLAINT |
| 2427378 | 1 | 11/07/2024 | 909 | R&R pass side headlight bulb and repair damaged harness | OPERATOR COMPLAINT |
| 2500609 | 1 | 01/08/2025 | 809 | REPLACE BRAKE LIGHT BULB | OPERATOR COMPLAINT |
| 2411472 | 4 | 05/31/2024 | 823 | REPLACE REAR BRAKE LAMP ASSEMBLY | OPERATOR COMPLAINT |
| PT1503 | 1413 | ELEC.SYS.SWITCHES-BREAKER | Total Line Count for System Code 1413 : | | 2 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 1916657 | 3 | 09/24/2019 | 839 | REPLCD ALL FUSES IN BATTERY CIRCUIT BOARD | OPERATOR COMPLAINT |
| 1916657 | 2 | 09/24/2019 | 849 | INSTALLED NEW BATTERY FUSE BOX, STILLSAME ISSUE--ORDERED NEW NEGATIVE CABLE | OPERATOR COMPLAINT |
| PT1503 | 1431 | INSTALLED CANCEIVER | Total Line Count for System Code 1431 : | | 1 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 1514994 | 1 | 10/26/2015 | 818 | INSTALLED CANCEIVER-COMPLETED | SCHEDULED SERVICE |

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 04/10/2015 to 03/09/2025

System Code Range: 1100 to 9700

Print Date: 5/21/2025

Asset# Range: PT1503 to PT1503

| <u>BUS#</u> | <u>SYS Code</u> | <u>SYS Code Description</u> | | | <u>Cause-Reason</u> |
|---------------------|-----------------|----------------------------------|--|---|---------------------|
| PT1503 | 2200 | STEERING SYSTEMS | Total Line Count for System Code 2200 : | | 2 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 1907546 | 4 | 04/30/2019 | 828 | R/R CV AXLES ON BOTH SIDES | SCHEDULED SERVICE |
| 1907546 | 6 | 04/30/2019 | 828 | INSTALL BOTH SIDE CV AXLES--INSTALL BOTTOM BRACKETS--REPLCD ALL LUGNUTS | SCHEDULED SERVICE |
| PT1503 | 2201 | TROUBLESHOOT STEERING SYS | Total Line Count for System Code 2201 : | | 4 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 1921816 | 1 | 11/23/2019 | 828 | TROUBLESHOOT STEERING SYSTEM--WET ELECTRICAL PLUG TO STEERING MOTOR | OPERATOR COMPLAINT |
| 2411472 | 1 | 05/31/2024 | 823 | NEEDS ADJUSTMEN, MOTOR MOUNTS, LOWER CONTROL ARMS AND MOTOR MOUNTS | OPERATOR COMPLAINT |
| 2000821 | 1 | 02/10/2020 | 809 | TROUBLESHOOT STEERING SYSTEM---RACK & PINION---POO PART IN STOCK | OPERATOR COMPLAINT |
| 2000821 | 2 | 02/10/2020 | 849 | R/R RACK & PINION---NEED TO REPLC RIGHT OUTER TIE ROD--PUT WHEELS ON & SEND FOR ALIGN | OPERATOR COMPLAINT |
| PT1503 | 2214 | TIE ROD ENDS REPL | Total Line Count for System Code 2214 : | | 1 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 2000821 | 3 | 02/10/2020 | 849 | REPLCD RF OUTER TOE ROD--INSTALLED FRONT WHEELS--ROAD TEST | OPERATOR COMPLAINT |
| PT1503 | 2300 | SUSPENSION SYSTEM | Total Line Count for System Code 2300 : | | 1 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 2411472 | 3 | 05/31/2024 | 823 | R&R LOWER CONTROL ARMS | OPERATOR COMPLAINT |

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 04/10/2015 to 03/09/2025

System Code Range: **1100** to **9700**

Print Date: 5/21/2025

Asset# Range: **PT1503** to **PT1503**

| BUS# | SYS Code | SYS Code Description | | | | Total Line Count for System Code 2500 : | 12 | Cause-Reason |
|---------------------|-----------------|-----------------------------|------------------|--|--|--|-----------|---------------------|
| PT1503 | 2500 | BODY | | | | | | |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | | | | <u>Cause-Reason</u> |
| 2411472 | 2 | 05/31/2024 | 823 | REPAIR DRIVERS DOOR HANDLE | | | | OPERATOR COMPLAINT |
| 2233284 | 2 | 12/18/2022 | 797 | WASH CAR | | | | OPERATOR COMPLAINT |
| 2233284 | 3 | 12/18/2022 | 887 | REPAIR R/ REAR DOOR | | | | OPERATOR COMPLAINT |
| 2233284 | 4 | 12/18/2022 | 887 | REPAIR DAMAGE IN REAR DOOR | | | | OPERATOR COMPLAINT |
| 2233284 | 5 | 12/18/2022 | 887 | REPAIR DAMAGE IN REAR DOOR, PAINT | | | | OPERATOR COMPLAINT |
| 2233284 | 6 | 12/18/2022 | 887 | REPAIR DOOR TRIM, REASSEMBLE INSIDE DOOR PANEL | | | | OPERATOR COMPLAINT |
| 2226883 | 3 | 09/07/2022 | 797 | REPLACE CABIN FILTER | | | | SCHEDULED SERVICE |
| 2226883 | 4 | 09/07/2022 | 797 | WASH BODY AND VAC | | | | SCHEDULED SERVICE |
| 1901819 | 2 | 01/31/2019 | 828 | REPLCD ALL SPLASH GUARD SCREWS | | | | SCHEDULED SERVICE |
| 1907546 | 9 | 04/30/2019 | 828 | R/R DRVER SEAT BACK REST ADJUSTING HANDLE | | | | SCHEDULED SERVICE |
| 1706111 | 3 | 04/13/2017 | 809 | INSTALLED WIPERS | | | | OPERATOR COMPLAINT |
| 2101845 | 3 | 02/02/2021 | 828 | REPLCD DRIVE SEAT ADJ HANDLE | | | | SCHEDULED SERVICE |

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 04/10/2015 to 03/09/2025

System Code Range: **1100** to **9700**

Print Date: 5/21/2025

Asset# Range: **PT1503** to **PT1503**

| <u>BUS#</u> | <u>SYS Code</u> | <u>SYS Code Description</u> | | | <u>Cause-Reason</u> |
|---------------------|-----------------|-------------------------------|--|---|---------------------|
| PT1503 | 2501 | ACCIDENT DAMAGE REPAIR | Total Line Count for System Code 2501 : | | 8 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 1810538 | 1 | 07/05/2018 | 783 | ACCIDENT DAMAGE REPAIR | OPERATOR COMPLAINT |
| 1810538 | 2 | 07/05/2018 | 808 | PREP BODY PARTS | OPERATOR COMPLAINT |
| 1810538 | 3 | 07/05/2018 | 783 | REAR SUSPENSION KNUCKLE AND CONTROL ARM | OPERATOR COMPLAINT |
| 1815239 | 1 | 08/16/2018 | 759 | ACCIDENT DAMAGE REPAIR---PARTS ON ORDER | ACCIDENT |
| 1815239 | 2 | 08/16/2018 | 759 | ACCIDENT DAMAGE REPAIR--- | ACCIDENT |
| 1815239 | 3 | 08/16/2018 | 759 | ACCIDENT DAMAGE REPAIR--- | ACCIDENT |
| 1815239 | 4 | 08/16/2018 | 759 | ACCIDENT DAMAGE REPAIR--- | NORMAL WEAR |
| 1815239 | 5 | 08/16/2018 | 759 | ACCIDENT DAMAGE REPAIR--- | NORMAL WEAR |
| PT1503 | 2504 | BUS DECALS INSTALL | Total Line Count for System Code 2504 : | | 1 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 1804671 | 2 | 03/20/2018 | 780 | RR PALM TRAN DOOR DECALS | OPERATOR COMPLAINT |
| PT1503 | 2505 | WIPERS | Total Line Count for System Code 2505 : | | 7 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 1803222 | 2 | 02/21/2018 | 837 | R/R WIPER BLADES | SCHEDULED SERVICE |
| 1901819 | 4 | 01/31/2019 | 828 | REMOVE REAR WINDSHIELD WIPER ASSEMBLY | SCHEDULED SERVICE |
| 1901819 | 5 | 01/31/2019 | 828 | INSTALL NEW WIPER ARM & BLADE | SCHEDULED SERVICE |
| 2127451 | 1 | 10/14/2021 | 880 | R&R W/BLADES | OPERATOR COMPLAINT |
| 2114521 | 2 | 07/11/2021 | 828 | R/R WIPER BLADES | SCHEDULED SERVICE |
| 2122171 | 5 | 09/26/2021 | 853 | REAR BLADE ASSY | OPERATOR COMPLAINT |
| 2307524 | 2 | 03/27/2023 | 823 | install rear wiper | SCHEDULED SERVICE |

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 04/10/2015 to 03/09/2025 System Code Range: **1100** to **9700**

Print Date: 5/21/2025

Asset# Range: PT1503 to PT1503

| <u>BUS#</u> | <u>SYS Code</u> | <u>SYS Code Description</u> | | | <u>Cause-Reason</u> |
|---------------------|-----------------|-----------------------------|--|--|---------------------|
| PT1503 | 2511 | DRIVER SEATS | Total Line Count for System Code 2511 : | | 2 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 1804671 | 1 | 03/20/2018 | 780 | DRIVER SEATS-RR REAR BACK BOTTOM CUSHIONS COVERS BACK SPRING | OPERATOR COMPLAINT |
| 1804671 | 1 | 03/20/2018 | 837 | DRIVER SEATS-RR REAR BACK BOTTOM CUSHIONS COVERS BACK SPRING | OPERATOR COMPLAINT |
| PT1503 | 2600 | BRAKES | Total Line Count for System Code 2600 : | | 9 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 2101845 | 7 | 02/02/2021 | 833 | REPLCD RIGHT FRONT WHEEL LUGS--ALL 5 | SCHEDULED SERVICE |
| 1706111 | 2 | 04/13/2017 | 809 | INSTALLED BOLT BRAKE MASTER CYLINDER | SCHEDULED SERVICE |
| 2122171 | 7 | 09/26/2021 | 833 | INSPECTED BRAKE FLUID--CONTAMINATED/GREEN | OPERATOR COMPLAINT |
| 2122171 | 3 | 09/26/2021 | 828 | ROAD TEST---CK FOR ABS CODES--CK CHARGING SYSTEM--NEEDS A BATTERY, ALL ABS SENSORS | OPERATOR COMPLAINT |
| 2019725 | 2 | 10/06/2020 | 849 | brakes-flush brake fluis suck out drain in the resivoir and bleed dash call per tillnew fluid came out | SCHEDULED SERVICE |
| 2123022 | 4 | 10/18/2021 | 833 | SCAN FOR CODES | OPERATOR COMPLAINT |
| 2123022 | 2 | 10/18/2021 | 833 | FLUSH BRAKE SYSTEM & BLEED | OPERATOR COMPLAINT |
| 2123022 | 2 | 10/18/2021 | 833 | FLUSH BRAKE SYSTEM & BLEED | OPERATOR COMPLAINT |
| 2123022 | 5 | 10/18/2021 | 833 | REMOVE HARNESS FOR ABS-CK FOR BROKEN WIRES CORROSION OR BENT PINS | OPERATOR COMPLAINT |
| PT1503 | 2601 | TROUBLESHOOT BRAKES | Total Line Count for System Code 2601 : | | 3 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 2122171 | 8 | 09/26/2021 | 833 | FLUSH BRAKE FLUID--COMPLETE BRAKE SYSTEM FLUSHED/BLEED | OPERATOR COMPLAINT |
| 2122171 | 9 | 09/26/2021 | 833 | ABS WAS STICKING DUE TO CONTAMINATION--WORKING OK | OPERATOR COMPLAINT |
| 2122171 | 6 | 09/26/2021 | 833 | CODE FOR LOW BATTERY VOLTAGE, TCS CONTROL CHANNEL AND CONTROL MODULE | OPERATOR COMPLAINT |

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 04/10/2015 to 03/09/2025 System Code Range: **1100** to **9700**

Print Date: 5/21/2025

Asset# Range: PT1503 to PT1503

| <u>BUS#</u> | <u>SYS Code</u> | <u>SYS Code Description</u> | | | <u>Cause-Reason</u> |
|---------------------|-----------------|--------------------------------|--|--|---------------------|
| PT1503 | 2603 | FRONT RELINE | Total Line Count for System Code 2603 : | | 3 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 1803222 | 3 | 02/21/2018 | 837 | REMOVE FRONT BRAKES & ROTORS---WIP....WAITING FOR PARTS | SCHEDULED SERVICE |
| 1803222 | 4 | 02/21/2018 | 837 | INSTALL FRONT BRAKES/ROTORS | SCHEDULED SERVICE |
| 2101845 | 6 | 02/02/2021 | 833 | REPLCD FRONT BRAKE PADS & BRAKE ROTORS | SCHEDULED SERVICE |
| PT1503 | 2604 | REAR RELINE | Total Line Count for System Code 2604 : | | 2 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 1822352 | 7 | 10/29/2018 | 828 | rr brake pads and rotors | OPERATOR COMPLAINT |
| 2326455 | 3 | 11/08/2023 | 823 | r/r rear pads | SCHEDULED SERVICE |
| PT1503 | 2612 | TROUBLESHOOT ABS SYSTEM | Total Line Count for System Code 2612 : | | 1 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 2123022 | 1 | 10/18/2021 | 833 | SCAN -COCE V300 ACTIVE | OPERATOR COMPLAINT |
| PT1503 | 2800 | ENGINE | Total Line Count for System Code 2800 : | | 9 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 2210089 | 3 | 04/10/2022 | 823 | replace intake gasket and spark plugs | OPERATOR COMPLAINT |
| 2210089 | 1 | 04/10/2022 | 823 | need thermostat gasket, plugs r/r brake light intake gasket and 2 heater hoses | OPERATOR COMPLAINT |
| 2327970 | 3 | 11/29/2023 | 823 | r/r water pump, thermostat, alternator, belts and ac | OPERATOR COMPLAINT |
| 2327970 | 4 | 11/29/2023 | 823 | pcv valve n belt temsioner | OPERATOR COMPLAINT |
| 2424182 | 2 | 10/24/2024 | 833 | engine idle to working temp | OPERATOR COMPLAINT |
| 2424182 | 5 | 10/24/2024 | 833 | install rad fan asy | OPERATOR COMPLAINT |
| 2418468 | 3 | 08/02/2024 | 833 | Comnucation wire before throttle body and ecm was open. Repair wire and clear codes. | OPERATOR COMPLAINT |
| 1822352 | 9 | 10/29/2018 | 828 | replace oil pan plug on engine | OPERATOR COMPLAINT |
| 1827646 | 4 | 12/27/2018 | 828 | ADD OIL & COOLANT-- RESET OIL LIFE | OPERATOR COMPLAINT |

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 04/10/2015 to 03/09/2025

System Code Range: 1100 to 9700

Print Date: 5/21/2025

Asset# Range: PT1503 to PT1503

| <u>BUS#</u> | <u>SYS Code</u> | <u>SYS Code Description</u> | | | <u>Cause-Reason</u> |
|---------------------|-----------------|----------------------------------|--|---|---------------------|
| PT1503 | 2801 | TROUBLESHOOT ENGINE | Total Line Count for System Code 2801 : | | 4 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 1827646 | 3 | 12/27/2018 | 828 | TROUBLESHOOT ENGINE--LOW COOLANT--NEED TO RESET OIL LIFE | OPERATOR COMPLAINT |
| 2501129 | 1 | 03/09/2025 | 833 | After test driving and letting vehicle idle, transmission cooler is leaking | OPERATOR COMPLAINT |
| 2500817 | 1 | 01/10/2025 | 833 | Check for coolant leak found no leaks fan is working no leaks fan is working could not dupliacte overheating. | OPERATOR COMPLAINT |
| 2122171 | 1 | 09/26/2021 | 833 | TROUBLESHOOT ENGINE--ROAD TEST--NPF | OPERATOR COMPLAINT |
| PT1503 | 2803 | NO START | Total Line Count for System Code 2803 : | | 2 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 1916582 | 3 | 09/12/2019 | 752 | CHECK BATT CABLE AND CLEAN -CHECKED A/C FREON | OPERATOR COMPLAINT |
| 1916657 | 1 | 09/24/2019 | 849 | NO START---NEEDS BATTERY CIRCUIT BOARD | OPERATOR COMPLAINT |
| PT1503 | 2804 | STALLING | Total Line Count for System Code 2804 : | | 1 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 1822352 | 8 | 10/29/2018 | 828 | rr rear brkxae pads rotors and lug nuts | OPERATOR COMPLAINT |
| PT1503 | 2809 | AIR INTAKE SYSTEM REPAIR | Total Line Count for System Code 2809 : | | 1 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 1910116 | 6 | 06/07/2019 | 828 | REPAIR AIR FILTER HOUSING | OPERATOR COMPLAINT |
| PT1503 | 2810 | AIR FILTER REPL | Total Line Count for System Code 2810 : | | 3 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 1910116 | 7 | 06/07/2019 | 828 | REPLCD AIR INTAKE FILTER | OPERATOR COMPLAINT |
| 1903110 | 5 | 02/19/2019 | 828 | REPLCD AIR INTAKE FILTER | OPERATOR COMPLAINT |
| 1808433 | 2 | 04/26/2018 | 837 | R/R AIR FILTER | SCHEDULED SERVICE |
| PT1503 | 2814 | ENGINE BELTS REPL | Total Line Count for System Code 2814 : | | 1 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 1913367 | 1 | 07/25/2019 | 849 | REPLCD ALTERNATOR AC BELTS | OPERATOR COMPLAINT |
| PT1503 | 2816 | ENGINE GASKETS/SEALS REPL | Total Line Count for System Code 2816 : | | 1 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 2019725 | 3 | 10/06/2020 | 849 | ENGINE GASKETS SEALS REPLACED -REMOVED WIPRS COIL / BRKAE FLUID -TO REMOVE VALVE CC | SCHEDULED SERVICE |

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 04/10/2015 to 03/09/2025

System Code Range: 1100 to 9700

Print Date: 5/21/2025

Asset# Range: PT1503 to PT1503

| <u>BUS#</u> | <u>SYS Code</u> | <u>SYS Code Description</u> | | | <u>Cause-Reason</u> |
|---------------------|-----------------|----------------------------------|--|---|---------------------|
| PT1503 | 2818 | ENGINE MOUNTS REPL | Total Line Count for System Code 2818 : | | 2 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 2411472 | 6 | 05/31/2024 | 823 | R&R MOTOR MOUNT | OPERATOR COMPLAINT |
| 1903110 | 4 | 02/19/2019 | 828 | REPLCD ENGINE MOUNT & TOP TRANS MOUNT WITH BRACKET | OPERATOR COMPLAINT |
| PT1503 | 2900 | TRANSMISSION | Total Line Count for System Code 2900 : | | 4 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 1903110 | 1 | 02/19/2019 | 828 | TRANSMISSION---CK UNDER CARRIAGE--FOUND BAD TRANS MOUNT | OPERATOR COMPLAINT |
| 1910116 | 5 | 06/07/2019 | 828 | REPLCD SHIFTER CABLE FOR TRANS | OPERATOR COMPLAINT |
| 1910116 | 3 | 06/07/2019 | 828 | REMOVE INTAKE FILTER HOUSING--REMV CABLE END | OPERATOR COMPLAINT |
| 2219299 | 3 | 06/22/2022 | 833 | R/R TRANSMISSION SHIFTER CABLE | OPERATOR COMPLAINT |
| PT1503 | 2901 | TROUBLESHOOT TRANSMISSION | Total Line Count for System Code 2901 : | | 2 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 2219299 | 1 | 06/22/2022 | 823 | T/S TRANSMISSION | OPERATOR COMPLAINT |
| 1910116 | 4 | 06/07/2019 | 828 | NEEDS TRAN CABLE& INTAKE FILTER HOUSING | OPERATOR COMPLAINT |
| PT1503 | 2918 | TRANS MOUNT REPLACE | Total Line Count for System Code 2918 : | | 2 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 1903110 | 2 | 02/19/2019 | 828 | REPLCD BOTTOM TRANS MOUNT | OPERATOR COMPLAINT |
| 2411472 | 7 | 05/31/2024 | 823 | R&R TRANS MOUNT | OPERATOR COMPLAINT |

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 04/10/2015 to 03/09/2025

System Code Range: 1100 to 9700

Print Date: 5/21/2025

Asset# Range: PT1503 to PT1503

| <u>BUS#</u> | <u>SYS Code</u> | <u>SYS Code Description</u> | | | <u>Cause-Reason</u> |
|---------------------|-----------------|-----------------------------|--|---|---------------------|
| PT1503 | 4000 | TIRES | Total Line Count for System Code 4000 : | | 10 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 2226883 | 2 | 09/07/2022 | 797 | REPLACE 9 LUG NUTS | SCHEDULED SERVICE |
| 2302668 | 1 | 02/09/2023 | 833 | SLOW LEAK IN R/R TIRE | OPERATOR COMPLAINT |
| 2008118 | 2 | 05/07/2020 | 849 | ROTATED TIRES | OPERATOR COMPLAINT |
| 2008617 | 1 | 05/12/2020 | 797 | TIRES CHECK LEFT REAR TIRE AND REMOVE SCREW AND PLUG HOLE ADJ PRESSURE | OPERATOR COMPLAINT |
| 2008617 | 2 | 05/12/2020 | 797 | ADJ ALL TIRE PRESSURE | OPERATOR COMPLAINT |
| 2122171 | 2 | 09/26/2021 | 833 | CK AIR PRESSURE IN ALL TIRES--TPMS SENSOR MISSING | OPERATOR COMPLAINT |
| 1701927 | 2 | 02/03/2017 | 828 | ROTATE AND AIR UP TIRES | SCHEDULED SERVICE |
| 2101845 | 2 | 02/02/2021 | 828 | REPLCD LEFT REAR LUGNUTS | SCHEDULED SERVICE |
| 1827646 | 2 | 12/27/2018 | 828 | CK ALL TIRES--GOOD AIR PRESSURE--LEFT REAR SENSOR WILL OT PICK UP SIGNAL FROM TPMS RE | OPERATOR COMPLAINT |
| 1822352 | 5 | 10/29/2018 | 828 | replace all tires tpms sensor not picking up signal | OPERATOR COMPLAINT |
| PT1503 | 4011 | L/F TIRE REPLACEMENT | Total Line Count for System Code 4011 : | | 5 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 1615468 | 1 | 11/08/2016 | 752 | L/F TIRE EPLACEMENT -INSTALLED NEW TIRE | OPERATOR COMPLAINT |
| 1913219 | 3 | 07/24/2019 | 820 | R/R ;EFT FRONT TIRE | OPERATOR COMPLAINT |
| 1912910 | 3 | 07/15/2019 | 849 | REPLCD RF TIRE--ROTATE | SCHEDULED SERVICE |
| 2408346 | 2 | 04/20/2024 | 823 | If tire replace | SCHEDULED SERVICE |
| 2431765 | 1 | 12/28/2024 | 909 | R&R R/F TIRE | OPERATOR COMPLAINT |

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 04/10/2015 to 03/09/2025

System Code Range: 1100 to 9700

Print Date: 5/21/2025

Asset# Range: PT1503 to PT1503

| <u>BUS#</u> | <u>SYS Code</u> | <u>SYS Code Description</u> | | | <u>Cause-Reason</u> |
|---------------------|-----------------|-------------------------------|--|--|---------------------|
| PT1503 | 4012 | R/F TIRE REPLACEMENT | Total Line Count for System Code 4012 : | | 5 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 2408346 | 3 | 04/20/2024 | 823 | rf tire replace | SCHEDULED SERVICE |
| 1801147 | 3 | 01/22/2018 | 818 | RR RIGHT FRONT TIRE | OPERATOR COMPLAINT |
| 1801147 | 3 | 01/22/2018 | 849 | RR RIGHT FRONT TIRE | OPERATOR COMPLAINT |
| 1716488 | 2 | 09/14/2017 | 809 | R/R RIGHT FRONT TIRE | SCHEDULED SERVICE |
| 1615468 | 2 | 11/08/2016 | 752 | R/F TIRE REPLACEMENT -INSTALLED NEW TIRE | OPERATOR COMPLAINT |
| PT1503 | 4014 | L/R/I TIRE REPLACEMENT | Total Line Count for System Code 4014 : | | 1 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 2408346 | 5 | 04/20/2024 | 823 | l/r tire replace | SCHEDULED SERVICE |
| PT1503 | 4015 | R/R/O TIRE REPLACEMENT | Total Line Count for System Code 4015 : | | 1 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 2408346 | 4 | 04/20/2024 | 823 | r/r tire replace | SCHEDULED SERVICE |
| PT1503 | 5002 | RADIOS | Total Line Count for System Code 5002 : | | 4 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 2304068 | 1 | 02/16/2023 | 901 | signal loss, found broken antenna, replace antenna | OPERATOR COMPLAINT |
| 1513424 | 1 | 09/24/2015 | 641 | RADIOS | SCHEDULED SERVICE |
| 1801365 | 1 | 01/23/2018 | 29 | RADIOS | OPERATOR COMPLAINT |
| 1801703 | 1 | 01/25/2018 | 27 | RADIOS | SCHEDULED SERVICE |
| PT1503 | 5004 | AVL -- Repairs | Total Line Count for System Code 5004 : | | 2 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 1512773 | 1 | 09/11/2015 | 713 | AVL REPAIRS | OPERATOR COMPLAINT |
| 2023197 | 1 | 11/22/2020 | 27 | AVL---REPAIRS | SCHEDULED SERVICE |

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 04/10/2015 to 03/09/2025

System Code Range: 1100 to 9700

Print Date: 5/21/2025

Asset# Range: PT1503 to PT1503

| BUS# | SYS Code | SYS Code Description | | | Total Line Count for System Code | Cause-Reason |
|---------------------|-----------------|--------------------------------|------------------|--|---|----------------------------|
| PT1503 | 8010 | TRAVEL TIME - Road Call | | | 8 | |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | | <u>Cause-Reason</u> |
| 2327970 | 1 | 11/29/2023 | 909 | travel | | MAJOR MECHANICAL BREAKDOWN |
| 2418468 | 1 | 08/02/2024 | 809 | Swap w/ 1911 | | MAJOR MECHANICAL BREAKDOWN |
| 2418468 | 1 | 08/02/2024 | 929 | Swap w/ 1911 | | MAJOR MECHANICAL BREAKDOWN |
| 1910116 | 1 | 06/07/2019 | 752 | TRAVEL TIME--ROAD CALL-- | | OTHER MECHANICAL BREAKDOWN |
| 1916582 | 1 | 09/12/2019 | 752 | TRAVEL TIMEROAD CALL | | MAJOR MECHANICAL BREAKDOWN |
| 1913219 | 1 | 07/24/2019 | 820 | TRAVEL TIME--ROAD CALL-- | | MAJOR MECHANICAL BREAKDOWN |
| 1801147 | 1 | 01/22/2018 | 818 | TRAVEL TIME ROAD CALL -SERVICE ROAD CALL | | MAJOR MECHANICAL BREAKDOWN |
| 1801147 | 1 | 01/22/2018 | 849 | TRAVEL TIME ROAD CALL -SERVICE ROAD CALL | | MAJOR MECHANICAL BREAKDOWN |
| PT1503 | 8011 | TROUBLESHOOT ROAD CALL | | | 7 | |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | | <u>Cause-Reason</u> |
| 1801147 | 2 | 01/22/2018 | 818 | T/S ROAD CALL -RIGHT FRONT TIRE FLAT | | OPERATOR COMPLAINT |
| 1801147 | 2 | 01/22/2018 | 849 | T/S ROAD CALL -RIGHT FRONT TIRE FLAT | | OPERATOR COMPLAINT |
| 1913219 | 2 | 07/24/2019 | 820 | TROUBLESHOOT ROAD CALL---FLAT LEFT SIDE TIRE | | OPERATOR COMPLAINT |
| 1916582 | 2 | 09/12/2019 | 752 | T/S ROAD CALL | | OPERATOR COMPLAINT |
| 1910116 | 2 | 06/07/2019 | 752 | TROUBLESHOOT ROAD CALL--BROKEN SHIFTER CABLE | | OPERATOR COMPLAINT |
| 2418468 | 2 | 08/02/2024 | 833 | P2111-00 scanned codes and did a visual check. | | OPERATOR COMPLAINT |
| 2327970 | 2 | 11/29/2023 | 823 | t/s | | OPERATOR COMPLAINT |

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 04/10/2015 to 03/09/2025

System Code Range: **1100** to **9700**

Print Date: 5/21/2025

Asset# Range: PT1503 to PT1503

| BUS# | SYS Code | SYS Code Description | | | Total Line Count for System Code | | Cause-Reason |
|---------------------|-----------------|---------------------------------------|------------------|---|---|--|---------------------|
| PT1503 | 8020 | MISCELLANEOUS Travel Time | | | 8 | | |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | | | <u>Cause-Reason</u> |
| 2123022 | 7 | 10/18/2021 | 627 | PICK UP VEHICLE FROM DEALER | | | OPERATOR COMPLAINT |
| 2123022 | 7 | 10/18/2021 | 848 | PICK UP VEHICLE FROM DEALER | | | OPERATOR COMPLAINT |
| 2101845 | 4 | 02/02/2021 | 827 | DROP OFF @ELPIX TO REPLC TIRES | | | SCHEDULED SERVICE |
| 2101845 | 4 | 02/02/2021 | 752 | DROP OFF @ELPIX TO REPLC TIRES | | | SCHEDULED SERVICE |
| 2101845 | 5 | 02/02/2021 | 827 | P/UP VEHICLE FROM ELPIX--TIRES INSTALLED | | | SCHEDULED SERVICE |
| 2101845 | 5 | 02/02/2021 | 752 | P/UP VEHICLE FROM ELPIX--TIRES INSTALLED | | | SCHEDULED SERVICE |
| 1810538 | 5 | 07/05/2018 | 683 | ABS LIGHT ON -REPAIRED TRACTION CONTROL LIGHT ON- WIP | | | TRANSPORT |
| 1810538 | 5 | 07/05/2018 | 642 | ABS LIGHT ON -REPAIRED TRACTION CONTROL LIGHT ON- WIP | | | TRANSPORT |
| PT1503 | 8060 | DRIVE TO DEALER | | | 3 | | |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | | | <u>Cause-Reason</u> |
| 2123022 | 6 | 10/18/2021 | 627 | DROP VEHICLE OFF AT DEALER | | | OPERATOR COMPLAINT |
| 2123022 | 6 | 10/18/2021 | 848 | DROP VEHICLE OFF AT DEALER | | | OPERATOR COMPLAINT |
| 2000821 | 4 | 02/10/2020 | 828 | PICK UP FROM FORD | | | OPERATOR COMPLAINT |
| PT1503 | 9100 | IN SRVC GOLF/CAR/TRUC/VAN P.M. | | | 2 | | |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | | | <u>Cause-Reason</u> |
| 1505752 | 2 | 04/10/2015 | 828 | inservice p.m performed | | | SCHEDULED SERVICE |
| 1505752 | 1 | 04/10/2015 | 781 | in service golf/van/truck/car pm | | | SCHEDULED SERVICE |

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 04/10/2015 to 03/09/2025

System Code Range: **1100** to **9700**

Print Date: 5/21/2025

Asset# Range: **PT1503** to **PT1503**

| <u>BUS#</u> | <u>SYS Code</u> | <u>SYS Code Description</u> | | | <u>Cause-Reason</u> |
|---------------------|-----------------|-----------------------------|--|--------------------------------|---------------------|
| PT1503 | 9103 | 4,000 MILE PM CARS | Total Line Count for System Code 9103 : | | 5 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 1600042 | 1 | 01/05/2016 | 828 | 4.000 mile pm | SCHEDULED SERVICE |
| 1706111 | 1 | 04/13/2017 | 809 | 4.000 MILE PM | SCHEDULED SERVICE |
| 1808433 | 1 | 04/26/2018 | 837 | 4K MILE PM CARS---COMPLETED | SCHEDULED SERVICE |
| 2008118 | 1 | 05/07/2020 | 849 | 4.000 MILE PM CARS | OPERATOR COMPLAINT |
| 2226883 | 1 | 09/07/2022 | 797 | 4K PM | SCHEDULED SERVICE |
| PT1503 | 9108 | 8,000 MILE PM CARS | Total Line Count for System Code 9108 : | | 5 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 2233284 | 1 | 12/18/2022 | 887 | 8K PM | OPERATOR COMPLAINT |
| 2019061 | 1 | 09/28/2020 | 849 | 8K MILE PM CARS---COMPLETED | SCHEDULED SERVICE |
| 1823936 | 1 | 11/05/2018 | 781 | 8.000 MILE PM CARS | SCHEDULED SERVICE |
| 1711454 | 1 | 06/30/2017 | 752 | 8.000 MILE PM | OPERATOR COMPLAINT |
| 1604429 | 1 | 03/29/2016 | 828 | 8K MILE PM CARS-COMPLETED | SCHEDULED SERVICE |
| PT1503 | 9112 | 12,000 MILE PM CARS | Total Line Count for System Code 9112 : | | 4 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 2101845 | 1 | 02/02/2021 | 828 | 12K MILE PM CARS---COMPLETED | SCHEDULED SERVICE |
| 1901819 | 1 | 01/31/2019 | 828 | 12K MILE PM---CARS---COMPLETED | SCHEDULED SERVICE |
| 1608682 | 1 | 06/20/2016 | 773 | 12K MILE PM CARS-COMPLETED | SCHEDULED SERVICE |
| 2307524 | 1 | 03/27/2023 | 823 | pm | SCHEDULED SERVICE |

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 04/10/2015 to 03/09/2025

System Code Range: **1100** to **9700**

Print Date: 5/21/2025

Asset# Range: **PT1503** to **PT1503**

| <u>BUS#</u> | <u>SYS Code</u> | <u>SYS Code Description</u> | | | <u>Cause-Reason</u> |
|---------------------|-----------------|-----------------------------|--|--|---------------------|
| PT1503 | 9116 | 16,000 MILE PM CARS | Total Line Count for System Code 9116 : | | 4 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 2114521 | 1 | 07/11/2021 | 828 | 16K MILE PM CARS--COMPLETED | SCHEDULED SERVICE |
| 1907546 | 1 | 04/30/2019 | 828 | 16K MILE PM CARS----COMPLETED | SCHEDULED SERVICE |
| 1716488 | 1 | 09/14/2017 | 809 | 16K MILE PM CARS---COMPLETED | OPERATOR COMPLAINT |
| 1612785 | 1 | 09/07/2016 | 832 | 16K MILE PM CARS---COMPLETED | SCHEDULED SERVICE |
| PT1503 | 9120 | 20,000 MILE PM CARS | Total Line Count for System Code 9120 : | | 5 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 1616345 | 1 | 11/16/2016 | 780 | 20.000 MILE PM CARS | OPERATOR COMPLAINT |
| 1912910 | 1 | 07/15/2019 | 849 | 20K MILE PM CARS---COMPLETED | SCHEDULED SERVICE |
| 1721841 | 1 | 12/06/2017 | 841 | 20K MILE PM CARS---COMPLETE | OPERATOR COMPLAINT |
| 2134642 | 1 | 12/16/2021 | 833 | 20K PM COMPLETED | SCHEDULED SERVICE |
| 2408346 | 1 | 04/20/2024 | 823 | pm | SCHEDULED SERVICE |
| PT1503 | 9124 | 24,000 MILE PM CARS | Total Line Count for System Code 9124 : | | 5 |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | <u>Cause-Reason</u> |
| 2420171 | 1 | 08/23/2024 | 833 | PM compete Recommand service until rear tires replace. | OPERATOR COMPLAINT |
| 2214928 | 1 | 05/10/2022 | 823 | DONE | SCHEDULED SERVICE |
| 1701927 | 1 | 02/03/2017 | 828 | 24K MILE PM CARS---COMPLETED | SCHEDULED SERVICE |
| 1920734 | 1 | 11/07/2019 | 781 | 24K MILE PM CARS---COMPLETED | SCHEDULED SERVICE |
| 1803222 | 1 | 02/21/2018 | 827 | 24K MILE PM CARS----COMPLETED | SCHEDULED SERVICE |

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 04/10/2015 to 03/09/2025

System Code Range: **1100** to **9700**

Print Date: 5/21/2025

Asset# Range: **PT1503** to **PT1503**

| <u>BUS#</u> | <u>SYS Code</u> | <u>SYS Code Description</u> | | | Total Line Count for System Code 9700 : | 27 | <u>Cause-Reason</u> |
|---------------------|-----------------|-----------------------------|------------------|---|--|-----------|---------------------|
| PT1503 | 9700 | TEST RUN/ROAD TEST | | | | | |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | | | |
| 1822352 | 2 | 10/29/2018 | 828 | OVERHEATED WHILE ROAD TESTING | | | OPERATOR COMPLAINT |
| | | | | | | | SCHEDULED SERVICE |
| 1803222 | 5 | 02/21/2018 | 837 | ROAD TEST | | | OPERATOR COMPLAINT |
| 1822352 | 10 | 10/29/2018 | 828 | road test | | | SCHEDULED SERVICE |
| 1907546 | 7 | 04/30/2019 | 828 | ROAD TEST---OK | | | OPERATOR COMPLAINT |
| 1921816 | 3 | 11/23/2019 | 828 | NO PROBLEM FOUND @THIS TIME | | | OPERATOR COMPLAINT |
| 2106186 | 4 | 03/26/2021 | 833 | ROAD TEST | | | OPERATOR COMPLAINT |
| 1903110 | 3 | 02/19/2019 | 828 | ROAD TEST--STILL MAKES NOISE | | | OPERATOR COMPLAINT |
| 1810538 | 7 | 07/05/2018 | 746 | ROAD TEST | | | SCHEDULED SERVICE |
| 1808433 | 4 | 04/26/2018 | 837 | ROAD TEST | | | OPERATOR COMPLAINT |
| 2217073 | 2 | 06/02/2022 | 823 | ROAD TEST | | | OPERATOR COMPLAINT |
| 2210089 | 5 | 04/10/2022 | 823 | test drive | | | OPERATOR COMPLAINT |
| 2210089 | 7 | 04/10/2022 | 823 | test run | | | OPERATOR COMPLAINT |
| 2123022 | 3 | 10/18/2021 | 833 | ROAD TEST VEHICLE NO PROBLEM FOUND | | | OPERATOR COMPLAINT |
| 2209443 | 2 | 03/22/2022 | 823 | ROAD TEST | | | OPERATOR COMPLAINT |
| 2122171 | 10 | 09/26/2021 | 833 | ROAD TEST---OK | | | OPERATOR COMPLAINT |
| 2120361 | 2 | 08/11/2021 | 869 | ROAD TEST | | | OPERATOR COMPLAINT |
| 2119870 | 5 | 08/03/2021 | 833 | ROAD TEST | | | OPERATOR COMPLAINT |
| 2420171 | 2 | 08/23/2024 | 833 | Went and pick up 1503 in the tire shopo and brought it back. Both rear tires where replace. | | | OPERATOR COMPLAINT |

Report Description: Work Order History by Asset and System Code

WO Close Date Range: 04/10/2015 to 03/09/2025

System Code Range: **1100** to **9700**

Print Date: 5/21/2025

Asset# Range: **PT1503** to **PT1503**

| BUS# | SYS Code | SYS Code Description | | | Total Line Count for System Code 9700 : | 27 | Cause-Reason |
|---------------------|-----------------|-----------------------------|------------------|--|--|-----------|---------------------|
| PT1503 | 9700 | TEST RUN/ROAD TEST | | | | | |
| <u>Work Order #</u> | <u>Line#</u> | <u>Close Date</u> | <u>Employee#</u> | <u>Description of Work</u> | | | |
| 2418468 | 4 | 08/02/2024 | 833 | Test drove 10 miles no issues no codes. | | | OPERATOR COMPLAINT |
| 2411472 | 8 | 05/31/2024 | 823 | ROAD TEST | | | OPERATOR COMPLAINT |
| 2411472 | 5 | 05/31/2024 | 823 | ROAD TEST, STILL NEED MOTOR AND TRANS MOUNTS (POO) WIP | | | OPERATOR COMPLAINT |
| 2500817 | 2 | 01/10/2025 | 833 | Test drove for 15 miles A/C works and vehicle does not overheat. | | | OPERATOR COMPLAINT |
| 2328339 | 5 | 12/11/2023 | 823 | road test | | | OPERATOR COMPLAINT |
| 2326455 | 5 | 11/08/2023 | 823 | test run | | | SCHEDULED SERVICE |
| 2300739 | 2 | 01/18/2023 | 823 | ROAD TEST | | | OPERATOR COMPLAINT |
| 2308352 | 2 | 04/05/2023 | 823 | ROAD TEST | | | OPERATOR COMPLAINT |
| 2315831 | 2 | 07/09/2023 | 849 | test drove in road condition for one hour did not overheat, temp gauge stayed in normal area at all times. | | | OPERATOR COMPLAINT |