

10/17/2025
9:39:48 AM

Palm Beach County Fleet Management Asset Maintenance History
10208134 2018 TOYOTA PRIUS Car, Mid Size, Hybrid

Total Hours: 112.00 Labor: 8,081.00 Parts: 5,898.97 Comm: 1,587.11 Charged: 15567.08

Work Order: 1806290 **Meter:** 131 **In Date:** 06/19/2018 **Closed:** 06/21/2018
Problem: pre delivery inspection

Work Completed

- pre delivery inspection
- Shop Supplies

Parts Issued

	Quantity
Shop Supplies	1.00

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 2.00 Total: 122.00

Work Order: 1812299 **Meter:** 5095 **In Date:** 12/03/2018 **Closed:** 12/13/2018
Problem: P.M. Service.Recall.

Work Completed

- P.m. service.
- Rotate and balance all four tires. Nitrogen fill tires.
- Transport to and from dealer for recall 18v579 .
- Shop Supplies

Parts Issued

	Quantity
Napagold Oil Filter	1.00
Syn0w20	5.00
Shop Supplies	1.00

Hours: 5.00 Comm: 0.00 Labor: 335.00 Parts: 35.22 Total: 370.22

Work Order: 1904947 **Meter:** 9055 **In Date:** 05/07/2019 **Closed:** 05/13/2019
Problem: Check engine light on .

Work Completed

- Computer diagnose check engine light , code P05a0 . Inspect and replace damaged front grill and radiator shutter assembly .retest and clear codes .
- Shop Supplies

Parts Issued

	Quantity
Shutter Assy	1.00
Grille Rad	1.00
Shop Supplies	1.00

Hours: 3.50 Comm: 0.00 Labor: 234.50 Parts: 504.27 Total: 738.77

10/17/2025
9:39:48 AM

Palm Beach County Fleet Management Asset Maintenance History
10208134 2018 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 2100925 **Meter:** 28348 **In Date:** 01/26/2021 **Closed:** 02/04/2021
Problem: pm service

Work Completed

- Preventive Maint. Service
- Test drive
- Replace worn tires
- Replace cabin air filter
- Shop Supplies

Parts Issued

Quantity

Washer Fluid Concentr	1.00
Wiper Blade Rear	1.00
Front Wiper Blade Prius	1.00
Front Wipre Blade 2016 Prius	1.00
Syn0w20	5.00
Napagold Oil Filter	1.00
Tire Mic 195/65/15	4.00
Cabin Filter	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 4.50

Comm: 0.00

Labor: 328.50 Parts: 663.32 Total: 991.82

Work Order: 2104259 **Meter:** 33367 **In Date:** 04/15/2021 **Closed:** 04/20/2021
Problem: pm service

Work Completed

- pm service
- replaced cabin filter and cleaned evap
- rotate and balance
- test drive
- Shop Supplies

Parts Issued

Quantity

Washer Fluid Concentr	1.00
Wiper Blade Rear	1.00
Front Wiper Blade Prius	1.00
Front Wipre Blade 2016 Prius	1.00
Napagold Oil Filter	1.00
Syn0w20	5.00
Napa Gold Air Filter	1.00
Cabin Air Filter	1.00
Shop Supplies	1.00

Hours: 4.50

Comm: 0.00

Labor: 328.50 Parts: 182.49 Total: 510.99

10/17/2025
9:39:48 AM

Palm Beach County Fleet Management Asset Maintenance History
10208134 2018 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 2203324 **Meter:** 54322 **In Date:** 03/29/2022 **Closed:** 04/12/2022
Problem: PM Service.

Work Completed

- Preventive Maintenance Service
- Rotate and balance tires
- Test Drive
- Shop Supplies

Parts Issued

Quantity

Syn0w20	5.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade Rear	1.00
Front Wipre Blade 2016 Prius	1.00
Front Wiper Blade Prius	1.00
Shop Supplies	1.00

Hours: 3.50

Comm: 0.00

Labor: 255.50 Parts: 109.12 Total: 364.62

Work Order: 2206761 **Meter:** 59630 **In Date:** 06/27/2022 **Closed:** 06/30/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- balance and rotate all 4 tires . Nitro fill all. Replace missing wheel cover
- check,replaced cabin a/c filter and refresh intake air
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Syn0w20	5.00
Front Wiper Blade Prius	1.00
Front Wipre Blade 2016 Prius	1.00
Wiper Blade Rear	1.00
Syn0w20	5.00
Cap Wheel	1.00
Cabin Air Filter	1.00
Shop Supplies	1.00

Hours: 3.50

Comm: 0.00

Labor: 255.50 Parts: 250.91 Total: 506.41

10/17/2025
9:39:48 AM

Palm Beach County Fleet Management Asset Maintenance History
10208134 2018 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 2301927 **Meter:** 74592 **In Date:** 02/27/2023 **Closed:** 03/13/2023
Problem: PM Service. Send for Detail ,check dome light switch .

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Inspect Dome Lamp Switch And Found Faulty. Replace Dome Lamp Switch Assembly And Verify Repair Complete.
- Rotate And Balance Four Tires. Relearn Tire Sensors.
- Shop Supplies

Napagold Oil Filter	1.00
Syn0w20	5.00
Washer Fluid Concentr	1.00
16in Exactfit-rear	1.00
17in Exactfit-hbrd	1.00
26in Exactfit-hbrd	1.00
Front Wiper Blade Prius	1.00
Front Wipre Blade 2016 Prius	1.00
Dome Lamp Assy	1.00
Shop Supplies	1.00

Hours: 3.80

Comm: 0.00

Labor: 277.40

Parts: 289.79

Total: 567.19

Work Order: 2302357 **Meter:** 74551 **In Date:** 03/07/2023 **Closed:** 03/08/2023
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued WO: 2301927 for: Jerry Wade

Work Completed

- 1 - Detail Vehicle Wash Ticket(s) Issued Wo: 2301927 for: Jerry Wade

Hours: 0.00

Comm: 84.75

Labor: 0.00

Parts: 0.00

Total: 84.75

Work Order: 2304555 **Meter:** 78182 **In Date:** 05/08/2023 **Closed:** 05/10/2023
Problem: left front flat

Work Completed

Parts Issued

Quantity

- Repair right front tire, reset
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 2.65

Total: 75.65

10/17/2025
9:39:48 AM

Palm Beach County Fleet Management Asset Maintenance History
10208134 2018 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 2402874 **Meter:** 94714 **In Date:** 02/29/2024 **Closed:** 03/21/2024
Problem: Damage to left side of front bumper.

Work Completed

- Damage to left side of front bumper.

Hours: 0.00 Comm: 1,271.89 Labor: 0.00 Parts: 0.00 Total: 1,271.89

Work Order: 2405392 **Meter:** 99652 **In Date:** 05/31/2024 **Closed:** 06/10/2024
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Rotate and speed balance, nitro fill
- Inspect all worn, R & i Front and rear brake pads, Resurface front rotors , R & i new rear rotors Burnish rotors on road test
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Syn0w20	4.00
Washer Fluid Concentr	1.00
Wiper Blade Rear	1.00
Front Wipre Blade 2016 Prius	1.00
Front Wiper Blade Prius	1.00
Non-chlor Brake Clnr	1.00
Brake Pads	1.00
Brake Rotor	2.00
Brake Pad	1.00
Shop Supplies	1.00

Hours: 8.00 Comm: 0.00 Labor: 584.00 Parts: 400.32 Total: 984.32

10/17/2025
9:39:48 AM

Palm Beach County Fleet Management Asset Maintenance History
10208134 2018 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 2411610 **Meter:** 110110 **In Date:** 12/09/2024 **Closed:** 12/26/2024

Problem: PM Service. Drivers Window makes loud "pop" sound when going down.

Work Completed

- Preventive Maint. Service
- R & i door trim necessary to repair popping noise in door when going down, lube regulator, trim & run channel
- Rotate and speed balance, nitro fill
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Syn0w20	5.00
Washer Fluid Concentr	1.00
Wiper Blade Rear	1.00
Front Wiper Blade Prius	1.00
Front Wipre Blade 2016 Prius	1.00
Regulador	1.00
Door Check	1.00
Shop Supplies	1.00

Hours: 4.00

Comm: 0.00

Labor: 292.00 Parts: 288.53 Total: 580.53

Work Order: 2502325 **Meter:** 114937 **In Date:** 03/10/2025 **Closed:** 03/19/2025

Problem: PM Service.

Work Completed

- perform Preventive Maint. Service
- perform balance rotate and nitro fill, tpms relearn
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Syn0w20	5.00
Washer Fluid Concentr	1.00
Wiper Blade Rear	1.00
16in Exactfit-beam	1.00
28in Exactfit-beam	1.00
Shop Supplies	1.00

Hours: 3.00

Comm: 0.00

Labor: 219.00 Parts: 78.39 Total: 297.39

Work Order: 2503713 **Meter:** 117193 **In Date:** 04/22/2025 **Closed:** 04/23/2025

Problem: Flat Tire

Work Completed

- Check & Repair Rr tire nail in, rebalance
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 73.00 Parts: 2.65 Total: 75.65

10/17/2025
9:39:48 AM

Palm Beach County Fleet Management Asset Maintenance History
10208134 2018 TOYOTA PRIUS Car, Mid Size, Hybrid

Work Order: 2504723 **Meter:** 119517 **In Date:** 05/20/2025 **Closed:** 06/05/2025
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Rotate and speed balance, nitro fill
- Check & replace remote battery low
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Syn0w20	5.00
Washer Fluid Concentr	1.00
16in Exactfit-rear	1.00
16in Exactfit-beam	1.00
28in Exactfit-beam	1.00
Enr Elect Battery	1.00
Shop Supplies	1.00

Hours: 3.20

Comm: 0.00

Labor: 233.60

Parts: 73.29

Total: 306.89

Work Order: 2508357 **Meter:** 124382 **In Date:** 09/04/2025 **Closed:** 09/05/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

Total Hours: 112.00

Total Labor: 8,081.00

Total Comm: 1,587.11

Total Parts: 5,898.97