

10/17/2025
10:24:20 AM

Palm Beach County Fleet Management Asset Maintenance History
10203956 2018 FORD F150 Pickup, 1/2 Ton, 4X4

Total Hours: 153.00 Labor: 10,960.75 Parts: 8,149.88 Comm: 0.00 Charged: 19110.63

Work Order: 1801107 **Meter:** 0 **In Date:** 01/30/2018 **Closed:** 02/01/2018
Problem: pre delivery inspection

Work Completed

- pre delivery inspection
- Shop Supplies

Hours: 2.00

Comm: 0.00

Parts Issued

| | Quantity |
|---------------|-----------------|
| Shop Supplies | 1.00 |

Labor: 120.00

Parts: 2.00

Total: 122.00

Work Order: 1806262 **Meter:** 3091 **In Date:** 06/19/2018 **Closed:** 06/27/2018
Problem: PM Service

Work Completed

- P.m. service.
- R&r left front door outside belt molding . loose coming up with window operation.
- Rotate and balance all four tires.
- Shop Supplies

Hours: 4.25

Comm: 0.00

Parts Issued

| | Quantity |
|-----------------------|-----------------|
| Napagold Oil Filter | 1.00 |
| 5w20 Engine Oil | 7.00 |
| Washer Fluid Concentr | 1.00 |
| Ford Triton Pvc Swc | 1.00 |
| Floor Mat-2pc Rub Bk | 1.00 |
| Door Molding | 1.00 |
| Shop Supplies | 1.00 |

Labor: 255.00

Parts: 156.46

Total: 411.46

Work Order: 1806655 **Meter:** 3182 **In Date:** 06/28/2018 **Closed:** 06/29/2018
Problem: needs 1 spare key

Work Completed

- order and program 1 spare key
- Shop Supplies

Hours: 1.00

Comm: 0.00

Parts Issued

| | Quantity |
|---------------|-----------------|
| ford side key | 1.00 |
| Shop Supplies | 1.00 |

Labor: 60.00

Parts: 84.29

Total: 144.29

10/17/2025
10:24:20 AM

Palm Beach County Fleet Management Asset Maintenance History
10203956 2018 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 1905884 **Meter:** 20164 **In Date:** 06/04/2019 **Closed:** 06/10/2019
Problem: P.M. Service.Left rear flat.

Work Completed

Parts Issued

Quantity

- P.m. service.
- Repair left rear tire . Rotate and high speed balance all four tires . Nitrofill all.
- Shop Supplies

| | |
|-------------------------|------|
| Napagold Oil Filter | 1.00 |
| 5w20 Engine Oil | 6.00 |
| Napagold Air Filter | 1.00 |
| Mac Wite Lithium Gres | 1.00 |
| Used Fire X Refurbished | 1.00 |
| 22" Wiper Blade | 2.00 |
| Shop Supplies | 1.00 |

Hours: 4.75

Comm: 0.00

Labor: 318.25 Parts: 57.96 Total: 376.21

Work Order: 1909695 **Meter:** 25685 **In Date:** 09/20/2019 **Closed:** 09/30/2019
Problem: PM Service

Work Completed

Parts Issued

Quantity

- P.m. service .
- Rotate and balance all four tires . Nitrofill all.
- Shop Supplies

| | |
|-----------------------|------|
| Napagold Oil Filter | 1.00 |
| 5w20 Engine Oil | 7.00 |
| Washer Fluid Concentr | 1.00 |
| 22" Wiper Blade | 2.00 |
| Shop Supplies | 1.00 |

Hours: 3.75

Comm: 0.00

Labor: 251.25 Parts: 35.37 Total: 286.62

Work Order: 1912203 **Meter:** 28984 **In Date:** 11/26/2019 **Closed:** 11/27/2019
Problem: Left tail light put.

Work Completed

Parts Issued

Quantity

- Replace left tail light bulb.

| | |
|------------------|------|
| Boxed Miniatures | 1.00 |
|------------------|------|

Hours: 0.50

Comm: 0.00

Labor: 36.50 Parts: 0.77 Total: 37.27

10/17/2025
10:24:20 AM

Palm Beach County Fleet Management Asset Maintenance History
10203956 2018 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 1912420 **Meter:** 29718 **In Date:** 12/04/2019 **Closed:** 12/10/2019
Problem: Spare on left rear ,flat tire in bed .

Work Completed

Parts Issued

Quantity

- Repair left rear tire and balance . Remount spare . Nitrofill all.
- Shop Supplies

Shop Supplies 1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 4.00 Total: 77.00

Work Order: 1913189 **Meter:** 30995 **In Date:** 12/31/2019 **Closed:** 01/13/2020
Problem: P.M. service.

Work Completed

Parts Issued

Quantity

- P.m. service .
- Replace two tires . Rotate and balance all four tires . Nitrofill all and reset Tpms .
- Perform complete front end alignment and road test .
- Shop Supplies

5w20 Engine Oil 7.00

Napagold Oil Filter 1.00

22" Wiper Blade 2.00

265 70 R17 Tire 2.00

Shop Supplies 1.00

Tire Disposal Fee 2.00

Hours: 7.25 Comm: 0.00 Labor: 529.25 Parts: 514.10 Total: 1,043.35

Work Order: 2004002 **Meter:** 35957 **In Date:** 04/22/2020 **Closed:** 04/30/2020
Problem: P.M. service.

Work Completed

Parts Issued

Quantity

- P.m. service.
- Replace cabin air filter and clean fresh air intake .
- Charge battery fully . Test battery and charging system . Battery failed load test . R&r defective battery . Hook up Ids to reset Bsm .
- Rotate and balance all four tires . Nitrofill all.
- Shop Supplies

5w20 Engine Oil 7.00

Napagold Oil Filter 1.00

Napagold Air Filter 1.00

22" Wiper Blade 2.00

Cabin Air Filter 1.00

Battry Motorcraft 1.00

Shop Supplies 1.00

Hours: 5.75 Comm: 0.00 Labor: 419.75 Parts: 235.21 Total: 654.96

10/17/2025
10:24:20 AM

Palm Beach County Fleet Management Asset Maintenance History
10203956 2018 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2101547 **Meter:** 46545 **In Date:** 02/10/2021 **Closed:** 02/23/2021
Problem: P.M. service and brake noise and check tires for nails .

Work Completed

- Preventive Maint. Service
- Remove and Replace 2 worn out tires at 4/32nds min with new. Rotate and balance all four wheels and tires. Nitrogen fill all wheels to proper psi and nitrogen fill.
- Rear brake worn below min spec and wearing into rotors. Remove and replace both rear brake rotors and brake pad assemblies. clean both rear brake calipers and brackets. Use scan tool to retract parking brake.
- Alignment. Use alignment machine to preform 4 wheel alignment. Use alignment machine to adjust front toe, Camber and caster. Center steering wheel.
- Pressure test and inspect cooling system . Remove and replace leaking water pump assembly. replace gasket at thermostat housing O-ring. install new pulley. Top off cooling system and bleed air.
- Shop Supplies

Hours: 14.25

Comm: 0.00

Parts Issued

Quantity

| | |
|------------------------|------|
| 5w20 Engine Oil | 7.00 |
| Napagold Oil Filter | 1.00 |
| Washer Fluid Concentr | 1.00 |
| 22" Wiper Blade | 2.00 |
| 265 70 R17 Tire | 2.00 |
| Non-chlor Brake Clnr | 2.00 |
| Brake Pad | 1.00 |
| Brake Rotor | 2.00 |
| Anti Freeze Motorcraft | 2.00 |
| Water Pump | 1.00 |
| Gasket | 1.00 |
| Shop Supplies | 1.00 |
| Tire Disposal Fee | 2.00 |

Labor: 1,040.25

Parts: 1,121.38

Total: 2,161.63

Work Order: 2107307 **Meter:** 52604 **In Date:** 07/07/2021 **Closed:** 07/12/2021
Problem: P.M. Service

Work Completed

- Preventive Maint. Service
- Inspect all, R & I two new on front, Rotate and speed balance all, nitro fill
- Check and replace cabin filter and clean fresh air intake .
- Shop Supplies

Hours: 5.25

Comm: 0.00

Parts Issued

Quantity

| | |
|-------------------------|------|
| Napagold Oil Filter | 1.00 |
| 5w20 Engine Oil | 7.00 |
| Washer Fluid Concentr | 1.00 |
| 22" Wiper Blade | 2.00 |
| Used Fire X Refurbished | 1.00 |
| 265/70/17 Tire Grappler | 2.00 |
| Cabin Air Filter | 1.00 |
| Shop Supplies | 1.00 |
| Tire Disposal Fee | 2.00 |

Labor: 383.25

Parts: 421.42

Total: 804.67

10/17/2025
10:24:20 AM

Palm Beach County Fleet Management Asset Maintenance History
10203956 2018 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2112535 **Meter:** 57476 **In Date:** 11/24/2021 **Closed:** 12/02/2021
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Rotate And Balance All 4 Tires With Nitro Fill
- R&r Dirty Cabin Air Filter, Clean Fresh Air Intake
- Shop Supplies

Parts Issued

Quantity

| | |
|---------------------|------|
| 5w20 Engine Oil | 8.00 |
| Filter | 1.00 |
| Napagold Air Filter | 1.00 |
| 22" Wiper Blade | 2.00 |
| Cabin Filter | 1.00 |
| Shop Supplies | 1.00 |

Hours: 4.25

Comm: 0.00

Labor: 310.25 Parts: 61.27 Total: 371.52

Work Order: 2204919 **Meter:** 63039 **In Date:** 05/06/2022 **Closed:** 05/12/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- rotate and balance all 4 tire nitro fill all
- Shop Supplies

Parts Issued

Quantity

| | |
|-------------------------|------|
| Napagold Oil Filter | 1.00 |
| 5w20 Engine Oil | 8.00 |
| Washer Fluid Concentr | 1.00 |
| 22" Wiper Blade | 2.00 |
| Used Fire X Refurbished | 1.00 |
| White Lithium Grease | 1.00 |
| Shop Supplies | 1.00 |

Hours: 3.75

Comm: 0.00

Labor: 273.75 Parts: 53.09 Total: 326.84

10/17/2025
10:24:20 AM

Palm Beach County Fleet Management Asset Maintenance History
10203956 2018 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2209325 **Meter:** 68174 **In Date:** 09/07/2022 **Closed:** 09/13/2022
Problem: PM Service and left rear tire going flat

Work Completed

- Preventive Maint. Service
- Replaced 2 tires. Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Shop Supplies

Parts Issued

Quantity

| | |
|-----------------------------|------|
| Napagold Oil Filter | 1.00 |
| 5w20 Engine Oil | 6.00 |
| 22" Wiper Blade | 2.00 |
| Used Fire X Refurbished | 1.00 |
| 265/70/17tirebfg | 2.00 |
| 265/70r17 Bfg Trail Terrain | 2.00 |
| Shop Supplies | 1.00 |
| Tire Disposal Fee | 2.00 |

Hours: 4.75

Comm: 0.00

Labor: 346.75

Parts: 919.22

Total: 1,265.97

Work Order: 2209439 **Meter:** 68175 **In Date:** 09/12/2022 **Closed:** 09/13/2022
Problem: Had to jump start .

Work Completed

- Charge battery fully . Test battery and charging system .battery failed load test . R&r defective battery . Hook up Ids to reset Bsm .
- Shop Supplies

Parts Issued

Quantity

| | |
|-------------------|------|
| Battry Motorcraft | 1.00 |
| Shop Supplies | 1.00 |

Hours: 1.50

Comm: 0.00

Labor: 109.50

Parts: 155.11

Total: 264.61

10/17/2025
10:24:20 AM

Palm Beach County Fleet Management Asset Maintenance History
10203956 2018 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2301026

Meter: 73346

In Date: 01/31/2023 **Closed:** 02/13/2023

Problem: PM Service.

Work Completed

- Preventive Maint. Service completed
- check and replaced cabin a/c filter and clen fresh air intake
- Computer diagnose engine misfire .check and performed major tune up by r&r all 6 spark plugs and intake gasket
- performed top engine decab and injector flush kit
- check,verify needs front pads,replaced front brakes pads,calipers,resurfaced both rotorsmbleed flush fluid then road test to verify normal operation
- rotate and balance all 4 tires . Nitro fill all.
- check,replaced defective trailer plug connector and fabricated wire as needed
- Shop Supplies

Hours: 14.95

Comm: 0.00

Parts Issued

Quantity

| | |
|----------------------------|------|
| Napagold Oil Filter | 1.00 |
| 5w20 Engine Oil | 6.00 |
| 22" Wiper Blade | 2.00 |
| Steering Wheel Cover Large | 1.00 |
| Cabin Filter Replaces Fp92 | 1.00 |
| Gasket | 1.00 |
| Spark Plug | 6.00 |
| Intake Cleaner Kit | 1.00 |
| Motor Tune-up 16oz | 1.00 |
| Brake Fluid Fot 4 Lv | 1.00 |
| Bracketed Caliper | 1.00 |
| Bracketed Caliper | 1.00 |
| Brake Pad | 1.00 |
| trailer plug | 1.00 |
| trailer plug | 1.00 |
| Shop Supplies | 1.00 |

Labor: 1,091.35

Parts: 350.91

Total: 1,442.26

10/17/2025
10:24:20 AM

Palm Beach County Fleet Management Asset Maintenance History
10203956 2018 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2305758 **Meter:** 78557 **In Date:** 06/09/2023 **Closed:** 06/14/2023
Problem: PM Service

Work Completed

- Preventive Maint. Service
- Inspect. R & I two new tires on front, Rotate and speed balance, nitro fill
- Ids diagnostic code# p06e9 starter performance, intermittent cranking ,check circuit R & I new starter relay . Clear code and retest .
- Perform front alignment and road test .
- Shop Supplies

Parts Issued

Quantity

| | |
|-----------------------------|------|
| Napagold Oil Filter | 2.00 |
| 5w20 Engine Oil | 6.00 |
| 22" Wiper Blade | 2.00 |
| 265 / 70 / 17 SI / Tire Gdy | 2.00 |
| Relay | 1.00 |
| Washer Fluid Concentr | 1.00 |
| Shop Supplies | 1.00 |
| Tire Disposal Fee | 2.00 |

Hours: 8.75

Comm: 0.00

Labor: 638.75

Parts: 443.12

Total: 1,081.87

Work Order: 2310517 **Meter:** 83828 **In Date:** 10/18/2023 **Closed:** 10/31/2023
Problem: PM Service. Trans. shudders. Has to play with key to start.

Work Completed

- Preventive Maint. Service
- cooling system was pressure tested during inspections and leak was found at a heater core hose R&r. Flush and refill cooling system . Retest .
- rotate and balance all 4 tires nitro fill all
- customer states has to play with key to start vehicle was scanned for Dtc's and Starter performance code (p06e9) was found R&r starter
- customer states transmission shudder was confirmed, and transmission Flush service was perform with filter change . Refill and road test .
- Shop Supplies

Parts Issued

Quantity

| | |
|-----------------------|-------|
| Oil Filter | 1.00 |
| 5w20 Engine Oil | 6.00 |
| Washer Fluid Concentr | 1.00 |
| 22" Wiper Blade | 2.00 |
| Mac Wite Lithium Gres | 1.00 |
| Relay | 1.00 |
| Heater Hose | 1.00 |
| Starter Motor Assy | 1.00 |
| Tram Oil Gasket | 1.00 |
| Screen Asy | 1.00 |
| oil auto | 10.00 |
| Shop Supplies | 1.00 |

Hours: 10.45

Comm: 0.00

Labor: 762.85

Parts: 483.12

Total: 1,245.97

10/17/2025
10:24:20 AM

Palm Beach County Fleet Management Asset Maintenance History
10203956 2018 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2503673 **Meter:** 104799 **In Date:** 04/21/2025 **Closed:** 05/07/2025
Problem: PM Service

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Rotate and balance four tires. Nitro fill all
- Shop Supplies

| | |
|---------------------|------|
| 5w20 Engine Oil | 6.00 |
| Napagold Oil Filter | 1.00 |
| Wiper Blade | 2.00 |
| Shop Supplies | 1.00 |

Hours: 3.75 Comm: 0.00

Labor: 273.75 Parts: 28.52 Total: 302.27

Work Order: 2507318 **Meter:** 107987 **In Date:** 08/06/2025 **Closed:** 08/08/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00

Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 153.00

Total Labor: 10,960.75

Total Comm: 0.00

Total Parts: 8,149.88