

3/4/2026
12:33:42 PM

Palm Beach County Fleet Management Asset Maintenance History
10201350 2016 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Total Hours: 259.55 Labor: 18,041.85 Parts: 20,889.23 Comm: 619.45 Charged: 39550.52

Work Order: 1608137 **Meter:** 396 **In Date:** 08/08/2016 **Closed:** 08/08/2016
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.50 Comm: 0.00 Labor: 150.00 Parts: 0.00 Total: 150.00

Work Order: 1608829 **Meter:** 398 **In Date:** 08/24/2016 **Closed:** 09/12/2016
Problem: mount skid unit

Work Completed

- Mount Skid unit in new truck from 10178878, fab brakets and wire in
- Shop Supplies

Parts Issued

Quantity

Batt Cable Connector	1.00
3/4" Spring Latch	4.00
Bulk Battery Cable	7.00
Bat/cabl	16.00
Vinyl Electrical Tape	1.00
Glos Blk	1.00
Iron Channel	1.00
Shop Supplies	1.00

Hours: 20.00 Comm: 0.00 Labor: 1,200.00 Parts: 343.76 Total: 1,543.76

Work Order: 1700735 **Meter:** 3914 **In Date:** 01/25/2017 **Closed:** 01/31/2017
Problem: P.M. service

Work Completed

- P.m. Service.
- Inspect and service winch.
- Rotate and balance tires.
- Shop Supplies

Parts Issued

Quantity

Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
Floor Mat-2pc Rub Bk	1.00
Stg Wheel Cov - Ford	1.00
Motor Oil Motorcraft	7.00
Napagold Oil Filter	1.00
Shop Supplies	1.00

Hours: 6.00 Comm: 0.00 Labor: 360.00 Parts: 109.48 Total: 469.48

3/4/2026
12:33:42 PM

Palm Beach County Fleet Management Asset Maintenance History
10201350 2016 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 1809004 **Meter:** 21604 **In Date:** 08/30/2018 **Closed:** 09/10/2018
Problem: pumper bracket broke loose

Work Completed

Parts Issued

Quantity

- repair bed and weld in lock mounts for skid unit
- Shop Supplies

Shop Supplies 1.00

Hours: 3.50 Comm: 0.00 Labor: 210.00 Parts: 2.00 Total: 212.00

Work Order: 1809076 **Meter:** 21672 **In Date:** 09/04/2018 **Closed:** 09/18/2018
Problem: P.M. service and relocate winch connector.

Work Completed

Parts Issued

Quantity

- P.m. service.
- Replace all four tires . Nitrogen fill and high speed balance all four tires.
- Replace both front sway bar links .
- Replace bent main drag link and both outter tie rod ends . Straighten steering stablizer mounting bracket .
- Perform complete front end alignment . Road test.
- Inspect and service winch .relocate winch control box and replace missing winch remote.
- Shop Supplies

Napagold Oil Filter 1.00
5w20 Engine Oil 7.00
22" Wiper Blade 2.00
Used Fire X Refurbished 1.00
Ford Triton Pvc Swc 1.00
Napagold Air Filter 1.00
35x12.5r17 Nitto Grap 4.00
Link 2.00
Tie 1.00
Remote Ctrl Ser. Part 1.00
end spin 1.00
Link Asy 1.00
Shop Supplies 1.00
Tire Disposal Fee 4.00

Hours: 14.70 Comm: 0.00 Labor: 882.00 Parts: 2,481.82 Total: 3,363.82

3/4/2026
12:33:42 PM

Palm Beach County Fleet Management Asset Maintenance History
10201350 2016 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 1912863 **Meter:** 36264 **In Date:** 12/17/2019 **Closed:** 12/26/2019
Problem: P.M. service and winch cable broke .

Work Completed

- P.m. service.
- Computer diagnose misfire . Replace defective number one and three coils ,all sixteen spark plugs and all ignition wire set . Clear codes and retest .
- Perform complete air intake decarb and cleaning . Flush injectors .
- Resurface both rear brake rotors and service calipers . Replace brake pads . Flush and bleed brake system . Road test .
- Inspect and service winch . Replace broken cable and hook .
- Inspect and service transfer case .
- Balance and rotate all four tires . Nitrofill all.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
Espak Plug Wire	4.00
Espak Plug Wire	4.00
Coil	2.00
Spark Plug	16.00
Motor Tune-up 16oz	1.00
Intake Cleaner Kit	1.00
Brake Pad	1.00
Rep/rope	1.00
Ford Transfer Case Fluid	3.00
Clevis Slip Hook-bulk	1.00
Shop Supplies	1.00

Hours: 20.10

Comm: 0.00

Labor: 1,467.30

Parts: 1,001.25

Total: 2,468.55

Work Order: 2000297 **Meter:** 36608 **In Date:** 01/09/2020 **Closed:** 01/16/2020
Problem: Vehicle will not start at top of parking garage .

Work Completed

- Computer diagnose , no codes . Test fuel pressure and mass air flow sensor . Mass air filter out of spec. R&r defective Maf sensor and air filter . Clear code and retest .
- Service call to Erm parking garage to diagnose and get running to transport to shop .
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Sensor Asy	1.00
Shop Supplies	1.00

Hours: 4.50

Comm: 0.00

Labor: 328.50

Parts: 212.20

Total: 540.70

3/4/2026
12:33:42 PM

Palm Beach County Fleet Management Asset Maintenance History
10201350 2016 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 2101045 **Meter:** 48408 **In Date:** 01/28/2021 **Closed:** 02/10/2021
Problem: PM Service. Thank you left side tail light inop .

Work Completed

- Preventive Maint. Service
- Diagnose Left tail light inop. Found to have moisture in light due to crack . Replaced both tail lamps due to moisture and broken. Fabricate and install strobes into new lights
- Inspect and serviced winch
- Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00	
Napa Quart 5w30	8.00	
Used Fire X Refurbished	1.00	
22" Wiper Blade	2.00	
Permatex	1.00	
Rear Tail Lamp Assembly	1.00	
Lamp Asy	1.00	
Shop Supplies	1.00	
Labor: 547.50	Parts: 229.08	Total: 776.58

Hours: 7.50

Comm: 0.00

3/4/2026
12:33:42 PM

Palm Beach County Fleet Management Asset Maintenance History
10201350 2016 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 2107748

Meter: 54436

In Date: 07/16/2021 **Closed:** 07/26/2021

Problem: PM Service and check engine light and tool box struts .

Work Completed

- Preventive Maint. Service
- Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Inspect and serviced winch
- Diagnose check engine light. Found to have misfire on cylinders 4,7 and coil 3 was arcing, Replaced all 3 coils. Performed tune up. Cleared codes and test drove.
- Perform decarbon service and fuel system flush
- Replaced both lift struts for tool box lid.
- Shop Supplies

Parts Issued

Quantity

Napa Quart 5w30	8.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Steering Wheel Cover Large	1.00
Wd40 Spr	1.00
Coil	1.00
Coil	1.00
Support	2.00
Spark Plug	16.00
Espak Plug Wire	4.00
Espak Plug Wire	4.00
Intake Cleaner Kit	1.00
Motor Tune-up 16oz	1.00
Coil	1.00
Napagold Air Filter	1.00
Shop Supplies	1.00

Hours: 14.20

Comm: 0.00

Labor: 1,036.60

Parts: 664.88

Total: 1,701.48

3/4/2026
12:33:42 PM

Palm Beach County Fleet Management Asset Maintenance History
10201350 2016 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 2201484

Meter: 61086

In Date: 02/09/2022 **Closed:** 03/10/2022

Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Checked Charging System And Load Tested Battery, Acid Leaking Out Of Battery Tested Bad R&r Battery
- 3rd Brake Light Not Working Bulbs Burnt Out Due To Bad Seal, R&r Brake Light Asseby, Right Rear Reverse Light Not Working Socket Burnt R&r Passanger Rear Reverse Socket And Bulb
- Tires Below Minimum Depth R&r All 4 Tires Balance With Nitro Fill
- Inspected Front Differential Water In Pan Bearings Good, Drain And Clean Differential Fill And Retest
- Front Brake Pads At Minimum Depth R&r Front Brake Pads, Resurface Rotors, And Replace Both Front Calipers, Bleed Brakes And Test Drive
- Test Drive And Perform Front End Alignment.install Adjustable Camber Caster Bushings.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Battery	1.00
Sockey Assy	1.00
Boxed Miniatures	1.00
Lamp Assy	1.00
Napa Gear 80w-90 Qt	3.00
Non-chlor Brake Clnr	1.00
Px Grey Rtv Silicone	1.00
Brk Fluid Dot 4-32oz	1.00
Brake Hose	1.00
Brake Hose	1.00
Reman/ca	1.00
Reman/ca	1.00
Front Brake Pad	1.00
Brake Rotor	2.00
Brake Rotor	2.00
35x12.5r17/tire	4.00
Caster-camber Bushing	1.00
Caster-camber Bushing	2.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 18.00

Comm: 0.00

Labor: 1,314.00

Parts: 2,228.00

Total: 3,542.00

3/4/2026
12:33:42 PM

Palm Beach County Fleet Management Asset Maintenance History
10201350 2016 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 2206014 **Meter:** 64731 **In Date:** 06/07/2022 **Closed:** 06/16/2022
Problem: Overheating - Check engine light is on. Thermostat light on.

Work Completed

- Operator Complaint Overheating Message On Dash, Cylinder Head Temp Sensor Shorting Out Due To Igniton Coils Spark Jumping And Touching Wire, Remove Intake And Replace Sensor And Harness Reinstall Wiht New Intake Gaskets And Coils, Test Drive
- Shop Supplies

Parts Issued

Quantity

Qd Electronic Cleaner	1.00
Coil	1.00
Al3z12029b	2.00
Wire Assy	1.00
Gasket	1.00
Tep Sensor	1.00
Shop Supplies	1.00

Hours: 6.00 Comm: 0.00 Labor: 438.00 Parts: 377.96 Total: 815.96

Work Order: 2206124 **Meter:** 64731 **In Date:** 06/10/2022 **Closed:** 06/16/2022
Problem: replace chipped windsield

Work Completed

- set up repairs & reasset
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 1.00 Comm: 376.35 Labor: 73.00 Parts: 2.65 Total: 452.00

Work Order: 2207263 **Meter:** 65507 **In Date:** 07/12/2022 **Closed:** 07/14/2022
Problem: Truck bed liner need to be check - Replaced or Repaired and winch inop .

Work Completed

- Remove tangled cable . Remove sun gears to clean and grease . Reinstall and spool cable and service winch
- Remove slide in to repair bed liner with new plate and remount rear mounts
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 4.00 Comm: 0.00 Labor: 292.00 Parts: 2.65 Total: 294.65

3/4/2026
12:33:42 PM

Palm Beach County Fleet Management Asset Maintenance History
10201350 2016 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 2300018 **Meter:** 71219 **In Date:** 01/03/2023 **Closed:** 01/11/2023
Problem: PM Service. tire going flat , turn signal inop and washers inop .

Work Completed

- Preventive Maint. Service
- Replace two front tires and rotate and balance all 4 tires nitro fill all
- lube and inspect winch
- customer states turn signal inop remove and replace right rear blinker
- customer states washer not working replace windshield washer nozzle
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Used Fire X Refurbished	1.00
22" Wiper Blade	2.00
Boxed Miniatures	1.00
Washer Jet	2.00
35x12.50/r17 Tire Countrym/t	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 8.00

Comm: 0.00

Labor: 584.00 Parts: 613.97 Total: 1,197.97

Work Order: 2307095 **Meter:** 79009 **In Date:** 07/19/2023 **Closed:** 07/31/2023
Problem: PM Service and recall 22S35

Work Completed

- Preventive Maint. Service
- mount 2 rotate and balance all 4 tires nitro fill all
- vehicle failed load test recharge battery and stilled failed R&r battery
- inpect cable and winch re wind cable spool
- Transport to and from dealer for recall 22s35 .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
35x12.50/r17 Tire Countrym/t	2.00
Battery	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 8.75

Comm: 0.00

Labor: 638.75 Parts: 762.52 Total: 1,401.27

3/4/2026
12:33:43 PM

Palm Beach County Fleet Management Asset Maintenance History
10201350 2016 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 2401250 **Meter:** 86932 **In Date:** 02/02/2024 **Closed:** 02/26/2024

Problem: PM Service Piggy Tail Broken - Needs replacement and cotter pin needed. The winch is not working.

Work Completed

- Preventive Maint. Service
- Customer states pig tail connector from auxiliary pump is broken. Inspect and replace both broken connectors and verify repair.
- Mount two new tires with valve stems, rotate and balance four. Relearn tire sensors.
- Resurface front and rear rotors. Replace worn brake pads, park brake shoes and adjust. Replace rear calipers, flush and bleed brake system. Road test to verify repair.
- Customer states winch not working. Inspect and found loose ground connection. Resecured connection and service power winch. Replace missing pintel pin from hitch.
- Inspect front differential and found water inside due to broken vent hose. Remove pan, drain and fill differential. Replace broken vent hose.
- Replace automatic transmission pan filter and flush transmission. Road test vehicle to verify repair.
- Remove rear differential pan, drain and fill with gear oil.
- Complete frontend alignment and road test to verify repair.
- Shop Supplies

Parts Issued

Quantity

Napagold Air Filter	1.00
Wiper Blade	2.00
Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
Fab Loom-split Poly	2.00
Batt Cable Connector	1.00
Brake Fluid Dot4lv	2.00
Non-chlor Brake Clnr	1.00
Pintle Pin W/clip	1.00
Px Grey Rtv Silicone	1.00
Fuel Line Hose	4.00
Napa Gear 80w-90 Qt	3.00
Transmission Filter	1.00
Friction Modifier	2.00
Px Grey Rtv Silicone	1.00
75w140 Ford Axle Lube	4.00
Brake Caliper	1.00
Brake Caliper	1.00
Brake Pad Set	1.00
Brake Pedal Pad	1.00
Tire Valve Stem	2.00
oil auto	20.00
35x12.50/r17 Tire Countrym/t	2.00
Front Brake Pad Duty	1.00
Brake Shoes Park	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 25.60

Comm: 0.00

Labor: 1,868.80

Parts: 1,533.92

Total: 3,402.72

3/4/2026
12:33:43 PM

Palm Beach County Fleet Management Asset Maintenance History
10201350 2016 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 2403767 **Meter:** 89078 **In Date:** 04/16/2024 **Closed:** 04/17/2024
Problem: broken trailer plug

Work Completed

Parts Issued

Quantity

- Rewire and replace trailer connector.
- Shop Supplies

Trailer Connector Truck Side	1.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 12.23 Total: 85.23

Work Order: 2406726 **Meter:** 91615 **In Date:** 07/11/2024 **Closed:** 07/23/2024
Problem: PM Service and The vehicle will not start - Possibly the starter. Will be towed to Fleet.

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Inspect and serviced winch
- Diagnose no start. Pinpoint test and found to have bad starter. R&r defective start. Check proper function
- Diagnose whining noise under hood when running. Found tensioner pully to be bad. R&r tensioner pully and belt
- Shop Supplies

Napa Quart 5w30	8.00
Napagold Oil Filter	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Macs Chain Cable Lube	1.00
Starter	1.00
V Belt	1.00
Tensioner	1.00
Shop Supplies	1.00

Hours: 8.70 Comm: 0.00 Labor: 635.10 Parts: 457.50 Total: 1,092.60

Work Order: 2406978 **Meter:** 91546 **In Date:** 07/11/2024 **Closed:** 07/19/2024
Problem: Tow-Won't start please tow

Work Completed

- Tow From: 2300 N Jog Rd, West Palm Beach 33411 Garage 5th Fl To: Fleet Vista Lv Shop

Hours: 0.00 Comm: 124.30 Labor: 0.00 Parts: 0.00 Total: 124.30

3/4/2026
12:33:43 PM

Palm Beach County Fleet Management Asset Maintenance History
10201350 2016 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 2502570 **Meter:** 98977 **In Date:** 03/17/2025 **Closed:** 04/03/2025

Problem: PM Service . Winch doesn't work - AC not blowing cold air.

Work Completed

- perform Preventive Maint. Service
- mount 2 tires, balance nitrofill, rotate all, tpms relearn
- Op complaint of ac not blowing cold. A/c performance test . Install A/c stop leak and perform air conditioning service . Retest
- operator complaint of winch not working, found winch cable to be bound up, untangled cable, service winch. replace missing hook
- Lf U-joint is worn out and seized. unserviceable, replace driverside driveshaft assembly
- battery failed load test, recharged battery, retested, failed load test, R&r battery clean and protect terminals
- Service rear differential
- Service front differential, clean dirt from housing and axle tubes, R&r diff and pinion bearings, shims, and seals. checked diff & pinion endplay & backlash. R&r axle seals inner and outer, R&r hub seals.
- pass tie rod end worn out, R&r tie rod end
- perform alignment, road test
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Freon Lv Shop 1	3.00
Red Angel Ac Stop Lk	1.00
Clevis Slip Hook-bulk	1.00
Joint Front	1.00
Battery	1.00
75w140	4.00
Friction Modifier	2.00
Permatex	1.00
Axle Shaft L/f	1.00
Left Axle Out Seal	2.00
Left Axle Seal	2.00
Seal	2.00
Non-chlor Brake Clnr	10.00
75w140	3.00
end spin	1.00
Ring & Pinion Kit	1.00
35x12.50r17 Tire	2.00
35x12.50r17 Tire	2.00
Cup	2.00
Bearing	2.00
Front Inner Diff Seal	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 30.90

Comm: 0.00

Labor: 2,255.70

Parts: 3,022.33

Total: 5,278.03

3/4/2026
12:33:43 PM

Palm Beach County Fleet Management Asset Maintenance History
10201350 2016 FORD F350 Pickup, 1 Ton, Ext Cab, 4X4

Work Order: 2507340 **Meter:** 104178 **In Date:** 08/06/2025 **Closed:** 09/15/2025
Problem: Tow-leaking transmission fluid, PM Service.

Work Completed

- Perform Pm Service.
- Service front differential. Inspect for damage.
- Replace broken transfer case, front drive shaft assembly.
- Replace two tires, balance and nitro service all.
- Service winch, inspect wire rope. and lubricate.
- Shop Supplies

Parts Issued

Quantity

Permatex	1.00
Gear Oil 75w140 98fs32	3.00
Transfer Case Asm	1.00
Front Driveshaft	1.00
Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Wiper Blade	2.00
Napagold Air Filter	1.00
35x12.50r17 Tire	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 10.75

Comm: 0.00

Labor: 784.75

Parts: 3,915.11

Total: 4,699.86

Work Order: 2508017 **Meter:** 104013 **In Date:** 08/06/2025 **Closed:** 08/27/2025
Problem: Tow-leaking transmission fluid

Work Completed

- Tow From: Beeline hwy, S of Kanner, N of Pratt Whitney To: fleet vista Lv shop

Hours: 0.00

Comm: 118.80

Labor: 0.00

Parts: 0.00

Total: 118.80

Work Order: 2600219 **Meter:** 108193 **In Date:** 01/08/2026 **Closed:** 01/13/2026
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

Total Hours: 259.55

Total Labor: 18,041.85

Total Comm: 619.45

Total Parts: 20,889.23