

4/28/2017
10:11:06AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169571 2007 TORO SANDPRO 3040 Ballfield Groomer, Mid Mount

Workorder: 740259 **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts
In Date: 06/19/2007	Hours	Description
Close Date: 06/19/2007	Quantity	
- Pre-Delivery Inspection	2.00	
Parts Charge: 0.00	Labor Charge: 110.00	

Workorder: 740262 **Problem:** WELD ASST# ON ATTACHMENTS

Meter Reading: 2	Labor	Parts
In Date: 06/19/2007	Hours	Description
Close Date: 06/22/2007	Quantity	
- Weld Asset Numbers On Attachments	1.00	SHOP SUPPLIES
- Shop Supplies		1.00
Parts Charge: 2.00	Labor Charge: 55.00	

Workorder: 840632 **Problem:** P.M. SERVICE

Meter Reading: 114	Labor	Parts
In Date: 06/27/2008	Hours	Description
Close Date: 08/12/2008	Quantity	
- P/M Service	4.00	10W30 MOTOR OIL
- Shop Supplies		492932 B&S OIL FILTER FRAM PH8170 WIX 57035
		3031 FUEL FILTER 1/4" FRM G1 WIX 33031
		6449 AIR FILTERFRM CA9248 WIX 46449
		SHOP SUPPLIES
		2.00
		1.00
		1.00
		1.00
		1.00
Parts Charge: 41.99	Labor Charge: 240.00	

Workorder: 943389 **Problem:** PM Service

Meter Reading: 225	Labor	Parts
In Date: 09/17/2009	Hours	Description
Close Date: 09/18/2009	Quantity	
- P.M. Service	5.50	492932 B&S OIL FILTER FRAM PH8170 WIX 57035
- Clear Restriction In Fueline		3031 FUEL FILTER 1/4" FRM G1 WIX 33031
- Shop Supplies		10W30 MOTOR OIL
- Performance Test		SHOP SUPPLIES
		1.00
		2.00
		1.00
		1.00
Parts Charge: 48.51	Labor Charge: 330.00	

4/28/2017
10:11:06AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169571 2007 TORO SANDPRO 3040 Ballfield Groomer, Mid Mount

Workorder: 946731

Problem: won't stay running

Meter Reading: 328	Labor	Parts	
In Date: 12/07/2009	Hours	Description	Quantity
<hr/>			
- Jump Start,Charge Battery,Internal Short,Remove Side Console To: R&R Battery	1.50	GROUP U1 BATTERY (ACD U1240W) SHOP SUPPLIES	1.00 1.00
- Shop Supplies			
Parts Charge:	55.48	Labor Charge:	180.00

Workorder: 1001756

Problem: SHUTS DOWN AFTER RUNNING FOR A WHILE

Meter Reading: 256	Labor	Parts	
In Date: 02/18/2010	Hours	Description	Quantity
<hr/>			
- Engine Shuts Off Hard To Start An Keep Running.	8.00	SHOP SUPPLIES	1.00
- Pm Service		3031 FUEL FILTER 1/4" FRM G1 WIX 33031	1.00
- Tune Up		6449 AIR FILTERFRM CA9248 WIX 46449	1.00
- Test Run In Yard		SPARK PLUGS / RC14YC	2.00
- Shop Supplies		10W30 MOTOR OIL	2.00
		492932 B&S OIL FILTER FRAM PH8170 WIX 57035	1.00
Parts Charge:	48.67	Labor Charge:	480.00

Workorder: 1106595

Problem: pm service

Meter Reading: 328	Labor	Parts	
In Date: 06/22/2011	Hours	Description	Quantity
<hr/>			
- Arraiged Outside Repair, Verified Repair	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00
		Commercial Charge:	282.83

4/28/2017
10:11:06AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169571 2007 TORO SANDPRO 3040 Ballfield Groomer, Mid Mount

Workorder: 1110509

Problem: Equipment runs for 3 minutes then shuts down;remove rear rake holder;order new seat

Meter Reading: 358	Labor	Parts	
In Date: 10/03/2011	Hours	Description	Quantity
- Reset Fuel Float In Carburetor, Cleaned Throttle Plate	3.50	SHOP SUPPLIES	1.00
- Replaced Operators Seat & Safety Switch		SPARK PLUGS / RC14YC	2.00
- Removed Rake Holder As Requested		SEAT / 108-6878	1.00
- Performance Test			
- Shop Supplies			
Parts Charge:	229.43	Labor Charge:	210.00

Workorder: 1112274

Problem: Engine cuts off

Meter Reading: 358	Labor	Parts	
In Date: 11/16/2011	Hours	Description	Quantity
- Replaced Fuel Solenoid, Removed Front Engine Cover And Reconfigured Wiring	6.50	SHOP SUPPLIES FUEL SENSOR / 692094	1.00 1.00
- Performance Test			
- Shop Supplies			
Parts Charge:	104.27	Labor Charge:	390.00

4/28/2017
10:11:06AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169571 2007 TORO SANDPRO 3040 Ballfield Groomer, Mid Mount

Workorder: 1208339

Problem: PM / Runs and shuts down / check hyd. lines

Meter Reading: 377	Labor	Parts
In Date: 09/04/2012	Hours	Quantity
- Pm	16.50	
- New Battery Check Charging Sys Test		492932 B&S OIL FILTER FRAM PH8170 WIX 57035 1.00
- Test And Diagnose Hydraulic Pump And Sys And		6449 AIR FILTERFRM CA9248 WIX 46449 1.00
Replace Hydro Valve. Hydro Service And Flush Hydro		33971 FUEL FILTER 1/4" GAS/DIESEL 1.00
Cooler And Liens Rebuild Hydro Pump R&R Safety Shaft		GROUP U1 BATTERY (ACD U1240W) 1.00
And Liens		AW68 HYDRO FLUID HYDRAULIC OIL 68 12.00
- Clean And Rebuild Carb Order Carb Rebuilt Kit		09997 BRAKE CLEAN 1.00
- Service Fuel Sys Flush Fuel Lines And Replace Fuel		09997 BRAKE CLEAN 1.00
Pump And Fuel Cap		BKR5E SPARK PLUG 7938 2.00
- Wash		VALVE ASSY 1.00
- Ign Sys Service Tune Up Repalce Ign. Key Switch Clean		SEAL 1.00
Wiring		SEAL 2.00
- Shop Supplies		FUEL SHUT OFF VALVE 1.00
		IGNITION SWITCH 1.00
		HYD FILTER 1.00
		CARB REBUILD KIT 1.00
		FUEL CAP 1.00
		SHOP SUPPLIES 1.00
		10W30 MOTOR OIL 2.00
		FUEL PUMP 1.00
Parts Charge:	760.82	Labor Charge: 990.00

4/28/2017
10:11:06AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169571 2007 TORO SANDPRO 3040 Ballfield Groomer, Mid Mount

Workorder: 1311679

Problem: Pm service and list.

Meter Reading: 412	Labor	Parts	
In Date: 11/19/2013	Hours	Description	Quantity
- Pm Service.	10.50	AW68 HYD FLUID TANK PAHOKEE	6.00
- Replace Scarifier Teeth And Rear Tines.		SHOP SUPPLIES	1.00
- Replace Rear Tires.		TIRE DISPOSAL FEE	2.00
- Remove And Clean Carb.		NAPAGOLD AIR FILTER	1.00
- Test Drive.		NAPAGOLD OIL FILTER	1.00
- Shop Supplies		TINE SCARIFIER	15.00
		NAPAGOLD FUEL FILTER	1.00
		22X1100X8 KNOBBY	2.00
		NAPA 10W30 QT	2.00
		NAPA HYDRAULIC FILTR	1.00
		RAKE-PRONG	27.00
Parts Charge:	1,345.51	Labor Charge:	630.00

Workorder: 1400095

Problem: Replace carb.

Meter Reading: 414	Labor	Parts	
In Date: 01/06/2014	Hours	Description	Quantity
- Replace Leaking Carb.	4.00	SHOP SUPPLIES	1.00
- Shop Supplies		CARB GASKET	1.00
		Freight Charge	1.00
		CARBURETOR ASSY	1.00
Parts Charge:	411.06	Labor Charge:	240.00

Workorder: 1409453

Problem: Pm service.

Meter Reading: 458	Labor	Parts	
In Date: 09/22/2014	Hours	Description	Quantity
- Pm Service.	3.00	NAPAGOLD FUEL FILTER	1.00
- Shop Supplies		NAPA 10W30 QT	2.00
		NAPAGOLD OIL FILTER	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	18.35	Labor Charge:	180.00

4/28/2017
10:11:06AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169571 2007 TORO SANDPRO 3040 Ballfield Groomer, Mid Mount

Workorder: 1510417

Problem: Won't start, service.

Meter Reading: 560 In Date: 10/15/2015	Close Date: 10/28/2015	Labor Hours	Description	Parts	Quantity
- Pm Service.		11.00	NAPAGOLD AIR FILTER		1.00
- Battery Failed Load Test. Replace Battery.			SOLENOID		1.00
- Hyd. System Service.			SHOP SUPPLIES		1.00
- Diagnose No Start. Check Start And Safety Circuit.			RELAY		1.00
Replace Shorted Starter Relay And Switch.			BATTERY		1.00
- Running Bad, Shutting Off. Carb Clogged, Fuel Valve			NAPAGOLD FUEL FILTER		1.00
Clogged. Remove And Cleaned Carb. Remove And Clean			CLEAN-R-CARB 200Z		1.00
Fuel Tank And Fuel Valve.			NAPA HYDRAULIC FILTR		1.00
- Shop Supplies			NAPAGOLD OIL FILTER		1.00
			NAPA 10W30 QT		2.00
Parts Charge:		120.74	Labor Charge:		660.00

Workorder: 1610983

Problem: Pm service and tire.

Meter Reading: 627 In Date: 10/24/2016	Close Date: 10/31/2016	Labor Hours	Description	Parts	Quantity
- Pm Service.		5.00	NAPA 10W30 QT		2.00
- Replace Damaged Tire.			NAPAGOLD OIL FILTER		1.00
- Hyd. System Service.			SHOP SUPPLIES		1.00
- Test Drive.			NAPAGOLD FUEL FILTER		1.00
- Shop Supplies			TIRE DISPOSAL FEE		1.00
			AW68 HYD FLUID TANK PAHOKEE		5.00
			22X1100X8 KNOBBY		1.00
			NAPAGOLD AIR FILTER		1.00
			NAPA HYDRAULIC FILTR		1.00
Parts Charge:		167.64	Labor Charge:		300.00

4/28/2017
10:11:06AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169571 2007 TORO SANDPRO 3040 Ballfield Groomer, Mid Mount

Workorder: 1700771

Problem: Shutting off.

Meter Reading: 634	Labor	Parts
In Date: 01/25/2017	Hours	Quantity
Close Date: 02/02/2017	Description	
- Diagnose Engine Running Rough. Spark Plugs Fouled.	5.00	2.00
- Replace Spark Plugs.		1.00
- Test Run.		
- Clean Clogged Carb And Fuel Lines.		
- Shop Supplies		
Parts Charge: 7.04	Labor Charge: 300.00	

Workorder: 1704040

Problem: Transition Prep Charge

Meter Reading: 655	Labor	Parts
In Date: 04/21/2017	Hours	Quantity
Close Date: 04/21/2017	Description	
- Transition Prep Charge	2.00	
Parts Charge: 0.00	Labor Charge: 0.00	

Total Parts Charges: **3,363.51** Total Labor Charges: **5,355.00** Total Comm. Charges: **282.83**