

4/9/2026  
7:10:11 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201321 2017 FORD EXPLORER Suv, Lg Mid Size, 4X4**

---

**Total Hours: 132.30 Labor: 9,286.80 Parts: 6,891.29 Comm: 95.40 Charged: 16273.49**

---

**Work Order:** 1700582      **Meter:** 313      **In Date:** 01/19/2017      **Closed:** 01/19/2017  
**Problem:** 1061 - Pre Delivery Inspection

**Work Completed**

- Pre Delivery Inspection

Hours: 3.00      Comm: 0.00      Labor: 180.00      Parts: 0.00      Total: 180.00

---

**Work Order:** 1701889      **Meter:** 2302      **In Date:** 02/23/2017      **Closed:** 03/15/2017  
**Problem:** Install fire extinguisher in rear cargo area.

**Work Completed**

- Install new fire extinguisher with bracket.  
- Shop Supplies

**Parts Issued**

**Quantity**

Fire Extinguisher      1.00  
Shop Supplies      1.00

Hours: 0.50      Comm: 0.00      Labor: 30.00      Parts: 91.99      Total: 121.99

---

**Work Order:** 1706095      **Meter:** 5469      **In Date:** 06/20/2017      **Closed:** 06/30/2017  
**Problem:** P.M. Service.

**Work Completed**

- P.m. Service.  
- Rotate and balance tires.  
- Shop Supplies

**Parts Issued**

**Quantity**

5w20 Engine Oil      6.00  
Napagold Oil Filter      1.00  
Washer Fluid Concentr      1.00  
Accufit Beam      1.00  
Accufit Beam      1.00  
Shop Supplies      1.00

Hours: 3.75      Comm: 0.00      Labor: 225.00      Parts: 47.17      Total: 272.17

---

**Work Order:** 1706582      **Meter:** 6517      **In Date:** 07/05/2017      **Closed:** 07/31/2017  
**Problem:** Left side axkle seal leaking .

**Work Completed**

- Transport vehicle to dealer for leaking rear axle seal.  
- Shop Supplies

**Parts Issued**

**Quantity**

Shop Supplies      1.00

Hours: 2.00      Comm: 0.00      Labor: 120.00      Parts: 2.00      Total: 122.00





4/9/2026  
7:10:11 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201321 2017 FORD EXPLORER Suv, Lg Mid Size, 4X4**

---

**Work Order:** 1908345      **Meter:** 32861      **In Date:** 08/12/2019      **Closed:** 08/28/2019  
**Problem:** P.M. service and recall 19S17.

**Work Completed**

- P.m. service.
- Rotate and balance all four tires . Nitrofill all.
- Transport to and from dealer for recall 19s17 and loose roof rack trim .
- Shop Supplies

**Parts Issued**

**Quantity**

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
Washer Fluid Concentr	1.00
11in Exactfit-rear	1.00
22in Exactfit-beam	1.00
26in Exactfit-beam	1.00
Napa Cabin Air Filter	1.00
Mac Wite Lithium Gres	1.00
Shop Supplies	1.00

Hours: 5.75

Comm: 0.00

Labor: 385.25      Parts: 81.90      Total: 467.15

---

**Work Order:** 2000848      **Meter:** 39024      **In Date:** 01/27/2020      **Closed:** 01/30/2020  
**Problem:** P.M. service.

**Work Completed**

- P.m. Service.
- Rotate and balance tires.
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
11in Exactfit-rear	1.00
22in Exactfit-beam	1.00
26in Exactfit-beam	1.00
Shop Supplies	1.00

Hours: 3.75

Comm: 0.00

Labor: 273.75      Parts: 65.22      Total: 338.97



4/9/2026  
7:10:11 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201321 2017 FORD EXPLORER Suv, Lg Mid Size, 4X4**

**Work Order:** 2012596      **Meter:** 48945      **In Date:** 12/17/2020      **Closed:** 12/31/2020

**Problem:** P.M. service, had to be jump started ,Windshield molding and check engine light .

**Work Completed**

**Parts Issued**

**Quantity**

- Preventive Maint. Service
- Replaced both broken windshield moldings.
- Charged battery fully. Battery tested bad. R and R bad battery. Use Ids to reset Bms
- Replaced 2 tires. Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Diagnose check engine light. Scan for codes and had code- P05a1. found to have broken active grill shutter. Remove front bumper to Replace active grill shutter assembly. Cleared code and test drove.
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
11in Exactfit-rear	1.00
26in Exactfit-beam	1.00
22in Exactfit-beam	1.00
Battery	1.00
245/60/18 Tire Mic	2.00
Moulding	1.00
Moulding	1.00
Moulding	1.00
Moulding	1.00
Shutter Assy	1.00
Washer Fluid Concentr	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 10.95

Comm: 0.00

Labor: 799.35

Parts: 1,934.32

Total: 2,733.67

**Work Order:** 2101281      **Meter:** 49495      **In Date:** 02/03/2021      **Closed:** 02/04/2021

**Problem:** Please replace the wiper cowl grille panel below windshield. It is dry rotted and deteriorating. Will drop off 02/03 by

**Work Completed**

**Parts Issued**

**Quantity**

- Remove wiper arms to replace wiper cowl panel assembly .
- Shop Supplies

Grille	1.00
Shop Supplies	1.00

Hours: 0.80

Comm: 0.00

Labor: 58.40

Parts: 219.16

Total: 277.56



4/9/2026  
7:10:11 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201321 2017 FORD EXPLORER Suv, Lg Mid Size, 4X4**

---

**Work Order:** 2200039      **Meter:** 56949      **In Date:** 01/03/2022      **Closed:** 01/11/2022  
**Problem:** PM Service. Recall # 21S22. Driver sun visor loose.

**Work Completed**

- Preventive Maint. Service
- balance and rotate all 4 tires
- check,sop,replaced defective sun visor clip
- check,replaced cabin a/c filter and refresh intake air
- Transport to and from dealer for recall 21s22
- Shop Supplies

**Parts Issued**

**Quantity**

5w20 Engine Oil	6.00
Filter	1.00
11in Exactfit-rear	1.00
22in Exactfit-beam	1.00
26in Exactfit-beam	1.00
Napa Cabin Air Filter	1.00
Clip	1.00
Shop Supplies	1.00

Hours: 6.75

Comm: 0.00

Labor: 492.75      Parts: 61.32      Total: 554.07

---

**Work Order:** 2206016      **Meter:** 62375      **In Date:** 06/07/2022      **Closed:** 06/09/2022  
**Problem:** PM Service.

**Work Completed**

- Preventive Maint. Service
- Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Found passenger visor clip to be broken during inspection. Replaced broken visor clip
- Shop Supplies

**Parts Issued**

**Quantity**

Washer Fluid Concentr	1.00
11in Exactfit-rear	1.00
22in Exactfit-beam	1.00
26in Exactfit-beam	1.00
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
Clip	1.00
Shop Supplies	1.00

Hours: 3.95

Comm: 0.00

Labor: 288.35      Parts: 73.61      Total: 361.96

---

**Work Order:** 2207328      **Meter:** 62932      **In Date:** 07/13/2022      **Closed:** 07/14/2022  
**Problem:** Replace 2 key fob batteries.

**Work Completed**

- Replace two key Fob batteries.

**Parts Issued**

**Quantity**

Enr Elect Battery	1.00
-------------------	------

Hours: 0.50

Comm: 0.00

Labor: 36.50      Parts: 6.75      Total: 43.25

4/9/2026  
7:10:11 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201321 2017 FORD EXPLORER Suv, Lg Mid Size, 4X4**

---

**Work Order:** 2211982                      **Meter:** 66845                      **In Date:** 11/29/2022   **Closed:** 12/05/2022  
**Problem:** PM Service.

**Work Completed**

- Preventive Maint. Service completed
- balance and rotate all 4 tires. Nitro fill all.
- Shop Supplies

**Parts Issued**

**Quantity**

5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
11in Exactfit-rear	1.00
22in Exactfit-beam	1.00
26in Exactfit-beam	1.00
Shop Supplies	1.00

Hours: 3.75

Comm: 0.00

Labor: 273.75

Parts: 57.84

Total: 331.59

---

**Work Order:** 2305062                      **Meter:** 72161                      **In Date:** 05/22/2023   **Closed:** 05/31/2023  
**Problem:** PM Service.

**Work Completed**

- Performed P.m. Service & Inspection.
- Performed Tire Rotation Balance On All 4 Wheels, Add Nitro Fill Reset Tpms.
- Load Test Battery, Battery Test Recommend Charge, Charged Battery & Retest Working As Design.
- Front Brakes Below Manufacture Specs, Removed Front Brake Pads & Rotors, Resurfaced Front Brake Rotors, Then Replaced Brake Pads. Bleed & Flush Entire Brake System Test Drive Vehicle And Burnish Brakes.
- Removed And Replaced Cabin Air Filter Clean A/c Vents & Check.
- Shop Supplies

**Parts Issued**

**Quantity**

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
11in Exactfit-rear	1.00
22in Exactfit-beam	1.00
26in Exactfit-beam	1.00
Used Fire X Refurbished	1.00
Non-chlor Brake Clnr	1.00
Brake Fl-dot 3-4 32oz	1.00
Napa Cabin Air Filter	1.00
Brake Pad	1.00
Shop Supplies	1.00

Hours: 8.25

Comm: 0.00

Labor: 602.25

Parts: 145.77

Total: 748.02



4/9/2026  
7:10:11 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201321 2017 FORD EXPLORER Suv, Lg Mid Size, 4X4**

**Work Order:** 2312463      **Meter:** 77184      **In Date:** 12/18/2023      **Closed:** 12/27/2023  
**Problem:** Paint chip on hood. Right front window inop

**Work Completed**

- Diagnose passenger front window. Pinpoint test check harness for high resistance. replace bad motor and regulator assembly. Disregard chip, vehicle being replaced
- Shop Supplies

Hours: 2.00

Comm: 0.00

**Parts Issued**

	<b>Quantity</b>
Motor Asm	1.00
Windor Regulator	1.00
Shop Supplies	1.00

Labor: 146.00

Parts: 154.68

Total: 300.68

**Work Order:** 2401757      **Meter:** 79965      **In Date:** 02/15/2024      **Closed:** 02/21/2024  
**Problem:** Key fob battery needs to be changed.

**Work Completed**

- Test and replace battery in key fob . Reset

Hours: 0.30

Comm: 0.00

**Parts Issued**

	<b>Quantity</b>
Enr Elect Battery	1.00

Labor: 21.90

Parts: 6.75

Total: 28.65

**Work Order:** 2402751      **Meter:** 81162      **In Date:** 03/18/2024      **Closed:** 03/30/2024  
**Problem:** PM Service and left front tire going flat

**Work Completed**

- Preventive Maint. Service
- Repair one , Rotate and speed balance, nitro fill
- Inspect all, R & i new rear brakes, service caliper slide pins, Replace both rear rotors, Burnish brakes, road test
- Shop Supplies

Hours: 8.75

Comm: 0.00

**Parts Issued**

	<b>Quantity</b>
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
11in Exactfit-rear	1.00
22in Exactfit-beam	1.00
26in Exactfit-beam	1.00
Used Fire X Refurbished	1.00
Tire Marke Crayon	1.00
Non-chlor Brake Clnr	1.00
Brk Fluid Dot 4-12oz	1.00
Brake Rotor	2.00
Brake Pad	1.00
Brake Rotor	2.00
Shop Supplies	1.00

Labor: 638.75

Parts: 440.01

Total: 1,078.76

4/9/2026  
7:10:11 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201321 2017 FORD EXPLORER Suv, Lg Mid Size, 4X4**

**Work Order:** 2408710      **Meter:** 85756      **In Date:** 09/10/2024      **Closed:** 09/24/2024  
**Problem:** PM Service and Safety recall # 24S02/24V031 A-pillar trim loose (improper assembly)

**Work Completed**

**Parts Issued**

**Quantity**

- Preventive Maint. Service
- Recall: Safety recall # 24s02/24v031 A-pillar trim loose (improper assembly)
- Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Diagnose humming noise while driving. Install chassis ears and test drove. Found Rr wheel bearing to be bad. R&r wheel bearing assembly. Test drove to confirm repair.
- Shop Supplies

Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
11in Exactfit-rear	1.00
22in Exactfit-beam	1.00
26in Exactfit-beam	1.00
Hub Asm	1.00
Shop Supplies	1.00

Hours: 5.85

Comm: 0.00

Labor: 427.05

Parts: 263.21

Total: 690.26

**Work Order:** 2411912      **Meter:** 89074      **In Date:** 12/17/2024      **Closed:** 01/07/2025  
**Problem:** PM Service.

**Work Completed**

**Parts Issued**

**Quantity**

- Preventive Maint. Service
- Diagnose Tpms light on tested sensors and found to have 2 bad sensors and 2 with very low batteries. R&r all 4 Tpms sensors. Rotated and balanced all4 tires. Nitrogen filled all tires. Programed all new sensors and test drove.
- Diagnose noise in windshield area. Found cowl panel weather strip to be humming. R&r complete cowl panel assembly. Test drove to confirm fix.
- Diagnose radio inop at times. Scanned for codes and no codes present. Could not duplicate concern at this time.
- Shop Supplies

11in Exactfit-rear	1.00
Washer Fluid Concentr	1.00
22in Exactfit-beam	1.00
26in Exactfit-beam	1.00
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
Napagold Air Filter	1.00
Kit Tpms Sensor	4.00
Grille	1.00
Shop Supplies	1.00

Hours: 6.75

Comm: 0.00

Labor: 492.75

Parts: 505.25

Total: 998.00



4/9/2026  
7:10:11 PM

**Palm Beach County Fleet Management Asset Maintenance History**  
**10201321 2017 FORD EXPLORER Suv, Lg Mid Size, 4X4**

---

**Work Order:** 2601735      **Meter:** 101330      **In Date:** 02/23/2026      **Closed:** 02/25/2026  
**Problem:** Transition Prep Charge

**Work Completed**

- Transition Prep Charge

Hours: 3.00      Comm: 0.00      Labor: 219.00      Parts: 0.00      Total: 219.00

**Total Hours: 132.30**

**Total Labor: 9,286.80**

**Total Comm: 95.40**

**Total Parts: 6,891.29**