

4/10/2026
9:33:56 AM

Palm Beach County Fleet Management Asset Maintenance History
10198322 2015 FORD F350 Utility Body, 13,700 Gvwr

Total Hours: 213.20 Labor: 14,907.50 Parts: 10,669.93 Comm: 1,280.12 Charged: 26857.55

Work Order: 1508611 **Meter:** 312 **In Date:** 08/27/2015 **Closed:** 08/27/2015
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection
- Make & Apply Decals. Check Fluids, Belts and Operation

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 0.00 Total: 180.00

Work Order: 1602065 **Meter:** 3259 **In Date:** 02/29/2016 **Closed:** 03/07/2016
Problem: P.M. service.

Work Completed

- Pm service.
- Rotate and balance all six tires.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
Floor Mat-2pc Rub Bk	1.00
Friction Modifier	1.00
Shop Supplies	1.00

Hours: 5.50 Comm: 0.00 Labor: 330.00 Parts: 70.87 Total: 400.87

Work Order: 1609041 **Meter:** 6265 **In Date:** 08/31/2016 **Closed:** 09/08/2016
Problem: P.M. service.

Work Completed

- P.m. Service.
- Test battery and charging system.recharge and retest battery,failed load test.replace dfective battery.
- Rotate and balance all six tires.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Battery 65	1.00
Shop Supplies	1.00

Hours: 6.50 Comm: 0.00 Labor: 390.00 Parts: 175.01 Total: 565.01

4/10/2026
9:33:56 AM

Palm Beach County Fleet Management Asset Maintenance History
10198322 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 1703262 **Meter:** 10404 **In Date:** 03/31/2017 **Closed:** 04/12/2017
Problem: P.M. service and check brake lights.

Work Completed

- P.m. Service.
- Rotate and balance all six tires.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Washer Fluid Concentr	1.00
Napagold Air Filter	1.00
4 Led S T T Lamp	2.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 5.50

Comm: 0.00

Labor: 330.00 Parts: 95.80 Total: 425.80

Work Order: 1710920 **Meter:** 14134 **In Date:** 11/03/2017 **Closed:** 11/16/2017
Problem: PM Service, Wipers still on when off.

Work Completed

- P.m. service.
- Two new tires mount on front.nitrogen fill tires and high speed balance all six tires.
- Wiper inop at times.diagnose with computer,code B1008 wiper mode switch failed .remove and install new wiper switch.
- Pintle pin missing .r&r with new.
- Complete front end alignment.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Used Fire X Refurbished	1.00
179636492 Lt245-75r17	2.00
Pintle Pin W/clip	1.00
Switch Asy	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 11.00

Comm: 0.00

Labor: 660.00 Parts: 533.69 Total: 1,193.69

4/10/2026
9:33:56 AM

Palm Beach County Fleet Management Asset Maintenance History
10198322 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 1804635 **Meter:** 17317 **In Date:** 05/03/2018 **Closed:** 05/14/2018

Problem: P.M. service and check power outlets and vise handle missing.

Work Completed

- P.m. service.
- Replace four tires .rotate and balance all six tires .nitrogen fill tires.
- Diagnose power outlet inop.replace blown twenty amp fuse .retest.
- Weld vise handle stops to prevent handle loss.
- Shop Supplies

Parts Issued

Quantity

5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
Napagold Air Filter	1.00
22" Wiper Blade	2.00
179636492 Lt245-75r17	4.00
Fmx-20 Fuse	1.00
ridgid vise handle	1.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 8.50

Comm: 0.00

Labor: 510.00 Parts: 1,005.57 Total: 1,515.57

Work Order: 1805557 **Meter:** 17800 **In Date:** 05/31/2018 **Closed:** 06/05/2018

Problem: Cigar lighter inop and power point inop.

Work Completed

- Test and replace both 20 amp fuses to power outlets. Retest.

Hours: 0.50

Comm: 0.00

Parts Issued

Quantity

Fmx-20lp Fuse	2.00
---------------	------

Labor: 30.00 Parts: 9.42 Total: 39.42

4/10/2026
9:33:56 AM

Palm Beach County Fleet Management Asset Maintenance History
10198322 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 2102193

Meter: 37202

In Date: 02/25/2021 **Closed:** 03/08/2021

Problem: P.M. service and check cabin air filter

Work Completed

- Preventive Maint. Service
- R&r Front Calipers, Rotors, Brake Hoses, And Pads Install And Bleed Brake System Drive And Retest
- Replace and balance all six tires . Nitro Fill
- Clean Fresh Air Intake And Evaporator . Flush evaporator core and case .
- Perform Front End Wheel Alignment Install Camber Bushings On Both Sides And Redrive
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	8.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
Brake Hose	1.00
Brake Hose	1.00
Brk Fluid Dot 4-32oz	1.00
Front Brake Pad	1.00
Reman/ca	1.00
Reman/ca	1.00
Lt 245/75/17 Tire Goyear	6.00
Evap Odor Elinitator	1.00
Big G Degreaser 1 Gal	1.00
Caster-camber Bushing	2.00
Shop Supplies	1.00
Tire Disposal Fee	6.00

Hours: 17.00

Comm: 0.00

Labor: 1,241.00

Parts: 2,014.26

Total: 3,255.26

4/10/2026
9:33:56 AM

Palm Beach County Fleet Management Asset Maintenance History
10198322 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 2110279

Meter: 41624

In Date: 09/22/2021 **Closed:** 10/28/2021

Problem: PM Service.

Work Completed

- Performed P.m. Service & Inspection.
- Performed Tire Rotation Balance On All 6 Wheels, Reset Tpms.
- Removed And Replaced Driver Side Rear Leaking Hub And Axle Seal For Rear Differntal.
- Rear Brakes Below Specs, Removed Both Rear Brake Pads & Calipers, Resurface Both Rear Brake Rotors, Install Both New Rear Brake Calipers And Brake Pads, Bleed & Flush Entire Brake System, Test Drive And Burnish Brakes Working As Design.
- Performed Decarb Service & Fuel Injection Flush Then Removed Throttle Body And Clean.
- Check Engine Light On, Performed Diagnosis Connect Scan Tool And Scan For Faults, Found Fault Code P06b6, Performed Test Plan & Found 2 Defective Coils, Performed Tune-up Replace 16 Spark Plugs & 8 Wires Then Defective Coils Cyl 2 & 4.
- Weld Crackes In Bumper, Sand And Apply Non-skid Protective Coating
- Shop Supplies

Parts Issued

Quantity

Drain Plug	1.00
5w20 Engine Oil	8.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Mac Wite Lithium Gres	1.00
Non-chlor Brake Clnr	2.00
Brk Fluid Dot 4-32oz	1.00
Axle Gasket	1.00
Seal	1.00
Brake Hose	1.00
Brake Caliper	1.00
Brake Caliper	1.00
Real Brake Pad	1.00
Caliper Washer	4.00
Motor Tune-up 16oz	1.00
Coil	2.00
Espak Plug Wire	4.00
Espak Plug Wire	4.00
Spark Plug	16.00
Raptor 2k Aero White	3.00
Intake Valve Cleaner	1.00
Shop Supplies	1.00

Hours: 25.00

Comm: 0.00

Labor: 1,825.00

Parts: 935.27

Total: 2,760.27

4/10/2026
9:33:56 AM

Palm Beach County Fleet Management Asset Maintenance History
10198322 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 2211485 **Meter:** 49987 **In Date:** 11/14/2022 **Closed:** 11/23/2022

Problem: PM Service and trailer hitch loose

Work Completed

- Preventive Maint. Service
- Rotate And Balance Tires With Nitro Fill
- Trailer Hitch Missing Bolts .replace With New Bolts .sent To He To Weld Bumper .
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
5w20 Engine Oil	8.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Steering Wheel Cover Large	1.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 7.00

Comm: 0.00

Labor: 511.00 Parts: 91.37 Total: 602.37

Work Order: 2211736 **Meter:** 49988 **In Date:** 11/18/2022 **Closed:** 01/03/2023

Problem: Weld Hitch

Work Completed

- Rear bumper mounts broken. Grind and prep mounts and hitch. Weld broken mounts.
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 4.50

Comm: 0.00

Labor: 328.50 Parts: 2.65 Total: 331.15

Work Order: 2300048 **Meter:** 49990 **In Date:** 01/03/2023 **Closed:** 01/09/2023

Problem: Water leak in cab and dry all interior

Work Completed

- Water leak test . Found high mount brake light cover leaking . Remove all interior to remove pad to dry . Dry all electrical connectors and seats . Replace high mounted cover and reseal .retest . reinstall
- Shop Supplies

Parts Issued

Quantity

2 Pc Dickies Black	1.00
Permatex	1.00
Cover	1.00
Shop Supplies	1.00

Hours: 3.00

Comm: 0.00

Labor: 219.00 Parts: 49.30 Total: 268.30

4/10/2026
9:33:56 AM

Palm Beach County Fleet Management Asset Maintenance History
10198322 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 2405748 **Meter:** 60939 **In Date:** 06/11/2024 **Closed:** 06/25/2024
Problem: PM Service.

Work Completed

- Performed P.m. Service & Inspection.
- Performed Tire Rotation And Balance On All 6 Tires, Add Nitro Fill Reset Tpms.
- Removed And Replaced Corroded Trailer Plug.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Trailer Connector Truck Side	1.00
Napagold Air Filter	1.00
Shop Supplies	1.00

Hours: 6.50

Comm: 0.00

Labor: 474.50 Parts: 79.20 Total: 553.70

Work Order: 2407571 **Meter:** 61950 **In Date:** 08/07/2024 **Closed:** 08/15/2024
Problem: power steering leaking

Work Completed

- Power Steering Winning While Car Started Found Fluid To Be Low Found Leaking Coming From Hydro Booster And Seepage At Gear Box Replace Booster And Bleed System Recheck For Leaks
- Shop Supplies

Parts Issued

Quantity

oil auto	2.00
Brake Booster	1.00
Shop Supplies	1.00

Hours: 3.20

Comm: 0.00

Labor: 233.60 Parts: 351.17 Total: 584.77

4/10/2026
9:33:56 AM

Palm Beach County Fleet Management Asset Maintenance History
10198322 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 2411909 **Meter:** 64420 **In Date:** 12/17/2024 **Closed:** 01/13/2025
Problem: PM Service.

Work Completed

Parts Issued

Quantity

- Performed P.m. Service & Inspection.
- Performed Tire Rotation Balance On All 6 Tires, Add Nitro Fill Reset Tpms.
- Vehicle Will Not Start Load Test Battery; Battery Test Recommend Charge. Charged Battery & Retest. Battery Failed. Removed & Replaced Battery. Then Reset Bms.
- Front Brake Pads Are Below Manufacture Specs, Removed Front Brake Calipers, Then Resurface Both Front Brake Rotors, Replaced Pads Lubricate Calipers Slide And Bleed The Entire Brake System. Test Drove Burnish Brakes On Vehicle.
- Rear Back-up Light Damaged. Removed And Replaced Then Check.
- Rear Back-up Camera Inop, Check & Confirm, Check Power And Ground Source. Power & Ground Ok, Camera System Defective. Removed & Replaced Complete System Modify And Reroute Wiring Harness. Rear Trailer Plug Connection Has Corrosion Cut & Splice Harnes
- Shop Supplies

Napa Quart 5w30	8.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Non-chlor Brake Clnr	2.00
Brk Fluid Dot 4-32oz	1.00
Front Brake Pad	1.00
4 Back-up Lamp	1.00
Backup Cam Kit w/mirror	1.00
Battery	1.00
4 Back-up Kit	1.00
Shop Supplies	1.00

Hours: 17.00 Comm: 0.00 Labor: 1,241.00 Parts: 480.26 Total: 1,721.26

Work Order: 2500999 **Meter:** 64420 **In Date:** 01/08/2025 **Closed:** 01/30/2025
Problem: Damage-to front bumper

Work Completed

- Damage-to front bumper

Hours: 0.00 Comm: 1,280.12 Labor: 0.00 Parts: 0.00 Total: 1,280.12

Work Order: 2501060 **Meter:** 64484 **In Date:** 02/03/2025 **Closed:** 02/04/2025
Problem: truck/trailer plug not working

Work Completed

Parts Issued

Quantity

- Check & replace trailer plug connector and rewire as needed
- Shop Supplies

Trailer Connector Truck Side	1.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 11.42 Total: 84.42

4/10/2026
9:33:56 AM

Palm Beach County Fleet Management Asset Maintenance History
10198322 2015 FORD F350 Utility Body, 13,700 Gvwr

Work Order: 2506233 **Meter:** 67942 **In Date:** 07/07/2025 **Closed:** 07/23/2025
Problem: PM Service. Has nail in driver, rear tire. LT245/75R/17

Work Completed

- Performed P.m. Service & Inspection.
- Performed Flat Repair On L/r Tire, Then Balance & Rotate All 6 Tires, Add Nitro Fill Set Tire Pressure.
- Performed Cooling Pressure Test, Radiator Leaking, Removed & Replaced Radiator As Well As Thermostat And Gaset And Er Rad Hse, Then Bleed And Flsh System & Check.
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Napa Quart 5w30	8.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Coolent	2.00
Thermostat	1.00
Radiator	1.00
Seal Thermostat	1.00
Upper Hose	1.00
Shop Supplies	1.00

Hours: 11.90 Comm: 0.00

Labor: 868.70 Parts: 1,048.41 Total: 1,917.11

Work Order: 2600391 **Meter:** 71705 **In Date:** 01/14/2026 **Closed:** 01/14/2026
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00

Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 213.20

Total Labor: 14,907.50

Total Comm: 1,280.12

Total Parts: 10,669.93