

4/10/2026
9:38:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10203940 2018 FORD F450 Utility Body, 16,500 Gvwr, Crew Cab, Topper

Total Hours: 239.50 Labor: 17,125.00 Parts: 14,934.18 Comm: 22,284.07 Charged: 54343.25

Work Order: 1801489 **Meter:** 327 **In Date:** 02/07/2018 **Closed:** 02/08/2018
Problem: pre delivery inspection

Work Completed

Parts Issued

Quantity

- pre delivery inspection
- Shop Supplies

Shop Supplies 1.00

Hours: 3.00 Comm: 0.00 Labor: 180.00 Parts: 2.00 Total: 182.00

Work Order: 1802681 **Meter:** 886 **In Date:** 03/12/2018 **Closed:** 03/15/2018
Problem: Install ignition power for radio

Work Completed

- Fabricate and install ignition power source for radio.

Hours: 0.50 Comm: 0.00 Labor: 30.00 Parts: 0.00 Total: 30.00

Work Order: 1805305 **Meter:** 2745 **In Date:** 05/24/2018 **Closed:** 06/01/2018
Problem: DEF

Work Completed

Parts Issued

Quantity

- def
- Shop Supplies

Blue Df 2.00

Shop Supplies 1.00

Hours: 0.50 Comm: 0.00 Labor: 30.00 Parts: 31.07 Total: 61.07

4/10/2026
9:38:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10203940 2018 FORD F450 Utility Body, 16,500 Gvwr, Crew Cab, Topper

Work Order: 1900974 **Meter:** 8549 **In Date:** 01/25/2019 **Closed:** 02/01/2019
Problem: PM

Work Completed

- Pm
- Def
- Service Ac
- R&r in tank fuel filter
- Remove water from tank
- Pintle pin
- Weld vice handle
- Test run
- Shop Supplies

Parts Issued

Quantity

Motor Tune-up 16oz	2.00
Non-chlor Brake Clnr	3.00
15-40 Oil	15.00
Napagold Oil Filter	1.00
Air Filter	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Blue Df	2.00
Cabin Air Filter	1.00
Fuel Fil	1.00
Pintle Pin W/clip	1.00
ridgid vise handle	1.00
Shop Supplies	1.00

Hours: 11.50 Comm: 0.00 Labor: 770.50 Parts: 363.14 Total: 1,133.64

Work Order: 1902705 **Meter:** 9640 **In Date:** 03/12/2019 **Closed:** 03/12/2019
Problem: Dead Battery

Work Completed

- Jump Start
- To R&b
- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 2.00 Comm: 0.00 Labor: 134.00 Parts: 3.00 Total: 137.00

Work Order: 1904164 **Meter:** 10691 **In Date:** 04/17/2019 **Closed:** 04/26/2019
Problem: trailer plug issue

Work Completed

- Replace bad trailer plug
- Shop Supplies

Parts Issued

Quantity

trailer plug	1.00
Shop Supplies	1.00

Hours: 2.00 Comm: 0.00 Labor: 134.00 Parts: 14.10 Total: 148.10

4/10/2026
9:38:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10203940 2018 FORD F450 Utility Body, 16,500 Gvwr, Crew Cab, Topper

Work Order: 1907791 **Meter:** 13725 **In Date:** 07/26/2019 **Closed:** 08/01/2019
Problem: PM

Work Completed

Parts Issued

Quantity

- pm	15-40 Oil	15.00		
- add def	Napagold Oil Filter	1.00		
- replace intank fuel filter	Air Filter	1.00		
- ac service	Fuel Fil	1.00		
- replace tag light assembly	Washer Fluid Concentr	1.00		
- pull codes with scan tool. B0001 airbag code	Wiper Blade	2.00		
- to ford 2xs	Non-chlor Brake Clnr	2.00		
- road test	Blue Df	2.00		
- Shop Supplies	Cabin Air Filter	1.00		
	Stick-on Rd Reflector	1.00		
	Led Tag Light	1.00		
	Shop Supplies	1.00		
Hours: 13.50	Comm: 0.00	Labor: 904.50	Parts: 259.05	Total: 1,163.55

Work Order: 1909043 **Meter:** 14123 **In Date:** 08/29/2019 **Closed:** 09/09/2019
Problem: DEF

Work Completed

Parts Issued

Quantity

- add def	Blue Df	3.00		
- Shop Supplies	Shop Supplies	1.00		
Hours: 1.00	Comm: 0.00	Labor: 67.00	Parts: 49.53	Total: 116.53

Work Order: 1909476 **Meter:** 14693 **In Date:** 09/16/2019 **Closed:** 09/19/2019
Problem: brake lights

Work Completed

Parts Issued

Quantity

- replace 2 rear brake lights and 2 body lights	Led Sup Mdl 44 42 Dio	2.00		
- Shop Supplies	Grommet Mount Kit	2.00		
	Shop Supplies	1.00		
Hours: 1.50	Comm: 0.00	Labor: 100.50	Parts: 164.79	Total: 265.29

4/10/2026
9:38:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10203940 2018 FORD F450 Utility Body, 16,500 Gvwr, Crew Cab, Topper

Work Order: 2107791 **Meter:** 31042 **In Date:** 07/16/2021 **Closed:** 07/23/2021
Problem: PM Service. will turn in of Friday/ Wiper

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service	15-40 Oil	15.00		
- Road test	Air Filter	1.00		
- Add Def	Fuel Fil	1.00		
- Service A/c system	Napagold Oil Filter	1.00		
- Replace Brake light lamps	Washer Fluid Concentr	1.00		
- Tires, 225/70r19.5 Lh rear 2	Wiper Blade	2.00		
- Wiper motor switch assy.	Cabin Air Filter	1.00		
- Shop Supplies	Blue Df	2.00		
	Used Fire X Refurbished	1.00		
	Led Sup Mdl 44 42 Dio	2.00		
	Wiper Switch	1.00		
	Shop Supplies	1.00		
Hours: 9.00	Comm: 0.00	Labor: 657.00	Parts: 333.26	Total: 990.26

Work Order: 2107925 **Meter:** 31042 **In Date:** 07/19/2021 **Closed:** 07/21/2021
Problem: LRIO Tires

Work Completed

- Tire Service: He Problem: Lrio Tires

Hours: 0.00 Comm: 149.13 Labor: 0.00 Parts: 0.00 Total: 149.13

Work Order: 2107927 **Meter:** 31042 **In Date:** 07/21/2021 **Closed:** 07/21/2021
Problem: LRIO Tires

Work Completed

- Tire Service: He Problem: Lrio Tires

Hours: 0.00 Comm: 508.55 Labor: 0.00 Parts: 0.00 Total: 508.55

4/10/2026
9:38:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10203940 2018 FORD F450 Utility Body, 16,500 Gvwr, Crew Cab, Topper

Work Order: 2112100

Meter: 33937

In Date: 11/10/2021 **Closed:** 12/22/2021

Problem: Repair Inverter

Work Completed

- Power inverter not operating. Found unit to have internal short, replace inverter and power cable.
- Hitch worn out due to loose hitch ball, replace hitch assembly.
- Unhook trailer from truck at Roads parking lot.
- Shop Supplies

Hours: 4.50

Comm: 0.00

Parts Issued

	Quantity
Bulk Battery Cable	14.00
3000 Watt Thor Inverter	1.00
Pntl Hitch	1.00
Shop Supplies	1.00

Labor: 328.50

Parts: 609.49

Total: 937.99

4/10/2026
9:38:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10203940 2018 FORD F450 Utility Body, 16,500 Gvwr, Crew Cab, Topper

Work Order: 2202476

Meter: 36598

In Date: 03/04/2022 **Closed:** 03/21/2022

Problem: PM Service. will turn in tomorrow

Work Completed

- Preventive Maint. Service
- Road test
- Add Def fluid
- Service A/c system
- Install Front brake pads, front rotors, bleed front brake system
- Install Rear brake pads, rear rotors, rear axle seals
- Remove & replace Battery
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	15.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Non-chlor Brake Clnr	2.00
Used Fire X Refurbished	1.00
Cabin Air Filter	1.00
Fuel Fil	1.00
Air Filter	1.00
Blue Df	2.00
Caliper	1.00
Caliper	1.00
Brake Pads	1.00
Rotor	2.00
Brake Pads	1.00
Seal	2.00
Left Axle Seal	2.00
Non-chlor Brake Clnr	2.00
Brk Fluid Dot 4-32oz	2.00
F81z1001ba Seal Ring	2.00
Caliper	1.00
Caliper	1.00
Rotor	2.00
Battery	2.00
Shop Supplies	1.00

Hours: 23.00

Comm: 0.00

Labor: 1,679.00

Parts: 2,112.57

Total: 3,791.57

4/10/2026
9:38:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10203940 2018 FORD F450 Utility Body, 16,500 Gvwr, Crew Cab, Topper

Work Order: 2202850 **Meter:** 36598 **In Date:** 03/09/2022 **Closed:** 03/16/2022
Problem: RRIO tires

Work Completed

- Tire Service: He Problem: Rrio tires

Hours: 0.00 Comm: 508.55 Labor: 0.00 Parts: 0.00 Total: 508.55

Work Order: 2202854 **Meter:** 36598 **In Date:** 03/16/2022 **Closed:** 03/16/2022
Problem: RRIO tires

Work Completed

- Tire Service: He Problem: Rrio tires

Hours: 0.00 Comm: 246.23 Labor: 0.00 Parts: 0.00 Total: 246.23

Work Order: 2206981 **Meter:** 39234 **In Date:** 07/01/2022 **Closed:** 07/05/2022
Problem: Motor Oil

Work Completed

- Add motor Oil
- Shop Supplies

Parts Issued	Quantity
Allterrain 15w40 Ga	4.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 103.45 Total: 176.45

Work Order: 2207301 **Meter:** 39411 **In Date:** 07/13/2022 **Closed:** 07/14/2022
Problem: Dist.3 Robert, truck needs training fluid

Work Completed

- Transmission - Main
- Shop Supplies

Parts Issued	Quantity
Multivehicleatf	2.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 18.40 Total: 91.40

Work Order: 2207508 **Meter:** 39654 **In Date:** 07/19/2022 **Closed:** 07/20/2022
Problem: Dist.3 Robert, truck is low on oil

Work Completed

- low on oil look for leaks an put new oil in
- Shop Supplies

Parts Issued	Quantity
Prem Blue 15w40 1 Gal	2.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 54.24 Total: 127.24

4/10/2026
9:38:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10203940 2018 FORD F450 Utility Body, 16,500 Gvwr, Crew Cab, Topper

Work Order: 2207653 **Meter:** 39875 **In Date:** 07/22/2022 **Closed:** 09/12/2022
Problem: Repair back door

Work Completed

Parts Issued

Quantity

- order back door latches
- Shop Supplies

slam latch	4.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 96.19 Total: 169.19

Work Order: 2207971 **Meter:** 39993 **In Date:** 08/02/2022 **Closed:** 08/04/2022
Problem: Oil

Work Completed

Parts Issued

Quantity

- Onsite Fueling, Lube
- Shop Supplies

Rotella T6 15w40 Ck4	1.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 41.16 Total: 114.16

Work Order: 2208573 **Meter:** 40505 **In Date:** 08/17/2022 **Closed:** 08/26/2022
Problem: Needs motor oil. Thank you

Work Completed

Parts Issued

Quantity

- Add motor Oil
- Shop Supplies

15-40 Oil	4.00
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 18.75 Total: 91.75

4/10/2026
9:38:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10203940 2018 FORD F450 Utility Body, 16,500 Gvwr, Crew Cab, Topper

Work Order: 2209276 **Meter:** 41023 **In Date:** 09/06/2022 **Closed:** 12/19/2022
Problem: PM/Dead Battery/AC inop

Work Completed

- Dead Batteries. Replace 2 batteries. Clean corrosion from cables and trays. Check charging system, Ok.
- Rear Utility door latches. Replace 4 latches. Loose glass in rear door, Remove clean and reinstall inside door.
- Service Call to Roads lot and back 2x
- Ac blower motor inoperative, verified power, ground and signal to blower motor. Replace blower motor. Check operation Ok.
- Pm Service.
- Ac Service. Change cabin air filter.
- Transmission Service.
- Broken Led backup light, replace backup light. Failing led brake lights. Replace both brake lights.
- Add Def
- Parasitic draw on batteries. Found .5amp draw from radio with key off. Radio stays on, screen displays (Maintenance mode external device).
- Check engine light. Scan, P2201 Nox sensor circuit range performance bank1 sensor 1. P20c2 Reductant heater C control performance. replace cab mounts
- to ford 2xs
- Shop Supplies

Parts Issued

Quantity

Battery	2.00
Blower Motor Asy	1.00
15-40 Oil	15.00
Blue Df	2.00
Led Back-up Lamp Sys	1.00
Transmission Filter	1.00
trans pan gasket	1.00
Syn-atf Trans Fluid S	12.00
Proformer Cabin Fil	1.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
Non-chlor Brake Clnr	2.00
Fuel Fil	1.00
Air Filter	1.00
Napagold Oil Filter	1.00
Led Sup Mdl 44 42 Dio	2.00
Tape	1.00
Shop Supplies	1.00

Hours: 24.00 Comm: 597.43 Labor: 1,752.00 Parts: 1,221.02 Total: 3,570.45

Work Order: 2212348 **Meter:** 4207 **In Date:** 12/09/2022 **Closed:** 12/14/2022
Problem: Dist.3 Robert, truck needs coolant

Work Completed

Parts Issued

Quantity

- low on coolant search for leak and add fluid
- search for leak and add fluid
- Shop Supplies

Coolent	1.00
oil auto	2.00
Shop Supplies	1.00

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 40.47 Total: 186.47

4/10/2026
9:38:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10203940 2018 FORD F450 Utility Body, 16,500 Gvwr, Crew Cab, Topper

Work Order: 2304721 **Meter:** 46022 **In Date:** 04/28/2023 **Closed:** 05/11/2023
Problem: Tires: All Wear. Replace Tire

Work Completed

- Tire Service: He Problem: Tires: All Wear. Replace Tire

Hours: 0.00 Comm: 2,342.81 Labor: 0.00 Parts: 0.00 Total: 2,342.81

Work Order: 2308316 **Meter:** 48818 **In Date:** 08/18/2023 **Closed:** 01/29/2024
Problem: PM Service Dist.3 Robert, will turn in today please let me know if it needs to go to the dealer . would like to get some

Work Completed

- Preventive Maint. Service
- Recall
- Ac goes out sometimes upon further inspection found vehicle to be low on freon found vehicle to have damaged ac condenser
- Found Air bag to be splitting and wheel to have deterioration on top of wheel replaced both steering wheel and air bag.
- Found batteries to be leaking and corroded removed and replaced both batteries.
- Found ac system not to be operating as designed found fan clutch to be damaged and also found damage to ac condenser upon further inspection found coolers to be damaged with debris removed all hoses and wires to remove cooler assembly
- Replaced Drive Belt along with belt tensioner and idler pulley
- Steering service
- Replaced Washer fluid pump
- Removal and reinstallation of front end. bumper, grille, headlights, all mounting, horn, core support
- Disassembled cooling system assembly main radiator and aux radiator along with condenser and replaced all parts to rebuild pack reused necessary hardware. replaced fan shrouds. see line 6 for parts
- Extended test drive to ensure proper repairs.
- Replaced lower radiator hose along with upper radiator hose

Parts Issued

Quantity

Clutch Assy	1.00
A/cseal	1.00
Condenser	1.00
Wheel Assy	1.00
Thermostat	1.00
Thermostat	1.00
Hose Asm	1.00
Radiator	1.00
Radiator	1.00
Tensioner	1.00
Pulley	1.00
Belt	1.00
Washer Pump	1.00
oil auto	2.00
Reservoir	1.00
Brake Parts Cleaner	2.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Brake Parts Cleaner	4.00
15-40 Oil	15.00
Used Fire X Refurbished	1.00
Napagold Oil Filter	1.00

4/10/2026
9:38:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10203940 2018 FORD F450 Utility Body, 16,500 Gvwr, Crew Cab, Topper

- Upon Pm service found engine to be severely sledged from lack of service intervals. Removed oil pan cleaned pickup cleaned oil pan reassembled with sealant. Removed engine oil filter housing . Replaced gasket and cleaned housing.

- Performed multiple oil changes on vehicle along with letting vehicle run with engine flush and seafoam. Inspected all seals for any leaks and engine for abnormal sounds.

- Add Def

- Found blower motor to be intermittently in op tested voltage at blower motor checked blower motor for debris, found fuse to be good but found relay to be faulty removed and replaced relay

- repair engine light by Ford

- Shop Supplies

Parts Issued	Quantity
Fuel Fil	1.00
Air Filter	1.00
Cabin Air Filter	1.00
Distilled Water 1gal	4.00
Coolent	7.00
O Rings	1.00
Shroud	1.00
Shroud	1.00
Shroud	1.00
Px Grey Rtv Silicone	1.00
Napagold Oil Filter	2.00
Hose Assy	1.00
Tube	1.00
Flush	2.00
15-40 Oil	30.00
Hose Assy	1.00
Heater Hose	1.00
Hose	1.00
Blue Sky Def 2.5gal	2.00
Distilled Water 1gal	3.00
Relay	1.00
Shop Supplies	1.00
Labor: 3,212.00	Parts: 4,097.38
Total: 8,121.17	

Hours: 44.00

Comm: 811.79

4/10/2026
9:38:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10203940 2018 FORD F450 Utility Body, 16,500 Gvwr, Crew Cab, Topper

Work Order: 2402942 **Meter:** 51952 **In Date:** 03/25/2024 **Closed:** 04/01/2025

Problem: PM/ A/C not working./engine light on

Work Completed

- ac/engine light/gear box repair by ford
- Recall: Customer Satisfaction Program 20n04. Steering damper replacement for sustained steering oscillation.
- to ford 2xs
- Preventive Maint. Service
- Add Def Fluid
- A/c Service + Relay
- Replace two rear brake lights
- Replace Ccv Filter
- Jump start truck, replace both batteries and battery brackets
- To weber
- alignment
- Ford repair exhaust
- rewire radio harness through firewall grommet
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	15.00
Non-chlor Brake Clnr	6.00
Used Fire X Refurbished	1.00
Napagold Oil Filter	1.00
Fuel Fil	1.00
Air Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Blue Df	2.00
Relay	1.00
Cabin Air Filter	1.00
Led Sup Mdl 44 42 Dio	2.00
Damper Asy	1.00
Oil Separator	1.00
Battery	2.00
Battery Bracket	2.00
Align Front Truck	1.00
Shop Supplies	1.00

Hours: 26.00

Comm: 9,177.41

Labor: 1,898.00

Parts: 1,359.13

Total: 12,434.54

Work Order: 2404427 **Meter:** 50941 **In Date:** 05/03/2024 **Closed:** 05/06/2024

Problem: D3 Robert, truck battery is dead in our yard key is in it

Work Completed

- Operator states truck will not start, found dead battery. Batteries failed load test. Replace batteries. Clean corrosion from terminals trays and brackets.
- Service Call to Roads lot and back.
- Shop Supplies

Parts Issued

Quantity

Battery	2.00
Shop Supplies	1.00

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 377.57

Total: 523.57

4/10/2026
9:38:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10203940 2018 FORD F450 Utility Body, 16,500 Gvwr, Crew Cab, Topper

Work Order: 2502870 **Meter:** 52548 **In Date:** 03/26/2025 **Closed:** 03/27/2025
Problem: D3 Robert, truck AC not blowing

Work Completed

Parts Issued

Quantity

- A/c not functioning, found blown front blower motor fuse and relay,
replace both, test amp draw from blower motor, amps within spec
- Shop Supplies

Relay	1.00
Shop Supplies	1.00

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 28.99 Total: 174.99

Work Order: 2511016 **Meter:** 59998 **In Date:** 11/21/2025 **Closed:** 01/24/2026
Problem: PM engine knock/turbo not working right BLOWN ENGINE DECLINED FORD REPAIR

Work Completed

- Al Packer - inspection decline repair

Hours: 0.00 Comm: 235.44 Labor: 0.00 Parts: 0.00 Total: 235.44

Work Order: 2511486 **Meter:** 59998 **In Date:** 11/25/2025 **Closed:** 12/11/2025
Problem: Tow-making noises

Work Completed

- Tow From: Fleet Vista He Shop To: Al Packer East

Hours: 0.00 Comm: 216.00 Labor: 0.00 Parts: 0.00 Total: 216.00

Work Order: 2511489 **Meter:** 59998 **In Date:** 11/20/2025 **Closed:** 12/11/2025
Problem: Tow-runs, just wont move

Work Completed

- Tow From: Jog Rd, S of Belvedere. Nb To: fleet vista He shop

Hours: 0.00 Comm: 216.00 Labor: 0.00 Parts: 0.00 Total: 216.00

Work Order: 2600442 **Meter:** 59998 **In Date:** 01/06/2026 **Closed:** 01/15/2026
Problem: Tow-return truck from dealer to be towed on 1/7/26

Work Completed

- Tow From: Al packer E To: fleet vista He shop

Hours: 0.00 Comm: 216.00 Labor: 0.00 Parts: 0.00 Total: 216.00

4/10/2026
9:38:34 AM

Palm Beach County Fleet Management Asset Maintenance History
10203940 2018 FORD F450 Utility Body, 16,500 Gvwr, Crew Cab, Topper

Work Order: 2602417 **Meter:** 59998 **In Date:** 03/12/2026 **Closed:** 03/24/2026
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 239.50

Total Labor: 17,125.00

Total Comm: 22,284.07

Total Parts: 14,934.18