

4/10/2026
9:41:41 AM

10198918

Palm Beach County Fleet Management Asset Maintenance History
2016 INTERNATIONAL DURASTAR Dump Truck, 5 Yd, 25,500 Gvwr, Steel Body

Total Hours: 299.00 Labor: 20,813.00 Parts: 26,152.23 Comm: 28,305.78 Charged: 75271.00

Work Order: 1513102 **Meter:** 357 **In Date:** 12/31/2015 **Closed:** 01/15/2016
Problem: fill def tank

Work Completed

Parts Issued

Quantity

- Parts Only

Def Quart

10.00

Hours: 0.00

Comm: 0.00

Labor: 0.00

Parts: 15.45

Total: 15.45

Work Order: 1513122 **Meter:** 356 **In Date:** 12/31/2015 **Closed:** 12/31/2015
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 5.00

Comm: 0.00

Labor: 300.00

Parts: 0.00

Total: 300.00

Work Order: 1601184 **Meter:** 357 **In Date:** 02/03/2016 **Closed:**
Problem: Side Boards

Work Completed

-

Hours: 0.00

Comm: 0.00

Labor: 0.00

Parts: 0.00

Total: 0.00

Work Order: 1602971 **Meter:** 1561 **In Date:** 03/21/2016 **Closed:** 03/25/2016
Problem: DEF

Work Completed

Parts Issued

Quantity

- add Def

Blue Df

3.00

- to lake lytal

Shop Supplies

1.00

- Shop Supplies

Hours: 1.50

Comm: 0.00

Labor: 90.00

Parts: 42.73

Total: 132.73

Work Order: 1603794 **Meter:** 2115 **In Date:** 04/08/2016 **Closed:** 04/11/2016
Problem: Accident at Lake Lyal Park

Work Completed

- Tow From: Lake Lytal Park To: Accident Line

Hours: 0.00

Comm: 242.40

Labor: 0.00

Parts: 0.00

Total: 242.40

4/10/2026
9:41:41 AM

10198918

Palm Beach County Fleet Management Asset Maintenance History
2016 INTERNATIONAL DURASTAR Dump Truck, 5 Yd, 25,500 Gvwr, Steel Body

Work Order: 1700660

Meter: 6596

In Date: 01/23/2017 **Closed:** 02/08/2017

Problem: pm

Work Completed

- pm
- replace airdryer and install tank and valves
- Def
- install fire ext
- road test
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	16.00
Napagold Fuel Filter	1.00
fuel filter	1.00
fuel filter	1.00
2602212c1 Air Filter	1.00
Napa Cabin Air Filter	1.00
Wiper Blade	2.00
Ad Ip Dryer Cart	1.00
Drain Valve	2.00
Def Bulk Qts	12.00
Used Fire X Refurbished	1.00
Custom Bracket Fire Ex	1.00
Shop Supplies	1.00

Hours: 11.00

Comm: 0.00

Labor: 660.00

Parts: 492.22

Total: 1,152.22

4/10/2026
9:41:41 AM

10198918

Palm Beach County Fleet Management Asset Maintenance History
2016 INTERNATIONAL DURASTAR Dump Truck, 5 Yd, 25,500 Gvwr, Steel Body

Work Order: 1707329

Meter: 12111

In Date: 07/26/2017 **Closed:** 08/21/2017

Problem: pm/list

Work Completed

- Pm
- Add Def
- Replace Rear Brake Light, Drill Holes
- Replace Hitch And Install New Bolts
- Reattach Hood Insulation
- Road Test
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	16.00
57182 Oil Filter Frm	1.00
fuel filter	1.00
Air Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Non-chlor Brake Clnr	1.00
Used Fire X Refurbished	1.00
fuel filter	1.00
Blue Df	1.00
led light	1.00
Pintle Hook Rigid 20t	1.00
mounting kit	1.00
Marine Adh Seal White	1.00
Cable Tie	1.00
Shop Supplies	1.00

Hours: 11.50

Comm: 0.00

Labor: 690.00

Parts: 511.36

Total: 1,201.36

4/10/2026
9:41:41 AM

10198918

Palm Beach County Fleet Management Asset Maintenance History
2016 INTERNATIONAL DURASTAR Dump Truck, 5 Yd, 25,500 Gvwr, Steel Body

Work Order: 1802248
Problem: PM

Meter: 18338

In Date: 02/28/2018 **Closed:** 03/13/2018

Work Completed

- Pm
- Service Ac
- Repair tag light
- Service Air Dryer
- Def tank filter
- Road test
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	16.00
57182 Oil Filter Frm	1.00
Napagold Fuel Filter	1.00
Used Fire X Refurbished	1.00
Wiper Blade	2.00
Non-chlor Brake Clnr	1.00
fuel filter	1.00
Air Filter	1.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Bracket	1.00
Led License Kit	1.00
Ad Ip Dryer Cart	1.00
Def Filter	1.00
Shop Supplies	1.00

Hours: 12.50

Comm: 0.00

Labor: 750.00 Parts: 528.77 Total: 1,278.77

Work Order: 1804880
Problem: DEF

Meter: 20032

In Date: 05/10/2018 **Closed:** 06/01/2018

Work Completed

- def
- Shop Supplies

Parts Issued

Quantity

Blue Df	2.00
Shop Supplies	1.00

Hours: 0.50

Comm: 0.00

Labor: 30.00 Parts: 31.07 Total: 61.07

4/10/2026
9:41:41 AM

10198918

Palm Beach County Fleet Management Asset Maintenance History
2016 INTERNATIONAL DURASTAR Dump Truck, 5 Yd, 25,500 Gvwr, Steel Body

Work Order: 1809310
Problem: pm

Meter: 23143

In Date: 09/11/2018 **Closed:** 10/02/2018

Work Completed

- Pm
- Def
- Service Trans
- Replace stop light, tag light and running lights. Repaired tag bracket
- Ps service
- Replace lower radiator support
- Replace tarp chain case
- Road test
- Shop Supplies

Parts Issued

Quantity

Non-chlor Brake Clnr	2.00
15-40 Oil	16.00
oil filter	1.00
fuel filter	1.00
Napagold Fuel Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Blue Df	1.00
Syn-atf Trans Fluid S	20.00
Napa Trans Filter	1.00
Led Red Tail Light	2.00
Grommet Mount Kit	2.00
Led Tag Light	1.00
Psf Qt	1.00
Power Steering Filter	1.00
24 175 Uvb Cable Tie	1.00
Swing Arm	1.00
Tarp Bar	1.00
Chain - Roller	1.00
Control Crank Kit	1.00
License Plate Brkt	1.00
Shop Supplies	1.00

Hours: 19.00

Comm: 0.00

Labor: 1,273.00

Parts: 1,004.67

Total: 2,277.67

4/10/2026
9:41:41 AM

10198918

Palm Beach County Fleet Management Asset Maintenance History
2016 INTERNATIONAL DURASTAR Dump Truck, 5 Yd, 25,500 Gvwr, Steel Body

Work Order: 1900045
Problem: Batteries

Meter: 24598

In Date: 01/02/2019 **Closed:** 01/09/2019

Work Completed

- Replace batteries
- To Jp Park
- Shop Supplies

Hours: 2.00

Comm: 0.00

Parts Issued

Group 31 Stud Delco

2.00

Shop Supplies

1.00

Labor: 134.00

Parts: 302.34

Total: 436.34

4/10/2026
9:41:41 AM

10198918

Palm Beach County Fleet Management Asset Maintenance History
2016 INTERNATIONAL DURASTAR Dump Truck, 5 Yd, 25,500 Gvwr, Steel Body

Work Order: 1901701 **Meter:** 25537 **In Date:** 02/13/2019 **Closed:** 03/07/2019
Problem: AC / Plate

Work Completed

- Replace evaporator, dryer, exp. valve, charged system, and cleaned air box
- R&r tag light assembly
- Pm
- Replace Def filter
- Road test
- Shop Supplies

Parts Issued

Quantity

Evap Odor Elinitator	1.00
Expansion Valve	1.00
Filter Dryer	1.00
evap coil	1.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
E8 A/c Oil Univ W Dye	1.00
Freon He Shop	8.00
A/c Seal Kit	1.00
Led Tag Light	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
15-40 Oil	16.00
Air Filter	1.00
Napagold Fuel Filter	1.00
fuel filter	1.00
oil filter	1.00
Urea Def Filter	1.00
Blue Df	1.00
Shop Supplies	1.00

Hours: 24.50

Comm: 0.00

Labor: 1,641.50

Parts: 1,669.53

Total: 3,311.03

Work Order: 1905636 **Meter:** 27728 **In Date:** 05/21/2019 **Closed:** 05/29/2019
Problem: Driver Rear inside tire, chunk out of tire, needs replaced

Work Completed

- Tire Service Jpp, maint compound, pole barn - Driver Rear inside tire, chunk out of tire, needs replaced

Hours: 0.00

Comm: 401.42

Labor: 0.00

Parts: 0.00

Total: 401.42

4/10/2026
9:41:41 AM

10198918

Palm Beach County Fleet Management Asset Maintenance History
2016 INTERNATIONAL DURASTAR Dump Truck, 5 Yd, 25,500 Gvwr, Steel Body

Work Order: 1910247 **Meter:** 30730 **In Date:** 10/03/2019 **Closed:** 11/06/2019
Problem: PM/ wood for bed

Work Completed

- pm
- a/c svc
- def replace filter
- svc air dryer
- repair tarp add wood rails
- trans filter
- test run
- Shop Supplies

Parts Issued

Quantity

1cart Palladium 2 Grs	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Napagold Fuel Filter	1.00
fuel filter	1.00
Air Fltr	1.00
oil filter	1.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Def Filter	1.00
Ad Ip Dryer Cart	1.00
Tarp Bar	1.00
Bushing	4.00
Connect Arm Kit	1.00
2x6 10ft Trl Wood	2.00
15-40 Oil	16.00
Shop Supplies	1.00

Hours: 18.00

Comm: 0.00

Labor: 1,314.00

Parts: 764.56

Total: 2,078.56

Work Order: 2002369 **Meter:** 33755 **In Date:** 03/06/2020 **Closed:** 03/25/2020
Problem: DEF tank guage

Work Completed

- Def guage stuck on full. Def multi-fuction head unit failed. Replaced
- Service coolant
- Test Drive
- Shop Supplies

Parts Issued

Quantity

Sensor Mod Unit	1.00
Funnel	1.00
Rotell Elc Antifeerze	6.00
Shop Supplies	1.00

Hours: 8.00

Comm: 0.00

Labor: 584.00

Parts: 2,779.84

Total: 3,363.84

4/10/2026
9:41:41 AM

10198918

Palm Beach County Fleet Management Asset Maintenance History
2016 INTERNATIONAL DURASTAR Dump Truck, 5 Yd, 25,500 Gvwr, Steel Body

Work Order: 2012963 **Meter:** 39525 **In Date:** 12/30/2020 **Closed:** 12/31/2020
Problem: Tires

Work Completed

- Tire Replacement
- Shop Supplies

Parts Issued

Quantity

11r22.5bstone R268	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 0.00

Comm: 0.00

Labor: 0.00

Parts: 1,190.70

Total: 1,190.70

Work Order: 2106478 **Meter:** 44261 **In Date:** 06/15/2021 **Closed:** 06/30/2021
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Add Def
- Service A/c and clean evaporator
- Tarp arms broken. R&r tarp arms and tarp assy.
- R&r Def filter
- R&r air drier
- Service Trans
- Service cooling system
- Service Power steering
- Replace leaking hub caps. Front axle bearings loose. Adjust front wheel bearings.
- Air tank leaking at water drain valve. R&r drain valve
- Test Run
- Shop Supplies

Parts Issued

Quantity

Washer Fluid Concentr	1.00
Wiper Blade	2.00
15-40 Oil	16.00
Air Fltr	1.00
Napagold Fuel Filter	1.00
Fuel Filter Repace Ff63009	1.00
57182 Oil Filter Frm	1.00
Non-chlor Brake Clnr	3.00
Used Fire X Refurbished	1.00
1qt Syngear Oil 75-90	3.00
Cap Hub	2.00
Blue Df	2.00
Evap Odor Elinitator	1.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Bushing	4.00
Tarp 7.5x18	1.00
Swing Arm	2.00
Tarp Bar	1.00
Connect Arm Kit	1.00
Cable Tie	1.00

4/10/2026
9:41:41 AM

10198918

Palm Beach County Fleet Management Asset Maintenance History
2016 INTERNATIONAL DURASTAR Dump Truck, 5 Yd, 25,500 Gvwr, Steel Body

Parts Issued	Quantity
Hose Clamp	8.00
Urea Def Filter	1.00
Ad Ip Dryer Cart	1.00
Napa Trans Filter	1.00
Syn-atf Trans Fluid S	20.00
Distilled Water 1gal	6.00
Rotell Elc Antifeerze	6.00
Psf Qt	2.00
Power Steering Filter	1.00
Fittings From Mako	1.00
Shop Supplies	1.00

Hours: 30.00

Comm: 0.00

Labor: 2,190.00

Parts: 1,552.21

Total: 3,742.21

Work Order: 2107369

Meter: 44546

In Date: 07/08/2021 **Closed:** 07/09/2021

Problem: This dump truck blew an air hose and the bed will not go down. At JPP Maint. Compound. by pole barns. Key above visor.

Work Completed

- air leak- replace several fittings
- to and from jpp 7/8
- to and from mako .5 wait 7/8
- Shop Supplies

Parts Issued	Quantity
Fittings From Mako	1.00
Shop Supplies	1.00

Hours: 4.00

Comm: 0.00

Labor: 292.00

Parts: 61.50

Total: 353.50

Work Order: 2107838

Meter: 44795

In Date: 07/15/2021 **Closed:** 07/19/2021

Problem: LRI flat

Work Completed

- Tire Service: Jpp Problem: Lri flat

Hours: 0.00

Comm: 74.37

Labor: 0.00

Parts: 0.00

Total: 74.37

4/10/2026
9:41:41 AM

**10198918 Palm Beach County Fleet Management Asset Maintenance History
2016 INTERNATIONAL DURASTAR Dump Truck, 5 Yd, 25,500 Gvwr, Steel Body**

Work Order: 2108917 **Meter:** 45233 **In Date:** 08/17/2021 **Closed:** 08/18/2021
Problem: Staff are working down south with this truck. They said that the chain came off the tarp roller. Can you please help?

Work Completed

Parts Issued

Quantity

- Remove chain drive cover.re install and lube chain drive for tarp system.
- Shop Supplies

Shop Supplies 1.00

Hours: 1.50 Comm: 0.00 Labor: 109.50 Parts: 2.65 Total: 112.15

Work Order: 2108975 **Meter:** 45233 **In Date:** 08/18/2021 **Closed:** 09/15/2021
Problem: Had chain fixed yesterday, but tech did not put staff's tie back on the chain to prevent the chain from coming back off.

Work Completed

Parts Issued

Quantity

- Tarp crank box broken. Remove broken crank box. Modify new crank box to work with truck design and mounting. Install new crank box, chain and cover. Fix tarp to rod mounts.
- Shop Supplies

crank box 1.00

Shop Supplies 1.00

Freight Charge 1.00

Hours: 3.00 Comm: 0.00 Labor: 219.00 Parts: 455.78 Total: 674.78

Work Order: 2113700 **Meter:** 47175 **In Date:** 12/30/2021 **Closed:** 02/09/2022
Problem: PM

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- added def
- coolant low. Ran a pressure test and decided to add more coolant
- test drive
- Shop Supplies

15-40 Oil 16.00

57182 Oil Filter Frm 1.00

Napagold Fuel Filter 1.00

Air Fltr 1.00

Fuel Filter Repace Ff63009 1.00

Washer Fluid Concentr 1.00

Wiper Blade 2.00

Non-chlor Brake Clnr 3.00

Used Fire X Refurbished 1.00

Blue Df 2.00

Rotell Elc Antifeerze 1.00

Shop Supplies 1.00

Hours: 8.50 Comm: 0.00 Labor: 620.50 Parts: 244.33 Total: 864.83

4/10/2026
9:41:41 AM

10198918

Palm Beach County Fleet Management Asset Maintenance History
2016 INTERNATIONAL DURASTAR Dump Truck, 5 Yd, 25,500 Gvwr, Steel Body

Work Order: 2210594 **Meter:** 53889 **In Date:** 10/17/2022 **Closed:** 12/21/2022
Problem: PM Service./pintle pin

Work Completed

- Preventive Maint. Service
- Upon Inspection found leaking crankcase oil lines, remove fuel filter and electrical harnesses to gain access to lines, also replace crankcase ventilation filter to avoid further leakage
- Add Def
- A/c Service including cleaner
- Power Steering Service
- Cooling System Service
- Operator complaint, pintle pin needs replaced
- Upon inspection air noise coming from valve solenoid, upon further inspection found solenoid to be leaking, replace and test
- Fix ripped tarp and reel back in straight
- Road Test
- Shop Supplies

Parts Issued

Quantity

1cart Palladium 2 Grs	1.00
Non-chlor Brake Clnr	3.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
57182 Oil Filter Frm	1.00
Air Fltr	1.00
Napagold Fuel Filter	1.00
Tube Lube	1.00
Crankcase Breather Element	1.00
Hose Coupler	2.00
Urea Def Filter	1.00
Blue Df	1.00
Evap Odor Elinitator	1.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Psf Qt	2.00
Power Steering Filter	1.00
Rotell Elc Antifeerze	1.00
Pin For 1/4"x3" Pintle Hook	1.00
15-40 Oil	16.00
Used Fire X Refurbished	1.00
Fitting	1.00
Valve	1.00
Shop Supplies	1.00

Hours: 20.50

Comm: 0.00

Labor: 1,496.50

Parts: 783.06

Total: 2,279.56

Work Order: 2307534
Problem: PM Service.

Meter: 60317

In Date: 07/28/2023 **Closed:** 11/09/2023

Work Completed

4/10/2026
9:41:41 AM

10198918

Palm Beach County Fleet Management Asset Maintenance History
2016 INTERNATIONAL DURASTAR Dump Truck, 5 Yd, 25,500 Gvwr, Steel Body

	Parts Issued	Quantity
- Preventive Maint. Service	1cart Palladium 2 Grs	1.00
- Remove and replace air dryer	Napa Gal 15w40	4.00
- Service cabin filters and perform evaporator cleaning	Used Fire X Refurbished	1.00
- Add Def	Non-chlor Brake Clnr	4.00
- Found rear tail lights to be damaged and have faulty leds removed and replaced both led tail lamps on vehicle	57182 Oil Filter Frm	1.00
- Upon inspection found hydraulic hoses coming from and to hydraulic tank to be damaged multiple cracks and wear through both hoses removed and replaced after wait and travel to mako	Air Fltr	1.00
- Travel to mako for hoses plus wait	Napagold Fuel Filter	1.00
- Operator states board on drivers side dump bed damaged remove and replace .	Wiper Blade	2.00
- Rebuild Tarp assembly new arms new tarp new corner arms along with new tarp bar	Washer Fluid Concentr	1.00
- Pressure valve on air dryer receiver is faulty causing air system to not reach desired air pressure removed and replaced air dryer assembly	Ad Ip Dryer Cart	1.00
- Test Run	Evap Odor Elinitator	1.00
- Shop Supplies	Cabin Air Filter	1.00
	cabin filter	1.00
	Def Filter	1.00
	Blue Sky Def 2.5gal	3.00
	Fuel Filter Repace Ff63009	1.00
	Hose From Mako	1.00
	3m Tm Headlight Lens	1.00
	Cable Tie	1.00
	Rainx	1.00
	Rain-x Original Glass	1.00
	Wd40 Spr	1.00
	Tail Light Asm	1.00
	Tail Light	1.00
	2x6-12ft Pt Wood	1.00
	Blue Monster Teflon Tape	1.00
	Reman Air Dryer	1.00
	Swing Arm	2.00
	Tarp Bar	1.00
	Connect Arm Kit	1.00

4/10/2026
9:41:41 AM

10198918

Palm Beach County Fleet Management Asset Maintenance History
2016 INTERNATIONAL DURASTAR Dump Truck, 5 Yd, 25,500 Gvwr, Steel Body

Parts Issued	Quantity
---------------------	-----------------

Bushing	4.00
---------	------

7-6 X 14' Tarp	1.00
----------------	------

Shop Supplies	1.00
---------------	------

Hours: 27.50

Comm: 0.00

Labor: 2,007.50

Parts: 1,611.05

Total: 3,618.55

Work Order: 2311751

Meter: 60548

In Date: 11/27/2023 **Closed:** 11/29/2023

Problem: Add oil

Work Completed

Parts Issued	Quantity
---------------------	-----------------

- add hydraulic oil to dump body system , check for any major leaks none found.

Aw68 Hydro Fluid Hydr	25.00
-----------------------	-------

- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.00

Comm: 0.00

Labor: 73.00

Parts: 87.35

Total: 160.35

4/10/2026
9:41:41 AM

10198918

Palm Beach County Fleet Management Asset Maintenance History
2016 INTERNATIONAL DURASTAR Dump Truck, 5 Yd, 25,500 Gvwr, Steel Body

Work Order: 2400326

Meter: 61183

In Date: 01/10/2024 **Closed:** 12/16/2024

Problem: PM/Air brake leaking, right front slack adjuster rubber seal, tag light, hyd resevoir cap loose leaking

Work Completed

- Preventive Maint. Service
- Road test
- Add Def fluid & change Def filter
- Replace Tag light assy. & rewire pig tail
- Hydraulic resevoir cap
- Pm power steering pump
- Service A/c system, clean evaporator, change cab filter
- Install Batteries & check charging system
- Install Rh front Slack adjuster assy.
- to rechtien 2xs
- rechtien repairs
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	16.00
Used Fire X Refurbished	1.00
Wd40 Spr	1.00
Non-chlor Brake Clnr	4.00
Rotell Elc Antifeerze	1.00
Wiper Blade	2.00
Washer Fluid Concentr	2.00
oil filter	1.00
Napagold Fuel Filter	1.00
Fuel Filter Repace Ff63009	1.00
Air Fltr	1.00
Def Filter	1.00
Blue Df	2.00
Led Tag Light	1.00
Tran Flu Qt Dexron3i	2.00
Power Steering Filter	1.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Group 31 Stud Delco	2.00
Slack Adjuster	1.00
Hub Seal	2.00
New Pig	1.00
Breather	1.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 22.50

Comm: 0.00

Labor: 1,642.50

Parts: 1,056.38

Total: 2,698.88

4/10/2026
9:41:41 AM

10198918

Palm Beach County Fleet Management Asset Maintenance History
2016 INTERNATIONAL DURASTAR Dump Truck, 5 Yd, 25,500 Gvwr, Steel Body

Work Order: 2506664

Meter: 67100

In Date: 07/18/2025 **Closed:** 01/30/2026

Problem: PM Service / check engine / headlight

Work Completed

- Preventive Maint. Service (mobile tech svcs. and repairs)
- add Def- change filter
- trans svc.
- replace air dryer filter ; replace leaking fitting on foot valve.
- replace crankcase filter
- a/c svc.
- check engine light - codes for turbo, Egr, Def
- repair by Rechten
- to Rechten
- replace fogged up headlight assys. ; replace bulb
- On site Alignment - kingpins, drag link and alignment
- test drive / check over / order parts
- replace bad roof marker light
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	16.00
oil filter	1.00
Napagold Fuel Filter	1.00
Fuel Filter Repace Ff63009	1.00
Air Fltr	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
1cart Palladium 2 Grs	2.00
Non-chlor Brake Clnr	2.00
Used Fire X Refurbished	1.00
Def Filter	1.00
Blue Df	1.00
Napa Trans Filter	1.00
Syn-atf Trans Fluid S	20.00
Ad Ip Dryer Cart	1.00
Crankcase Breather Element	1.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Macs Chain Cable Lube	1.00
Head Light Assy	1.00
Head Light Assy	1.00
Clearance Light	1.00
Parts And Service On-site Alignment	1.00
Boxed Capsules	1.00
Parts & Service	1.00
Shop Supplies	1.00

Hours: 10.00

Comm: 1,808.89

Labor: 730.00

Parts: 9,039.34

Total: 11,578.23

4/10/2026
9:41:41 AM

10198918

Palm Beach County Fleet Management Asset Maintenance History
2016 INTERNATIONAL DURASTAR Dump Truck, 5 Yd, 25,500 Gvwr, Steel Body

Work Order: 2602086

Meter: 70076

In Date: 03/04/2026 **Closed:** 03/11/2026

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 0.00

Total: 146.00

Total Hours: 299.00

Total Labor: 20,813.00

Total Comm: 28,305.78

Total Parts: 26,152.23