



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V482**

In Date: 11/04/2005

Close Date: 12/07/2005

Meter Reading:

**Problem?**

set up new unit R47

Task performed:

Parts	Quantity
14-7014HGR-1 HELMET HOOK	1
5025TERMINAL BOX	2

**Workorder: V773**

In Date: 12/01/2005

Close Date: 12/07/2005

Meter Reading:

**Problem?**

WIDOW TINT WILL NOT LET P/SIDE WINDOW GO DOWN, R-47

Task performed:

Parts	Quantity
NO PARTS USED	

**Workorder: V830**

In Date: 12/07/2005

Close Date: 12/12/2005

Meter Reading:

**Problem?**

AIR LEAK, POWER DOOR LOCKS INOP, R-47

Task performed:

Parts	Quantity
NO PARTS USED	



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V857**

In Date: 12/08/2005  
Close Date: 12/19/2005

Meter Reading:

**Problem?**

CAB DOOR AJAR LIGHTS ON, R-47

Parts	Quantity
-------	----------

**Task performed:**

091-3YWCOVER KUSSMAUL AUTO EJECT	1
----------------------------------	---

**Workorder: V912**

In Date: 12/13/2005  
Close Date: 12/21/2005

Meter Reading:

**Problem?**

ENGINE LEAKING OIL, R-47

Parts	Quantity
-------	----------

**Task performed:**

NO PARTS USED	
---------------	--

**Workorder: V1014**

In Date: 12/27/2005  
Close Date: 01/06/2006

Meter Reading:

**Problem?**

CHANGE TIME ON VISTA SCREEN TO DISPATCH TIME, R-47

Parts	Quantity
-------	----------

**Task performed:**

NO PARTS USED	
---------------	--



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V1116**

In Date: 01/04/2006  
Close Date: 01/10/2006

Meter Reading:

**Problem?**

LT, AIR PACK BRACKET NEEDS ADJUSTMENT, WARNING FOR SCENE LIGHT EXTENDED BROKEN, R-47

Parts ----- Quantity -----

Task performed:

NO PARTS USED

**Workorder: V1250**

In Date: 01/23/2006  
Close Date: 01/24/2006

Meter Reading:

**Problem?**

STEERING TILT FOOT LEVER INOP, R-47

Parts ----- Quantity -----

Task performed:

RGT-452258FFOOT PEDAL STERRING COLUMN 1

**Workorder: V1356**

In Date: 01/30/2006  
Close Date: 02/02/2006

Meter Reading:

**Problem?**

BACK-UP ALARM STAYS ON ALL THE TIME R-47

Parts ----- Quantity -----

Task performed:

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V1474**

In Date: 02/10/2006  
Close Date: 02/23/2006

Meter Reading:

**Problem?**

REAR STRECTHER HITTING STEP, R-47

Parts ----- Quantity -----

Task performed:

NO PARTS USED

**Workorder: V1577**

In Date: 02/21/2006  
Close Date: 02/23/2006

Meter Reading:

**Problem?**

FRONT END PULLS TO THE RIGHT, R-47

Parts ----- Quantity -----

Task performed:

NO PARTS USED

**Workorder: V1856**

In Date: 03/15/2006  
Close Date: 03/31/2006

Meter Reading:

**Problem?**

P/SIDE CURB VIEW MIRROR BROKEN, R-47

Parts ----- Quantity -----

Task performed:

2FC00ZCR4 IN ROUND LED	2
4070091740 GROMMET T/L 4 IN	2
PRUMX409MIRROR 28763 GROTE	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V1927**

In Date: 03/22/2006  
Close Date: 04/05/2006

Meter Reading:

**Problem?**

OIL LEAK, R-47

Parts ----- Quantity -----

**Task performed:**

Do for "B" inspection

NO PARTS USED

**Workorder: V1744**

In Date: 03/06/2006  
Close Date: 04/10/2006

Meter Reading:

**Problem?**

CHECK REAR TIRES, R-47

Parts ----- Quantity -----

**Task performed:**

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V1977**

In Date: 03/27/2006  
Close Date: 04/14/2006

Meter Reading:

**Problem?**

B INSPECTION, R-47

**Task performed:**

See B Inspection pre-printed form

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
3541435414 CLAMP 2 1/2"	2
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
A17-14297-000HOOD LIFT CLY A17-14297-002 M2	1
A22-54624-001DOWN VIEW MIRROR M2	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1
VBK-HBRACKET FOR WHEEL AIR EXTENSION	2

**Workorder: V2273**

In Date: 04/18/2006  
Close Date: 04/21/2006

Meter Reading:

**Problem?**

VEHICLE WAS IN ACCIDENT, R-47

**Task performed:**

Parts	Quantity
NO PARTS USED	



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V2257**

In Date: 04/17/2006  
Close Date: 05/02/2006

Meter Reading:

**Problem?**

TOW R-47 FROM STA-42 TO SHOP, (SISTERS TOWING)

Parts

Quantity

Task performed:

NO PARTS USED

Vendor? SISTERS TOWING

**Workorder: V4279**

In Date: 09/06/2006  
Close Date: 09/15/2006

Meter Reading: 11,586.00

**Problem?**

A INSPECTION AND REPAIRS AS NEEDED R47

Parts

Quantity

Task performed:

VCC/36000006A/C FILTER CAB M2

1

**Workorder: V4414**

In Date: 09/12/2006  
Close Date: 09/25/2006

Meter Reading: 770.10

**Problem?**

WINDSHIELD LEAKS WHEN RAINING. LEAK IS AT THE TOP OF THE WINDSHEILD APPROX 20" FROM THE LEFT SIDE R47

Parts

Quantity

Task performed:

1. RESEAL TOP OF DF WINDSHIELD.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V5000**

In Date: 10/21/2006  
Close Date: 10/27/2006

Meter Reading: 9,860.00

**Problem?**

R47 front passenger seat seems to be loose, rocks back and forth. R-47

Parts ----- Quantity -----

**Task performed:**

- 1. TRAVELED TO STN 47. SEAT WILL HAVE TO REPLACED.

NO PARTS USED

**Workorder: V5163**

In Date: 10/30/2006  
Close Date: 11/07/2006

Meter Reading: 1,032.30

**Problem?**

high pitched moan toward the rear when going approx 35 mph, noise increases in volume as speed increases R47

Parts ----- Quantity -----

**Task performed:**

- 1. noise from trans , add oil

NO PARTS USED

**Workorder: V5364**

In Date: 11/12/2006  
Close Date: 11/27/2006

Meter Reading: 11,122.00

**Problem?**

replace windshield wipers and fix the wiper wash system R47

Parts ----- Quantity -----

**Task performed:**

- 1. REPLACE WINDSHIELD WASHER HOSE 2 REPLACE WINDSHIELD WIPER BLADES

52-24WIPER BLADES ANCO 24	2
91-22WIPER BLADE	2





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V5853**

**In Date:** 12/18/2006

**Meter Reading:** 19,872.00

**Close Date:** 01/03/2007

**Problem?**

REPAIR FLAT AT 47 CALLAGHAN ENT

Parts

Quantity

**Task performed:**

1. Flat repair at Sta47 Callaghan Ent

NO PARTS USED

**Vendor?** CALLAGHAN ENT



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

### \* ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V5896**

**In Date:** 12/20/2006

**Meter Reading:** 19,872.00

**Close Date:** 01/03/2007

**Problem?**

**B Inspection and all Needed Repairs**

**Task performed:**

1. B Inspection Installed new wiper blades, installed missing valve stem caps install missing lug nut covers 2. Trans service 3. Air dryer service 4. Torque u-bolts & straighten sway bar. Secure level valves and adjust. Secure air lines 5. Repair door hinges, latches, and tool brackets 6. clean and service batteries 7. Replace rear side strobe 8. Install air horn kits and adjust 9. Pressure test cooling system. Repaired leaks at multiple hose clamps 10. Checked all systems for codes 11. Replaced all hand lights 12 Replaced stretcher lock 13. Replaced cab a/c filter 14. Evacuate, vacume, and charge front a/c system leak check and protect hoses 15. Dianose and test amp gauge 16. Jump start R29 charge batteries disconnected neg. cables

**Parts**

**Quantity**

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
090-0278STRECHER BAR NEW	1
29526898 29548988 TRANS FILTER ALLISON	1
42809AIR FILTER M2	1
5008414CARTRIDGE DC100	1
549076C91549076C91 HORN KIT	1
800404USE K022105 PURGE KIT AD-IP-IS	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
ACX-8453LUG CAPS WHEELED COACH # CH2732	2
RSR03ZCRLIGHT LED RED TIR3 SERIES	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1
VCC/36000006A/C FILTER CAB M2	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V6282**

In Date: 01/15/2007  
Close Date: 01/18/2007

Meter Reading: 615.50

**Problem?**

REPAIR DOOR LATCH TO TOP MEDICAL DRAWER. R-47

**Task performed:**

1. TRAVELED TO STN 47. ADJUSTED MEDICAL DRAWER LATCH. 2. CHECKED REAR 110 A/C FOUND UNIT WORKING.

Parts	Quantity
91398907 VALVE KIT 3 IN AKRON	1
LTC1020606LATCH	6
LTC5992C5-12-15-3 LATCH LEVER NON-LOCKING	2

**Workorder: V7480**

In Date: 04/02/2007  
Close Date: 04/18/2007

Meter Reading: 29,344.00

**Problem?**

REPLACE TIRES AT STA 47 R47 CALLAGHAN ENT

**Task performed:**

Replaced tires at station 47 R47 Callaghan Ent

Parts	Quantity
NO PARTS USED	

Vendor? CALLAGHAN ENT

**Workorder: V7507**

In Date: 04/03/2007  
Close Date: 04/18/2007

Meter Reading: 29,344.00

**Problem?**

flat repair r47 callaghan ent

**Task performed:**

Flat repair R47 Callaghan Ent

Parts	Quantity
NO PARTS USED	

Vendor? CALLAGHAN ENT



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

### \* ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V7754**

In Date: 04/16/2007  
Close Date: 04/18/2007

Meter Reading: 2,988.00

**Problem?**

wipers coming on without turning on switch r47

**Task performed:**

1. wipers coming on with rt turn signal check and found wiper switch bad r&r wiper switch recheck npf

Parts	Quantity
A06-36956-000A06-36956-003 WIPER-TURN SWITCH	1

**Workorder: V7611**

In Date: 04/09/2007  
Close Date: 04/30/2007

Meter Reading: 29,880.00

**Problem?**

B INSPECTION AND REPAIRS AS NEEDED R47

**Task performed:**

B-Inspection 1. Belt squeals-adjust 2. L/F tire leaking valve core-defective stem; rem tire; vendor replc stem; retested tire 3. L/S step loose; rep stripped threads 4. Pat compt door pnls loose; tighten all dr pnls/shlvs; rep pull out cabinet 5. Batt chrgr lite inop;-defective indicator; replc ligte assy 6. (2) cab dr lites inop; rep wiring to lites 7. A/C still not cooling properly; fnd defective evap probe 8. battery tray screws loose; rep btry tray 9. Cab A/C inop; leak @ side; hole @ condensor. replc end of hole

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
032-0116549297 BATTERY INDICATOR	1
22-53754-000VENT INBOARD LH	2
22-54273-000CLIP RETAINER VENT	1
440STEM EXTENSION	2
4407S08-6462BS 45 DEG FITTING 8 SB1312	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	1
VCC/83000036PROBE	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V8227**

In Date: 05/13/2007  
Close Date: 06/01/2007

Meter Reading: 2,138.20

**Problem?**

air horn does not work R-47

Parts ----- Quantity -----

**Task performed:**

1. P/U Hoover at Sta 16 2. Adjusted horn

02036273300 TURBO94 CORNERLINEAR REFLECTC	1
---	---

**Workorder: V8327**

In Date: 05/19/2007  
Close Date: 06/05/2007

Meter Reading: 2,138.20

**Problem?**

officer's seat loose, airhorne not working on the foot pedal, passenger compartment overhead lights (2 out) R47

Parts ----- Quantity -----

**Task performed:**

1. Not repairing seat 2. Traced out problem with air horns, found bad connection on air horn solenoid

NO PARTS USED	
---------------	--

**Workorder: V8723**

In Date: 06/11/2007  
Close Date: 06/19/2007

Meter Reading: 2,318.50

**Problem?**

Front passenger seat is a "rocking chair" . Can we stop it from rocking? Thank you. R-47

Parts ----- Quantity -----

**Task performed:**

1. Will send letter to BC about seat

NO PARTS USED	
---------------	--



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V9315**

In Date: 07/16/2007  
Close Date: 07/17/2007

Meter Reading: 2,508.00

**Problem?**

front a/c not working properly R47 ON CALL

**Task performed:**

No front A/C ; will take too long to repair; crew would be out of service;  
swap out unit; replc broken slider drawer

Parts ----- Quantity -----

VCC/36000006A/C FILTER CAB M2	1
-------------------------------	---

**Workorder: V9322**

In Date: 07/16/2007  
Close Date: 07/17/2007

Meter Reading: 36,536.00

**Problem?**

REPAIR A/C R47

**Task performed:**

1. DIAG & FOUND BROKEN (HOLE) IN A/C COMP. NECESSARY TO R&R AND FLUSH SYSTEM- EVAC & CHARGE SYSTEM. 2. R&R BOTH BELTS. 3. A INSPECTION. 4. LATCH LOOSE, NECESSARY TO LOCAT BRACKET & TIGHTEN AS NECESSARY.

Parts ----- Quantity -----

01-29866-118BELT ALT. M2	1
0128042000PULLY TENSION	1
533303-0609 A/C COMPRESSOR M2 4485	1
9420BELT	1
ABPN83319744USE 7197 DRYER M2	1

**Workorder: V9241**

In Date: 07/10/2007  
Close Date: 07/18/2007

Meter Reading: 2,508.00

**Problem?**

front passenger side bumper came loose and crew removed for safety.  
R-47

**Task performed:**

Reinstalled right side bumper that fell off & rewired siren speakers

Parts ----- Quantity -----

23-12080-150BOLT BUMPER	4
-------------------------	---



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V9199**

In Date: 07/07/2007  
Close Date: 07/19/2007

Meter Reading:

**Problem?**

Air horn not working. R47

Parts

Quantity

NO PARTS USED

**Task performed:**

1. AIR HORN INOP. TRACED OUT PROBLEM- FOUND BAD GROUND- REPAIRED AND TESTED. 2. AUTO EJECT INOP. TRACED OUT PROBLEM. FOUND BAD GROUND ON UNIT. REPAIRED. 3. 110 A/C NOT WORKING. TRACED OUT PROBLEM. FOUND BAD CONNECTION AT ON-OFF SWITCH. REPAIRED.

**Workorder: V9358**

In Date: 07/16/2007  
Close Date: 08/01/2007

Meter Reading: 36,536.00

**Problem?**

replace all 6 tires R47 (outside agency-callaghan tire)

Parts

Quantity

NO PARTS USED

**Task performed:**

Replace all (6) tires - Callaghan

Vendor? CALLAGHAN

**Workorder: V9625**

In Date: 07/30/2007  
Close Date: 08/07/2007

Meter Reading: 38,078.00

**Problem?**

front a/c innop R47

Parts

Quantity

NO PARTS USED

**Task performed:**

void duplicate



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V9715**

In Date: 08/03/2007  
Close Date: 08/07/2007

Meter Reading: 2,646.20

**Problem?**

pt compartment rear bottom window broken completey out by stretcher that was not locking... R47

Parts ----- Quantity -----

**Task performed:**

1. replace rear compartment door glass 2. check out rear a/c no problem found

WIN6488PATIENT WINDOW LOWER SMALL	1
-----------------------------------	---

**Workorder: V9594**

In Date: 07/28/2007  
Close Date: 08/10/2007

Meter Reading: 38,078.00

**Problem?**

REPAIR A/C R47

Parts ----- Quantity -----

**Task performed:**

1. check out front a/c-found leak at high line fitting at condenser, also at pipe crimp at compressor. replaced high pressure line and modify piping, solider new fittings. 2. complete rear brake job removed and ordered all new shoes and haedware

3744BRAKE DRUM REAR	2
4407S08-6462BS 45 DEG FITTING 8 SB1312	1
4909SCUT AND FAB FITTING	1
55021-07SWITCH	1
ACX-84534LUG NUT COVER PK10	2
KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V10145**

In Date: 08/27/2007  
Close Date: 09/11/2007

Meter Reading: 40,337.00

**Problem?**

repair oil leak re47 fla detroit diesel

Parts

Quantity

**Task performed:**

rep oil leak - Florida Detroit Diesel

NO PARTS USED

Vendor? DETROIT DIESEL

**Workorder: V10188**

In Date: 08/31/2007  
Close Date: 09/17/2007

Meter Reading: 40,675.00

**Problem?**

air leak r47

Parts

Quantity

**Task performed:**

Chkd for air leak; fnd air dryer purge valve leaking; cln/tested

NO PARTS USED

**Workorder: V10651**

In Date: 09/25/2007  
Close Date: 10/01/2007

Meter Reading: 42,495.00

**Problem?**

DOOR OPEN LIGHT ON, R-47

Parts

Quantity

**Task performed:**

1. TRACED OUT PROBLEM WITH LIGHT GOING OFF FOUND BAD CONNECTION. 2. READJUSTED STRETCHER MOUNT

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V10775**

In Date: 10/02/2007  
Close Date: 10/02/2007

Meter Reading: 42,495.00

**Problem?**

REPAIR HOOD LATCH R47

Parts ----- Quantity -----

**Task performed:**

1. REPAIRED LATCH ON HOOD THAT WAS FALLING OFF

NO PARTS USED

**Workorder: V9553**

In Date: 07/26/2007  
Close Date: 10/15/2007

Meter Reading: 37,680.00

**Problem?**

FRONT AND REAR AC BROKEN R46

Parts ----- Quantity -----

**Task performed:**

rear and front a/c not workin. no problem with cab a/c found. replace a/c filter

78R536078R5360M 2PK FILTER AIR COND 2

**Workorder: V9567**

In Date: 07/26/2007  
Close Date: 10/15/2007

Meter Reading: 2,590.60

**Problem?**

cab a/c does not cool. r47

Parts ----- Quantity -----

**Task performed:**

charged a/c unit found leak unit will need to go to shop for repair

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

### \* ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V10950**

In Date: 10/11/2007  
Close Date: 10/22/2007

Meter Reading: 43,883.00

**Problem?**

REAR DOME LIGHTS INOP, R-47

**Task performed:**

1. replaced bulb in rear of rescue. 2. traced out problem with cab a/c condenser fans not coming on. found blown fuse and melted wires. repaired where needed.

Parts	Quantity
LB-D30BULB QUARTZ HAL. 12V 150W	5

**Workorder: V11014**

In Date: 10/14/2007  
Close Date: 10/22/2007

Meter Reading: 3,024.90

**Problem?**

Adapter on shore power line for R47 broken

**Task performed:**

1. auto eject inoperable/cord broken. repaired cord and repaired pin on auto eject. 2. air ride seat driver side inoperable. repaired air line to seat.

Parts	Quantity
0915520120AUTO EJECT 20 AERO OTL3925	1
5-20PH1PGK4 CONNECTOR 120V 20A FEMALE	1

**Workorder: V11142**

In Date: 10/20/2007  
Close Date: 10/25/2007

Meter Reading: 2,263.60

**Problem?**

Driver side headlight not working. No replacement bulbs at station. R47

**Task performed:**

1. I head light inoperable. bulb installed (go back to shop for parts).

Parts	Quantity
9006XSLLHEADLAMP M2 HI	2



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V11345**

In Date: 10/31/2007  
Close Date: 10/31/2007

Meter Reading: 45,395.00

**Problem?**

ON CALL BATTERY SWITCH BAD R47

**Task performed:**

Faulty battery switch

Parts ----- Quantity -----

M-284-01SWITCH BATTERY MASTER	1
-------------------------------	---

**Workorder: V11317**

In Date: 10/30/2007  
Close Date: 11/09/2007

Meter Reading: 45,127.00

**Problem?**

stretcher mount 10-7 r47

**Task performed:**

R/R stretcher latch

Parts ----- Quantity -----

090-0278STRECHER BAR NEW	1
--------------------------	---

**Workorder: V11431**

In Date: 11/05/2007  
Close Date: 11/14/2007

Meter Reading: 45,395.00

**Problem?**

REAR COMPARTMENT DOOR INOP, R-47

**Task performed:**

1. Adjusted rear door linkage.

Parts ----- Quantity -----

NO PARTS USED	
---------------	--



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V11691**

In Date: 11/20/2007  
Close Date: 11/28/2007

Meter Reading: 47,171.00

**Problem?**

repair map light r47

**Task performed:**

Installed new maplight j

Parts	Quantity
LF18TS-LEDMAP LIGHT LED 18 IN	1

**Workorder: V11801**

In Date: 11/29/2007  
Close Date: 12/06/2007

Meter Reading: 47,955.00

**Problem?**

R47 LEANS TO LEFT

**Task performed:**

1. Readjusted air bags. 2. Readjusted stretcher mount that was not latching. 3. Checked problem with 110 A/C not coming on, Found bad connection in 110 plug.

Parts	Quantity
NO PARTS USED	

**Workorder: V11826**

In Date: 11/30/2007  
Close Date: 12/06/2007

Meter Reading: 3,311.30

**Problem?**

master button is starting to not work properly. The lights shut off but screen shows there still on. Once off they will not come back on unless you shut th truck down. q47

**Task performed:**

1. Checked problem with master button and found no problem with button

Parts	Quantity
NO PARTS USED	



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V12203**

In Date: 12/22/2007  
Close Date: 01/04/2008

Meter Reading: 3,400.00

**Problem?**

spotlight on roof of r47 broken

Parts ----- Quantity -----

**Task performed:**

1. Found spot light Inop, found bad connection, repaired wires.

NO PARTS USED

**Workorder: V11956**

In Date: 12/07/2007  
Close Date: 01/08/2008

Meter Reading: 48,457.00

**Problem?**

REPLACE ALL 6 TIRES R-47

Parts ----- Quantity -----

**Task performed:**

Replace all (6) tires R47 - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

**Workorder: V12371**

In Date: 01/05/2008  
Close Date: 01/08/2008

Meter Reading: 50,758.00

**Problem?**

rescue is running hot coolant is leaking R-47

Parts ----- Quantity -----

**Task performed:**

Coolant reservoir cracked; sent to shop & replc reservoir j

05-23195-000Z05-30740-000 SURGE TANK 1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V7821**

In Date: 04/19/2007  
Close Date: 01/14/2008

Meter Reading: 2,988.00

**Problem?**

flat repair callaghan ent r47

Parts ----- Quantity -----

**Task performed:**

NO PARTS USED

**Workorder: V8183**

In Date: 05/10/2007  
Close Date: 01/14/2008

Meter Reading: 3,180.00

**Problem?**

DOOR OPEN LIGHT, R-47

Parts ----- Quantity -----

**Task performed:**

NO PARTS USED

**Workorder: V12431**

In Date: 01/08/2008  
Close Date: 01/16/2008

Meter Reading: 50,758.00

**Problem?**

rear a/c warm r47

Parts ----- Quantity -----

**Task performed:**

1. Recharged rear unit.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

### \* ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V12421**

**In Date:** 01/07/2008

**Meter Reading:** 50,758.00

**Close Date:** 01/24/2008

**Problem?**

c inspection and repairs as needed r47

**Task performed:**

1. Tighten all door latches. Coolant system service. Service diff. 2. Tighter U-bolts. R+R A/c fans under truck. R+R all battery. 3. Check A/C system for charger. Ra=R air dryer service. 4. R+R battery. 5. "C" inspection. 6. R+R UV light. R+R marker light. R+R A/C filter. 7. R+R A/C vent rear. R+f P/S filter, service. R+R Air filter.

**Parts**

**Quantity**

0000900087DDE/A0000900087 FILTER HEAD SM MEI	1
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
05-17223-002RAD CAP 20 LB	1
15-22150-06OIL PLUG ADAPTER MBE900	1
15W40BSYN OIL BULK QTS	25
209FILLER	1
42809AIR FILTER M2	1
5008414CARTRIDGE DC100	1
60027FAN A/C COND 12IN 860026-2-W	2
72R320072R3200 VENT A/C 4 1/2"	1
78R536078R5360M 2PK FILTER AIR COND	1
800404USE K022105 PURGE KIT AD-IP-IS	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
CLR9185109186-1500-10 MARKER LT. RED LED	1
HP-31DBATTERY 950CCA HP-31D	4
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1
VCC/36000006A/C FILTER CAB M2	1
VML/T1808D2503221C1 FILTER POWER STEERING	1





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V12908**

In Date: 01/30/2008  
Close Date: 02/05/2008

Meter Reading: 52,842.00

**Problem?**

REPAIR COMP DOOR R47

Parts

Quantity

**Task performed:**

1. Door hard to open, adjusted rear door linkage 2. Air horn inop, traced out problem, found bad ground on fire wall.

NO PARTS USED

**Workorder: V13164**

In Date: 02/11/2008  
Close Date: 02/12/2008

Meter Reading: 54,007.00

**Problem?**

ON CALL R47 WHITE SMOKE POORING OUT EXHAUST

Parts

Quantity

**Task performed:**

1. Towed to shop

NO PARTS USED

**Workorder: V13169**

In Date: 02/11/2008  
Close Date: 02/21/2008

Meter Reading: 54,007.00

**Problem?**

tow uit to shop sisters towing

Parts

Quantity

**Task performed:**

Tow unit to shop - Sister's Towing j

NO PARTS USED

**Vendor?** SISTERS TOWING



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V13521**

In Date: 02/26/2008  
Close Date: 02/27/2008

Meter Reading: 54,007.00

**Problem?**

secondary air system will not build air r47

**Task performed:**

1. Check out air system, test dump switch governor ect, adjust unit 2. A/C not blowing, checkout filter, switches, pressure ect, R & R blower motor, OK 3. "A" inspection 4. R & R striker pin and adjust door

Parts	Quantity
6.5-70-18XSTRAP U-JOINT	1
STP594115449 STRIKER PIN	1
VCC/35000003BLOWER MOTOR VCCT1000904A M2	1
VCC/36000006A/C FILTER CAB M2	1
VCC/83000036PROBE	1

**Workorder: V13526**

In Date: 02/26/2008  
Close Date: 03/03/2008

Meter Reading: 54,007.00

**Problem?**

tow unit from fla detroit to shop r47

**Task performed:**

Tow unit (R47) from Florida Detroit to shop j

Parts	Quantity
NO PARTS USED	

**Vendor?** SISTERS TOWING



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

### \* ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V13572**

In Date: 02/28/2008  
Close Date: 03/13/2008

Meter Reading: 54,007.00

**Problem?**

repair air leak r47

**Task performed:**

1. Air leak, replaced purge valve 2. Rear door inop, readjusted door linkage

Parts	Quantity
5004049GOV CHK VALVE KIT M2	1
800404USE K022105 PURGE KIT AD-IP-IS	1
VML-T1413T3248 SIGHT GLASS	1

**Workorder: V13632**

In Date: 03/03/2008  
Close Date: 03/14/2008

Meter Reading: 54,007.00

**Problem?**

REAR DOOR INOP, R-47

**Task performed:**

1. Rear door not opening, replaced rear door latch and tested

Parts	Quantity
LTC594111656-16 LATCH R/H MEDIC MASTER	1
LTC594211657-16 LATCH L/H MEDIC MASTER	1

**Workorder: V13838**

In Date: 03/12/2008  
Close Date: 03/20/2008

Meter Reading:

**Problem?**

LEAK ON THE MAIN O2 ADAPTOR. THE RESCUE IS WITHOUT A WORKING MAIN O2 TANK. r47

**Task performed:**

1. O2 leak, replaced O2 regulator and tested

Parts	Quantity
NO PARTS USED	



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V14161**

In Date: 03/29/2008  
Close Date: 03/31/2008

Meter Reading: 57,177.00

**Problem?**

Per Tommy, rubber mat on emergency panel needs replacing. r47

**Task performed:**

No emergency light; fnd control pad bad; will order part. j

Parts ----- Quantity -----

0K00-1958-00KEY PAD 7 POSITION	1
--------------------------------	---

**Workorder: V14042**

In Date: 03/23/2008  
Close Date: 04/02/2008

Meter Reading: 3,871.00

**Problem?**

rear officer (right) side turn signal. The signal has moisture under the plastic lens. R47

**Task performed:**

1. Cleaned out moisture in turn signal

Parts ----- Quantity -----

NO PARTS USED	
---------------	--

**Workorder: V14230**

In Date: 04/02/2008  
Close Date: 04/10/2008

Meter Reading: 57,656.00

**Problem?**

REMOVE TRANS FLUID FROM COOLANT R47

**Task performed:**

1. flushed out all trans. fluid from coolant tank and refilled with coolant.

Parts ----- Quantity -----

4537BULB 100W SPOT	2
--------------------	---



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V14519**

In Date: 04/17/2008  
Close Date: 04/22/2008

Meter Reading: 59,143.00

**Problem?**

BACK UP ALARM STAYS ON, R-47

Parts ----- Quantity -----

**Task performed:**

- 1. traced out problem with back up alarm staying on-reprogrammed node and tested.

NO PARTS USED

**Workorder: V14777**

In Date: 04/29/2008  
Close Date: 05/06/2008

Meter Reading: 4,088.30

**Problem?**

Fix toggle switch on search light R47

Parts ----- Quantity -----

**Task performed:**

- 1. REPLACE SWITCH FOR SPOT LIGHT 2. 110 OUTLET FOR 110 A/C WAS SHORTED OUT REPLACE

LGHGO-2020GOLIGHT MODEL 2020 SEARCH LIGHT 1

**Workorder: V15007**

In Date: 05/12/2008  
Close Date: 05/12/2008

Meter Reading: 60,896.00

**Problem?**

ON CALL CHECK ENG LT ON R47

Parts ----- Quantity -----

**Task performed:**

- 1. Clear codes in computer

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V14990**

In Date: 05/10/2008  
Close Date: 05/13/2008

Meter Reading:

**Problem?**

check engine and engine protect light on. R47

Parts

Quantity

**Task performed:**

1. codes in engine will clear codes

NO PARTS USED

**Workorder: V14797**

In Date: 05/01/2008  
Close Date: 05/14/2008

Meter Reading: 60,274.00

**Problem?**

WIPERS TURN ON BY THEMSELVES R-47

Parts

Quantity

**Task performed:**

1. replaced wiper switch and tested

A06-36956-000A06-36956-003 WIPER-TURN SWITCH

1

**Workorder: V15222**

In Date: 05/20/2008  
Close Date: 06/05/2008

Meter Reading:

**Problem?**

L. REAR TIRE BALD r47

Parts

Quantity

**Task performed:**

New tires all (4) rear. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V15276**

In Date: 05/22/2008  
Close Date: 06/11/2008

Meter Reading: 61,866.00

**Problem?**

replace tires at sta 47

Parts ----- Quantity -----

**Task performed:**

Replace tires Stn47 - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

**Workorder: V15395**

In Date: 05/29/2008  
Close Date: 06/12/2008

Meter Reading: 62,607.00

**Problem?**

repair stretcher for rescue 47 at station 42 (outside agency-medco)

Parts ----- Quantity -----

**Task performed:**

Repair stretcherfor R47 at Stn42 - Medco j

NO PARTS USED

Vendor? MEDCO

**Workorder: V15539**

In Date: 06/05/2008  
Close Date: 07/01/2008

Meter Reading: 63,135.50

**Problem?**

COOLANT LEAK R47

Parts ----- Quantity -----

**Task performed:**

1.PRESSURE TESTED COLANT SYSTEM AND FOUND NO LEAKS WII  
MONITOR

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V16053**

**In Date:** 06/30/2008

**Meter Reading:** 89,512.00

**Close Date:** 07/03/2008

**Problem?**

REPAIR COOLANT LEAK

Parts

Quantity

**Task performed:**

1. pressure test system would not hold pressure found over pressure check valve at back of res. tank. replace tank and pressure test. npf

05-23195-000Z05-30740-000 SURGE TANK

1





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V15867**

**In Date:** 06/20/2008

**Meter Reading:** 64,185.00

**Close Date:** 07/14/2008

**Problem?**

b inspection and repairs as needed r47

Parts

Quantity



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

### \* ADVANCED LIFE SUPPORT VEHICLE

#### Task performed:

B-Inspection 2. Both cab A/C inop; chkout sys; fnd bad leak at expansion valve on cab rear unit; diss rear A/C unit & change out expansion valve; replc dryer assemble; reassemble A/C unit; evac/recharge unit; now ok. 3. Chk eng & eng protect lights on, in dash; chk out eng for loss of coolant; pressure test & fnd sys would not hold any pressure; leaking from rear connection on expansion/res. bottle; replc bottle asy; retest; now holds pressure. 4. P/S res leaking fluid; fnd sys overfilled blowing excess out cap; drain down fluid to proper level & wash out all residue of oil. 5. Right rear turn light half filled w/water; rem light assemble & chk lens. Note: lens cracked at two mountings holes; silicone cracks as a temp repairs as part; dept has no lens like this & will take a week or two to get. 6. Rem handlights frm cab center console and reinstall in L-1 compt; mk up wire harness & install to L-1 compt; install glove holders on console where handlights were. 7. Complete brake job - front & rear. 8. Left rear door lock inop; trace wiring to find problem of no power to lock asy; rem severa body/door panels for access to wiring harness; order (2) wiring harnesses; install harnesses, lock asy, door/body pensl. 9. Replc wiperblades. 10. Replc frnt/rear L/S brokn cab door step plates 11. Mod turbo hose clamp brkt to cln hood inner fender well when closing. j

0000900087DDE/A0000900087 FILTER HEAD SM MEI	1
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
05-17223-002RAD CAP 20 LB	1
12-0612AUSE 1600 VALVE EXPANSION RED DOT HC	1
126850021O-RING	1
15W40BSYN OIL BULK QTS	24
18-46375-00018-46375-004 TREAD PLATE LH M2	2
23920-9213UTILITY PUMP	1
3744BRAKE DRUM REAR	2
3753BRAKE DRUM RUMPER FRONT	2
574950006 IN O-RING SEAL	1
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
A06-46513-000WIRE HARNESS DOOR LOCK	1
A06-46514-000WIRE HARNESS DOOR LOCK	1
A18-42549-002A18-60466-002 M2 LEFT DOOR LATCH	1
ABPN83319744USE 7197 DRYER M2	1
ACX-84534LUG NUT COVER PK10	4
FREIGHTSHIPPING CHARGES	2
KSMA2124703QFRONTBRAKE KIT RUMPER AND 4D	2
KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2
LF18TS-LEDMAP LIGHT LED 18 IN	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1
VCC/36000006A/C FILTER CAB M2	1
VCC/83000036PROBE	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V16261**

In Date: 07/10/2008  
Close Date: 07/23/2008

Meter Reading: 7,898.70

**Problem?**

tried using airhorn multiple times but does not work R47

Parts ----- Quantity -----

**Task performed:**

Air horn inop; fnd bad connection. j

NO PARTS USED

**Workorder: V16585**

In Date: 07/25/2008  
Close Date: 07/29/2008

Meter Reading: 65,169.00

**Problem?**

LEFT REAR WINDOW NOT GOING UP, R-47

Parts ----- Quantity -----

**Task performed:**

1. removed door panel and repaired , broken wire.

NO PARTS USED

**Workorder: V16496**

In Date: 07/21/2008  
Close Date: 07/30/2008

Meter Reading: 4,412.10

**Problem?**

m tank regulator has a slow leak r47

Parts ----- Quantity -----

**Task performed:**

1. replaced o2 regulator 2. side door not opening from inside- readjusted door linkage

REG041462369 O2 REGULATOR 2



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V16762**

In Date: 07/31/2008  
Close Date: 08/07/2008

Meter Reading: 4,466.00

**Problem?**

Upon turning on vehicle check engine light came on R-47

**Task performed:**

Coolant leak; low on coolant; refilled; chkd for leaks; no leaks fnd. j

Parts	Quantity
15W40QSYN OIL QT	12
ALA00350-50 EXTENDED LIFE COOLANT GAL	2

**Workorder: V16778**

In Date: 08/01/2008  
Close Date: 08/14/2008

Meter Reading: 4,479.50

**Problem?**

R47 body molding on drivers side fell off of truck. Appears glue holding it in place has failed. Needs to be glued on. Piece will be on LT's desk.

**Task performed:**

Reglued molding. j

Parts	Quantity
NO PARTS USED	

**Workorder: V16912**

In Date: 08/08/2008  
Close Date: 08/14/2008

Meter Reading: 66,289.00

**Problem?**

DOOR MOLDING FALLING OFF, R-47

**Task performed:**

Reinstalled door molding. j

Parts	Quantity
NO PARTS USED	



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V17045**

In Date: 08/14/2008  
Close Date: 08/14/2008

Meter Reading: 66,912.00

**Problem?**

COOLANT LEAK, R-47

Parts

Quantity

**Task performed:**

1. road call out to station 47 to check coolant leak. coolant is leaking from egr system.

NO PARTS USED

**Workorder: V16940**

In Date: 08/10/2008  
Close Date: 08/15/2008

Meter Reading: 4,526.40

**Problem?**

check engine light and engine protectant light keeps coming on and off, when checked coolant was low. And also driver seat will not go all the way down R-47

Parts

Quantity

**Task performed:**

1. Coolant leak; pressure tested & fnd no leaks. 2. Brakes inop; road tested & tested ok. 3. Drivers seat; rep broken air line & tested. j

NO PARTS USED

**Workorder: V17116**

In Date: 08/18/2008  
Close Date: 09/16/2008

Meter Reading: 66,912.00

**Problem?**

REPLACE LEAKING EGR COOLER FLA DETROIT

Parts

Quantity

**Task performed:**

REPLACE BAD EGR COOLER FLORIDA DETROIT DIESEL

NO PARTS USED

Vendor? FLA DETROIT DIESEL



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V17443**

In Date: 09/02/2008  
Close Date: 09/29/2008

Meter Reading: 67,732.90

**Problem?**

REPAIR HEADLIGHT R47

**Task performed:**  
Replaced Headlight

Parts	Quantity
9006XSLLHEADLAMP M2 HI	2

**Workorder: V18075**

In Date: 10/02/2008  
Close Date: 10/07/2008

Meter Reading: 69,906.60

**Problem?**

REPAIR MIKE FOR RADIO, R-47

**Task performed:**  
1- SWAPED OUT RADIO MIKE WITH SPARE.

Parts	Quantity
NO PARTS USED	

**Workorder: V18256**

In Date: 10/10/2008  
Close Date: 10/15/2008

Meter Reading:

**Problem?**

engine oil is low, needs 3-4 quarts. Please bring extra for overstock r47

**Task performed:**  
1-Dropped off case of oil to sation. 2-Rear pt light on one side. found bad connection onl ight.

Parts	Quantity
NO PARTS USED	



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V18909**

In Date: 11/07/2008  
Close Date: 12/01/2008

Meter Reading: 72,397.20

**Problem?**

STRECTHER LATCH INOP, R-47

Parts ----- Quantity -----

**Task performed:**

Readjusted stretcher latch. j

NO PARTS USED

**Workorder: V19168**

In Date: 11/19/2008  
Close Date: 12/02/2008

Meter Reading: 73,496.00

**Problem?**

VEHICLE LEANS TO ONE SIDE, R-47

Parts ----- Quantity -----

**Task performed:**

1. Adj rear air bags & road tested. 2. Rep dri ver's side mirror that was loose. j

NO PARTS USED

**Workorder: V19471**

In Date: 12/03/2008  
Close Date: 12/12/2008

Meter Reading: 74,732.00

**Problem?**

front end shakes r47

Parts ----- Quantity -----

**Task performed:**

Front end shakes; road tested; need front end aignment & (2) tires. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V19891**

In Date: 12/22/2008  
Close Date: 01/02/2009

Meter Reading: 76,227.00

**Problem?**

ON CALL CHECK ENG LT ON R47

Parts ----- Quantity -----

**Task performed:**

Road call to Stn47; Eng light on; fnd low coolant sensor code; topped off reservoir; press test; ck ok; ran/ck opn; ck ok; returned home. j

NO PARTS USED

**Workorder: V18968**

In Date: 11/10/2008  
Close Date: 01/05/2009

Meter Reading: 4,936.50

**Problem?**

Need to get SCBA hold installed in driver compartment #2 R-47

Parts ----- Quantity -----

**Task performed:**

Not installing per Batt Chief. j

NO PARTS USED

**Workorder: V19584**

In Date: 12/07/2008  
Close Date: 01/05/2009

Meter Reading:

**Problem?**

Steering column adjust pedal broken. Steering column unstable when braking. R-47

Parts ----- Quantity -----

**Task performed:**

Installed new tilt wheel pedal. j

RGT-452258FFOOT PEDAL STERRING COLUMN	1
RGT401737ESPRING PEDAL RETURN	1
RGT401741CRETURN SPRING	1





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V19744**

In Date: 12/15/2008  
Close Date: 01/05/2009

Meter Reading: 75,642.00

**Problem?**

PAT. A/C INOP, R-47

Parts ----- Quantity -----

**Task performed:**

Recharged A/C & chkd for leak. j

NO PARTS USED

**Workorder: V19876**

In Date: 12/20/2008  
Close Date: 01/05/2009

Meter Reading: 76,227.00

**Problem?**

Rear door window (oval) bottom, right side broken. R-47

Parts ----- Quantity -----

**Task performed:**

Replcd rear window that was broken. j

NO PARTS USED

**Workorder: V19877**

In Date: 12/20/2008  
Close Date: 01/05/2009

Meter Reading: 5,115.00

**Problem?**

stretcher holder sticking open. R-47

Parts ----- Quantity -----

**Task performed:**

Replcd stretcher latch. j

090-0278STRECHER BAR NEW	1
RSR03ZCRLIGHT LED RED TIR3 SERIES	4



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V20558**

**In Date:** 01/24/2009

**Meter Reading:**

**Close Date:** 02/13/2009

**Problem?**

side pt compartment door handle. Handle gets stuck upon opening. Door opens however handle is weakened. r47

Parts

Quantity

**Task performed:**

Replcd door handle that was broken. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V20005**

**In Date:** 12/29/2008

**Meter Reading:** 76,458.00

**Close Date:** 02/17/2009

**Problem?**

C INSPECTION AND REPAIRS AS NEEDED R47

Parts

Quantity



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

### \* ADVANCED LIFE SUPPORT VEHICLE

#### Task performed:

1. Physical therapy.
2. C-Inspection
3. R/R/ air dryer & purge valve.
4. Physical therapy.
5. Rep grd for L/R door warning light.
6. Tighten all door latches.
7. Rep L-2 compt bracket.
8. Suck down & refill cab A/C.
9. Rem water pump.
10. Start install new water pump.
11. Install new water pump & tensioner.
12. Physical therapy.
13. R/R fuel pump
14. Cln bay.
15. R/R EGR cooler on engine.
16. Chk out for leaks & get up to temp; chl for leaks - pressure chk - ok; ready for svc. j

0000900087DDE/A0000900087 FILTER HEAD SM MEI	1
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
15W40BSYN OIL BULK QTS	48
5008414CARTRIDGE DC100	1
800404USE K022105 PURGE KIT AD-IP-IS	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
9060910580FUEL PUMP GASKET M2	1
9060920510FUEL CHECK VALVE	1
9062010080GASKET M2 WATER PUMP	1
9062030015PIPE SOCKET TO WP	1
9420BELT	1
AEVDOOR LOCK BEZEL	2
AS75807OXM1757-01 OXYGEN WRENCH	1
DDE-0052035975A0052032675 THERMOSTAT ELEMI	2
DDE-0076030102007603016102 WASHER OIL SEND	1
DDE-9062030180GASKET SOCKET TO HEAD M2	1
DDE-R0040910501FUEL PUMP M2	1
DDE-R90620043019062006301 WATER PUMP SOME	1
DDE/0209971148A0249972848 SEAL RING	2
DDE/A02799760480-RINGS M2 WATER PUMP	2
DDE/A9062003170BELT TENSIONOR MERCEDES	1
DDE/R9062006201RA906200620 WATER PUMP REM	1
L1261F33585XE FUEL FILTER WIX	1
N917003022003GASKET/SEAL M2 WATER PUMP	1
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
S448GAUGE TIRE TREAD DEPTH	1
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V21002**

In Date: 02/10/2009  
Close Date: 02/23/2009

Meter Reading: 78,372.60

**Problem?**

repair comp door r47

Parts ----- Quantity -----

**Task performed:**

Door stuck closed; freed up door & adj linkage. j

NO PARTS USED

**Workorder: V20927**

In Date: 02/06/2009  
Close Date: 02/28/2009

Meter Reading: 78,058.40

**Problem?**

flat tire R47 (outside agency-callaghan tire)

Parts ----- Quantity -----

**Task performed:**

Flat tire R47 - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

**Workorder: V21220**

In Date: 02/20/2009  
Close Date: 03/05/2009

Meter Reading: 78,989.00

**Problem?**

TURN SIGNALS INOP, R-47

Parts ----- Quantity -----

**Task performed:**

Rear turn signals not working; fnd bad connection in frame rail. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V20191**

In Date: 01/07/2009  
Close Date: 03/06/2009

Meter Reading: 76,458.00

**Problem?**

replace tires at shop r47

Parts ----- Quantity -----

**Task performed:**

Replace tires at shop R47 - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

**Workorder: V20320**

In Date: 01/13/2009  
Close Date: 03/10/2009

Meter Reading: 76,458.00

**Problem?**

REPLACE EGR COOLER, R-47

Parts ----- Quantity -----

**Task performed:**

A90614206791EA9061421179 EGR COOLER 1

**Workorder: V22031**

In Date: 03/23/2009  
Close Date: 03/25/2009

Meter Reading: 82,275.60

**Problem?**

REPLACE LOW COOLANT SENSOR, R-47

Parts ----- Quantity -----

**Task performed:**

Engine light on; hooked up computer; fnd low coolant sensor bad; replcd sensor; filled reservoir; ran/ck opn; ck ok. j

23520380SENSOR COOLANT 1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V21997**

In Date: 03/23/2009  
Close Date: 04/03/2009

Meter Reading: 82,275.60

**Problem?**

REPAIR PAITIENT LTS R47

Parts

Quantity

NO PARTS USED

**Task performed:**

1. Pat light out on right side; rep bad connection in wiring. 2. Wipers inop; traced out;fnd blow fuse; replcd/tested. 3. Bench seat coming off; rem bench seat & rep hinge & reinstalled.

**Workorder: V21891**

In Date: 03/17/2009  
Close Date: 04/06/2009

Meter Reading: 5,485.90

**Problem?**

broken rear right lower corner light r47

Parts

Quantity

RSR03ZCRLIGHT LED RED TIR3 SERIES

2

**Task performed:**

1. Replcd brkn LED light. 2. Air leak; traced out air leaks; fnd & rep. 3. Right frnt air ride seat inop; rep air line. j

**Workorder: V21892**

In Date: 03/17/2009  
Close Date: 04/06/2009

Meter Reading: 5,485.90

**Problem?**

broken rear right lower corner side light r47

Parts

Quantity

NO PARTS USED

**Task performed:**

1. 110 A/C inop; fnd no 110 power from station; reset breaker. 2. Marker lights not working; traced out problem; fnd bad connection. j



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V22221**

In Date: 03/31/2009  
Close Date: 04/13/2009

Meter Reading: 83,021.60

**Problem?**

front a/c not working properly. r47

Parts

Quantity

**Task performed:**

A/C inop; cldn A/C compressor coils & tested. j

NO PARTS USED

**Workorder: V22481**

In Date: 04/12/2009  
Close Date: 05/01/2009

Meter Reading: 83,971.00

**Problem?**

A/C INOP, R-47

Parts

Quantity

**Task performed:**

A/C inop; cldn A/C condensor fans & tested sys. j

NO PARTS USED

**Workorder: V22744**

In Date: 04/23/2009  
Close Date: 05/01/2009

Meter Reading: 84,646.90

**Problem?**

replace wiper blades r47

Parts

Quantity

**Task performed:**

A/c inop; replcd diode for A/C end; tested. j

DUFDT04-4P-RT03EL35674 DIODE PACK GRAY

1





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V22810**

In Date: 04/27/2009  
Close Date: 05/04/2009

Meter Reading: 5,703.60

**Problem?**

R47 blew radiator hose. Mech attempted to fix. needs to be towed to st 42

**Task performed:**

Coolant leak - blown hoses; tried to rep; swapped out. j 2. Travel to Strn; replcd brkn plastic tee; brought back to shop to finish repairs & svc. 3. Repld coolant hose to reservoir & EGR coolant hoses swollen; replcd hoses. j

Parts	Quantity
05-23281-001COOLANT HOSE ECR	1
ALA00350-50 EXTENDED LIFE COOLANT GAL	4
EXO3AH00015SPLUG RAD. DRAIN	1
FREIGHTSHIPPING CHARGES	1

**Workorder: V22806**

In Date: 04/27/2009  
Close Date: 05/13/2009

Meter Reading: 85,137.30

**Problem?**

REPLACE RADAITOR HOSE, R-47

**Task performed:**

Parts	Quantity
DDE/A0039973352EGR COOLING HOSE	2



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V22816**

**In Date:** 04/27/2009  
**Close Date:** 05/13/2009

**Meter Reading:** 85,137.30

**Problem?**

BINSPECTION R47

**Task performed:**

B-Inspection completed 2. Cab A/C intermittent problem; loose connector @ evap temp probe; rep connector. 3. Tires pulls to the right; rotated frnt tires & road tested ok. 4. rear doos loose-msng stripped panel/latch screws; svc rear doors. 5. SCBA brkts loose; msng loose screws; tightened SCBA brkts. 6. Exh stack bent & loose; straightened stck. 7.P/S leak; fitting loose; clnd/tightened fitting. j

Parts	Quantity
0000900087DDE/A0000900087 FILTER HEAD SM MEI	1
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
15W40BSYN OIL BULK QTS	24
3157TAIL LIGHT BULBS	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	1

**Workorder: V23259**

**In Date:** 05/13/2009  
**Close Date:** 05/21/2009

**Meter Reading:** 85,857.40

**Problem?**

replace broken wiper arm r47

**Task performed:**

1. R/S wiper arm brkn; replcd wiper arm. 2. Pat compt dome light inop; installed new bulb. j

Parts	Quantity
91-22WIPER BLADE	1
A2252082003WIPER ARM RIGHTSIDE M2	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V23482**

In Date: 05/22/2009  
Close Date: 06/02/2009

Meter Reading: 5,780.00

**Problem?**

right rear door window gasket is falling out. R-47

Parts ----- Quantity -----

**Task performed:**

Rep rear window that was falling out. j

NO PARTS USED

**Workorder: V23527**

In Date: 05/26/2009  
Close Date: 06/02/2009

Meter Reading: 89,910.60

**Problem?**

power window 10-7 r47

Parts ----- Quantity -----

**Task performed:**

Traced out problem w/power windows; fnd brkn wire in door. j

NO PARTS USED

**Workorder: V23738**

In Date: 06/02/2009  
Close Date: 06/19/2009

Meter Reading:

**Problem?**

Rear officer side door lower oval window leaking. R47

Parts ----- Quantity -----

**Task performed:**

Resealed rear window that was leaking. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V23771**

In Date: 06/03/2009  
Close Date: 06/19/2009

Meter Reading: 87,381.80

**Problem?**

BATTERY CHARGER 10-7 R47

Parts

Quantity

**Task performed:**

110 charge inop; rep 110 outlet plug for shore power & retested. j

NO PARTS USED

**Workorder: V23889**

In Date: 06/08/2009  
Close Date: 06/24/2009

Meter Reading: 87,590.80

**Problem?**

ON CALL R47 A/C 10-7

Parts

Quantity

**Task performed:**

A/C ok. j

NO PARTS USED

**Workorder: V24174**

In Date: 06/18/2009  
Close Date: 07/06/2009

Meter Reading: 88,527.70

**Problem?**

repair air bags r47

Parts

Quantity

**Task performed:**

Readj rear air bags & road tested. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V24298**

In Date: 06/24/2009  
Close Date: 07/08/2009

Meter Reading: 89,079.00

**Problem?**

water leak in cab r47

Parts ----- Quantity -----

**Task performed:**

1. water in cab; resealed top of roof. 2., Stretcher latch inop; rep & adj latch. j

NO PARTS USED

**Workorder: V25136**

In Date: 07/29/2009  
Close Date: 08/05/2009

Meter Reading: 91,667.10

**Problem?**

SIDE DOOR NOT OPENING, R-47

Parts ----- Quantity -----

**Task performed:**

1. Side door inop; readj door linkage. 2. Wipers inop; rep wiper switch. j

NO PARTS USED

**Workorder: V25245**

In Date: 08/03/2009  
Close Date: 08/17/2009

Meter Reading: 92,376.00

**Problem?**

R-47 rear window falling out

Parts ----- Quantity -----

**Task performed:**

1. Rear window falling out rep window. 2. Rear A/C recharged. 3. Turn signals inop; rep bad connection. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V25373**

In Date: 08/06/2009  
Close Date: 08/17/2009

Meter Reading: 6,174.30

**Problem?**

Front a/c not working in R47

Parts ----- Quantity -----

**Task performed:**

A/C inop; recharged A/C & chkd for leaks. j

NO PARTS USED

**Workorder: V25642**

In Date: 08/19/2009  
Close Date: 08/19/2009

Meter Reading: 92,678.70

**Problem?**

repair check out lights r47

Parts ----- Quantity -----

**Task performed:**

Traced light problem to brkn wire in door jam; rep brkn wire; also replcd button/switch on rear entry door; (rusted/corroded). j

25-358SWITCH COVER	1
923182-2151 SWITCH MOMENTARY 24-372	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V25204**

In Date: 07/31/2009

Meter Reading: 92,376.00

Close Date: 08/20/2009

**Problem?**

C INSPECTION + REPAIRS R 47

Parts

Quantity



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

### \* ADVANCED LIFE SUPPORT VEHICLE

#### Task performed:

Perform "C" Svc. 2. Replcd all (4) btrys; replc pos/neg btry jumper cables. 3. Replcd eng air filter. 4. Svc air dryer. 5. Svc trans. 6. Replcd grnd light on pass side of cab; R/R brkt to straighten; redrill/tap new mntng holes. 7. Replcd rear axle air bags. 8. Replcd rear axle brake shoes. 9. Replcd fan belts (R/R fan). 10. Replcd quick disconnect fitting in fan air line w/compression type fitting. 11. Replcd wiper blades. 12. Clned debris frm window washer squirters & topped reservoir. 13. Replcd frnt cab A/C filter. 14. Replcd rear cab A/C filter. 15. Replcd pat compt A/C filter. 16. Replcd flag stickers (faded). 17. Replcd (3) pat compt door light bulbs. 18. Adj left rear pat compt entry door strikers so door wld close tightly. (loose/rattling) 19. Painted fuel cap. 20. Replcd pass step non skid (worn off). 21. Tightened/lubed/adj all door latches, hold opens & hinges. 22. Rep squad bench latch (bent). 23. T-shoot L/R cab door alarm inop; traced problem to faulty door latch/switch asy; replcd latch asy inside of door & tested sys. 24. Replcd air pack release cable on right frnt seat; fabbed new mntng for cable & rerouted cable; adj w/air pack asy. 25. Reinstalled rear wheels after tire guy was here; replcd msng lugnut cvrs; air up ties & took truck off jack stands. 26. Replcd air pack release cable on right rear seat; relocated cable mnt & shortened release brkt; adj w/air pack asy. 27. Replcd air pack release cable on left rear seat; relocated cable mnt & shorted release brkt; adj w/asy. 28. Installed "out of svc" stickers. 29. R/R steering wheel to straighten.

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
0127110042BELT MERCEDES MOTORS	1
1045-255-101SEAT CONTROL CABLE LEFT 61 IN	2
1045-257-101SEAT CONTROL CABLE RIGHT 51 IN	1
1500900017000USE 9 X 14 FILTER	1
15W40BSYN OIL BULK QTS	24
16-15762-00016-19471-000 AIR BAG	2
29526898 29548988 TRANS FILTER ALLISON	1
322502BULB PATIENT GH22	3
42809AIR FILTER M2	1
5008414CARTRIDGE DC100	1
607141-05USE 61H01 COPMPARTMENT LIGHT	1
680-10LAMERICAN FLAG W UV CLEAR LEFT	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
9420BELT	1
A0631087000CABLE BATT. POS.	1
A0631088000CABLE BATT. NEG.	1
A18-42549-006LATCH LR M2	1
ACX-84534LUG NUT COVER PK10	10
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
HP-31DBATTERY 950CCA HP-31D	4
K022105PURGE VALVE AD-IP-IS	1
KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
S777COUPLING NIPPLE	1
VCC/36000006A/C FILTER CAB M2	1





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V25577**

In Date: 08/17/2009      Meter Reading: 92,678.70

Close Date: 08/26/2009

**Problem?**

replace tires at shop r47 elpex

Parts	Quantity
NO PARTS USED	

**Task performed:**

Replace tires at shop R47 - Tiresoles j

Vendor? TIRESOLES

**Workorder: V26227**

In Date: 09/14/2009      Meter Reading: 95,005.80

Close Date: 10/21/2009

**Problem?**

ON CALL R47 A/C 10-7

Parts	Quantity
VCC/35000003BLOWER MOTOR VCCT1000904A M2	1
VCC/83000038AC WIRE HARNESS	1

**Task performed:**

1. A/C inop; recharged A/C & clnd condensor fans. 2. Wipers inop; fnd blown fuse. j

**Workorder: V26924**

In Date: 10/16/2009      Meter Reading: 97,554.80

Close Date: 10/22/2009

**Problem?**

ON CALL R47 ALT 10-7

Parts	Quantity
NO PARTS USED	

**Task performed:**

1. Alt not charging btry; swapout unit. 2. Travel to shop; had to do A-Insp on unit to be swapped into. j



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V26926**

**In Date:** 10/16/2009

**Meter Reading:** 97,554.80

**Close Date:** 10/26/2009

**Problem?**

B inspection and repairs as needed / Charging system 10-7 R47

Parts

Quantity



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

### \* ADVANCED LIFE SUPPORT VEHICLE

#### Task performed:

1. Look for keys to veh (John Vasko had them).
2. B-Inspection
3. Rem alt & pulley; install on new alt.
4. Replc belt tensioner.
5. Install alt, rem fan to replc A/C belt; replc A/C hose shields; repl alt belt.
6. Replc frnt shocks.
7. Rem both frnt brake chamber hoses; replc both frt brake chamber hoses.
8. Replc wiper blades.
9. Replc squad bench shocks; replc middle pat compt shocks.
10. Rep windhld washer; unplugg lines.
11. T-shoot & rep btry charger status lights.
12. Rep pat compt door trim.
13. Replc hi/lo bullt in middle dome pat compt.
14. Replc plexiglass on pat door; drill new holes; install new latch.
15. Rep O2 door in pat compt.
16. R/R A/C vent ir cab.
17. Rem glass trim on L/side entry door; cln glass of dirt & install w/sealer.
18. Replc bellow btwn cab/pat box.
19. R/R rear shocks.
20. Rep O2 wrench holder.
21. j

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
032-0116549297 BATTERY INDICATOR	1
12-21022-023M2 FRONT BRAKE LINES	2
15W40BSYN OIL BULK QTS	26
161657700065489 SHOCK REAR NEW RESCUE	2
288214END CAP EONE	3
3040130401 GROMMET KIT	1
322502BULB PATIENT GH22	1
516TIRE INFLATOR	1
65140FRONT SHOCK NEW M2	2
72R311018-2640 VENT A/C NEW # 1719	1
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
921LIGHT BULB	1
DDE/9062002470BELT TENSIONER MERCEDES	1
DOOR5LEXAN 9 X 38 1/2 IN	1
GASK-BEL0110002439 WINDOW BELLOWS 6 IN WID	8
GSS1717UL1717UL0270N 343/09 GAS SHOCK 60 LB	4
HA24027HINGE EA	1
K022105PURGE VALVE AD-IP-IS	1
LTC5992C5-12-15-3 LATCH LEVER NON-LOCKING	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
S777COUPLING NIPPLE	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V26355**

In Date: 09/21/2009  
Close Date: 11/06/2009

Meter Reading: 95,815.80

**Problem?**

DOOR WONT CLOSE R47

Parts ----- Quantity -----

**Task performed:**

1. Read rear door linkage. 2. Roof leak; resealed top roof. j

NO PARTS USED

**Workorder: V24887**

In Date: 07/20/2009  
Close Date: 12/03/2009

Meter Reading: 91,272.60

**Problem?**

REPAIR A/C R47

Parts ----- Quantity -----

**Task performed:**

see 25204

NO PARTS USED

**Workorder: V27383**

In Date: 11/03/2009  
Close Date: 12/09/2009

Meter Reading: 98,677.70

**Problem?**

STRETCHER LATCH 10-7 R47

Parts ----- Quantity -----

**Task performed:**

Adj stretcher latch. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V27894**

In Date: 11/24/2009  
Close Date: 01/13/2010

Meter Reading: 100,146.30

**Problem?**

turn signals 10-7 r47

Parts ----- Quantity -----

**Task performed:**

1. T-signals inop; rep contacts on t-signal switch. 2. Rear door hard to open; readj door linkage. j

NO PARTS USED

**Workorder: V28435**

In Date: 12/17/2009  
Close Date: 01/15/2010

Meter Reading: 101,904.80

**Problem?**

WINDSHIELD WIPER 10-7 R47

Parts ----- Quantity -----

**Task performed:**

Rep back connection in wiper switch. j

NO PARTS USED

**Workorder: V28992**

In Date: 01/11/2010  
Close Date: 02/10/2010

Meter Reading: 101,904.80

**Problem?**

siren 10-7 r47 on call

Parts ----- Quantity -----

**Task performed:**

Replcd siren module head. j

WS-295HFSM1USE 295SLSA1 SIREN 1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V28888**

In Date: 01/07/2010  
Close Date: 02/22/2010

Meter Reading: 101,904.80

**Problem?**

heater 10-7 r47

Parts

Quantity

**Task performed:**

1. Opened heater valves and tested. 2. Air leak; fnd no air leaks at this time. j

NO PARTS USED

**Workorder: V29634**

In Date: 02/02/2010  
Close Date: 03/02/2010

Meter Reading: 105,434.50

**Problem?**

replace rear tires at 42 boulevard tire r47

Parts

Quantity

**Task performed:**

Replace rear tires at 42 - Boulevard Tire j

NO PARTS USED

Vendor? BOULEVARD TIRE



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

### \* ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V29488**

**In Date:** 01/27/2010

**Meter Reading:** 104,327.00

**Close Date:** 03/05/2010

**Problem?**

c inspection and repairs as needed r47

**Task performed:**

C-Inspection 2. Replc all A/C filters (cab/pat compt). 3. Svc P/steering. 4. Program/replc driver side door grd light. 5. Rem steering column shaft; rem u-joints; work w/Art on part (u-joint). 6. Reseal bellow betwn cab/pat compt. 7. Vista screen shows fault N-3; chk; fnd node #3 pin C shorted; traced/fnd (1) A/C condensor fan shorted; replcd both A/C fans for pat compt A/C. 8. Defrosters not working; chk; chk doors; fnd defroster door jammed; rep; defrosters work ok. 9. Replc lug nut cvrs. 10. Chk for air leak; bleeds down overnight; fnd air fitting on foot valve leaking; replc fitting; rechk; fnd air horn solenoid leaking; replc solenoid; rechk air sys - ok. 11. Replc steering u-joint; road test veh; rem steering wheel & center; take for another road test; ok. j

**Parts**

**Quantity**

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
010263488-5010263488-5W CLEARANCE LIGHT LEC	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	28
2FC00ZCR4 IN ROUND LED	1
42809AIR FILTER M2	1
60027FAN A/C COND 12IN 860026-2-W	2
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
ACX-84534LUG NUT COVER PK10	10
CD2004DRAIN HOSE	1
EL360081760611 SOLENOID AIR HORN	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
SK000282STEERING U JOINT	1
TFLANGECMOUNT FOR 2 IN LED	1
VCC/36000006A/C FILTER CAB M2	1
VML/T1808D2503221C1 FILTER POWER STEERING	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V29805**

In Date: 02/08/2010  
Close Date: 03/19/2010

Meter Reading: 105,561.30

**Problem?**

repair flat r47

Parts

Quantity

**Task performed:**

Repair flat R47 - Boulevard j

NO PARTS USED

Vendor? BOULEVARD

**Workorder: V29869**

In Date: 02/10/2010  
Close Date: 03/19/2010

Meter Reading: 105,561.30

**Problem?**

compartment # 2, the drivers compartment, is not opening. the 2nd opening door is jammed. r47

Parts

Quantity

**Task performed:**

Rep L-2 compt door that wld not open. j

NO PARTS USED

**Workorder: V30151**

In Date: 02/22/2010  
Close Date: 03/26/2010

Meter Reading: 106,666.00

**Problem?**

the rear bumper on R47 will not stay in the up position while taking the stretcher out. This has causes complications extracting patients from the rear of the rescue R47

Parts

Quantity

**Task performed:**

1. Rep rear step on rescue. 2. Rep rear door latch that was hard to open door. j

NO PARTS USED





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V30928**

In Date: 03/22/2010      Meter Reading: 109,089.60  
Close Date: 04/06/2010

**Problem?**

stretcher broken R47 (on-call)

Parts ----- Quantity -----

**Task performed:**

Dispatch called; R47 stretcher brkn; call rescue crew; locate batt spare stretcher & coordinate swapout; w/EMS captain. j

NO PARTS USED

**Workorder: V31103**

In Date: 03/29/2010      Meter Reading: 109,089.60  
Close Date: 04/20/2010

**Problem?**

r47 not running. at20 called out R47

Parts ----- Quantity -----

**Task performed:**

1. Fnd auto-eject plug not kicking out; stalling truck; need aut-eject. 2. R/R auto-eject & replc spring kit; work ok at this time. j

091-55-048AUTO EJECT SPRING KIT	1
0915520120AUTO EJECT 20 AERO OTL3925	1

**Workorder: V30962**

In Date: 03/23/2010      Meter Reading: 109,089.60  
Close Date: 04/22/2010

**Problem?**

repair stretcher R47 at sta. 42 (outside agency-medco eqipt. repair)

Parts ----- Quantity -----

**Task performed:**

Repair stretcher R47 - Medco Eqmpt j

NO PARTS USED

**Vendor?** MEDCO EQMPT



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V31132**

In Date: 03/30/2010  
Close Date: 05/01/2010

Meter Reading: 109,089.60

**Problem?**

CAB BOOT FALLING OFF R47

Parts

Quantity

**Task performed:**

Rep cab boot that was falling off. j

NO PARTS USED

**Workorder: V31450**

In Date: 04/12/2010  
Close Date: 05/01/2010

Meter Reading: 110,658.60

**Problem?**

rubber lining in between box and cab is sagging R47

Parts

Quantity

**Task performed:**

Rep rubber boot for lab. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

### \* ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V31995**

**In Date:** 05/04/2010  
**Close Date:** 05/24/2010

**Meter Reading:** 112,341.00

**Problem?**

B inispection

**Task performed:**

B-Inspection 2. Dia R/window squirter inop; fnd washer tube kinked; repos tube & rem nozzle & clnd. 3. Start B-Inspection; btrys dead; try to jump-NG; bring out btry charger & hookup. 4. Jump start veh; charge btrys, test, cln cables. 5. Rear brakes. 6. Replcd L/rear grease seal. 7. Replcd L/side roof clearance lite. 8. Chk toe angle alignment - ok. 9. Defroster mode inop; dia problem; fnd bad control unit; R/R dash & replcd unit. 10. Replcd steering column tilt wishbone & springs. 11. Erase trans code; reprogram laptop for nex Q. 12. Rehung headset hanger. j

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
14-7014HGR-1 HELMET HOOK	2
15W40BSYN OIL BULK QTS	24
3744BRAKE DRUM REAR	2
380003ASEAL	1
401581GASKET AXLE FL80 R002435	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
A22-57054-003A/C SWITCH	1
A9061840408SPINNER OIL FILTER COVER M2	1
ACX-84534LUG NUT COVER PK10	1
CLR9185209186-1500-20 MARKER LT.AMBER LED	2
KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2
RGT-452258FFOOT PEDAL STERRING COLUMN	1
RGT401741CRETURN SPRING	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V32256**

In Date: 05/18/2010  
Close Date: 06/28/2010

Meter Reading: 112,341.00

**Problem?**

REPLACE CAB BOOT R47

Parts ----- Quantity -----

**Task performed:**

Replcd cab boot in rear of rescue. j

GASK-BEL0110002439 WINDOW BELLOWS 6 IN WID	6
--	---

**Workorder: V32575**

In Date: 06/01/2010  
Close Date: 06/30/2010

Meter Reading: 112,938.00

**Problem?**

replace tires boulevard tire r47

Parts ----- Quantity -----

**Task performed:**

Replc tires R47 - Boulevard j

NO PARTS USED	
---------------	--

Vendor? BOULEVARD TIRE

**Workorder: V29529**

In Date: 01/29/2010  
Close Date: 07/08/2010

Meter Reading: 6,954.00

**Problem?**

R47 im told is in the shop for PM. The rear tires may need to be changed due to tread wear

Parts ----- Quantity -----

**Task performed:**

NO PARTS USED	
---------------	--



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V33012**

In Date: 06/20/2010  
Close Date: 07/14/2010

Meter Reading: 115,190.10

**Problem?**

drivers side headlight out R47

**Task performed:**

R/R L/frnt headlight at Stn47. j

Parts	Quantity
9006XSLLEHEADLAMP M2 HI	1

**Workorder: V33262**

In Date: 07/01/2010  
Close Date: 07/29/2010

Meter Reading: 117,292.20

**Problem?**

A-TECH NOTIFIED VIA LANLINE: R47 DAMAGE TO OFFICER'S SIDE SCBA COMPARTMENT DOORS(UNABLE TO OPEN FOR SPARE BOTTLES) INCLUDING BOTTOM METAL FLASHING AT SIDE DOOR ENTRANCE. FOO TRACKING # A-10-055 r47

**Task performed:**

SCBA doors will have to be cut off & replcd at shop. ja

Parts	Quantity
NO PARTS USED	

**Workorder: V33487**

In Date: 07/12/2010  
Close Date: 08/02/2010

Meter Reading: 116,585.60

**Problem?**

ST47-Shoreline does not auto-eject from the Res once it is started. Need repair.

**Task performed:**

Go to Stn47; R47; rem auto-eject frm truck replc spring kit in unit; working ok at this time; reinstall aut-eject back in truck. ja

Parts	Quantity
NO PARTS USED	



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V33791**

In Date: 07/26/2010  
Close Date: 08/02/2010

Meter Reading: 117,702.90

**Problem?**

ON CALL CHECK ENG LT ON R47

**Task performed:**

Chk eng warn lights on; coolant leak - defective drain plug; replcd plug. ja

Parts	Quantity
EXO3AH00015SPLUG RAD. DRAIN	2

**Workorder: V34784**

In Date: 09/07/2010  
Close Date: 09/28/2010

Meter Reading: 11,782.90

**Problem?**

a/c inop R47

**Task performed:**

Cab A/C blower faulty; part not on svc truck; went to shop; fnd part; came back to stn; R47 out on call; waited for them; R/R blower worn. j

Parts	Quantity
VCC/35000003BLOWER MOTOR VCCT1000904A M2	1

**Workorder: V35256**

In Date: 09/28/2010  
Close Date: 10/08/2010

Meter Reading: 11,782.90

**Problem?**

repair charging system r47

**Task performed:**

1. travel to station 42; check charging system, found shorline charging, load test batterys checked ok, checked alternator, found alternaor not charging, sent truck to shop for alternator. 2. replace alternator; check ok. jab

Parts	Quantity
A0014949PA4949PA/4962 320 AMP UPGRADE SADI	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V33771**

In Date: 07/24/2010  
Close Date: 10/19/2010

Meter Reading: 117,702.90

**Problem?**

rescue engine oil low, check engine light and engine protect light on, a tech was notified via land line R47

Parts ----- Quantity -----

**Task performed:**

Completed j

NO PARTS USED

**Workorder: V34521**

In Date: 08/26/2010  
Close Date: 10/20/2010

Meter Reading: 11,782.90

**Problem?**

boot between cab torn R47

Parts ----- Quantity -----

**Task performed:**

Rep rear boot. j

NO PARTS USED

**Workorder: V35017**

In Date: 09/17/2010  
Close Date: 10/20/2010

Meter Reading: 11,782.90

**Problem?**

Cab A/C not working properly R47

Parts ----- Quantity -----

**Task performed:**

1. Blower inop (A/C); replc blower motor & wire harness. 2. O2 leak; chkd for leaks, fnd none. 3. Dropped off oil. j

15W40QSYN OIL QT	10
BPM8YSPRK PLUG BLOWER	1
VCC/35000003BLOWER MOTOR VCCT1000904A M2	1
VCC/83000038AC WIRE HARNESS	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V35566**

**In Date:** 10/12/2010

**Meter Reading:** 12,380.20

**Close Date:** 10/26/2010

**Problem?**

Call out to repair air leak.

Parts

Quantity

**Task performed:**

1. check vehicle for air leak,found air leak at treadle valve,r&r fitting ,test ok.
2. air pressure alarm going off, test and found improper air switch , alarm not going off to 100psi, needs new air pressure switch. job

NO PARTS USED





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V36132**

**In Date:** 11/02/2010  
**Close Date:** 11/16/2010

**Meter Reading:** 125,029.00

**Problem?**

**C INSPECTION AND REPAIRS AS NEEDED R47**

**Task performed:**

C-Inspection & road test. 2. Eng comp dirty; press wash. 3. Rem frnt tires, install (2) new frnt tires. 4. Rem (6) tires; got (6) frm Bldg 3 as per Mike Lehan; chk press, change valve extension & support; install on truck. 5. Exh heat shield loose; sec holddown strap; exh tip loose; replc tip 4" reducer band to a 4" straight band & tighten. 6. Cab center marker light dim; frnd bulb connection loose; sec loose bulb socket. 7. Rem (2) damaged SCBA tube. 8. Svc air dryer & purge kit. 9. Fuel cap needs painting; rem, cln & paint fuel cap. 10. Officers door warning light 10-7; frnd door light disconnected, reconnect. 11. A/C filters svc, cab dash, cab rear & pat compt; 110 A/C filter. 12. 110 A/C cvr unsecure; secure 110 A/C cvr. 13. L/rear SCBA release latch loose; adj latch/secure pull lever asy. 14. A/C belt svc. 15. Eng serpentine belt svc. 16. A/C line shaffing - install protection hose. 17. R/Rear cab door entrance molding brkn; rem/install new molding. 18. Pat compt UV bulb 10-7; rem blown UV bulb install new bulb. 19. Cab to modular partition damage; diss, sec loose internal supports & reenforce support; reassem, install tooth & spacer. 20. Cab glove box brkn; rem/install new box. 21. Windshield wiper blade removal & install new blades. 22. L-4 compt vent brkn; rem/fab panel install. 23. Baseboard reflector damage; sec loose baseboard reflector rubber bumper; sec reflector & cut away loose jagged edges. 24. Side entrance nonskid pads worn out; rem/cln surface; install new skid pads. 25. Action area instrument panel drop down unsecure; diss locking mechanism; ajd/secure. 26. Cab electronic box lock 10-7; adj locking mechanism. 27. Road test after tire replacement; no pulling or shimmying of steering on driving or braking. j

Parts	Quantity
0/2-311-610-372SDUEL AIR GAUGE M2	1
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
0127110042BELT MERCEDES MOTORS	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	24
18-46375-00118-46375-005 TREAD PLATE RH M2	1
33961C35976 MUFFLER CLAMP	1
5008414CARTRIDGE DC100	1
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
9420BELT	1
ACX-84534LUG NUT COVER PK10	11
AMH-1AMH-1 VALVE EXTENSION	1
DOR4011AD0010-0 DOOR SCBA COMPT.	1
E-600013-3052 NUT	2
GASK-BEL0110002439 WINDOW BELLOWS 6 IN WID	7
K022105PURGE VALVE AD-IP-IS	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1
VCC/36000006A/C FILTER CAB M2	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V36192**

In Date: 11/04/2010  
Close Date: 11/18/2010

Meter Reading: 124,793.90

**Problem?**

-request a mic clip mount for the PA mic in R47 LT seat -also check possible break/air leak on startup -need new main O2 regulator with new wrench as well the current regulator reads inaccurate

**Task performed:**

1. Opr complaint; air lost on startup; chk sys; unable to dupe air sys fault; chk/fnd gauge connection faulty; gauge on B/O; install air PSI gauge & ressemble dashboard. 2. Btry chk, charging sys; chk volt & current is within specs; no fault fnd at this time as to opr complain. 3. O2 regulator - replc bad regulator & new wrench. 4. Drill/tap holddown for replcement mi holder; install on officers side. j

Parts	Quantity
AS75807OXM1757-01 OXYGEN WRENCH	1
REG041462369 O2 REGULATOR	1

**Workorder: V37277**

In Date: 12/20/2010  
Close Date: 12/20/2010

Meter Reading: 12,665.60

**Problem?**

OIL CAP LOST R47

**Task performed:**

1. replace oil cap

Parts	Quantity
DDE-0000100285OIL CAP M2	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V35162**

In Date: 09/24/2010  
Close Date: 12/22/2010

Meter Reading: 11,782.90

**Problem?**

R47 The connecting piece that connects the cab to the patient compartment is coming down. This is letting in the rain etc. Needs fixed ASAP....Please call 47 to confirm this W.O. when you get it..Thank you.. Chris

Parts ----- Quantity -----

**Task performed:**

(1) CAB BOOT FELL DOWN LETTING RAIN IN. REPAIRED CAB BOOT.

NO PARTS USED

**Workorder: V35185**

In Date: 09/26/2010  
Close Date: 12/22/2010

Meter Reading: 11,782.90

**Problem?**

AC BLOWING HOT. WE HAVE BEEN DRIVING WITH WINDOWS OPEN BECAUSE IT IS MUCH COOLER THAN USING THE AC E47 R47?

Parts ----- Quantity -----

**Task performed:**

(1) A/C SYSTEM NOT COOLING. REPAIRED FREON LEAK,PRESSURE TESTED SYSTEM, RECHARGED SYSTEM AND CHECKED COOLING. OK. J.W.

RD546400P11-2630 SWITCH BINARY 1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V35204**

**In Date:** 09/27/2010  
**Close Date:** 12/22/2010

**Meter Reading:** 11,782.90

**Problem?**

shore line is plugged in but no ac is running in the rescue..only hearing a humming sound if anything R47

**Parts** ----- **Quantity** -----

NO PARTS USED

**Task performed:**

(1) SHORELINE ON R47 IS PLUGGED IN BUT A/C IS NOT RUNNING. REAR 110 VOLT A/C NOT WORKING. 110VOLT BREAKER BLOWN. RESET THE BREAKER AND TESTED OK. (2) NO CAB A/C. REPAIRED LEAK AND RECHARGED SYSTEM.

**Workorder: V37649**

**In Date:** 01/05/2011  
**Close Date:** 01/06/2011

**Meter Reading:** 129,243.60

**Problem?**

Rescue losing air pressure. Takes a while to build pressure in order to drive. r47

**Parts** ----- **Quantity** -----

S4640024430VALVE LEVELIN 1

**Task performed:**

(1) TRAVELED TO ST-47 TO REPAIR AIR PRESSURE PROBLEM OF PUMPING UP PRESSURE SLOWLY ON R47. REPLACED LEFT REAR AIR BAG LEVELING VALVE THAT WAS LEAKING AIR. ADJUSTED RIDE HEIGHT. OK. J.W.



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V37276**

In Date: 12/20/2010  
Close Date: 01/10/2011

Meter Reading: 12,665.60

**Problem?**

ON CALL OIL CAP LOST R47

Parts ----- Quantity -----

**Task performed:**

Oil cap msgng; replc cap. j

NO PARTS USED

**Workorder: V38472**

In Date: 02/13/2011  
Close Date: 02/23/2011

Meter Reading: 132,801.00

**Problem?**

on call door wont open R47

Parts ----- Quantity -----

**Task performed:**

Rear pat door locks inop; diss door panels, window, pull rods & rem locks;  
replc locks & reassem; test to ensure locks; work & adj door jam. j  
(2/23/11) Readj door latch. Rep rear dump switch that fell out of dash. j  
(3/10/10)

LTC594111656-16 LATCH R/H MEDIC MASTER	2
LTC594211657-16 LATCH L/H MEDIC MASTER	2

**Workorder: V37762**

In Date: 01/12/2011  
Close Date: 02/25/2011

Meter Reading: 129,243.60

**Problem?**

-tool brackets needed -outside air leak from rubber corrugated section  
between front and rear cab needs repair -LT's seat on R47 very rocky

Parts ----- Quantity -----

**Task performed:**

1. Remounted tools in rear compt. 2. Installed new rubber gskt for cab. j

5269LPVM-5 SM MOUNT	10
---------------------	----



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

### \* ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V38318**

**In Date:** 02/07/2011

**Meter Reading:** 133,092.00

**Close Date:** 03/02/2011

**Problem?**

B inspection and repairs as needed R47

**Task performed:**

B-Inspection 2. R/R front brakes. 3. Rem right rear pat door cvr & adj linkage rods; door was sticking. 4. R/R frnt brake shoes, drums & hardware. 5. Quality check. 6. Replc struts on inner compt of pat compt. 7 Rem/reroute driver's side wash line. 8. Tighten/adj all compt door latches. 9. Charge pat A/C; chk for leaks; pull out freon; replc lo-side shrader fitting; vac sys & recharge. 10. Cln/polish both frnt headlights. 11. Replc left rear mud flap. 12. Replc left rear nader pin cvr. 13. R/R right air bag leveling valve/fittings. 14. Fnd L/rear spring shifted; rem u-bolts; move spring into place; replc u-bolts; tightened other u-bolts; ck opn; adj level; c ok. j

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	24
16-31438915 VALVE CORE A/C 3544706C1	1
3753BRAKE DRUM RUMPER FRONT	2
39008USE 39045 KIT	2
8T7836U-BOLT	2
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
A9061840408SPINNER OIL FILTER COVER M2	1
DN78NUT	4
HLD3999GSS1715UV 30LB STRUT GAS	2
KSMA2124703QFRONTBRAKE KIT RUMPER AND 4D	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
S4640024430VALVE LEVELIN	1
SUW78WASHER	4



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V37605**

In Date: 01/03/2011      Meter Reading: 129,243.60  
Close Date: 03/08/2011

**Problem?**

R47 needs a bracket & strap to secure an extinguisher in the engineer/driver compartment

Parts ----- Quantity -----

**Task performed:**

Installed straps in L-1 compt. j

NO PARTS USED

**Workorder: V37781**

In Date: 01/12/2011      Meter Reading: 129,243.60  
Close Date: 03/08/2011

**Problem?**

Need Glass Mstr mounting bracket installed inside R47 L2 wall (see black dots), Also Q47 R1 inside door (see black dots). Also, Need NY Hook inside R47 L4 door (see black dots). Tommy knows about it. R47

Parts ----- Quantity -----

**Task performed:**

Mounted glass cutter in L-1 compt. j

GASK-BEL0110002439 WINDOW BELLOWS 6 IN WID      6

**Workorder: V37853**

In Date: 01/18/2011      Meter Reading: 129,243.60  
Close Date: 03/08/2011

**Problem?**

ON CALL WATER LEAK IN CAB R47

Parts ----- Quantity -----

**Task performed:**

Fnd wtr in cab; rep rubber boot. j

ALA00350-50 EXTENDED LIFE COOLANT GAL      1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V37974**

In Date: 01/21/2011  
Close Date: 03/08/2011

Meter Reading: 129,243.60

**Problem?**

Tommy, We added the NY Hook clamps to L5 of R47. We tapped the bottom screw holes for each bracket but didn't have the 3/4" screws to secure it. Need 2 screws to complete job (both threaded already) thanks.

Parts ----- Quantity -----

**Task performed:**

reinstalled tools in L-1 compt. j

NO PARTS USED

**Workorder: V39577**

In Date: 03/31/2011  
Close Date: 04/01/2011

Meter Reading: 137,621.20

**Problem?**

on call check eng lt on r 47

Parts ----- Quantity -----

**Task performed:**

Eng warning on - low coolant; add coolant, press test, tightened hose clamp as needed. j

15W40QSYN OIL QT 12

**Workorder: V40008**

In Date: 04/19/2011  
Close Date: 04/27/2011

Meter Reading: 139,538.00

**Problem?**

system that dumps rear of truck to allow ease of loading stretcher is leaking air and needs time to build up pressure to raise after it has been dumped. Sta47.

Parts ----- Quantity -----

**Task performed:**

1. Chk air dump sys - unknown; inspected - air dump working properly; has a normal delay while air bag refill. 2. Coolant leak - poss EGR cooler; press tested - no external leaks; EGR cooler shows signs of leakage. j

S4640024430VALVE LEVELIN 2





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V40122**

**In Date:** 04/25/2011

**Meter Reading:** 140,341.00

**Close Date:** 05/02/2011

**Problem?**

C inspection and repairs R47 COOLANT LEAK POSS EGR COOLER.

Parts

Quantity



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

### \* ADVANCED LIFE SUPPORT VEHICLE

#### Task performed:

C-Inspection 2. pat compt cabinet molding fell off; install/secure with new replacement screws. 3. Pat compt A/C filter - blow out filter & reinstall. 4. Svc diff. 5. Cab A/C filter; rem dirty filter & install cln filter. 6. R/side doorway step molding shattered; rem/install new molding. 7. R/side dashboard cvr asy brkn; diss; rem/add on accesories; reassem new dashboard & install. 8. A/C UV bulb inop; rem blown UV bulb & install new bulb. 9. Rear brakes; rem wheels/diss brakes; cln parts; install new brake shoe; adj slack adjuster. 10. Rear axle seals leaking; rem axle, drum, seal cln drum; install new seal; reassem, fill diff; all work done to mfr specs. 11 Left seat excess rocking; diss as per Ed Ehrke; no fault fnd; Ed took pictures; reassem. 12. L/frnt spring mnt brkt nut/bolt loose; torque nut/bolt tight. 13. Dia EGR; fnd sys leaking coolant; diss/rem EGR frm unit; cln parts, reassem EGR cooler/valve; reinstall. 14. Coolant leak - press test sys; fnd no external leak in cab or on grd; coolant leak throwing a code (111). 15. Coolant sys svc. 16. Eng belt svc. 17. A/C belt svc. 18. Cab to modular unit partition damage; rem, cln surface; cut/install new partition booth. 19. Stretcher stop msng; install replacement stretcher stop. 20. Cal marker lights 10-7; drop headliner to gain access & rem blown light bulb; install new marker light bulbs asy & reassem headliner. 21. R-1 & L-2 lock need timing; adj lock rod travel. 22. Rear pat entrance door window glass seal loose; rem, cln retaining ring & groove; reinstall seal. 23. L-2 & L-3 door panel loose; secure loose panel. 24. R/R wiper blades; filled washer fluid; replc msng nut cvrs. 25. Cleared eng codes; topped off collant; ck ok. 26. Fnd pat A/C hoses rubbing at eng turbo outlet; insulated/tied up hoses; ck opn - ck ok. 27. Quality check. 28. PU, cln & scrub bay. j

0000900087DDE/A0000900087 FILTER HEAD SM MEI	1
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
0127110042BELT MERCEDES MOTORS	1
18-46375-00118-46375-005 TREAD PLATE RH M2	1
380003ASEAL	2
401581GASKET AXLE FL80 R002435	2
42809AIR FILTER M2	1
6092036018J HOOK STRYKER	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
9420BELT	1
A06-40578-000TOP CLEARANCE LIGHT M2	2
A22-54059-000DASH PANEL R/H M2	1
A9061420580GASKET	1
A90614206791EA9061421179 EGR COOLER	1
A9061420880GASKET	1
A9061421080GASKET EGR COOLER	1
ACX-84534LUG NUT COVER PK10	6
DDE/A0039973352EGR COOLING HOSE	2
EA9061420619RA9061420619 EGR VALVE	1
GASK-BEL0110002439 WINDOW BELLOWS 6 IN WID	6
KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1
VCC/36000006A/C FILTER CAB M2	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V40211**

In Date: 04/27/2011  
Close Date: 05/02/2011

Meter Reading: 140,233.00

**Problem?**

while R47's unit is in for maintainence, we need the plastic glove box holder in the cab replaced..thanks

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

Rem brkn glove box & install new box. j

NO PARTS USED

**Workorder: V40246**

In Date: 04/29/2011  
Close Date: 05/02/2011

Meter Reading: 140,233.00

**Problem?**

won't start.

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

Unit will not start; chk btry, starter; starter relay, solenoid - all has power; swapout unit; travel to shop for spare. j

NO PARTS USED

**Workorder: V40245**

In Date: 04/29/2011  
Close Date: 05/03/2011

Meter Reading: 140,233.00

**Problem?**

won't start.

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

Travel to 47; Dia no start; fnd bad starter; replc starter. j

11132766583 STARTER 28MT 5.9 10 TOOTH 104650 1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V40293**

In Date: 04/30/2011  
Close Date: 05/04/2011

Meter Reading: 140,233.00

**Problem?**

R47 appears to have a slow leak of redish color fluid that appears to be radiator fluid. R47 just returned on 4/29 from repair of coolant system issue

**Task performed:**

1. Coolant leak; fnd loose radiator hose clamp; secure clamp & add 2 qts coolant. 2. No-start; unit started when arrived; chk btry on a full load; sys maintaining 13.6V full load 13.9 no load. j

Parts	Quantity
FSC17492134NC SW PARK BK SPADE TYPE CONNE	1

**Workorder: V38767**

In Date: 02/25/2011  
Close Date: 05/05/2011

Meter Reading: 134,490.40

**Problem?**

The spotlight on rescue 47's roof does not work properly. The light moves left and right but does not move up and down. r47

**Task performed:**

Fnd no problem w/light. j

Parts	Quantity
NO PARTS USED	

**Workorder: V39168**

In Date: 03/14/2011  
Close Date: 05/05/2011

Meter Reading: 1,234.00

**Problem?**

Box light charger behind driver seat on R47 does not charge. sta 47.

**Task performed:**

Sent to shop. j

Parts	Quantity
NO PARTS USED	



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

### \* ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V40160**

In Date: 04/26/2011  
Close Date: 05/09/2011

Meter Reading: 140,233.00

**Problem?**

replace all 6 tires (outside agency-boulevard tire)

Parts ----- Quantity

**Task performed:**

Replc all (6) tires - Boulevard j

NO PARTS USED

Vendor? BOULEVARD

**Workorder: V40526**

In Date: 05/10/2011  
Close Date: 05/10/2011

Meter Reading: 140,233.00

**Problem?**

unit will not start, R-47

Parts ----- Quantity

**Task performed:**

1. travel to south palms elem. school, check vehicle for no start, check batterys, found 2 bad batterys, replace all 4 batterys and check charging system, 13.8 travel back to s/shop

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/ 4  
HP-31DBATTERY 950CCA HP-31D 4

**Workorder: V39878**

In Date: 04/12/2011  
Close Date: 05/13/2011

Meter Reading: 139,224.20

**Problem?**

R47 has been burning through heavy amounts of oil and engine coolant daily...does not appear to be leaking..is due to PM also according to miles

Parts ----- Quantity

**Task performed:**

1. Replc wipers. 2. C/O alarm going off; tested unit & tested ok. 3. Sharps draw inop; rep slides. j

5632-1010 IN DRAWER SLIDES PR 4  
91-22WIPER BLADE 4  
MNT587148Z671 ALARM CARBON MONOXIDE 1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V39273**

In Date: 03/17/2011  
Close Date: 06/03/2011

Meter Reading: 136,343.20

**Problem?**

The electric spotlight on the top of the cab moves left and right but not up and down. R47

Parts ----- Quantity -----

**Task performed:**

1. Rear cab A/C leaking; unclogged drain for A/C 2. Chk roof spotlight; fnd unit working. j

2020-DDASH MOUNT REMOTE CONTROL	1
---------------------------------	---

**Workorder: V41057**

In Date: 06/02/2011  
Close Date: 06/09/2011

Meter Reading: 142,439.90

**Problem?**

front cab front dash AC not blowing on R47, Sta 47.

Parts ----- Quantity -----

**Task performed:**

Recharged sys & chkd for leaks. j

NO PARTS USED	
---------------	--

**Workorder: V42076**

In Date: 07/17/2011  
Close Date: 07/18/2011

Meter Reading: 145,021.30

**Problem?**

R47 cab ac (dash) not blowing

Parts ----- Quantity -----

**Task performed:**

R47 AC 10-7 NO BLOWER FOUND LOOSE PLUG ON UNIT REPAIR WORKING OK AT THIS TIME. AK

NO PARTS USED	
---------------	--



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V42111**

In Date: 07/19/2011  
Close Date: 07/19/2011

Meter Reading: 145,021.30

**Problem?**

Light out.

Parts ----- Quantity -----

**Task performed:**

light out check out found no problem with truck drove truck with light all work ok at this time ak

NO PARTS USED

**Workorder: V41785**

In Date: 07/05/2011  
Close Date: 07/20/2011

Meter Reading: 145,021.30

**Problem?**

Lost oil cap.

Parts ----- Quantity -----

**Task performed:**

clean off all oil from engine and installed new cap ak

DDE-0000100285OIL CAP M2 1

**Workorder: V40343**

In Date: 05/02/2011  
Close Date: 08/03/2011

Meter Reading: 140,233.00

**Problem?**

REPLACE TIRES R47

Parts ----- Quantity -----

**Task performed:**

Replace tires R47 - Boulevard j

NO PARTS USED

Vendor? BOULEVARD



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V41768**

In Date: 07/03/2011  
Close Date: 08/08/2011

Meter Reading: 145,021.30

**Problem?**

shore line connection is very loose. Operation under shoreline power is intermittent. Charging light not functioning while connected. R 47

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

checked connection nd tested ok

NO PARTS USED

**Workorder: V41895**

In Date: 07/09/2011  
Close Date: 08/08/2011

Meter Reading: 145,021.30

**Problem?**

per medic, top spot light on R47 not working properly

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

tested light and tested ok

NO PARTS USED

**Workorder: V42617**

In Date: 08/07/2011  
Close Date: 08/17/2011

Meter Reading: 147,147.60

**Problem?**

check engine light, consulted with on call a-tech. R 47

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

Fnd faulty boost sensor active code; came to shop for part; replc sensor & cleared code. j

DDE/A0041537028SENSOR PRESSURE 1





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V42297**

In Date: 07/26/2011  
Close Date: 08/25/2011

Meter Reading: 146,715.00

**Problem?**

A/C not blowing cold.

Parts

Quantity

**Task performed:**

Rep connection on condensor fan. j

NO PARTS USED

**Workorder: V42361**

In Date: 07/28/2011  
Close Date: 08/26/2011

Meter Reading: 146,715.00

**Problem?**

Cab AC won't turn on on R47.

Parts

Quantity

**Task performed:**

1. Replc blower motor & wires. 2. Rep air leak & rechkd. j

VCC/35000003BLOWER MOTOR VCCT1000904A M2 1

VCC/83000038AC WIRE HARNESS 1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V42876**

**In Date:** 08/17/2011

**Meter Reading:** 148,164.70

**Close Date:** 09/06/2011

**Problem?**

B INSPECTION AND REPAIRS AS NEEDED R 47

Parts

Quantity



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Task performed:**

1. Dia & replc radiator. 2. Quality inspection. 3. B-Inspection 4. Assist w/rad - radiator. 5. Install rear air bags. 6. Trans svc. 7. Retorque u-bolts. 8. Install pedal for steering wheel tilt. 9. Rem rear pat door panel & extract brkn bolt; also replc stretcher hook & tighten L/rear compt door strop. 10. C/O A/C defroSts not working; reset cntrl head. 11. Rem Medtec cntrl panel & diss; cln board & replc power buttons. 12. Replc rear A/C hose frm condensor to compressor; evac & recharge sys. 13. replc wiperblades & cln spray nozzle. 14. Rem rear brake drums & inspect brakes; adj all brakes. 15. Replc all A/C air filters. 16. Install air dryer kit. 17. Install \_\_\_\_\_ gauge grnd cables on nodes 2&3; take a long test drrive; tighten all cables in node compt. 18. Rep wiring to flush light charger. 19. install bolts in center console & tighten head rail on side of cab. 20. Install rear A/C vent & reglue pass thru molding. 21. Install auto-eject cvr. 22. Install corner lights on hood. j

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
05-17223-002RAD CAP 20 LB	1
091-3YWCOVER KUSSMAUL AUTO EJECT	1
0K00-1958-00KEY PAD 7 POSITION	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	24
16-15762-00016-19471-000 AIR BAG	2
29526898 29548988 TRANS FILTER ALLISON	1
389843HOSE & FITTING	1
5008414CARTRIDGE DC100	1
6092036018J HOOK STRYKER	1
72R31001720 DIFFUSER A/C 3.5 IN	1
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
9UCAPCC9UCAPCC END CAP CLEAR	1
ACX-84534LUG NUT COVER PK10	7
C1673FRE04 RADIATOR	1
K022105PURGE VALVE AD-IP-IS	1
RGT-452258FFOOT PEDAL STERRING COLUMN	1
RGT401737ESPRING PEDAL RETURN	1
RGT401741CRETURN SPRING	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
TRANSYNDALLISON TRANS FLUID GAL	5
VCC/36000006A/C FILTER CAB M2	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

### \* ADVANCED LIFE SUPPORT VEHICLE

#### Workorder: V42929

In Date: 08/20/2011  
Close Date: 09/06/2011

Meter Reading: 148,164.70

#### Problem?

Intermittent electrical problems with emergency lights, back up alarm, and information panel in the cab. Spotlight does not function. Air conditon also malfunctions intermitantly in the crew cab. R47

Parts ----- Quantity -----

#### Task performed:

SEE w.o. 42876 J

NO PARTS USED

#### Workorder: V43182

In Date: 08/31/2011  
Close Date: 09/06/2011

Meter Reading: 148,164.70

#### Problem?

CAB A/C 10-7 R 47

Parts ----- Quantity -----

#### Task performed:

1. Jerry assisted w/compressor reinstall. 2. Rem belt frm compressor & compressor frm truck rem. 3. Rem both dryers & step opened condensor; fnd hoses bad; clnd & order new hoses. j

390330HOSE & FITTING ASSY	1
533303-0609 A/C COMPRESSOR M2 4485	1
ABPN83319744USE 7197 DRYER M2	1
RD-5-7063-OP07-2618A A/C DRIER 7155	1

#### Workorder: V42733

In Date: 08/10/2011  
Close Date: 09/12/2011

Meter Reading: 148,045.00

#### Problem?

R47 is not receiving the shore line

Parts ----- Quantity -----

#### Task performed:

repaired 110 shore line and tested

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V43107**

In Date: 08/28/2011  
Close Date: 09/19/2011

Meter Reading: 148,164.70

**Problem?**

upon checkout, noticed strong burning odor..possible coming from a belt under the hood...tommy has been dispatched out to respond...hes enroute...R47

Parts ----- Quantity -----

**Task performed:**

FOUND CAB A/C COMPRESSOR LOCKED UP SWAP OUT TRUCK

NO PARTS USED

**Workorder: V43376**

In Date: 09/01/2011  
Close Date: 09/19/2011

Meter Reading: 148,164.70

**Problem?**

REPLACE SEAT SHOCK R 47

Parts ----- Quantity -----

**Task performed:**

replaced shock on seat

102363PSSEAT SHOCK	1
FREIGHTSHIPPING CHARGES	33

**Workorder: V43467**

In Date: 09/06/2011  
Close Date: 09/21/2011

Meter Reading: 149,305.20

**Problem?**

-check engine light going on and off.. -did the same last month, repaired by mechanic .. -truck is running normal, Sta 47.

Parts ----- Quantity -----

**Task performed:**

1. check for codes, found code for # 6 injector , called Mike at detroit was advised to check wiring harness then r&r injector. advised Ed E and was told that detroit was going to make repair at sta-47

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V43704**

In Date: 09/15/2011  
Close Date: 09/21/2011

Meter Reading: 149,902.00

**Problem?**

R47 front dash ac blowing warm at idle, cooling off when going 20+ mph

**Task performed:**

check for a/c leak, evacuate system and charge with nitron found leak at bulk head fitting on red dot a/c system. put unit back in service until part arrived. pulled unit o/s remove street side step and red dot a/c assy. replace bulk head fitting, pump system down and recharge recheck for leaks found none at this time.

Parts ----- Quantity

RD-4-3804-0BRACKET ASSY RED DOT	1
---------------------------------	---

**Workorder: V43807**

In Date: 09/20/2011  
Close Date: 09/21/2011

Meter Reading: 150,436.00

**Problem?**

air leak.

**Task performed:**

Air leak line frm compressor to dryer; brought to shop; replc line. j

Parts ----- Quantity

A1211593054HOSE DISCHG	1
------------------------	---

**Workorder: V43808**

In Date: 09/20/2011  
Close Date: 09/21/2011

Meter Reading: 150,436.00

**Problem?**

Cab a/c inop.

**Task performed:**

cab a/c inop low refrigerant add 2lb refrigerant found small leak at hi side sh--may need to come to shop if it leaks out

Parts ----- Quantity

NO PARTS USED	
---------------	--



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V43742**

**In Date:** 09/18/2011  
**Close Date:** 09/23/2011

**Meter Reading:** 150,121.90

**Problem?**

R47 front and rear cab AC blowing warm today. Mechanic john came out, added freon, stated the truck may need to come to the shop for possible leak repair. Pt compartment AC working fine with no issues. Sta 47.

Parts ----- Quantity -----

**Task performed:**

recharged unit and tested

NO PARTS USED

**Workorder: V43743**

**In Date:** 09/18/2011  
**Close Date:** 09/23/2011

**Meter Reading:** 150,121.90

**Problem?**

Bellows between pt compartment and cab coming apart, needs repair. Rather not swap out for repair. This is not a high priority, chronic problem. Sta 47

Parts ----- Quantity -----

**Task performed:**

repaired seal for cab and body

NO PARTS USED

**Workorder: V43748**

**In Date:** 09/19/2011  
**Close Date:** 09/23/2011

**Meter Reading:** 150,121.90

**Problem?**

update from earlier work order. john the mechanic added freon, was blowing cold. Now after 2 calls, its midnight and all cab AC is blowing warm again. Sta 47.

Parts ----- Quantity -----

**Task performed:**

will send to shop for leak

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V43412**

In Date: 09/06/2011  
Close Date: 10/06/2011

Meter Reading: 149,305.20

**Problem?**

REPLACE INJECTOR R 47

Parts ----- Quantity -----

**Task performed:**

Replace injector R47 - Fla Detroit Diesel j

NO PARTS USED

Vendor? FLA DETROIT DIESEL

**Workorder: V29643**

In Date: 10/11/2011  
Close Date: 10/11/2011

Meter Reading: 105,434.50

**Problem?**

test do not delete

Parts ----- Quantity -----

**Task performed:**

NO PARTS USED

**Workorder: V44492**

In Date: 10/19/2011  
Close Date: 10/28/2011

Meter Reading:

**Problem?**

R47's spare unit (10136360) has the driver's side head light out, brights included.

Parts ----- Quantity -----

**Task performed:**

Replc headlight. j

H6054USE CV TYPE SEALED BEAM 2





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V45202**

In Date: 11/16/2011  
Close Date: 11/18/2011

Meter Reading: 151,289.00

**Problem?**

A INSPECTION /CHECK REPAIR BY FLA DETROIT ENG. REBUILT

**Task performed:**

A-Inspection 2. Install both belts & serpentine belt tensioner. 3. Swap front tires from side-to-side; road test. 4. Pull off steering column plastic & grease slip yoke. 5. Reroute wiper washer hoses. j

Parts	Quantity
0127110042BELT MERCEDES MOTORS	1
9420BELT	1
DDE/A9062003170BELT TENSIONOR MERCEDES	1

**Workorder: V44054**

In Date: 09/30/2011  
Close Date: 12/05/2011

Meter Reading: 150,941.00

**Problem?**

R+R CAM SHAFT DETROIT

**Task performed:**

R&R CAM SHAFT DETROIT.

Parts	Quantity
NO PARTS USED	

Vendor? FLORIDA DETROIT DIES

**Workorder: V45402**

In Date: 11/23/2011  
Close Date: 12/12/2011

Meter Reading:

**Problem?**

drivers side headlight is out R47

**Task performed:**

replaced headlight repaired strecher latch

Parts	Quantity
3157NAAMBER BULB	8
9006XSLLEHEADLAMP M2 HI	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V45770**

In Date: 12/09/2011  
Close Date: 12/14/2011

Meter Reading:

**Problem?**

R47 tires getting low on tread, some areas worse then others

Parts

Quantity

**Task performed:**

R47 TIRES GETTING LOW ON TREAD, SOME AREAS WORSE THEN OTHERS.

NO PARTS USED

Vendor? BOULEVARD

**Workorder: V45928**

In Date: 12/18/2011  
Close Date: 01/03/2012

Meter Reading:

**Problem?**

TRUCK IS LEAKING LARGE AMOUNTS OF WHAT APPEARS TO BE RADIATOR COOLANT, Sta 47

Parts

Quantity

**Task performed:**

coolant leak found leak repaired hose and refilled with coolant

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V46204**

In Date: 01/01/2012  
Close Date: 01/05/2012

Meter Reading:

**Problem?**

4 issues -coolant leak -oil leak -front dash AC warm R47 -roof spot light out

**Task performed:**

1. check for coolant leak, found hose clamps missing install hose clamps. recheck for leaks, found clamps loose tighten clamps recheck then found over flow tank leaking, replace tank. recheck no more leaks... 2. check for oil leak found oil coming from breather tube, engine was just rebuilt, advised driver when ever possible to keep high idle on untill engine is broken in 3. roof spot light inop, remove panel and found wires pulled from connector, reinstall wires,

Parts	Quantity
05-17223-002RAD CAP 20 LB	1
05-23195-000Z05-30740-000 SURGE TANK	1

**Workorder: V46416**

In Date: 01/09/2012  
Close Date: 01/10/2012

Meter Reading: 155,792.70

**Problem?**

a/c not cold.

**Task performed:**

CHECK A/C PRESSURE .5 CHARGE AND REPLACE A/C CABIN FILTER  
- #VCC136000006 WHILE THERE FOR AIR PACKS.

Parts	Quantity
VCC/36000006A/C FILTER CAB M2	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V45988**

In Date: 12/20/2011  
Close Date: 01/13/2012

Meter Reading: 154,127.40

**Problem?**

R47 and Q47 both have a small leak of oil on bay floor... also R47 spot light on roof it out, Sta 47

Parts ----- Quantity -----

**Task performed:**

REPAIRED SPOT LIGHT AND TESTED.

NO PARTS USED

**Workorder: V46683**

In Date: 01/18/2012  
Close Date: 01/27/2012

Meter Reading: 156,775.00

**Problem?**

while driving the large passenger size mirror fell out of frame. There is no large passenger mirror Q47

Parts ----- Quantity -----

**Task performed:**

REPLACED MIRROR AND READJUSTED.

A22-58516-001MIRROR HEAD 1

**Workorder: V46763**

In Date: 01/23/2012  
Close Date: 01/27/2012

Meter Reading: 156,775.00

**Problem?**

Rescue hit toll plaza.

Parts ----- Quantity -----

**Task performed:**

DAMAGE TO RIGHT SIDE HOOD DAMAGE HOLE IN OIL PAN FRONT END BENT.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V46979**

**In Date:** 01/31/2012

**Meter Reading:** 156,775.00

**Close Date:** 02/03/2012

**Problem?**

Right front turn signal not operational. Sta 47

Parts

Quantity

**Task performed:**

REPLACED BULB IN LIGHT.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V46664**

**In Date:** 01/18/2012

**Meter Reading:** 156,775.00

**Close Date:** 03/05/2012

**Problem?**

**C INSPECTION R 47**

**Task performed:**

1. CHECK OUT ACCIDENT DAMAGE AND ORDER PARTS. 2. REPLACED OIL PAN (HAD TO REMOVE U-BOLTS AND DROP FRONT AXLE TO R&R OIL PAN). 3. DROVE TO TOTAL TRUCK TO GET CENTE BOLTS FOR FRONT AXEL. 4. RESEALED TURB RETURN - (LEAKING) 5. CUT NEW CENTER PINS TO SIZE AND INSTALLED. 6. INSTALLED NEW U-BOLTS ON STEER AXLE AND TORQUED TO SPEC. 7. REPLACED LEFT AND RIGHT TIEROD ENDS AND TIEROD TUBE ASSEMBLY. (BENT) SET TOE ADJUSTMENT. 8. PERFORM C SERVICE. 9. REPLACED RIGHT FRONT TIRE AND WHEEL, TORC HEC OFF BENT WHEEL STUDS. REPLACED ALL TEN STUDS AND NUTS. (ACCIDENT DAMAGE) 10. REPLACED RIGHT STEER AXLE HUB CAP. TOPPED OFF FLUID. ( CRACKED). 11. REPLACED RIGHT MID CAB STROBE AND REWIRED. 12. REPLACED AMBER MARKER ON LEFT, FRONT, TOP OF BODY. 13. PAINTED FUEL CAP. 14. REPLACED WIPER BLADES. 15. REPLACED AIR FILTER. 16. CHANGED OUT AIR PACK BRACKETS. 17. RECHECKED TOE SPEC WITH TRUCK ON THE GROUND. INSTALLED OIL PAN PLUG AND FILLED WITH MOTOR OIL. ROAD TESTED TRUCK.

**Parts**

**Quantity**

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
13-1571STUD BRAKE CM 10001399	10
23-00461-006U BOLT WASHERS	8
23-12734-120U-BOLTS	4
42809AIR FILTER M2	1
50R03ZCRLIGHT LED RED TIR 6	1
6803304403TIE ROD ASSY	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
9186-1501-30CLEAR UTILITY LED	2
A06-51039-001A06-75732-005 RH HEAD LIGHT ASS'	1
A17-14930-001BEZEL RH HEADLAMP	1
A9060101813OIL PAN	1
A9060140922GASKET OIL PAN M2	1
ACX-84534LUG NUT COVER PK10	10
CB1510CENTER BOLT	2
CHR1612340-4024 HUB COVER - FRONT AXLE 2004	1
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
DDE-5411870080GASKET OIL RETURN TUBE TURBO	1
E-600013-3052 NUT	10
N000908030012OIL PAN PLUG	1
N007603030100GASKET PAN PLUG	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V47017**

In Date: 02/01/2012      Meter Reading: 156,775.00  
Close Date: 03/07/2012

**Problem?**

Repair accident damage

Parts ----- Quantity -----

**Task performed:**  
REPAIR ACCIDENT DAMAGE.

NO PARTS USED

Vendor? SOUTHEAST TRUCK SPEC

**Workorder: V47679**

In Date: 03/01/2012      Meter Reading: 156,775.00  
Close Date: 03/07/2012

**Problem?**

Finish repairs from C inspection

Parts ----- Quantity -----

**Task performed:**  
1. REPLACED RIGHT SIDE LOWER FRONT STROBE LIGHT ASSEMBL ON BODY. 2. CHECKED OUT CAB A/C BLOWING WARM AIR. FOUND TRUCK LOW ON FREON. RECOVERED LEAK CHECKED. (FOUND NO LEAKS) VACUUMED AND RECHARGED. A/C IS NOW COOLING NORMALLY. 3. CHECKED OVER TRUCK AND ROAD TESTED. 4. RETORQUED STEER AXLE U-BOLTS. 5. REPLACED REAR AXLE BRAKE SHOES. (WORN) 6. TROUBLESHOT AIR LEAK. TRACED LEAK TO AIR OVER ELECTRIC VALVES ON FRAME. RECYCLE CROSS MEMBER UNDER REAR OF TRUCK. REPLACED VALVE AND RECHECKED. ALSO SEALED NUMEROUS AIR FITTING ON AIR TANKS.

ACX-84534LUG NUT COVER PK10	14
KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2
NRG-27-SWB-011RNRG27SWB311R A12-19777-011	1
RSR03ZCRLIGHT LED RED TIR3 SERIES	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V42919**

In Date: 08/19/2011  
Close Date: 03/09/2012

Meter Reading: 148,164.70

**Problem?**

the stryker stretcher hook was removed from R47 and placed in the spare rescue..please replace the hook while its at the shop..

Parts ----- Quantity -----

**Task performed:**

NO PARTS USED

**Workorder: V46061**

In Date: 12/24/2011  
Close Date: 03/12/2012

Meter Reading:

**Problem?**

spot light not working

Parts ----- Quantity -----

**Task performed:**

NO PARTS USED

**Workorder: V46078**

In Date: 12/26/2011  
Close Date: 03/12/2012

Meter Reading:

**Problem?**

FRONT AC NOT WORKING, COOLANT LEVEL LOW, HAS COOLANT LEAK R 47

Parts ----- Quantity -----

**Task performed:**

NO PARTS USED





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V46169**

In Date: 12/30/2011  
Close Date: 03/12/2012

Meter Reading:

**Problem?**

passenger side view convex mirror broken. R47

**Task performed:**

Parts	Quantity
A22-59713-001MIRROR HEAD	1

**Workorder: V47980**

In Date: 03/15/2012  
Close Date: 03/15/2012

Meter Reading:

**Problem?**

rear compartment door does not unlock/open from inside cab.

**Task performed:**

1. check rear entry doors not opening, ajust door strickers..

Parts	Quantity
NO PARTS USED	



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

### \* ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V48382**

**In Date:** 04/02/2012

**Meter Reading:** 159,454.00

**Close Date:** 04/03/2012

**Problem?**

cab a/c clutch caught on fire, R-47

**Task performed:**

1. while at sta-47 working on E-47 (covering for quint) r-47 pulled into station from call and had smoke coming from under hood, lifted hood and found cab a/c clutch on fire driver got garden hose and put out fire. disconnect cab a/c clutch and followed unit back to s/shop and had them swap into spare rescue 10142536 2. remove fan belt, remove rear pat. compt a/c compressor belt, remove a/c compressor, lines and compressor, check compressor oil,ok replace o rings on a/c lines, install new compressor, install new dryer, evacaute system, system will not hold vac., fill with nitrogen and test system, found leak in red dot system under cab, remove step, found bottom a/c line on bulk head fitting loose, remove fitting and replace o ring, reinstall,replace dryer for red dot system, evacaute system again, holds vac. now, add oil for dryer's, replace pat. a/c compressor belt, and install new serpitne fan belt, (melted marks wher comp. caught on fire), charge system and check cools at 50 degrees, found L/side condensor fan not running on red dot system, replace both cond. fans. recheck cooling 28 degrees now.....

**Parts**

**Quantity**

0127110042BELT MERCEDES MOTORS	1
1512BINARY SWITCH 22-36474	1
333000006BATTERY JUNCTION BLOCK	1
533303-0609 A/C COMPRESSOR M2 4485	1
65-72BXT65750 BATTERY	2
719707-0614A AC DRIER M2	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	2
EL36009JUNCTION BLOCK 300A	1
RD-5-7063-OP07-2618A A/C DRIER 7155	1
RD571290 01-2616 MOTOR 12V 73R-0542 3512	2

**Workorder: V48465**

**In Date:** 04/05/2012

**Meter Reading:** 159,668.00

**Close Date:** 04/05/2012

**Problem?**

R-47 needs engine oil

**Task performed:**

1. check engine oil level, found 3qts low add oil, leave 1 case of engine oil at sta-47

**Parts**

**Quantity**

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V48636**

In Date: 04/13/2012  
Close Date: 04/26/2012

Meter Reading:

**Problem?**

front cab ac not working. sta 47

Parts ----- Quantity -----

**Task performed:**  
see wo 48833

NO PARTS USED

**Workorder: V48833**

In Date: 04/23/2012  
Close Date: 04/26/2012

Meter Reading:

**Problem?**

R47 air conditioning no longer working, was fixed last week, but out of freon again

Parts ----- Quantity -----

**Task performed:**

1. travel to sta-47 2. replace L/side headlight assy 3. check cab a/c low on freon top off system and check for leaks, remove side step and check red dot system, found hose that was just replaced leaking at crimp, next time i is low will have to come to the shop to replace hose.

NO PARTS USED

**Workorder: V49035**

In Date: 05/01/2012  
Close Date: 05/04/2012

Meter Reading: 161,662.00

**Problem?**

ON CALL A/C 10-7 R 47

Parts ----- Quantity -----

**Task performed:**

BELT NOISE/CAB A/C COMP CLUTCH LOCKED UP/SWAPPED OUT  
CAME BACK TO SHOP FOR SPARE RESCUE.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V48977**

In Date: 04/30/2012  
Close Date: 05/11/2012

Meter Reading: 161,662.00

**Problem?**

back right turning signal stays on at all times R 47

Parts ----- Quantity -----

**Task performed:**

REPAIRED BAD CONNECTION IN LIGHT.

NO PARTS USED

**Workorder: V49038**

In Date: 05/07/2012  
Close Date: 05/15/2012

Meter Reading: 161,662.00

**Problem?**

A/C 10-7 R 47

Parts ----- Quantity -----

**Task performed:**

1. REMOVE RADIATOR TANK TO REMOVE BOTH BELTS REMOVE All COMPRESSOR AND DRYER ASSEMBLY. 2. INSTALL CAB A/C COMPRESSOR, AND DRYER FLUSH A/C SYSTEM INSTALL BELTS AND RADIATOR FAN EVACUATE AND RECHARGE A/C SYSTEM. 3. A PER SHOP FORMAN STEVE R. REMOVE BELT AND FIND A REPLACEMENT BELT TO BY PASS A/C COMPRESSOR TO PUT IN SERVICE TRUCKS.

0127110042BELT MERCEDES MOTORS	1
1839415C91OIL PRESSURE SENSOR	1
22512960001498 SWITCH BINA	1
533303-0609 A/C COMPRESSOR M2 4485	1
719707-0614A AC DRIER M2	1
A22451940011499 SWITCH A/C HIGH PRESSURE NC	1
DUFDT04-4P-RT03EL35674 DIODE PACK GRAY	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V49225**

**In Date:** 05/09/2012  
**Close Date:** 05/15/2012

**Meter Reading:** 161,662.00

**Problem?**

B inspection

**Task performed:**

1. START B-INSPECTION. 2. FINISH B-INSPECTION. 3. INSTALL PATIENT A/C UV LIGHT BULB AND AIR FILTER. 4. INSTALL PATIENT A/C DOOR SHOCKS AND INSIDE L-1 COMPARTMENT SHOCKS. 5. REMOVE CENTER ROOF TRIM PANEL TO ACCESS ROOF MARKER LIGHT. 6. INSTALL BOTH CAB A/C FILTERS. 7. INSTALL R/F FENDER MARKER LIGHT BULBS CLEAN CONTACTS. 8. CLEAN R/S OF ENGINE AND CHECK FOR LEAKS FOUND LEAK AT TURBO OIL RETURN TUBE. 9. ACCESS TURBO OIL RETURN TUBE AND REMOVE INSTALL NEW TUBE TO TURBO GASKET RECHECK LEAKS. 10. REMOVE R/S FROM SEAT BASE HAD TO REMOVE WASHER BOTTLE TO ACCESS SEAT BASE NUT. REPLACE SEAT BASE AND REINSTALL. 11. REPLACE WIPER BLADES. 12. REMOVE TRIM PANELS AND HEAD SET PLUGS TO ACCESS PASS THRU SEAL REPLACE PASS THRU SEAL. 13. REPLACE BIO HAZARD DRAWER SLIDES. 14. INSTALL CHARGER INDICATOR LIGHTS. 15. Q.C. TRUCK 16. REPLACE R/F SIDE ROOF MARKER LIGHT. 17. TAKE ON TEST DRIVE AND RECHECK OIL LEAK OK.

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
032-0116549297 BATTERY INDICATOR	1
1501450007750USE 0775145	4
181503PSSEAT SUSPENSION	1
194BULB	1
194-ABULB	1
27-102A22-54259-000 DOOM LIGHT SWITCH M2	1
5632-1010 IN DRAWER SLIDES PR	2
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
A06-40578-000TOP CLEARANCE LIGHT M2	1
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
DDE-5411870080GASKET OIL RETURN TUBE TURBO	1
GASK-BEL0110002439 WINDOW BELLOWS 6 IN WID	7
HLD3999GSS1715UV 30LB STRUT GAS	4
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1
VCC/36000006A/C FILTER CAB M2	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V49519**

**In Date:** 05/21/2012  
**Close Date:** 05/31/2012

**Meter Reading:** 161,662.00

**Problem?**

cab a/c blowing warm and rear cab unit not blowing at all

**Task performed:**

1. CHECK OUT LEAK OR LOW AIR A/C, NOT COLD. 2. FOUND A/C HOSES IN CONDENSOR LEAKING,PUMP DOWN UNIT AND REMOVE HOSES TO HAVE NEW MADE. 3. GOT HOSES BACK FOR MAKO GOT O-RING AND INSTALL ALL HOSES, PUMP DOWN AND LEAK TEST UNIT AND CHARGER SYSTEM WITH R-134 - TEST DRIVE OK. 4. AFTER TEST DRIVE, R&R CAB FILTER AND BLOW OUT A/C FAN AND EVAP UNIT, SO A/C COULD FLOW THROUGH UNIT AFTER CLEANING 37 DEGREE OUT VENT GOOD.

Parts ----- Quantity -----

409142HOSE AND FITTING	1
------------------------	---

**Workorder: V50083**

**In Date:** 06/12/2012  
**Close Date:** 06/14/2012

**Meter Reading:** 161,867.70

**Problem?**

A inspection

**Task performed:**

1. A INSPECTION. 2. REPLACE QUICK CONNECT FITTING ON COMPRESSOR FOR AIR LEAK.

Parts ----- Quantity -----

NO PARTS USED	
---------------	--



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V50370**

In Date: 06/25/2012  
Close Date: 07/03/2012

Meter Reading: 162,490.20

**Problem?**

1) Spot light is out. 2) Housing in drivers compt. is hanging needs rivets/screws. 3) R-16 is leaning to the Left possible air bladder problem.

**Task performed:**

1. TRAVEL TO 16 FOUND SWITCH MELTED FOR SPOTLIGHT REPLACED SWITCH OUT OF NEW LIGHT ASSEMBLY. 2. SECURED SAFETY CAGE HOUSING IN L-2 COMPARTMENT. 3. ADJUSTED REAR SUSPENSION TO REPAIR LEON.

Parts	Quantity
2020-DDASH MOUNT REMOTE CONTROL	1

**Workorder: V50528**

In Date: 07/02/2012  
Close Date: 07/03/2012

Meter Reading: 162,814.30

**Problem?**

auto eject inop R16

**Task performed:**

TRAVEL TO 16 REPLACED AUTO EJECT.

Parts	Quantity
0915520120AUTO EJECT 20 AERO OTL3925	1

**Workorder: V50753**

In Date: 07/11/2012  
Close Date: 07/12/2012

Meter Reading: 163,213.00

**Problem?**

a/c in the front cab works off and on at station 16

**Task performed:**

REPLACED WIRING HARNESS TO BLOWER MOTOR.

Parts	Quantity
VCC/35000003BLOWER MOTOR VCCT1000904A M2	1
VCC/83000038AC WIRE HARNESS	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V51072**

In Date: 07/24/2012  
Close Date: 07/26/2012

Meter Reading: 163,839.70

**Problem?**

air leak

Parts

Quantity

NO PARTS USED

**Task performed:**

TRAVEL TO RIVERWALK LANE - FOUND HOLE IN AIR COMPRESSOR DISCHARGE LINE. INSTALL FITTINGS IN NEW HOSE. INSTALL ON TRUCK. TIE STRAP HOSE TO SECURE. TRAVEL HOME.

**Workorder: V51239**

In Date: 07/31/2012  
Close Date: 08/02/2012

Meter Reading: 164,177.60

**Problem?**

Shoreline a/c and charger inop R16

Parts

Quantity

NO PARTS USED

**Task performed:**

REMOVED AUTO EJECT FOUND PLUG MELTED CUT PLUG OUT OF SYSTEM HARD WIRED CHECKED OPERATION OK.

**Workorder: V51607**

In Date: 08/15/2012  
Close Date: 09/14/2012

Meter Reading:

**Problem?**

pigtail for shore line is shorting out. And the Rescue needs some new wiper blades. R16

Parts

Quantity

**Task performed:**

1. REPLACED WIPER BLADES. 2. REPLACED PLUG FOR PIGTAIL ON SHORE LINE. 3. ADJUSTED SLIDES FOR BIOHAZARD DRAWER. 4. REPLACED BLOWN DOME LIGHT BULBS.

295SLSA6FLSIREN AMP W/PARK WPB	1
322502BULB PATIENT GH22	2
91-22WIPER BLADE	2





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V51752**

In Date: 08/20/2012  
Close Date: 09/24/2012

Meter Reading:

**Problem?**

Styrker stretcher hydraulic lift is inoperable, work request has been forwarded to EMSAR R 16

Parts ----- Quantity -----

**Task performed:**

EMSAR CONTACTED FOR REPAIR.

NO PARTS USED

**Workorder: V52589**

In Date: 09/24/2012  
Close Date: 09/26/2012

Meter Reading:

**Problem?**

rubber boot is torn away, rain/heat are able to filter into the cab. shoreline cable was disconnected from the ceiling while going on a call. no damage to the cable. R 16

Parts ----- Quantity -----

**Task performed:**

REPLACED BOOT BETWEEN CAB AND BODY.

GASK-BEL0110002439 WINDOW BELLOWS 6 IN WID 8

**Workorder: V52673**

In Date: 09/27/2012  
Close Date: 10/01/2012

Meter Reading:

**Problem?**

Possible transmission fluid leak per C shift. R16

Parts ----- Quantity -----

**Task performed:**

TRVL TO 16 CHKED FOR TRANS LEAK NO PROBLEM FOUND.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

### \* ADVANCED LIFE SUPPORT VEHICLE

#### Workorder: V53029

In Date: 10/12/2012  
Close Date: 10/16/2012

Meter Reading:

#### Problem?

R16 low oxygen alarm keeps going off eventhough the M tank is full. Alarm going off even whent he pt is on oxygen. Don't know if it's a sensor problem or line problem

Parts ----- Quantity -----

#### Task performed:

TRAVEL TO 16 REPLACED O2 SENSOR AT TANK.

98032R 41032-3 RED REFLECTOR OVAL REFLECTO	2
AST4000ASENSOR O2 REGULATOR	1

#### Workorder: V53238

In Date: 10/22/2012  
Close Date: 10/22/2012

Meter Reading: 168,296.20

#### Problem?

Engine oil low R16

Parts ----- Quantity -----

#### Task performed:

CHECK AND ADD OIL TO ENGINE VERY LOW ADD 4 QT. TO ENGINE LEVEL 4 QT.

15W40QSYN OIL QT	12
------------------	----

#### Workorder: V52163

In Date: 09/05/2012  
Close Date: 11/08/2012

Meter Reading: 166,114.00

#### Problem?

right rear turn signal on all the time

Parts ----- Quantity -----

#### Task performed:

CHECKED REAR SIGNAL LOOKED FOR BAD GROUND TRUCK GOT CALLED OUT WILL RETURN.

NO PARTS USED	
---------------	--



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V53531**

In Date: 11/05/2012  
Close Date: 11/08/2012

Meter Reading:

**Problem?**

THE STAND THAT HOLDS THE MDT CAME LOSE AND IS NO LONGER ABLE TO SUPPORT UNIT R16

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

CHECKED MDT STANDS IN BOTH TRUCKS? NO PROBLEM FOUND.

NO PARTS USED

**Workorder: V53489**

In Date: 11/02/2012  
Close Date: 11/19/2012

Meter Reading: 169,086.00

**Problem?**

Both outside rear tires are down to the wear bars. R16

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

BOTH OUTSIDE REAR TIRES ARE DOWN TO THE WEAR BARS. R16.

NO PARTS USED

**Vendor?** BOULEVARD TIRE CENTE



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V53571**

**In Date:** 11/06/2012  
**Close Date:** 11/28/2012

**Meter Reading:** 169,086.00

**Problem?**

**C INSPECTION SR 9**

**Task performed:**

1. C INSP 2. FAILED BATT TEST REPLACED 4 BATTS- REPAIR 3 SMALL WIRE ENDS CONNECTOR TO BAT POS AND NEG POST. 3. REPAIR L/REAR INNER DUAL TIRE FLAT INSTALL NEW SHRADDER VALVE FIRST HOOK UP AIR LINE AND WORK TIRE TO CATCH BEAD AND START FILLING FILL TO PROPER LEVEL. 4. REINSTALL BELLOWS BETWEEN CAB AND BOX. 5. TROUBLESHOOT WASHERS INOP FOUND HOSE KINKED AT WASHER BOTTLE. 6. ADJUST AND TIGHTEN LATCHES ON INSIDE CAB CABINET. 7. SERVICE AIR DRYER. 8. FREE UP CLEN AND LUBE BATTERY SLIDE OUT. 9. SERVICE POWER STEERING. 10. REPLACE BOTH SIDE FENDER MARKER/ TS LIGHT ASSEMBLIES. 11. CHECK RIGHT REAR TAIL LIGHT, FOUND BAD FENDER T/S CONNECTOR REPLACED CONNECTOR. 12. R/R MAP LIGHT. 13. REPLACED ALL REAR AND SIDE WARNING LIGHT. 14. CHECK FOR OIL LEAK R/S ENGINE TIGHTEN TURBO OIL RETURN HOSE CLAMPS AND FLANGE. 15. ADJUST AIR HORNS. 16. MOVE TRAILING ARMS TO CENTER AIR BAGS. 17. CHECK FOR AIR LEAKS REPLACE COOLING FAN AIR ELECTRIC SOLENOID REPLACE TOP FITTINGS ON TREADLE VALVE

Parts	Quantity
0000900087DDE/A0000900087 FILTER HEAD SM MEI	1
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
010263488-5010263488-5W CLEARANCE LIGHT LEC	1
14-15612-000GASKET RVR PWR STRG M2	1
1501450007750USE 0775145	1
42809AIR FILTER M2	1
5008414CARTRIDGE DC100	1
6819634283068-1963428-30 LENS CLR	6
68318358710600 SER NON OPTIC AMBER	2
68318358730600 SER LENS NON OPTIC	2
68318358750600 NON OPTIC RED LENS	2
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
A06-40131-000MARKER LIGHT M2 HOOD	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
EL360081760611 SOLENOID AIR HORN	1
HP-31DBATTERY 950CCA HP-31D	4
K022105PURGE VALVE AD-IP-IS	1
LF18TS-LEDMAP LIGHT LED 18 IN	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	1
VML/T1808D2503221C1 FILTER POWER STEERING	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V54430**

In Date: 12/13/2012  
Close Date: 12/14/2012

Meter Reading: 169,809.00

**Problem?**

unit hit bay door r93

Parts ----- Quantity

NO PARTS USED

**Task performed:**

TRAVEL TO ST 93, GARAGE DOOR HANG UP ON ROOF TOP A/C DISASSEMBLE CROSSBAR ON DOOR TO RECIEVE TENSION SO UN COULD PULL OUT OF BAY- INSPECT UNIT NO OUT OF SERVICE DAMAGE INQUIRED-A/C GUARD WILL NEED MINOR REPAIR.

**Workorder: V53505**

In Date: 11/02/2012  
Close Date: 12/19/2012

Meter Reading:

**Problem?**

Front left tire is worn on the outside , Boulevard Tire Technician recommends that it be replaced.

Parts ----- Quantity

NO PARTS USED

**Task performed:**

FRONT LEFT TIRE IS WORN ON THE OUTSIDE, BOULEVARD TIRE TECHNICIAN RECOMMENDS THAT IT BE REPLACED.

Vendor? BOULEVARD TIRE

**Workorder: V54055**

In Date: 11/28/2012  
Close Date: 12/26/2012

Meter Reading: 169,086.00

**Problem?**

NEED SCBA BRACKET FOR DRIVERS SCBA BOTTLE IN MIDDLE COMPARTMENT. R93

Parts ----- Quantity

NO PARTS USED

**Task performed:**

INSTALLED NEW BOTTLE HOLDER IN L-1.



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V54064**

In Date: 11/28/2012  
Close Date: 01/03/2013

Meter Reading:

**Problem?**

R93 needs a mounting strap to secure C02 EXTINGUISHER

Parts	Quantity
-------	----------

**Task performed:**

INSTALLED STRAP FOR EXT.

A0048201010SWITCH DOOR	2
------------------------	---

**Workorder: V54388**

In Date: 12/12/2012  
Close Date: 01/14/2013

Meter Reading:

**Problem?**

repair/replace 110 roof a/c unit. R93

Parts	Quantity
-------	----------

**Task performed:**

WILL NEED TO REPLACE 110 A/C UNIT ONCE UNIT STARTS TO BLOW WARM.

NO PARTS USED	
---------------	--

**Workorder: V54952**

In Date: 01/09/2013  
Close Date: 01/25/2013

Meter Reading: 172,360.00

**Problem?**

2 dome light bulbs out over patient in patient compartment

Parts	Quantity
-------	----------

**Task performed:**

1. REPAIRED DOME LIGHTS. 2. MOUNTED TOOLS IN REAR.

NO PARTS USED	
---------------	--



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V55531**

In Date: 02/04/2013  
Close Date: 02/06/2013

Meter Reading: 173,592.00

**Problem?**

coolant leak

Parts ----- Quantity -----

**Task performed:**

TRAVEL TO LAKE AVE AND 600 BLK. CHECK OUT TRUCK COOLANT HOSE BROKEN R&R HOSE REFILL SYSTEM TEST OK.

NO PARTS USED

**Workorder: V55353**

In Date: 01/28/2013  
Close Date: 02/08/2013

Meter Reading:

**Problem?**

air dump system

Parts ----- Quantity -----

**Task performed:**

TRAVEL TO ST 93 CHECK OUT AIR RIDE SYST ADJUST VALVES RETEST OK.

NO PARTS USED

**Workorder: V55988**

In Date: 02/25/2013  
Close Date: 02/26/2013

Meter Reading:

**Problem?**

Warm A/C front and rear. r93

Parts ----- Quantity -----

**Task performed:**

1. CHECK CAB A/C. RECOVER FREON OVER 1LB LOW LEAK TEST REPLACE HOSE INSIDE CONDENSEOR UNIT MAKE HOSE EVACUAT AND RECHARGE. 2. CHECK PATIENT A/C BLOWING AT 48 DEGREES CONDENSOR FAN WORKING NORMAL RUN SYSTEM FOR 1/2 HR NC FAILURE.

08-6062BUSE 08-6962BS FITTING A/C 4403 SB1302	1
16-31498925 VALVE CORE	1
4411S08-6962BS 90 DEGREE SB1322	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V55289**

**In Date:** 01/25/2013  
**Close Date:** 03/05/2013

**Meter Reading:** 173,212.00

**Problem?**

The back up camera in R93 is not working. There just pixalated lines that run vertical that do not change when new objects are introduced into the camera's sight.

**Parts** ----- **Quantity** -----

**Task performed:**

1. 110 A/C TESTED UNIT AND TESTED OK REINSTALLED NEW SCREWS. 2. WILL NEED TO REPLACE BACK-UP-CAMERA.

NO PARTS USED

**Workorder: V55327**

**In Date:** 01/27/2013  
**Close Date:** 03/05/2013

**Meter Reading:** 173,592.00

**Problem?**

It seems we have a leak in our air system. Every time we start up the air warning light comes on for no more than 30 seconds. Also the truck automatically dumps in neutral without back doors open. R93

**Parts** ----- **Quantity** -----

**Task performed:**

DIAGNOSED ELECTRICAL PROBLEM TO BE BAD DOOR SWITCH INSTALLED NEW DOOR SWITCH IN REAR OF TRUCK TESTED OK.

NO PARTS USED





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V56084**

**In Date:** 03/01/2013  
**Close Date:** 03/06/2013

**Meter Reading:** 175,497.40

**Problem?**

AC compressor smoking from under the hood.

**Task performed:**

1. FOUND CAB A/C COMPRESSOR BAD - FOUND LOW SIDE SERVICE PART LEAKING. RECOVER FREON - REMOVE LINES, BELT AND COMPRESSOR ADJUSTED NEW COMPRESSOR OIL LEVEL. 2. REPLACED BACK CAMERS. (INOP) HAD TO REPAIR BROKEN TERMINALS ON NEW CAMERA. 3. SECURED GROUND LIGHT UNDER LEFT REAR STEP AND REPAIRED WIRES. 4. REPAIR CAB A/C CONT REPLACED A/C COMPRESSOR-FOUND LOW SIDE SERVICE PORT SCHRADER CORE LEAKING - R&R CORE - LEAK TEST STILL LEAKING - R&R CORE AGAIN STILL LEAKING REMOVED LINE - LINE LEAKING. 5. REPAIR CAB A/C - REMOVED SUCTION LINE FROM EEP VALVE TO COMPRESSOR. CUT OFF LEAKING FITTING - WENT TO MAKE HOSE HAD HOSE REPAIRED - RETURN - INSTALLED HOSE - VAC AND CHARGE A/C - CHECK OK. 6. ASSISTED WITH A/C REPAIRS. ALSO WENT TO MAKO TO HAVE A/C HOSE REPAIRED. 7. ASSISTED WITH A/C REPAIR.

Parts	Quantity
16-3148VALVE CORE A/C 8926	1
16-31498925 VALVE CORE	3
431034HOSE & FITTING ASSY	1
431240HOSE & FITTING ASSY	1
533303-0609 A/C COMPRESSOR M2 4485	1
719707-0614A AC DRIER M2	1
CVC460MICAMERA	1
RD-5-7063-OP07-2618A A/C DRIER 7155	1

**Workorder: V56229**

**In Date:** 03/07/2013  
**Close Date:** 03/11/2013

**Meter Reading:** 175,497.40

**Problem?**

a/c blowing warm

**Task performed:**

1. WENT TO 93 FOUND SYSTEM LOW LOW SIDE SERVICE PART LEAKING - RESCUE WENT ON A CALL. 2. WENT TO 93 FOUND SYSTEM EMPTY - REMOVED AND CLEANED LOW SIDE SERV. PART CHARGE A/C - CHECK OK.

Parts	Quantity
16-3148VALVE CORE A/C 8926	1
16-31498925 VALVE CORE	1
VCC/35000003BLOWER MOTOR VCCT1000904A M2	1
VCC/83000038AC WIRE HARNESS	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

### \* ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V55724**

In Date: 02/12/2013  
Close Date: 03/15/2013

Meter Reading: 174,691.70

**Problem?**

the first clear dome line closest to the cab on the passengers side is burnt out.

Parts ----- Quantity -----

**Task performed:**

1. REPLACED WIPERS. 2. REPAIRED AIR LEAK.

91-22WIPER BLADE	2
------------------	---

**Workorder: V55926**

In Date: 02/22/2013  
Close Date: 03/15/2013

Meter Reading: 175,277.00

**Problem?**

Rescue 93...10163702 Air conditioning not working in front cab

Parts ----- Quantity -----

**Task performed:**

DECHARGED SYSTEM.

NO PARTS USED	
---------------	--

**Workorder: V56035**

In Date: 02/27/2013  
Close Date: 03/15/2013

Meter Reading: 175,497.40

**Problem?**

AC UNIT IN FRONT CAB IS NOT WORKING. WAS JUST IN THE SHOP FOR SAME KIND OF INCIDENT YESTERDAY 02/25/13. TIME IS 02:15 AM HOURS R93

Parts ----- Quantity -----

**Task performed:**

1. RECHARGED UNIT AND CHECKED FOR LEAKS. 2. INSTALLED NEW BLOWER MOTOR.

VCC/35000003BLOWER MOTOR VCCT1000904A M2	1
VCC/83000038AC WIRE HARNESS	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V56441**

In Date: 03/16/2013  
Close Date: 03/19/2013

Meter Reading: 176,380.20

**Problem?**

The AC compressor froze up and a belt broke while enroute to a call. The overheat light came on and temp rose above 220. R93 towed to the shop.

**Task performed:**

ENGINE OVER HEATING/ A/C COMP CLUTCH BURNT AND CAME APART/ TOW BACK TO STATION GO TO SHOP AND GET SPARE.

Parts

Quantity

NO PARTS USED

**Workorder: V47809**

In Date: 03/07/2012  
Close Date: 04/08/2013

Meter Reading: 156,775.00

**Problem?**

repalce wiper/turn signal switch. replace wiper blades

**Task performed:**

Parts

Quantity

91-22WIPER BLADE	2
A06-36956-000A06-36956-003 WIPER-TURN SWITCH	1
A06-75732-004HEADLAMP LH M2	1

**Workorder: V51927**

In Date: 08/27/2012  
Close Date: 04/08/2013

Meter Reading: 165,902.00

**Problem?**

ENGINE OIL SAMPLE SR9 @ ST16

**Task performed:**

Parts

Quantity

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V56019**

In Date: 02/26/2013  
Close Date: 04/10/2013

Meter Reading: 175,497.40

**Problem?**

BACK UP CAMERA IS NOT WORKING AT ALL. VERTICAL LINES  
ACROSS THE MONITOR SCREEN WHEN PLACING VEHICLE INTO  
REVERSE

Parts ----- Quantity -----

**Task performed:**

REPAIRED BAD CONNECTION IN CABLE.

NO PARTS USED

**Workorder: V56021**

In Date: 02/26/2013  
Close Date: 04/10/2013

Meter Reading: 175,497.40

**Problem?**

NEED BRACKET FOR PIKE POLE.

Parts ----- Quantity -----

**Task performed:**

NEED TO CONTACT DC TO GET NEW PIKE POLE

NO PARTS USED

**Workorder: V56336**

In Date: 03/12/2013  
Close Date: 04/10/2013

Meter Reading: 176,380.20

**Problem?**

Front AC was recharged in the morning. By the afterooen, the front A/C was  
already blowing warm air. Possible leak in the system. R-93

Parts ----- Quantity -----

**Task performed:**

CHECKED A/C AND RECHARGED AND SENT TO SHOP.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V56503**

In Date: 03/19/2013

Close Date: 04/15/2013

Meter Reading: 176,380.20

**Problem?**

B inspection R93

Parts

Quantity



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

### \* ADVANCED LIFE SUPPORT VEHICLE

#### Task performed:

1. DIAGNOSE A/C FAILURE - COMPRESSOR SEAZED UP FOUND EVAPORATION LEAKING FREON - DRAIN COOLANT; INORDER TO G ACCESS TO EVAPORATOR - REMOVE EVAPOR, BOLT EXPANSION VALVE AND DRYERS, RIGHT FENDER - REPLACE ALL COMPONENT: AFTER FLUSHING SYSTEM RECHARGE. REASSEMBLE. 2. B-INSPECTION; SECURE LOOSE HANGING UNDER CARRAGE CABLES. 3. 110 A/C INOP - REMOVE COVER DIAGNOSE FAULT. FOUND CONDENSOR FAN FAILURE REMOVE FAILED UNIT - BENCH TEST DNI UNIT FROM BLDG 3 UNIT WORKS AND COOL TO 38 DEGREE INSTALL IN RESCUE AND OPERATE, UNIT WORKING TO SPECS. 4. REAR BRAKES - REMOVE WORN BRAKE SHOES AND DRUM - INSTALL NEW SHOES, DRUMS AND ADJUST SLACK ADJUSTER TO NEW SPECS. 5. LEFT FRONT SPRING MOUNT BRACKET NUT AND BOLT LOOSE - SECURE AND TORQUE LOOSE NUT AND BOLT FOR SPRING MOUNT BRACKET. 6. OIL LEAK AND TURBO SUPPLY LINE - REMOVE- AIR CLEANER AND SUPPLY LINES AND TURBO, CLEAN AREA AND SECURE LOOSE LINE - REASSEMBLE AND OPERATE. 7. CAB TO MODULER BOX PARTICIAN SEPERATED - REMOVE BOOTH CLEAN AREA, APPLY ADHESIVE AN REASSEMBLE. 8. ACCROIES REPAIR; NIGHT ROLE LIGHT INOP; PATIENT COMP. UV BULB BLOWN; PATIENT COMP A/C FILTER; PATIENT COMP EXHAUST LOWER BROKEN; WINDSHIELD WIPER BLADE AND FLUID BOTTLE EMPTY REPAIR, REPLACE AND CORRECT FAULTS. 9. MODULE BOX LEFT REAR LEANS - ADJUST LEVELING ROD. 10. AA0 A/C ROOF MOUNTED SUPPORT CAGE DAMAGE - MSTRAIGHTEN SUPPORT AND DIMOND PLATE SHEET METAL, CLEAN FOR REASSEMBLE AND WELD. 11. ROAD TEST AFTER BRAKE JOB, FRONT CHASSIVE SPRING MOUNT RETORQUE TURBO OIL LEAK AND CAB A/C REPAIRS. 12. LEFT REAR CAB DOOF GROUND LIGHT INOP - REMOVE LIGHT ASSEMBLY AND INSTALL NEW LIGHT. 13. MODULAR BOX R & L COMPARTMENTS DOOR PANELS FALLING OFF AND REAR DOOR WINDOWS SCREWS MISSING - SECURE DOOR PANEL AND GLASS MOD DOWN SCREWS - INSTALL NEW SCREWS WHERE NEEDED. 14. PERFORM Q & A INSPECTION. 15. WELD BRACKET BACK ON TOP OF A/C UNIT.

0000900087DDE/A0000900087 FILTER HEAD SM MEI	1
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
01-29866-118BELT ALT. M2	1
0106837849C8COMP LIGHT WHITE LED 200	1
1501450007750USE 0775145	1
16-34465580 CAP-BLACK R134A	1
160012-2012A EXPANSION VALVE 71R8301	1
161812-0617A EXPANSION VALVE VCC88000030	1
18300YMARKER LIGHT YELLOW	2
360708LOUVER A/C BOX SUTPHEN	1
3744BRAKE DRUM REAR	2
432541HOSE AND FITTING	1
432639HOSE AND FITTING	1
533303-0609 A/C COMPRESSOR M2 4485	1
719707-0614A AC DRIER M2	1
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2
RD-5-7063-OP07-2618A A/C DRIER 7155	1
S153BLOW GUN	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
SAHSVS2510STRAP	1
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1
VCC/36000006A/C FILTER CAB M2	1
VCC5000003105-0615 EVAPORATOR	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V46577**

In Date: 01/14/2012  
Close Date: 04/29/2013

Meter Reading:

**Problem?**

stretcher on R47 is not working. the battery was changed 3 times last night and it had to be manually operated with the trigger.

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

NO PARTS USED

**Workorder: V57393**

In Date: 05/01/2013  
Close Date: 05/02/2013

Meter Reading: 179,188.00

**Problem?**

Brake problem R93

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

1. TRAVEL TO ST 93 CHECK OUT BRAKES ADJUST FRONT AND TES DRIVE OK.

NO PARTS USED

**Workorder: V57454**

In Date: 05/03/2013  
Close Date: 05/16/2013

Meter Reading:

**Problem?**

Ferno stretcher asset #10180672 charger clips broke. The charger clips into the battery and both chargers at St93 have broken clips.

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

TRAVEL TO ST 93 CHECK OUT STRETCHER ECT. NEED EMSR TO REPLACE ALL SHOP GET REPAIRED.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V57672**

In Date: 05/12/2013  
Close Date: 05/20/2013

Meter Reading:

**Problem?**

WHEN PLUGGING SHORE LINE INTO THE RESCUE, IT'S TRIPPING TH  
BREAKER SWITCH THAT IT'S CONNECTED TO

Parts ----- Quantity -----

**Task performed:**

CHECK OUT 110V A/C STATION BRAKER IS BAD LET BUILING MAINT  
RENEW.

NO PARTS USED

**Workorder: V57673**

In Date: 05/12/2013  
Close Date: 05/20/2013

Meter Reading:

**Problem?**

A/C IS BLOWING, BUT NOT COLD IN FRONT CAB OF RESCUE TRUCK.  
COMPRESSOR IS ON, BUT NO COLD AIR AT ALL!

Parts ----- Quantity -----

**Task performed:**

1. CHECK OUT A/C SYST LINES FANS ECT FREON ADD SOME  
PRESSURE OK. 2. CHEK COOLING SYST ADD FLUID TIGHTEN LOOS  
CLAMPS.

ALA00350-50 EXTENDED LIFE COOLANT GAL 2

**Workorder: V57951**

In Date: 05/24/2013  
Close Date: 05/29/2013

Meter Reading:

**Problem?**

Main AC in front cab not blowing cool or cold air. The system has declined  
since Monday when the AC was accually blowing cool.

Parts ----- Quantity -----

**Task performed:**

1. CAB A/C INOP FOUND HOSE CLAMP LEAKING. INSTALL NEW  
HOSE FITTING , DRYER VAC. CHANGE SYSTEM FREOM. 2. REAR PA  
COMP DOOR LOCK- REMOVE DOOR PANEL REPLACE BROKEN LOC  
AND REASSEMBLED.

438280HOSE & FITTING ASSY 1  
4507SFITTING AC SB1312-3 1  
LTC594211657-16 LATCH L/H MEDIC MASTER 1  
RD-5-7063-OP07-2618A A/C DRIER 7155 1





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V57892**

In Date: 05/22/2013  
Close Date: 05/30/2013

Meter Reading:

**Problem?**

The AC is not blowing cold. The air from the AC is cool and has decline since the last time freon was added.

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

TRAVEL TO ST 93 A/C FREON LOW CHARGE TO GET COMPRESSOR TO WORK. SEND TO SHOP.

NO PARTS USED

**Workorder: V58220**

In Date: 06/05/2013  
Close Date: 06/12/2013

Meter Reading: 181,467.90

**Problem?**

A/C IS INTERMITTENT AND WHEN IT KICKS OFF, RPMS WITH ENGINE JERK TRUCK BACK AND FORTH LIKE THE TRANSMISSION IS SHIFTIN GEARS! R93

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

CHECK CAB A/C OK NO PROBLEM FOUND AT THIS TIME. CHECKED TRANS FLUID. (OK)

NO PARTS USED

**Workorder: V58221**

In Date: 06/05/2013  
Close Date: 06/12/2013

Meter Reading: 181,467.90

**Problem?**

WHEN PLACING TRUCK INTO REVERSE, BACK UP CAMERA IS NOT TURNING ON AND BACK UP SOUND/BEEP IS NOT WORKING EITHER r93

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

TRAVEL TO STA 93 - CHECKED BACK UP CAMERA AND ALARM. OK NO PROBLEM AT THIS TIME.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V58431**

**In Date:** 06/14/2013  
**Close Date:** 06/17/2013

**Meter Reading:**

**Problem?**

Returned back from 56320, the both front AC units started blowing warm ai  
The AC was shut off and windows put down. A strong electrical burning  
smell was noted.

**Parts** ----- **Quantity** -----

**Task performed:**

REMOVED AND REPLACED CAB A/C COMPRESSURE- RAN UNIT AN  
ALL TESTED OK.

533303-0609 A/C COMPRESSOR M2 4485	1
A22-60416-001AC HOSE	1

**Workorder: V57968**

**In Date:** 05/25/2013  
**Close Date:** 07/03/2013

**Meter Reading:** 181,274.30

**Problem?**

can diesel engine be reprogrammed for a little more horsepower, truck very  
very slow climbing I-95 hill and starting off from a dead stop. needs better  
aceleration.

**Parts** ----- **Quantity** -----

**Task performed:**

TRAVEL TO ST 91 CHECK OUT INTAKE PIPING AND HOSES FOR  
TEARS ETC. SET UP LAP TOP, CHECK CODES TRY TO SET MOTOR  
TO 800 A.P. DIDN'T WORK DEFAULT SEETINGS.

NO PARTS USED	
---------------	--

**Workorder: V58451**

**In Date:** 06/15/2013  
**Close Date:** 07/19/2013

**Meter Reading:** 181,994.60

**Problem?**

blinker/wiper switch replacement R 93

**Parts** ----- **Quantity** -----

**Task performed:**

TRAVEL TO ST 93 R&R STEERING COLUMN R&R MULTY FUNCTION  
SWITCH AND TEST OK.

A06-36956-000A06-36956-003 WIPER-TURN SWITCH	1
--	---



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V59077**

In Date: 07/15/2013  
Close Date: 07/19/2013

Meter Reading: 184,436.00

**Problem?**

MECHANIC WAS HERE YESTERDAY AND STATED A/C UNIT IN REAR (110) NEEDS TO BE REPLACED. ALSO A/C IN FRONT CAB NEEDS FREON.R93

Parts ----- Quantity -----

**Task performed:**

SHORELINE BURNT/110 A/C DRAWING TOO MANY AMPS/REPAIRED SHORELINE AND DISCONNECTED 110 CHECK A/C.

NO PARTS USED

**Workorder: V59118**

In Date: 07/16/2013  
Close Date: 07/19/2013

Meter Reading: 184,436.00

**Problem?**

Shoreline connector burnt R93

Parts ----- Quantity -----

**Task performed:**

REPAIRED ON 59077

NO PARTS USED

**Workorder: V59072**

In Date: 07/14/2013  
Close Date: 08/09/2013

Meter Reading: 184,436.00

**Problem?**

Went to disconnect the shore line from truck for daily truck check. Shore line (cable) was extremely hot to the touch. So went to remove it from plug of truck and it was smoking! Burning smell was noted afterwards. R 93

Parts ----- Quantity -----

**Task performed:**

1. BEGAN CHANGING OUT 110V A/C ROOF UNIT. 2. CONTINUED/COMPLETED REPLACEMENT OF 110V A/C ROOF UNIT.

63152HVAC UNIT ROOF MOUNTED 1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V59279**

In Date: 07/23/2013  
Close Date: 08/09/2013

Meter Reading: 185,064.00

**Problem?**

NEED NEW BRACKETS FOR THE NEW YORK HOOK. DOESN'T FIT THE CURRENT BRACKETS THAT ARE THERE NOW. NEED (SMALL)BRACKETS. OUR HOOK DOESN'T HAVE THE PADDING ON IT, THEREFORE, FALLS OUT OF TRUCK WHEN OPENING DOOR!!

Parts ----- Quantity -----

**Task performed:**

1. REMOVED OLD BRACKETS FOR N.Y. HOOK. INSTALLED BRACKETS SO HOOK BE SECURED WHEN DOOR IS OPENED (L-4 COMPARTMENT) 2. ALSO IN L-4 COMPARTMENT, STRAIGHTENED AND TIGHTENED SHELVES. (LOOSE/CROOKED)

Parts	Quantity
5269LPVM-5 SM MOUNT	1

**Workorder: V59699**

In Date: 08/09/2013  
Close Date: 08/13/2013

Meter Reading: 144,550.30

**Problem?**

repalce 4 rear tires

Parts ----- Quantity -----

**Task performed:**

REPLACE 4 REAR TIRES.

NO PARTS USED	
---------------	--

Vendor? BOULEVARD TIRE CENTE



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

### \* ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V59380**

**In Date:** 07/26/2013

**Meter Reading:** 185,064.00

**Close Date:** 08/14/2013

**Problem?**

C inspection R93

**Task performed:**

1. PERFORM "C" INSPECTION. 2. SERVICED AIR BRAKE DRYER. 3. REPLACED FRONT CAB A/C FILTER. 4. REPLACED REAR CAB A/C FILTER. 5. REPLACED PATIENT COMPARTMENT A/C FILTER. 6. REPLACED WIPER BLADES, CLEANED DEBRIS FROM WINDSHIELD WASHER SQUIRTER ON PASSENGER SIDE AND TOPPED OFF WASHER RESERVIOR. 7. REPLACED TOP, RIGHT, FRONT BODY MARKER LIGHT. (BURNT OUT) 8. REPLACED LEFT REAR CAB DOOR SILL/THRESHOLD. (BROKEN) 9. PAINTED FUEL CAP. 10. REPLACED ALL 4 REAR TIRES (WORN OUT) WITH 4 TIRES FROM BILDING 3. 11. REGAN REPLACING DASHBOARD FRAME. (BROKEN AROUND PARK BRAKE VALVE). 12. CONTINUED/COMPLETED DASHBOARD FRAME REPLACEMENT. 13. TROUBLESHOOT LEFT REAR CAB DOOR WINDOW INOP. REMOVED DOOR PANEL AND TRACED PROBLEM TO FAULTY WINDOW MOTOR. ORDERED NEW PART. 14. CONTINUED DOOR WINDOW REPAIR. PART WILL NOT BE HERE FOR A WEEK OR TWO. SMACKED WINDOW MOTOR AND GOT WINDOW TO GO UP AND DOWN. REINSTALLED DOOR PANEL. 15. SERVICED P/S SYSTEM. DRAINED FLUID, REPLACED FILTER, TOPPED OFF RESERVIOR AND PURGED AIR FROM SYSTEM. 16. REATTACHED HINGE ASSEMBLY IN L-3 COMPARTMENT. 17. REPLACED SIGN/NUMBER PLACARDS AND FRAMES. REMOVED OLD FRAMES, USE ERASER TO REMOVE DOUBLE STICK TAPE, MOUNT NEW FRAMES. 18. CONTINUED SIGN/NUMBER PLACARDS AND FRMAES. MADE UP NO SIGNS WITH NEW NUMBERS AND INSTALLED. 19. Q.A INSPECTION CHECK OK.

**Parts**

**Quantity**

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
1501450007750USE 0775145	1
18-46375-00018-46375-004 TREAD PLATE LH M2	1
22-63282-000DASH REINFORCMENT	1
5008414CARTRIDGE DC100	1
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
A22-62508-000UPPER DASH	1
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
E-600013-3052 NUT	1
K022105PURGE VALVE AD-IP-IS	1
L PLACARDLARGE SIDE PLACARD	2
L PLACARD INSERTLARGE PLACARD INSERT CAR	2
S PLACARDFRONT AND BACK PLACARD	2
S PLACARD INSERTFRONT AND BACK INSERT CAR	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
S777COUPLING NIPPLE	1
VCC/36000006A/C FILTER CAB M2	1
VML/T1808D2503221C1 FILTER POWER STEERING	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V59730**

In Date: 08/11/2013  
Close Date: 08/15/2013

Meter Reading: 144,550.30

**Problem?**

a/c warm front and rear, just got back from pm. R93

**Task performed:**

TRAVEL TO ST 93 CHECK OUT A/C PRESSURES GOOD COMP. 2 MONTH OLD WORKING OK. DR. SAID NO PROBLEMS PROBLEM UNFOUNDED.

Parts

Quantity

NO PARTS USED

**Workorder: V59942**

In Date: 08/20/2013  
Close Date: 09/04/2013

Meter Reading: 185,709.20

**Problem?**

slow air leak for the air brakes R93

**Task performed:**

1. TRAVEL TO ST 93 CHECK OUT AIR LEAK COULDN'T TAKE TRUCK OUT THEY GOT CALL WAIT FOR TRUCK TO GET BACK. GET OUT OF SERVICE PULL DASH ETC. CHECK FOR LEAKS FOUND LEAK ON BRAKE VALVE R&R FITTING WILL GO BACK AND RECHECK LATER.  
2. FOUND L/R BRAKE NOT WORKING PIN FOR ADJUSTING ROD MISSING ADJUST BRAKE INSTALL PIN IN AUTO ADJUST ROD.

Parts

Quantity

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V60029**

In Date: 08/26/2013  
Close Date: 09/05/2013

Meter Reading: 186,327.40

**Problem?**

TRUCK IS NOT RETAINING AIR PRESSURE. PSI IS LESS THAN 50 PSI WHEN TRUCK STARTS UP AND HAVE TO BUILD UP PRESSURE BEFORE PULLING OUT OF STATION CAUSING CARCINOGENS TO BUILD UP IN THE BAY.

Parts ----- Quantity -----

**Task performed:**  
REPAIRED ON W.O. #59942.

NO PARTS USED

**Workorder: V59767**

In Date: 08/13/2013  
Close Date: 09/11/2013

Meter Reading: 144,550.30

**Problem?**

NEW YORK HOOK NEEDS BRACKETS. WHEN OPENING COMPARTMENT, IT FALLS (OUT) OF THE COMPARTMENT CAUSING / SAFETY HAZARD!

Parts ----- Quantity -----

**Task performed:**  
MOUNT ANY HOOK IN BACK BOARD COMPT.

NO PARTS USED

**Workorder: V60480**

In Date: 09/13/2013  
Close Date: 09/19/2013

Meter Reading: 187,358.50

**Problem?**

Air leak

Parts ----- Quantity -----

**Task performed:**  
TRAVEL TO H.Q. CHECK OUT AIR LEAK ON TRUCK FOUND DRYER LEAKING NEEDS REPLACED SEND TRUCK TO SHOP FOR REPAIR.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V60486**

In Date: 09/13/2013  
Close Date: 09/19/2013

Meter Reading: 187,358.50

**Problem?**

Air leak

Parts ----- Quantity -----

**Task performed:**

AIR LEAK - AIR NOT BUILDING FAST - REMOVE DRYER AND PURGE ASSEMBLY INSTALL NEW DRYER ASSEMBLY - OPERATE SYSTEM AIR FAULT CORRECTED.

801330DRIER ASSBLY AD-IS 5011074 5011075	1
--	---

**Workorder: V60614**

In Date: 09/19/2013  
Close Date: 09/23/2013

Meter Reading: 187,942.00

**Problem?**

PSI LEAK CAUSING A DELAY IN RESPONSE TIME FOR EMERGENCY CALLS. WHEN TRUCK STARTS UP, PSI AT 25 ON GUAGE! NEEDS TO BE FIXED!

Parts ----- Quantity -----

**Task performed:**

1. TRAVEL TO ST 93 CHECK AIR LEAK COMPLAINT SPRAY CONNECTIONS ETC. WITH SOAP AND WATER USE LEAK EAR CHECKER CAN'T FIND LEAK CREW WANTING TO SWAP OUT OK TRUCK TILL REPAIRED.

91-22WIPER BLADE	2
------------------	---

**Workorder: V57939**

In Date: 05/23/2013  
Close Date: 10/09/2013

Meter Reading:

**Problem?**

Cab AC is not blowing cold air at all.

Parts ----- Quantity -----

**Task performed:**

REPAIRED ON WO V58431.

NO PARTS USED	
---------------	--





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V61007**

In Date: 10/04/2013  
Close Date: 10/09/2013

Meter Reading: 187,942.00

**Problem?**

Air pressure leaks

**Task performed:**

1. AC LEAK-USE OF ULTRASONIC TESTOR UNABLE TO FIND LEAK-  
DISASSEMBLE DASH, CHECK ALL AC OPERATED PARTS AND  
FITTING/ CONNECTION/TUBES FOUND LEVELING VALVE  
LEAKING.REMOVE BOLT AND INSTALL 2 NEW VALVE AND ADJUST  
ROD FOR HEIGHT.

Parts ----- Quantity -----

S4640024430VALVE LEVELIN	2
--------------------------	---

**Workorder: V60990**

In Date: 10/04/2013  
Close Date: 10/10/2013

Meter Reading: 187,942.00

**Problem?**

Air leak

**Task performed:**

TRAVEL TO ST 93 CHECK OUT AIR LEAKS FOUND LEAK AT HORN  
VALVE REPAIR TEST STILL LEAKING SEND BACK TO SHOP.

Parts ----- Quantity -----

NO PARTS USED	
---------------	--



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V60761**

**In Date:** 09/24/2013

**Meter Reading:** 187,942.00

**Close Date:** 10/15/2013

**Problem?**

REPLACE WINDOW REGULATOR R93

Parts

Quantity

**Task performed:**

1. DIAGNOSE REGULATOR DISASSEMBLE DOOR - REMOVE GLASS AND REGULATOR PARTS ON ORDER. 2. DRIVER DOOR FOOT MOLDING BROKEN - REMOVE AND INSTALL NEW MOLDING. 3. DRIVER DOOR OPEN SWITCH BROKEN - REMOVE AND INSTALL NEW SWITCH. 4. ENGINE COMP. NOISE - NOISE UNDETERMINE AFTER ROAD TEST. ALL EQUIPMENT OPERATING NORMAL UNIT TO GO BACK IN SERVICE AS PER E. EHRKE.

Parts	Quantity
A18-58283-000WINDOW REGULATOR L/H A18-4274:	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V60888**

**In Date:** 09/30/2013  
**Close Date:** 10/22/2013

**Meter Reading:** 187,942.00

**Problem?**

air leaks/check tires/check pat a/c

**Task performed:**

1. CAB A/C NOT BLOWING COLD CHECK FREON-LOW ON FREON-N  
LEAK FOUND CHARGE SYSTEM, OPERATING WITHIN  
SPECS-CODING TO 360. 2. CHECH TIRE PRESSURES AND TIRES  
AIRED TO PROPOSED SPECS, REARS ARE NEW - FRONT ARE IN  
RANGE OF SPECS. 3. PACENT A/C INOP - LOW ON FREON SYSTEM  
LEAKING RECOVER AND CHECK FOR LEAK - VACUUM TEST PASS -  
CHARGE AND OPERATE UNIT - COOLING TO 35 DEGREE  
PRESSURES GOOD. REASSEMBLE. 4. CAB A/C REAR FAN INOP -  
DIAGNOSE FAULT FOUND WIRE HARNESS CUT AT POWER SOURCI  
NO FUSE IN SYSTEM - FUSE WITH 15 AMP FUSE AND REPAIR  
BROKEN WIRE. 5. AIR LEAK DIAGNOSE AIR LEAK FOUND ABS 3  
VALVE PACK ASSEMBLE LEAKING - REMOVE AIR LINES,  
ELECTRICAL SENSOR LINE AND REMOVE VALVE INSTALL NEW  
VALVE AND REASSEMBLE. FOUND COMPRESSOR TO DRYER LINE  
LEAKING REMOVE AND MAKE REPLACEMENT LINE - INSTALL.

Parts	Quantity
18-46375-00018-46375-004 TREAD PLATE LH M2	1
27-102A22-54259-000 DOOM LIGHT SWITCH M2	1
472-500-121-0ABS ASSBLY	1
MO14830MO14830 GROMET	1

**Workorder: V61404**

**In Date:** 10/21/2013  
**Close Date:** 10/30/2013

**Meter Reading:**

**Problem?**

INSIDE DOOR HANDLE TO OPEN DOOR TO GET OUT OF FRONT CAB  
BROKEN ON OFFICERS SIDE OF RESCUE TRUCK R93

**Task performed:**

TRAVEL TO ST-93 FOR BROKEN DOOR HADNLE R&R HANDLE ON  
PASS DOOR.

Parts	Quantity
A18-46490-000DOOR HANDLE M2	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V61663**

In Date: 10/30/2013  
Close Date: 11/07/2013

Meter Reading:

**Problem?**

CO MONITOR SCREW CLIP WAS LOOSE AND DETACHED ITSELF FROM THE MONITOR ON A CALL. NO WAY TO MONITOR CO LEVELS THE AIR WHILE ON A CALL DUE TO CLIP BEING BROKEN.

Parts ----- Quantity -----

**Task performed:**

1. TRAVEL TO ST-93 BROKEN CO2 MONITOR FIND BOLT TO FIT UNI R&R BOLT AND LOCK TIGHT IN.

NO PARTS USED

**Workorder: V61781**

In Date: 11/05/2013  
Close Date: 11/14/2013

Meter Reading:

**Problem?**

The main O2 has a leak in the system. Possibly the manual bypass switch, knob is very loose. We have replaced the main O2 twice this week.

Parts ----- Quantity -----

**Task performed:**

TRAVEL TO ST-93 CHECK O2 LEAKING CHECK FITTINGS ON TANK AND IN WALL CHECK VALVE NO LEAKS OUSH IN FLOW METERS LEAKING LET CAP KNOW.

NO PARTS USED

**Workorder: V61931**

In Date: 11/11/2013  
Close Date: 11/22/2013

Meter Reading:

**Problem?**

OXYGEN FROM MAIN D TANK IS LEAKING CAUSING US TO HAVE TO SHUT IT OFF AFTER EACH USE! HAVING TO REPLACE BIG O2 TANKS ALMOST EVERY OTHER SHIFT DUE TO LEAK. R93

Parts ----- Quantity -----

**Task performed:**

ALREADY REPLACED ON ANOTHER WO VALVE LEAKING THEY SAII THEY WOULD REPLACE.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V61930**

In Date: 11/11/2013  
Close Date: 12/12/2013

Meter Reading:

**Problem?**

RIGHT REAR BOTTOM EMERGENCY STROBE IS OUT ON VEHICLE WHEN GOING CODE 3 TO CALL. NEEDS TO BE REPLACED. THANK YOU!! :) R93

Parts ----- Quantity -----

**Task performed:**

CHECK OUT LT OUT TEST FOR POWER AND GROUND FOUND LT B/ R&R LIGHT AND REWIRE.

50R03ZCRLIGHT LED RED TIR 6	1
TRANSYND-GGAL CONTAINER TRANS FLUID	1

**Workorder: V62434**

In Date: 12/03/2013  
Close Date: 12/12/2013

Meter Reading:

**Problem?**

FLASHLIGHT BOX CHARGERS ARE NOT BEING TURNED ON TO CHARGE BOX LIGHTS WHEN RESCUE IS BOTH ON OR OFF WITH BATTERY. 1 CHARGER IS IN THE FRONT CAB BEHIND DRIVERS SEAT 2 OTHERS ARE LOCATED DRIVERS SIDE COMPARTMENT.

Parts ----- Quantity -----

**Task performed:**

TRAVEL TO ST-93 CHECK LT BOX CHARGES FOUND NO POWER ON UNITS CHECK WIRING PULL R&R . CONSOL FOUND FUSE BLOWN R&R FUSE TEST OK.

NO PARTS USED	
---------------	--



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V62537**

In Date: 12/06/2013  
Close Date: 12/18/2013

Meter Reading:

**Problem?**

steering wheel stuck in up position.

**Task performed:**

TRAVEL TO ST-93 STEERING WHEEL STUCK PULL OFF COVERS ON COLUMN CHECK LINKAGE ECT MISSINGSPRINGS INSTALL REBUILD KIT FOR WHEEL ADJUSTMENT TEST OK.

Parts	Quantity
RGT-452258FFOOT PEDAL STERRING COLUMN	1
RGT401737ESPRING PEDAL RETURN	1
RGT401741CRETURN SPRING	1

**Workorder: V63841**

In Date: 01/30/2014  
Close Date: 01/31/2014

Meter Reading: 194,547.70

**Problem?**

replace front tires R93

**Task performed:**

REPLACE FRONT TIRES R93

Parts	Quantity
NO PARTS USED	

Vendor? BOULEVARD TIRE



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V63780**

In Date: 01/28/2014  
Close Date: 02/13/2014

Meter Reading:

**Problem?**

OXYGEN THAT IS SUPPLIED TO HOOK UPS IN PATIENT COMPARTMENT LEAKS FROM THE MAIN D CYLINDER TANK TO THE ACTUAL PORTS IN THE PASSENGER COMPARTMENT. HAVE TO TURN ON AND OFF EVERYTIME IT'S USED FOR PATIENT CARE.

Parts ----- Quantity -----

NO PARTS USED

**Task performed:**

TRAVEL TO ST-93 CHECK OXY LEAK SPRAY ALL CONNECTIONS IN TRUCK AND IN WALL. NO LEAK FOUND, FLOW MELTER LEAKING, TOLD DR TO GET NEW ONE.

**Workorder: V64127**

In Date: 02/11/2014  
Close Date: 02/13/2014

Meter Reading:

**Problem?**

battery on stretcher die rapidly has to be on constant charge.

Parts ----- Quantity -----

NO PARTS USED

**Task performed:**

DROP OFF NEW BATT.

**Workorder: V63616**

In Date: 01/22/2014  
Close Date: 02/19/2014

Meter Reading:

**Problem?**

Install Stryker stretcher

Parts ----- Quantity -----

NO PARTS USED

**Task performed:**

TIRES REPAIRED.



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V63779**

In Date: 01/28/2014  
Close Date: 03/26/2014

Meter Reading:

**Problem?**

TWO FRONT TIRES ON RESCUE TRUCK ARE COMPLETELY WORN AND BALD ON THE OUTER AND INNER OF BOTH FRONT TIRES! POSES A SAFETY ISSUE WHEN RESPONDING CODE 3 TO A CALL.

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

REPAIRED ON WORK ORDER #63841 BY BOULEVARD TIRE.

NO PARTS USED

**Workorder: V65317**

In Date: 03/31/2014  
Close Date: 04/02/2014

Meter Reading: 196,466.80

**Problem?**

A inspection

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

1. A-INSP. 2. REMOVE ACCREDITATION DECALS AND BUFF OUT SIDES. 3. AIR BAG SUSPENSION LOOSEN U-BOLTS ON LEFT SIDE SET UP JACK STAND AND DRY OVER BAG SUPPORT ARM TO ALIGN WITH AIR BAG THAT WAS WOULD BE STRAIGHT UP AND DOWN- REPLACE AIR BAG THAT WAS WORN OUT FROM BEING OFF ANGLE READJUST HEOGHT VALVES.

NO PARTS USED





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

### \* ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V64324**

**In Date:** 02/18/2014

**Meter Reading:** 195,536.00

**Close Date:** 04/07/2014

**Problem?**

B inspection old R93

**Task performed:**

1. B-INSPECTION. 2. BATTERIES FAILED BATT TEST-REPLACE ALL BATT. 3. BATT SLIDE DRAW. BLOW OUT DEBRIS FROM SLIDE TRACK- LUBAE AND REPAIR LATCH. 4. WASHER REPAIR BROKEN HOSE ON L/SIDE WIPER ARM. 5. WIPER BLADES WIPER BLADES. 6. R&R A/C COMPRESSOR AND DRYER RECOVER SYSTEM, VACUUM AND CHARGE SYSTEM. 7. REMOVE POLE LIGHTS. 8. REMOVE STICKER OFF WINDSHIELD. 9. LOOSEN U-BOLT STAND TRACK FRAME AND TIGHTEN U-BOLT AND TORQUE THEM. 10. R&R TWO GROUND LIGHT BULBS. 11. CHECK SPOT LIGHT FOUND BAD CONNECTION. R&R CONNECTION AND SPOTLIGHT WORKED. 12. CHECKED STEERING COLUMN FOUND BAD U-JOINT R&R U-LIGHT. 13. UNDER TRUCK LTS. REPAIRS LOOSE UNDER TRUCK LT BRACKETS- SOME SCREW HOLES STRIPED OUT REPAIR. 14. A/C AIR INTAKE FILTERS. REPLACE ALL A/C INTAKE FILTERS. 15. CAB SHOCKS. REPLACE BOTH CAM SUSPENSION SHOCKS.

**Parts**

**Quantity**

000090155133634 FUEL FILTER WIX MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
071601A07-0602A DRIER A/C 7118	1
1501450007750USE 0775145	1
16-15762-00016-19471-000 AIR BAG	1
18-43504-000CAB SHOCK	2
22-57855-000LOWER COVER M2	1
42809AIR FILTER M2	1
5790COMPRESSOR A/C	1
61H01LED GROUND LITE CLEAR	2
78R536078R5360M 2PK FILTER AIR COND	2
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER B/	4
HP-31DBATTERY 950CCA HP-31D	4
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
SK000198UJOINT STEERING 1-0475	1
VCC/36000006A/C FILTER CAB M2	2



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V65454**

In Date: 04/04/2014  
Close Date: 04/09/2014

Meter Reading: 196,682.30

**Problem?**

a/c inop

Parts

Quantity

NO PARTS USED

**Task performed:**

TRAVEL TO ST-31 CHECK A/C INOP CONDENSOR FANS INOP CHEC FOR POWER PWH STEP ON SIDE OF TRUCK OPEN UP UNTI PRESSURE SWITCH OK. TEST POWER TRACE WIRING CHECK FIREWALL FUSE BLOCK FOR CHECK IN V-MUX HOOK LAPTOP CHECK NODE OUTPUT IN NODE 1 PIN PUMP TEST MOTOR OK NODI BAD NO NODE ON TRUCK WILL WILL MOVE ON CALL TECH REPLACE IN A.M.

**Workorder: V65791**

In Date: 04/18/2014  
Close Date: 04/21/2014

Meter Reading: 197,282.00

**Problem?**

No start

Parts

Quantity

3069053CLAMP V-BAND EXH3923060	1
83000266831 38MT 11 TOOTH STARTER	1

**Task performed:**

1. ATTEMPT TO START VEHICLE. REMOVE AIR TANK DRAIN AND INSTALL FITTING AIR VEHICLE TO UNLOCK BRAKES, TOW VEHICLE INTO BAY. DIAGNOSE NO START PROBLEM. FOUND BAD STARTER. REPLACED STARTER REWIRE TO USE ADDITIONAL STARTER SWITCH. TEST OK. 2. HELP MOVE DEAD VEH INTO SHOP.



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V65857**

In Date: 04/21/2014  
Close Date: 04/23/2014

Meter Reading: 197,282.00

**Problem?**

check cab a/c

**Task performed:**

1. TROUBLESHOOT CAB A/C INOP. 2. CONTINUED TROUBLESHOOTING A/C CONCERN (ELECTRICAL PROBLEM). 3. TRACED A/C CONCERN TO FAULTY INSTALATION OF COMPRESSOR GROUND TO STARTER POSITIVE POST. REMOVED GROUND WIRE FROM POS STUD AND REINSTALLED ON NEGATIVE POST. A/C NOW WORKS NORMALLY.

Parts

Quantity

DUFDT04-4P-RT03EL35674 DIODE PACK GRAY

1

**Workorder: V65740**

In Date: 04/15/2014  
Close Date: 04/24/2014

Meter Reading: 197,282.00

**Problem?**

replace starter

**Task performed:**

SR 21 NO START R/R STARTER STILL NO START.

Parts

Quantity

11132766583 STARTER 28MT 5.9 10 TOOTH 104650

1

**Workorder: V66204**

In Date: 05/03/2014  
Close Date: 05/05/2014

Meter Reading:

**Problem?**

OUTSIDE REAR TIRES WORN PAST WEAR BAR R36

**Task performed:**

TIRES WERE REPLACED.

Parts

Quantity

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V66227**

In Date: 05/05/2014  
Close Date: 05/05/2014

Meter Reading: 198,552.80

**Problem?**

coolant leak

Parts

Quantity

**Task performed:**

1. REPLACED ALL FOUR TIRES IN REAR. 2. REMOVED LOWER COOLANT HOSE AND REPLACED CLAMPS PRESSURE TESTED.

NO PARTS USED

**Workorder: V66367**

In Date: 05/09/2014  
Close Date: 05/13/2014

Meter Reading: 198,552.80

**Problem?**

replace rear tires

Parts

Quantity

**Task performed:**

replace rear tires

NO PARTS USED

Vendor? BOULEVARD TIRE

**Workorder: V66431**

In Date: 05/12/2014  
Close Date: 05/15/2014

Meter Reading:

**Problem?**

The MDT docking station has no power. @ST21

Parts

Quantity

**Task performed:**

TRAVEL TO 21 DRIVER COMPLAINT ROCKING STATION INOP CHECKED SYSTEM OK.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V66287**

In Date: 05/06/2014  
Close Date: 05/21/2014

Meter Reading: 198,552.80

**Problem?**

A inspection SR21

Parts ----- Quantity -----

**Task performed:**

1. A INSP. 2. AIR LEVELING VALVES OUT OF ADJUSTMENT. 3. ASSIST NORRIS WITH ABOVE.

NO PARTS USED

**Workorder: V66565**

In Date: 05/18/2014  
Close Date: 05/21/2014

Meter Reading:

**Problem?**

Backup alarm works intermittently, safety hazard R24

Parts ----- Quantity -----

**Task performed:**

TRAVEL TO 24 DRIVER COMPLAINT BACK UP ALARM INTERMITTEN TIGHTENED GROUND WHILE ON ALRM AND TESTED OK.

NO PARTS USED

**Workorder: V66754**

In Date: 05/27/2014  
Close Date: 06/16/2014

Meter Reading: 199,904.20

**Problem?**

R24 no lights

Parts ----- Quantity -----

**Task performed:**

no emergency lights replaced Y connector and lights repaired ok.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V67442**

In Date: 06/24/2014  
Close Date: 07/03/2014

Meter Reading:

**Problem?**

SHELF IN DRIVERS SIDE REAR COMPARTMENT BROKE AND COLLAPSED ON TO BOTTOM SHELF ON TOP OF RAMS. THE BRACKE HOLDING THE SHELF SPLIT FROM SIDE WALL. R43

Parts ----- Quantity -----

**Task performed:**

REPAIRED SLIDE OUT TRAY THAT WAS NOT MOVING OUT.

NO PARTS USED

**Workorder: V67701**

In Date: 07/06/2014  
Close Date: 07/10/2014

Meter Reading:

**Problem?**

PRESSURE RELIEF VALVE DOES NOT WORK PROPERLY AND HAS A STEADY LEAK FLOODING THE BAY FLOOR. FOAM SYSTEM DOES NC WORK PROPERLY. PASS. SIDE STROBE ON CAB OUT. R43

Parts ----- Quantity -----

**Task performed:**

Repaired air leak at rear air bags. Road tested.

NO PARTS USED

**Workorder: V67706**

In Date: 07/06/2014  
Close Date: 07/11/2014

Meter Reading:

**Problem?**

There is an electrical issue that has started recently. While in E-mode and idling the engine will not keep a constant idle, it alternates from high to low. Also the turn signals nor the windshield wipers are working.

Parts ----- Quantity -----

**Task performed:**

Sent to shop

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V67709**

In Date: 07/06/2014

Meter Reading:

Close Date: 07/11/2014

**Problem?**

To add to the earlier list of issues, the milage readout is not functioning.  
Unable to document milage or engine hours when fueling the rescue. R43

Parts ----- Quantity -----

**Task performed:**

Unit was swapped out and sent to shop.

NO PARTS USED

**Workorder: V67792**

In Date: 07/09/2014

Meter Reading:

Close Date: 07/21/2014

**Problem?**

a-inspection

Parts ----- Quantity -----

**Task performed:**

1.A-Inspection 2.Electrical Problems 3.C- Inspections 4.Install air bags and leveling valves and adjust valves. Air dry service. 5.Bolts and Pullys check to find where squeal was coming from ground lights,dome lights, Air filter and compartment drawer. 6.Assist in air bag adjusment.

512-0070-00-0MIV HANDLE 1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V67907**

**In Date:** 07/14/2014  
**Close Date:** 07/29/2014

**Meter Reading:** 201,994.70

**Problem?**

C inspection SR21

**Task performed:**

Electrical issues.Low air pressure warning goes off at any time. Remove and replaced pressure switch.

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
01-29866-118BELT ALT. M2	1
16-15762-00016-19471-000 AIR BAG	2
2FC00ZCR4 IN ROUND LED	4
322502BULB PATIENT GH22	1
42809AIR FILTER M2	1
5008414CARTRIDGE DC100	1
5632-1010 IN DRAWER SLIDES PR	1
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
91-22WIPER BLADE	2
921LIGHT BULB	1
9420BELT	1
A2C53081955CLUSTER M2	1
DDE/A9062003170BELT TENSIONOR MERCEDES	1
K022105PURGE VALVE AD-IP-IS	1
NRG-27-SWB-013RA12-19777-013 AMU006 VALVE A	1
NRG27-SWA-111RA12-19776-111 MODULE REPLACI	1
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
S4640024430VALVE LEVELIN	2
VCC/36000006A/C FILTER CAB M2	1





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V67717**

In Date: 07/07/2014  
Close Date: 08/14/2014

Meter Reading:

**Problem?**

AIR LEAK UNABLE TO MOVE ENGINE UNTIL AIR PRESSURE BUILTS  
BACK UP

Parts ----- Quantity -----

**Task performed:**

WORK WAS COMPLETE AT TIME OF SER AT SHOP W/O V67792

NO PARTS USED

**Workorder: V67718**

In Date: 07/07/2014  
Close Date: 08/14/2014

Meter Reading:

**Problem?**

emergency lights working intermittantly, turn signals/wipers 10/7, other  
electrical problems in cab.

Parts ----- Quantity -----

**Task performed:**

WORK WAS COMPLETE AT TIME OF SER AT SHOP W/O V67792

NO PARTS USED

**Workorder: V68775**

In Date: 08/19/2014  
Close Date: 08/22/2014

Meter Reading: 202,769.00

**Problem?**

BELT CAME OFF R36

Parts ----- Quantity -----

**Task performed:**

round a/c belt broken R&R BELT.

9420BELT 1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V68919**

In Date: 08/25/2014  
Close Date: 08/26/2014

Meter Reading: 203,310.00

**Problem?**

smoke coming from under hood

Parts ----- Quantity -----

**Task performed:**

travel to sta36 ck,out smoking found compressor bearing out can,t drive tow to shop.

NO PARTS USED

**Workorder: V68914**

In Date: 08/25/2014  
Close Date: 08/29/2014

Meter Reading: 203,310.00

**Problem?**

R36 coolant leak

Parts ----- Quantity -----

**Task performed:**

Traced out coolant leak. Found blown heater hose removed and replaced.

NO PARTS USED

**Workorder: V68929**

In Date: 08/25/2014  
Close Date: 09/02/2014

Meter Reading: 203,310.00

**Problem?**

A/C inop compressor locked

Parts ----- Quantity -----

**Task performed:**

1. ck, out system failing a/c found bad a/c compressor/ dryer and have to flash out system clean condensor fab new discharge hose installed all equipment pump down and charge system tested system ok. 2. assist with al repairs

01-29866-118BELT ALT. M2	1
08-3001B4479 SPLICER B/L	2
533303-0609 A/C COMPRESSOR M2 4485	1
719707-0614A AC DRIER M2	1
9420BELT	1
DDE/A9062003170BELT TENSIONOR MERCEDES	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V69144**

In Date: 09/03/2014  
Close Date: 09/05/2014

Meter Reading: 203,716.20

**Problem?**

coolant leak

Parts ----- Quantity -----

**Task performed:**

found to hose blown did not find replacement switch out unit.

NO PARTS USED

**Workorder: V68944**

In Date: 08/26/2014  
Close Date: 09/08/2014

Meter Reading:

**Problem?**

Plastic Grill is about to fall off screw fell off and needs new brackets to hold grill R36

Parts ----- Quantity -----

**Task performed:**

REPAIRED GRILL AND REPAIRED AIR HORN BRACKET.

NO PARTS USED

**Workorder: V69596**

In Date: 09/23/2014  
Close Date: 09/23/2014

Meter Reading: 203,716.20

**Problem?**

Install new vist screen

Parts ----- Quantity -----

**Task performed:**

Install new vist screen and program it.

6231-0010-11VISTA III SREEEN WELDON	1
FRT V27865FREIGHT CHARGE	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V69425**

In Date: 09/16/2014  
Close Date: 09/25/2014

Meter Reading: 203,716.20

**Problem?**

Coolant leak

**Task performed:**

WAAPPED HOSE WITH DUCK TAPE TO GET TRUCK TO SHOP  
REMOVE HOSE AND TAKE TO PARTS ROOM TO GET NEW ONE DID  
NOT HAVE, HAVE TO ORDER ONE TO INSTALL. INSTALLED NEW  
HOSE AND PRESSURE CK, SYSTEM OK.

Parts	Quantity
05-22029-001UPPER RAD HOSE M2	1
FRT V67259FREIGHT CHARGE	1

**Workorder: V70329**

In Date: 10/21/2014  
Close Date: 11/06/2014

Meter Reading: 204,372.00

**Problem?**

A inspection

**Task performed:**

1. Perform A service. 2. R & R wiper blades. Top off washer fluid. 3.Top  
off all tires. Top off all fluids, coolant, etc. Check under truck for repairs if  
needed. Repair oxygen wrench. Test drive after. OK.

Parts	Quantity
22-58581-000WASHER RESIVOR CAP	1
388863HOSE KIT	1
91-22WIPER BLADE	2



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V70765**

**In Date:** 11/07/2014  
**Close Date:** 11/12/2014

**Meter Reading:** 204,372.00

**Problem?**

A-inspection

**Task performed:**

1."A" inspection-Secure loose coolant overflow hose 2. Grill support hole broken-Fabbed support plate, drill hole and install support plate rmeount grill and secure. 3. R-2 door lock loose-screw holes worn out-Remove lock, retap screw hole and reisntall lock. 4. Cab marker light out- Remove head line to remove spinning light screws-had to grind off head of screws to remove light assembly-Install new light and reassemble.

Parts

Quantity

A06-40578-000TOP CLEARANCE LIGHT M2

1

**Workorder: V71051**

**In Date:** 11/18/2014  
**Close Date:** 11/20/2014

**Meter Reading:**

**Problem?**

Rear Door of rescue handle is broken. R37

**Task performed:**

Travel to station 32, check out rear door handle inop-found handle broken off pull door apart R/R outer door handle adjust strikers on door and lube.

Parts

Quantity

HND5948TM22676-02 HANDLE DOOR ENTRY

1

**Workorder: V71154**

**In Date:** 11/24/2014  
**Close Date:** 11/25/2014

**Meter Reading:** 204,863.00

**Problem?**

Engine overheating

**Task performed:**

Engine overheating/fan clutch/manually locked clutch.

Parts

Quantity

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V71195**

In Date: 11/25/2014  
Close Date: 11/25/2014

Meter Reading: 204,960.00

**Problem?**

replace fan clutch

**Task performed:**

Dignosed overheat/fan clutch in locked postion and air line disables. Fan clutch failed-R/R fan clutch fabbed and installed new air line. Verified proper operation.

Parts	Quantity
HOR/991450HT 650 FAN ASY.	1

**Workorder: V71856**

In Date: 12/24/2014  
Close Date: 01/20/2015

Meter Reading: 207,159.00

**Problem?**

B inspection, steering wheel may need replacing

**Task performed:**

1. Starter removing steering columb ordered new one 2. Starter removing rear brakes and installing new ones 3. Finished rear brake job-installed new drums shoes 4. Repaired dash broken areas-repaired door switch change cab filter-corrected trans fluid level-oil level. 5. Installed new steering wheel 6. Change cab air filter-tighten door springs patient AC filter 7. Installed new batterys-checked system.

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
0775145PANEL FILTER	1
3744BRAKE DRUM REAR	2
78R536078R5360M 2PK FILTER AIR COND	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
A14-12612-002STEERING WHEEL M2	1
A14-15776-000STEERING COLUMN	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
HP-31DBATTERY 950CCA HP-31D	4
KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2
S3226FL02FUEL FILTER 33813 L/F # LFF5851	1
VCC/36000006A/C FILTER CAB M2	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V72322**

In Date: 01/14/2015  
Close Date: 01/28/2015

Meter Reading:

**Problem?**

STA 36 officer side top mirror loose and unable to see traffic approaching from drivers side

Parts ----- Quantity -----

**Task performed:**

Repaired mirror that was loose. Road tested truck. Mirror ok.

NO PARTS USED

**Workorder: V65517**

In Date: 04/07/2014  
Close Date: 02/11/2015

Meter Reading: 196,926.30

**Problem?**

a/c cab inop

Parts ----- Quantity -----

**Task performed:**

WENT TO STATION INSTALLED NEW CONTROLLER BOX FOR V-MU)

6000000003NODE HERCULES V-MUX	1
82000056808 38MT 12T STARTER	1

**Workorder: V72664**

In Date: 01/27/2015  
Close Date: 02/11/2015

Meter Reading:

**Problem?**

electrical system would not turn on--Vehicle's mod screen was bright white--no emergency lights or mod power. After turning off and on engine and battery multiple times, the issue seems to have resolved.

Parts ----- Quantity -----

**Task performed:**

Checked all connections - ok.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V72581**

In Date: 01/25/2015  
Close Date: 03/16/2015

Meter Reading:

**Problem?**

Two yellow box lights are not charging properly. Will not hold charge. R36

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

1. Swapped out head lights.

NO PARTS USED

**Workorder: V74001**

In Date: 03/19/2015  
Close Date: 03/31/2015

Meter Reading: 214,364.80

**Problem?**

Low voltage alarm

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

1. LOW voltage alarm- Check battery charging - alternator charging- Full load 13.2 V- unit in service 2. COOLANT ON FLOOR- COOLANT LEVEL FULL.

NO PARTS USED

**Workorder: V74717**

In Date: 04/16/2015  
Close Date: 04/16/2015

Meter Reading: 12,629.40

**Problem?**

rear tire replaced

Parts \_\_\_\_\_ Quantity \_\_\_\_\_

**Task performed:**

rear tires replaced

NO PARTS USED

Vendor? BOULEVARD TIRE





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

## 10163702

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V74178**

**In Date:** 03/25/2015  
**Close Date:** 05/22/2015

**Meter Reading:** 214,364.80

**Problem?**

Low voltage

**Task performed:**

1. Work on removing alternator. 2. Finish removing alternator. Replace it and install back A/C compressor. 3. Found coolant leak pressure, test system. Found heater hose leak, replace hose clamps. Test again, found radiator leak needs new one. 4. Remove front air cooler and all hoses. Remove coolant, remove radiator. 5. Clean up and prep radiator mounting brackets and all bolts. Install radiator on bottom bracket. 6. Work on radiator. Installation. 7. Back on radiator installation. Test for operation. Adjust front bumper corner and adjust right side mirror bracket. It's good now.

Parts	Quantity
A0014949PA4949PA/4962 320 AMP UPGRADE SADI	1
C1673FRE04 RADIATOR	1

**Workorder: V74469**

**In Date:** 04/06/2015  
**Close Date:** 07/08/2015

**Meter Reading:** 214,535.00

**Problem?**

check cooling system and belt squealing

**Task performed:**

replace tensioner and belts

Parts	Quantity
01-29866-118BELT ALT. M2	1
0128042000PULLY TENSION	1
9420BELT	1
DDE/A9062003170BELT TENSIONOR MERCEDES	1

376