



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V16314

In Date: 07/11/2008
Close Date: 07/16/2008

Meter Reading: 88.00

Problem?

right outer rear wheel leaks at valve stem sensor r73

Parts	Quantity
-------	----------

Task performed:

drie to Stn73; rem R/R/I air pressure snesor; refill tire. j

NO PARTS USED

Workorder: V16404

In Date: 07/17/2008
Close Date: 07/21/2008

Meter Reading: 88.00

Problem?

air horn pedal and swith on dash sticks in the on position when used. e73

Parts	Quantity
-------	----------

Task performed:

1. contacted hallmark.

NO PARTS USED

Workorder: V16393

In Date: 07/16/2008
Close Date: 07/28/2008

Meter Reading: 88.00

Problem?

driver's side rear door panel is coming loose and the fill this diesel tank first sign came off of the tank. r73

Parts	Quantity
-------	----------

Task performed:

1. reglued door panel back on .

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V16459

In Date: 07/19/2008 **Meter Reading:** 2,039.00
Close Date: 07/28/2008

Problem?

Driver side rear window pops out once a shift needs to be resealed. Air horn sticks and remains on for extended periods of time.

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

1. contacted hallmark for warranty repair.

Workorder: V16718

In Date: 07/30/2008 **Meter Reading:**
Close Date: 08/04/2008

Problem?

seal around rear drivers side window of the pt compartment has dislodged and the rear window pops out due to pressure displacement when rear doors are closed R73

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

WARRANTY - Ed O. contacted Scott @ Hallmark 7/30/08 j

Workorder: V17832

In Date: 09/20/2008 **Meter Reading:** 264.00
Close Date: 09/30/2008

Problem?

LEFT REAR PRIVACY WINDOW IS WORKING INTERMITTENTLY.

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

contacted hallmark for warranty repair



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V17969

In Date: 09/27/2008 Meter Reading: 294.00
 Close Date: 09/30/2008

Problem?

right side front scene light out. R73

Parts	Quantity
-------	----------

Task performed:

drive to sta 73-replace right scene light bulb-test

NO PARTS USED

Workorder: V18251

In Date: 10/10/2008 Meter Reading: 4,790.00
 Close Date: 10/14/2008

Problem?

REPLACE HEADLIGHT, R-73

Parts	Quantity
-------	----------

Task performed:

1- 4 Head lights inop, bulb. installed new bulbs, have to go to shop for parts.

9007H9007 BULB ASSY	2
---------------------	---

Workorder: V16321

In Date: 07/11/2008 Meter Reading: 88.00
 Close Date: 10/17/2008

Problem?

electic door locks not working in cab. r73

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V18676

In Date: 10/29/2008 Meter Reading: 4,321.00
Close Date: 10/31/2008

Problem?

REPAIR AIR PACK BRACKET R73

Parts	Quantity
-------	----------

Task performed:

Adj all air pack brackets in truck to fit new air packs. j

NO PARTS USED

Workorder: V19164

In Date: 11/18/2008 Meter Reading: 5,601.00
Close Date: 11/26/2008

Problem?

airhorns are not working R73

Parts	Quantity
-------	----------

Task performed:

Ck air horns - ck ok. j

NO PARTS USED

Workorder: V18945

In Date: 11/09/2008 Meter Reading: 437.00
Close Date: 12/11/2008

Problem?

#1-the rear window in the box on the back doors keeps coming on and off from no privacy to privacy,#2-the handle was stripped out after the hallmark guy workd on the window,#3- the air dump works when it wants. R73

Parts	Quantity
-------	----------

Task performed:

R/R PATIENT COMPT. INNER DOOR GRAB HANDLE & PANEL.INSTALLED NUTS ON BACK OF PANEL.

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V19165

In Date: 11/18/2008 Meter Reading:
Close Date: 12/11/2008

Problem?

the privacy windows stay on you can't see out of the windows. the airhorns do not work. the rear airpack holder behind the Lts seat does not work. R73

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:
CALLED HALLMARK FOR REPAIR.

Workorder: V19372

In Date: 11/28/2008 Meter Reading:
Close Date: 12/11/2008

Problem?

the front air blower does not work,the the ac does not blow at all R-73

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:
SENT TO INTERNATIONAL FOR REPAIR.

Workorder: V19399

In Date: 11/30/2008 Meter Reading:
Close Date: 12/11/2008

Problem?

the front a/c does not blow air. the motor does not come on at all R-73

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:
REPAIRED BY INTERNATIONAL.



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V19940

In Date: 12/23/2008

Meter Reading: 7,141.00

Close Date: 01/06/2009

Problem?

c inspection and repairs as needed r73

Task performed:

C-Inspection 2. Blow out dirt/debris from all A/C condensers. 3. Replc nonskid on side door entry to pat area. 4. Rear step holding cup brckts bent; straighten brkts. 5. Rear step compt door latches inop. Lube inside lock parts; redrill stationary lock tab & reposition to line up w/lock asy. 6. Replc right frnt tire (to match L/F tire). 7. Replc all veh A/C sys filters. 8. Coolant sys fill tank way overfilled; drain out coolant to proper level intake; make up label for tank level & install new rad cap. 9. Replc wiperblades. 10. Tighten right side step mirror & adj. 11. Rem lower brake lights & reprogram from flashing to steady burn. 12. Clin off adhesive brock frm fuel tank cvr & install new emblem in new location. 13. Rep side entry mec cabinet draw latch & sharps pull out door latch; & (2) med cabinet pull out draws. 14. Replc several zerks in frnt suspension in order to grease. 15. Rear under truck light brkt bent/twisted; rem brkt frm veh & straighten out brkt; reinstall on veh & rep brkn wiring to light fixture. 16. Rep btry tray slides to open & close properly. 17. Rem tar-like substance from all btry & electrical wiring terminals & connectors. 18. Redesign air bottle seat brkts; rem/reinstall; mk all ness adjustments. 19. Rem pat area bench seat; senc out for rep; reinstall bench seat & align to latch properly. 20. Adj air bag valves to set chassis height. j

Parts

Quantity

1500900017000USE 9 X 14 FILTER	3
15W40BSYN OIL BULK QTS	28
1873910C91FUEL STRAINER HORTON	1
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
46870AIR FILTER	1
5774457744XD OIL FILTER	1
78R539018-2699 A/C FILTER	1
91-22WIPER BLADE	2
F6DZ-8100-A9C3Z8101B RADIATOR CAP 10238 STAI	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V19677

In Date: 12/10/2008
Close Date: 01/13/2009

Meter Reading: 7,141.00

Problem?

repair of air horns r73

Parts	Quantity
-------	----------

Task performed:

Repair air horns R73 - Rechten Intl j

NO PARTS USED

Vendor? RECHTIEN

Workorder: V20679

In Date: 01/28/2009
Close Date: 01/28/2009

Meter Reading:

Problem?

privacy windows on pt. compt. not shutting off. r73

Parts	Quantity
-------	----------

Task performed:

contacted hallmark for repair 10/28/09

NO PARTS USED

Workorder: V20484

In Date: 01/21/2009
Close Date: 02/09/2009

Meter Reading: 7,692.00

Problem?

VEHICLE LEANING TO THE LEFT, R-73A

Parts	Quantity
-------	----------

Task performed:

Svc call to training; fnd left air bag empty; dumped air suspension in cab & out rear door; bag installed; adj levelling rod mnt to balance air bags. j

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V18946

In Date: 11/09/2008 Meter Reading: 437.00
Close Date: 02/19/2009

Problem?

repair seat central auto trim r73

Parts	Quantity
-------	----------

Task performed:

Repair seat - Central Auto Trim j

NO PARTS USED

Vendor? CENTRAL AUTO TRIM

Workorder: V19118

In Date: 11/17/2008 Meter Reading: 6,346.00
Close Date: 02/19/2009

Problem?

REPAIR FLAT R 73

Parts	Quantity
-------	----------

Task performed:

Repair flat R73 - Callghan j

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V17101

In Date: 08/17/2008 Meter Reading: 208.00
Close Date: 03/02/2009

Problem?

SCBA harness locking pin broke off and is non functional. Air horn on steering wheel is sticking for approx. five min. Need a new dry chem extinguisher. R-73

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V21511

In Date: 03/03/2009 Meter Reading: 10,103.00
Close Date: 03/16/2009

Problem?

Install long stretcher release rod R73

Parts	Quantity
-------	----------

Task performed:

R/R stretcher rod; adjust; also adjust stretcher lock out swtchs in stretcher body, etc; retest lockout - ok. j

NO PARTS USED

Workorder: V21880

In Date: 03/17/2009 Meter Reading: 794.00
Close Date: 03/27/2009

Problem?

rear ground light under rear step found hanging loose, bracket bent. r73

Parts	Quantity
-------	----------

Task performed:

Rem brkt asy; straightened light brkt; reinstalled light/brkt; ck ok; returned to WPB. j

NO PARTS USED

Workorder: V22177

In Date: 03/30/2009 Meter Reading: 794.00
Close Date: 04/17/2009

Problem?

Need brackets mounted for signage. R73

Parts	Quantity
-------	----------

Task performed:

1. Left placker with Stn to install; Ed needed me back at shop ASAP (out on call). 2. Drive back to shop. j

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V22047

In Date: 03/24/2009
Close Date: 04/21/2009

Meter Reading: 794.00

Problem?

water and oil sensor arms itself and oxygen alarm sets on when the tank itself is full.

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

1. Low O2 sys seems to work normally; off now; bleed press off & alarm goes off; fnd O2 bottle turned off; this will allow alarm to come on when press bleeds off. 2. Travel from Stn74 to Stn73. 3. A/C out in frnt; C/O unit; chk wiring; rem unit; C /O wiring; pull dash apart to find short & rep; ok now. 4. C/O O2 sys; replcd gauge stuck on 1200 PSI; cldnt read gauge. j

Workorder: V22632

In Date: 04/18/2009
Close Date: 04/27/2009

Meter Reading: 889.00

Problem?

arm that holds stretcher onto floor is loose, stretcher comes out sideways o some turns R73

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

Went to Stn73; R73 on-call; waited for truck; fnd strether lock loose; adj stretcher lock; ck opn; ck ok; returned to WPB. j



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V22762

In Date: 04/23/2009 Meter Reading: 12,385.00
Close Date: 05/11/2009

Problem?

repair tire at st-73...callaghan R-73

Parts	Quantity
-------	----------

Task performed:

Repair tire at Stn73 - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V23283

In Date: 05/14/2009 Meter Reading: 950.00
Close Date: 05/14/2009

Problem?

Alarm: Low oil/fluids Alarm: Low coolant Both fluids are full and alarm is still activating R73

Parts	Quantity
-------	----------

Task performed:

REPAIRED OVER PHONE NO PARTS NO LABOR

NO PARTS USED

Workorder: V23408

In Date: 05/20/2009 Meter Reading: 998.00
Close Date: 06/12/2009

Problem?

Leaking power steering fluid. Low coolant alarm sounding even when fluid is full. r73

Parts	Quantity
-------	----------

Task performed:

Chk; fnd clamp loose; tighten & add fluid. j

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V23465

In Date: 05/21/2009
Close Date: 06/12/2009

Meter Reading: 13,778.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED R 73

Task performed:

B-Inspection 2. Left headlight out; R/R bulb; R/R wiper blades. 3. Both air horns loose; rep mtns/replcd right support mnt. 4. L-1 compt light not mnted; reinstalled light; rope in channel. 5. Torque u-bolts; both axles. 6. Cln cond fans; had to cln pat air filters. 7. Ck P/S leak; ck hoses at pump ck ok; tightened clamps on P/S supply hose; filled P/S reservoir; ck ok. 8. Ck for coolant leak; pressurize sys; fnd leak at top rad hose flange on eng topped off sys; leak will be rep under warranty. 9. Ck cab A/C; ran A/C; fnd A/C cooling after cond coils wwere clnd; ck ok. 10. Left hood turn signal light brkn; rem hood strap/light; ordered part; temp. glued & rep light; reinstalled light; ck ok. j

Parts	Quantity
15W40BSYN OIL BULK QTS	24
1873910C91FUEL STRAINER HORTON	1
1878042C91FUEL FILTER 2008 HORTON	1
35200-RLIGHT MARKER LED RED	1
35200-YLIGHT MARKER LEDAMBER	1
5774457744XD OIL FILTER	1
9007H9007 BULB ASSY	1
F6DZ-8100-A9C3Z8101B RADIATOR CAP 10238 STAI	1
GRV1720244770R1 HORN SUPPORT BRKT	1

Workorder: V23707

In Date: 06/01/2009
Close Date: 07/08/2009

Meter Reading: 13,778.00

Problem?

adjust fast idle RECHTIEN

Task performed:

Adjust fast idle - Rechten j

Parts	Quantity
NO PARTS USED	

Vendor? RECHTEIN



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V24611

In Date: 07/07/2009 Meter Reading: 15,444.00
Close Date: 07/15/2009

Problem?

on call r73 a patient a/c 10-7

Parts	Quantity
-------	----------

Task performed:

Svc call; fnd A/C k ok/ needed to set temp control; returned home. j

NO PARTS USED

Workorder: V24969

In Date: 07/22/2009 Meter Reading: 1,163.00
Close Date: 07/22/2009

Problem?

Rear A/C unit still leaking into compartment. Rear door switches (air dump and check out lights) still broken. r73

Parts	Quantity
-------	----------

Task performed:

contacted hallmark for warranty repair

NO PARTS USED

Workorder: V24872

In Date: 07/19/2009 Meter Reading: 1,163.00
Close Date: 07/23/2009

Problem?

Oil in water alarm going off again. A/C unit is leaking into compartment again; shelf is filling with water, gear/equipment is getting wet. R74

Parts	Quantity
-------	----------

Task performed:

contacted hallmark for warranty repair 7/19

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V25494

In Date: 08/12/2009 Meter Reading: 1,209.00
Close Date: 08/25/2009

Problem?

Error message states, "mod 9a Pin 4 fail". Rear A/C unit still leaking into compartment. r73

Parts	Quantity
-------	----------

Task performed:

Unit rep under warranty by Hallmark. j

NO PARTS USED

Workorder: V26346

In Date: 09/21/2009 Meter Reading: 19,067.00
Close Date: 09/24/2009

Problem?

on call R73 engine alarm going off

Parts	Quantity
-------	----------

Task performed:

Went to Stn73; press cooling sys; ck ok; added coolant. j

NO PARTS USED

Workorder: V26247

In Date: 09/14/2009 Meter Reading: 1,315.00
Close Date: 10/16/2009

Problem?

LEFT REAR SCENE LAMP IS NOT WORKING. r73

Parts	Quantity
-------	----------

Task performed:

1. Rem light; ck power & arnd; ck ok; did not have bulb on svc truck; reinstalled light. 2. R/R L/R scenelight. j

H35SN12BULB	1
-------------	---



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V27332

In Date: 11/02/2009

Meter Reading: 1,527.00

Close Date: 11/17/2009

Problem?

the rear A/C unit does not come on when the truck is plugged in to the shoreline. unable to keep the drugs cool when in bay. R-73b having same problem

Parts

Quantity

Task performed:

Rep by Hallmark under WARRANTY. j

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V27870

In Date: 11/23/2009

Meter Reading: 21,941.00

Close Date: 12/08/2009

Problem?

C INSPECTION AND REPAIRS AS NEEDED R 73

Task performed:

C-Inspection, road test 2. Btry failed load test; rem (3) btrys & install (3) new btrys. 3. Diff oil level low; no visible leak; top off oil level. 4. Secure loose wire harness along chassis. 5. Bring coolant to proper level. 6. Air dryer svc. 7. Tires under inflated at 90 psi; air tires to 110 psi. 8. Tailgate flip step loose; drill access porthole; tighten bolt; install additional support lockwasher & nut on back side of bolt & torque down nuts. 9. R/rear mud flap support bent; straighten out metal support brkt. 10. Ped box plexi glas brkn; rem to have one cut to fit. 11. 11. Rem old SCBA brkts. 12. Assemble, install/adj SCBA brkt in unit (3). 13. Rem cab/pat compts A/C filters & install new filters. 14. Secure loose tool holder brkt asy in L-2 compt. 15. O2 wrench unsecure; secure wrench via cable & nut; bolt to slide out O2 rack asy. 16. Rem eng & A/C belts for svc; install new belts. 17. Turbo blowing oil into intake cooler; rem intake to inspect; inspect air compressor air intake - no oil. 18. Windshield wiper blade installation; fill washer fluid reservoir & add bug solvent. 19. P/S sys fluid & filter svc; unable to find cause for low fluid level in reservoir. 20. Box in pat compt plexi-glass; drill mntng screws hole in plexi-glass; install on cabinet roof & rehung cabinet door. 21. Pulling to right; chk toe-in within specs; rotate frnt tires. 22. Road test after chng frnt end; unit steers straight. 23. 110 power inop; as per dealer, rem 110 converter; rewire new converter; fab support brkt & install unit. j

Parts

Quantity

065624AD-IP DRIER	1
15W40BSYN OIL BULK QTS	30
1847727C1BELT	1
1873910C91FUEL STRAINER HORTON	1
1878042C91FUEL FILTER 2008 HORTON	1
46870AIR FILTER	1
5774457744XD OIL FILTER	1
91-22WIPER BLADE	2
9485BELT	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	3
DOOR47 3/4 X 21 WINDOW HORTON	1
FREIGHTSHIPPING CHARGES	116
HP-31DBATTERY 950CCA HP-31D	3
K060695BELT	1
PD9175DLS75 CONVERTOR 110V 75 AMP	1
VML/T1808D2503221C1 FILTER POWER STEERING	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V28309

In Date: 12/13/2009
Close Date: 12/14/2009

Meter Reading: 1,619.00

Problem?

Rubber boot between cab and patient compartment leaking again. R73

Parts	Quantity
-------	----------

Task performed:

contacted hallmark for repair

NO PARTS USED

Workorder: V28305

In Date: 12/13/2009
Close Date: 01/05/2010

Meter Reading: 1,619.00

Problem?

R73. Drivers side scene light is out.

Parts	Quantity
-------	----------

Task performed:

C/O veh - scene light working ok; NPF at this time. j

NO PARTS USED

Workorder: V28603

In Date: 12/27/2009
Close Date: 01/08/2010

Meter Reading: 1,674.00

Problem?

drivers side headlight out and oil/water alarm constantly goes off...very annoying! R73

Parts	Quantity
-------	----------

Task performed:

1. Wetn to Stn73; fnd coolant low; topped off tank; press tested cooling sys; ck ok/ started & ran; ck ok. 2. R/R left headlight; ck ok. j

9007H9007 BULB ASSY	1
---------------------	---



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V28617

In Date: 12/28/2009 Meter Reading: 23,167.00
Close Date: 01/08/2010

Problem?

ON CALL O2 ALARM GOING OFF R33

Parts	Quantity
-------	----------

Task performed:

O2 alarm going off; replc gauge. j

NO PARTS USED

Workorder: V28750

In Date: 01/02/2010 Meter Reading: 1,697.00
Close Date: 01/28/2010

Problem?

stretcher is possibly malfunctioning. the stretcher wants to collapse after pulling the red handle when removing the stretcher from the pt compartmen R73

Parts	Quantity
-------	----------

Task performed:

Contacted Medco equip for repair. j

NO PARTS USED

Workorder: V28865

In Date: 01/06/2010 Meter Reading:
Close Date: 02/08/2010

Problem?

Oil/Water alarm still going off. Coolant level is low. Adding fluid almost ever shift. Ongoing problem. r73

Parts	Quantity
-------	----------

Task performed:

Ck coolant level; press test; NPF; fnd at this time. j

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V29460

In Date: 01/26/2010 **Meter Reading:** 1,782.00
Close Date: 03/04/2010

Problem?

front left scene light out R73

Parts	Quantity
-------	----------

Task performed:

Out of station for the day 2/5 & 2/10/10. R/R light; fnd wire loose on light; repair; work ok at this time. j

NO PARTS USED

Workorder: V29952

In Date: 02/13/2010 **Meter Reading:** 25,637.00
Close Date: 03/18/2010

Problem?

R73 minor transmission slip from 3rd to 4th gear

Parts	Quantity
-------	----------

Task performed:

C/O no code in trans/fluid fuel; drive dtruck; felt it rev betwn 4&5; called Ed; he will advise. j

NO PARTS USED

Workorder: V30798

In Date: 03/17/2010 **Meter Reading:** 27,288.00
Close Date: 04/02/2010

Problem?

THERE IS A RATTLE HEARD IN THE MOD DURING DRIVING.. PER OPERATORS SOUNDS LIKE SOMETHING IS GOING TO FALL OUT. HISTORY HAS SHOWN LOOSE AC?? r73

Parts	Quantity
-------	----------

Task performed:

Look for something loose under pass side of compt; fnd can under needle compt. j

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V26295

In Date: 09/16/2009 Meter Reading: 19,067.00
Close Date: 04/13/2010

Problem?

replace swich on rear paitient door r73 Parts only

Parts	Quantity
-------	----------

Task performed:
parts only no labor

NO PARTS USED

Workorder: V31118

In Date: 03/29/2010 Meter Reading: 27,572.00
Close Date: 04/20/2010

Problem?

main oxygen regulator in broke. still in service R73

Parts	Quantity
-------	----------

Task performed:
Chk/replc O2 gauges on rescue tank; need b igger bottle on O2 so it fits into holder. j

MG-C23SPMGC23 GAUGE	1
---------------------	---

Workorder: V30554

In Date: 03/08/2010 Meter Reading: 26,286.00
Close Date: 04/21/2010

Problem?

ac vent on officer side broken / front seat R 73

Parts	Quantity
-------	----------

Task performed:
Repair A/C vent on R/side, snap back in place. C/O seat; they want seat moved back; had to see past Captain's; chk w/Hallmark. Chk w/Ed Ehrke; he advised that the seat was going to stay were it is; move back as far as can get. j

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V31525

In Date: 04/14/2010 Meter Reading: 27,572.00
Close Date: 04/27/2010

Problem?

Install moulding around screen R73

Parts	Quantity
-------	----------

Task performed:

Install molding on scree mount - complete. j

NO PARTS USED

Workorder: V31566

In Date: 04/15/2010 Meter Reading: 27,572.00
Close Date: 04/29/2010

Problem?

oil leak R73

Parts	Quantity
-------	----------

Task performed:

Chk on this truck; looks like it has oil leaking also; tighten valve cover & all filter & oil cooler; cln off, have crew watch it till secure. j

NO PARTS USED

Workorder: V31874

In Date: 04/29/2010 Meter Reading: 13,778.00
Close Date: 05/11/2010

Problem?

replace all 6 tires R73A (outside agency-boulevard tire)

Parts	Quantity
-------	----------

Task performed:

Replace all (6) tires R73A - Boulevard j

NO PARTS USED

Vendor? BOULEVARD TIRE



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V32168

In Date: 05/12/2010 Meter Reading: 30,018.00
Close Date: 05/19/2010

Problem?

repair stretcher R73 (outside agency-medco equipt. repair)

Parts	Quantity
-------	----------

Task performed:

Rep stretcher R73 - Medco j Readj air horns on both sides to work; drive out in parking lot; working ok. j

Vendor? MEDCO

NO PARTS USED

Workorder: V31826

In Date: 04/27/2010 Meter Reading: 28,921.00
Close Date: 05/24/2010

Problem?

Rear A/C unit blowing was blowing warm air, now not blowing at all.
When plugged in R73

Parts	Quantity
-------	----------

Task performed:

1. C/O - fnd both A/C fans not working; need (2) fans for A/C. 2. R/R both fans motor under unit; A/C working ok at this time. 3. Remnt air pack brkt on side compt; came off - screw msng; drill/locktite all screws; readj hold brkts. 4. Chk on rattle under truck right side; tighten all bolts/mounts; chk A/C fans; will have to order thru parts. j Need all new tires on truck - 255-70-22.5 A73R, B73R. (Scott had taken care of this). j

50-1500USE FAN KIT PANCAKE MOTOR DANHARD	2
--	---



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V32281

In Date: 05/18/2010
Close Date: 06/01/2010

Meter Reading: 30,018.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED R73

Task performed:

B-Inspection 2. Chk A/C suck down sys; vac/recharged. 3. R/R wiper blades. 4. R/R R/rear scene light bulb. 5. Quality test. 6. Add mats on SCBA tubes. j

Parts	Quantity
1501450007750USE 0775145	3
15W40BSYN OIL BULK QTS	30
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
5774457744XD OIL FILTER	1
78R539018-2699 A/C FILTER	1
91-22WIPER BLADE	2
H35SN12BULB	1

Workorder: V32289

In Date: 05/18/2010
Close Date: 06/10/2010

Meter Reading: 30,018.00

Problem?

the air conditioning is leaking in the pt compartment on the floor from the front. R73

Task performed:

Reference W/O 32281 j

Parts	Quantity
NO PARTS USED	



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V32583

In Date: 06/01/2010 **Meter Reading:** 30,665.00
Close Date: 06/18/2010

Problem?

boot between cab and pt compartment is leaking R73

Parts	Quantity
-------	----------

Task performed:

Chk the boot; it looks ok but where it comes tog, it is not sealed; isntalled glue on seam; ok at this time. j

NO PARTS USED

Workorder: V32584

In Date: 06/01/2010 **Meter Reading:** 30,665.00
Close Date: 06/25/2010

Problem?

pt compartment a/c leaking into compartment R73

Parts	Quantity
-------	----------

Task performed:

1. C/O leak; pull cver off side; look at A/C evap tank; ok but line out side o drain tank; need plate installed by line to drain into tank. NOTE: need to chk all the trucks. 2. Tape up line to A/C unit in rear to stop sweating on lo-side line; R/R cvr on side to access unit to tape up; ok at this time.

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V33695

In Date: 07/21/2010
Close Date: 07/22/2010

Meter Reading: 32,773.00

Problem?

water pump on R73 is appears to be leaking

Task performed:

1. TRAVEL TO STA 73 PRESSURE TEST COOLING SYSTEM LOCATE LEAK AT WATER PUMP. REMOVE INNER FENDER , DRAIN COOLING SYSTEM, REMOVE BELTS, REMOVE TENSIONER, REMOVE PULLEY ON WATER PUMP, REMOVE WATER PUMP, INSTALL WATER PUMP RESSEMBLE ALL PREVIOUS COMPONENTS, FILL COOLING SYSTEM PRESURE TEST AND ROAD TEST.

Parts	Quantity
1842665C92WATER PUMP DT570	1

Workorder: V34655

In Date: 09/01/2010
Close Date: 09/15/2010

Meter Reading: 34,721.00

Problem?

replace wiper blades R73

Task performed:

Replc wiper blades on R73A - both bad. j

Parts	Quantity
91-22WIPER BLADE	2

Workorder: V33381

In Date: 07/07/2010
Close Date: 10/19/2010

Meter Reading: 32,162.00

Problem?

drivers side low beam headlight out r73

Task performed:

Completed j

Parts	Quantity
9007H9007 BULB ASSY	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V35952

In Date: 10/27/2010

Meter Reading: 37,641.00

Close Date: 11/15/2010

Problem?

C INSPECTION AND REPAIRS AS NEEDED R73

Task performed:

C-Inspection 2. Air tires to proper pressure. 3. Jump start veh - charge btrys. 4. Fully charge btrys & test -ok; cln cables & switch btrys end to end; mkup longer cable for neg; cln frame area for grnd & install cable. 5. Chk codes; erase inactive codes. 6. Fill/chk LRI tire for leak - ok. 7. Add coolant & P/S fluid; press chk cooling sys. 8. Arrange tire monitor sensors correctly for each tire. 9. Chk shoreline btry charger - inop; fnd brkr tripped; reset brkr & chk volt at btry - ok. 10. Svc dryer & rebuild; purge valve. 11. Chk/adj brakes. 12. lube all door latches; adj pat compt latches/strikers; tighten all door skin screws; adj squad bench striker; sec R/rear cab door trim. 13. Rem squad bench for reupholstery. 14. Rem rear nonskid strip frm pat cargo area; cut new strip to size & apply. 15. Ordered rumbler kit. 16. Mnt tire press monitor on dash. 17. Chk eng miss cyl #1 low power; erase code & drive; code came back; perform virtual compression test; 1, 3 & 4 cyl low; ship to International. 18. Chk eng oil leak rear of motor by valve cover; sent to International. 19. Install rear sea & hinge. 20. Road test veh with Ed Ehrke for wheel vibration - ok. 21. Chk codes in eng frm work performed at Intl; fnd (2) inactive codes; erased codes. 22. Adj O2 bottle brkts. j

Parts

Quantity

065624AD-IP DRIER	1
15W40BSYN OIL BULK QTS	30
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
46870AIR FILTER	1
5774457744XD OIL FILTER	1
698698 CHUCK	1
EC17802NUT COVERS 33MM	1
K022105PURGE VALVE AD-IP-IS	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V35592

In Date: 10/12/2010
Close Date: 12/22/2010

Meter Reading: 36,858.00

Problem?

check engine light on

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED

Workorder: V35753

In Date: 10/19/2010
Close Date: 12/22/2010

Meter Reading: 36,858.00

Problem?

driver's side left scene flood light is out. R73

Parts	Quantity
-------	----------

Task performed:

(1) TRAVELED TO ST73 TO FIX LEFT SIDE SCENE LIGHT ON R73. BULB CHECKED OUT OK. FOUND THE GREASE IN THE SOCKET OF THE BULB STOPPING THE ELECTRICAL CONNECTION FROM WORKING. AFTER CLEANING IT THE LIGHT WORKED OK. J.W.

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V35870

In Date: 10/23/2010
Close Date: 12/22/2010

Meter Reading: 36,858.00

Problem?

3rd medication drawer up in pt. compartment will not latch. keeps flying open. R73

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

(1) TRAVELED TO HQ TO REPAIR THE 3RD UP FROM THE BOTTOM, MEDICATION DRAWER IN THE PATIENT AREA OF R73 THAT WILL NOT LATCH CLOSED. THEY WERE THERE FOR OUT OF SERVICE TRAINING. FOUND LOOSE SCREWS/ ONE MISSING. REPLACED SCREW. TIGHTENED ALL OTHER SCREWS AND CHECKED ALL OF THE OTHER DRAWERS. OK. J.W.

Workorder: V36370

In Date: 11/11/2010
Close Date: 12/22/2010

Meter Reading: 23,851.00

Problem?

Vehicle leaking oil R73

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

Workorder: V37090

In Date: 12/11/2010
Close Date: 01/04/2011

Meter Reading: 39,117.00

Problem?

right rear cab door PANEL came off. R73

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

Drive to Stn73; ___ cover on right rear door fell off; drill & screw panel back in place. j



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V36979

In Date: 12/07/2010
Close Date: 01/10/2011

Meter Reading: 39,117.00

Problem?

wont start r73

Task performed:

Drive to location of truck; no start; btry dead; replc all btrys; they said that yesterday, they had to charge them to start after it was outside; About 1-1/2 hr, wld not start again; replc-ok; top off coolant & left one for stn; Top off coolant & left one gal total two gal; left stan some coolant. j

Parts	Quantity
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	3
HP-31DBATTERY 950CCA HP-31D	3

Workorder: V37716

In Date: 01/10/2011
Close Date: 01/10/2011

Meter Reading: 40,599.00

Problem?

need coolant Sta 73

Task performed:

Parts only - no labor. j

Parts	Quantity
ALA00350-50 EXTENDED LIFE COOLANT GAL	2

Workorder: V37231

In Date: 12/17/2010
Close Date: 01/19/2011

Meter Reading: 39,117.00

Problem?

Front left scene/flodd light is out. Privacy windows not working. R73

Task performed:

(1) TRAVELED TO ST-73 TO REPAIR PRIVACY WINDOW IN R73. INSTALLED NEW INVERTIS IN SYSTEM, OK. (2) LEFT SCENE LIGHT 10-7. REPLACED BULB, CLEANED PLUG,WORKING OK. J.W.

Parts	Quantity
H35SN12BULB	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V37319

In Date: 12/20/2010
Close Date: 01/20/2011

Meter Reading: 39,117.00

Problem?

- 1. The spot light on top of the truck is not moving up and down all the way.
 - 2. The back cab windows are always frosted and we can't see out of them.
- loud rattling noise when truck is driving coming from under right si R73

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

(1) TRAVELED TO ST-73 TO REPAIR SPOT LIGHT ON TOP OF TRUCK THAT ISN'T MOVING UP AND DOWN OLL THE WAY. REPAIR LIGHT WHEN R73 COMES IN FOR SERVICE. LOUD NOISE COMING FROM THE RIGHT SIDE UNDER THE BODY. CHECKED OUT AND FOUND NO NOISE AT THIS TIME. SEE TICKET # 37633 J.W.

Workorder: V37633

In Date: 01/04/2011
Close Date: 01/20/2011

Meter Reading: 40,599.00

Problem?

- truck is leaking oil from the rear transmission and the spot light will not go u all the way. And rear windows are always frosted. r73

Parts	Quantity
-------	----------

10006527WINDOW INVERTOR	1
-------------------------	---

Task performed:

(1) TRAVELED TO ST-73 TO CHECK OUT R73. OIL LEAKING FROM REAR OF TRANSMISSION. CHECKED OUT AND FOUND IT TO BE THE SAME LEAK AS BEFORE. VALVE COVER GASKET AND O RING SEAL AROUND THE WIRES TO THE INJECTOR ARE LEAKING. NEED TO REPLACE THE GASKET AND O RING. (2) SPOT LIGHT RANGE OF MOTION IS LIMITED. CHECKED OUT AND FOUND THAT THE PLASTIC COVER ON THE LIGHT WAS BINDING ON IT. CUT OFF SMALL SECTION OF THE PLASTIC COVER AND HAS FULL RANGE OF MOTION NOW. J.W.



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V37942

In Date: 01/20/2011
Close Date: 02/14/2011

Meter Reading: 40,876.00

Problem?

Left head light out r73

Task performed:

Replc headlight at strn. j

Parts	Quantity
H4651USE CV TYPE SEALED BEAM	1
H4656USE CV TYPE HEAD LIGHT	1

Workorder: V38260

In Date: 02/03/2011
Close Date: 02/14/2011

Meter Reading: 41,622.00

Problem?

The sliders on the draw that hold our sharps and medical waste bearings came out and the draw will not go back in it is on the floor. R73

Task performed:

R/R both slides to door; remnt tracks & drill holes to fit new ones; ok now.

Parts	Quantity
2220-145632-14 DRAWER SLIDE	2

Workorder: V38099

In Date: 01/27/2011
Close Date: 02/18/2011

Meter Reading: 41,333.00

Problem?

Left front scene light is out and right turn signal on front fender is out. r73

Task performed:

C/O light; looked at both - all working ok at this time; repaired at earlier date. j

Parts	Quantity
NO PARTS USED	



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V38639

In Date: 02/19/2011 Meter Reading: 42,281.00
Close Date: 02/25/2011

Problem?

starts very rough and runs very rough at idle R73

Parts	Quantity
-------	----------

Task performed:

Hard start, rough running complaint; no codes & truck ran
_____ . j

NO PARTS USED

Workorder: V38662

In Date: 02/21/2011 Meter Reading: 42,443.00
Close Date: 02/28/2011

Problem?

right brake flasher out r73

Parts	Quantity
-------	----------

Task performed:

Travel to Stn73; C/O light; truck not there, will go back. j

NO PARTS USED

Workorder: V38712

In Date: 02/23/2011 Meter Reading: 42,443.00
Close Date: 02/28/2011

Problem?

Left rear lower brake light is not stobing when brakes are applied. R73

Parts	Quantity
-------	----------

Task performed:

Rep on W.O. 38742. j

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V38742

In Date: 02/23/2011 Meter Reading: 42,443.00
 Close Date: 02/28/2011

Problem?

Bottom clear left brake light works off and on. Also some water was noted inside the light.R73

Parts	Quantity
-------	----------

Task performed:

Travel to Stn73; C/O light, R/R tir 6 & set to flash; ok. j

50R03ZCRLIGHT LED RED TIR 6	1
-----------------------------	---

Workorder: V38544

In Date: 02/15/2011 Meter Reading: 41,847.00
 Close Date: 03/03/2011

Problem?

the windows in the pt compartment stay frosted all the time the sensor was switched out and the windows still stay frosted. r73

Parts	Quantity
-------	----------

Task performed:

Installed new inverter on window; did not fix; need new window installed. j (2/25/11) need new window - deferred to shop Travel to Stn73; R/R windows & inverter. j (3/3/11)

10006527WINDOW INVERTOR	2
10007599WINDOW HORTON	3



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V39528

In Date: 03/29/2011
Close Date: 04/18/2011

Meter Reading: 43,758.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED R 73

Task performed:

B-Inspection 2. Rear scene light out; R/R bulb. 3. R/R brkn aut-eject cvr. 4. R/R oxygen wrench mnts. 5. Paint fuel cap. 6. Oxygen latch faulty; rep latch. 7. Tighten loose trim on squad bench. 8. R/R trans. 9. R/R rear diff. 10. T-shoot insjector code; starting going thru steps on servicemaxx. 11. Cln rear/left side of motor; fnd oil leaking frm valve cvr gskt; rem/chk valve lash frm injector; T-shoot; R/R gskt. 12. Suspect EGR cooler leaking; rem cooler & set up plugs/fittings to test; EGR cooler not leaking; fnd out press tester faulty; put EGR back on. 13. Wash eng to find oil leak; fnd fuel leak at bottom of fuel filter hsng; tighten cvr section screws; road test/rechk. 14. Install A/C blower motor & reassem R/S dash. j

Parts	Quantity
091-3YWCOVER KUSSMAUL AUTO EJECT	1
15W40BSYN OIL BULK QTS	30
1850500C92VALVE COVER GASKET INT.	1
1873940C3RAD HOSE	3
1875808C1GASKET EGR COOLER	3
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
2602872C91SURGE TANK	1
29526898 29548988 TRANS FILTER ALLISON	1
3536182C1RESET BREAKERS NEW HORTONS	1
3553628C3SHOCK REAR WPB	2
5774457744XD OIL FILTER	1
75W90GEAR OIL SYN QT	14
ANTICOOLANT ANTIFREEZE GAL	3
F6DZ-8100-A9C3Z8101B RADIATOR CAP 10238 STAI	1
H35SN12BULB	1
TRANSYNDALLISON TRANS FLUID GAL	5



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V39393

In Date: 03/23/2011
Close Date: 04/19/2011

Meter Reading: 43,461.00

Problem?

spoke to BC and he said it was ok to put on FOG lights and the rumbler on the rescue. sta73.

Task performed:

1. Fab brckts; paint brkts; drill holes mnt lights; run wiring to switch frm fuse panel ign source; mnt switch on dash; test. 2. Fnd cab blower motor fuse burned; contacts loose; rem tem from fuse panel block; bend term for more tension; reinstall in block; install 30 AMP ckt brkr instead of fuse & test opn. 3. Mnt fog lite; relay & wire grnds & power. j

Parts	Quantity
5291FOG LIGHTS	1

Workorder: V40296

In Date: 04/30/2011
Close Date: 05/10/2011

Meter Reading: 44,741.00

Problem?

While attempting to turn the engine on, takes 10 secs or so to start. Not the norm for this truck. Even when plugged in all night. R73

Task performed:

Travel to Stn73; C/Co hard start problem; Chk fuel sys, etc.; poss hi-press pump bad or pump sensor; send to shop; swap out trk. j

Parts	Quantity
NO PARTS USED	



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V40426

In Date: 05/05/2011
Close Date: 05/19/2011

Meter Reading: 44,919.00

Problem?

REPAIR FUEL SYSTEM HARD START NO START

Task performed:

WARRANTY 1. T-shoot long start time; replc IPR valve w/updated valve. ; Assisted w/t-shooting & snapshots. 3. Replcd hi-press oil pump. 4. Installed updated hi-press oil line/fittings. 5. Finish hi-press oil pump replacement; added oil, ran/ck for leaks; ck ok; cleared codes; test drove, boxed & marked parts for warranty. 6. Fnd P/S return hose bad; R/R hose from box to reservoir; loomed & freed up hose; filled sys; ran/ck ok. 7. Install howler sirens; _____ installed howler, wired & loomed; fan/ck ok. j

Parts	Quantity
1882259C931882259C94 HIGH PRESSURE OIL PUMI	1
1893940C911893940C93 OIL LINE HIGH PRESS PUM	1
3591094C1FUEL FITTING	1
55020-04 MOMENTARY SWITCH WEATHERPROOF	1
CORECORE CHARGE	1
HOWLERSIREN	1

Workorder: V40736

In Date: 05/19/2011
Close Date: 06/01/2011

Meter Reading: 44,741.00

Problem?

mount equipment

Task performed:

1. C/O A/C inop; chk press w/guages; chk codes w/laptop; fnd sensor code keeping A/C off; clear codes, test sys - ok now. 2. Mnt eqmpt brkt for tools; mnt glove holders; mov MIC mnts; travel to Stn73. j

Parts	Quantity
NO PARTS USED	



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V40774

In Date: 05/22/2011 **Meter Reading:** 44,741.00
Close Date: 06/06/2011

Problem?

circular airhorn bracket is broken off on driver's side. It is the bracket that encircles around the horn and has one bolt attaching to the fender. Needs new bracket, bolt is present. R 73

Parts ----- Quantity -----

Task performed:

R/R horn brkt that was brkn. j

GRV1720244770R1 HORN SUPPORT BRKT	1
-----------------------------------	---

Workorder: V41111

In Date: 06/05/2011 **Meter Reading:** 44,741.00
Close Date: 06/08/2011

Problem?

Vehicle has trouble starting; this happened yesterday morning, dispch notified to call mechanic for questions, last night and again this morning vehicle hasd trouble starting, check enging light comes on and off R73

Parts ----- Quantity -----

Task performed:

Went to 73; started truck; started ok; cld not access computer; load test btry; ck ok; clnd cables; ck charging/shoreline sys; ck ok; NPF; return home. j

NO PARTS USED

Workorder: V41218

In Date: 06/09/2011 **Meter Reading:** 44,741.00
Close Date: 06/13/2011

Problem?

on call wont start r 73

Parts ----- Quantity -----

Task performed:

Intermittant no start; brought to shop to swap out. j

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V41212

In Date: 06/08/2011
Close Date: 07/13/2011

Meter Reading: 44,741.00

Problem?

SPINS OVER BUT WILL NOT START SEVERAL ATTEMPTS MADE. THE IT STARTED FINE, AFTER SEVERAL MIN. INTERMITENT R 73

Task performed:

1. Chk code; fnd (8) codes; printed code & cleared them; the came back active so went to ISTS t-shooting; fnd code 1113 was to be for ECM; it said to chk if ECM fuse & relay; fnd bad relay; R/R relay; all codes cleared & did not come back. 2. Assist w/service maxx t-shooting. 3. Chk first thing next morning to see if it wld start; it started good; went to test drive; drove good & no codes; top off windshield wiper wash tank. 4. Started truck after sitting all night; it started good but set a code 4571 (cyl one balance may limit exceeded); cleared the code; test drove & run KDEO test & KOER test on code; trk run good. j

Parts	Quantity
3505300C1RELAY	1

Workorder: V41624

In Date: 06/27/2011
Close Date: 07/13/2011

Meter Reading: 44,741.00

Problem?

replace front tire r73

Task performed:

Replace front tire R73 - Boulevard j

Parts	Quantity
NO PARTS USED	

Vendor? BOULEVARD



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V41987

In Date: 07/13/2011 Meter Reading: 47,605.00
 Close Date: 07/18/2011

Problem?

Driver side marker light on pt. compartment is out. Sta 73.

Task performed:

TRAVEL TO ST 73 R&R UPPER MARKER LIGHT AND REWIRE AK

Parts	Quantity
CLR9185209186-1500-20 MARKER LT.AMBER LED	1

Workorder: V41986

In Date: 07/13/2011 Meter Reading: 47,605.00
 Close Date: 08/15/2011

Problem?

Driver compartment door shock is broken. Sta 73.

Task performed:

CHECK OUT DOOR CHOCK REINSTALL ON UNIT REPLACE PINS AK
 Take driver to store where truck is; brok down - no spark; go back to shop
 rob parts off another trk; wan't coil; go back to shop for tow trk; told to tow
 back to shop. 3. Assist John in bringing truck to shop. 4. Rem air clnr &
 air tube; rem dist. cap; ck for 5V ref; cut, t-shoot & repair wires; replc fuse
 at inside fuse panel w/new harness; ck ok. j

Parts	Quantity
02840875DOOR CLEVIS CLIP	7

Workorder: V43149

In Date: 08/29/2011 Meter Reading: 49,747.00
 Close Date: 09/06/2011

Problem?

Paint chipping off of front between bumper and grill R 73

Task performed:

travel to st 73 travel to st 72 check out paint falling off let ed know take picture of paint

Parts	Quantity
NO PARTS USED	



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V43557

In Date: 09/09/2011 Meter Reading: 50,425.00
 Close Date: 09/21/2011

Problem?

Shoreline cover is missing on outside of R73.

Task performed:

travel to station 73 changed shoreline cover on r 73

Parts	Quantity
091-3YWCOVER KUSSMAUL AUTO EJECT	1

Workorder: V43750

In Date: 09/19/2011 Meter Reading: 50,640.00
 Close Date: 09/27/2011

Problem?

Driver headlight does not work correctly. Doesn't want to stay on while driving at night. Light flickers on sometimes. Also causes passenger light to work incorrectly if you keep attempting to use the switch constantly, Sta 73.

Task performed:

changed head light bulb

Parts	Quantity
9007H9007 BULB ASSY	1

Workorder: V43849

In Date: 09/22/2011 Meter Reading: 50,640.00
 Close Date: 09/28/2011

Problem?

Still difficult to start, worse when cold. Right front tire excessively worn on outside edge. Sta 73.

Task performed:

travel to station driver complaint truck steering shaking while driving found front passenger tire needs replaced

Parts	Quantity
NO PARTS USED	



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V44189

In Date: 10/05/2011
Close Date: 10/06/2011

Meter Reading: 50,640.00

Problem?

REPLACE TIRES

Parts ----- Quantity -----

Task performed:

boulevard tire center service call reg hours mount dismount med trk 8oz
micro bal beads 10oz micro bal beads med trk med trk valve med trk tire
stm scap stat of fl tire fee 5 b stone tires

NO PARTS USED

Vendor? BOULEVARD



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V43607

In Date: 09/12/2011

Close Date: 10/13/2011

Meter Reading: 51,072.00

Problem?

C INSPECTION R 73

Parts

Quantity



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Task performed:

C INSPECTION ASSISTED WITH SERVICE MAXX DIAGNOSIS AND DPF CLEANING ENGINE ICP CODE 2335, SERVICE MAX DIAGNOSE AND DPF CLEANING OF EXHAUST SYSTEM, ROAD TEST AND RECHECK FOR CODES, CLEARED ENGINE HARD START, SERVICE OF OIL AND ROAD TEST, NOT START AS NORMAL OPERATION REQUIRED PAINT STRAPPING ON FRONT HEAD LOWER BODY MOLDING, REMOVE HEAD STRAP OUT SIDE FENDER REPAIR INSTALL BODY MOLDING AND CLEAN AND WAX REAR END BREATHER FITTING BROKE OFF, EXTRACT BROKEN FITTING FROM DIFFERENTIAL HOUSING, CLEAN AREA, INSTALL NEW 90 DEGREE FITTING AND SECURE BREATHER TUBE AIR BAGS DAMAGE CUTS AND SLASHES, REMOVE AIR BAG SERVICE AIR DRYER L2 DOOR PANEL LOOSE, SECURE DOOR PANEL SCREWS L2 DOOR STRUT LOOSE, FOOT STRT HOLD DOWN SCREWS WORN, REPLACE SCREWS L2 TOOL HOLDER LOOSE, SECURE TOOL HOLDER AND REPLACE MISSING SCRES BOTH SIDE BACK UP LIGHT 10-7, REMOVE ASSEMBLY FOUND BULBS BLOWN, CLEAN ASSEMBLY AND INSTALL NEW BULBS TRAUMA CABINET HANDLE LOOSE, SECURE LOOSE CABINET HANGLE PATIENT COMPARTMENT ELECTRICAL COMP LIGHT 10-7 REMOVE LBOWN BULB AND INSTALL NEW BULB O2 WRENCH MISSING INSTALL AND SECURE REPLACMENT O2 WRENCH L4 STRUT MOUNT LOOSE, DISASSEMBLE, SEVURE SHOC MOUNT AND REASSEMBLE FOG LIGHT FULL OF WATER, DISAAEMBLE, DULL DRAIN L--AND REASSEMBLE COOLANT COP FAIL PSI TET, REPLACE COOLANT CAP WITH NEW CAP INTALL HEA COOLANT SHUT OFF VALVES REPLACE DIRTY CAB AND PATIENT COMPARTMENT A/C FITLERS OIL AT TURBO BREATHER TUBE ----OI --UNIT NO LEAKS AT THIS TIME ELECTICAL CABLE HANGING LOOSE ON FRAME, SECURE ELECTRICAL CABLE TO FRAME SUPPORT BATTERY BOX SLICE INOP, DISASSEMBLE AND REMOVE DEFECTIVE SLIDER, CLEAN --, INSTALL NEW BATTERY TRY AND SLIDER ASSEMBLY SERVICE PWOER STEERING FLUID AND FILTER TRANSMISSION FLUID LOW, CHECK FOR LEAKS, NONE FOUND, AD 1/5 QUARTS OF TRANSMISSION FLUID TIME MONITOR 10-7, REMOV SYSTEM, INSTALL SENSORS AT TIRE 3 INSTALLED AND ON BACK ORDER, AIR TIRES TO 110 PSI AS PER MANUFACTORY SPECS

02841108BATTERY TRAY KWIKEE	1
065624AD-IP DRIER	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	28
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
2507061C1PS RESV GASKET	1
366555GTL6 13 X 19 FILTER	2
388863HOSE KIT	2
4DA2545W LAMP	2
546126000TPM/QG HALE REPAIR KIT	1
5774457744XD OIL FILTER	1
75W90GEAR OIL SYN QT	10
78R539018-2699 A/C FILTER	1
AS75807OXM1757-01 OXYGEN WRENCH	1
F6DZ-8100-A9C3Z8101B RADIATOR CAP 10238 STAI	1
GUI1R11216GY1R11216 AIR BAG INT.	1
HLD3999GSS1715UV 30LB STRUT GAS	3
K022105PURGE VALVE AD-IP-IS	1
RWTG1234LED PRESSURE CAP	4
TRANSYNDALLISON TRANS FLUID GAL	1
VML/T1808D2503221C1 FILTER POWER STEERING	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

CABINET STRUTS WEAK, REMOVE AND INSTALL NEW STRUTS,
 PATIENT COMP CABINET LATCH 10-7, DRILL TAP LATCH AND INSTAL
 SLIDE HANDLE TO LATCH AND SECURE SECURE LOOSE TOOL
 HOLDER IN COMP L2

Workorder: V44120

In Date: 10/03/2011 **Meter Reading:** 50,640.00
Close Date: 10/18/2011

Problem?

REPLACE BODY MOUNTS R 73

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

body mount, lift and set box on jack stan, remove 110 a/c condensor,
 remove body mount, install new body mounts and reassemble unit

Workorder: V44584

In Date: 10/21/2011 **Meter Reading:**
Close Date: 10/25/2011

Problem?

rear door light flash when door is closed

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

Travel to stn73; C/O rear door buzzer on chem switches; order new rear
 door switch. j



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V44112

In Date: 10/03/2011
Close Date: 11/04/2011

Meter Reading: 50,640.00

Problem?

REPLACE AIR PRESS MONITORS ON FRONT PARTS ORDERED

Task performed:

Travel to stn73; replc press monitors on all tires; set air press to level test ok; return to shop. j

Parts	Quantity
RWTG1234LED PRESSURE CAP	6

Workorder: V45199

In Date: 11/15/2011
Close Date: 11/21/2011

Meter Reading:

Problem?

windshield wipers need replacements. R73

Task performed:

travel to st 73 try to regen syst.dpf plugged up remove dpf return to shop r&r wipers

Parts	Quantity
91-22WIPER BLADE	2

Workorder: V45224

In Date: 11/16/2011
Close Date: 11/23/2011

Meter Reading: 52,575.00

Problem?

Exhaust plug,Sta 73

Task performed:

go to shop pick up dpf, travel to st 73, install test, drive truck, get check eng light off, still inop, will return with laptop travel to st 73 hook up laptop, do dpf cleaner test, test drive unit, still inop, redo test, test drive again, check injectors, need to go to sop, still in de--ate mode, return to shop

Parts	Quantity
NO PARTS USED	



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V45092

In Date: 11/10/2011 Meter Reading:
Close Date: 11/29/2011

Problem?

Officer side Rear scene light inop R73

Task performed:

travel to st 73 check out rear light r&r bulb

Parts	Quantity
H50SN12BULB	1

Workorder: V45391

In Date: 11/23/2011 Meter Reading: 52,575.00
Close Date: 12/01/2011

Problem?

R73 engine performance issues. Oil diluted with fuel.

Task performed:

HOOK UP LAP TOP, CHANGE OIL AND FILTER, TAKE FOR TEST
DRIVE WITH STEVE REINSE, OK

Parts	Quantity
NO PARTS USED	

Workorder: V45677

In Date: 12/06/2011 Meter Reading: 52,575.00
Close Date: 12/06/2011

Problem?

install tiles in compt r 73

Task performed:

cut and install tiles for 2 compartments

Parts	Quantity
1212BTURTLE TILE 12X12 BLACK	14



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V45647

In Date: 12/05/2011
Close Date: 12/09/2011

Meter Reading: 52,575.00

Problem?

replace air bag r 73

Task performed:
r&r air bag

Parts	Quantity
GUI1R11216GY1R11216 AIR BAG INT.	1

Workorder: V45551

In Date: 12/01/2011
Close Date: 12/15/2011

Meter Reading: 52,575.00

Problem?

Low power.

Task performed:

TEST DROVE - FOUND LOW POWER, HISTORY OF PLUGGED AND D.P.F., ENGINE MISSING, EXCESSIVE EXHAUST SMOKE AND EXH. TEMP. H. ON AT ALL STOPS - HOOKED UP TO SERVICE MAXX - RAN ALL KOEO TESTS - PASSED RONALL ENG. RUN TESTS - PASSED. ASSIST TROUBLESHOOT AND REPAIR. LOW POWER CONT. RAN INJECTOR DISABLE TESTS - RAN RELATIVE COMPRESSON TEST - FOUND #1 AND #4 HIGH, #2,3,5 AND 6 UNEVEN AND LOW - REMOVED AIR CLEANER, VALVE COVER- CK VALVE LASH - CK OK - REMOVED VALVE COVER GASKET/INJ. HARNESS, HIGH PRESS. OIL RAIL LOW POWER CONT. ALL INJECTORS - FOUND INJECTOR TIPS PLUGGED ANDNOT ATOMIZING FUEL PROPERLY - REPLACED 6 INJECTORS - REPLACED OIL RAIL SEALS - REASSEMBLED ALL PARTS RAN ENGINE - TEST DROVE - CK OPERATION AND CODES - CK OK. ALL INJECTOR SER. #S ON BACK.

Parts	Quantity
1822135C1 214 ORING BREATHER INT.	1
1842626C951842626C96 OIL RAIL MANIFOLD SEALS	2
5010561R925010561R93 INJECTOR	6
CORECORE CHARGE	6



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V46150

In Date: 12/28/2011
Close Date: 12/30/2011

Meter Reading: 53,107.00

Problem?

- 1. When rear door closes the sensor doesn't register it, warning lights flash.
- 2. Heat/Cool damper isn't connected properly, heat doesn't work.
- 3. Remote control in Rescue doesn't open rear bay door #5. R73

Parts	Quantity
-------	----------

Task performed:

1. CHECK DOOR AJAR WARNING LIGHT - CHECK OPERATION WITH OFFICER - NO PROBLEMS FOUND - REMOVED AND CLEANED RIGH REAR PAT. DOOR SENSOR- CHECK DOOR ADJUSTMENT - CHECK OK. 2. CHECK FOR NO HEAT - OPENED HEATER SHUTT-OFF VALVE ON BOTH RESCUES.

NO PARTS USED

Workorder: V46085

In Date: 12/27/2011
Close Date: 01/04/2012

Meter Reading: 53,107.00

Problem?

drove off road.

Parts	Quantity
-------	----------

Task performed:

PULLED TRUCK OUT OF DITCH.

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V46411

In Date: 01/09/2012
Close Date: 01/10/2012

Meter Reading: 54,072.00

Problem?

CHECK ENGINE LIGHT

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

WENT TO 73 - CHECK OIL LEVEL - CHECK OK - CHECK FOR ENJGINE CODES - NO CODES RAN AND CHECK OPERATION - CHECK OK - FOUND RT. REAR CAB WINDOW AND LOCK IN-OP - REMOVED SW AMD RESET - CHECK OK. - RETURN HOME.

Workorder: V46970

In Date: 01/30/2012
Close Date: 02/01/2012

Meter Reading: 55,149.00

Problem?

Engine sounds like misfiring, "knocking and banging", yes oil is at proper levels, and regen system activated today, Sta 73

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

DIAGNOSE ENGINE PROBLEM. CHECKED RELATIVE COMPRESSION # 2 CY O. PERFORMED KO EO STANDARD TEST AND INJ TEST. REMOVE VALVE COVER FOUND #U CY1 ROCKERS LOOSE FROM BAD CAM, INSTALL VALVE COVER AND TOW TO DEALER.

Workorder: V47018

In Date: 02/01/2012
Close Date: 02/02/2012

Meter Reading: 55,149.00

Problem?

Engine running rough.

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

NO SPARE (IN SPARE?). MEET DRIVER AT SHOP TO SWAP OUT ANI BACK HOME.



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V47706

In Date: 03/02/2012
Close Date: 03/15/2012

Meter Reading: 55,755.00

Problem?

Check items from B inspection. Seat belts, engine oil leak, trans fluid level. p/s fluid level, battery test, air leaks.

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

1. TRAVEL TO ST 73 CHECK TRANS FLUID, P/S FLUID SOAP DOWN TK FOR AIR LEAKS. 2. CHECK OUT SEAT BELTS. 3. TEST BATTERIE: OK.

Workorder: V48261

In Date: 03/28/2012
Close Date: 04/06/2012

Meter Reading: 57,069.00

Problem?

COOLING FLUID LEAK. NOT VISIBLE, LEFT TURN SIGNAL WON'T STAY TIGHT TO FENDER. STATION NEEDS COOLANT FOR VEHICLES R 73

Parts	Quantity
-------	----------

2505876C91DASH VALVE	1
3561965C1LIGHT	1
ALA00350-50 EXTENDED LIFE COOLANT GAL	2
F6DZ-8100-A9C3Z8101B RADIATOR CAP 10238 STAI	1

Task performed:

1. TRAVEL TO ST 73 CHECK COOLANT LEVEL TOP OFF SYSTEM CHECK FOR LEAKS R&R RAD CAP GIVE EXTRA COOLANT. 2. TRAVE TO ST 73 R&R PARK BRAKE VALVE TEST OK NO LEAKS. 3. R&R HOOD TURN SIGNAL LIGHT.

Workorder: V48266

In Date: 03/28/2012
Close Date: 04/06/2012

Meter Reading: 57,069.00

Problem?

Stereo seems to be popping out of dash. Works. R 73

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

TRAVEL TO ST 73 CHECKOUT RADIO FOR LOOSENESS TIGHTEN SIDE BASE FOR HOLDER.



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V48276

In Date: 03/29/2012
Close Date: 04/06/2012

Meter Reading: 57,069.00

Problem?

Truck was leaning to the left when not started and when they went to start i there was no air in the brakes and lights and alarms were going off on dash r 73

Task performed:

TRAVEL TO ST 73 CHECK OUT AIR BAG SYSTEM CHECK SYSTEM FOR LEAKS FOUND PARK BRAKE LEAKING WILL RETURN WITH PARTS FOUND NO PROBLEM WITH AIR BAGS.

Parts	Quantity
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
GC2845A BATTERY GOLF CAR 135 AMP	4

Workorder: V48938

In Date: 04/27/2012
Close Date: 05/30/2012

Meter Reading: 58,437.00

Problem?

Interior front cab lights stay on R73

Task performed:

1. TRAVEL TO ST 73 CHECK OUT CAB LIGHTS ON TRUCK DOOR SENSORS BROKEN OFF R&R CAB DOOR SENSORS RETEST OK. 2. R&R BULB OUT IN PIA LIGHT CLEAN UP ALL RUSTED UP LUBE SOCKET REINSTALL LIGHT. 3. CHECK OUT BROKEN CHECK OUT LIGHT SWITCH NEED PART AND CHECK OUT BROKEN LED ON CAB DIDN'T HAVE PARTS GET LIGHT WORKING FOR NOW. 4. R&R BROKEN LIGHT ON DRIVER SIDE STEP.

Parts	Quantity
3579984C1DOOR SWITCH	4
3910010SW COVER LED	1
5TSMACMOUNT 500 TIR SER CHROME	1
H3LIGHT BULB BP1255/H3 H	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V49587

In Date: 05/23/2012
Close Date: 06/01/2012

Meter Reading: 59,183.00

Problem?

REPAIR A/C R 73

Parts	Quantity
-------	----------

Task performed:

TRAVEL TO ST 73 CHECK OUT A/C SYSTEM FREON LEAKING FROM H-BLOCK REMOVE H-BLOCK REPLACE O-RING RETAP BLOCK CLEAR THREADS ON BOLT REINSTALL ADD FREON RETEST OK.

NO PARTS USED

Workorder: V49384

In Date: 05/15/2012
Close Date: 06/13/2012

Meter Reading: 59,183.00

Problem?

AC in the front of the truck is blowing hot air.

Parts	Quantity
-------	----------

Task performed:

1. RECOVERED SYSTEM, REMOVED COMPRESSOR, DRYER AND EXPANSION VALVE. HAD TO DRILL OUT EXPANSION VALVE HOLD DOWN BOLTS (RUSTED). INSTALLED NEW EXPANSION VALVE AND DRYER. VACUUMED SYSTEM AND CHARGED. ALSO CHECKED DOC AND SWITCHES WITH LAPTOP. ALSO SYSTEMS WORKING NORMALLY AND COOLING PROPERLY. 2. DRAINED AND FILLED NEW COMPRESSOR - INSTALLED COMPRESSOR, LINES AND BELT - ASSIST IN A/C REPAIR.

3611894C9103-0805 A/C COMPRESSOR 4347	1
3660853C22512331C1 EXP VALVE NAV	1
3666273C1A/C DRIER NAV	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V50226

In Date: 06/19/2012
Close Date: 06/22/2012

Meter Reading: 61,391.00

Problem?

ON CALL FUEL LEAK R 73

Parts	Quantity
-------	----------

Task performed:

TRAVEL TO STA 73 - INSPECT TRUCK FOR DIESEL LEAKAGE. COUL NOT FIND FUEL LEAK. FOUND COOLANT LEAK AT LOWER TURBO HOSE CLAMP AND EGR COOLER CLAMP. TIGHTENED CLAMPS. RUI VEHICLE OK.

NO PARTS USED

Workorder: V47370

In Date: 02/16/2012
Close Date: 06/27/2012

Meter Reading: 55,209.00

Problem?

B INSPECTION R 73

Parts	Quantity
-------	----------

Task performed:

1. B-SERVICE. 2. REPLACE ENGINE COOLANT HOSE LEAK ON MOTOR AND CLAMPS. DELIVER TRUCK TO STA 23. 3. B-SERVICE. 4 R&R REAR BRAKE SHOES AND DRUMS. 5. DRIVE UNIT BACK TO 73, RETURN TO SHOP.

1878042C91FUEL FILTER 2008 HORTON	1
211-2BULB	2
3757REAR DRUMS 3757X 3647X	2
46870AIR FILTER	1
5774457744XD OIL FILTER	1
6092036018J HOOK STRYKER	1
XK4034707QPMHD SHOE KIT 3/8 BEAM	2



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V50396

In Date: 06/26/2012
Close Date: 06/28/2012

Meter Reading: 61,391.00

Problem?

small of fuel in cab r 73

Task performed:

1. TRAVEL TO ST 73 CHECK FUEL LEAK ON R73 FOUND FUEL LEAK AND COOLANT LEAK ORDER PARTS SWAP OUT INTO SPARE. 2. TRAVEL TO ST 73 AND REPAIR FUEL LINE AT FUEL FILTER HOUSING
3. REPAIR EGR VALVE COOLANT HOSE PRESSURE TEST SYSTEM.

Parts	Quantity
3591094C1FUEL FITTING	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V50625

In Date: 07/05/2012
Close Date: 07/27/2012

Meter Reading: 61,713.00

Problem?

C INSPECTION R 73

Task performed:

1. C INSPECTION 2. C INSPECTION 3. RESECURE GROUND LIGHTS.
 4. SERVICE AIR DRYER. 5. R&R REAR SHOCKS. 6. FREE UP, CLEAN AND LUBE BATTERY TRAY. 7. CHECK FOR AIR LEAKS REPLACE GOVERNOR AND FITTINGS AND MISCELANNOSE QUICK CONNECT FITTINGS. 8. R&R FRONT SHOCKS. 9. CHECK FOR LEAKS ON 111V A/C, RE-CRAMP FITTINGS AT CONDENSOR. 10. RE-SECURE CENTE
 CONSOLE DRILL NEW HOLES NUT AND BOLT FROM UNDER TRUCK
 11. REPLACE ALL A/C FILTERS. 12. CHECK FOR COOLANT LEAKS TIGHTEN ALL HOSE CLAMPS, REPLACE WITH SILICONE HOSE CLAMP. 13. R&R ENGINE BELTS. 14. ADJUST AIR HORNS. 15. REPAI
 SQUAD BENCH LATCHES. 16. TIGHTEN LUBE AND ADJUST ALL DOC LATCHES.

Parts	Quantity
065624AD-IP DRIER	1
10005596GRABRAIL	2
103385NDRAIN COCK	2
1501450007750USE 0775145	2
1847727C1BELT	1
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	2
284358GOVERNOR D-2	1
3553628C3SHOCK REAR WPB	2
3578105C2FRONT SHOCKS	2
5774457744XD OIL FILTER	1
K022105PURGE VALVE AD-IP-IS	1
K060695BELT	1
RD5-6526-1MOTOR BLOWER REAR CAB UNIT HOR	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V50465

In Date: 06/28/2012
Close Date: 08/03/2012

Meter Reading: 61,713.00

Problem?

R73 leaking diese fuel after the last call approx:20:00, a fuel leak was apparently repaired last shift unit put back in service on 6/27/12 Shop personnel was called when put out of service, spair unit in service

Task performed:

1. CLEAN UNDER SIDE OF TRUCK, LOOK FOR LEAKS, TAKE FOR DRIVE, LEAK COMING FROM UPPER L/R OF ENGINE. 2. START TO REMOVE CENTER CONSOLE AND DOG HOSE TO PIN POINT SOURC OF LEAK. 3. FINISH REMOVAL OF CENTER CONSOLE AND DOG HOSE. 4. REMOVE PLUG FROM REAR OF FUEL RAIL ON TOP OF INTAKE. INSTALL NEW O-RING TORQUE TO 18 FT. LBS STILL LEAKING, COMING FROM GASKET. 5. TORQUE ALL ACCESSABLE BOLTS TO 45 FT. LBS, RESTART TRUCK LET RUN, GASKET STILL LEAKING. 6. START REMOVAL OF INTAKE MANIFOLD. 7. CONTINUE REMOVAL OF MANIFOLD. 8. INSTALL NEW INTAKE MANIFOLD AND GASKETS. 9. INSTALL NEW MANIFOLD AND GASKET, TORQUE ALL BOLTS TO 45 FT. LBS. 10. TAKE TRUCK FOR LONG TEST DRIVE, CHECK FOR LEAKS OK.

Parts ----- Quantity -----

1842033C1GASKET	1
1845023C1GASKET	1
1870742C92MANIFOLD INTAKE	1
1873906C1SEAL FUEL FILTER HSG	1
1875808C1GASKET EGR COOLER	1
3533426C3FUEL FITTING	1
3591094C1FUEL FITTING	1
6360-030-031RED KNOB	1
6360-30-11LARGE FLOOR PLATE	1

Workorder: V51292

In Date: 08/01/2012
Close Date: 08/09/2012

Meter Reading: 61,966.00

Problem?

cab a/c blowing hot air intermitantly. Noticed compressor clutch not turning. r 73

Task performed:

TRAVEL TO STATION CHECK A/C ON CAB.

Parts ----- Quantity -----

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V51488

In Date: 08/09/2012 Meter Reading:
Close Date: 09/11/2012

Problem?

Left rear axle/hub cap missing. R73

Parts	Quantity
-------	----------

Task performed:
REPAIRED ON WO #51282

NO PARTS USED

Workorder: V51742

In Date: 08/20/2012 Meter Reading:
Close Date: 09/17/2012

Problem?

AC not blowing cold both units. R73

Parts	Quantity
-------	----------

Task performed:
TRVL TO 73 TK AT HQ TRVL TO HQ CHK OUT A/C SYST FOUND FAN
MODE NOT WORKING REPAIR MODE TEST.

NO PARTS USED

Workorder: V52225

In Date: 09/07/2012 Meter Reading: 63,945.00
Close Date: 09/21/2012

Problem?

REPAIR 110 A/C R 73

Parts	Quantity
-------	----------

Task performed:
TRVL TO ST 73 R&R POWER SUPPLY FOR UNIT AND REWIRE UNIT
RETURN TO SHOP.

90-9117SAME AS PD9160A POWER SUPPLY DANHA	1
---	---



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V51087

In Date: 07/24/2012
Close Date: 09/24/2012

Meter Reading:

Problem?

Rear a/c thermostat (shoreline a/c) is inoperable. Rear a/c runs for 1 - 2 minutes after plugging in shoreline, thermostat screen goes blank, and defaults back to 85 degrees. Unable to keep pt. compartment cool. R 73

Parts	Quantity
-------	----------

Task performed:

TRVL TO 73 CHK OUT A/C SYST IS GOING OFF R&R THERMASTATE UNIT AND REWIRE TEST ONE FAN UNDER IT IS OUT OF ORDER TEST AND RETURN LATER.

50-1500USE FAN KIT PANCAKE MOTOR DANHARD	2
TH5220D1003WALL THERMOSTATE HORTON	2

Workorder: V52801

In Date: 10/02/2012
Close Date: 10/12/2012

Meter Reading:

Problem?

Needs new windshield wippers. Slow air leak. R 72

Parts	Quantity
-------	----------

Task performed:

TRVL TO ST 72 R&R WIPERS CHK FOR AIR LEAKS REPAIR LEAKS O LINES AND AIR TANKS.

91-22WIPER BLADE	3
------------------	---



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V52952

In Date: 10/09/2012

Meter Reading: 66,276.00

Close Date: 10/29/2012

Problem?

B INSPECTION AND NEEDED REPAIRS

Task performed:

1. B-Inspection. 2. Check for coolant loss - marked res. tank test drove. 3. Check for air leaks - sprayed fittings, drains and air level valves found left level valve fitting leaking. 4. Found air tank mounts broken or air bags removed airlines, mount plate, tanks and brackets. drilled and installed new tank mounts. 5. repair air tank cont. Reinstalled mount plate and lines. Check for leaks. Check ok. 6. Repair air leaks cont. Removed lines and fittings at level valve. 7. Repair air leaks cont. Resealed air fittings - reassembled all parts - ran and checked ok. Found air horn solenoid leaking removed lines, mounting block and solenoids r&r solenoid. Reassembled check ok. 8. Repair air leaks cont. found fittings on rt level valve r&r fittings - Ran and check ok. 9. Found air tank mount cables loose tightened all cables checked ok. 10. R&R wiper blades - repair batt. switch knob cleaned a/c condensers. 11. Check engine oil leak - found oil pressure sending unit leaking R&R sending unit ran and check ok. 12. Check cab step lights found lights inop traced wires repaired wires check ok. R&R cab door light bulbs. 13. Check for coolant loss - pressure test system found hose behind turbo leaking could not hose clamps off drained coolant removed air cleaner. 14. Check for coolant loss cont. removed air tubes, fender, brackets, water pipe from EGR cooler and pipe to front cover. Replaced hose, clamps and O-rings reinstalled pipes. 15. Check for coolant leaks cont. Finish assembling parts - R&R clamps - filled rad. 16. Check for coolant leak cont. Repaired other clamps test drove check ok. 17. Check map light out removed console control panel- Repaired wire connection - check ok. 18. Q.C. truck.

Parts

Quantity

1157BULB	2
15-40B15W40 MOTOR OIL NON SYN	30
1839415C91OIL PRESSURE SENSOR	1
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
2506713C91AIR HORN SOL	1
357884 IN CLAMP	2
5774457744XD OIL FILTER	1
57746XDOIL FILTER ISL CUMMINS	1
91-22WIPER BLADE	2
RWTG1234LED PRESSURE CAP	2



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V53349

In Date: 10/28/2012
Close Date: 10/31/2012

Meter Reading: 66,460.00

Problem?

The door open visual alarm continues to blink. Unable to determine which door indicator is not making contact. R 73

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

WAIT FOR TK. CHECK OUT DOOR OPEN WARN ALARM FOUND MAGNET ON REAR DOOR WEAK R&R MAGNETS AND SWITCHES ON REAR DOORS.

Workorder: V53379

In Date: 10/30/2012
Close Date: 10/31/2012

Meter Reading: 66,460.00

Problem?

Red light for the door sensor is on in the cab. All doors are secure. R73

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

REPAIRED ON W O # 53349.

Workorder: V53495

In Date: 11/02/2012
Close Date: 11/08/2012

Meter Reading:

Problem?

slight air leak when parked for period of time.

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

TRAVEL TO ST 73 CHK FOR AIR LEAKS FOUND ONE IN DASH REPAIR LINE.



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V53954

In Date: 11/22/2012
Close Date: 12/03/2012

Meter Reading:

Problem?

Air brakes are leaking. The truck will not hold air pressure. R73

Task performed:

1. FOUND FITTINGS FOR AIR BAGS LEAKING. 2. CHANGED FITTINGS. FOUND BRAKE (FOOT VALVE) LEAKING CHANGED VALVE AND ALL FITTINGS.

Parts	Quantity
800629 VALVE THROTTLE FOOT	1

Workorder: V53887

In Date: 11/19/2012
Close Date: 12/04/2012

Meter Reading:

Problem?

Air leak in the rear of the truck the Air dump loses air after truck is shut off. the right fog light is not working, The red light in the front cab of the truck keeps flashing when truck is driving. prob. sensor. r73

Task performed:

1. CHECK FOR AIR LEAKS REPAIR LINES AND FITTINGS ON TANK. 2 CHECK D.O.W SYSTEM. R&R REAR DOOR SWITCHES AND REWIRE.

Parts	Quantity
03910021DOOR MAGNETS	2
H3LIGHT BULB BP1255/H3 H	1

Workorder: V54277

In Date: 12/06/2012
Close Date: 12/19/2012

Meter Reading: 68,087.00

Problem?

REPLACE TIRE

Task performed:

REPLACE TIRE.

Parts	Quantity
NO PARTS USED	

Vendor? BOULEVARD TIRE



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V54577

In Date: 12/23/2012
Close Date: 01/17/2013

Meter Reading:

Problem?

Over head light in the cabin would not shut off, so we removed the light. R7

Parts	Quantity
-------	----------

Task performed:

CHECK OUT DOOR SWITCHES, OK R&R UPPER LIGHT ASSY SWITCH BAD.

3626066C1DOME LIGHT ASSY	1
--------------------------	---

Workorder: V55180

In Date: 01/20/2013
Close Date: 01/28/2013

Meter Reading:

Problem?

The ac is not blowing cold air when plugged in to the shoreline of the station.

Parts	Quantity
-------	----------

Task performed:

CHECK OUT A/C FOUND CONDENSER FANS OUT PULL UNIT R&R FANS AND REWIRE.

50-1500USE FAN KIT PANCAKE MOTOR DANHARD	2
--	---

Workorder: V54304

In Date: 12/08/2012
Close Date: 01/31/2013

Meter Reading:

Problem?

air leaking. brake pressure drops when truck off. R73

Parts	Quantity
-------	----------

Task performed:

TRAVEL TO ST 73 CHECK FOR AIR LEAKS REPAIR LEAKING HOSES AND R&R FITTINGS RETEST OK.

NO PARTS USED	
---------------	--



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V55494

In Date: 02/02/2013 Meter Reading: 70,449.00
 Close Date: 02/20/2013

Problem?

Driver side fog light is not working. R 73

Task performed:

TRAVEL TO ST 73 R&R BULB TURN LIGHT OVER WATER GETTING II LIGHT.

Parts	Quantity
H3LIGHT BULB BP1255/H3 H	2

Workorder: V56018

In Date: 02/26/2013 Meter Reading:
 Close Date: 02/27/2013

Problem?

left front driver tire needs to replaced R73

Task performed:

LEFT FRONT DRIVER TIRE NEEDS TO BE REPLACED R73.

Parts	Quantity
NO PARTS USED	

Vendor? BOULEVARD TIRE

Workorder: V56184

In Date: 03/06/2013 Meter Reading: 72,601.00
 Close Date: 03/18/2013

Problem?

Right side exhaust cover is loose because the bracket that is bolted on the exhaust is broken. No hurry. R-73

Task performed:

TRAVEL TO ST 73 R&R EXHAUST COVER AND REPLACE BROKEN CLAMPS CUT OFF BROKEN BOLTS INSTALL COVER AND NEW BOLTS.

Parts	Quantity
3599692C1CLAMP EXH SHIELD	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V56448

In Date: 03/17/2013
Close Date: 03/21/2013

Meter Reading: 73,193.00

Problem?

REAR DRIVERS SIDE DOOR NEEDS TO BE REALIGNED.. RUBBING WHEN OPENED R73

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

1. TRAVEL TO ST 73 CHECK DOOR ADJUST DOOR AND LUBE. 2. REAR BODY SIDE SOOR NOT CLOSING CORRECT ADJUST DOOR STRIKER AND LUBE.

Workorder: V51282

In Date: 08/01/2012
Close Date: 04/04/2013

Meter Reading:

Problem?

drivers side rear hub cap fell off. All parts retrieved????

Parts	Quantity
-------	----------

10002417LOGO HORTON HUBCAP	2
10006871MOUNTING BOLT HUBCAP	2
10006872BRKT HUBCAP COVER	2

Task performed:

1. R&R HUB CAP HARDWARE ON WHEEL REINSTALL HUB CAP ASS' CHK OUTTER SIDE.

Workorder: V53714

In Date: 11/12/2012
Close Date: 04/08/2013

Meter Reading:

Problem?

per Lt. cab is leaning back towards box

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V56578

In Date: 03/21/2013
Close Date: 04/08/2013

Meter Reading: 73,498.00

Problem?

Drivers window control cover torn; switch exposed. R-73

Task performed:

TRAVEL TO ST 73 R&R DRIVER WINDOW POD ON DRIVER SIDE.

Parts	Quantity
3544935C6DOOR POD L/H NAV	1

Workorder: V56921

In Date: 04/09/2013
Close Date: 04/12/2013

Meter Reading: 73,963.00

Problem?

check engine light

Task performed:

1. SCAN COMPUTER FOUND FAULTY ICP SENSOR. REMOVE VALVE COVER AND REPLACE ICP SENSOR. 2. DRAIN AND REFILL OIL OVER FULL. 3. TEST DRIVE AND RECHECK CODES TOP OFF ALL FLUIDS.

Parts	Quantity
1875784C921875784C93 ICP SENSOR	1
RWTG1234LED PRESSURE CAP	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V56931

In Date: 04/10/2013

Close Date: 04/29/2013

Meter Reading: 73,963.00

Problem?

C INSPECTION R 73

Parts

Quantity



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Task performed:

1. C INSPECTION. 2. FINISH C INSPECTION. 3. REPLACE EJECT DOOR. 4. DRAIN RADIATOR AND REPLACE EGR HOSES ON LEFT SIDE PULL CROSS OVER TUBE AND CHECK COOLERS NO SIDES OF COOLERS LEAKING. 5. REMOVE ACCREDATION STICKERS. 6. TIGHTEN ALL COMPARTMENT SCREWS AND DOOR STOPS. 7. INSTALL ENGINE AIR FILTER. 8. INSTALL BACK UP CAMERA. 9. INSTALL REAR LOAD LIGHT. 10. INSTALL RADIATOR DRAIN VALVE REFILL SYSTEM AND PRESSURE TEST COLD AND HOT. 11. REMOVE SQUAD BENCH SEND OUT TO BE FIXED. 12. CHECK AIR LEAKS. 13. TEST DRIVE TO VERIFY EGR LOADERS OK. 14. INSTALL L/F DOOR SEAL. 15. DIAGNSE A/C SYSTEM REPLACE BELND DOOR MOTOR AND MODE DOOR MOTOR. 16. REVIEW REPAIR SEGMENTS, MOVE TRUCK TO OTHER BAY, MOVE ALL PARTS FOUND MORE REPAIRS. ORDERED PARTS. 17. REPAIR A/C FOUND FRESH AIR SERVICE DISASSEMBLED COULD NOT FIND LINKAGES FOR DOOR- FOUND COMPRESSOR DISCHARGE HOSE LEAKING- RECOVER FREON SERV. LEAKING. 18. REPAIR A/C DOOR ASSEMBLY- INSTALLED LINKAGE, SERVICE AND MOUNT, LEAK TEST. 19. REPAIR A/C REMOVED DISCHARGE HOSE- R&R DISCHARGE SERVICE VALVE. 20. REPAIR CRANK CASE FILTER- REMOVE AND TUBES, HOSES AN FILTER ASSEMBLY- DISASSEMBLED ASSEMBLY, CLEANED FILTER, HOUSING, HOSES AND AIR TUBES- REPPLACED GASKET AND SEALS. 21. REPAIR CRANK CASE FILTER CONT; INSTALLED HOUSING, HOSES AND TUBES- RAN AND CHECK OK. 22. REPAIR BATT CHARGER- RESET BREAKERS CHARGER- CHECK OK. REPAIF BATTERY CABLES AND TIED DOWN- ADJUSTED BATTERY DOOR LATCHES AND CHECK OK. 23. CHECK REAR BRAKES- FOUND REAF AXLES SLACK ADJUSTERS WORN REMOVED SLACKS- CLEANED SHIMS AND SNAP RING, REPLACED SLACK ADJUSTED. 24. CHECK REAR BRAKES CONT INSTALLED PINS AND PAWLS, ADJUSTED, GREASED AND CHECK OK. 25. REPAIR CAB A/C- REMOVED AIR CLEANER ASSEMBLY- INSTALLED DISCHARGE HOSE- VAC AND CHARGE A/C RAN AND CHECK OK- INSTALLED AIR CLEANER. 26. INSTALLED REPAIRED BENCH SEAT- R&R PAT A/C FILTERS- R&R WIPER BLADES. 27. SERVICE DRIER- R&R PURGE VALVE AND FILTER- RAN AND CHECK OK. 28. CHECK FOR COOLANT LEAKS-

065624AD-IP DRIER	1
091-3YWCOWER KUSSMAUL AUTO EJECT	1
15-40B15W40 MOTOR OIL NON SYN	30
1501450007750USE 0775145	2
16-31438915 VALVE CORE A/C 3544706C1	1
1846481C92SENSOR MAP	1
1875838C91SENSOR MANIFOLD AIR TEMP MAT	1
1875880C2SEAL	1
1876922C91SEAL KIT	1
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
2593986C1DPF GASKET	1
2593998C1DPF GASKET	1
3508972C6DOOR SEAL F	2
3542606C12611234C1 VENT ACTUATOR	4
3548695C1SCREW INSERT	1
435262HOSE AND FITTING	1
46870AIR FILTER	1
5774457744XD OIL FILTER	1
607141-05USE 61H01 COPMPARTMENT LIGHT	1
78R539018-2699 A/C FILTER	2
91-22WIPER BLADE	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	3
H35SN12BULB	1
HP-31DBATTERY 950CCA HP-31D	3
K022105PURGE VALVE AD-IP-IS	1
R802446AUTO SLACK ADJ	1
R802447AUTO SLACK ADJ	1
RWTG1234LED PRESSURE CAP	2
VCCS150VOYAGER CAMERA	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

PRESS TEST SYSTEM REPAIRED LEAKS AT RT LOWER PIPE FITTING. 29. CHECK FOR LEAKS CONT- TIGHTENED HOSE CLAMPS. REPLACED RAD CLAMPS- PRESS TEST CHECK OK. 30. CHECK HIGH EXT TEMP- RAN ENG RAN TESTS- TEST DROVE PERFORM D.P.F CLEANINESS TEST AND TEST ABORTED. 31. RECHECK ALL CODES. NO CODES- RAN DRAG. CHECKS. 32. REPAIR PLUGGED EXT. REMOVED D.P.F- CUT WELDS OR EXT MOUNTS. 33. REPAIR PLUGGED EXH. CONT. REMOVED EXH PREFILTER- CLEANED PIPE AND FILTER- DISCONNECTED PRESS. SENSOR AND TEMP SENDERS- REASEMBLED- REPLACED D.P.F. 34. REPAIR PLUGGEL EXH CONT. R&R M.A.P AND INTAKE TEMP SENSORS- CHECK EASE CODES- TEST DROVE- CHECK CODES- CHECK OK. 35. Q.C TRUCK.

Workorder: V57338

In Date: 04/29/2013 **Meter Reading:** 73,963.00
Close Date: 05/01/2013

Problem?

Replace rear tires R73 Tires from our stock

Parts	Quantity
216568BRIDGESTONE 255/70R22.5	4

Task performed:

REPLACE REAR TIRES R73 TIRES FROM OUR STOCK.

Vendor? BOULEVARD TIRE CENTE

Workorder: V58728

In Date: 06/27/2013 **Meter Reading:** 76,573.00
Close Date: 07/17/2013

Problem?

repalce front tires

Parts	Quantity
216568BRIDGESTONE 255/70R22.5	2

Task performed:

REPLACE FRONT TIRES.

Vendor? BOULEVARD TIRE CENTE



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V58465

In Date: 06/16/2013
Close Date: 07/29/2013

Meter Reading: 76,448.00

Problem?

rear view camera not working in reverse. says no signal on screen. R73

Parts	Quantity
-------	----------

Task performed:

CHECK OUT CAMERA PULL PANELS TO REPLACE CAMERA FOUND WIRING BAD REPAIR WIRING RETURN TO SHOP.

NO PARTS USED

Workorder: V59562

In Date: 08/05/2013
Close Date: 08/08/2013

Meter Reading: 77,897.00

Problem?

replace door check on passenger side

Parts	Quantity
-------	----------

Task performed:

1. PICK UP UNIT AT HUELLET. 2. REMOVE DOOR PANNEL L/R, REMOVE WINDOW MOTOR, REMOVE DAMAGE DOOR CHECK ASSEMBLY - INSTALL NEW DOOR CHECK ASSEMBLY AND REASSEMBLE.

3551973C2REAR DOOR CHECK	1
3552184C3PIN	2

Workorder: V59073

In Date: 07/14/2013
Close Date: 09/05/2013

Meter Reading: 77,636.00

Problem?

Rear driver side passenger middle door hinge is not attached .It needs a bolt, the door functions. R 73

Parts	Quantity
-------	----------

Task performed:

INSTALL OF HINGE STOP AT SHOP.

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V59663

In Date: 08/07/2013
Close Date: 09/05/2013

Meter Reading:

Problem?

Stryker stretcher malfunction assigned to R73 at station 72 asset # 10175534

<u>Parts</u> -----	<u>Quantity</u> -----
--------------------	-----------------------

Task performed:

NO PARTS USED

Workorder: V59689

In Date: 08/09/2013
Close Date: 09/05/2013

Meter Reading: 78,827.00

Problem?

Front driver side aftermarket fog light was loose. Light was removed from frame because the nuts from the bolts are missing. Light housing is left behind. Small nuts needed.

<u>Parts</u> -----	<u>Quantity</u> -----
--------------------	-----------------------

Task performed:

REINSTALL LIGHT AND WIRE IN.

NO PARTS USED

Workorder: V59324

In Date: 07/24/2013
Close Date: 09/10/2013

Meter Reading: 80,036.00

Problem?

Rescue has cockroach infestation.

<u>Parts</u> -----	<u>Quantity</u> -----
--------------------	-----------------------

Task performed:

DPO-440-1FR072513-627

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V60932

In Date: 10/02/2013
Close Date: 10/10/2013

Meter Reading: 81,224.00

Problem?

Replaced four tires.

Parts	Quantity
-------	----------

Task performed:
REPLACED FOUR TIRES.

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE

Workorder: V61277

In Date: 10/15/2013
Close Date: 11/04/2013

Meter Reading: 81,552.00

Problem?

B inspection R73

Parts	Quantity
-------	----------

Task performed:
1.B INSPECTION. 2. ACTION AREA LIGHT, FOG LIGHT L-SIDE INOP-
REPLACE BLOW ACTION AREA BULBS, REPLACE BLOWN FOG LIGH
BULB. 3. WINDSHEILD WIPERBLADE AND FLUID AND BUG SOLVENT
4. A/C FILTER CAB AND PACENT A/C. 5. 3 TIRE SENSOR LED INOP-
AIR TIRES TO 110PSI AND INSTALL PSI WARNING SENSOR. 6.
BATTERY SLIDING TRAY INOP- CLEAN SLIDES AND LUBRICATE.

1501450007750USE 0775145	2
1878042C91FUEL FILTER 2008 HORTON	1
211-2BULB	4
2506656C124316 WIX CAB A/C FILTER	1
5774457744XD OIL FILTER	1
91-22WIPER BLADE	2
H3LIGHT BULB BP1255/H3 H	1
RWTG1234LED PRESSURE CAP	3



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V57227

In Date: 04/23/2013
Close Date: 12/12/2013

Meter Reading: 73,963.00

Problem?

egr coolers leaking

Task performed:
R&R EGR COVERS.

Parts	Quantity
1878918C2EGR VALVE	1
4307362R91KIT EGR COOLER COLD SIDE OLD 187	1
7090595C91COOLER EGR KIT 330MM EXH SIDE OLI	1
CORECORE CHARGE	1

Workorder: V61046

In Date: 10/06/2013
Close Date: 12/12/2013

Meter Reading:

Problem?

left fog light needs replacement

Task performed:
REPAIRED ON B INSPECTION WO 61277.

Parts	Quantity
H3-100WBP1210H3 BULB	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V62258

In Date: 11/25/2013

Meter Reading: 81,552.00

Close Date: 01/02/2014

Problem?

complete repairs from pm list

Task performed:

1. L-2 TOOL HOLDER LOOSE- SUPPORT HOLE TORN OUT, RETAP A MOUNT TOOL HOLDER. 2. REAR PACENT ENTRANCE FLIP UP TAIL BOARD LOOSE- FOUND NUT AND BOLT MISSING AND LOOSE- REMOVE, DRILL OUT INSERTS AND SECURE WITH/ NEW NUTS AND BOLTS. 3. R-1 DOOR PANNEL AND HOLD OPEN LOOSE- SECURE DOOR PANNEL AND HOLD OPEN STRAUT. 4. PACENT AC COOL- DIAGNOSE FAULT LOW ON FREON- VAC YSTEM CHECK FOR LEAK-NONE FOUND- CHANGE AND OPERATION UNIT SYSTEM OPERATING NORMAL. 5. CAB AC INOP-DIAGNOSE FAULT FOUND COMPRESSOR BAD- RECOVER FREON DISASSEMBLE A/C COMP DRYER AND EXPANSION VALVE- INSTALL NEW COMPRESSOREXP VALVE AND DRYER VACUUM AND CHARGE. 6. TRANSMISSION FLUI LOW-LOW LEAK FOUND- TOP OFF FLUID LEVEL 2 QUARTS. 7. CAB AC TENSIONER NOISY- REMOVE AND INSTALL NEW TENSIONER. 8. INSPECT FRONT BRAKES AFTER REMOVING TIRES AND DRUM NEV SHOES ARE 7.8 IN BRAKE WARE ARE AT 5.9 IN REPAIR 75% GOOD REASSEMBLE REPLACE DAMAGE ARE MISSING ENG COVER TOTAL 10 REAR 50%. 9. DOMELIGHT INOP- REPLACE 4 MISSING BULBS- LIGHT INOP- REMOVE AND TEST ALL DOOR SWITCH -GOOD WEATHER BOOTH ALL MISSING- TRACE WIRE, WORK WITH SWITCH ON - POWER OFF LIGHT STILL ON- WIRE HARNESS MISSING. CAUSES IT WITH ATC 18 ON PROPER LOCATION TO INSTALL BIODE INSTALL BIODE AND SECURE WIRE HARNESS. REPLACEMENT SWITCH FOR DOOR ON ORDER. OPERATE LIGHTING-FUNCTIONING PROPERLY AFTER DIODE INSTALL- INSTALL 4 DOOR SWITCH. 10. REMOVE REAR LIGHTS FOR SHEVRON REMOVAL- SHEVRON PEELING OFF- INSTALL LIGHTINGAFTER SHEVRON INSTALL. 11. AIF LEAK OVERNIGHT- UNABLE TO FIND LEAK AT THIS TIME. 12. CHECK ENGINE CODES NONE ACTIVE OR PRESENT. 13. UNIT # HOLDER AND CARD- ASSEMBLY AND INSTALL. 14. Q.A VEH.

Parts

Quantity

091-84-022DIODE 6 AMP	2
1873217C2BELT TENSIONER	1
211-2BULB	2
3579984C1DOOR SWITCH	4
3611894C9103-0805 A/C COMPRESSOR 4347	1
3660853C22512331C1 EXP VALVE NAV	1
3666273C1A/C DRIER NAV	1
ACX-84534LUG NUT COVER PK10	10
L PLACARD INSERTLARGE PLACARD INSERT CAR	9
S PLACARDFRONT AND BACK PLACARD	1
S PLACARD INSERTFRONT AND BACK INSERT CAR	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V62797

In Date: 12/18/2013 Meter Reading:
Close Date: 01/10/2014

Problem?

Leaking valve on the main connection, small leak. Also electrical connection to the main system is broken. Complete removal from the bracket. Broken plastic fitting. R73

Parts	Quantity
-------	----------

10004858O2 SENSOR HORTON 0-3000	1
---------------------------------	---

Task performed:

DRIVER COMPLAINT 02 LEAK. REPLACED BROKEN SENSOR AND RESEALED ALL FITTINGS.

Workorder: V63213

In Date: 01/07/2014 Meter Reading:
Close Date: 01/10/2014

Problem?

air break leak on R73

Parts	Quantity
-------	----------

NO PARTS USED	
---------------	--

Task performed:

DRIVER COMPLAINT AIR LEAS CHECKED FOR LEAKS FOUND 2 MINOR LEAKS AND REPAIRED.

Workorder: V63548

In Date: 01/20/2014 Meter Reading: 84,004.00
Close Date: 01/24/2014

Problem?

PASSENGER SIDE STEP DOWN MIRROR BROKEN R73

Parts	Quantity
-------	----------

2585911C2GLASS LOOKDOWN MIRROR	1
--------------------------------	---

Task performed:

DRIVER COMPLAINT MIRROR BROKEN REPLACED MIRROR HEAD TRAVEL TO STATION 73.



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V63549

In Date: 01/20/2014
Close Date: 01/24/2014

Meter Reading: 84,004.00

Problem?

broken upper passenger mirror R73

Parts	Quantity
-------	----------

Task performed:
REPLACED MIRROR.

NO PARTS USED

Workorder: V64022

In Date: 02/06/2014
Close Date: 02/18/2014

Meter Reading:

Problem?

1.Windsheld wipers need replacing. 2.Interior handle of left rear door (pt compartment) difficult to open. 3.Bottom cabinet draw slide does allow draw to close. 4.Plexiglass broken on left door (pt compartment).

Parts	Quantity
-------	----------

Task performed:
DRIVER COMPLAINT WIERS 10-7 R&R WIPER BLADES.

5632-1212 IN PAIR DRAWER SLIDES	1
91-22WIPER BLADE	2

Workorder: V64735

In Date: 03/06/2014
Close Date: 03/10/2014

Meter Reading: 86,516.00

Problem?

left brake light out

Parts	Quantity
-------	----------

Task performed:
LEFT BRAKE LIGHTS INOP, REPLACED LOWER CAMP ASSY.

50R03ZCRLIGHT LED RED TIR 6	1
-----------------------------	---



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V61724

In Date: 11/02/2013
Close Date: 03/27/2014

Meter Reading:

Problem?

2 scba bottles are leaking from valves, tagged and in bay for pick up

Parts	Quantity
-------	----------

Task performed:
REPAIRS COMPLETE.

NO PARTS USED

Workorder: V64805

In Date: 03/09/2014
Close Date: 04/01/2014

Meter Reading:

Problem?

Driver side rear window will not go down; Dome light will not turn off, light has been removed.

Parts	Quantity
-------	----------

Task performed:
INSTALLED BUZZERS FOR DOOR AJAR.

03990035CHIME	2
FREIGHTSHIPPING CHARGES	1

Workorder: V64886

In Date: 03/12/2014
Close Date: 04/01/2014

Meter Reading:

Problem?

Dome light stays illuminated when vehicle is shut off. Light has been removed. Driver side rear window will not go down.

Parts	Quantity
-------	----------

Task performed:
1. LIGHT IS MISSING GET NEW ONE FROM SHOP TO CHECK OUT. 2. PARTS ORDER. 3. REPLACED DOME LIGHTS AND TESTED OK. 4. REPLACED WINDOW SWITCH ASSEMBLY.

3544935C6DOOR POD L/H NAV	1
3609781C1DOME LIGHT	1
RBKT1MTG BRACKET	2
RSC03ZCRTIR3 CLEAR WHITE	1
RSR03ZCRLIGHT LED RED TIR3 SERIES	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V65090

In Date: 03/21/2014 Meter Reading:
Close Date: 04/01/2014

Problem?

left PIA is not working and missing a guard

Parts	Quantity
-------	----------

Task performed:

DRIVER COMPLAINT LEFT LIGHT MISSING COVER DRIVER IS CORRECT SECURED LIGHT OK.

NO PARTS USED

Workorder: V65186

In Date: 03/25/2014 Meter Reading:
Close Date: 04/01/2014

Problem?

front left fog light come on and off when it wants to work, blinker light on front right wheel well is hang off. Dome light stays on all of the time and never goes off. The whole light needs to be replaced.

Parts	Quantity
-------	----------

Task performed:

1. DRIVER COMPLAINT LEFT FOG LIGHT INOP CLEANED AND REPAIRED CONNECTION. 2. DRIVER COMPLAINT RIGHT SIDE SIGN/ LIGHT LOOSE SECURED LIGHT.

91-22WIPER BLADE	2
------------------	---

Workorder: V65681

In Date: 04/14/2014 Meter Reading:
Close Date: 04/15/2014

Problem?

door handle to officers side pt compartment entry broke off. Need to replace entire door handle assembly R73

Parts	Quantity
-------	----------

Task performed:

TRAVEL TO 73 DRIVER COMPLAINT DOOR HANDLE 10-7 R&R DOOR HANDLE.

10008145HANDLE LH HORTON	1
10008146HND5948 HANDLE RH HORTON	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V66288

In Date: 05/06/2014
Close Date: 06/18/2014

Meter Reading: 90,251.00

Problem?

C inspection R73

Task performed:

1. START C-INSPECTION. 2. START ON REPAIRS ON LIST. 3. REPLACE ON TICKET. 4. BRAKES AND BELT ALL TIRES OFF AND OFF AND ON, ADJUST ALL TIRES PRESSURES AND CAPS. 5. Q.A INSPECTION. 6. FINISH UP ON REPAIRS ON LIST.

Parts	Quantity
065624AD-IP DRIER	1
0775145PANEL FILTER	3
1847727C1BELT	1
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
2507061C1PS RESV GASKET	1
3532811C1FILTER MINDER INT.	1
3753BRAKE DRUM RUMPER FRONT	2
3757REAR DRUMS 3757X 3647X	2
435 VALVE CAP	6
46870AIR FILTER	1
50-2204FAN KIT DANHARD CONDENSER	1
5291FOG LIGHTS	1
5774457744XD OIL FILTER	1
91-22WIPER BLADE	2
94LDRAWER LATCH ASSY	1
K022105PURGE VALVE AD-IP-IS	1
K060695BELT	1
KSMA2124703QFRONTBRAKE KIT RUMPER AND 4D	2
LF18TS-LEDMAP LIGHT LED 18 IN	1
S777COUPLING NIPPLE	1
VML/T1808D2503221C1 FILTER POWER STEERING	1
XK4034707QPMHD SHOE KIT 3/8 BEAM	2



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V64140

In Date: 02/11/2014
Close Date: 07/17/2014

Meter Reading: 84,894.00

Problem?

Air leak

Parts	Quantity
-------	----------

Task performed:

air leaks repaired on ticket 63213

2507385C1CAB AIR LEVEL VALVE INT	1
----------------------------------	---

Workorder: V68589

In Date: 08/11/2014
Close Date: 08/12/2014

Meter Reading: 93,352.00

Problem?

a/c belt broken

Parts	Quantity
-------	----------

Task performed:

Drive to station found out patient A/C compressor clutch burn out needs a new compressor clutch burn out needs a new compressor unit must come to shop for repairs. Check Quint 73 . CPO light on and acting up.

NO PARTS USED	
---------------	--

Workorder: V68635

In Date: 08/13/2014
Close Date: 08/18/2014

Meter Reading: 93,352.00

Problem?

pat a/c compressor faulty

Parts	Quantity
-------	----------

Task performed:

1.Remove and replace patient A/C compressor, dryer and belt. Blow out A/C hoses as per office. 2.Charger system. Found high side very high. Check, found one condensor fan bad. Remove and replace both condensor fan and high side was good.

071601A07-0602A DRIER A/C 7118	1
577903-3673 COMP USE 5591 MANIFOLD	1
60027FAN A/C COND 12IN 860026-2-W	2
8201L17-3428 ESTER OIL E7	1
K060695BELT	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V69017

In Date: 08/28/2014
Close Date: 09/03/2014

Meter Reading: 94,217.00

Problem?

rear air dump inop

Task performed:

TRAVEL TO STA,73 CK, OUT DUMP INOP, R&R REAR DOOR OVERRIDE SW, AND RESET COMPUTER RETESTED STILL INOP, FRONT DUMP SW, WAS ON RESET TESTED OK.

Parts	Quantity
03210072SWITCH DUMP/FLOR LT	1
3910010SW COVER LED	2

Workorder: V71036

In Date: 11/18/2014
Close Date: 11/21/2014

Meter Reading: 98,733.00

Problem?

B inspection R73

Task performed:

1-3. "B" inspection 4. R/R batt tray-remove batts-remove air tanks-R/R batty tray-install new batts, reinstall air tanks. 5. Test drive truck-install new F/tires from building 3-test drive to ensure no shaking 6. A/C line leaking-remove air filter housing-recovered freon-removed line-sent out to Mako for repair. 7. Coolant temp-inop removed air filter housing. Drained coolant, removed ETC switch and replaced.

Parts	Quantity
02841108BATTERY TRAY KWIKEE	1
1836537C91OIL/WATER TEMP SENDER NAV	1
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
487761HOSE & FITTINGS	1
5774457744XD OIL FILTER	1
91-22WIPER BLADE	1
H3-100WBP1210H3 BULB	2



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V70933

In Date: 11/14/2014 Meter Reading:
Close Date: 11/24/2014

Problem?

110V Rooftop A/C keeps popping station breaker.

Parts	Quantity
-------	----------

Task performed:

Check AC during B inspection working ok

NO PARTS USED

Workorder: V70506

In Date: 10/28/2014 Meter Reading:
Close Date: 11/25/2014

Problem?

Front light head light is out.

Parts	Quantity
-------	----------

Task performed:

lights for station

2586872C1LOCK RING HEADLITE	2
2587313C1SPRING WASHER HEADLITE	2
9007H9007 BULB ASSY	4

Workorder: V71202

In Date: 11/25/2014 Meter Reading: 99,161.00
Close Date: 11/25/2014

Problem?

replace rear tires

Parts	Quantity
-------	----------

Task performed:

WORK REPAIRS REQUESTED.

NO PARTS USED

Vendor? BLVD TIRE CENTER



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V71504

In Date: 12/09/2014 Meter Reading: 99,850.00
 Close Date: 12/09/2014

Problem?

Rear air bags will not come up R73

Parts	Quantity
-------	----------

Task performed:

Rear air bag kneel module 10-7 went to 72 for parts off r72 before going to shop

NO PARTS USED

Workorder: V71600

In Date: 12/12/2014 Meter Reading: 100,132.00
 Close Date: 12/12/2014

Problem?

The stretcher (10175534) wheels on R73 is not lifting without assistance when loading a patient in the back of the rescue.

Parts	Quantity
-------	----------

Task performed:

Contacted Captain 7. He is calling EMSAR for repair.

NO PARTS USED

Workorder: V72041

In Date: 01/03/2015 Meter Reading:
 Close Date: 01/29/2015

Problem?

left large loading light in light bar is burned out R73

Parts	Quantity
-------	----------

Task performed:

Replaced loading light bulb.

H35SN12BULB	3
-------------	---



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V72731

In Date: 01/30/2015 Meter Reading:
Close Date: 02/19/2015

Problem?

broken PIAA fog light/officers side

Parts	Quantity
-------	----------

Task performed:

Repaired on another repair w/o order.

NO PARTS USED

Workorder: V72823

In Date: 02/02/2015 Meter Reading:
Close Date: 02/19/2015

Problem?

Diver side fog lamp is missing R73

Parts	Quantity
-------	----------

Task performed:

Light replaced on another repair order.

NO PARTS USED

Workorder: V72952

In Date: 02/06/2015 Meter Reading:
Close Date: 02/19/2015

Problem?

Front Passenger side FOG light missing in bumper

Parts	Quantity
-------	----------

Task performed:

Travel to ST 73. Replaced PIA lights on rescue.

5291FOG LIGHTS	1
----------------	---



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V72822

In Date: 02/02/2015 Meter Reading:
Close Date: 02/24/2015

Problem?

Driver rear door bottom lock doesn't engage R73

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

1. Checked door locks. Need to order door lock activator. 2. Replaced and rewired activator for door lock.

Workorder: V73071

In Date: 02/11/2015 Meter Reading:
Close Date: 02/24/2015

Problem?

Fog lamps on R73 do not turn on

Parts	Quantity
-------	----------

5291FOG LIGHTS	1
----------------	---

Task performed:

Traced down and repaired broken light module.

Workorder: V73072

In Date: 02/11/2015 Meter Reading:
Close Date: 02/24/2015

Problem?

Rear passager side door inside handle is loose

Parts	Quantity
-------	----------

10004900ACTUATOR DOOR LOCK	1
LTC594111656-16 LATCH R/H MEDIC MASTER	1
LTC594211657-16 LATCH L/H MEDIC MASTER	1
SPAL002ACTUATOR-DOOR	1

Task performed:

Replaced lower latch in door.



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V73150

In Date: 02/13/2015 Meter Reading:
Close Date: 02/24/2015

Problem?

Occasional air leaking sound from drivers side.

Parts	Quantity
-------	----------

Task performed:

Repaired oil leaks under truck.

NO PARTS USED

Workorder: V73174

In Date: 02/15/2015 Meter Reading:
Close Date: 02/24/2015

Problem?

Air Leak (break system)

Parts	Quantity
-------	----------

Task performed:

Replaced leaking air fitting on governor.

NO PARTS USED

Workorder: V73521

In Date: 02/28/2015 Meter Reading:
Close Date: 04/07/2015

Problem?

The bravo shorelines do not auto eject from the plugs on the alpha rescue.

Parts	Quantity
-------	----------

Task performed:

1. Lubricated and cleaned both auto ejects.

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V73647

In Date: 03/04/2015
Close Date: 04/07/2015

Meter Reading:

Problem?

while turning key to start rescue it sounds like it wants to stall out. Even after it has been running a while. no warning lights

<u>Parts</u>	<u>Quantity</u>
--------------	-----------------

Task performed:

1. Checked starting found no problem.

NO PARTS USED

Workorder: V73821

In Date: 03/12/2015
Close Date: 05/01/2015

Meter Reading: 105,773.00

Problem?

C-inspection

<u>Parts</u>	<u>Quantity</u>
--------------	-----------------

Task performed:

ticket not used

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V73824

In Date: 03/12/2015

Close Date: 05/01/2015

Meter Reading: 105,773.00

Problem?

C inspection

Parts

Quantity



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Task performed:

1. C- Inspection. 2. C- Inspection. 3. C- Inspection. 4. Inflate all tires to 115PSI (6) 5. Driver's seat belt female buckle falls to floor. R&R attaching bolt. Apply loctite to threads- Now ok. 6. Diagnose why O2 alarms don't work. Order parts. 7. R&R wiper blades. 8. R&R L/R cab door courtesy light assembly. 9. Get metric locnuts and washers from horn selection. Install on air filter housing mount. 10. Remove chassis support BRKY for R/S step. Straighten BRKT. Fabricate rubber insulator. Install brkt. Attach to step with new hardware. 11. Service rear axle. Change oil etc. 12. Tighten all bolts holding R/F mud flap 13. Secure wire harness at vehicle horns hanging down. 14. R&R L/S top amber marker LT assembly. Also repair threads for one of the mounting screws. 15. Add 3 qts. trans fluid to trans. 16. Tighten all screws on inner door panel on compt L-2 doors, also tighten all brackets on hold open air springs. 17. Adj door latch strikers on compt L-3 lower door set- rubbing and difficult to open. 18. Diagnose why inverter not working. Reset circuit BRKR. On back of unit. 19. Get new O2 wrench from parts. Fabricate new attaching cable. Secure cable to wrench and compt wall. Apply velcro to wall and wrench. 20. Remove radiator from vehicle start re-assembly with new radiator. 21. Finish reassembly of new radiator install. Install missing hardware. repair broken bolt holding grill. 22. Evacuate A/C system. Failed vac test. Pressurize with nitrogen. No leak found evacuate and recharge system. 23. Start diagnostics of crank case breather assembly. 24. R&R engine breather assembly. Inspect centrifuge portion. Install new seals and reinstall on vehicle. 25. Remove rumbler siren. Remove whelen siren and bracket off front bumper. 26. Disassemble exhaust system. Straighten smashed pipe. Cut and install new flex pipe and new band clamps. 27. Drill oversize and retap 3 mounting nuts on bracket for r/s inner splash well on r/f wheel opening. 28. Weld up bracket for siren driver, weld on new plate end. 29. Fabricate overlay bracket for r/s front siren mounting bracket. Cut to size and shape. Give to Carl Reed to weld crack and weld overlay. 30. Jackup vehicle. Remove tires, drums hubs. Clean all grease from bearings and hubs. R&R seals. reassemble. Adj brng preload. Install oil type hub convers. and oil until full. 31. Finish above repair 32. R7R cab aux A/C filter. R&R A/C filters in patient area. Redrill and retap holes for A/C filter retainer under seat. 33. Reinstall repaired siren bracket on to bumper. Reinstall seiren speaker assembly. Reinstall rumbler siren and secure all wiring. 34. Remove 2 broken glove

00108156CONDENSER BRACKET	2
03190096O2 ALARM	2
0775145PANEL FILTER	3
1842130C11842130C3 THERMOSTAT DT466	1
1873932C97FUEL FILTER ASSY	1
1876922C91SEAL KIT	1
1878042C91FUEL FILTER 2008 HORTON	1
20A-400CLAMP 4" 33969	2
2506656C124316 WIX CAB A/C FILTER	1
2593302C912593302C92 RADIATOR ASSY	1
284358GOVERNOR D-2	1
3570659C1BRAKE HOSE FR 262366-20	1
3609347C1LAMP MARKER INT. DOOR PANEL	1
370001ASEAL 35066	2
40022STAINLESS FLEX PIPE 4"	2
46870AIR FILTER	1
5774457744XD OIL FILTER	1
78R539018-2699 A/C FILTER	1
91-22WIPER BLADE	2
AS75807OXM1757-01 OXYGEN WRENCH	1
CHR1612340-4024 HUB COVER - FRONT AXLE 2004	2
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
FRT 66081FREIGHT CHARGE	1
FRT V27618FREIGHT CHARGE	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

holders. Remove all old adhesive. Put new adhesive onto new glove holders. Install in rear of cab. 35. Find air leak. R&R governor. R&R airline fittings on governor replace missing allen bolt attaching governor to compressor. 36. Dignose fault code symbol on dash and fuel filter message in display. R&R low pressure sensor. Found metal in filter housing and no prime in low pressure side of fuel system. 37. Remove fue filter housing off side of enging block. R&R low pressure fuel pump. Disassemble and clean F/F housing and check valves. 38. Install new F/F assembly. Hook up all fuel lines and elec switches. Reassemble all removed items to remove and replace housing assembly. 39. Bleed fuel system. Road test vehicle and check for fuel pressure codes. None check for leaks after repair. 40. Check wiring and connections at temp sender- ok. Install updates into body computer. Road test. Remp gauge now work; but engine temporarily 170 degress verified with laptop. Thermostat must be bad. 41. Remove 2 broken A/C condenser brackets under R/S of vehicle. Fabricate 2 new brackets. 42. Install 2 fabricated condenser brackets onto vehicle condenser and fans assembly.

Workorder: V74526

In Date: 04/09/2015

Meter Reading:

Close Date: 05/11/2015

Problem?

Engine warn message is showing along with a yellow triangle hazzard sign.

Parts

Quantity

Task performed:

1. Check out truck with laptop. Found injector coil code. Test. Ok inactive code.

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175525

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V73646

In Date: 03/04/2015

Meter Reading:

Close Date: 05/19/2015

Problem?

rescue sounds like it is leaking air while driving.

Parts

Quantity

Task performed:

NO PARTS USED