



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V34965

In Date: 09/15/2010

Meter Reading: 1,260.00

Close Date: 10/18/2010

Problem?

B INSPECTION AND NEW VEHICLE SET UP R25

Task performed:

1. remove light and clean antiseize, remove horns , and scba tubes
2. reinstall lights and air horns and scba tubes
3. install tool and equipment holders and safety equipment.
4. b inspection
5. remove nail from drivers steer tire, check for leak, checks ok.
6. install nater pin covers
7. r&r king pin grease fittings , to gain access to zerk
8. install new equipment

Parts	Quantity
0567042LONG STRECHER BAR	1
101-124-000CRASH RESTRAINT STRAPS	1
14-7014HGR-1 HELMET HOOK	2
1878042C91FUEL FILTER 2008 HORTON	1
5269LPVM-5 SM MOUNT	8
5632-1212 IN PAIR DRAWER SLIDES	1
680-10LAMERICAN FLAG W UV CLEAR LEFT	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
L PLACARDLARGE SIDE PLACARD	4
LPVM-7LG MOUNT	3
S PLACARDFRONT AND BACK PLACARD	1
UH-6CYLINDER CLIPS	2
UMVS162511STRAP	3
UMVS254411STRAP 46 IN	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V35904

In Date: 10/25/2010 **Meter Reading:** 1,605.00
Close Date: 10/27/2010

Problem?

MODIFY REAR STEP TO ACOMIDATE STRETCHER R25

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

WARRANTY CLAIM. 1. Rear bumper not to KKK spec; rem bumper to set at 10" max frm box; had to drill new holes in brkt; stretcher can now be rer more safely. 2. Had to set rear bumper to KKK standards; set at 14"; had problems getting stretcher out; set to 9" had to cut out brkts & reset needs fixed on next batch of tks. j

Workorder: V35711

In Date: 10/18/2010 **Meter Reading:** 1,323.00
Close Date: 10/29/2010

Problem?

*

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

No shoreline charging sys; C/O; fnd that a tube was put in hole where brki & tripped it; reset - all ok at this time. j

Workorder: V35761

In Date: 10/19/2010 **Meter Reading:** 1,323.00
Close Date: 11/03/2010

Problem?

rear emergancy light is not working on driver side. Headlight flasher button does not work. R25

Parts	Quantity
-------	----------

UMVS162511STRAP	2
-----------------	---

Task performed:

Travel to stn; Rear emergency light inop; poss programming issue; will contact Horton. j



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V36354

In Date: 11/10/2010 Meter Reading: 2,175.00
Close Date: 11/10/2010

Problem?

rear emergency light bar not working properly r25

Parts	Quantity
-------	----------

Task performed:

contacted hallmark for warranty repair

NO PARTS USED

Workorder: V36488

In Date: 11/16/2010 Meter Reading: 2,243.00
Close Date: 11/30/2010

Problem?

when stretcher was placed into load position it would drop down r25

Parts	Quantity
-------	----------

Task performed:

(1) WHEN R25 STRETCHER WAS PLACED IN LOAD POSITION, IT WOULD DROP DOWN . CONTACTED MEDCO FOR REPAIR OF STRETCHER. J.W.

NO PARTS USED

Workorder: V36391

In Date: 11/12/2010 Meter Reading: 2,243.00
Close Date: 12/01/2010

Problem?

two of the three siren noises work. B25

Parts	Quantity
-------	----------

Task performed:

Chk siren - tested - working ok. j

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V36769

In Date: 11/30/2010
Close Date: 12/07/2010

Meter Reading: 2,823.00

Problem?

left rear bottom brake light blinking when braking. need hand tool remounte r25

<u>Parts</u>	<u>Quantity</u>
NO PARTS USED	

Task performed:

1. Travel to stn; left brake light flashes - programmed wrong; reprogrammed light. 2. Remnt tools in L-1 compt. j

Workorder: V35626

In Date: 10/13/2010
Close Date: 12/22/2010

Meter Reading: 1,260.00

Problem?

Safty strap for back boards,the lower strecher catch needs to be lower for old strecher,mounts for a NY hook in back board compartment. Is there a striker strecher for this unit and a MDT? R25

<u>Parts</u>	<u>Quantity</u>
NO PARTS USED	

Task performed:

Workorder: V37132

In Date: 12/14/2010
Close Date: 12/29/2010

Meter Reading: 3,232.00

Problem?

Bracket needs to be moved for the SCBA because the SCBA hoses are rubbing on a corner. r25

<u>Parts</u>	<u>Quantity</u>
NO PARTS USED	

Task performed:

(1) TRAVELED TO ST25 TO MOVE SCBA MOUNT. ADJUSTED MOUNT CAGE SO HOSE ON SCBA WOULD NOT BE IN CONTACT OF CORNER/RUBBING ON R25. J.W.



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V37131

In Date: 12/14/2010
Close Date: 12/30/2010

Meter Reading: 3,232.00

Problem?

A/C vents in the pt compartment, under the jump seat is leaking pink fluid onto the floor. r25

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

(1) TRAVELED TO ST25 TO CHECK OUT PATIENT AREA FOR LEAKIN FLUID ON FLOOR. FOUND A HOSE FITTING LOOSE. TIGHTENED UP AND TESTED OK. (2) TRAVELED TO ST25 TO INSTALL A MIC MOUNT IN R25. DRILLED AND TAPPED COMPUTOR MOUNT AND BOLTED MI TO BODY OF LOADING DOCK. OK. J.W.

Workorder: V36885

In Date: 12/05/2010
Close Date: 01/05/2011

Meter Reading: 2,924.00

Problem?

Headlights aim up too high R25

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

Adj headlights - too high. j

Workorder: V37555

In Date: 01/02/2011
Close Date: 01/05/2011

Meter Reading: 4,222.00

Problem?

T1 siren does not work r25

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

(1) T1 SIREN DOES NOT WORK ON NEW R25. WARRANTY, DONE BY HALLMARK. J.W.



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V36588

In Date: 11/20/2010 Meter Reading: 2,517.00
Close Date: 01/06/2011

Problem?

T1 siren is not working on R25

Parts	Quantity
-------	----------

Task performed:

Travel to stn; T-q siren inop - unknown; siren working properly. j

NO PARTS USED

Workorder: V37537

In Date: 01/01/2011 Meter Reading: 4,222.00
Close Date: 01/06/2011

Problem?

SCBA compartment door hinge shock needs a nut for the mount. Door swings freely with no stop. R25

Parts	Quantity
-------	----------

Task performed:

(1) TRAVELED TO ST-25 TO REPAIR SCBA DOOR DO TO A NUT MISSING ON THE STRUT CAUSING THE DOOR TO SWING FREELY. INSTALLED A NUT AND TIGHTENED DOOR. OK. J.W.

NO PARTS USED

Workorder: V37224

In Date: 12/17/2010 Meter Reading: 3,519.00
Close Date: 01/10/2011

Problem?

left back auxillary brake light flashing. it appears that the truck is going to make a left turn when they could be going straight or right. R25

Parts	Quantity
-------	----------

Task performed:

Left bumper brake light flashes; reprogrammed light. j

3579984C1DOOR SWITCH	1
----------------------	---



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V37338

In Date: 12/21/2010
Close Date: 01/10/2011

Meter Reading: 3,636.00

Problem?

left flood light is out r25

Parts	Quantity
-------	----------

Task performed:

Travel to stn; Left flood light inop replcd bulb. j

H50SN12BULB	4
-------------	---

Workorder: V37407

In Date: 12/25/2010
Close Date: 01/11/2011

Meter Reading: 3,747.00

Problem?

front cab a/c blowing warm air only R25

Parts	Quantity
-------	----------

Task performed:

(1) TRAVELED TO ST-25 TO REPAIR FRONT CAB A/C ON R25. CHECKED OUT THE SYSTEM AND ALL PRESSURES AND TEMPS WNL. OK. J.W

NO PARTS USED	
---------------	--

Workorder: V37545

In Date: 01/02/2011
Close Date: 03/08/2011

Meter Reading: 3,841.00

Problem?

front cab AC not blowing cold and driver side rear window does not work. r25

Parts	Quantity
-------	----------

Task performed:

1. Travel to stn; cab A/C inop - no power to compressor; chkd electrical - no codes; still has refrigerant; sent to shop. 2. L/R window inop - lost control signal; unplugged mount & reset window. 3. A/C compressor for cab inop; hookup A/C machine; has freon; no power going to compressor; hookup laptop; thermister not reading on hi-side; replc thermister. j

3622764C32606229C92 THERMISTER	1
--------------------------------	---



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V39362

In Date: 03/22/2011 Meter Reading: 7,130.00
Close Date: 03/28/2011

Problem?

SENSOR REAR OUTER TIRE LOST SIGNAL. sta 25.

Parts	Quantity
-------	----------

Task performed:

Travel to 25; reset monitor - ok. j

NO PARTS USED

Workorder: V39700

In Date: 04/05/2011 Meter Reading: 7,614.00
Close Date: 04/14/2011

Problem?

Repair stretcher R25 (outside agency-medco equipt. repair)

Parts	Quantity
-------	----------

Task performed:

Rep stretcher R25 - Medco j

NO PARTS USED

Vendor? MEDCO

Workorder: V39855

In Date: 04/12/2011 Meter Reading: 7,813.00
Close Date: 04/19/2011

Problem?

ON CALL A/C 10-7 R 25

Parts	Quantity
-------	----------

Task performed:

Went to Stn25; fnd cab A/C blower bad; brought truck to shop; rem blower from another truck; replc blower; ran/chk ok; return home. j

3674285C1BLOWER MOTOR	1
-----------------------	---



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V39872

In Date: 04/12/2011
Close Date: 05/03/2011

Meter Reading: 8,175.00

Problem?

C INSPECTION AND REPAIRS AS NEEDED R25

Task performed:

C-Inspection 2. Trans svc. 3. Replc wiper blades. 4. Svc air dryer. 5. Replc pat A/C filters. 6. O2 wrench ___ damaged - in bad location; remntd tether location & replc. 7. P/S leak; clnd area; rem clip retainer & replc w/hose clamp; tightened & topped off fluid. 8. Fnd coolant leaking when eng ___ & hi-idling; had to rem air box & inner ___ to access leaking pipe; tightened hose clamps & press tested. 9. Ck air bad level; activated leving valves; chk ok. 10. Ck for air leak; fnd fitting leaking; replc fitting; ran/chk for leak; ck ok.

Parts	Quantity
065624AD-IP DRIER	1
1501450007750USE 0775145	3
15W40BSYN OIL BULK QTS	30
16-31455533 CAP LOW SIDE BLUE	1
16-3444CAP R134A - RED 5575/5557	1
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
29526898 29548988 TRANS FILTER ALLISON	1
5774457744XD OIL FILTER	1
91-22WIPER BLADE	2
ANTICOOLANT ANTIFREEZE GAL	1
K022105PURGE VALVE AD-IP-IS	1
TRANSYNDALLISON TRANS FLUID GAL	5

Workorder: V40772

In Date: 05/22/2011
Close Date: 05/25/2011

Meter Reading: 8,736.00

Problem?

4 strobe lights/wig lights are out in the front top and back top of the rescue unit R 25

Task performed:

Travel to 25; lights in secondary mode; put to primary - ok. j

Parts	Quantity
NO PARTS USED	



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V40778

In Date: 05/22/2011
Close Date: 05/25/2011

Meter Reading: 8,736.00

Problem?

The A/C in the pt transport area is intermitten turning on and off with the cooling down the patient area. The left vents is cooling it down but it has to been done manually not automatically. Right vents is not working. R 25

Parts ----- Quantity -----

Task performed:

Adj t-stat for a/c. J

NO PARTS USED

Workorder: V41094

In Date: 06/03/2011
Close Date: 06/06/2011

Meter Reading: 9,043.00

Problem?

A/C in the back patient transport compartment is not working properly theautomatic is not working u have to manual bring the temp. down but it is still warm back there, Sta 25.

Parts ----- Quantity -----

Task performed:

Travel to 25; fnd no hi-idle & volt dropping below 12.6 wtih lights on; will gr programmed. j

NO PARTS USED

Workorder: V41481

In Date: 06/21/2011
Close Date: 06/24/2011

Meter Reading: 9,648.00

Problem?

4x6 ferno Floor cover is crack or broken in half inside transport compartment next to the stretcher lock in position on the floor needs to be replaced. r25

Parts ----- Quantity -----

Task performed:

Travel to 25; replc brken floor plate. j

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V42449

In Date: 08/01/2011 Meter Reading: 10,870.00
Close Date: 08/09/2011

Problem?

Repair side door cylinder, oxygen regulator rubbing on divider.

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

1. Fnd oxgen regulator rubbing on divider; rem reg & all oxygen bottles; rem back boards; cut divider; reinstalled edge guard; clnd comp; restalled all parts; ck ok. 2. Fnd apt side door cyl off; remnt/replc msng bolts; ck ok.
j

Workorder: V42412

In Date: 07/31/2011 Meter Reading: 10,787.00
Close Date: 08/16/2011

Problem?

A/C is not blowing cold air r 25

Parts	Quantity
-------	----------

3622764C32606229C92 THERMISTER 2

Task performed:

CK CODES - INSTALLED COMPUTER UPDATES - RAN A/C - FOUND THERMO -- NOT WORKING PROPERLY RECOVER FREON AND REPLACED BOTH THERMOSTATS - AND CHARGE A/C CLEARED CODES - RAN AND CK FOR CODES CK OK

Workorder: V43717

In Date: 09/16/2011 Meter Reading: 12,062.00
Close Date: 09/21/2011

Problem?

Temp. gauge indicator light came on reading 185 @ the time. Sta 25.

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

travel to station 25 checked trucks coolant system and for codes talked with driver found out truck went into regin and was ok



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V43740

In Date: 09/18/2011 Meter Reading: 12,062.00
 Close Date: 09/21/2011

Problem?

The back A/C is not working when plugged into the shoreline. The fan will run, but no cool air. Sta 25.

Parts	Quantity
-------	----------

Task performed:

travel to 25 found switch for a/c in manual not auto turned to auto ok

NO PARTS USED

Workorder: V43839

In Date: 09/22/2011 Meter Reading: 12,213.00
 Close Date: 09/26/2011

Problem?

Handle to the lifepack bracket is missing a pin. Sta 25.

Parts	Quantity
-------	----------

Task performed:

TRAVEL TO 25 REPAIRED BRACKET FOR LIFEPAK HOLDER

NO PARTS USED

Workorder: V44072

In Date: 10/01/2011 Meter Reading: 12,442.00
 Close Date: 10/07/2011

Problem?

A/c in front cab not blowing cool R25

Parts	Quantity
-------	----------

Task performed:

travel to 25 checked pressures ok cleaned condenser with water and turned fan on run good

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V44412

In Date: 10/15/2011 Meter Reading:
Close Date: 10/19/2011

Problem?

Cab air conditioner is blowing hot air again. Was repaired recently at the vehicle shop. R 25

Parts	Quantity
-------	----------

Task performed:

travel to st 25 not there, wait fr tr, will return later travel to 25 a/c working fine ???

NO PARTS USED

Workorder: V44184

In Date: 10/05/2011 Meter Reading: 12,505.00
Close Date: 10/26/2011

Problem?

Cab A/C blows warm air after 30min of running. Sta 25.

Parts	Quantity
-------	----------

Task performed:

1. Travel to 25; thermometer bad; sent to shop. 2. Fnd thermometer measuring temp out of range; evac; R/R sensor; vac/charge sys. j

3622764C32606229C92 THERMISTER	1
--------------------------------	---

Workorder: V44786

In Date: 10/31/2011 Meter Reading: 13,159.00
Close Date: 11/01/2011

Problem?

on call a/c 10-7 r 25

Parts	Quantity
-------	----------

Task performed:

found comp engaged installed gauges, found systme would not build heac pressure, possibl bad compressor went to 22

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V41658

In Date: 06/28/2011
Close Date: 11/02/2011

Meter Reading: 9,861.00

Problem?

R 25 has a leak between the box and cab, Sta 25.

Parts	Quantity
-------	----------

Task performed:
warranty from hallmark

NO PARTS USED

Workorder: V44878

In Date: 11/01/2011
Close Date: 11/30/2011

Meter Reading: 13,159.00

Problem?

REPAIR A/C R 25

Parts	Quantity
-------	----------

Task performed:
diagnose faulty a/c compressor, replace compressor dryer and expansion valve, evacuate and recharge system test drive

3611894C9103-0805 A/C COMPRESSOR 4347	1
3660853C22512331C1 EXP VALVE NAV	1
3670134C1ACCUMULATOR ASSY INT.	1

Workorder: V45468

In Date: 11/28/2011
Close Date: 11/30/2011

Meter Reading:

Problem?

cab AC blowing warm air again. R25

Parts	Quantity
-------	----------

Task performed:
Checked system; found thermoter bad; scheduled to shop for repair.bp

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V45799

In Date: 12/12/2011
Close Date: 12/19/2011

Meter Reading:

Problem?

spot light is out. Sta 25

Task performed:

REPLACED BULB NO POWER REPLACED BULB NO POWER TO LIGHT WILL REPLACE. TRAVEL TO STA 25 REPLACED SPOT LIGHT HEAD AND CONTROLLER.

Parts	Quantity
H9SPOT LIGHT BULB	1
LGHGO-2020GOLIGHT MODEL 2020 SEARCH LIGHT	1

Workorder: V45703

In Date: 12/07/2011
Close Date: 12/20/2011

Meter Reading: 14,469.00

Problem?

CAB A/C 10-7 R 25

Task performed:

DIAGNOSE A/C SYSTEM. DISCHARGE A/C SYSTEM R&R EVAP OUTLET TEMP THERMISTOR. EVACUATE AND RECHARGE SYSTEM TEST RUN - OK.

Parts	Quantity
3622764C32606229C92 THERMISTER	1

Workorder: V45942

In Date: 12/19/2011
Close Date: 12/21/2011

Meter Reading:

Problem?

rear light bar amber and red light not functioning properly, Sta 25

Task performed:

TRAVEL TO STA 25 CHECKED REAR LIGHTS FOUND MOST OF LIGHT BAR CHECKED CONNECTIONS AT NODE 1 LOOSE PLUG NEED TO ORDER 1 AMBER LED.

Parts	Quantity
01-0286361211LAMP ASSY LED AMBER/AMBER	2



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V46337

In Date: 01/05/2012

Meter Reading: 15,242.00

Close Date: 01/12/2012

Problem?

B INSPECTION AND REAIRS R25

Task performed:

1. B-INSPECTION. 2. TOP OF BATTERIES SO DIRTY CAN'T CLEAN TERMINALS AND DEM CORROSION PROTECTION GOOEY MESS. CLEAN TOP OF ALL BATTERIES AND CABLES. R&R CABLES AND CLEAN POSTS AND TERMS. 3. R&R CAB A/C FILTER 4. R&R A/C COMPRESSOR SUPPORT BRACKET BOLTS. 5. R&R ENGINE AIR FILTER. DATE FILTER HOUSING. 6. REMOVE DORAN TIRE PRESSUF MONITORING SYSTEM FROM VEHICLE. REMOVE 6 WHEEL SENSOR REMOVE DASH DISPLAY. CAP WIRING TO DISPLAY FILL HOLE LEFT IN DASH PANEL. 7. R&R CAB AUX. A/C FILTER - HAVE TO PARTIALLY DISASSEMBLE UNIT TO R&R FILTER ON THIS UNIT. 8. R&R PATIENT HEAT AND A/C FILTERS. R&R 110 VOLT PATIENT HEAT & A/C FILTEF 9. DIAGNOSE WHY 110 VOLT A/C NOT WORKING. 10. COOLING SYSTEM LEAKS. 11. INSTALL NEW (6) LOW TIRE PRESSURE INDICATOR SYSTEM. 12. INSTALL SHUT OFF VALVES FOR CAB HEATER. VALVES IN STOCK DON'T FIT THIS TRUCK. HAD TO GO TO MAKO HOSE FOR OTHER FITTINGS. PUT TOGETHER RUBE GOLDBERG FITTING VALVE AND COUPLING SETUP TO MAKE IT WORK. DRAIN AND REFILL COOLING SYSTEM TO WORK ON IT. 13. REPAIR REAR STEP BUMPER. ONE MALE NUBBIN ON R/S MISSING. REPLACED. ALIGN BOTH FEMALE RECEIVERS TO ACCEPT NUBBIN. 14. DIAGNOSE WHY ONBOARD BATTERY CHARGER NOT WORKING

Parts

Quantity

1501450007750USE 0775145	3
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
388863HOSE KIT	2
388863-1HTR HOSE SHUT VALVE NEW HORTONS	1
46870AIR FILTER	1
5774457744XD OIL FILTER	1
78R539018-2699 A/C FILTER	1
RWTG1234LED PRESSURE CAP	8



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V46492

In Date: 01/11/2012
Close Date: 01/13/2012

Meter Reading: 15,242.00

Problem?

REPLACE TIRES R 25

Parts	Quantity
-------	----------

Task performed:
REPLACE TIRES R-25

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE

Workorder: V46348

In Date: 01/05/2012
Close Date: 01/19/2012

Meter Reading: 15,242.00

Problem?

Body mounts.

Parts	Quantity
-------	----------

Task performed:
1. R&R 10 BODY MOUNTS. 2. CONTINUE R&R 10 BODY MOUNTS.

NO PARTS USED

Workorder: V46351

In Date: 01/05/2012
Close Date: 01/26/2012

Meter Reading: 15,242.00

Problem?

Replace torque arm bushings.

Parts	Quantity
-------	----------

Task performed:
REPLACE TORQUE ARM BUSHINGS.

NO PARTS USED

Vendor? TOTAL TRUCK PARTS



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V46349

In Date: 01/05/2012 Meter Reading: 15,242.00
Close Date: 02/08/2012

Problem?

Replace torque arm bushings.

Parts ----- Quantity -----

Task performed:

1. REMOVE REAR TORQUE ARM - HAD TO CUT BUSHING - BLOCKIN BOLT FOR REMOVAL. 2. INSTALL REAR TORQUE ARM WOULD NOT FIT BACK IN - HAD TO USE PORTO POWER TO MOVE REAR AXLE TO INSTALL.

NO PARTS USED

Workorder: V47949

In Date: 03/14/2012 Meter Reading: 17,534.00
Close Date: 03/20/2012

Problem?

Screw missing in hardware that holds the lifepak monitor in the patient compartment of rescue. R25

Parts ----- Quantity -----

Task performed:

WENT TO 25 - FOUND LATCH MISSING SCREW - REPLACED SCREW - TIGHTENED ALL OTHER SCREWS.

NO PARTS USED

Workorder: V48015

In Date: 03/16/2012 Meter Reading: 17,534.00
Close Date: 03/30/2012

Problem?

Passenger side step bracket(diamond plate) loose bolts fell out of support bracket R25

Parts ----- Quantity -----

Task performed:

INSTALLED NEW BOLTS SECURED STEP BRACKETS

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V49326

In Date: 05/14/2012
Close Date: 05/29/2012

Meter Reading: 19,182.00

Problem?

C INSPECTION R25 TO BECOME 231

Task performed:

1. C-INSPECTION. 2. C-INSPECTION. 3. SERVICE DRYER. 4. TIGHTEN AND ADJUST ALL DOOR LATCHES AND PENS. 5. PULL DOWN AND RECHARGE 110 V A/C , CLEAN CONDENSER. 6. CHECK FOR AIR LEAKS, REPLACE FITTINGS ON GOVERNER AND REMOVE AUTO DRAINS.

Parts	Quantity
065624AD-IP DRIER	1
103385NDRAIN COCK	1
1501450007750USE 0775145	1
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
5774457744XD OIL FILTER	1
K022105PURGE VALVE AD-IP-IS	1
L PLACARDLARGE SIDE PLACARD	1
L PLACARD INSERTLARGE PLACARD INSERT CAR	1
S PLACARDFRONT AND BACK PLACARD	1
S PLACARD INSERTFRONT AND BACK INSERT CAR	1

Workorder: V49467

In Date: 05/18/2012
Close Date: 05/30/2012

Meter Reading: 19,411.00

Problem?

*Pry bar needs to be mounted preferably on upper tank under door sil on either side 23 check with chief *Front passenger seat is to close to dash and needs more leg room

Task performed:

1. TRAVEL TO 23 MADE PARTS LIST FOR BOTH RESCUES TO MOUNT EQUIPMENT. 2. CHECKED SEAT TRUCK WILL HAVE TO WAIT UNTIL SERVICE FOR SEAT TO BE MOVED. 3. MOUNTED EQUIPMENT IN R3 COMPARTMENT.

Parts	Quantity
5269LPVM-5 SM MOUNT	2



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V49774

In Date: 05/31/2012
Close Date: 06/21/2012

Meter Reading: 20,448.00

Problem?

A/C is running only blowing hot.

Task performed:

1. CHECK OUT A/C SYSTEM, NOT CODING, PUMP DOWN AND RECHARGE SYSTEM, FOUND BAD A/C COMPRESSOR, PUMP DOWN REPLACE A/C COMPRESSOR, EXP VALVE, DRYER AND CHARGER SYSTEM OK. 2. ASSIST IN A/C REPAIR AT OIL LEVEL IN COMPRESSOR - REPLACED COMP - INSTALLED A/C LINES AND BELTS - VAC AND CHARGE CHECK OK.

Parts	Quantity
3611894C9103-0805 A/C COMPRESSOR 4347	1
3660853C22512331C1 EXP VALVE NAV	1
3670134C1ACCUMULATOR ASSY INT.	1

Workorder: V50296

In Date: 06/21/2012
Close Date: 07/05/2012

Meter Reading: 22,242.00

Problem?

both ac units in r23's cab are blowing out hot air. R23

Task performed:

1. DIAGNOSE CAB A/C DISCH EVAC RECHARGE SYSTEM R&R 2 LOW SIDE THERMISTORS - SAW VISUAL FREON LEAK WHEN DONE. DIS SYSTEM R&R EXPANSION VALVE AND ALL SEALS AND O-RINGS - EVAC AND RECHARGE SYSTEM - OK. 2. R&R WIPER BLADES.

Parts	Quantity
3622764C32606229C92 THERMISTER	2
3660853C22512331C1 EXP VALVE NAV	1
91-22WIPER BLADE	2



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V50930

In Date: 07/17/2012
Close Date: 07/19/2012

Meter Reading: 24,224.00

Problem?

CAB A/C 10-7 R 23

Parts	Quantity
-------	----------

Task performed:

A/C INOP/EVAP OUTLET THERMISTOR BAD/EVAL A/C SYSTEM
REPLACED THERMISTOR VACUUM AND RECHARGED.

3622764C32606229C92 THERMISTER	1
--------------------------------	---

Workorder: V50599

In Date: 07/04/2012
Close Date: 07/25/2012

Meter Reading: 23,320.00

Problem?

Rear lightbar needs some bulbs replaced, not all working... R23

Parts	Quantity
-------	----------

Task performed:

1. CHECKED EMERGENCY LIGHT. FOUND 1 LIGHT OUT IN LIGHT BAR
L OUT ON REAR SIDE BOTH AMBER PARTS ON ORDER. 2. TRAVEL
STA 23 REPLACED EMERGENCY LIGHTS IN REAR LIGHT BAR AND
SIDE LIGHT.

01-0286361211LAMP ASSY LED AMBER/AMBER	1
--	---

Workorder: V51396

In Date: 08/06/2012
Close Date: 08/09/2012

Meter Reading: 25,717.00

Problem?

R23 check a/c system

Parts	Quantity
-------	----------

Task performed:

EVACUATED SYSTEM INSTALLED 2 NEW THERMOSISTERS
VACUUMED SYSTEM CHECKED FOR LEAKS RECHARGED CHECKED
FOR OPERATION.

3622764C32606229C92 THERMISTER	2
--------------------------------	---



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V51738

In Date: 08/20/2012 Meter Reading: 26,566.00
 Close Date: 09/06/2012

Problem?

B INSPECTION R 23 OIL CHANGE SERVICES

Parts	Quantity
-------	----------

Task performed:

B INSPECTION OIL CHANGE SERVICES

NO PARTS USED

Vendor? OIL CHANGE SERVICES

Workorder: V51942

In Date: 08/28/2012 Meter Reading: 27,302.00
 Close Date: 09/12/2012

Problem?

pulls rt r23

Parts	Quantity
-------	----------

Task performed:

1. CHK BRAKING PULL CONCERN: CHK FRT BRAKES AND SLACKS
 CHK STEERING LINKAGE AND SUSPENION JACKED UP FRT OF
 TRUCK AND CHK RING PINS AND WHEELS BEARINGS. ROAD
 TESTED FOUND NO PROB AND COULD NOT REPRODUCE PULL
 CONCERN.

NO PARTS USED

Workorder: V51606

In Date: 08/15/2012 Meter Reading:
 Close Date: 09/14/2012

Problem?

Front drivers side tire sensor keeps blinkning red without any indication of trouble or warning in the truck

Parts	Quantity
-------	----------

Task performed:

TRVL TO 23 ADDED OIL TO TIRES OK.

RWTG1234LED PRESSURE CAP	2
--------------------------	---



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V52209

In Date: 09/06/2012
Close Date: 09/20/2012

Meter Reading: 27,864.00

Problem?

REPAIRS FROM B INSPECTION R 23

Task performed:

1. CHKD AIR COMPRESSOR FOR OIL LEAK-CLASS 1 LEAK I WILL MONITOR. 2. STRAIGHTEN AND ADJ DOOR HOLD OPEN BRACKETS AND REPLACED HOLD OPEN SHACK. 3. CHKD SEAT WILL HAVE REPAIRED WHEN IN FOR C INSPEC. 4. REPLACED MISSING LENS ON SCENE LIGHT BULBS.

Parts	Quantity
6811813493LENS CLEAR 68-1181349-3	1
EAA-8350-30UGSS1783UQ STRUT-LIFT	2
H35SN12BULB	2

Workorder: V52724

In Date: 09/30/2012
Close Date: 10/04/2012

Meter Reading: 29,897.00

Problem?

front headlight right side R 23

Task performed:

R&R HEADLIGHT.

Parts	Quantity
9007H9007 BULB ASSY	1

Workorder: V52997

In Date: 10/10/2012
Close Date: 10/15/2012

Meter Reading: 30,343.00

Problem?

REPAIR FLAT TIRE R23

Task performed:

REPAIR FLAT TIRE R23

Parts	Quantity
NO PARTS USED	

Vendor? BOULEVARD TIRE CENTE



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V53055

In Date: 10/13/2012
Close Date: 10/18/2012

Meter Reading:

Problem?

AIR LEAK HEARD FROM REAR AXLE, FULLY DRAINED IN 6 HOUR PERIOD R 23

Parts	Quantity
-------	----------

Task performed:
INSTALL AIR BAGS TEST FOR OTHER LEAKS.

GUI1R11216GY1R11216 AIR BAG INT.	2
----------------------------------	---

Workorder: V53158

In Date: 10/17/2012
Close Date: 10/18/2012

Meter Reading:

Problem?

R23-When parked the suspension air dump and leaking air and the back drops. Also the AM/FM radio has no display screen.

Parts	Quantity
-------	----------

Task performed:
ORDER RADIO.

3825124P91PP105222 RADIO AM/FM/WB	1
-----------------------------------	---

Workorder: V53198

In Date: 10/19/2012
Close Date: 10/22/2012

Meter Reading: 30,957.00

Problem?

replace tire

Parts	Quantity
-------	----------

Task performed:
REPLACE TIRE

NO PARTS USED	
---------------	--

Vendor? BOULEVARD TIRE CENTE



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V53314

In Date: 10/25/2012
Close Date: 10/31/2012

Meter Reading: 31,687.00

Problem?

Front tires need to be replaced. balding on the outsides of both tires. R23

Parts	Quantity
-------	----------

Task performed:

TRAVEL TO 23 CHECKED TIRES AND HAD REPLACED.

NO PARTS USED

Workorder: V53388

In Date: 10/30/2012
Close Date: 10/31/2012

Meter Reading: 31,930.00

Problem?

REPLACE TIRES

Parts	Quantity
-------	----------

Task performed:

REPLACE TIRES

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE

Workorder: V53526

In Date: 11/04/2012
Close Date: 11/08/2012

Meter Reading:

Problem?

Front A/C blowing Hot..... R23

Parts	Quantity
-------	----------

Task performed:

LOOK AT A/C FOUND BAD THERMISTATE SO I RECOVERED SYSTEM
R&R BOTH THERMISTATES CHARGED SYSTEM AND TEST DROVE.

3622764C32606229C92 THERMISTER 2



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V53538

In Date: 11/05/2012
Close Date: 11/13/2012

Meter Reading: 32,451.00

Problem?

ON CALL A/C 10-7 R231

Parts	Quantity
-------	----------

Task performed:

PHONE CALL R 23 A/C NOT WORKING CALLED BACK IT WAS NOW WORKING CALLED BACK SAID STOPPED WORKING. TRAVEL TO ST 23 CHK CODES FOUND OUTLET TEMP CODE TOO HIGHT. COMPRESSOR NOT ON. INSTALL CONTROLLER A/C COMPRESSOR ON. TRAVEL HOME.

NO PARTS USED

Workorder: V54738

In Date: 01/02/2013
Close Date: 01/02/2013

Meter Reading: 35,968.00

Problem?

ON CALL SEVERAL LIGHTS OUT R23

Parts	Quantity
-------	----------

Task performed:

TRAVEL TO STATION 23 FOUND L FRT STROBE OK, DIAGNOSE PROBLEM WITH R TURN AND R STROBE -FOUND BAD CONNECTION AT BREAKER. REPAIR CONNECTION. COULD NOT VERIFY COMPLAINT ON CODE INTERPLEX.

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V54740

In Date: 01/02/2013 Meter Reading: 35,968.00
 Close Date: 01/02/2013

Problem?

ON CALL HAED LIGHT OUT R 23

Task performed:

TRAVEL TO ST 23 RESCUE GOT CALLED OUT. DROPPED OF 2 HEADLIGHTS FOR CREW.

Parts	Quantity
9007H9007 BULB ASSY	2

Workorder: V54301

In Date: 12/07/2012 Meter Reading: 34,868.00
 Close Date: 01/23/2013

Problem?

request a new AM/FM radio, screen is broken. r

Task performed:

INSTALLED NEW RADIO.

Parts	Quantity
NO PARTS USED	

Workorder: V54699

In Date: 12/29/2012 Meter Reading: 35,720.00
 Close Date: 01/23/2013

Problem?

right rear turn signal, front driver side grill strobe both out.

Task performed:

TRAVEL TO 23 CHECKED SIGNAL LIGHT FOUND NO POWER TRACE WIRES FOUND SHORT UNDER BODY CORRECTED SHORT RESET BROKEN OK.

Parts	Quantity
60A00TARLED TURN SIGNAL LAMP	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V55198

In Date: 01/22/2013

Meter Reading: 37,723.00

Close Date: 01/23/2013

Problem?

left headlight out

Task performed:

TRAVEL TO 23 REPLACED LEFT HEADLIGHT AND REPLACED MISSING BULB CLAMP.

Parts	Quantity
2586872C1LOCK RING HEADLITE	1
2587313C1SPRING WASHER HEADLITE	1
9007H9007 BULB ASSY	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V54283

In Date: 12/07/2012

Meter Reading: 34,868.00

Close Date: 02/06/2013

Problem?

C INSPECTION R 23

Task performed:

1. C INSP 2. C INSP 3. CHECK L/F WHEEL BEGANS FOR PLAY, WHEEL OK PLAY IS NOT EXCESSIVE. 4. ENGINE CODES RECORDED, INACTIVE CODES, CLEARED CODES ROAD TEST OK. 5 REAR COMPARTMENT WILL NOT STAY CLOSED, LATCH OUT OF AD ADJUST REAR COMPARTMENT LATCH AND LUBE TESTED OK. 6. 110V A/C INOP. COMPRESSOR FAN DRAWING EXCESSIVE AMPS CAUSED BREAKER TO TRIP. REPPAIRED TERMINAL AT BREAKER INSIDE BOX AND REPLACED CONDENSOR FANS. 7. EXHAUST STACK HIT BODY, STRAIGHTEN EXHAUST AND SECURED STACK. 8 R-3 COMPARMENT HARD TO OPEN LINKAGE OUT OF ADJUSTED AN LUBED LINKAGE. 9. SERVICE AIR DRIER AND PURGE VALVE. 10. POWER STEERING LOW LEAKING, CLEANED LEAK AREA INSTALLEI NEW CLAMP TOP OFF FLUID. 11. SHORTLINE AUTO EJECT COVER BROKEN INSTALLED NEW COVER. 12. REAR BRAKES WORN REPLACED REAR BRAKEKS AN DRUMS. 13. R-S EMERGENCY LIGHTS ABOVE REAR TIRE INOP BULB BURNT, INSTALLED NEW LIGHT ASSY. 14. R-S GROUND LIGHT UP, BULB BURNT INSTALLED NEW GROUND LIGHT ASSY ALSO REPAIRED BRACKET. 15. WIPER BLADES WORN, INSTALLED NEW WIPER BLADES. 16. COOLANT LEAK, WATER PUMP PRESSURE TEST LOCATE LEAK ORER PUMP START TO DRAIN COOLANT. 17. R-R T-SIGNAL AND REPAIR SIDE SIGNAL INOP, OPEN CIRCUIT TO SIGNAL. 18. R/R T-SIGNAL INOP OPEN CIRCUIT OUT CONNECTOR UNDER DASH PIN PUSHED BACK AND LAST CONTACT LOCATED AND REPAIRED OPEM CIRCUIT. 19. REPLACE WATER PUMP, LEAKING, REPLACED WATER PUMP. 20. REPLACE WATER PUMP CONTINUED.

Parts

Quantity

065624AD-IP DRIER	1
091-3YWCOVER KUSSMAUL AUTO EJECT	1
1501450007750USE 0775145	1
1842665C93WATER PUMP DT570	1
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
3757REAR DRUMS 3757X 3647X	2
50-2204FAN KIT DANHARD CONDENSER	1
5774457744XD OIL FILTER	1
607141-05USE 61H01 COPMPARTMENT LIGHT	1
91-22WIPER BLADE	2
K022105PURGE VALVE AD-IP-IS	1
XK4034707QPMHD SHOE KIT 3/8 BEAM	2



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V54118

In Date: 12/01/2012
Close Date: 02/08/2013

Meter Reading:

Problem?

R23 has warning light "mod4pin" when the primary lights are turned on. Lt. McLaughlin

Parts	Quantity
-------	----------

Task performed:

TRAVEL TO 25 CHECKED CODES FOUND LIGHT OUT WILL ORDER.
REPAIR WIRE ON PLUG TEST OK.

2505306C92LIGHT L/H MIRROR HORTON RESCUE	1
--	---

Workorder: V54727

In Date: 01/01/2013
Close Date: 02/08/2013

Meter Reading:

Problem?

mod 11A pin 4 fail R 23

Parts	Quantity
-------	----------

Task performed:

REPLACED LIGHTS.

QL64SFC-RCSPLIT R-C QUDRAFLARE	1
--------------------------------	---



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V55565

In Date: 02/05/2013
Close Date: 02/13/2013

Meter Reading: 38,970.00

Problem?

B inspection

Task performed:

1. B-INSPECTION 2. DIAGNOSE PROBLEM WITH FRONT STROBE. FOUND CUT WIRE AT WIRING HARNESS PLUG. REPAIR WIRE AND TEST (OK). 3. DIAGNOSE LEFT MIRROR INOP. FOUND LED STRIP BAD. ORDERED PART. REASSEMBLE MIRRORS. 4. REPLACE REAR PATIENT COMPT A/C REGISTER. 5. REPLACE BAD WHEEL TIRE PRESSURE SENSORS. 6. CHECK LRI TIRE FOR LEAK. TIGHTENED VALVE STEM. 7. OIL AND AIR LEAK AT FITTING TOP OF COMPRESSOR. REMOVE AIR LINE AND ATTACHING BRACKETS AND REMOVE LINE. REMOVE COMPRESSOR OUT RET FITTING AND SEA THREADS. RE-INSTALL AND TEST (OK). 8. COMPRESSOR INLET HOSE RUBBING ON EGR COOLER WATER HOSE. DRAIN COOLANT, REPLACED EGR HOSE. FILL COOLANT AND PRESSURE CHECKED (OK), INSTALL LOOM ON COMPRESSOR HOSE AND SECURE TO PIP AWAY FROM HOSE. 9. AIR LEAK AT FITTING FOR AIR PUMP SOLENOIDS. REPLACED LEAKING SOLENOID AND FITTING. AIR VEHICLE AND CHECK FOR LEAKS NOW OTHER SOLENOID LEAKING ORDERED SOLENOID. 10. REPLACED LEFT MIRROR LIGHT. 11. TIGHTEN R-3, L-2, AND SIDE PATIENT COMPT. DOOR SHOCK BOLTS 12. DIAGNOSE AIR LEAKS. FOUND SMALL LEAK AT PARKING BRAKE VALVE. REPLACED VALVE. 13. INSTALL AIR PUMP SOLENOID. AIR POURING OUT PUMP. INSTALL ANOTHER SOLENOID VALVE SAME THING. INSTALL OLD SOLENOID (OK). WRONG PARTS. 14. Q&A.

Parts	Quantity
1873940C3RAD HOSE	1
1878042C91FUEL FILTER 2008 HORTON	1
2505876C91DASH VALVE	1
2506656C124316 WIX CAB A/C FILTER	1
5774457744XD OIL FILTER	1
7605-7459USE VENT	1
RWTG1234LED PRESSURE CAP	2



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V56086

In Date: 03/01/2013
Close Date: 03/04/2013

Meter Reading: 40,281.00

Problem?

back l rear tire has large slice in side wall of tire

Parts	Quantity
-------	----------

Task performed:

BACK 1 REAR TIRE HAS LARGE SLICE IN SIDE WALL OF TIRE.

216568BRIDGESTONE 255/70R22.5	1
-------------------------------	---

Vendor? BOULEVARD TIRE CENTE

Workorder: V51723

In Date: 08/20/2012
Close Date: 04/04/2013

Meter Reading: 26,566.00

Problem?

tint stripe on windshield r23

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED

Workorder: V50384

In Date: 06/25/2012
Close Date: 04/08/2013

Meter Reading:

Problem?

the SRS light came on saying SAR FAULT, the check engine light came on and then went off, yellow rectangle light saying exhusst filter is always on.

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V56657

In Date: 03/26/2013
Close Date: 04/08/2013

Meter Reading: 42,471.00

Problem?

Need lens cover for large LED emergency light on officer's side of truck.
Cover missing. R23

Parts ----- Quantity -----

Task performed:

REPLACED BROKEN LENS COVER ON RF.

6811813493LENS CLEAR 68-1181349-3	2
-----------------------------------	---



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V57705

In Date: 05/13/2013

Meter Reading: 45,732.00

Close Date: 05/24/2013

Problem?

C inspection R23

Task performed:

1. C INSP. 2. C INSP. 3. REPLACE ALL BATTS. 4. BATT TRAY. 5. BATT BOX-COVER/STEP-READJUST HINGE AND 4 LOCK LATCHES. 6. REAR TIRES- REMOVE REAR WHEELS AND TIRES TO REPAIR VALV STEM EXTENSIONS. 7. ENG COOLANT- TIGHTEN ALL CLAMPS- RECHECK. 8. REPLACE WIPER BLADES. 9. A/C INSTAKE FILTERS- REDRILL, INSTALL ALL NEW SCREWS AND TIGHTEN PROPERLY. 10. DOOR HOLD OPEN-REPLACE MISSING SCREWS AND TIGHTEN REMAINDER. 11. COMP DOORS-SECURE SCRES ON ALL PANELS. 1 110V A/C SYSTEM-REINSTALL 'REASSEMBLE ON WALL AND RECHECK OK. 13. PWR INVERTER INOP-INSTALL NEW RECEPTICAL AND RESET BRAKER- NOW OK. 14. SERV AIR DRYER. 15. RUBBER AIR DEFLECTOR FALLING OFF-RESECURE. 16. SWICH FRT TIRES FROM SIDE TO SIDE. 17. REPLACED SIX GROUND LTS-CUT AND INSTALL NEW WIRE. 18. CAB A/C SYSTEM-EVACUATE SYSTEM AND REPALCE SHRADER VALVE ON HIGH SIDE. 19. 110 OUTSIDE RECEPT-REMOVE COVER FROM OUTSIDE 110V RECEPTICAL. 20. CITY HORNS INOP-REPLACE BOTH HORNS. 21. ASSIST LARS W/ ABOVE HORN REPAIR. 22. VEHICLE AIR LEAKS.

Parts

Quantity

0392004315A RECPT LIGHTED	1
065624AD-IP DRIER	1
1501450007750USE 0775145	3
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
3523179C92ELECTRIC HORN LOW	1
3558466C92ELECTRIC HORN HI	1
440-5 VALVE EXT.	2
46870AIR FILTER	1
5774457744XD OIL FILTER	1
607141-05USE 61H01 COPMPARTMENT LIGHT	6
78R539018-2699 A/C FILTER	1
91-22WIPER BLADE	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	3
HP-31DBATTERY 950CCA HP-31D	3
K022105PURGE VALVE AD-IP-IS	1
RWTG1234LED PRESSURE CAP	4



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V58550

In Date: 06/19/2013
Close Date: 06/20/2013

Meter Reading: 3,866.00

Problem?

Cab a/c intermittent

Task performed:

DIAGNOSE INTERMITTENT CAB A/C PROBLEM - FOUND A/C WORKING OK AT THIS TIME AND NO ACTIVE CODE. INACTIVE CODE FOR EVAP TEMP OUTLET HIGH. RECOVER FREON, REPLACED BOT A/C THERMESTORS. VACUUM SYSTEM AND CHARGE A/C ROAD TEST VEHICLE AND CHECK FOR ANY A/C CODES NONE. CHECKED A/C GAUGE PRESSURES 225H AND 40L. CHECKED OUTLET TEMP 5 DEGREES F. CHECKED REAR CAB FILTER AND FRONT FILTER. OK.

Parts	Quantity
-------	----------

3622764C32606229C92 THERMISTER	1
--------------------------------	---

Workorder: V58412

In Date: 06/14/2013
Close Date: 06/21/2013

Meter Reading: 47,692.00

Problem?

Cabb ac turns off and on by itself. Seems like there may be a loose connection somewhere

Task performed:

INSTALLED NEW BLOWER MODULE

Parts	Quantity
-------	----------

3626414C1BLOWER MOTOR RESISTOR	1
--------------------------------	---



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V58803

In Date: 07/01/2013
Close Date: 07/02/2013

Meter Reading: 48,811.00

Problem?

Check engine light on

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

FOUND STEP/WARNING LIGHT ON - CHECK OIL LEVEL - CHECK OK
FOUND COOLANT LOW - CHECK CODES - FOUND ECL CRITICEL
LOW - PRESS TEST CAP - CHECKOK - PRESS TEST COOLING
SYSTEM - TIGHTENED CLAMPS AT HOSE BEHIND TURBO -
REPLACED 2 CLAMPS AT RES. TANK - FILLED ANC CHECK OK.

Workorder: V59154

In Date: 07/17/2013
Close Date: 07/19/2013

Meter Reading: 50,146.00

Problem?

need coolant [part only]

Parts	Quantity
-------	----------

ALA00350-50 EXTENDED LIFE COOLANT GAL	6
---------------------------------------	---

Task performed:

PARTS ONLY.

Workorder: V59499

In Date: 08/01/2013
Close Date: 08/02/2013

Meter Reading: 90,664.00

Problem?

c/e light

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

TRAVEL TO 23 R23 STOP ENGINE LIGHT ON CHECKED CODES
FOUND COOLANT LEVEL LOW ADDED COOLANT AND PUT BACK IN
SERVICE.



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V59526

In Date: 08/03/2013 Meter Reading: 51,428.00
 Close Date: 08/08/2013

Problem?

CAB A/C INTERMITTENT R23

Parts	Quantity
-------	----------

Task performed:

TRAVEL TO STATION 23 CAB A/C WARM. FREON LEVEL OK.
CLEANED OUT CONDENSOR AND TESTED OK.

NO PARTS USED

Workorder: V57802

In Date: 05/25/2013 Meter Reading: 4,321.00
 Close Date: 08/12/2013

Problem?

no power to pat comp

Parts	Quantity
-------	----------

Task performed:

NO POWER TO PAT COMP REPLACED MASTER BATTERY SWITCH.

51-30219-1045 MASTER SWITCH 175 AMP	1
-------------------------------------	---

Workorder: V59501

In Date: 08/02/2013 Meter Reading: 51,362.00
 Close Date: 08/12/2013

Problem?

The rear scene lights have one or two bulbs out on reverse

Parts	Quantity
-------	----------

Task performed:

CHECKED SCENE LIGHTS AND REPAIRED LOOSE WIRE.

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V59539

In Date: 08/04/2013 Meter Reading: 51,428.00
 Close Date: 08/12/2013

Problem?

passenger comp. a.c out of service --. patient comp. a.c blowing very weak.
R23

<u>Parts</u>	<u>Quantity</u>
--------------	-----------------

Task performed:

TRAVEL TO 23 CHECKED A/C FOUND ACTIVE CODE FOR A BAD THERMOSTER SENT TO SHOP.

NO PARTS USED

Workorder: V59593

In Date: 08/05/2013 Meter Reading: 51,428.00
 Close Date: 08/12/2013

Problem?

ac blowing hot air in cab

<u>Parts</u>	<u>Quantity</u>
--------------	-----------------

Task performed:

1. CHECKED A/C FOUND NO CODES, CHECK PRESSURES THEY LOOK LOW SO RECOVER FOUND IT WASN'T LOW AND FOUND CONDENSE FAN ON ALL THE TIME PLUGGED FOR SWITCH BAD ANI FOUND ON COMPUTER THE THERMISTER WERE R&R THERMISTER CHARGED SYSTEM AND SYSTEM WORKED GOOD. 2. ASSIST IN A/C REPAIR.

3622764C32606229C92 THERMISTER	2
8201L17-3428 ESTER OIL E7	1

Workorder: V59672

In Date: 08/08/2013 Meter Reading: 51,818.00
 Close Date: 08/12/2013

Problem?

Passenger A/C out of service. Blowing hot air.

<u>Parts</u>	<u>Quantity</u>
--------------	-----------------

Task performed:

CHECKED A/C SENT TO SHOP.

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V59734

In Date: 08/10/2013
Close Date: 08/13/2013

Meter Reading: 51,991.00

Problem?

R23 warm a/c front and rear

Parts	Quantity
-------	----------

Task performed:

TRAVEL TO STA 23 CHECK FOR A/C CODES (NONE0 CHECK GAUGE PRESSURES. REMOVE SOME FREON TO GET PROPER PRESSURE. CLEAN FRONT CONDENSER. UNPLUG FAN SOLENOID TO KEEP FAN ON. (REAR A/C) CONNECT GAUGES ADD SMALL AMOUNT OF FREON WASH CONDENSER. TRAVEL HOME.

NO PARTS USED

Workorder: V59885

In Date: 08/19/2013
Close Date: 08/19/2013

Meter Reading: 52,530.00

Problem?

cab a/c intermittent

Parts	Quantity
-------	----------

Task performed:

RESCUE 23 FRONT A/C INOP AT TIMES CHECK OVER, CHECK PRESSURES, CHECK WIRES, FOUND NO CODES IN SYSTEM, MAYBE BODY CONTROLLER BAD.

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V59900

In Date: 08/19/2013
Close Date: 08/20/2013

Meter Reading: 52,530.00

Problem?

a/c 10-7 r 23

Task performed:

CHECK A/C NOT WORKING FOUND THERMOSTATIC SENSOR WERE NOT WORKING GOOD. EVAC A/C AND REPLACE SENSORS. ALSO FOUND A BLEND DOOR MOTOR NOT WORKING REPLACE MOTOR AND TEST IS GOOD.

Parts	Quantity
3542606C12611234C1 VENT ACTUATOR	1
3622764C32606229C92 THERMISTER	2

Workorder: V59857

In Date: 08/16/2013
Close Date: 08/21/2013

Meter Reading: 52,400.00

Problem?

o2 gauge stuck on a 1,000 psi and cab a/c is intermittent

Task performed:

1. CHECK O2 GAUGE - FOUND GAUGE ON REGULATOR DAMAGED - R&R GAUGE AND FITTING - CHECK OK. 2. CHECK CAB A/C SHUTS OFF INTERMITTENTLY - FOUND THERM. CODES - R&R ELECTRICAL PLUGS - RAN AND CHECK OK - CLEARED CODES.

Parts	Quantity
3535379C1CONNECTOR THERMISTER	2
3536590C1TERMINAL THERMISTER	4
3536591C1LOCK THERMISTER	2
MG-C23SPMGC23 GAUGE	1

Workorder: V59914

In Date: 08/19/2013
Close Date: 08/26/2013

Meter Reading: 52,530.00

Problem?

3 TIRES- DRIVER FRONT, AND 2 PASSENGER REAR TIRES HAVE LOW TREAD. OIL IS A LITTLE HIGH. R23

Task performed:

1. TRAVEL TO 23 ALL TIRES 10.7 ORDERED FROM SHOP. 2. CHECKED OIL LEVEL. SHOP IS GOING TO CHANGE.

Parts	Quantity
NO PARTS USED	



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V60114

In Date: 08/27/2013
Close Date: 08/27/2013

Meter Reading: 52,946.00

Problem?

R23 replace all tires

Parts	Quantity
-------	----------

Task performed:

R23 REPLACE ALL TIRES.

216568BRIDGESTONE 255/70R22.5	2
-------------------------------	---

Vendor? BOULEVARD TIRE CENTE

Workorder: V60158

In Date: 08/29/2013
Close Date: 09/06/2013

Meter Reading: 52,946.00

Problem?

tint windows on R23

Parts	Quantity
-------	----------

Task performed:

TINT WINDOWS ON R23.

NO PARTS USED

Vendor? 60 MINUTE AUTO TINT



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V60690

In Date: 09/23/2013
Close Date: 09/24/2013

Meter Reading: 53,375.00

Problem?

no power

Task performed:

GO TO ST 23 CHECK OUT TRUCK FOUND PLUG OFF ON THIS FAN PLUG IN FAN TO GET ENGINE TO HEAT UP TO TRY TO BEGAN, STO ENGINE LIGHT ON. TRY TO BEGAN NUMEROUS TIMES ON ARAYABI TO REGEN TAKE TO SHOP AND REPLACE DPF TO REPAIR CLEAN ALL CODES AND DRIVE OK.

Parts	Quantity
2593986C1DPF GASKET	1
2593998C1DPF GASKET	1
DPFCLEANED UNIT	1

Workorder: V60746

In Date: 09/24/2013
Close Date: 09/26/2013

Meter Reading: 53,375.00

Problem?

Pt compartment A.C. warm

Task performed:

1. CHECK PT. A/C FOR OPERATION FOUND HIGH PRESSURE A/C HOSE BROKE OFF THE A/C COMPRESSOR. 2. REMOVE DAMAGE A/C HOSE DRIVE TO MAKO HOSE TO GET A NEW ONE AND INSTALL ON UNIT. 3. VACUUM A/C SYSTEM RECHARGE AND TEST FOUND A/C COMPRESSOR IS NOT GOOD - NEED DRYER AND EXPANSION VALVE. 4. REMOVE AND REPLACE A/C COMPRESSOR, A/C DRYER, AND EXPANSION VALVE VACUUM AND CHARGE SYSTEM TEST FOF OPERATION IS GOOD NOW.

Parts	Quantity
071601A07-0602A DRIER A/C 7118	1
12-3022A1608 2 1/2 TON VALVE EXPANSION	1
448744HOSE AND FITTING	1
577903-3673 COMP USE 5591 MANIFOLD	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V57411

In Date: 05/01/2013
Close Date: 10/09/2013

Meter Reading: 45,270.00

Problem?

Cab a/c inop R23

Task performed:

REPAIRED ON WO V57705.

Parts	Quantity
15W40BSYN OIL BULK QTS	25
16-31438915 VALVE CORE A/C 3544706C1	2
3611894C9103-0805 A/C COMPRESSOR 4347	1
3660853C22512331C1 EXP VALVE NAV	1
3670134C1ACCUMULATOR ASSY INT.	1

Workorder: V60136

In Date: 08/28/2013
Close Date: 10/10/2013

Meter Reading: 52,946.00

Problem?

B INSPECTION R23

Task performed:

1. B INSP ON RESCUE. 2. REMOVED REAR BRAKES AND SHOES INSTALLED NEW PARTS. 3. ADJUSTED LEVELING VALVES AND CHECKED OPERATION.

Parts	Quantity
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
3609972C1PANEL	1
3615415C92PANEL ASM FUSE DOOR	1
3757REAR DRUMS 3757X 3647X	2
5774457744XD OIL FILTER	1
XK4034707QPMHD SHOE KIT 3/8 BEAM	2



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V60731

In Date: 09/24/2013
Close Date: 10/11/2013

Meter Reading:

Problem?

Pt compartment A.C. not always blowing cold. R23

Parts	Quantity
-------	----------

Task performed:

REPAIRS ON V60892

NO PARTS USED

Workorder: V60841

In Date: 09/27/2013
Close Date: 10/11/2013

Meter Reading:

Problem?

CHRONIC PROBLEM: WHEN VEHICLE IS PARKED AND IDLING, THE CAB A/C WILL BLOW HOT AIR. IN THE PT COMPARTMENT A RATTLING SOUND IS COMING FROM THE A/C AREA AND WATER IS COMING OUT FROM UNDER THE LT CHAIR. MCLAUGHLIN R23

Parts	Quantity
-------	----------

Task performed:

REPAIRS ON V60892

NO PARTS USED

Workorder: V60892

In Date: 09/30/2013
Close Date: 10/11/2013

Meter Reading:

Problem?

passenger compartment A.C. malfunction. blowing cold for 5 minutes and hot for 45 minutes. tried shutting down the truck then restarting it with no success. r23

Parts	Quantity
-------	----------

Task performed:

DRIVER COMPLAINT A/C INOP INTERMITTENTLY CHECKED CODES FOUND TRANSMITTER CODE AND SENT TO SHOP FOR REPAIR.

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V60904

In Date: 09/30/2013
Close Date: 10/11/2013

Meter Reading:

Problem?

passenger compartment A.C. malfunction. blowing cold for 5 minutes and hot for 45 minutes. tried shutting down the truck then restarting it with no success. r23

Parts	Quantity
-------	----------

Task performed:

VACUUMED A/C INSTALLED NEW THERMASTAT IN SYST CHARGED
TEST DROVE CHECJED OK.

3622764C32606229C92 THERMISTER	2
--------------------------------	---

Workorder: V61757

In Date: 11/04/2013
Close Date: 11/05/2013

Meter Reading: 56,378.00

Problem?

flat repair

Parts	Quantity
-------	----------

Task performed:

FLAT REPAIR

NO PARTS USED

Vendor? BOULEVARD TIRE

Workorder: V62772

In Date: 12/17/2013
Close Date: 12/19/2013

Meter Reading:

Problem?

air suspension behind the driver side rear tire is leaking air. the truck still raises and lowers fine, drives fine, but you can hear a hissing sound.

Parts	Quantity
-------	----------

Task performed:

REMOVE AND REPLACE REAR SUSPENSION AIR BAGS AND ADJUS
TO PROPER HIGH.

GUI1R11216GY1R11216 AIR BAG INT.	2
----------------------------------	---



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V57413

In Date: 05/01/2013
Close Date: 01/02/2014

Meter Reading: 45,208.00

Problem?

needs wiper blades

Task performed:
PARTS ONLY NO LABOR.

Parts	Quantity
91-22WIPER BLADE	2

Workorder: V62895

In Date: 12/23/2013
Close Date: 01/02/2014

Meter Reading:

Problem?

Front AC in the cab is not working properly and there seems to be a leak with the main O2.

Task performed:
1. TRAVEL TO 23 CHECKED CAB A/C, WORKING GOOD. 2. DRIVER COMPLAINT O2 LEAK SECURED LOOSE FITTING AT BOTTLE AND TESTED OK.

Parts	Quantity
NO PARTS USED	

Workorder: V59285

In Date: 07/23/2013
Close Date: 01/23/2014

Meter Reading: 58,932.00

Problem?

left rear tire red sensor light on.

Task performed:
CHECKED AIR PRESSURE OK.

Parts	Quantity
NO PARTS USED	



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V63760

In Date: 01/27/2014

Close Date: 02/21/2014

Meter Reading: 63,109.00

Problem?

C inspection R23

Parts

Quantity



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Task performed:

1. C-INSP. 2. CONTINUE C-INSP. 3. REPAIR LEAKS IN O2 SYSTEM. R&R SEVERAL FITTINGS AND RESEAL AND RESEAL AND RETEST. 4. DIAGNOSE WHY CAB A/C NOT COLD. R&R A/C COMPRESSOR R&R RECIEVER DRYER, REPLACED ALL O-RINGS AND BRACKETS. EVACUATE SYSTEM. 5. TIGHTEN ALL ALUM BLOCKS AND MTNG HOWR ON L/R DOUBLE COMPT DOORS- UPPER AND LOWER (4 DOORS). 6. CHARGER AND RETEST BATTERIES- ALL PASS. 7. FINIS CAB A/C SYSTEM. TEST RUN SYSTEM. TEMPS GOOD REINSTALL AI FILTER ASSY. 8. R&R R/F MARKER LT BUBS. 9. REAR COMPT DOESNT CLOSE. R&R STRIKER PLATE BEND AND SMOOTH CONTAI SURFACE. CLEAN AND LUBE LATCH ASSY. ADJUST STRIKER. CLEAN HINGE OF ROAD DIRT. 10. R&R UV LIGHT ASSY. R&R BULB. 11. R&R O2 WRENCH. DRILL AND TAP WRENCH FOR CABLE. APPLY VELCRO TO WRENCH AND CABINET WALL. ATTACH CABLE TO CABINET WALL. 12. R&R WIPER BLADES. 13. R&R CAB AUX A/C FILTER. 14. R&R RADIATOR HOSE RETAINER AND TY WRAP. 15. R& EXHAUST SHIELD- HAD TO CUT BOLTS OFF-FROZEN. R&R EXHAUS SHIELD MOUNT ON EX PIPE. 16. R&R EDGE GUARD ON DIVIDER IN O2 COMPT. SMOOTH METAL EDGES WHERE GUARD COULD NOT B APPLIED. 17. CHECK AIR DRYER SIGNAL LINES FOR LEAKS. R&R 2 FITTINGS AT GOVERNOR. BUILD SYSTEM AND RECHECK. 18. SERVICE P/S SYSTEM CHARGE FLUID ,FILTER AND CANISTER GASKET. 19. R&R L/S CAB DOOR PANEL IN ORDER TO REPAIR WIRING TO BLINKING RED LT INTERIOR PANEL. DO SAME ON L/S REAR DOOR. 20. R&R 4 GROUND LTS. HAD TO CUT CONNECTORS OFF AND SPLICE AND HEATSHRINK CONNECTIONS. 21. REMOVE MAP LT ASSY. HOUSING IS BROKEN- NEEDS NEW NONE IN STOCK- ORDERED. REINSTALL UNTIL NEW PART ARRIVES. 22. Q.C TRUCK. 23. HOOK UP LAPTOP CHECK DP CODE. CHECK DPF DATA FOR BAI PRESSURE AND ASTT ACCUMULATION CHECK WITH PARTS DEPT WHEN DPF WAS CHARGED 5-13 WS CHANGED ROAD TEST VEH EREASE CODE. 24. SIGNS OF LEAK ON L/S OF ENGINE. WAS AREA. RUN VEH. DRIVE VEH- NO LEAK FOUND.

15-40B15W40 MOTOR OIL NON SYN	30
1878042C91FUEL FILTER 2008 HORTON	1
194-ABULB	1
2506656C124316 WIX CAB A/C FILTER	1
2507061C1PS RESV GASKET	1
3599692C1CLAMP EXH SHIELD	1
3611894C9103-0805 A/C COMPRESSOR 4347	1
3670134C1ACCUMULATOR ASSY INT.	1
3835278C92PANEL DOMELIGHT	1
5774457744XD OIL FILTER	1
61H01LED GROUND LITE CLEAR	4
78R539018-2699 A/C FILTER	1
91-22WIPER BLADE	2
AS75807OXM1757-01 OXYGEN WRENCH	1
GPX13ULTRA VIOLET LIGHT SHORT	1
VML/T1808D2503221C1 FILTER POWER STEERING	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V64510

In Date: 02/25/2014 Meter Reading: 64,184.00
Close Date: 03/03/2014

Problem?

Running hot belts broken R23

Task performed:
BROKEN BELT R&R WENT BACK TO SHOP TO GET PARTS.

Parts	Quantity
1847727C1BELT	1
ANTICOOLANT ANTIFREEZE GAL	3

Workorder: V63349

In Date: 01/13/2014 Meter Reading:
Close Date: 03/20/2014

Problem?

AC not blowing cold.

Task performed:
REPAIRED ON WORK ORDER #63698.

Parts	Quantity
NO PARTS USED	

Workorder: V65017

In Date: 03/18/2014 Meter Reading:
Close Date: 03/28/2014

Problem?

Grill underneath officers seat in patient compartment missing screws and hanging off. r23

Task performed:
1. OUT AT STATION, 8:40 AM. 2. CHECKOUT FOUND SIREN MISSING
INSTALLED NEW SCREW SECURE BACK TO BOTTOM OF SET.
CHECK OK.

Parts	Quantity
NO PARTS USED	



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V65121

In Date: 03/22/2014
Close Date: 03/28/2014

Meter Reading:

Problem?

steering is very stiff, feels like there is something wrong with the power steering. We just got the truck back from the shop 2 days ago R23

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

SEE TICKET #65180.

Workorder: V65308

In Date: 03/30/2014
Close Date: 04/03/2014

Meter Reading:

Problem?

Airpack bracket in left front compartment (drivers airpack) is missing a screw so it is not mounted firmly in place.

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

TRAVEL TO 23 DRIVER COMPLAINT SCBA BRACKET IN L2 COMPARTMENT LOOSE SECURED BRACKET.

Workorder: V65415

In Date: 04/02/2014
Close Date: 04/03/2014

Meter Reading:

Problem?

hard start r23

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

WENT TO 23 CHECK OIL ADDED 1/2 GALLON OF COOLANT. STARTE AND RAN CHECK OK- CHECK CODES D.P.R CODE 4670. RAN REGEI CHECK OK- RETURN HOME.



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V65425

In Date: 04/03/2014
Close Date: 04/03/2014

Meter Reading: 67,303.00

Problem?

hard starting

Task performed:

1. FOUND D.P.R PLUGGED- R&R DPF- CLEANED PREFILTERS PIPE-
CHK CODES- CHK OK. 2. ASSIST KEVIN.

Parts	Quantity
DPFCLEANED UNIT	1

Workorder: V65671

In Date: 04/13/2014
Close Date: 04/21/2014

Meter Reading: 68,481.00

Problem?

Cab a/c inop

Task performed:

A/C SYSTEM HOOK UP A/C MACHINE CHECK OUT PRESSURES AND
OPERATION. FOUND LEAKAGE AT HIGH PRESSURE SHREADER-
SYSTEM WAS ONLY DOWN ABOUT 1/2 A POUND. HIGH SIDE
PRESSURE DOWN ERRACTIC. REPAIR COMPRESSOR AND
SHREADER VALVE. VACUUM AND RECHARGE, NOW LOOKING OK.

Parts	Quantity
16-31498925 VALVE CORE	1
3611894C9103-0805 A/C COMPRESSOR 4347	1

Workorder: V66005

In Date: 04/27/2014
Close Date: 04/29/2014

Meter Reading:

Problem?

R23 rear tires are approaching tire wear equal to the tread depth indicators
and the engine oil dipstick is reading overfull.

Task performed:

TRAVEL TO 23 DRIVER COMPLAINT TUIRES LOW. CALLED SHOP
AND ORDERED TIRES.

Parts	Quantity
NO PARTS USED	



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V66125

In Date: 05/01/2014
Close Date: 05/02/2014

Meter Reading: 69,470.00

Problem?

Replace rear tires

Parts	Quantity
-------	----------

Task performed:
Replace rear tires

NO PARTS USED

Vendor? BOULEVARD TIRE

Workorder: V66445

In Date: 05/13/2014
Close Date: 05/15/2014

Meter Reading:

Problem?

shoreline not charging

Parts	Quantity
-------	----------

Task performed:
DRIVER COMPLAINT SHORELINE CHARGER INOP. TURNED IRCUIT
BROKEN ON OK.

NO PARTS USED

Workorder: V66638

In Date: 05/20/2014
Close Date: 06/10/2014

Meter Reading:

Problem?

rear scene lights not working. they do not work when trying to turn them on manually with the switch on the dash they also dont come on automatically when you open back doors

Parts	Quantity
-------	----------

Task performed:
DRiver compartment rear scene lights out replaced both scene light bulbs

H35SN12BULB	2
-------------	---



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V67067

In Date: 06/08/2014
Close Date: 06/17/2014

Meter Reading:

Problem?

spot light is out on top of R23

Task performed:

TRAVEL TO 23 DRIVER COMPLAINT SPOT LIGHT OUT REPLACED SPOT LIGHT BULB AND CONTROLLER LIGHT STILL INOP WILL RETURN FOR WIRING PROBLEM.

Parts	Quantity
LGHGO-2020GOLIGHT MODEL 2020 SEARCH LIGHT	1

Workorder: V67070

In Date: 06/08/2014
Close Date: 06/17/2014

Meter Reading:

Problem?

RLT seat is not secured. The seat comes off of the mount.

Task performed:

DRIVER COMPLAINT SEAT BASE LOOSE REPLACED MISSING SCREWS AND TESTED OK.

Parts	Quantity
NO PARTS USED	

Workorder: V67418

In Date: 06/24/2014
Close Date: 06/25/2014

Meter Reading: 74,161.00

Problem?

replace two front tires

Task performed:

replace two front tires

Parts	Quantity
NO PARTS USED	

Vendor? BOULEVARD TIRE



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V67369

In Date: 06/22/2014
Close Date: 06/27/2014

Meter Reading:

Problem?

Spot light is out on top of R23

Parts	Quantity
-------	----------

Task performed:

travel to sta 23 driver compliant spot light inop repaired spot light .

NO PARTS USED

Workorder: V66967

In Date: 06/03/2014
Close Date: 07/01/2014

Meter Reading: 72,731.00

Problem?

B inspection R23

Parts	Quantity
-------	----------

Task performed:

completed on 65425

0775145PANEL FILTER	3
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
54-53030055-30BX CIRCUIT BREAKER	1
5774457744XD OIL FILTER	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V67294

In Date: 06/17/2014
Close Date: 07/01/2014

Meter Reading:

Problem?

The rear cab AC in the rescue is tripping the breaker on the shoreline at the station and not working properly. Also the rear and front AC is not working properly in the front cab. The AC in the front is blowing hot air.

Task performed:

1. A/C INOP - LEAKING SHRADER CORE VALVES AND BAD THERMISTORS TOPPED OFF COOLANT- CHECKED FOR CODES - CHECKED TIRES NEEDS TIRES NEEDS NEW PART TOP A/C UNIT. 2. INSTALLED GUAGES ASSIST IN A/C REPAIR.

Parts	Quantity
0915520120AUTO EJECT 20 AERO OTL3925	1
16-31438915 VALVE CORE A/C 3544706C1	1
1693981C1CAP A/C INTERNATIONAL	1
3544705C1CAP A/C INTERNATIONAL	1
3544706C1SCHRADER VALVE INT.	1
3622764C32606229C92 THERMISTER	1
F6DZ-8100-A9C3Z8101B RADIATOR CAP 10238 STAI	1

Workorder: V67503

In Date: 06/27/2014
Close Date: 07/07/2014

Meter Reading: 74,239.00

Problem?

cab a/c inop

Task performed:

1. CHECK CODE FOUND MIX DOOR CODE SO TOOK BOTH DOOR MOTOR OFF INSIDE BOTH DOR WORKED BY HAND AND BOTH MOTOR WORK SO PUT THEM BACK FOUND ONE THERMISTATE NO READING RIGHT. RECOVER SYSTEM R&R THEMISTER AND PLUGS CLEANED CONDENSER AND CHARGE SYSTEM. 2. ASSIST IN A/C TROUBLESHOOT.

Parts	Quantity
3542606C12611234C1 VENT ACTUATOR	2
3622764C32606229C92 THERMISTER	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V67420

In Date: 06/24/2014
Close Date: 07/14/2014

Meter Reading: 74,161.00

Problem?

Back up alarm and lights inop

Task performed:

check and repair auto eject. Back up and list alarm. Check out problem. Found alarm shorted. This would knock out LTS. Replace alarm system. Retest now all work ok.

Parts	Quantity
575BACKUP ALARM ECCO 107 DEC	1

Workorder: V65507

In Date: 04/07/2014
Close Date: 07/15/2014

Meter Reading:

Problem?

R23 is difficult to start and idles rough

Task performed:

work complete on ticket v 65425.

Parts	Quantity
NO PARTS USED	

Workorder: V67260

In Date: 06/16/2014
Close Date: 07/16/2014

Meter Reading:

Problem?

shoreline a/c not working when plugged into station.

Task performed:

repairs done on ticket v67294

Parts	Quantity
NO PARTS USED	



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V67805

In Date: 07/09/2014
Close Date: 07/16/2014

Meter Reading:

Problem?

Front cab A/C only blowing hot air R23

Task performed:
repaired on v67503

Parts	Quantity
2506656C124316 WIX CAB A/C FILTER	1
3542606C12611234C1 VENT ACTUATOR	1
3546241C1SWITCH A/C PRESSURE INT.	1

Workorder: V67852

In Date: 07/12/2014
Close Date: 07/16/2014

Meter Reading:

Problem?

The AC in the front cab is blowing hot intermitantly.

Task performed:
repaired on ticket v67503

Parts	Quantity
NO PARTS USED	

Workorder: V67999

In Date: 07/18/2014
Close Date: 07/21/2014

Meter Reading: 75,768.00

Problem?

broke down

Task performed:
Travel to Mezidian way and Okechobee. R23 broken down checked codes found active code for ICP wont build pressure. Tried starting unit with active with silicone spray. No work waited on wrecker.

Parts	Quantity
NO PARTS USED	



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V68327

In Date: 07/31/2014 Meter Reading:
Close Date: 08/05/2014

Problem?

pt compartment ac filters need to be replaced, and ac filter cover needs to be repaired. It keeps falling down.

Parts	Quantity
-------	----------

ZAJ1621901FRT BRAKE CAMBER 20" L/S INT. 36793	2
---	---

Task performed:

Remove and replace filters.

Workorder: V68328

In Date: 07/31/2014 Meter Reading:
Close Date: 08/05/2014

Problem?

passenger compartment ac blowing hot air

Parts	Quantity
-------	----------

NO PARTS USED	
---------------	--

Task performed:

Checked AC. Ran system, no codes found. Recover freon . Recharge system. Ran and checked operation. Check engine fan, checked ok.

Workorder: V68329

In Date: 07/31/2014 Meter Reading:
Close Date: 08/05/2014

Problem?

sharps drawer in pt compartment fell off the hinges. needs repair

Parts	Quantity
-------	----------

2220-145632-14 DRAWER SLIDE	2
5632-1212 IN PAIR DRAWER SLIDES	1

Task performed:

Found slide tracks broken on drawer. Removed old tracks, drilled and mounted new slides. Adjsuted slide.Checked ok.



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V68367

In Date: 08/03/2014
Close Date: 08/05/2014

Meter Reading:

Problem?

still need a/c cover in pt compartment screwed in so it doesnt fall down in the way of employees with pt's

Parts	Quantity
-------	----------

Task performed:

Inspected all covers. Checked ok.

NO PARTS USED

Workorder: V68540

In Date: 08/09/2014
Close Date: 08/13/2014

Meter Reading:

Problem?

Shoreline ac does not work when plugged in. R23

Parts	Quantity
-------	----------

Task performed:

ck, a/c 110v found braker triped reset for sta, ck, ok

NO PARTS USED

Workorder: V67078

In Date: 06/09/2014
Close Date: 08/21/2014

Meter Reading:

Problem?

high oil level

Parts	Quantity
-------	----------

Task performed:

repaired on 68083

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V68712

In Date: 08/15/2014 Meter Reading:
Close Date: 08/21/2014

Problem?

1)bay door remote control is non-functional. 2)pt compartment single chair vent below has come loose due to screws falling out. r23

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

TRAVEL TO STA, 23 DRIVER COMPLANT A/C VENT LOOSE
INSTALLED SCREW IN A/C VENT .

Workorder: V68965

In Date: 08/26/2014 Meter Reading: 77,857.00
Close Date: 08/28/2014

Problem?

AC in the front compartment won't cool. Blowing hot air in both front and back vents. R23

Parts	Quantity
-------	----------

3611894C9103-0805 A/C COMPRESSOR 4347	1
3622764C32606229C92 THERMISTER	1

Task performed:

Preformed A/C diagnostics with scantool and leak tests. Found A/C compressors valves failing. Recovered freon and reclaimed. Replaced failed compressor System cooled for 20 minutes and compressor turned off. Further diagnostics showed fsiled evaporator output thermnistor failure. Recovered system, replaced thermistor and rechagred to specs

Workorder: V68864

In Date: 08/21/2014 Meter Reading:
Close Date: 09/02/2014

Problem?

Rear air conditioner charging port does not work on rescue 23.

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

travel to sta,23 ck,a/c found no 110v a/c will order parts to repair .



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V69094

In Date: 09/01/2014
Close Date: 09/03/2014

Meter Reading: 78,259.00

Problem?

A/C inop

Task performed:

Found 2 inside servo codes. Removed panels. Recover freon. 2. Repair A/C continue. Remove and replace both inside door servo. motors. Remove and replace thermistors, outlet shorted. Blow out oil in system. Remove and replace shrader cores. Vaccuum and leak test. Charge system, reset door motors. Checked ok.

Parts	Quantity
16-31438915 VALVE CORE A/C 3544706C1	1
3542606C12611234C1 VENT ACTUATOR	2
3544706C1SCHRADER VALVE INT.	4
3622764C32606229C92 THERMISTER	1

Workorder: V69110

In Date: 09/01/2014
Close Date: 09/03/2014

Meter Reading: 78,259.00

Problem?

ON CALL A/C 10-7 R23

Task performed:

Cab A/C inoperable. Recovered freon and vacuumed system. Recharged with 2lb 4oz. A/C worked fine, cooled down to 50 degrees.

Parts	Quantity
NO PARTS USED	

Workorder: V69082

In Date: 09/01/2014
Close Date: 09/04/2014

Meter Reading:

Problem?

The air conditioning began working intermittenly in the front cab. The AC would begin to blow out warm air. R23

Task performed:

travel to sta,23 ck, freon level but could not get compressor to come on hooked up laptop program inop, called international no luck sent to shop.

Parts	Quantity
NO PARTS USED	



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V69436

In Date: 09/17/2014 Meter Reading:
Close Date: 09/19/2014

Problem?

cab AC intermittently blows warm air

Task performed:

travel to sta23 tested unit no problem found at this time.

Parts	Quantity
-------	----------

NO PARTS USED

Workorder: V68924

In Date: 08/25/2014 Meter Reading: 77,799.00
Close Date: 09/25/2014

Problem?

a/c in cab intermittent master power switch inop

Task performed:

Parts	Quantity
-------	----------

51-30219-1045 MASTER SWITCH 175 AMP	1
-------------------------------------	---

Workorder: V69754

In Date: 09/29/2014 Meter Reading: 80,526.00
Close Date: 09/30/2014

Problem?

cab a/c not cold

Task performed:

CK, COMPUTER FOR A/C CODES CK, SYSTEM FOUND FAN CLUTCH BAD INSTALLED NEW CLUTCH CK, OK

Parts	Quantity
-------	----------

HOR994972FAN CLUTCH INT. 3611885C93	1
-------------------------------------	---



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V69794

In Date: 09/30/2014

Meter Reading:

Close Date: 10/29/2014

Problem?

Left side emergency light cover is missing light is working

Parts

Quantity

Task performed:

Completed on WO# 70136

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V70136

In Date: 10/14/2014
Close Date: 10/29/2014

Meter Reading: 81,967.00

Problem?

C-inspection

Task performed:

1. "C" inspection 2. Replace batteries 3. Front brakes- Remove and replace drums, shoes and kits. Adjust brakes to proper adjustment 4. Install new cover on side box light. Remove water from rear back up lights and diagnose rear emergency lights not working properly. 5. Transmission service 6. Siren's inop- Diagnose sirens not coming on 7. Convert grease bearings over to oil and retorque bearings. 8. 110v A/C inoperable- Diagnose, remove converter box and check wires for shorts. Check converter box for power All connections good, trace wires to thermostat all wires good. Jumper wire at thermostat. Bad thermostat. 9. Fan clutch inop Electrical diagnostics 10. Air governor leaking. R/R air governor with new fittings.

Parts	Quantity
02840366DOOR SHOCK HORTON	2
0775145PANEL FILTER	2
091-84-022DIODE 6 AMP	2
16-31438915 VALVE CORE A/C 3544706C1	1
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
284358GOVERNOR D-2	1
29526898 29548988 TRANS FILTER ALLISON	1
295SLSA1SIREN	1
370001ASEAL 35066	2
3753BRAKE DRUM RUMPER FRONT	2
5774457744XD OIL FILTER	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	6
CHR1612340-4024 HUB COVER - FRONT AXLE 2004	2
F6DZ-8100-A9C3Z8101B RADIATOR CAP 10238 STAI	1
HP-31DBATTERY 950CCA HP-31D	6
KSMA2124703QFRONTBRAKE KIT RUMPER AND 4D	2
QL97SFCAAAMBER QUAD LIGHT	1
TH5220D1003WALL THERMOSTATE HORTON	1
Z8012062C-02LENS CLEAR 9 X 7 FLUTED	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V70530

In Date: 10/28/2014
Close Date: 11/03/2014

Meter Reading: 82,442.00

Problem?

Right headlight out R23

Task performed:

Travel to 23 , replaced headlight

Parts	Quantity
9007H9007 BULB ASSY	1

Workorder: V69541

In Date: 09/20/2014
Close Date: 11/05/2014

Meter Reading: 80,027.00

Problem?

AC intermittently blows hot air after running for a while R23

Task performed:

Came to shop to repair. 1. Found A/C codes. 1552 motor jammed 1547-48 inlet and outlets sensor open. Remove and replace fresh air servo motor, ran unit not cooling. Recover freon. 2. Repair A/C, remove and repair accum and expansion valve. Flushed condensor, lines and evaporator. Remove and repair thermsitors. Vacuum and charge outlet thermistors code. Remove and repair connector reset blend doors. Ran and checked ok.

Parts	Quantity
3622764C32606229C92 THERMISTER	1
3660853C22512331C1 EXP VALVE NAV	1
3670134C1ACCUMULATOR ASSY INT.	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V70133

In Date: 10/14/2014
Close Date: 11/05/2014

Meter Reading: 81,967.00

Problem?

Cab a/c inop

Task performed:

1. Thermistors shorted out-Recover freon and replace thermistors and shradar cores. 2.Blend door on fire well jammed-Remove and replace motor and reset motors

Parts	Quantity
3542606C12611234C1 VENT ACTUATOR	1
3622764C32606229C92 THERMISTER	1

Workorder: V70929

In Date: 11/14/2014
Close Date: 11/20/2014

Meter Reading:

Problem?

The back up alarm when backing the truck does not go off.

Task performed:

Check unit for back up alarm, not working alarms working good at this time. Check for loose connection. Test for operation, it's ok.

Parts	Quantity
NO PARTS USED	



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V68083

In Date: 07/22/2014

Close Date: 12/03/2014

Meter Reading: 75,768.00

Problem?

high pressure pump bad

Task performed:

Parts	Quantity
065624AD-IP DRIER	1
1812348C1FUEL LINE SLEEVE INT	4
1842626C951842626C96 OIL RAIL MANIFOLD SEALS	1
1875784C921875784C93 ICP SENSOR	1
1882259C931882259C94 HIGH PRESSURE OIL PUMI	1
1893940C911893940C93 OIL LINE HIGH PRESS PUV	1
2593986C1DPF GASKET	1
2593998C1DPF GASKET	1
3757REAR DRUMS 3757X 3647X	2
46870AIR FILTER	1
5010561R925010561R93 INJECTOR	6
91-22WIPER BLADE	2
ACX-84534LUG NUT COVER PK10	3
DPFCLEANED UNIT	1
K022105PURGE VALVE AD-IP-IS	1
XK4034707QPMHD SHOE KIT 3/8 BEAM	2



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V68368

In Date: 08/03/2014
Close Date: 12/03/2014

Meter Reading:

Problem?

this truck just came back from service. it drives worse then when it when in. Temp light comes on after a while, wont accelerate from a stop. This truck i becoming unsafe for employees and pt's.

Task performed:

Parts	Quantity
1841923C97INJ PUCK ADAPTER	6
5010561R925010561R93 INJECTOR	1
CORECORE CHARGE	1

Workorder: V71295

In Date: 12/01/2014
Close Date: 12/03/2014

Meter Reading: 85,407.00

Problem?

ON CALL AIR LEAK R23

Task performed:

Drive to station, check unit found needs rear air bags. All repair got done at cnetral shop. Including welding on rear step stoppeers, it's good now.

Parts	Quantity
GUI1R11216GY1R11216 AIR BAG INT.	2

Workorder: V71511

In Date: 12/09/2014
Close Date: 12/10/2014

Meter Reading: 8,565.00

Problem?

BIO HAZARD DRAWER BROKEN

Task performed:

Replaced sides on bio hazard drawer-had to redrill all mounting holes (stripped out) and install next size up hardware also adjust latch and bend striker back in place.

Parts	Quantity
2220-145632-14 DRAWER SLIDE	2
5632-1212 IN PAIR DRAWER SLIDES	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V71582

In Date: 12/11/2014 **Meter Reading:** 8,565.00
Close Date: 12/12/2014

Problem?

the rear passanger scene light is 10-7. Also the radiator fluid is just above the low indicator on the reservoir.

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

Corrected loose bulb and added fluid

Workorder: V71236

In Date: 11/28/2014 **Meter Reading:**
Close Date: 12/15/2014

Problem?

Air leak coming from the back axle air dump. Unit is drivable

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

Checked for air leak in dump working-correctly no problem found.

Workorder: V71465

In Date: 12/07/2014 **Meter Reading:** 8,565.00
Close Date: 12/15/2014

Problem?

biohazard drawer broken and needs re mounting

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

Truck repaired at shop on another ticket-no parts, no labor



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V71604

In Date: 12/12/2014
Close Date: 12/15/2014

Meter Reading: 86,446.00

Problem?

during morning inspection it was noted the the oil level was above the max indicator line.

Parts	Quantity
-------	----------

Task performed:

Went to 23-found oil level just above level-Ok to run.

NO PARTS USED

Workorder: V70931

In Date: 11/14/2014
Close Date: 01/02/2015

Meter Reading:

Problem?

The trendelenburg on the stretcher does not work. Unable to lift the legs.
The bottom portion of the stretcher does not "click" into a lifted position.

Parts	Quantity
-------	----------

Task performed:

Problem was reported to Emsar for repair

NO PARTS USED

Workorder: V71193

In Date: 11/25/2014
Close Date: 01/02/2015

Meter Reading:

Problem?

air compressor/tank leaking air driver side rear

Parts	Quantity
-------	----------

Task performed:

Completed. See work order V71236

NO PARTS USED



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V72296

In Date: 01/13/2015
Close Date: 01/16/2015

Meter Reading: 89,400.00

Problem?

replaced rear tires

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

WORK REPAIRS AS REQUESTED.

Vendor? BLVD TIRE CENTER

Workorder: V72485

In Date: 01/21/2015
Close Date: 01/22/2015

Meter Reading:

Problem?

need new windshield wipers

Parts	Quantity
-------	----------

91-22WIPER BLADE	2
------------------	---

Task performed:

Replaced wiper blades.

Workorder: V69404

In Date: 09/15/2014
Close Date: 01/23/2015

Meter Reading:

Problem?

A/C Power when vechile is parked is not turn the air conditionor systemr on R23

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

repairs complete on w/o 69541



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V72533

In Date: 01/22/2015
Close Date: 01/23/2015

Meter Reading:

Problem?

oil level was above the max indicator line during the morning vehicle check.

Task performed:

Change oil and filter.

Parts	Quantity
15-40B15W40 MOTOR OIL NON SYN	30
5774457744XD OIL FILTER	1

Workorder: V72832

In Date: 02/03/2015
Close Date: 02/10/2015

Meter Reading: 91,316.00

Problem?

batt switch bad

Task performed:

Battery switch inop.

Parts	Quantity
51-30219-1045 MASTER SWITCH 175 AMP	1
SBJ-4201RELAY GLOW PLUGS SUTPHEN	1

Workorder: V72600

In Date: 01/26/2015
Close Date: 02/23/2015

Meter Reading:

Problem?

back light do not work put request in three weeks ago still not working

Task performed:

Replaced rear load light.

Parts	Quantity
H35SN12BULB	1



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V73852

In Date: 03/12/2015
Close Date: 03/12/2015

Meter Reading: 93,890.00

Problem?

REPLACES FRONT TIRES

Parts	Quantity
-------	----------

Task performed:
REPLACE FRONT TIRES

NO PARTS USED

Vendor? BOULEVARD

Workorder: V73793

In Date: 03/10/2015
Close Date: 03/17/2015

Meter Reading:

Problem?

Driver side low headlight is out. R23

Parts	Quantity
-------	----------

Task performed:
1. Travel to 23. Replaced bown headlight.

9007H9007 BULB ASSY	1
---------------------	---



4/20/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V73378

In Date: 02/24/2015
Close Date: 04/10/2015

Meter Reading: 93,085.00

Problem?

B inspection R23

Task performed:

1. B-Service. 2. Repair lights on rear of unit electrical problems. 3. Remove and send seat (driver) for repair. Install. 4. Correct pressure in tire- Coolant level power steering level. 5. Install new seat belt for driver seat.

Vendor? CENTRAL AUTO TRIM

Parts	Quantity
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
3711331C1SEAT BELT	1
3711355C91RECIEVER SEAT BELT BUCKLE WITH TI	1
5774457744XD OIL FILTER	1
QL97SFCAAAMBER QUAD LIGHT	1

Workorder: V74129

In Date: 03/24/2015
Close Date: 04/30/2015

Meter Reading:

Problem?

driver side headlight out

Task performed:

1. Travel to 23 R&R headlight.

Parts	Quantity
9007H9007 BULB ASSY	1



4/20/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182101

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V71887

In Date: 12/28/2014

Meter Reading:

Close Date: 06/30/2015

Problem?

ABS and Electrical fault light on. R23

Parts

Quantity

Task performed:

NO PARTS USED