



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V203

In Date: 10/13/2005

Close Date: 10/18/2005

Meter Reading: 51,417.00

Problem?

B INSPECTION SPARE R53

Task performed:

See B Inspection pre-printed form

Parts

Quantity

007985006541SCREW OBSOLETE	1
032-0116549297 BATTERY INDICATOR	1
6806970098SEAL DOOR	1
A1834388002MOLD L/H	1
A1834388003MOLD R/H	1
CA8193AIR FILTER 46744 WIX	1
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1
VML-S1414FILTER P/S	1
VML-T1264GASKET P/S COVER	1
VML-T1279WASHER P/S	1

Workorder: V851

In Date: 12/08/2005

Close Date: 12/15/2005

Meter Reading:

Problem?

A INSPECTION R26

Task performed:

Parts

Quantity

322502BULB PATIENT GH22	4
-------------------------	---



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V1368

In Date: 01/31/2006
Close Date: 02/22/2006

Meter Reading:

Problem?

LITE OUT IN FRONT LIGHT BAR, SR-3 AT STA-35

Parts	Quantity
-------	----------

Task performed:

02038249800CLIGHT ROTATOR USE 01-0416333-00	1
---	---

Workorder: V1473

In Date: 02/10/2006
Close Date: 03/02/2006

Meter Reading:

Problem?

REAR A/C INOP, R-41

Parts	Quantity
-------	----------

Task performed:

22-49905-000CABLE HEATER	1
ABPN83322930CONTROL HEAD AC/HEAT	1



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V1510

In Date: 02/14/2006
Close Date: 03/02/2006

Meter Reading: 56,838.00

Problem?

a inspection r41 spare

Task performed:

Parts	Quantity
17211899000FILTER AIR 30-963	1
18-29935-001RH DOOR LATCH NEW	1
194BULB	4
5757 BULB	1
BPR5ESSPARK PLUG 7734	1
V122XARESCUES MARKER LIGHT	1
V122XRCAN USE 46892-5 MARKER LIGHT	1

Workorder: V1922

In Date: 03/21/2006
Close Date: 03/24/2006

Meter Reading: 58,376.00

Problem?

A INSPECTION

Task performed:

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V1712

In Date: 03/02/2006
Close Date: 03/27/2006

Meter Reading: 57,580.00

Problem?

A INSPECTION SPARE R32

Task performed:

Parts	Quantity
18-20141-000WASHER	3
ESX120105112STARTER RELAY ESX-120-105112	1
SWT54924ACTUATOR-RED	1

Workorder: V2022

In Date: 03/29/2006
Close Date: 04/12/2006

Meter Reading:

Problem?

NEED 2 TIRES SR-3

Task performed:

Parts	Quantity
NO PARTS USED	

Vendor? TCI

Workorder: V2290

In Date: 04/18/2006
Close Date: 04/26/2006

Meter Reading:

Problem?

A INSPECTION SR-3 (BACK FROM STA-17)

Task performed:

Parts	Quantity
4864JBRALTERNATOR 270 A	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V1118

In Date: 01/04/2006
Close Date: 05/11/2006

Meter Reading:

Problem?

A INSPECTION SPARE R32

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED

Workorder: V747

In Date: 11/30/2005
Close Date: 05/11/2006

Meter Reading:

Problem?

ONE HALOGEN LIGHT OUT IN FRONT LIGHT BAR, SR-10 AT STA-47

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED

Workorder: V2370

In Date: 04/24/2006
Close Date: 05/23/2006

Meter Reading:

Problem?

A INSPECTION, SR-3

Parts	Quantity
-------	----------

Task performed:

MTR3030VM-100 VOLT METER	1
--------------------------	---



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V2780

In Date: 05/27/2006
Close Date: 05/30/2006

Meter Reading:

Problem?

Pt compartment a/c not working

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED

Workorder: V2676

In Date: 05/18/2006
Close Date: 06/07/2006

Meter Reading: 57,000.00

Problem?

AirHorn not working right

Parts	Quantity
-------	----------

Task performed:

FTT5392USE 1432 SWITCH PRESSURE AC LO LIMIT	1
VML-T1264GASKET P/S COVER	1

Workorder: V2933

In Date: 06/11/2006
Close Date: 06/13/2006

Meter Reading:

Problem?

Noticed "engine check" light on while driving. Turned engine off and back on, engine light now noted off.

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10136370 FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V2984

In Date: 06/14/2006
Close Date: 06/27/2006

Meter Reading: 59,578.00

Problem?

B INSPECTION, SR-3 (BACK FROM STA-32)

Task performed:

Parts	Quantity
11-24WIPER REFILL	1
1141BULB	1
1149610278 MIRROR	1
565044SHOCK FRONT SER TRK	2
565100SHOCK REAR SER TKR	2
A1834388003MOLD R/H	1
L1261F33585XE FUEL FILTER WIX	1
MK184HDBRAKE PADS	1
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1

Workorder: V3203

In Date: 06/28/2006
Close Date: 07/06/2006

Meter Reading: 59,740.00

Problem?

A INSPECTION AND REPAIRS AS NEEDED BACK FROM STA 16

Task performed:

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10136370 FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V3462

In Date: 07/13/2006
Close Date: 07/28/2006

Meter Reading:

Problem?

A INSPECTION AND REPAIRS AS NESS. SR3 BACK FROM 18

Task performed:

Parts	Quantity
02036320700LINEAR STROBE MOD.6E EXTR. MOUN	1
02038332800REFLECTOR	1
6809880678STUD DZ	2
6809940145CLIP	2
6811802645S68-1180264-5S LENS RED	1
A0631087000CABLE BATT. POS.	1
A0631088000CABLE BATT. NEG.	1
HP-31DBATTERY 950CCA HP-31D	4

Workorder: V3722

In Date: 08/01/2006
Close Date: 08/08/2006

Meter Reading:

Problem?

DOOR OPEN WARNING LT ON SR3 AT 31 ON CALL

Task performed:

Parts	Quantity
SWT5924DOOR OPEN MAP DISPLAY	1



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V3819

In Date: 08/07/2006
Close Date: 08/22/2006

Meter Reading:

Problem?

A INSPECTION AND REPAIRS AS NEEDED SR3 BACK FROM 31

Task performed:

Parts	Quantity
322502BULB PATIENT GH22	1
9451BELT	1
9485BELT	1
K080733BELT	1

Workorder: V4002

In Date: 08/18/2006
Close Date: 08/23/2006

Meter Reading: 60,775.00

Problem?

A INSPECTION AND REPAIRS AS NECESARY BACK FROM 31

Task performed:

Parts	Quantity
322502BULB PATIENT GH22	1
921LIGHT BULB	1
98003RREFLECTOR RED 40132 GROTE	1
LTC594111656-16 LATCH R/H MEDIC MASTER	1
SWT5924DOOR OPEN MAP DISPLAY	1
VF445F11FSO140A RELAY A/C DIODE SUP	1



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V4219

In Date: 09/01/2006
Close Date: 09/06/2006

Meter Reading: 60,919.00

Problem?

A INSPECTION AND REPAIRS AS NEEDED SR3 BACK FROM 53

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED

Workorder: V4308

In Date: 09/07/2006
Close Date: 09/11/2006

Meter Reading: 6,234.20

Problem?

Open door alarm sounds when vehicle put into DRIVE, all doors checked, alarm continues to sound. R14

Parts	Quantity
-------	----------

Task performed:

SWT5924DOOR OPEN MAP DISPLAY	1
------------------------------	---

Workorder: V4358

In Date: 09/10/2006
Close Date: 09/11/2006

Meter Reading: 6,238.00

Problem?

Bad A/C clutch for cab A/C, per mechanic. SR3 AT 14 ON CALL

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V4425

In Date: 09/13/2006 Meter Reading: 61,124.00
 Close Date: 09/26/2006

Problem?

A INSPECTION AND REPAIRS AS NEEDED SR3 BACK FROM 14

Parts	Quantity
-------	----------

Task performed:

1. PERFORMED A-INSPECTION.

NO PARTS USED

Workorder: V4838

In Date: 10/10/2006 Meter Reading: 61,124.00
 Close Date: 10/11/2006

Problem?

A INSPECTION AND REPAIRS AS NEEDED SR3 BACK FROM 18

Parts	Quantity
-------	----------

Task performed:

1. PERFORMED "A" INSPECTION. 2. WASHER FLUID NOZZLE BROKEN- REMOVE INSTALL NEW NOZZLE TIP.

SPRGW2612WASHER NOZZLE W/RELIEF	5
---------------------------------	---



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10136370 FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V5165

In Date: 10/30/2006
Close Date: 11/03/2006

Meter Reading: 62,100.00

Problem?

A INSPECTION AND REPAIRS AS NEEDED SR3 BACK FROM 41

Task performed:

1. PERFORM "A" INSPECTION. 2. REPAIR AIR HOSE. 3. COPY 50 "A" INSPECTION FORMS AND STAPLE. 4. REPAIR REAR A/C REPLACED HIGH SIDE PRESSURE SWITCH. DEFECTIVE PART, INSTALL 2ND SWITCH (OK).

<u>Parts</u>	<u>Quantity</u>
01-20152-00501-20152-006 CLAMP	2
038-1550-00VALVE CHECK HALE 1/4"	1
101291015434 LATCH TRIGGER S/O	1
102162TANK LEVEL TRANSDUCER PRES	2
102245111661 GAUGE TANK LEVEL CLASS 1	1
1156BULB	10
2032-0000-30LENS CLEAR	1
372000030BATTERY ON DISPLAY	1
52-24WIPER BLADES ANCO 24	2
6256LNC6256LNC COVER LUG NUT	1
78R536078R5360M 2PK FILTER AIR COND	1
91513AMBER LENS	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
DPSTDPST SW-ROCKER	2
EXO3AH00015SPLUG RAD. DRAIN	1
FTT53931491 SW PRESS. HI SIDE NC OPEN-350 CL(2
HP-31DBATTERY 950CCA HP-31D	4
SPRGW2612WASHER NOZZLE W/RELIEF	1
SWT54913SW ROCKER SPST ON-OFF RED	1



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V5366

In Date: 11/13/2006 Meter Reading: 62,331.00
 Close Date: 11/13/2006

Problem?

ON CALL DOOR OPEN WARNING LT GOING OFF SR 3 AT 32

Task performed:

Parts	Quantity
LTC5993SSM1-63-8 LATCH STAINLESS	2
SWT5924DOOR OPEN MAP DISPLAY	3

Workorder: V5473

In Date: 11/21/2006 Meter Reading: 62,647.00
 Close Date: 11/27/2006

Problem?

A INSPECTION AND REPAIRS AS NEEDED SR3 BACK FROM 32

Task performed:

1. "A" INSPECTION 2 REPLACE BOI HAZARD DOOR

Parts	Quantity
05-17223-000CAP RADIATOR 10 LB	1
DOOR2LEXAN 14.5 X 8.5	1

Workorder: V5788

In Date: 12/12/2006 Meter Reading: 62,647.00
 Close Date: 12/14/2006

Problem?

REPAIR STRETCHER MEDCO EQUIP. REPAIR SR3 AT14

Task performed:

1. STRETCHER SENT TO MEDCO EQUIPMENT REPAIR INC. FOR EMERGENCY REPAIR.

Vendor? MEDCO EQUIPMENT REP/

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V5117

In Date: 10/27/2006 Meter Reading: 6,329.00
 Close Date: 12/21/2006

Problem?

a/c unit in the back compartment not blowing cold.r41

Task performed:

- 1. Repaired A/C

Parts	Quantity
-------	----------

NO PARTS USED

Workorder: V5993

In Date: 12/28/2006 Meter Reading: 63,111.00
 Close Date: 12/29/2006

Problem?

A Inspection and needed repairs SR back from 31

Task performed:

- 1. A Inspection Replaced 2 valve stem caps

Parts	Quantity
-------	----------

435 VALVE CAP	2
---------------	---

Workorder: V10994

In Date: 10/12/2007 Meter Reading: 67,034.00
 Close Date: 10/22/2007

Problem?

A inspection and related repairs (back from Pompano) please verify tach radio is on our frequency

Task performed:

- 1. perform "A" service
- 2. replaced wiper blades
- 3. replaced left, front lingh bar marker light bulb
- 4. replaced left side turn signal side marker light bulb
- 5. trouble shoot rear directional light bar. replaced 2 light bulbs. rewired light bar plug. replaced control head in console.

Parts	Quantity
-------	----------

1895BULB	1
194BULB	1
52-24WIPER BLADES ANCO 24	2
H20SN12H20SN12 BULB	2



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10136370 FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V11227

In Date: 10/24/2007

Meter Reading: 71,698.00

Close Date: 11/15/2007

Problem?

b inspection and repairs as needed sr3 back fro 36

Task performed:

1. Protect upper Rad. hose. Pressure check found fitting seeping at connection to air compressor. removed hoses for access and tightened fitting 2. Replace rear shocks 3. Replaced LR mud flap. Cut and drill to size. 4. Remove non skid stripping from side patient Comp. step. Clean area of old adhesive and apply new strips. 5. Tighten A/C belts. 6. R+R 6 wheels and tires with new. Air tires to 100 psi. 7. Road test for new tires erased ABS codes and check Trans. fluid warm after service. 8. Clean shop floor, sweep and used machine to clean. 9. B-inspection fill washer reservoir P/S reservoir replaced LF hub plug. Install missing fender fastener. 10. Service batteries. 11. Lubricate all hold opens, latches and hinges. replace missing fasteners in door panels and tighten all fastners. Install missing screws patient comp. trim. tighten loose latches. 12. Cooler service. 13. Diagnose roof spot light not moving found bad control unit. replaced control unit. 14. Vac, pick up supplies for turkey day, cook and clean, clinic. 15. Trans service 16. Meeting 17. Rear A/C service. 18. Install patient Copm. weatherstrip. replaced R side reflective trim and Insert cut front trim piece sticking out and secured. 19. Air dryer service. 20. tighten loose front shock and front left spring eye bolt. 21. Rebuild dryer and purge valve. 22. replaced wiper blades. 23. parts Dept. 24. Replaced patient Comp. exhaust blower. 25. Torque U-Bolts 26. Check engine trans and Abs codes found 434 engine and inactive Abs code. erased codes. 27. Diagnose 110V A/C. Found bad compressor. Replaced compressor. 28. Repair wiring for O2 guage. 29. Install 2 Comp shocks need 2 more parts ordered. 30. Install L side door hinge. Drill out holes to correct size and repair striped bolt threads. 31. Replace L+R front door weatherstripping. 32. Remove L front seat belt fastener and untwist seat be

Parts

Quantity

161657700065489 SHOCK REAR NEW RESCUE	2
2436A432436A43 MUD FLAP 24X36	1
29526898 29548988 TRANS FILTER ALLISON	1
453879OIL PLUG CAN USE STEMCO	1
52-24WIPER BLADES ANCO 24	2
6806970098SEAL DOOR	1
6809880678STUD DZ	1
CA8193AIR FILTER 46744 WIX	1
DEC6100DECAL REFLECTIVE STRIPE	8
ELB56711446175 BLOWER 4 IN	1
HLD3999GSS1715UV 30LB STRUT GAS	1
HLD44614446 1/4 LATCH	1
JABSC289447USE 21481 REMOTE CONT. FOR MOD	1
L1261F33585XE FUEL FILTER WIX	1
MFG9928PL17008 VERSACELL DECAL BACKING	8
PH8942FILTER OIL 57182 LFP3729	1
RKB5513COMPRESSOR A/C 115V R22	1
RN60JDRYER KIT	1
S3225PFUEL FILTER 33630 LFF5849	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10136370 FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V11350

In Date: 10/31/2007 Meter Reading: 71,698.00
Close Date: 11/21/2007

Problem?

replace tires at callaghan ent sr3

Parts ----- Quantity -----

Task performed:

Replace tire - Callghan j

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V11745

In Date: 11/26/2007 Meter Reading: 72,035.00
Close Date: 11/29/2007

Problem?

on call r45 b patient a/c 10-7

Parts ----- Quantity -----

Task performed:

1. Patient comp. A/C inop./ wiring broken to compressor, repaired wiring.

NO PARTS USED

Workorder: V12375

In Date: 01/05/2008 Meter Reading: 7,188.90
Close Date: 01/09/2008

Problem?

need new headset(driver) R-73

Parts ----- Quantity -----

Task performed:

1. Dropped off headsets for Rescue.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V12376

In Date: 01/05/2008 Meter Reading: 7,188.90
 Close Date: 01/09/2008

Problem?

lens missing passenger strobe lens R-73

Task performed:

1. Replaced broken lens for right, front, upper, strobe light on body.

Parts	Quantity
9E0C20RUUSE 902000RR RED STROBE LIGHT	1

Workorder: V11098

In Date: 10/18/2007 Meter Reading: 67,034.00
 Close Date: 01/15/2008

Problem?

ON CALL WONT START SR3 AT 36

Task performed:

Parts	Quantity
4864JBRALTERNATOR 270 A	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
HP-31DBATTERY 950CCA HP-31D	4

Workorder: V12516

In Date: 01/11/2008 Meter Reading: 72,493.00
 Close Date: 01/24/2008

Problem?

CHECK ENG LT R73

Task performed:

1. Drove to Sta. Reset 434 codes reset. take compartment door apart replace hinges and lock, test OK. 2. Rework mid door drill holes installed hinges.

Parts	Quantity
LTC594111656-16 LATCH R/H MEDIC MASTER	1



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V12911

In Date: 01/30/2008 Meter Reading: 7,256.00
 Close Date: 02/04/2008

Problem?

passenger side compartment door not opening again. r73

Parts	Quantity
-------	----------

Task performed:

Drive to Stn73; repair R-1 compartment door j

NO PARTS USED

Workorder: V12377

In Date: 01/05/2008 Meter Reading: 7,188.90
 Close Date: 02/06/2008

Problem?

driverside compartment hinge broken R-73

Parts	Quantity
-------	----------

Task performed:

1. Travel to st 73 2. remove broken hinge on L2 compartment

HLD44614446 1/4 LATCH	1
-----------------------	---

Workorder: V13470

In Date: 02/25/2008 Meter Reading: 75,067.00
 Close Date: 02/27/2008

Problem?

A/C compressor broken R73 (on-call)

Parts	Quantity
-------	----------

Task performed:

Call Stn; get compressor part number; drive to shop; unable to find compressor; bring (3) compressors to Stn73; none are correct; try to adj broken one-NG; bring driver to shop; swap out trucks. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10136370 FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V13517

In Date: 02/26/2008
Close Date: 03/05/2008

Meter Reading: 75,067.00

Problem?

repair a/c compressor r73

Task performed:

1. "A" inspection 2. R & R A/C compressor, ear broken off, R&R A/C dryer, R&R belts 3. Tighten all door latches, R&R rear compartment light, R&R rear compartment light, Replace screw in over head light

Parts	Quantity
16-31455533 CAP LOW SIDE BLUE	1
16-3444CAP R134A - RED 5575/5557	1
322502BULB PATIENT GH22	1
532703-0602 COMPRESSOR U4735 4471	1
716907-0610A DRYER	1
8201L17-3428 ESTER OIL E7	1
9451BELT	1
9485BELT	1

Workorder: V13525

In Date: 02/26/2008
Close Date: 03/13/2008

Meter Reading: 75,067.00

Problem?

tow unit from sta 73 to shop

Task performed:

Tow unit from Stn73 to shop - Moss Transportation j

Parts	Quantity
NO PARTS USED	

Vendor? MOSS TRANS



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V13808

In Date: 03/11/2008 Meter Reading: 7,410.00
 Close Date: 03/17/2008

Problem?

the front a/c unit blows hot only r73

Parts	Quantity
-------	----------

Task performed:

1. Go to station and back home 2. Repair A/C not cooling, found heater cables off of heater control valve, repaired cable.

NO PARTS USED

Workorder: V14215

In Date: 04/01/2008 Meter Reading: 7,513.40
 Close Date: 04/04/2008

Problem?

place bracket in backboard compartment to hold pike pole. sb 7 e

Parts	Quantity
-------	----------

Task performed:

1. mount pike pole brackets.

5269LPVM-5 SM MOUNT	2
---------------------	---

Workorder: V14531

In Date: 04/17/2008 Meter Reading: 7,562.60
 Close Date: 05/02/2008

Problem?

front strobes are not activating and side strobes are not flashing all the time R-73

Parts	Quantity
-------	----------

Task performed:

1. Checked all strobes and charging system

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V14683

In Date: 04/25/2008
Close Date: 05/02/2008

Meter Reading: 7,574.00

Problem?

At approx 1930 on 2/24/08 the check transimition light turned on

Task performed:

1. Checked transmission light on, no codes found, ran fast adapt on transmission and road tested

Parts	Quantity
-------	----------

NO PARTS USED

Workorder: V15064

In Date: 05/14/2008
Close Date: 05/14/2008

Meter Reading: 79,096.00

Problem?

on call r73 door ajar It on

Task performed:

1. adjusted door ajar switch

Parts	Quantity
-------	----------

NO PARTS USED

Workorder: V15372

In Date: 05/28/2008
Close Date: 06/02/2008

Meter Reading: 79,271.00

Problem?

Running hot at head quarters

Task performed:

Road call to HQ to check out overheat; fnd fan ws unplugged; plugged in fan harness. j

Parts	Quantity
-------	----------

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10136370 FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V15178

In Date: 05/19/2008
Close Date: 06/06/2008

Meter Reading: 79,271.00

Problem?

B inspection and repairs as needed r 73

Task performed:

B-Inspection 5/20/08 1.0 hrs 5/21/08 2.0 hrs 5/22/08 1.0 hrs Total 4.0 hrs
2. Swapped into on-call truck 3. Monitored phones in shop ofc during shop foremen meeting. 4. Replc oil pan gsket 5/21/08 3.5 hrs 5/22/08 1.5 hrs Total 5.0 hrs 5. R/R turbo oil; return tube to Rescue (leaking) 6. Troubleshoot 110V A/C inop; traced prblm to faulty positive connection in wiring frm Kussmal outlet on body. 7. Troubleshoot A/C not cooling after aboe rep; traced problem to low freon charge due to faulty/loose Schrader valves; tightend valves, vac; charged/rechkd A/C sys. 8. Replc water pump. 9. replc serpentine belt. 10. Replc frt brakes 11. Replc rear A/C filter 12. Replc wiper blades & clnd debris out of windshild squirter. Sec spotlight controller in center console; (loose/falling thru). 13. Rem/untwist/reinstall pass side seat belt. 14. Replc R-side rear pat compt dome ight build(blowen) 15. Svc battery; replc term end for ECM pos connection; (brkn when rem to cln) 16. Cln shop bay after PM. j

Parts	Quantity
15W40BSYN OIL BULK QTS	16
322502BULB PATIENT GH22	1
3286278WATER PUMP ISB	1
3959052PAN GASKET B ENGINE	1
39768315259022 GROOVED TENSIONER OLD#39:	1
52-24WIPER BLADES ANCO 24	2
DDE-5411870080GASKET OIL RETURN TUBE TURBO	1
K080733BELT	1
L1261F33585XE FUEL FILTER WIX	1
MK184HDBRAKE PADS	1
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1

Workorder: V15295

In Date: 05/23/2008
Close Date: 06/11/2008

Meter Reading: 79,271.00

Problem?

REAR TIRE FLAT R73

Task performed:

Rar tire flat R73 - Callaghan j

Vendor? CALLAGHAN

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V15922

In Date: 06/23/2008 Meter Reading: 79,920.00
 Close Date: 06/27/2008

Problem?

left front spring hangar loose r73

Parts	Quantity
-------	----------

Task performed:

Spring hanger bolts loose; secure loose nut/bolts for spring hanger support. j

NO PARTS USED

Workorder: V15677

In Date: 06/11/2008 Meter Reading: 7,680.00
 Close Date: 07/01/2008

Problem?

brake light on driver side not working! r73

Parts	Quantity
-------	----------

Task performed:

1. l/brake light inop. bulb bad. installed new bulb

STOPSN12BULB STOP/TAIL LIGHT	1
------------------------------	---

Workorder: V15918

In Date: 06/23/2008 Meter Reading: 79,920.00
 Close Date: 07/10/2008

Problem?

replace bad turn signal switch

Parts	Quantity
-------	----------

Task performed:

1. R/R SIGNAL SWITCH

6805450124SWITCH TURN SIGNAL	1
------------------------------	---



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V16004

In Date: 06/26/2008
Close Date: 07/10/2008

Meter Reading:

Problem?

Please send large fish eye mirror. we will attach it to the rear view mirror.
r73

Parts	Quantity
-------	----------

Task performed:

1. Travel to Stn73. 2. Switch w/spare rescue. j

NO PARTS USED

Workorder: V16043

In Date: 06/29/2008
Close Date: 07/14/2008

Meter Reading: 7,754.00

Problem?

square strobe light on top of cab on drivers side not working. R73

Parts	Quantity
-------	----------

Task performed:

Chkd all lights on truck; all working at this time. j

NO PARTS USED

Workorder: V16183

In Date: 07/07/2008
Close Date: 07/21/2008

Meter Reading: 80,601.00

Problem?

ON CALL UNIT OVERHEATING

Parts	Quantity
-------	----------

Task performed:

Drove to Belle Glade & blew out radiator; clogged with sand. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V17684

In Date: 09/13/2008
Close Date: 09/29/2008

Meter Reading: 81,364.00

Problem?

The red emergency strobe light is out on the driver side box. The red strobe emergency light on the passenger side box is shorted out and needs to be replaced. STA-73

Parts	Quantity
-------	----------

Task performed:

TURBO64STROBE TUBE	2
--------------------	---

Workorder: V17718

In Date: 09/15/2008
Close Date: 09/29/2008

Meter Reading: 7,844.30

Problem?

re left front, red ems light does not work. s r at 73

Parts	Quantity
-------	----------

Task performed:

REPLACE LEFT FRONT EME LT AND TRAVEL BACK TO SHOP FROM 73

HND5941USE HAN-1L METAL LATCH INTERIOR LOC	1
HND5948TM22676-02 HANDLE DOOR ENTRY	1

Workorder: V18140

In Date: 10/06/2008
Close Date: 10/09/2008

Meter Reading: 81,886.10

Problem?

ON CALL R 74 A/C 10-7

Parts	Quantity
-------	----------

Task performed:

1. Drive to Sta-73. C/O rear A/C. repair wires going to blower motor resister. (R.T.)

NO PARTS USED	
---------------	--



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V19841

In Date: 12/18/2008
Close Date: 12/18/2008

Meter Reading: 7,928.00

Problem?

The shoreline does not work when plugged into the unit. The a/c does not work and there is no power or recharging of the unit. The reserve rescue does have the second shoreline a/c in the rear. r73

Parts	Quantity
-------	----------

Task performed:

repaired breaker in station was blown

NO PARTS USED

Workorder: V20449

In Date: 01/19/2009
Close Date: 02/24/2009

Meter Reading: 83,938.00

Problem?

Oxygen Gage on spare rescue is broken. The part that is connected to the O2 bottle. The inside digital gage seems to be working correctly. R-72

Parts	Quantity
-------	----------

Task performed:

Replcd O2 gauge. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10136370 FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V20641

In Date: 01/27/2009
Close Date: 02/25/2009

Meter Reading: 83,938.00

Problem?

C INSPECTION AND REPAIRS AS NEEDED SB7R

Task performed:

C-Inspection 2. Meeting 3. C-Inspection 4. Replcd bulb LF marker. 5. Fill all tires to proper pressure. 6. Protect upper rad hose & sec w/tie straps. 7. Add rear axle fluid. 8. Rep Kussmal door; lube/freed up spring & hinge. 9. Replcd drivers door light. 10.Replaced LF headlight. 11. Rep R-Rear compt wires. 12. Replcd bulbs for actionary light. 13. P/S svc. 14. Replcd btry tender indicator; shrink wrap electrical connections. 15. Replcd rear pat door handle insert. 16. Tighten P/S fitting. 17. Paint fuel cap. 18. Cln rad & E-core. 19. Cln frt A/C lines & leak chkd -OK. 20. Dia L2 door open warning not working; rep wire term at map display & replcd door swtch. 21. Rep door alarm sys. 22. Veh had active code 434 that went away; chk voltage at AIT (OK); chkd ECM fuses ok; tried to erase inactive codes; insite software expired. 23. Cln shop floor. 24. R/R door holdopens, latches, hinges, brkts & msng screws on compt doors. 25. Union meeting. 26. replcd plexi-glass compt door & shaps door; drill holes & relocate hinges; install new latches; rem hardware/decals & transfer to new door. 27. Sec fender skirt. 28. Coolant leak; dia; fnd leaking comp line & other line fitting; rem hoses for access & tightened line & fitting. 29. Replcd air bags. 30. Rebuild air dryer & purge valve. 31. Replcd air restrict hose. j

Parts

Quantity

032-0116549297 BATTERY INDICATOR	1
15W40BSYN OIL BULK QTS	16
16-15762-00016-19471-000 AIR BAG	2
194BULB	1
4020362171 GRO LAMP DOME 4 IN	1
91823SWITCH SWT5499 MED MASTER	1
921LIGHT BULB	10
AEVDOOR LOCK BEZEL	1
CA8193AIR FILTER 46744 WIX	1
DOOR2LEXAN 14.5 X 8.5	1
DOOR5LEXAN 9 X 38 1/2 IN	1
H6054USE CV TYPE SEALED BEAM	1
L1261F33585XE FUEL FILTER WIX	1
MG-C23SPMGC23 GAUGE	1
PH8942FILTER OIL 57182 LFP3729	1
RN60JDRYER KIT	1
S3225PFUEL FILTER 33630 LFF5849	1
VML-S1414FILTER P/S	1
VML-T1264GASKET P/S COVER	1
VML-T1279WASHER P/S	1



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V19479

In Date: 12/03/2008
Close Date: 03/02/2009

Meter Reading: 81,886.10

Problem?

check eng lt on sr at 73

Parts	Quantity
-------	----------

Task performed:

Drive to Stn; 434 codes; clear; test drive ok. j

NO PARTS USED

Workorder: V23563

In Date: 05/26/2009
Close Date: 05/27/2009

Meter Reading: 8,122.20

Problem?

Spare rescue 73. Rear AC is in not working. The blower works but does not get cool.

Parts	Quantity
-------	----------

Task performed:

Svc call to Stn73; went to Stn73; waited for truck to return; stn parking lot under water; went to Stn74; fnd cond fan bad; R/R fan; topped off A/C w/freon; returned home. j

60027FAN A/C COND 12IN 860026-2-W	1
-----------------------------------	---

Workorder: V24461

In Date: 06/30/2009
Close Date: 07/01/2009

Meter Reading: 85,456.40

Problem?

cab a/c 10-7 r73 spare

Parts	Quantity
-------	----------

Task performed:

Went to Stn73; Dia & rep cab A/C. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10136370 FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V24528

In Date: 07/02/2009 Meter Reading: 972.50
Close Date: 07/21/2009

Problem?

1. driver side rear emergency light out. 2. On board main O2 digital gauge, No read in patient compartment. r73 spare

Parts ----- Quantity -----

Task performed:

1. Went to Stn73; truck is parked at Stn72; went to Stn72; fnd strobe bad; didnt have light on svc truck. 2. R/R strobe light; had to go to Stn72. j

TURBO5TUBE - STROBE	1
---------------------	---

Workorder: V24565

In Date: 07/04/2009 Meter Reading: 86,270.80
Close Date: 07/21/2009

Problem?

O2 alarm is sounding in patient compartment even when there is 2000 psi i main O2. SR AT 73

Parts ----- Quantity -----

Task performed:

Travel to Stn; C/O O2 sys; fnd wires on O2 sen sor brkn at valve; replc bottle unit. j

AS77909SENDER TRANSDUCER	1
FREIGHTSHIPPING CHARGES	1
REG041462369 O2 REGULATOR	1

Workorder: V25564

In Date: 08/16/2009 Meter Reading: 8,281.60
Close Date: 08/25/2009

Problem?

SR @ 72 had check engine light come on Sunday evening. North end mechanic was notified and advised if there were any driving or mechanical issue found to call back. After restarting, light went off.

Parts ----- Quantity -----

Task performed:

Drive to Stn72; C/O code in ECM; fnd code 434 (3) cunt inactive code; chk fuses/btry; condensation ok; clear all-ok.

NO PARTS USED	
---------------	--



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V26252

In Date: 09/14/2009
Close Date: 09/29/2009

Meter Reading: 8,281.60

Problem?

Rear dump switch at rear door broken. sb7 r

Parts

Quantity

Task performed:

k air dump sys; ck ok; has been repaired. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10136370 FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V26701

In Date: 10/06/2009
Close Date: 10/19/2009

Meter Reading: 86,828.60

Problem?

B INSPECTION AND REPAIRS AS NEEDED SB7R

Task performed:

B-Service 2. R/R left rear strobe light top. 3. R/R all flag on rear doors. 4. Replc right door entry light & door switch. 5. R/R all engine belts. 6. R/R al (4) brtrys. 7. R/R auto-eject cvr platge. 8. C/O press cap on radiator & press; chk cooland sys. 9. Chk/charge both A/C sys, R-134 sys. 10. R/R lights in rear overhead; (3) out. 11. Cln out washer/adj sprayer. 12. Chk/rep street horns. 13. Installed updated board in A/C sys; switch over wiring. 14. Installed new shocks in A/C door. 15. Installed A/C gauges on shoreline A/C sys; chk/charge system. 16. Cln condensor under truck. 17. Cln evap in back of truck. 18. R/R tires on left rear side NG; replc with one out of Bldg 3 off other truck. j

Parts

Quantity

02036320700LINEAR STROBE MOD.6E EXTR. MOUN	1
05-17223-000CAP RADIATOR 10 LB	1
091-3YWCOVER KUSSMAUL AUTO EJECT	1
15W40BSYN OIL BULK QTS	24
322502BULB PATIENT GH22	3
4020362171 GRO LAMP DOME 4 IN	1
680-10LAMERICAN FLAG W UV CLEAR LEFT	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
9451BELT	1
9485BELT	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
CM110VCONTROL BOARD OLD REV-3	1
HLD3999GSS1715UV 30LB STRUT GAS	3
HP-31DBATTERY 950CCA HP-31D	4
K080733BELT	1
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
S1818COUPLING	1
S3225PFUEL FILTER 33630 LFF5849	1



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V28154

In Date: 12/07/2009
Close Date: 12/17/2009

Meter Reading: 88,142.80

Problem?

check engine light on R73

Parts	Quantity
-------	----------

Task performed:

1. Drive rescue to Stn74; hookup laptop; bad injection pump; drive back to shop. 2. Drive to Stn73; C/O rescue out of svc; went to Stn72; rep at Stn72; return to Stn73 PU bill; drive back to shop. j

NO PARTS USED

Workorder: V28153

In Date: 12/07/2009
Close Date: 01/15/2010

Meter Reading: 88,142.80

Problem?

tow from sta 73 to cummins dealer(outside agency-moss towing)

Parts	Quantity
-------	----------

Task performed:

Tow from Stn73 to Cummins - Moss Towing j

NO PARTS USED

Vendor? MOSS TOWING

Workorder: V28316

In Date: 12/14/2009
Close Date: 01/15/2010

Meter Reading: 88,142.80

Problem?

REPAIR FUEL SYSTEM CUMMINS POWER SOUTH

Parts	Quantity
-------	----------

Task performed:

Rep fuel sys - Cummins j

NO PARTS USED

Vendor? CUMMINS



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V28974

In Date: 01/11/2010 **Meter Reading:** 89,183.00
Close Date: 01/27/2010

Problem?

ojn call check eng lt on sr at 73

Parts	Quantity
-------	----------

Task performed:

Drive to Stn72; C/O truck for code 434; key to clear codes. j

NO PARTS USED

Workorder: V28723

In Date: 12/31/2009 **Meter Reading:** 8,301.20
Close Date: 02/11/2010

Problem?

not taking charge R73

Parts	Quantity
-------	----------

Task performed:

Wrong asset on W/O.; shld have been for 10175527; written up on another W/O. j

NO PARTS USED

Workorder: V29073

In Date: 12/14/2009 **Meter Reading:** 89,183.00
Close Date: 02/25/2010

Problem?

repair seat (outside agency-central auto)

Parts	Quantity
-------	----------

Task performed:

Repair seat - Central Auto j

NO PARTS USED

Vendor? CENTRAL AUTO



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V32125

In Date: 05/11/2010
Close Date: 05/21/2010

Meter Reading: 90,825.10

Problem?

on call strecher 10-7 r72

Parts

Quantity

Task performed:

Went to shop; fnd & mov R72; rem stretcher; gave stretcher to St72; brkn stretcher at stn; return home. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V33091

In Date: 06/23/2010
Close Date: 07/14/2010

Meter Reading: 91,491.60

Problem?

C INSPECTION AND REPAIRS AS NEEDED SR batt 7

Task performed:

C-Inspection. 2. Torque all u-bolts. 3. Replc compt light. 4. Rep windshielc washer. 5. replc "A" post cvr. 6. Svc P/S. 7. Trans svc. 8. Replc frn grill strobe light lenses. 9. Replc L-3 door brkt. 10. Replc shocks in pat compt L2. 11. Replc slides in bio-hazard drawer. j

Parts

Quantity

02-0383470-CROBSOLETE LENS RED/CLEAR	2
15W40BSYN OIL BULK QTS	16
180R002HURST HYD. FLUID QT	2
1829601001RHINGE PILLAR RESCUE	1
29526898 29548988 TRANS FILTER ALLISON	1
4020362171 GRO LAMP DOME 4 IN	1
5632-1010 IN DRAWER SLIDES PR	2
CA8193AIR FILTER 46744 WIX	1
HLD3999GSS1715UV 30LB STRUT GAS	2
HLD44614446 1/4 LATCH	1
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
RN60JDRYER KIT	1
S3225PFUEL FILTER 33630 LFF5849	1
SPR-W58-1TEE PLASTIC	1
VML-S1414FILTER P/S	1
VML-T1264GASKET P/S COVER	1
VML-T1279WASHER P/S	1
VML-T1311COVER PWR STEER RES	1



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V33442

In Date: 07/09/2010
Close Date: 08/02/2010

Meter Reading: 91,770.00

Problem?

Battery switch on B7SR is broken. truck doesn't turn on. Sometimes switch is positional. Rescue 72

Parts	Quantity
-------	----------

Task performed:

R/R btry switch in console; some wire ends burned; replc ends; install new switch; working ok. j

75908SWITCH BATTERY MASTER 300A	1
---------------------------------	---

Workorder: V34104

In Date: 08/07/2010
Close Date: 09/01/2010

Meter Reading: 91,770.00

Problem?

air brakes dont work R72

Parts	Quantity
-------	----------

Task performed:

R/R dash panel; replc park brake valve to rep part park; still has hose problem; work on it further; fnd air line blocked up w/mud - cln. All lines rechk; reinstalled dash panel and all eqmpt; test drive - ok at this time; back in svc. js

KN20021DASH VALVE	1
-------------------	---

Workorder: V34525

In Date: 08/26/2010
Close Date: 09/15/2010

Meter Reading: 91,925.00

Problem?

wipers on R73b need replaced unable to see when its raining

Parts	Quantity
-------	----------

Task performed:

Drive out to Stn73; R/R wiper on rescue with new ones; ok at this time. j

52-24WIPER BLADES ANCO 24	2
91-22WIPER BLADE	4



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V34831

In Date: 09/08/2010 **Meter Reading:** 92,339.00
Close Date: 09/27/2010

Problem?

Driver side mirror broken. When turning mirror in mirror cracked. sr at 72

Parts	Quantity
-------	----------

Task performed:

Drive to Stn72; change out mirro - brkn glass. j

1149610278 MIRROR	1
-------------------	---

Workorder: V35754

In Date: 10/19/2010 **Meter Reading:** 93,179.00
Close Date: 10/28/2010

Problem?

Siren volume low.

Parts	Quantity
-------	----------

Task performed:

1. siren inop, inspect siren, found siren full of water,r&r siren driver. checks ok. jab

SD-210RSIREN DRIVER	1
---------------------	---

Workorder: V36263

In Date: 11/08/2010 **Meter Reading:** 89,183.00
Close Date: 11/18/2010

Problem?

door alarm won't shut off R73

Parts	Quantity
-------	----------

Task performed:

Travel to Stn73; work on door open alarm system; cld not fix; disabled alarm sys. j

NO PARTS USED	
---------------	--



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10136370 FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V36265

In Date: 11/08/2010
Close Date: 11/19/2010

Meter Reading: 89,183.00

Problem?

door alarm won't shut off R73

Task performed:

1. door alarm on, right front door switch threads stripped, r&r switch. jab

Parts	Quantity
10048011712407 DOOR PROX SWITCH 2418/2407	2
1004803PROX MAGNET	2
52-624SWITCH DOOR	2
91823SWITCH SWT5499 MED MASTER	2
FSC17491907NO SWITCH LOW AIR PRESSURE	1
FSC17492134NC SW PARK BK SPADE TYPE CONNE	1
SWT5924DOOR OPEN MAP DISPLAY	1

Workorder: V37004

In Date: 12/08/2010
Close Date: 12/30/2010

Meter Reading: 93,418.70

Problem?

BATTERY INDICATOR LIGHT STAYS ON WITH HIGH IDLE, AND NO ELECTRICAL DRAW, VOLTMETER READING 11.3 sr at 72

Task performed:

(1) TRAVELED TO ST72 TO REPAIR CHARGING SYSTEM ON BSR-7. CHECKED OUT AND FOUND VOLTAGE READING TO BE WNL(13.8) A GAUGE. (2) CHECKED OUT STROBE, THEY SAID THAT THE BOX STROBE SIDE WERE GOING ON & OFF. CHECKED THEM OUT. ALL SEEMS TO BE WORKING OK AT THIS TIME. STROBE PAC MAY BE GOING OUT. THIS IS THE OLD STYLE. WILL REPLACE PAC IF PROBLEM HAPPENS AGAIN. J.W.

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V36686

In Date: 11/28/2010
Close Date: 01/05/2011

Meter Reading: 93,418.70

Problem?

ROUGH RUNING DURING START UP AFTER SITTING. ONCE IT CLEAR UP IT RUNS FINE sr at 73

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

Drive to Stn73; not there; go to Stn74 - same; go to stn72; C/O truck - needs injector; test. j

Workorder: V38087

In Date: 01/27/2011
Close Date: 02/14/2011

Meter Reading: 94,606.00

Problem?

driver side scene light out and officer side orange marker light out R73

Parts	Quantity
-------	----------

H50SN12BULB	1
-------------	---

Task performed:

1. R/R cover off light; rem frnt truck; installed new light SN50-12V; working ok at this time. 2. R/R cvr to turn marker light right frnt; replc light 3157 bulb; working ok at this time. j

Workorder: V38602

In Date: 02/17/2011
Close Date: 02/24/2011

Meter Reading: 94,606.00

Problem?

STROBE LIGHT LENS COVER MISSING, DRIVERS SIDE REAR WHEEL.R73

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

Replc both reflectors on rear of truck; no strobe light covers - ok. j



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10136370 FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V38935

In Date: 03/03/2011
Close Date: 04/01/2011

Meter Reading: 94,763.00

Problem?

B inspection and repairs as needed sb7r

Task performed:

road test & B-Inspection 2. Svc read end. 3. Frnt brakes svc. 4. Rear brakes svc. 5. Windshield wiper blade; rem/install new blades; all bug solvent & top off fluid reservoir. 6. Officers window molding brkn; rem/install new molding. 7. Driver's door weatherstrip torn; rem damaged weatherstrip & install new strip. 8. Dia wigway failure; fnd bad grd & weal flasher control box; correct grd fault; replc bad flasher unit. 9. Help dia problem w/wigways; fnd bad grd - Byrum 10. Crankcase breather element clogged; rem/install new crank case breather asy. 11. Trans level low; add 1.5 quartz of fluid to proper level; no leaks fnd. 12. Pat compt ligh 10-7; fnd disconnected grd cable; reconnect. 13. Stretcher safety hook msg; hook boltholes worn out. drill, retap, install safety hook. 14. L1 & R1 door lock out of timing; diss door panel; retime lock & operate; nut serts loose on door panel; rem/install new nut serts. 15. R-1 door panel loose; replc worn out screws; R-3 door holdopen lever loose; secure mntng brkt. 16. Pat compt A/C filter dirty; rem/install new filter. 17. ___ 10-7; dia fault; fnd pinched electrical connection in console; rep fault. j

Parts

Quantity

1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	24
322502BULB PATIENT GH22	1
39449613944961 BREATHER	1
52-24WIPER BLADES ANCO 24	2
6092036018J HOOK STRYKER	1
A1834388003MOLD R/H	1
L1261F33585XE FUEL FILTER WIX	1
MK184HDBRAKE PADS	2
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1
SWT54913SW ROCKER SPST ON-OFF RED	1
SWT5492744435 ACTUATOR-BLACK	1
UHF-2150AFLASHER-WHELEN HEADLIGHT HIGH BE	1

Workorder: V39478

In Date: 03/27/2011
Close Date: 04/01/2011

Meter Reading: 95,252.00

Problem?

R731 stryker stretcher rear yellow catch hook came off. Holes need to be retapped or drilled.

Task performed:

Travel to Stn73; remnt stretcher; hook in rear of trk; drill/tap new holes in floor; seal up. j

Parts

Quantity

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V39755

In Date: 04/06/2011 Meter Reading: 95,252.00
Close Date: 04/14/2011

Problem?

driver side head light is out SR at 72

Task performed:

Travel to Stn72; R/R headlight; return to shop. j

Parts	Quantity
H6054USE CV TYPE SEALED BEAM	1

Workorder: V40091

In Date: 04/22/2011 Meter Reading: 95,252.00
Close Date: 04/29/2011

Problem?

left front turn signal is not working. R72?

Task performed:

Travel to Stn72; C/O t-signals; pull light - cln socket & lube; test ok; tighter up grd connector; return to shop. j

Parts	Quantity
NO PARTS USED	

Workorder: V40424

In Date: 05/05/2011 Meter Reading: 95,252.00
Close Date: 05/10/2011

Problem?

a/c inop, Sta 74.

Task performed:

Travel to Stn72; C/O A/C on R72; fnd press switch wiring open; fnd brake: ____; rep/retest ok. j

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V40751

In Date: 05/20/2011 Meter Reading: 95,252.00
 Close Date: 05/25/2011

Problem?

Right rear strobe light out on Batt7 Spare Rescue. Sta 74.

Parts	Quantity
-------	----------

Task performed:

Travel to stn74 to C/O light not there at 72; travel to Stn72; R/R bulb & light lens on pass side rear strobe. j

681183132RALENS 97 E RED/AMBER	1
--------------------------------	---

Workorder: V40752

In Date: 05/20/2011 Meter Reading: 95,252.00
 Close Date: 06/15/2011

Problem?

Driver side rear tire (outside) is flat and will not hold air. Sta 72.

Parts	Quantity
-------	----------

Task performed:

Driver side rear tire(outside) is flat - not holding air; Stn72 - Boulevard j

NO PARTS USED	
---------------	--

Vendor? BOULEVARD

Workorder: V40954

In Date: 05/29/2011 Meter Reading: 95,840.00
 Close Date: 08/05/2011

Problem?

middle fold out compartment hinge broken on driver side R 72

Parts	Quantity
-------	----------

Task performed:

completed already on 5-30-11

HLD44614446 1/4 LATCH	1
-----------------------	---



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V43708

In Date: 09/16/2011 **Meter Reading:** 97,321.70
Close Date: 09/27/2011

Problem?

The air horn pedel inside the rescue cab on the driver's left foot area does not work. When depressed the air horn does not sound. Sta 72

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

checked air horn system found pedals working but horns on hood loose or one side and off on the other side adjusted horns checked ok travel to anc from station

Workorder: V44125

In Date: 10/03/2011 **Meter Reading:** 97,592.00
Close Date: 10/07/2011

Problem?

this vehicle is at station 73 the rescue is the spare to r73. the patient compartment side door does not stay shut or locked unless you manually grasp it and jiggle it locked. SR AT 73

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

travel to 73 check out side doors couldnt find problem with door check all doors on rbr 73b no problem found



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10136370 FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V44930

In Date: 11/03/2011
Close Date: 11/10/2011

Meter Reading: 98,236.00

Problem?

c INSPECTION AND REPAIRS B7SR

Task performed:

C-Inspection 2. Driver seats torn; rem for outside vendor rep. 3. Crankcase breather clogged; rem breather box; cln filter hose; crankcase breather hose soft; rem/install new hose. 4. Radiator hose svc. 5. Coolant svc. 6. Frt light bar marker light 10-7; rem blown bulb & install new bulb. 7 110V ckt tripping; dia fault; fnd weak 110V brkr; rem/install new brkr. 8. Btry tender indicator inop; fnd indicator LED burnt out; replc indicator; indicator wired wrng; corrent fault; unit operating normal. 9. Pat compt A/C filter svc. 10. Svc windshield wiper blade & bug solvent added to fluid tank top off fluid level; windshield spray nozzle clogged; rem/isntall (2) new spray nozzles. 11. P/S svc. 12. Driver/pass door lock & handle stripped; rem unit & install new asy. 13. Driver window molding brkn; rem/isntall nev molding. 14. Belts A/C & eng. 15. Compt door panels screws loose; secure loose screws & replc bad ones. 16. Pat compt wall corner pading fell off; secure to wall w/screws. 17. Press cln eng compt of all dirt, grease & grime. 18. Officers window molding damaged; re/install new molding. 19. Dia pat compt A/C fan noise; rem loose foam padding in vent hsng. 20. Quality check truck - Hines. j

Parts

Quantity

032-0116549297 BATTERY INDICATOR	1
05-17542-002HOSE UPPER RADIATOR	1
05-17544-002HOSE LOWER RADIATOR	1
1501450007750USE 0775145	1
52-24WIPER BLADES ANCO 24	2
6807600070HANDLE DOOR EXT L/H	1
6807600170HANDLE DOOR EXT. R/H	1
9451BELT	1
9485BELT	1
A1834388002MOLD L/H	1
A1834388003MOLD R/H	1
CA8193AIR FILTER 46744 WIX	1
DDE/A0039973352EGR COOLING HOSE	1
K080733BELT	1
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
QO120GFIGFI CIRCUIT BREAKER 20 AMP	1
S3225PFUEL FILTER 33630 LFF5849	1
SPRGW251WASHER NOZZLE	2
VML-S1414FILTER P/S	1
VML-T1264GASKET P/S COVER	1



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V45439

In Date: 11/27/2011 Meter Reading:
Close Date: 12/01/2011

Problem?

I already replaced both headlights, need replacements. 2 H6054,
THANKS!!! R73

Parts	Quantity
-------	----------

Task performed:
travel to st 73 drop off lights check out

H6054USE CV TYPE SEALED BEAM	2
------------------------------	---

Workorder: V46714

In Date: 01/19/2012 Meter Reading: 99,982.00
Close Date: 01/23/2012

Problem?

Right head light out on spare Rescue. Sta 72

Parts	Quantity
-------	----------

Task performed:
TRAVEL TO ST 72 R&R HEAD LIGHT RETURN TO SHOP.

NO PARTS USED

Workorder: V46785

In Date: 01/23/2012 Meter Reading: 100,309.60
Close Date: 01/30/2012

Problem?

R72 uneven tire wear. Left front tire is wearing out on the inside of the tire.
And right front tire is wearing uneven on the outside of the tire.

Parts	Quantity
-------	----------

Task performed:
TRAVEL TO ST 72 CHECK OUT TIRES ON TK. REARS OK CALL FOR
FRONT TIRE REPLACEMENT TOMORROW. RETURN TO SHOP.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V46934

In Date: 01/30/2012
Close Date: 01/31/2012

Meter Reading: 100,703.00

Problem?

replace front tires

Parts	Quantity
-------	----------

Task performed:
REPLACE FRONT TIRES.

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE

Workorder: V47690

In Date: 03/02/2012
Close Date: 03/07/2012

Meter Reading: 101,630.00

Problem?

airhorn inop.

Parts	Quantity
-------	----------

Task performed:
DRIVE TO TRAINING INSTALL AIR HORN KITS.

1094KIT-AIR HORN-GROVER	2
-------------------------	---

Workorder: V49531

In Date: 05/22/2012
Close Date: 06/01/2012

Meter Reading: 102,007.00

Problem?

head light is out. asset# 10136370 R72

Parts	Quantity
-------	----------

Task performed:
TRAVEL TO ST 72 R&R HEAD LIGHT.

H6054USE CV TYPE SEALED BEAM	1
------------------------------	---



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V49598

In Date: 05/24/2012
Close Date: 06/12/2012

Meter Reading: 102,137.10

Problem?

strob and rotater lite out on rear lite bar....air horn not working r 72

Task performed:

TRAVEL TO ST 74 TK NOT THERE GO TO ST 73 CHECK OUT REAR LIGHT BAR PULL APART LIGHT BAR R&R STROBE LIGHT AND ONE ROTATER BULB.

Parts	Quantity
02036317300STROBE LINEAR REFLECTOR 6ELTUBI	1
02036320700LINEAR STROBE MOD.6E EXTR. MOUN	1
1094KIT-AIR HORN-GROVER	2
12258H1 EIK BULB 55W	1
H27SN12BULB	1
H3LIGHT BULB BP1255/H3 H	1

Workorder: V49834

In Date: 06/02/2012
Close Date: 06/12/2012

Meter Reading: 102,266.00

Problem?

air horn on drivers floor not working. R73

Task performed:

CHECK OUT AIR HORN AND SWITCH ON FIRE WALL CHECK POWER AND GROUND CHECK WIRING RELAYS, FUSES, ETC. FOUND BAD GROUND WIRE IN CKT AND REPAIR.

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V51059

In Date: 07/23/2012 Meter Reading: 103,693.90
 Close Date: 07/30/2012

Problem?

B INSPECTION OIL CHANGE SERVICES

Parts	Quantity
-------	----------

Task performed:

B INSPECTION OIL CHANGE SERVICES

NO PARTS USED

Vendor? OIL CHANGE SERVICES

Workorder: V51223

In Date: 07/30/2012 Meter Reading: 103,693.90
 Close Date: 08/14/2012

Problem?

make repairs from b inspection B 7 SR

Parts	Quantity
-------	----------

Task performed:

1. TRAVEL TO ST 72 COMPLETE REPAIRS FROM LAST SERVICE
 REINSTALL TRIM IN PATIENT COMPARTMENT REPLACE SCREWS
 WITH LONGER. 2. CHECK OUT P/S LEAK FOUND P/S TANK LID BOLT
 LOOSE TIGHTEN UP CAP AND BOLT ON LID TOP OFF FLUID CLEAN
 UP UNIT. 3. TIGHTEN UP L/SIDE MOUNT MOTOR, TRANS. 4. TRAVEL
 TO ST 72 R&R DRIVER SIDE SEAT BELT ASSY.

IMMF13224BELT SEAT DRIVER SIDE IMMF11851 OL	1
---	---



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V52402

In Date: 09/15/2012
Close Date: 09/26/2012

Meter Reading:

Problem?

The radiator cap was taken off of the spare for the primary rescue. sr at 74

Parts	Quantity
-------	----------

Task performed:

TRVL TO ST 72 R&R AND CAP ADJUST STRETCHER MOUNT TO FIT COT.

05-17223-000CAP RADIATOR 10 LB	1
--------------------------------	---

Workorder: V53096

In Date: 10/15/2012
Close Date: 10/23/2012

Meter Reading: 105,845.00

Problem?

Patient compartment A/C not working. E73

Parts	Quantity
-------	----------

Task performed:

FOUND BLOWER ASSEMBLY INOP - REMOVED EVEP - CHUTE, REAI STAT, GROUNDS, INSULATION TAPE AND T-STAT WIRES - REMOVE HOUSING - R&R BLOWER MOTOR - REASSEMBLED - REWIRED T-STAT-RAN-FOUND REOSTAT BAD - REPAIRED WIRES REPLACED REOSTAT - CHECK OK.

123411-0806 RESISTOR BLOWER MTR A/C	1
UNT1400BLOWER MTR. + SQU IRREL CAGE ASSY.	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10136370 FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V53501

In Date: 11/02/2012
Close Date: 12/05/2012

Meter Reading: 106,424.00

Problem?

A INSPECTION

Task performed:

1. A INSP 2. ALL TIRES LOW PRESSURE, VALVE CORES STICKING R&R VALVE CORE STILL LEAKING. 3. AUTO EJECT INOP, LACK OF LUBE. LUBED TERMINALS AND STRAIGHTENED TERMINAL AUTO REPLACED BROKEN COVER. 4. L/R STROBE INOP, CONNECTOR BURNT. REPAIRED STROBE WIRING. 5. L-S TAIL LIGHT INOP, SOCKET CORRODED. CLEANED CORROSION FROM L- TAIL LIGHT ASSY. 6. WRONG GVW DECAL. REMOVE OLD DECAL AND INSTALL NEW ONE. 7. REAR DOOR HARD TO OPEN, LINKAGE STICKING BEHIND REMOVE PANEL ND LUBE DOOR LINKAGE AND LATCHES. 8. INSTALL BRAKE BOOSTER AND MASTER CYLINDER. 9. HYDRA BOOST, LEAKING, REMOVED HYDRA BOOST AND MASTER CYLINDER LEAKING ALSO ORDERED NEW BOOSTER. 10. FUEL LEA SEVERAL INJESTOR NOZZLES LOOSE TIGHTENED NOZZLES. 11. BODY MARKER LIGHTS INOP, LIGHTS ASSY'S RUSTED AND CORRODED, INSTALLED NEW MARKER LIGHT ASSY'S ALSO REPLACED INDIVIDUAL BULBS AS NEEDED. 12. 1 PATIENT HI DOME LIGHT INOP BULB INSTALLED NEW BULB. 13. INSTALL BARKE BOOSTER AND MASTER CYLINDER ROAD TEST OK.

Parts

Quantity

091-3YWCOVER KUSSMAUL AUTO EJECT	1
2234934MASTER CYLINDER ASL	1
322502BULB PATIENT GH22	2
404-100 VALVE CORE	10
46892-546892-5 MARKER LAMP	2
52-24WIPER BLADES ANCO 24	2
621714 IN LIGHT	1
ASL3369972HYDRO-BOOST	1
V122XARESCUES MARKER LIGHT	2



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V54780

In Date: 01/03/2013
Close Date: 01/04/2013

Meter Reading: 106,424.00

Problem?

battery dead

Parts	Quantity
-------	----------

Task performed:

BATTERY READ- JUMP START UNIT. PLUG IN JUMP START BATTER' UNIT RUN RECHARGE.

NO PARTS USED

Workorder: V54957

In Date: 01/09/2013
Close Date: 01/10/2013

Meter Reading: 106,424.00

Problem?

batteries dead

Parts	Quantity
-------	----------

Task performed:

SEARCH SHOP EXTENSION CORDS CONNECT 3 EXTENSION CORD AND HOOK UP CHARGER. CHARGE BATTERIES START VEHICLE AN LET RUN.

NO PARTS USED

Workorder: V55110

In Date: 01/16/2013
Close Date: 01/22/2013

Meter Reading: 106,424.00

Problem?

REPLACE TIRE

Parts	Quantity
-------	----------

Task performed:

REPLACE TIRE.

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V53069

In Date: 10/14/2012 Meter Reading: 105,845.00
 Close Date: 04/04/2013

Problem?

styker strecher wheel needs to be changed due to damage #10175534

Parts	Quantity
-------	----------

Task performed:
 CONTACTED EMSAR FOR REPAIR.

NO PARTS USED

Workorder: V57148

In Date: 04/19/2013 Meter Reading: 108,312.00
 Close Date: 04/22/2013

Problem?

4 batteries replaced

Parts	Quantity
-------	----------

Task performed:
 REPLACED 4 BATTERIES IN SPARE RESCUE.

BATTERY EPA TAX	4
BATTERY EPA TAX \$1.50 PER B/	
HP-31DBATTERY 950CCA HP-31D	4

Workorder: V55507

In Date: 02/04/2013 Meter Reading:
 Close Date: 04/24/2013

Problem?

Inside door handle of back door of the spare was broken at 42?

Parts	Quantity
-------	----------

Task performed:
 REPAIRS A-1 STATION.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V57565

In Date: 05/07/2013

Close Date: 05/24/2013

Meter Reading: 108,312.00

Problem?

C inspection SR17

Parts

Quantity



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Task performed:

1. C- INSP. 2. 4 BATTERY SERVICE REPLACEMENT. 3. AIR DRYER SERVICE. 4. TRANSMISSION FILTER AND OIL SERVICE. 5. RIGHT SIDE AIR HORN SUPPORT BRACKET MISSING- INSTALL AND SECURE HORN BRACKET. 6. PT COMP CABINET STUCK AND CABINET DRAW SLIDES BROKEN. REMOVE LATCH AND REPOSITION CATCH PINTO PROPERLY LOCK CABINET, REMOVE BROKEN SLIDER AND INSTALL NEW ONE. 7. WIND SHIELD WIPERBLADE AND FLUID RESEVOIR SERVICE. 8. LIGHT INOP-BLOWN BULBS. 9. RIGHT SIDE HOOD STROBE BLOWN- REMOVE AND INSTALL NEW STROBE LIGHT BAR BULB. 10. REAR LIGHT BAR INNER LIGHT ROTATION NOT ROTATING REMOVE LENSES AND REPLACE ROTATOR. 11. 110 A/C VENT COVER FALLING OFF- REMOVE RETAP SCREW HOLE AND NEW SIGNAL. 12. A/C BLOWING WARM -CHECK REAR FREON LEVEL- FREON PRESSURE LOW EVACUATE SYSTEM. TEST FOR LEAK NON FOUND. 13. R DOOR HOLD OPEN SIDE DOOR ENTRANCE LOCK FALLING OFF. INSTALL NEW HOLD OPEN. 14. L-4 DOOR SEAL MISSING- CLEAN AREA AND INSTALL NEW NEW DOOR WEATHER SEAL AND REPLACEMENT REFLECTOR. 15. ROOF TOP SPOT LIGHT INOP. REMOVE AND REPLACE WITH DNI PART. 16. LEFT REAR FRAME RAIL CRANK FRONTSUSPENSION MOUNT SPIDER CRANKS, CLEAN AREA AND MARK CRACKS TO BE MONITORED AS PER SUPERVISOR. 17. REAR 3 TIRES- REMOVE ACQUIRE 3 NEW. INSTALL NEW ON UNIT AND AIR VALVE EXTENSION. 18. ENGINE MOUNTS BUSHING WORN-REMOVE WORN ENGINE SIDE MOUNTS AND INSTALL NEW MOUNTS. 19. REMOVE CERTIFICATION COMMISSION DECAL. CLEAN AND POLISH. 20. DOOR OPEN LIGHT AND ALARM INOP-REASSEMBLE. 21. DRIVER SEAT AIR CONTROL VALVE LOOSE SECURE AIR CONTROL VALVE TO SEAT MOUNTING HOLES. 22. 110 A/C PT COMP INOP- FAULTY SYSTEM. 23. REAR PT DOOR LOCK MECHANISM BROKEN- REMOVE FABRICATE NEW SUPPORT TO ACCOMMODATE NEW DESIGN. 24. Q.C TRUCK.

01-0416333-00LIGHT ROTATOR	1
071601A07-0602A DRIER A/C 7118	1
15W40BSYN OIL BULK QTS	18
1895BULB	1
194BULB	1
29526898 29548988 TRANS FILTER ALLISON	1
322502BULB PATIENT GH22	1
52-24WIPER BLADES ANCO 24	2
58ELTUBE58L4TUBE STROBE/REFLECTOR ASSY. 5	1
621714 IN LIGHT	2
6802410218MOUNT	2
921LIGHT BULB	1
98003RREFLECTOR RED 40132 GROTE	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
GRV1720244770R1 HORN SUPPORT BRKT	1
HAN-1LBEZEL AND HANDLE	1
HP-31DBATTERY 950CCA HP-31D	4
J20120-4ISOLATOR	2
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
RN60JDRYER KIT	1
S3225PFUEL FILTER 33630 LFF5849	1
SLD5366HT4932-16 DRAWER SLIDE 16	1
TRANSYNDALLISON TRANS FLUID GAL	4



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V59575

In Date: 08/05/2013 Meter Reading: 112,104.30
 Close Date: 08/07/2013

Problem?

A inspection SR17 from 44

Parts	Quantity
-------	----------

Task performed:
 INSPECTION NOT DONE AT THIS TIME.

NO PARTS USED

Workorder: V58668

In Date: 06/25/2013 Meter Reading: 110,255.00
 Close Date: 08/15/2013

Problem?

a light on the rear light bar is burned out and the silver half circle dosent spin around it. R18

Parts	Quantity
-------	----------

Task performed:
 R & R ROTATORS IN REAR LIGHT BAR.

01-0416333-00LIGHT ROTATOR	2
----------------------------	---



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10136370 FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V60165

In Date: 08/29/2013
Close Date: 09/03/2013

Meter Reading: 112,337.10

Problem?

A-inspection

Task performed:

1. STARTED CHECKING OUT TRUCK TO GO TO ST 35. FOUND TO MANY REPAIRS TO LET TRUCK GO. 2. DISASSEMBLE FRONT LIGHT BAR TO ACCESS PIERCER LIGHT AND REPLACE. REASSEMBLED LIGHT BAR. 3. REPLACED STROBE LIGHT BULB IN RIGHT, FRONT, UPPER, SIDE STROBE. (BURNT). 4. DISASSEMBLED REAR LIGHT BAR, REPAIRED WIRING IN ROTATER STROBE ASSEMBLY. REPLACED TWO STROBE LIGHTS. REASSEMBLED LIGHT BAR. 5. REPLACED DRAWER SLIDES ON CABINET DRAWER IN PATIENT COMPARTMENT. (BROKEN) HAD TO DRILL ALL NEW MOUNTING HOLES TO ACCOMADATE NEW SLIDES. ALSO REPLACED DRAWER LATCH.

Parts	Quantity
02036317300STROBE LINEAR REFLECTOR 6ELTUBI	3
LTC5993SSM1-63-8 LATCH STAINLESS	1
SLD5366HT4932-16 DRAWER SLIDE 16	2
TURBO5TUBE - STROBE	1

Workorder: V60289

In Date: 09/05/2013
Close Date: 09/06/2013

Meter Reading: 112,337.10

Problem?

QC rescue to swap w/R39

Task performed:

1. PERFORM A-INSPECTION. 2. WIPER BLADES - REMOVE AND REPLACE WIPER BLADES ADD WINDSHIELD WASHER FLUID.

Parts	Quantity
52-24WIPER BLADES ANCO 24	2



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10136370 FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V60567

In Date: 09/17/2013
Close Date: 09/23/2013

Meter Reading: 113,350.70

Problem?

Emergency lights shut down while driving. Strobes cut out. rotators continue. on a call now

Task performed:

TRAVEL TO ST 39 FOR LIGHTS INOP WAIT FOR TRUCK TRAVEL TO : 34 TO MEET TRUCK. CHECK ALL SYSTEM FOUND ALTERNATOR NO CHARGING R&R ALTERNATOR AND TEST SYSTEM OK.

Parts	Quantity
4867JB320 UPGRADE ALTERNATOR	1

Workorder: V59848

In Date: 08/16/2013
Close Date: 10/10/2013

Meter Reading: 113,156.80

Problem?

A inspection

Task performed:

1. A SERVICE. 2. REPAIRS, START TO REPAIR BOARDS IN REAR OF TRUCK BURNED, FOUND RELAY ALL LOOSES AND SOLDER MELTEI RESOLDER CONNECTOR INSTALL RELAYS. 3. COMPLETE WORK OI REAR BOARDS, HAVE TO DO TWO OTHER RELAYS ALSO, REPAIR WIRES ALSO, BURNED ENDS REPLACE WITH NEW ENDS OK ALL WORKING. 4. CHECK OUT ?? LIGHT OUT CHECK BULBS, NEED NEW LIGHT ASSEMBLE, REPLACE WITH NEW ONE, WIRE IN TO PANEL. 5 CHECK AND REPAIR O/2 LIGHT, WIRING PROBLEM REPAIR OK. 6. CHECK AND REPAIR LIGHT IN RIGHT FRONT FINDER NOT COMING ON, REPAIR WIRING. 7. REPAIR STEP LIGHT IN SIDE REAR SIDE DOOR BAD CONNECTION TO LIGHT REPAIR. 8. REPLACE LIGHT IN CAB, DOME. REPAIR LENSES ALSO. 9. CHECK OUT LIGHT IN FRONT LIGHT BAR NOT ROTATING, REMOVE ALL COVER TO CHECK, FOUN PLASTIC TOP MELTED DOWN ON LIGHT, REMOVE LIGHT AND REPAIR.

Parts	Quantity
101331605QUINT COOLANT RES CAP	1
87401RY-30T RELAY 5 PIN 12V	3
P616LIGHT ASSBLY	1



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V61317

In Date: 10/17/2013
Close Date: 10/21/2013

Meter Reading: 113,156.80

Problem?

Check engine light

Task performed:

1. CHECK ENGINE LIGHT FOUND LIGHT NO ON - COULD NOT CONNECT TO ECM TRIED MULTIPLE COMP - TEST DROVE NO PROBLEMS FOUND CHECK OK. 2. CHECK ALL LIGHTS, A/C ETC. - R&R REAR TOP CENTER H BULB CHECK OK MOVED TRUCK.

Parts	Quantity
1895BULB	1

Workorder: V62142

In Date: 11/19/2013
Close Date: 12/04/2013

Meter Reading: 114,741.70

Problem?

A-inspection

Task performed:

1. A-INSPECTION. 2. A PILLAR PANEL INNER AND OUTER DAMAGE - REMOVE AND DISCARD PREP AND PAINT NEW OUTER PILLAR PANEL - INSTALL NEW A-PILLAR MOLDING INSIDE AND OUT. 3. L/REAR PANEL INNER AND OUTER DAMAGE - REMOVE FOUND MOTOR HIGH RESISTANCE, CURRENT DRAW - INSTALLNEW ROTATOR ASSEMBLY. 4. WINDSHIELD SQUIRTER INOP - REMOVE NOZZLES AND INSTALLNEW NOZZLES. 5. PATIENT SIDE DOOR NON - SKID LOOSE - REMOVE NONE SKID CLEAN SURFACE - INSTALL NEW NONE SKID.

Parts	Quantity
1829601000LHINGE PILLAR RESCUE	1
673-688-00-06INNER L/PILLAR	1
SPRGW251WASHER NOZZLE	1
SPRGW2612WASHER NOZZLE W/RELIEF	1



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V63654

In Date: 01/16/2014 **Meter Reading:** 118,281.60
Close Date: 01/23/2014

Problem?

install number plates, R-400

Parts	Quantity
-------	----------

Task performed:

1. remove metal number plates, install new plastic number plates and numbers, top off coolant, add 2 qts oil,

NO PARTS USED

Workorder: V63667

In Date: 01/24/2014 **Meter Reading:** 118,281.60
Close Date: 02/05/2014

Problem?

service front hubs R400

Parts	Quantity
-------	----------

Task performed:

1. ASSIST E. ORLANDO AT STA 42 WHEL HUBS. 2. ASSIST E. ORLANDO AT STA 42 WATER IN WHEEL HUBS.

CHR1612340-4024 HUB COVER - FRONT AXLE 2004	2
---	---

Workorder: V63840

In Date: 01/30/2014 **Meter Reading:**
Close Date: 02/25/2014

Problem?

Turing signals not working.

Parts	Quantity
-------	----------

Task performed:

REPAIRED BAD CONNECTION IN STEERING COLUMN.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V63999

In Date: 02/05/2014
Close Date: 03/19/2014

Meter Reading: 119,168.00

Problem?

B inspection

Task performed:

B inspection oil and filter change by OCS

Vendor? OCS

Parts	Quantity
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1

Workorder: V64340

In Date: 02/19/2014
Close Date: 03/21/2014

Meter Reading: 119,168.00

Problem?

repairs from pm list

Task performed:

1. TROUBLESHOOT REAR A/C INOP, FOUND BAD SHOULDER CONNECTION AT CONTROL PANEL REPAIR. 2. CHECK FREON LEVE LOW. CHECK FOR LEAKS, REPLACE HIGHT AND LOW SHOULDER VALVES, RECRIMP LINES, VAC AND RECHARGE. 3. CHECK FOR COOLANT LEAKS, TIGHTEN AND REPLACE ALL COOLANT CLAMPS. TROUBLESHOOT CLAMPS. 5. REPAIR DRIVERS SEAT AIR RIDE SWITCH. 6. TROUBLESHOOT L/S HEADLIGHT INOP, FOUND WIRE IN BACK OF DILL BOARD FOR RELAY LOOSE. REMOVE AND REPAIR WIRE.

Parts	Quantity
1501450007750USE 0775145	1
68054400K0BEZEL HEADLIGHT	1
6809881078DZ STUD	2
EL12FLASHER ELECTRONIC	1
H6054USE CV TYPE SEALED BEAM	1



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V63849

In Date: 01/30/2014 Meter Reading:
Close Date: 03/26/2014

Problem?

Driver side headlight out. R400

Parts	Quantity
-------	----------

Task performed:
REPAIRED ON WORK ORDER #63907.

NO PARTS USED

Workorder: V65094

In Date: 03/21/2014 Meter Reading: 119,168.00
Close Date: 03/26/2014

Problem?

No start

Parts	Quantity
-------	----------

Task performed:
1. NO START- CHECK CHARGING SYSTEM. 2. LIGHTS. 3. HORN- NO CITY HORN. 4. CHECK ENGINE LIGHT-COULD NOT GET COMPUTER CONNECTOR.

02038332800REFLECTOR	1
A0631117000HORN HIGH NEW # 06-52125-039	1
A0631117003HORN LOW NEW #06-52125-041	1
TURBO5TUBE - STROBE	1

Workorder: V66186

In Date: 05/02/2014 Meter Reading:
Close Date: 05/05/2014

Problem?

A/C in the patient compartment not working

Parts	Quantity
-------	----------

Task performed:
AFTER TRUCK WAS FINISHING DELIVERED TO STA-30 TO PICK THEM UP.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10136370 FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V63768

In Date: 01/28/2014
Close Date: 06/10/2014

Meter Reading:

Problem?

R400 (spare) will not start. Possible battery...

Task performed:
Replaced starter

Parts	Quantity
11132766583 STARTER 28MT 5.9 10 TOOTH 104650	1

Workorder: V68782

In Date: 08/19/2014
Close Date: 09/19/2014

Meter Reading: 119,529.30

Problem?

A inspection SR1

Task performed:

1. "A" inspection and batteries. 2. Condensor fans rewire condensor fans and 110 A/C compressor fan needed to be fabricated to fit new fan. 3. Air bags. Remove and repair air bags. 4. Front and rear brake pads and defroster cable adjust. L3 compartment door tighten.

Parts	Quantity
16-15762-00016-19471-000 AIR BAG	2
60027FAN A/C COND 12IN 860026-2-W	3
8201L17-3428 ESTER OIL E7	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
HP-31DBATTERY 950CCA HP-31D	4
MK184HDBRAKE PADS	2



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10136370 FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V70419

In Date: 10/27/2014
Close Date: 11/20/2014

Meter Reading: 119,529.30

Problem?

C inspection SR1

Task performed:

1. Perform "C" service 2. Truck batteries were dead. Hooked up batteries to charger and charged batteries in parking lot before service. 3. Continued/completed "C" service 4. Replaced engine air filter 5. Replaced right side turn signal side marker light bulb and lens 6. Replaced wiper blades and cleaned debris from windshield squirter also topped off res. 7. Replaced patient compartment AC filter 8. Replaced pt compartment dome light bulb (burnt) 9. Replaced pt compartment cabinet hold open shocks (4) 10. Replaced left and right cab door trims (broken) 11. Replaced both door weatherstrip (torn) 12. Made and installed truck height sticker 13. Painted fuel cap 14. Replaced burnt out bulb in pt compartment side entry door light. 15. Checked out low alternator output. Once batteries were charged to 100% alternator output came back to acceptable output with all accessories on. 16. Disassembled front light bar to replace strobe on left end and peircer in the center (burnt out) 17. Removed old peeling non skid from both cab steps and pt compartment side entry door and install new (cut to length and width) 18. Replaced pull cord style air truck drains with petcocks. 19. Serviced haldex type dryer 20. Serviced power steering 21. Started tearing down steer axle wheel hubs. (water contamination) 22. Cleaned all parts from hubs, bearings, races, hubs and spindles. Reassembled with new seals. refilled with new gear oil. 23. Road tested truck, found ABS light staying on, traced problems to right front wheel sensor adjusted sensor and retested light is no staying off also checked hub oil and seals all good

Parts	Quantity
02036317300STROBE LINEAR REFLECTOR 6ELTUBI	2
0775145PANEL FILTER	1
103385NDRAIN COCK	2
194BULB	1
322502BULB PATIENT GH22	1
370150ASEAL	2
453868GASKET AXLE COVER CR	2
52-24WIPER BLADES ANCO 24	2
681-291-00-82BRAKE PEDAL PAD	1
91513AMBER LENS	1
A1834388002MOLD L/H	1
A1834388003MOLD R/H	1
CA8193AIR FILTER 46744 WIX	1
HLD3999GSS1715UV 30LB STRUT GAS	4
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
RN60JDRYER KIT	1
S3225PFUEL FILTER 33630 LFF5849	1
VML-T1264GASKET P/S COVER	1



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V71346

In Date: 12/02/2014
Close Date: 01/02/2015

Meter Reading: 119,838.20

Problem?

A-inspection

Task performed:

1. "A" inspection 2. Install new rotator light assembly in red light bar 3. Reinstall patient compartment loose draw slides 4. Check wiring for short in AC condensor fan circuit. Found circuit had 20 amp fuse should be 30 amp.

Parts	Quantity
01-0416333-00LIGHT ROTATOR	1
SWT54924ACTUATOR-RED	1
UCB30FUSE 30AMP	1

Workorder: V72169

In Date: 01/09/2015
Close Date: 01/20/2015

Meter Reading: 119,983.00

Problem?

A Inspect SR1

Task performed:

1. A Inspection. 2. Charge batteries. Clean up cab. Adjust air horns.

Parts	Quantity
NO PARTS USED	

Workorder: V73073

In Date: 02/11/2015
Close Date: 02/19/2015

Meter Reading: 119,838.20

Problem?

Batteries dead

Task performed:

1 Battery dead. Jump start battery charge to 13.5. Dies with load. Alternator charging at 14.1 volts. Remove battery. Instal new one. 2. Fuel leak. Filter housing drain valve leaking. Remove assembly. Install drain valve kit. Reassemble to operate.

Parts	Quantity
3926759-SDRAIN KIT	1
3963983WASHER SEAL ISB	4
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
HP-31DBATTERY 950CCA HP-31D	4



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136370

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V73892

In Date: 03/16/2015
Close Date: 04/27/2015

Meter Reading: 120,310.00

Problem?

Headlight inop

Parts

Quantity

Task performed:

1. R&R head light on spare R400.

Parts	Quantity
H6054BLH6054CVC1 HEADLIGHT EXTRA BRIGHT	1

146