



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142536

**FL60 ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V402**

In Date: 11/01/2005  
Close Date: 11/07/2005

Meter Reading:

**Problem?**

CHECK FRONT TIRES, SMALL FLAP LOOSE ON OUTER REAR TIRE  
SIDEWALL R-34

Parts ----- Quantity

Task performed:

NO PARTS USED

**Workorder: V618**

In Date: 11/18/2005  
Close Date: 11/22/2005

Meter Reading:

**Problem?**

multiple patient lights out R34

Parts ----- Quantity

Task performed:

322502BULB PATIENT GH22 2

**Workorder: V1138**

In Date: 01/09/2006  
Close Date: 01/10/2006

Meter Reading:

**Problem?**

REAR AIR BAGS WILL NOT FILL UP, R-34

Parts ----- Quantity

Task performed:

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V1520**

In Date: 02/15/2006

Close Date: 02/22/2006

Meter Reading:

**Problem?**

AIR HORNS INOP, R-34

Parts

Quantity

Task performed:

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V1331**

In Date: 01/27/2006  
Close Date: 02/23/2006

Meter Reading: 59,907.00

**Problem?**

**B INSPECTION R34**

**Task performed:**

See B Inspection pre-printed form

Parts	Quantity
091-3YWCOVER KUSSMAUL AUTO EJECT	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
29526898 29548988 TRANS FILTER ALLISON	1
800405PURGE VALVE KIT	1
9451BELT	1
9485BELT	1
98003RREFLECTOR RED 40132 GROTE	1
A1834388002MOLD L/H	1
HLD374211 IN HOLD-OPEN 30LB	2
HLD3999GSS1715UV 30LB STRUT GAS	4
K080733BELT	1
L1261F33585XE FUEL FILTER WIX	1
MK184HDBRAKE PADS	1
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

**10142536**  
**FL60 ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V1470**

In Date: 02/10/2006  
Close Date: 02/27/2006

Meter Reading:

**Problem?**

PASS. SIDE AIR HORN INOP, R-34

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED

**Workorder: V1568**

In Date: 02/21/2006  
Close Date: 03/06/2006

Meter Reading: 60,730.00

**Problem?**

LIGHT BAR ROTATOR'S INOP, R-34

Parts	Quantity
-------	----------

Task performed:

SWT54912SWITCH DOOR LGHT	1
SWT54930SWITCH DOOR	1

**Workorder: V1688**

In Date: 03/01/2006  
Close Date: 03/27/2006

Meter Reading:

**Problem?**

LIGHT OUT IN REAR LIGHT BAR & FRONT LIGHT BAR, AIR HORN INOP R-34

Parts	Quantity
-------	----------

Task performed:

01-0416333-00LIGHT ROTATOR	3
H50SN12BULB	3



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V1923**

In Date: 03/22/2006  
Close Date: 04/06/2006

Meter Reading:

**Problem?**

NEED FRONT SHOCKS, R-34

Task performed:

Parts	Quantity
SA66613SHOCK FRONT RESC	2

**Workorder: V2156**

In Date: 04/10/2006  
Close Date: 04/14/2006

Meter Reading:

**Problem?**

D/SIDE WIG-WAG INOP,3 PAT, LIGHTS INOP, R-34

Task performed:

Parts	Quantity
322502BULB PATIENT GH22	3
508RED58EC20RU STROBE-RED SURFACE MOUNT	1

**Workorder: V1556**

In Date: 04/20/2006  
Close Date: 04/20/2006

Meter Reading:

**Problem?**

LEFT FRONT TIRE FLAT-REPLACE TIRE (OUTSIDE VENDOR- TCI) R34

Task performed:

Parts	Quantity
22-49905-000CABLE HEATER	1

Vendor? TCI



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V2402**

In Date: 04/27/2006

Close Date: 05/17/2006

Meter Reading:

**Problem?**

B INSPECTION, R-34

Parts

Quantity



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Task performed:**

See B Inspection pre-printed form

032-0116549297 BATTERY INDICATOR	1
05-17223-000CAP RADIATOR 10 LB	1
16-31438915 VALVE CORE A/C 3544706C1	1
22-27156-000GASKET FUEL SENDER	1
22-40867-000RESERVOIR	1
25877BEARING	2
262194BRAASS FITTINGS	1
370150ASEAL	2
453868GASKET AXLE COVER CR	2
453879OIL PLUG CAN USE STEMCO	2
680-470-05-40STRAP FUEL TANK	2
680-883-10-14STEP BRACKETS	2
6804750148INSULATION	4
6804750303BRACKET FUEL TANK	2
6808880023GRILLE FRTLNR. A17-14766-000	1
A03-23537-001FUEL TANK 45 GAL RESCUE	1
A2243065003FUEL SENDING UNIT	1
ABPN8332229011-3050 SWITCH BLOWER	1
ACX-8453LUG CAPS WHEELED COACH # CH2732	1
AMH-1AMH-1 VALVE EXTENSION	1
ASL4152737141-70003 BRAKE CALIPER REAR ONL'	2
D6176M121-83014 ROTORS RESCUE	2
E-600013-3052 NUT	1
MK184HDBRAKE PADS	2
S4640024430VALVE LEVELIN	2
S777COUPLING NIPPLE	2



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V2036**

In Date: 03/30/2006  
Close Date: 05/26/2006

Meter Reading:

**Problem?**

2 TIRES HAVE NAILS (OUTSIDE AGENCY-TCI TIRE CENTER) R34

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED

**Workorder: V2855**

In Date: 06/04/2006  
Close Date: 06/08/2006

Meter Reading:

**Problem?**

Rear door of SCBA compartment on R34 has a broken hinge. The door swings open all the way hitting SCBA spare bottle compartment.

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED

**Workorder: V2968**

In Date: 06/13/2006  
Close Date: 06/13/2006

Meter Reading:

**Problem?**

110 volt a/c inop R34

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED





4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V2505**

In Date: 05/05/2006  
Close Date: 06/14/2006

Meter Reading:

**Problem?**

NEED 5 REAR TIRES, R-34 (CALLAGHAN TIRE)

Parts

Quantity

Task performed:

NO PARTS USED

Vendor? VC-15214



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V3460**

**In Date:** 07/13/2006

**Meter Reading:** 67,786.00

**Close Date:** 07/25/2006

**Problem?**

B INSPECTION AND REPAIRS AS NESSECARY

Parts

Quantity



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Task performed:**

107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
16-31438915 VALVE CORE A/C 3544706C1	2
20A-400CLAMP 4" 33969	1
22512960001498 SWITCH BINA	1
23-12080-150BOLT BUMPER	2
31-24WIPER BLADES	2
322502BULB PATIENT GH22	1
39181903918190 WASHER	1
3920773WASHER DRAIN PLUG	1
440-5 VALVE EXT.	1
4923090025DASH BULB VDO	2
6806970098SEAL DOOR	1
716907-0610A DRYER	1
800405PURGE VALVE KIT	1
806050014900KNOB A/C FREIGHTLINER	1
91513AMBER LENS	2
921LIGHT BULB	1
98003RREFLECTOR RED 40132 GROTE	2
A0631087000CABLE BATT. POS.	1
A0631088000CABLE BATT. NEG.	1
A0631117000HORN HIGH NEW # 06-52125-039	1
A0631117003HORN LOW NEW #06-52125-041	1
A1834388002MOLD L/H	1
A1834388003MOLD R/H	1
A22451940011499 SWITCH A/C HIGH PRESSURE NC	1
B2420LP-SMUD FLAP 24 X 24	1
B484RB484R REFLECT-RED	1
CA46362CA46362 RUBBER D-GRABBER	1
CA8193AIR FILTER 46744 WIX	1
DOOR2LEXAN 14.5 X 8.5	1



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

EXO3AH00015SPLUG RAD. DRAIN	0
FSC17492134NC SW PARK BK SPADE TYPE CONNE	1
HND5941USE HAN-1L METAL LATCH INTERIOR LO	1
HP-31DBATTERY 950CCA HP-31D	4
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1

**Workorder: V3902**

In Date: 08/14/2006      Meter Reading:  
 Close Date: 08/18/2006

**Problem?**

TURN SIGNALS,HIGH BEAMS,AND FLASHERS NOT WORKING. R-34

<u>Parts</u>	<u>Quantity</u>
--------------	-----------------

**Task performed:**

NO PARTS USED

**Workorder: V4712**

In Date: 10/03/2006      Meter Reading: 70,034.00  
 Close Date: 11/29/2006

**Problem?**

REPAIR DAMAGE FROM ACCIDENT R-34 (SEBOKS AUTO BODY)

<u>Parts</u>	<u>Quantity</u>
--------------	-----------------

**Task performed:**

- 1. repair damage from accident

NO PARTS USED

**Vendor?** SEBOKS



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10142536 FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V5585**

**In Date:** 11/28/2006  
**Close Date:** 12/06/2006

**Meter Reading:** 70,034.00

**Problem?**

REPLACE RUB RAIL AND SCBA COMP A INSPECTION AND REPAIRS AS NEEDED R34

**Task performed:**

1. CUT & WELD NEW DOOR/ COLLAR ON SCBA COMP. ALSO WELD UP 2 SCBA COMP FOR STOCK. 2. FABRICATE NEW RUB FOR LEFT REAR OF BODY. 3. REPLACE SECOND SCBA COMP DOOR ALSO. 4. SWAPPED INTO ON CALL TRUCK. 5. REPLACED DRIVERS SIDE MIRROR. 6. INSTALLED NEW FENDER MOLDING ON LEFT REAR. 7. PERFORM "A" SERVICE. 8. WIRED IN NEW L.E.D. TAIL/ STOP LIGHTS. 9. REPLACED FRT TIRES & RIGHT HUB CAP. 10. REPLACED TIE ROD TUBE ASSEMBLY, ALIGNED FRT END. 11. R/R STEERING WHEEL TO STRAIGHTEN, ROAD TEST.

Parts	Quantity
CH27007BUMPER DOOR	2
DEC6100DECAL REFLECTIVE STRIPE	4
EXT4534RUBRAIL EXTRUSION PER FT	4
GRO716SGRO716S MIRROR S/S	1
MFG9928PL17008 VERSACELL DECAL BACKING	4
RBR7862GA48800 RUBRAIL INSET	4
TDA-A2-3102K4379TIE ROD ASSY.	1

**Workorder: V6028**

**In Date:** 01/01/2007  
**Close Date:** 01/04/2007

**Meter Reading:** 5,507.70

**Problem?**

FRONT STROBE, REAR STROBE, FRONT GRILL R-34

**Task performed:**

1. Checked power packs and lights. Found cable to light bad. Replaced cable ok

Parts	Quantity
NO PARTS USED	



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

**10142536**

**FL60 ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V6285**

In Date: 01/16/2007      Meter Reading: 72,680.00  
 Close Date: 01/24/2007

**Problem?**

ON CALL COMP DOOR WONT OPEN R34

Parts	Quantity
-------	----------

**Task performed:**

NO PARTS USED

**Workorder: V6523**

In Date: 01/29/2007      Meter Reading: 73,472.00  
 Close Date: 01/29/2007

**Problem?**

R34 airhorns are not working....

Parts	Quantity
-------	----------

**Task performed:**

1. rebuild and tune both air horns

1094KIT-AIR HORN-GROVER	2
-------------------------	---

**Workorder: V6331**

In Date: 01/18/2007      Meter Reading: 72,938.00  
 Close Date: 02/01/2007

**Problem?**

2 strobes in lightbar are out r34

Parts	Quantity
-------	----------

**Task performed:**

Work completed on Work order number V6374

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V6374**

In Date: 01/20/2007  
Close Date: 02/01/2007

Meter Reading: 5,591.00

**Problem?**

1 stobe light out on front light bar and 1 strobe light out on rear light bar.  
R-34

Parts	Quantity
-------	----------

**Task performed:**

1. Replaced strobes in front and rear light bars

NO PARTS USED

**Workorder: V6603**

In Date: 02/03/2007  
Close Date: 02/06/2007

Meter Reading: 5,668.70

**Problem?**

Front right headlight is out needs repair. Thank you. R-34

Parts	Quantity
-------	----------

**Task performed:**

1. R&R headlight

194BULB	10
H6054USE CV TYPE SEALED BEAM	2

**Workorder: V6676**

In Date: 02/08/2007  
Close Date: 02/12/2007

Meter Reading: 5,692.00

**Problem?**

Parking Brake needs to be adjusted. Thank You r34

Parts	Quantity
-------	----------

**Task performed:**

1. Adjusted parking brake

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V6769**

In Date: 02/14/2007      Meter Reading: 5,712.00  
 Close Date: 03/02/2007

**Problem?**

The A/C in the back doesn't get cold on the shore line. The A/C in the back does get cold when the truck is running and during pt. care. r34

Parts	Quantity
-------	----------

**Task performed:**

Fill unit w/freon; look for leak Tighten fitting & clamps

NO PARTS USED
---------------

**Workorder: V7042**

In Date: 03/02/2007      Meter Reading: 5,793.00  
 Close Date: 03/08/2007

**Problem?**

fron passenger head light out R34

Parts	Quantity
-------	----------

**Task performed:**

R&R headlight

H6054USE CV TYPE SEALED BEAM	1
------------------------------	---





4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V7110**

**In Date:** 03/08/2007

**Meter Reading:** 76,125.00

**Close Date:** 03/16/2007

**Problem?**

b inspection and repairs as needed r34

Parts

Quantity



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10142536 FL60 ADVANCED LIFE SUPPORT VEHICLE

**Task performed:**

1. Clean work area
2. Pick up rescue at station 34 for p/m
3. B Inspection
4. Replaced rear tires
5. Secured patient compartment door panels replaced missing and stripped screws. Also repaired latches and levers
6. Replaced patient comp. plexi glass doors
7. Replaced 2 marker lights. R&S strobe bulbs and repaired strobe connectors
8. Serviced air dryer
9. R&R master cylinder and booster. Replaced booster o rings
10. Tightened and adjusted mirrors
11. Replaced broken a/c compressor and dryer. Replaced stripped low side connector
12. Repaired stripped bolts in grab handle
13. Replaced belts and adjusted
14. Repaired rear overhead panel and reinstalled
15. Repaired loose rear fold up step

107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
2234934MASTER CYLINDER ASL	1
31-24WIPER BLADES	2
3541435414 CLAMP 2 1/2"	2
3917746ISOLATOR VIBRATION	8
39177473917747 INSULATOR	6
532703-0602 COMPRESSOR U4735 4471	1
716907-0610A DRYER	1
800405PURGE VALVE KIT	1
9451BELT	1
9485BELT	1
ASL-2770932O-RING POWER BOOSTER	2
ASL2772866ASL2772866 BOOSTER BRAKE	1
CA8193AIR FILTER 46744 WIX	1
DOOR2LEXAN 14.5 X 8.5	1
DOOR5LEXAN 9 X 38 1/2 IN	1
FG-Q347367FILLER CAP POWER STEERING	1
HE50477VENT	4
HND5941USE HAN-1L METAL LATCH INTERIOR LOCK	2
K080733BELT	1
L1261F33585XE FUEL FILTER WIX	1
LTC5992C5-12-15-3 LATCH LEVER NON-LOCKING	1
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1
TURBO5TUBE - STROBE	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V7149**

In Date: 03/11/2007      Meter Reading: 76,163.00  
 Close Date: 04/03/2007

**Problem?**

replace tires at callaghan ent r34

Parts	Quantity
-------	----------

**Task performed:**

Replace tires at Callaghan Ent R34

NO PARTS USED
---------------

Vendor? CALLAGHAN ENT

**Workorder: V7728**

In Date: 04/15/2007      Meter Reading: 5,966.00  
 Close Date: 04/30/2007

**Problem?**

Rear drivers side emergency flasher has 1 bulb out R-34

Parts	Quantity
-------	----------

**Task performed:**

R/R emergency flashere bulb

TURBO5TUBE - STROBE	1
---------------------	---

**Workorder: V7858**

In Date: 04/22/2007      Meter Reading: 5,997.70  
 Close Date: 05/03/2007

**Problem?**

1. R34 DRIVER'S SIDE REAR DOOR - EMERGENCY LIGHT DOES NOT WORK. 2. R34 SPOT LIGHT DOES NOT ROTATE FULLY, RANGE OF MOTION SEEMS TO BE LIMITED.

Parts	Quantity
-------	----------

**Task performed:**

R/R bulb in rear lite bar & get spotlight back on track; test ok

H50SN12BULB	1
-------------	---



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10142536 FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V8234**

In Date: 05/14/2007      Meter Reading: 79,689.00  
Close Date: 06/06/2007

**Problem?**

GAS IN DIESEL TANK R-34

**Task performed:**

- 1. On call, drive out to Sta, bring to shop, pump out tank, change fuel filters

Parts	Quantity
33047FUEL FILTER RACOR S6464 E-ONE	1
R90PFILTER FUEL 33231	1

**Workorder: V8274**

In Date: 05/15/2007      Meter Reading: 6,095.00  
Close Date: 06/06/2007

**Problem?**

- 1.Lt side exterior side entry door to pt area needs new door handle.
- 2.Battery indicator panel by shore power needs to be replaced. RE34

**Task performed:**

- 1. Take side door apart, replace inside and outside latch & adjust rods. Reinstalled panel on door, test OK 2. Rewire battery indicator panel. Light inop. Rewired, test OK

Parts	Quantity
032-0116549297 BATTERY INDICATOR	1
CLP3991CLP3991 CLIP-PLASTIC FOR	2
HND5948TM22676-02 HANDLE DOOR ENTRY	1

**Workorder: V8262**

In Date: 05/15/2007      Meter Reading: 6,095.00  
Close Date: 06/07/2007

**Problem?**

Shore power not working. cord has power r34

**Task performed:**

- 1. Reset breaker, check for loose wires

Parts	Quantity
NO PARTS USED	



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142536

**FL60 ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V8449**

In Date: 05/28/2007

Meter Reading: 80,477.00

Close Date: 06/11/2007

**Problem?**

ON CALL R34 REAR A/C 10-7

**Task performed:**

Problem: rear A/C inop again - He says this happens about every 3-4 months - says vehicle has been in shop a couple of times but because the leak is so small it has not been found yet. A quick re-charge and its good for another 3-4 months 1. First - 110V A/C was plugged in and fans running but was blowing hot air - compressor not on - checked electrical panel and found terminals on converter burnt up - (so much for the 110V system). Next - Iturned on vehicles 12V patient A/C - (Also NG)(this is where they thought it was out of freon) Went to charge system and found this service vehicle has no A/C guages nor any 134 freon bottle, so we brought the vehicle to the shop - hooked up A/C machine and reclaimed freon from system - system was full, drew out 2lbs 15oz - (so much for their theory on being empty) - Next, checked electrical to A/C system - control board and blower fans had power but none to compressor or condensor fans - checked other circuits also - NG - This waas gonna take some time to fugure out and then repair - had crew change out.

Parts

Quantity

NO PARTS USED

**Workorder: V8444**

In Date: 05/27/2007

Meter Reading: 80,477.00

Close Date: 06/14/2007

**Problem?**

REPAIR PATIENT A/C

**Task performed:**

1. Found power converter bad, R/R & charge 110V A/C

Parts

Quantity

5-20PH1PGK4 CONNECTOR 120V 20A FEMALE

1

PD9180CONVERTOR 110V 80 AMP

1



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V8570**

In Date: 06/04/2007      Meter Reading: 80,595.00  
 Close Date: 06/21/2007

**Problem?**

REPAIR PAITENT A/C R34

Parts	Quantity
-------	----------

**Task performed:**

1. R22 system low on freon due to pressure switch leak, replaced pressure switch, vacumed & filled system. Checked freon in R134A system

11-26521487 SWITCH NC O 340 - C 210 HIGH PRE	2
--	---

**Workorder: V8701**

In Date: 06/11/2007      Meter Reading: 81,068.00  
 Close Date: 06/26/2007

**Problem?**

PAITENT A/C 10-7 R34 ON CALL

Parts	Quantity
-------	----------

**Task performed:**

Chkd rear A/c; fnd swch in wrng position & slightly over charged @ 60; Repaired patient compt door latch

NO PARTS USED
---------------

**Workorder: V8969**

In Date: 06/22/2007      Meter Reading: 6,240.20  
 Close Date: 07/02/2007

**Problem?**

RIGHT SIDE AIRHORN DOES NOT WORK. ATTEMPTED TO TIGHTEN DOWN, BUT SEAL APPEARS TO BE BROKEN. AND LEFT SIDE AIRHORN SOUNDS LIKE IT NEEDS TO BE TUNED. r34

Parts	Quantity
-------	----------

**Task performed:**

1. Drive to Stn; rescue out on call 2. Drive to Stn; rebuild air horn & adj - test ok 3. Apparatus committee meeting

1094KIT-AIR HORN-GROVER	1
-------------------------	---



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V8968**

In Date: 06/22/2007  
Close Date: 07/03/2007

Meter Reading: 6,240.20

**Problem?**

DRIVER SIDE SEATBELT IS BROKEN. RED PUSH BUTTON ON CLIP BROKE AND IS NO LONGER IN PLACE, AND SEATBELT IS UNABLE TO APPLY OR TAKE OFF. r34

Parts	Quantity
-------	----------

**Task performed:**

drive to stn; installed seat belt; test ok

NO PARTS USED

**Workorder: V9348**

In Date: 07/16/2007  
Close Date: 07/19/2007

Meter Reading: 82,957.00

**Problem?**

Vehicle shakes badly on brake application R34

Parts	Quantity
-------	----------

**Task performed:**

1. ROAD CALL TO STA 34 TO CHECK OUT BRAKE PROBLEM. FOUND R FRONT BRAKE METAL TO METAL. 2. REPLACED FT BRAKE PAD, ROTORS, CALIPERS, SEALS AND HUB SEALS. FILLED WITH NEW FLUID. ALSO REPLACED REAR AXLE BRAKE PADS. 3. REPLACED P COMP. A/C FILTER. 4. REPLACED STEER AXLE TIRES.

370150ASEAL	2
453868GASKET AXLE COVER CR	2
ASL4152092CALIPER F/R RESCUE 55314 NEW	2
D6176M121-83014 ROTORS RESCUE	2
E-600013-3052 NUT	1
MK184HDBRAKE PADS	2



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V9797**

In Date: 08/09/2007      Meter Reading: 83,839.00  
 Close Date: 08/10/2007

**Problem?**

on call r34 paitent a/c 10-7

Parts	Quantity
-------	----------

**Task performed:**

Fnd too much freon in system; press too high; ness to let out freon

NO PARTS USED

**Workorder: V9808**

In Date: 08/09/2007      Meter Reading: 6,409.50  
 Close Date: 08/10/2007

**Problem?**

rear ac not working properly. ac not cooling rear compartment past 80 degrees.r34

Parts	Quantity
-------	----------

**Task performed:**

Fnd rear A/C not cool; ness to add freon & clean condensor

NO PARTS USED

**Workorder: V9911**

In Date: 08/14/2007      Meter Reading: 84,017.00  
 Close Date: 09/07/2007

**Problem?**

Replace 6 tires R34 (outside agency-callaghan tire)

Parts	Quantity
-------	----------

**Task performed:**

Replace (6) tires - Callaghan

NO PARTS USED

**Vendor?** CALLAGHAN





4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V10184**

**In Date:** 08/30/2007  
**Close Date:** 09/11/2007

**Meter Reading:** 6,501.00

**Problem?**

rear ac in rescue does not work when plugged into electrical ac outlet. r34

Parts

Quantity

**Task performed:**

Drive to Stn; chk freon-low; fill; chk for leak; fnd none

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V10643**

**In Date:** 09/24/2007  
**Close Date:** 10/25/2007

**Meter Reading:** 85,593.00

**Problem?**

b inspection and repairs as needed r34

Parts

Quantity



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Task performed:**

1. b inspection 2. replaced batteries. failed load test also lubricated latches and slides. 3. added coolant. coolant low. 4. replaced radiator cap. did not pass test. 5. checked drag link and tie rods on service. found excessive play in all joints and drag link. set toe in after repairs. 6. oil pan leak found on service. removed oil pan. cleaned affected area and pan. removed old gasket. installed new gasket and pan. added oil. ok. 7. front seal on engine leaking. found on service. removed all bolts and fan hub assembly. removed balancer and front cover. replaced front seal, belts and balancer. reassembled and tested ok. 8. 8 hours vacation. 9. had 2 strobes out on service. replaced grill strobe and light bar started to work. replaced rotator bulb and cleaned lens on front ok. 10. found lights out on pm. repaired cat clearance, hi + lo dome, action area lights 11. loose door latches and cracked covers found on v. replaced inner door latch covers. replaced and tightened screws in body door latches. replaced compartment hold opens. 12. secured loose tool holders and replaced worn out stretcher latch found on b. 13. replaced city horns. both inoperable found on b. 14. replace worn wipers found on b. 15. replaced drivers and passengers seat belts. noth had holes in them found on b. 16. replaced broken a/c vents found on b. 17. spotlight stuck. replaced blown fuse in spot 18. clean work area after 3.

05-17223-000CAP RADIATOR 10 LB	1
090-0278STRECHER BAR NEW	1
194BULB	3
322502BULB PATIENT GH22	1
3804899SEAL FRONT COVER B	1
3918999HARMONIC BALANCER OLD RESCUES	1
3959052PAN GASKET B ENGINE	1
52-24WIPER BLADES ANCO 24	2
58ELTUBE58L4TUBE STROBE/REFLECTOR ASSY. 5	1
6808300074VENT A/C LH	2
6808300174VENT A/C RH	2
68318336550 508 4 HOLE LENS 68-3183365-50	1
921LIGHT BULB	1
9451BELT	1
9485BELT	1
A0631117000HORN HIGH NEW # 06-52125-039	1
A0631117003HORN LOW NEW #06-52125-041	1
A1414374000DRAG LINK RESCUE	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/H27SN12BULB	4
HLD3999GSS1715UV 30LB STRUT GAS	1
HND5941USE HAN-1L METAL LATCH INTERIOR LOCK	6
HP-31DBATTERY 950CCA HP-31D	2
IMMF13224BELT SEAT DRIVER SIDE IMMF11851 OLD #	4
IMMF13225BELT SEAT PASS. IMMF11852 OLD #	1
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
R230068TIE ROD L/H PUMPER	1
R230069TIE ROD R/H PUMPER A3144D524	1
S3225PFUEL FILTER 33630 LFF5849	1



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V11573**

**In Date:** 11/13/2007      **Meter Reading:** 6,664.00  
**Close Date:** 11/19/2007

**Problem?**

Emergency lights on Rescue 34. One red light in front driver side is not functioning properly. One red light on driver rear is out.

Parts	Quantity
-------	----------

**Task performed:**

drive to Stn; R/R bulb front light bar & rear light bar bulb j

02036317300STROBE LINEAR REFLECTOR 6ELTUBI	1
H35SN12BULB	1

**Workorder: V11692**

**In Date:** 11/20/2007      **Meter Reading:** 87,632.00  
**Close Date:** 12/03/2007

**Problem?**

power steering fluid low-none in station R34

Parts	Quantity
-------	----------

**Task performed:**

1. Drive to Sta. found hose loose on gear box, rework fitting, fill, test OK.

NO PARTS USED
---------------

**Workorder: V11693**

**In Date:** 11/20/2007      **Meter Reading:** 6,700.00  
**Close Date:** 12/03/2007

**Problem?**

Power Steering Fluid Empty r34

Parts	Quantity
-------	----------

**Task performed:**

1. See WO # 11692

NO PARTS USED
---------------



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10142536 FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V12039**

In Date: 12/13/2007  
Close Date: 01/07/2008

Meter Reading: 6,769.60

**Problem?**

Will not start. r34

**Task performed:**

1. Chgecked problem with truck not starting. 2. Removed pick-up pump and fuel injecton pump 3. Install new pick-up pump, had to remove, found key way, skored. 4. Install new injector pump.

Parts	Quantity
322502BULB PATIENT GH22	1
3408430NXSENSOR SPEED USE 4921597	1
3935172USE 3963988 WASHER-SEAL	6
3964555RXFUEL PUMP ISB	2
4943048LIFT PUMP ISB	1
FSC17492134NC SW PARK BK SPADE TYPE CONNE	1
L1261F33585XE FUEL FILTER WIX	1
WIN6485PATIENT WINDOW UPPER REAR WINDOW	1
WIN6488PATIENT WINDOW LOWER SMALL	1

**Workorder: V12482**

In Date: 01/09/2008  
Close Date: 01/31/2008

Meter Reading: 6,831.10

**Problem?**

RIGHT AIRHORN DOES NOT WORK. R31

**Task performed:**

Air horn not working; adj air horns. j

Parts	Quantity
NO PARTS USED	



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V12922**

**In Date:** 01/30/2008      **Meter Reading:** 7,013.70  
**Close Date:** 02/05/2008

**Problem?**

RESCUE 31 RIGHT AIRHORN DOES STILL NOT WORK..

Parts	Quantity
-------	----------

**Task performed:**

1. Adjusted air horn on right side that was not working. 2. A/C Belt making noise, adjusted a/c compressor belts

NO PARTS USED

**Workorder: V13170**

**In Date:** 02/11/2008      **Meter Reading:** 91,444.00  
**Close Date:** 02/12/2008

**Problem?**

a inspection and repairs as needed r31

Parts	Quantity
-------	----------

**Task performed:**

1. "A" inspection, R & R lights in rearside, R & R stecton lock 1A. Work on line 1 above. 2. Assist with "A" inspection 3. Front tires weathered, wear, toe out, adjusted toe to 0 degrees 4. (Road tested) pulls to the right, front tires replaced. 5. Door panels loose, tighten patient compartment door panels 6. Mirrors out of adjustment, adjusted mirrors 7. Drawers hard to open, out of adjustment, adjusted drawers

090-0278STRECHER BAR NEW	1
322502BULB PATIENT GH22	4
TURBO5TUBE - STROBE	2

**Workorder: V13054**

**In Date:** 02/05/2008      **Meter Reading:** 7,032.00  
**Close Date:** 02/13/2008

**Problem?**

repair passenger door, and passenger seat belt. r31

Parts	Quantity
-------	----------

**Task performed:**

1. Adjusted all cab door latches 2. Checked seat belt and found no problem with seat belt.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V13607**

In Date: 02/29/2008      Meter Reading: 7,167.30  
 Close Date: 03/13/2008

**Problem?**

A/C NOT WORKING PROPERLY WHEN SHORE LINE IS PLUGED IN.  
 ONLY BLOWS OUT HOT AIR. r31

Parts ----- Quantity -----

**Task performed:**

1. recharged rear 110v A/C and tested

NO PARTS USED
---------------

**Workorder: V13862**

In Date: 03/12/2008      Meter Reading: 7,280.50  
 Close Date: 03/19/2008

**Problem?**

RPM's are higher than normal when shifting and it shifts very hard,  
 especially into second gear. R31

Parts ----- Quantity -----

**Task performed:**

1. Truck hard shifting, fast adapted and road tested, will monitor

NO PARTS USED
---------------

**Workorder: V13132**

In Date: 02/08/2008      Meter Reading: 91,444.00  
 Close Date: 04/11/2008

**Problem?**

RADIATOR LEAKING R31

Parts ----- Quantity -----

**Task performed:**

r/r radiator in truck due to crack in tank

BHT/A4570RADIATOR	1
PH-230-4-2ELBOW 90 DEG	1



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

**10142536**

**FL60 ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V14572**

In Date: 04/20/2008      Meter Reading: 7,470.20  
 Close Date: 04/30/2008

**Problem?**

Truck is leaking oil. Added approx. 2 quarts. R31

Parts	Quantity
-------	----------

**Task performed:**

1. sent to shop for pm.

NO PARTS USED

**Workorder: V14651**

In Date: 04/23/2008      Meter Reading: 7,484.00  
 Close Date: 04/30/2008

**Problem?**

Rescue 31 has problem shifting from 2 & 3rd gear. Seems to be worse when motor is hot, and will stick in 2nd or 3rd gear for an extended amount of time, causing truck to drive very slow with high RPM's.

Parts	Quantity
-------	----------

**Task performed:**

1. trouble shoot trans. road test, checks codes-46-21 for f solenoid circuit, replace TCM 2. clean shop

NO PARTS USED

**Workorder: V14782**

In Date: 04/30/2008      Meter Reading: 95,978.00  
 Close Date: 05/02/2008

**Problem?**

purchase of ecu for trans

Parts	Quantity
-------	----------

**Task performed:**

Purchase ECU for trans - Florida Detroit Diesel j

NO PARTS USED

**Vendor?** FLORIDA DETROIT





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10142536 FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V14676**

In Date: 04/24/2008  
Close Date: 05/06/2008

Meter Reading: 95,978.00

**Problem?**

B inspection and repairs as needed r31

**Task performed:**

1. Perform B Service
2. Service Batteries
3. Replace brake pads on steer axle and brake axle
4. Replaced wiper blades
5. Replaced patient compartment dome light
6. Replaced left, rear scene entry light in light bar
7. Secured loose exhaust clamp

Parts	Quantity
15W40BSYN OIL BULK QTS	16
18-29935-001RH DOOR LATCH NEW	1
322502BULB PATIENT GH22	1
52-24WIPER BLADES ANCO 24	2
ACX-84534LUG NUT COVER PK10	7
H35SN12BULB	1
L1261F33585XE FUEL FILTER WIX	1
MK184HDBRAKE PADS	2
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1

**Workorder: V14885**

In Date: 05/06/2008  
Close Date: 05/12/2008

Meter Reading:

**Problem?**

Truck is leaking radiator fluid r31

**Task performed:**

- Replaced leaking water pump j

Parts	Quantity
15W40QSYN OIL QT	12
3286278WATER PUMP ISB	1
ANTICOOLANT ANTIFREEZE GAL	7



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V14495**

In Date: 04/15/2008      Meter Reading:  
Close Date: 05/14/2008

**Problem?**

New light bulb in rear top reverse light R-34

Parts	Quantity
-------	----------

**Task performed:**

1. found no light out in rear

NO PARTS USED

**Workorder: V14997**

In Date: 05/11/2008      Meter Reading: 7,553.00  
Close Date: 06/02/2008

**Problem?**

flashlight charger in driver compartment not charging. PA not working R31

Parts	Quantity
-------	----------

**Task performed:**

Rep power wire for handlights. j

NO PARTS USED

**Workorder: V15085**

In Date: 05/14/2008      Meter Reading: 7,573.00  
Close Date: 06/02/2008

**Problem?**

A/C in patient compartment blows hot when plugged into shore line.

Parts	Quantity
-------	----------

**Task performed:**

Charged cab A/C & clean filters. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10142536 FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V15086**

In Date: 05/14/2008  
Close Date: 06/02/2008

Meter Reading: 7,573.00

**Problem?**

FRONT END SHAKES WHEN DRIVING OVER 30 MPH.

Parts ----- Quantity -----

**Task performed:**

Road tested & fnd small shake in frnt end; will monitor. j

NO PARTS USED

**Workorder: V14995**

In Date: 05/11/2008  
Close Date: 06/03/2008

Meter Reading: 7,553.00

**Problem?**

Truck is not shifting appropriately again. RPM's are going very high without the truck speed increasing like it should. Shore line does not automatically disconnect when truck is started R31

Parts ----- Quantity -----

**Task performed:**

Drain fluid; let trans cool off a little & rem valve body asy; replc all shift solenoid & speed sensor; scrape off old gskts frm metering plates & prepare for reassemble; reassemble fill & road test. j

29526898 29548988 TRANS FILTER ALLISON 1

**Workorder: V15088**

In Date: 05/14/2008  
Close Date: 06/03/2008

Meter Reading: 7,573.00

**Problem?**

RIGHT AIRHORN DOES NOT WORK, AND HAS TO CONSTANTLY BE ADJUSTED. R31

Parts ----- Quantity -----

**Task performed:**

Adjusted air horns j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V14748**

In Date: 04/29/2008      Meter Reading: 95,978.00  
 Close Date: 06/11/2008

**Problem?**

replace tires at shop r31 callaghan

Parts	Quantity
-------	----------

**Task performed:**

Replace tires at shop R31 - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

**Workorder: V14989**

In Date: 05/10/2008      Meter Reading: 7,553.00  
 Close Date: 06/13/2008

**Problem?**

Med. drawer roller bracket broken. R31

Parts	Quantity
-------	----------

**Task performed:**

replc slides in drawer. j

SLD5366HT4932-16 DRAWER SLIDE 16	2
----------------------------------	---

**Workorder: V15719**

In Date: 06/13/2008      Meter Reading: 7,761.90  
 Close Date: 07/09/2008

**Problem?**

REAR RIGHT SIDE STROBE DOES NOT WORK, AS WELL AS ONE OF THE MIDDLE STROBES IN THE REAR LIGHTBAR. r31

Parts	Quantity
-------	----------

**Task performed:**

1. replaced right rear strobe

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

**10142536**

**FL60 ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V15765**

In Date: 06/16/2008  
Close Date: 07/09/2008

Meter Reading: 7,777.30

**Problem?**

Rear officers side emergency light is out and 1 rear load light is out. r31

Parts	Quantity
-------	----------

**Task performed:**

1. repaired bad connection in rear load lights

NO PARTS USED

**Workorder: V15794**

In Date: 06/17/2008  
Close Date: 07/09/2008

Meter Reading: 7,777.30

**Problem?**

flash light charger in driver compartment not working. Flash lights are dead.  
R-31

Parts	Quantity
-------	----------

**Task performed:**

1. checked chargers out found units working

NO PARTS USED

**Workorder: V15828**

In Date: 06/18/2008  
Close Date: 07/09/2008

Meter Reading: 7,777.30

**Problem?**

Rear emergency strobe light out on Rescue 31

Parts	Quantity
-------	----------

**Task performed:**

1. repaired strobe on right side.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V15886**

In Date: 06/21/2008  
Close Date: 07/09/2008

Meter Reading: 98,770.00

**Problem?**

Box light charger not working in airway comp. Front left charger R31

Parts	Quantity
-------	----------

**Task performed:**

1. checked sl 40 handlights found units working.

NO PARTS USED

**Workorder: V15964**

In Date: 06/25/2008  
Close Date: 07/10/2008

Meter Reading: 7,623.00

**Problem?**

1 box light is not working. 1 box light charger is not working. r31

Parts	Quantity
-------	----------

**Task performed:**

Chkd SL-40 handlights & f nd both units charging. j

NO PARTS USED

**Workorder: V16277**

In Date: 07/10/2008  
Close Date: 07/18/2008

Meter Reading:

**Problem?**

FRONT END FEELS LOOSER THAN NORMAL AND SHAKES AT CRUISING SPEED. r31

Parts	Quantity
-------	----------

**Task performed:**

Road tested truck; fnd no problems. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

**10142536**

**FL60 ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V16046**

**In Date:** 06/29/2008      **Meter Reading:** 7,845.00  
**Close Date:** 07/24/2008

**Problem?**

front intake swivle handle missing R31

Parts	Quantity
-------	----------

**Task performed:**

waiting for E-One to supply small handle. j

NO PARTS USED

**Workorder: V16274**

**In Date:** 07/10/2008      **Meter Reading:** 99,767.00  
**Close Date:** 07/24/2008

**Problem?**

open compartment door alarm continously sounding with doors closed r31

Parts	Quantity
-------	----------

**Task performed:**

1. LED light out; FND bad connectdion in light & repaired. 2. Fnd no light going off at this time. j

02036273300 TURBO94 CORNERLINEAR REFLECTC	1
90R00FRR900 SERIES LED W/O FLANGE - RED	1



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V16636**

**In Date:** 07/28/2008

**Meter Reading:** 99,767.00

**Close Date:** 07/31/2008

**Problem?**

**B INSPECTION AND REPAIRS AS NEEDED, (OLD R-31)**

**Task performed:**

1. Perform special B-Inspection. 2. Svc cooling system 3. Rebuilt air brake dryer 4. Painted fuel cap. 5. Replc cab roof marker light bulb. 6. Replc broken "T" fitting in windshield. 7. Cut to fit/mnt new mud flap (missing). 8. Replc belts. 9. Replc left/right door weatherstrip moldings. (ripped/torn). 10. Replc left/right flag stickers on rear of body (faded). 11. Rem door panel; clnd, lube,adj door latch (binding/seized). 12. Replc both inner door latch bezels on pat compt (cracked/broken). 13. Replc pat compt plexiglass door (cracked broken). 14. Replc left/right turn signal side marker lenses (cracked). 15. Replc eng air filter. 16. Replc right side upper frt body strobe (burnt). 17. Replc bulb in traffic advisor & rewire faulty connection. 18. Replc left side, forward dome in pat compt. j

**Parts**

**Quantity**

107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
322502BULB PATIENT GH22	1
680-10LAMERICAN FLAG W UV CLEAR LEFT	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
6806970098SEAL DOOR	1
800405PURGE VALVE KIT	1
91513AMBER LENS	2
9451BELT	1
9485BELT	1
AEVDOOR LOCK BEZEL	2
B2420LP-SMUD FLAP 24 X 24	1
CA8193AIR FILTER 46744 WIX	1
DOOR5LEXAN 9 X 38 1/2 IN	1
H20SN12H20SN12 BULB	1
H35DSN12BULB 35W DUAL FILAMENT DOME	1
K080733BELT	1
SPR-W58-1TEE PLASTIC	1
TURBO5TUBE - STROBE	1





4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V15067**

In Date: 05/14/2008  
Close Date: 10/20/2008

Meter Reading: 7,573.00

**Problem?**

Truck is not shifting right, again. The RPM's go up very high and the truck does not shift. E-31

<u>Parts</u>	<u>Quantity</u>
--------------	-----------------

**Task performed:**

NO PARTS USED

**Workorder: V18590**

In Date: 10/24/2008  
Close Date: 11/05/2008

Meter Reading: 7,944.00

**Problem?**

air horn not working, dose not shift propely E20

<u>Parts</u>	<u>Quantity</u>
--------------	-----------------

**Task performed:**

Drive to Stn; installed air horn kit; adj air horns; test ok. j

1094KIT-AIR HORN-GROVER	1
-------------------------	---



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V19263**

**In Date:** 11/21/2008  
**Close Date:** 12/08/2008

**Meter Reading:** 100,052.80

**Problem?**

A INSPECTION AND REPAIRS AS NEEDED SR

**Task performed:**

A-Inspection, air tires, add oil, washer fluid, & P/S fluid; add (2) qts trans fluid. 2. Dia no city horns; replcd both high/low horns; cln contact. 3. Dia L-frnt box strobe out; fnd bad bulb; replcd bulb. 4. Replcd bulbs L-roof clearance light & rep connection LF side marker light; tighten L-3 hinge bolts. 5. Chk trans codes; fnd (1) count 4621F solenoid ckt over current; erased code & drove veh; chkd for codes again; ok at this time. 6. Dia door adjar light on; fnd bud magnet swtch on rear compt; replcd swtch. 7. Straighten bent door & mirror frame & adj mirror. 8. Meeting. j

Parts	Quantity
A0631117000HORN HIGH NEW # 06-52125-039	1
A0631117003HORN LOW NEW #06-52125-041	1
SWT54930SWITCH DOOR	1
TURBO5TUBE - STROBE	1
WIL-131973TPS SENSOR	1

**Workorder: V14994**

**In Date:** 05/11/2008  
**Close Date:** 01/02/2009

**Meter Reading:** 7,553.00

**Problem?**

A/C in patient compartment. not working when plugged into shore line. R31

**Task performed:**

Parts	Quantity
NO PARTS USED	



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V19462**

In Date: 12/02/2008  
Close Date: 01/07/2009

Meter Reading: 100,052.80

**Problem?**

A inspection (back from 15)

Parts	Quantity
-------	----------

**Task performed:**  
A-Inspection j

NO PARTS USED

**Workorder: V20159**

In Date: 01/06/2009  
Close Date: 01/07/2009

Meter Reading: 7,995.00

**Problem?**

Both outer rear tires have separation from re-cap on sidewall. Confirmed by mechanic.

Parts	Quantity
-------	----------

**Task performed:**

NO PARTS USED

**Workorder: V20342**

In Date: 01/13/2009  
Close Date: 01/27/2009

Meter Reading: 101,338.10

**Problem?**

TRANS SHIFTING HARD SR AT36

Parts	Quantity
-------	----------

**Task performed:**

1- Trans shifting hard, road tested and will monator the truck.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V20182**

In Date: 01/07/2009      Meter Reading: 100,839.00  
 Close Date: 02/17/2009

**Problem?**

REPLACE ALL 4 REAR TIRES, R-26

Parts	Quantity
-------	----------

**Task performed:**

Replace all (4) rear tires R26 - Callghan j

NO PARTS USED

Vendor? CALLAGHAN

**Workorder: V20642**

In Date: 01/27/2009      Meter Reading: 101,509.70  
 Close Date: 02/17/2009

**Problem?**

A INSPECTION AND REPAIRS AS NEEDED SR 1 CHECK TRANS

Parts	Quantity
-------	----------

**Task performed:**

A-Inspection 2. Rem tilt column lock asy to inspect all locking teeth; look ok; ordered replacement lock springs; installed springs in column. 3. Trans has code 4621; solenoid shorted; replcd trans ECU within \_\_\_\_ unit & test drove; code came back after an hour on road; performed pin & wire tested on solenoid all negative; sending to FDOA for repair. 4. Lube steering column boot. 5. Traced down banging noise in dash; fnd msng bolts in hood & dash support; isntalled new bolts & tested ok. 6.Traced & rep shorted door swtch wires in cab door. 7. Adj all horns. 8. Traced down & rep fuel leak; chkd transfer pump return lines & tightend injector lines. 9. Sec loose wire on RF siren speaker. 10. Diss light bar to trace wires for outer rotator; rep positive wire & clnd up ground. j

RGT/401667SPRING STEERING	1
RGT/401668SPRING LOWER STEERING	1



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V21268**

In Date: 02/22/2009      Meter Reading:  
Close Date: 02/28/2009

**Problem?**

Spare rescue leaking transmission fluid. R-16

Parts	Quantity
-------	----------

**Task performed:**

drive to location where trucks inop; trans code 46-21-relay bad; have their swapout; bring truck back to Stn. j

NO PARTS USED

**Workorder: V21082**

In Date: 02/12/2009      Meter Reading: 101,509.70  
Close Date: 03/06/2009

**Problem?**

REPAIR TRANSMISION SR 1

Parts	Quantity
-------	----------

**Task performed:**

NO PARTS USED

Vendor? FL DETROIT

**Workorder: V21967**

In Date: 03/20/2009      Meter Reading: 101,509.70  
Close Date: 03/27/2009

**Problem?**

A Inspection and related repairs

Parts	Quantity
-------	----------

**Task performed:**

1. A-Inspection. 2. Pressure test coolant sys. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V22823**

**In Date:** 04/27/2009  
**Close Date:** 05/04/2009

**Meter Reading:** 102,832.00

**Problem?**

A inspection and related repairs (from 43)

**Task performed:**

1. Perform "A" svc. 2. Replcd wiper blades. j

Parts

Quantity

52-24WIPER BLADES ANCO 24

2



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder:** V22267

**In Date:** 04/02/2009

**Meter Reading:** 102,213.30

**Close Date:** 05/07/2009

**Problem?**

C inspection and related repairs

**Task performed:**

C-Inspection 2. Tightened all body door latches. 3. Both siren speakers ok; light out in head. 4. Added ATF 5. Replaced (2) A/C vents 6. replcd msgng O2 wrench. 7. Replcd bulb in traffic advisor. 8. Replcd worn compt hold open. 9. Replcd sharps cover. 10. Replcd drawer slices in O2 drawers. 11. Rem rubber lock from side window; clnd/installed. 12. R/R seats for repair. 13. Replcd o-rings in electric motor for brake booster. 14. Repl cd msgng cab spotlight. 15. Rep drivers door steplight; R/R switch 16. Replcd exterior door handles on cab. 17. Installed tires to proper PSI 90. 18. Sec loose fitting at tank. j

Parts

Quantity

15W40BSYN OIL BULK QTS	24
6807600070HANDLE DOOR EXT L/H	1
6807600170HANDLE DOOR EXT. R/H	1
6808300074VENT A/C LH	1
6808300174VENT A/C RH	1
91823SWITCH SWT5499 MED MASTER	1
AS75807OXM1757-01 OXYGEN WRENCH	1
ASL-2770932O-RING POWER BOOSTER	2
CA8193AIR FILTER 46744 WIX	1
DOOR2LEXAN 14.5 X 8.5	1
GSS1717UL1717UL0270N 343/09 GAS SHOCK 60 LB	2
H20SN12H20SN12 BULB	1
HLD3999GSS1715UV 30LB STRUT GAS	4
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1
SLD5366HT4932-16 DRAWER SLIDE 16	2
TRANSYNDALLISON TRANS FLUID GAL	1



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V22515**

In Date: 04/13/2009  
Close Date: 05/08/2009

Meter Reading: 102,213.30

**Problem?**

repair allison trans sr1

Parts

Quantity

**Task performed:**

Repair SR1 - Allison Trans j

NO PARTS USED

Vendor? ALLISON TRANS

**Workorder: V22501**

In Date: 04/13/2009  
Close Date: 05/11/2009

Meter Reading: 102,213.30

**Problem?**

repair 2 seats (outside agency-central auto trim)

Parts

Quantity

**Task performed:**

Repair (2) seats - Central Auto Trim j

NO PARTS USED

Vendor? CENTRAL AUTO TRIM





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10142536 FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V23138**

In Date: 05/07/2009      Meter Reading: 103,304.40  
Close Date: 05/18/2009

**Problem?**

A inspection and related repairs (from 31)

**Task performed:**

A-Inspection 2. Inflate all (6) tires to proper level - 100 PSI frt; 110 PSI rear. 3. Rep (3) rocker switches on panel in pat compt. 4. Tighten bolts on (3) L/S door holdopens; bolts on L/S compt over wheel stripped; rem bolts install nut zerts; reassemble. 5. Sweep out & cln pat compt of rescue & throw out old papers on dashboard. j

Parts	Quantity
SWT5492744435 ACTUATOR-BLACK	3

**Workorder: V23811**

In Date: 06/03/2009      Meter Reading: 103,304.40  
Close Date: 06/18/2009

**Problem?**

A inspection and repairs (from 34)

**Task performed:**

Perform A-Inspection j

Parts	Quantity
NO PARTS USED	

**Workorder: V24124**

In Date: 06/16/2009      Meter Reading: 103,304.40  
Close Date: 06/23/2009

**Problem?**

patient a/c innop R17

**Task performed:**

Go to Stn17; T-shoot rear A/C inop; rep bad connection in control panel. j

Parts	Quantity
NO PARTS USED	



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

**10142536**  
**FL60 ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V24211**

In Date: 06/19/2009      Meter Reading: 8,192.00  
Close Date: 07/02/2009

**Problem?**

patient compartment shoreline a/c not blowing cold R17

Parts	Quantity
-------	----------

**Task performed:**

110 A/C chk low on freon; charge sys; chk for leaks; no leak detected or visable; operate sys temp; drop to 30 degrees; operating normal. j

NO PARTS USED

**Workorder: V24212**

In Date: 06/19/2009      Meter Reading: 8,192.00  
Close Date: 07/02/2009

**Problem?**

O2 system leak, fairly substantial, lost 1500+ psi in approx. 36 hours. R17

Parts	Quantity
-------	----------

**Task performed:**

Dia of O2 sys; chi all connection, fittings with use fof shop tank; no leak cld be fnd at this time. j

AS75807OXM1757-01 OXYGEN WRENCH	1
---------------------------------	---

**Workorder: V24214**

In Date: 06/19/2009      Meter Reading: 8,192.00  
Close Date: 07/02/2009

**Problem?**

shoreline autoejector does not eject power cord when truck started, does make noise, but cord stays attached. R17

Parts	Quantity
-------	----------

**Task performed:**

Chk opns of aut-eject; sys works as intended; couldn't get sys to fail. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V24383**

**In Date:** 06/26/2009      **Meter Reading:** 103,627.80  
**Close Date:** 07/02/2009

**Problem?**

A inspection and repairs (from 17)

Parts	Quantity
-------	----------

**Task performed:**  
road test & A-Inspection j

NO PARTS USED

**Workorder: V25271**

**In Date:** 08/04/2009      **Meter Reading:** 104,629.00  
**Close Date:** 08/25/2009

**Problem?**

A/C INOP, R-45

Parts	Quantity
-------	----------

**Task performed:**  
1. Cab A/C inop; recharged cab A/C & tested. 2. Rear door window loose; rep window that was falling out. j

NO PARTS USED

**Workorder: V25556**

**In Date:** 08/16/2009      **Meter Reading:** 8,390.20  
**Close Date:** 08/25/2009

**Problem?**

Air suspension has a leak. R45

Parts	Quantity
-------	----------

**Task performed:**  
Air leak; fitting to air gov bad; replc fitting @ starter. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V25958**

In Date: 09/01/2009      Meter Reading: 105,839.30  
 Close Date: 09/14/2009

**Problem?**

tow unit to fla detroit sisters

Parts	Quantity
-------	----------

**Task performed:**

Tow unit to Fla Detroit - Sisters j

NO PARTS USED

Vendor? SISTERS TOWING

**Workorder: V26104**

In Date: 09/08/2009      Meter Reading: 106,040.80  
 Close Date: 09/17/2009

**Problem?**

ON CALL R45 A/C 10-7

Parts	Quantity
-------	----------

**Task performed:**

Fnd bare wire in pat A/C comp; taped up wire & clnd dirty evap coil. j

NO PARTS USED

**Workorder: V26125**

In Date: 09/08/2009      Meter Reading: 106,040.80  
 Close Date: 09/21/2009

**Problem?**

There is a leak in the air dumping system R45

Parts	Quantity
-------	----------

**Task performed:**

1. Chk for air leak; write up; chkd air sys; all ok. 2. Cab A/C inop - low refrigerant; fnd discharge Shrader stuck & leaking; recharged sys. 3. Pat comp A/C inop; unknown; chkd our A/C; all connector fans wiring switch, etc.; all ok at this time. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V26812**

In Date: 10/12/2009      Meter Reading: 106,389.60  
 Close Date: 10/21/2009

**Problem?**

ON CALL ALT 10-7 R45

**Task performed:**

Low voltage warning; replcd alternator. j

Parts	Quantity
4867JB320 UPGRADE ALTERNATOR	1

**Workorder: V26966**

In Date: 10/19/2009      Meter Reading: 107,539.90  
 Close Date: 11/12/2009

**Problem?**

PROGRAM NODE T0 DEFAULT A/C ON R45A

**Task performed:**

1. Reprogram node to default A/C on. 2. Rep stretcher latch. j

Parts	Quantity
NO PARTS USED	

**Workorder: V27436**

In Date: 11/05/2009      Meter Reading: 107,657.10  
 Close Date: 11/20/2009

**Problem?**

A inspection and repairs

**Task performed:**

A-Inspection 2. Replc dome lite. 3. Fnd wig-wag lts not working on rt side; ck for wigwag flasher; ck wiring; fnd node #1 bad. R/R node; programmed new node; ck opn; ck ok; reinstalled all panels. j

Parts	Quantity
600000003NODE HERCULES V-MUX	1
921LIGHT BULB	1
H6054USE CV TYPE SEALED BEAM	1



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V27774**

**In Date:** 11/18/2009  
**Close Date:** 11/30/2009

**Meter Reading:** 107,657.10

**Problem?**

draws tracks bad R39

**Task performed:**

R/R draw tracks on med \_\_\_\_\_ box; R/R O2 wrench; go over E11 panel w/driver. j

Parts	Quantity
2220-10SLIDE 10 IN	2
AS75807OXM1757-01 OXYGEN WRENCH	1
SLD5366HT4932-16 DRAWER SLIDE 16	2

**Workorder: V27779**

**In Date:** 11/18/2009  
**Close Date:** 11/30/2009

**Meter Reading:** 107,657.10

**Problem?**

coolant leak R39

**Task performed:**

1. Dia coolant leak; fnd air compressor NG; rem compressor switch over fitting & P/S pump; install compressor; recharge A/C sys. 2. Rebuild AD-9 air dryer; road test vehicle. j 3. Coolant coming out of air dryer purge valve; air compressor head gskt leaking; spare brought to them to swap. j

Parts	Quantity
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
284358GOVERNOR D-2	1
3929751GASKET AIR COMPRESSOR	1
4946293RXCOMPRESSOR BRAKES	1
800405PURGE VALVE KIT	1
F4HT3K506AA154916 P.S. GASKET CUMMINS ISB	1



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

**10142536**

**FL60 ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V28110**

In Date: 12/03/2009      Meter Reading: 107,731.60  
 Close Date: 12/17/2009

**Problem?**

UNIT LEANS TO LEFT SR AT SO 19

Parts	Quantity
-------	----------

**Task performed:**

1. Unit leans to the left; level valve out of adj; adj leveling valve. 2. Air leak - fittings on gov replaced. j

NO PARTS USED

**Workorder: V28126**

In Date: 12/04/2009      Meter Reading: 8,694.00  
 Close Date: 12/17/2009

**Problem?**

drivers side rear suspension bag will not inflate (This is 1 of 2 rescues that special ops19 is using)

Parts	Quantity
-------	----------

**Task performed:**

Drive to Stn19; reset air susp. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10142536 FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V28325**

**In Date:** 12/14/2009  
**Close Date:** 01/11/2010

**Meter Reading:** 107,731.60

**Problem?**

A inspection and repairs (from 19)

**Task performed:**

A-Inspection 2. R/R F/S rear strobe in rear light bar; R/R center strobe in front/light bar; lens frzn to light bar; had to cut to get lens out. 3. Rem compt L-3 hold open-screws stripped; drill new holes & install nut serts. 4.R/R R/S lower fuse panel cvr; clear/reinstall A/C drain hose thru hole in cab floor. 5. Pat low beam not working; fnd wiring problem; R/R fixture; re; hot wire to low beam. 6. Adj door latch on elec access door below drivers door in cab. 7. Install Nader pin protection cvrs; drill (4) holes; countersink (4) holes; drill (4) holes in trk body mnt protectors. 8. Fnd a docking stn in med area behind jump seat; rem frm veh & give to radio shop. 9. R/R air pack brckt in jump seat; rework w/new clips & new lcn; R/R (2) air pack brkts in compt L-2; rework brkts w/new clips in new lcn for new air bottles.

Parts	Quantity
02036317300STROBE LINEAR REFLECTOR 6ELTUBI	2
322502BULB PATIENT GH22	1

**Workorder: V28823**

**In Date:** 01/05/2010  
**Close Date:** 01/26/2010

**Meter Reading:** 108,004.60

**Problem?**

no heater in patient compt. R26

**Task performed:**

Went to Stn26; opened both manual heater control valves; ran heater; ck opn-ck ok; returned to shop. j

Parts	Quantity
NO PARTS USED	





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10142536 FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V29105**

**In Date:** 01/13/2010  
**Close Date:** 02/08/2010

**Meter Reading:** 108,646.30

**Problem?**

**B INSPECTION AND REPAIRS AS NEEDED SR4**

**Task performed:**

B-Inspection 2. Rep flat tire. 3. Replcd strobe bulb. 4. Replc door light. 5. Reset rear doow window molds X 2. 6. Replc btrys X 4. 7. Replc frnt brake pads, left & right. 8. Replc rear brake pads. 9. Replc wiper blades. 10. Replc compressor hose. 11. Replcd belt tensioners. 12. Replc heater control cable. 13. Replc O2 gauge hold strap. 14. Tine all cable pins door. 15. Replcd siren head. j

**Parts**

**Quantity**

01-0862064-00SIREN FRONT SIDE	1
15W40BSYN OIL BULK QTS	28
22-49905-000CABLE HEATER	1
3944427INTAKE HOSE NEW #3949710	1
39768315259022 GROOVED TENSIONER OLD#39:	1
4020362171 GRO LAMP DOME 4 IN	1
52-24WIPER BLADES ANCO 24	2
ACX-84534LUG NUT COVER PK10	10
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
HP-31DBATTERY 950CCA HP-31D	4
L1261F33585XE FUEL FILTER WIX	1
MG-C23SPMGC23 GAUGE	1
MK184HDBRAKE PADS	2
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1
TURBO5TUBE - STROBE	1
UMVS162511STRAP	2



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

**10142536**

**FL60 ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V26627**

In Date: 10/01/2009      Meter Reading: 8,550.00  
 Close Date: 04/14/2010

**Problem?**

The driver side batcom control panel is unable to close.

Parts	Quantity
-------	----------

**Task performed:**

NO PARTS USED

**Workorder: V31383**

In Date: 04/09/2010      Meter Reading: 108,646.30  
 Close Date: 04/27/2010

**Problem?**

A/C blows warm sr1

Parts	Quantity
-------	----------

**Task performed:**

Replc Schrader valve. j Charge A/C sys; adj heater control valve. j

6808300174VENT A/C RH	2
-----------------------	---

**Workorder: V32095**

In Date: 05/10/2010      Meter Reading: 109,216.20  
 Close Date: 05/21/2010

**Problem?**

Check patient compartment A/C.

Parts	Quantity
-------	----------

**Task performed:**

Went to 46; FF's were able to get A/C on; no problem j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10142536 FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V32439**

In Date: 05/26/2010 Meter Reading: 109,942.60  
Close Date: 05/28/2010

**Problem?**

on call compt door 10-7 r46

Parts ----- Quantity

**Task performed:**

Rear door inop; linkage clip brkn; rep rear door. j

NO PARTS USED

**Workorder: V32440**

In Date: 05/26/2010 Meter Reading: 109,942.60  
Close Date: 05/28/2010

**Problem?**

AIR BAGS LEAKING SR AT 46

Parts ----- Quantity

**Task performed:**

1. Assist on air bags. 2. Air leak - pin holes in air bags; replc air bags. 3. Rear door inop; linkage clip brkn; rep rear door. Time for door repair is continued from on-call after hours. j

16-15762-00016-19471-000 AIR BAG 2

**Workorder: V32022**

In Date: 05/05/2010 Meter Reading: 108,646.30  
Close Date: 06/04/2010

**Problem?**

Truck now at Station 46. Rear shoreline A/C in pt compt not cooling. R46

Parts ----- Quantity

**Task performed:**

1. Half of light bar inop; rep bad grd. 2. Rear A/C inop; recharged unit. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V27631**

In Date: 11/13/2009  
Close Date: 07/13/2010

Meter Reading: 107,657.10

**Problem?**

cab warning lt on q57

Parts	Quantity
-------	----------

**Task performed:**

Verified job j

NO PARTS USED

**Workorder: V33068**

In Date: 06/22/2010  
Close Date: 07/20/2010

Meter Reading: 109,942.60

**Problem?**

passenger rear cab door has broken door handle R41

Parts	Quantity
-------	----------

**Task performed:**

replcd side rear box door handle. j

HND5948TM22676-02 HANDLE DOOR ENTRY	1
-------------------------------------	---

**Workorder: V33500**

In Date: 07/12/2010  
Close Date: 07/22/2010

Meter Reading: 111,128.00

**Problem?**

Emergency strobe light on the driver side of hood is out R41

Parts	Quantity
-------	----------

**Task performed:**

R/R I/FRNT STROBE LIGHT OUT; REPLC W/NEW UPDATED LIGHT.

02-0383470-CROBSOLETE LENS RED/CLEAR	1
508RED58EC20RU STROBE-RED SURFACE MOUNT	1



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V33780**

**In Date:** 07/25/2010      **Meter Reading:** 112,399.90  
**Close Date:** 08/18/2010

**Problem?**

Front ac not working properly. Bay A/C power cord does not eject when truck is started. r41

<u>Parts</u>	<u>Quantity</u>
--------------	-----------------

NO PARTS USED

**Task performed:**

1. A/C inop; rep condensor fans that had bad grd. 2. Rear door hard to open; adj rear door latch. 3. Air leaks-fnd no leaks. ja

**Workorder: V34451**

**In Date:** 08/23/2010      **Meter Reading:** 109,216.20  
**Close Date:** 09/08/2010

**Problem?**

patient A/C innop (callout repair)

<u>Parts</u>	<u>Quantity</u>
--------------	-----------------

NO PARTS USED

**Task performed:**

Pat A/C warm; sys low on charge; charged sys until pat A/C ablowing cold. j

**Workorder: V34475**

**In Date:** 08/24/2010      **Meter Reading:** 113,795.40  
**Close Date:** 09/08/2010

**Problem?**

on call broke down at bethesda hospital r43

<u>Parts</u>	<u>Quantity</u>
--------------	-----------------

NO PARTS USED

**Task performed:**

UP44 pump bad; need to switch out; tow to shop. j



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V34176**

**In Date:** 08/11/2010  
**Close Date:** 09/09/2010

**Meter Reading:** 113,371.50

**Problem?**

Right front headlight is out. R41B

Parts

Quantity

**Task performed:**

1. installed new headlight. 2. Chkd for A/C problem; fnd condensor fans were not working; rep connection. j

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V34639**

**In Date:** 08/31/2010  
**Close Date:** 09/29/2010

**Meter Reading:** 114,139.00

**Problem?**

C inspection and repair as needed sr 1 REPAIR FUEL SYSTEM

Parts

Quantity



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Task performed:**

1. Rem VP44 fuel pump & trans pump; replc trans pump & installed Rema VP44. 2. Started C-Inspection. 3. Svc rear diff. 4. Replc drag link. 5. Svc air dryer. Had Mike Lehan look at pin bushings; will not rep at this time; wi monitor. 7. Replc msng bolt for fender support; had to rep thrds to install bolt. 8. Recharged 110V A/C sys. 9. Fab brkt for O2 bottle. 10. Replcd P/S pump; flushed completed sys due to eng oil contamination. 11. Rep sign brkt. 12. Sec door striker L-2 compt. 13. Replc door seals. 14. Replc ra cap. 15. Replc brake pedal pad. 16. Rplcd light & door switch L-1 compt. 17. Rep wiper blades. 18. Painted fuel cap. 19. Polished strobe lens on frt of truck. 20. Sec compt door inner skins. 21. Replcd door switch in L-3 compt for compt light. 22. Replc holdopen L-4 compt. 23. Replcd LR side body marker/signal light. 24. Replcd pat compt dome light bulbs. 25. Replcd bio hazrd drawer slides. 26. Replcd stretcher latch; drilled stripped bolts out. 27. Sec/adj mirrors. 28. Rep windshield wtr nozzle. 29. Rep frt closure light. 30. Replc/wired door ajar light 31. Rep non-skid tape on step 32. Rebuilt/adj air horns. 33. Adjust tire pressures. j

05-17223-000CAP RADIATOR 10 LB	1
090-0278STRECHER BAR NEW	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1094KIT-AIR HORN-GROVER	2
14-14407-001P/S PUMP	1
1549164988280 GASKET P/S PUMP TO AIR COMP	1
15W40BSYN OIL BULK QTS	16
2220-10SLIDE 10 IN	2
322502BULB PATIENT GH22	2
367280HOSE ASSY	1
3935032O-RING ISB	1
3963983WASHER SEAL ISB	4
3963988WASHER SEAL	4
3964555RXFUEL PUMP ISB	1
3969988GASKET CONNECTION ISB	2
39901054943048 FUEL PUMP ISB	1
40202RT/L#40202R RED TAIL LIGHT	1
4020362171 GRO LAMP DOME 4 IN	1
50R00FRRFLASHER RED LED FLANGED	1
52-24WIPER BLADES ANCO 24	2
6806970098SEAL DOOR	1
68129100826812910082 BRAKE PEDAL	1
800405PURGE VALVE KIT	1
A1414374000DRAG LINK RESCUE	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
FREIGHTSHIPPING CHARGES	20
FSC17492134NC SW PARK BK SPADE TYPE CONNE	1
HLD374211 IN HOLD-OPEN 30LB	1
L1261F33585XE FUEL FILTER WIX	1





4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

LTC5993SSM1-63-8 LATCH STAINLESS	1
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1

**Workorder: V32976**

In Date: 06/17/2010      Meter Reading: 109,942.60  
 Close Date: 10/04/2010

**Problem?**

r41 bravo, radios in the rescue do not key up. incoming traffic works with no issue gave to radio shop 6/18/2010 mpl

Parts	Quantity
-------	----------

**Task performed:**

NO PARTS USED

**Workorder: V32316**

In Date: 05/19/2010      Meter Reading: 109,216.20  
 Close Date: 10/19/2010

**Problem?**

air leak R46

Parts	Quantity
-------	----------

**Task performed:**

completed j

FSC17492134NC SW PARK BK SPADE TYPE CONNE	1
---	---



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V36284**

In Date: 11/08/2010      Meter Reading: 114,452.00  
 Close Date: 12/08/2010

**Problem?**

Front A/C is blowing hot. Grinding noise from front axle when turning the wheel. SR AT 39

<u>Parts</u>	<u>Quantity</u>
--------------	-----------------

**Task performed:**

1. A/C blowing warm; recharged sys & rep leak. 2. Noise in frnt end; road tested; fnd no noise in frnt end. j

NO PARTS USED

**Workorder: V34877**

In Date: 09/11/2010      Meter Reading: 113,795.40  
 Close Date: 12/22/2010

**Problem?**

Red lens cover on passenger side rear emergency light fell off. Need new red lens cover. R41

<u>Parts</u>	<u>Quantity</u>
--------------	-----------------

**Task performed:**

(1) REAR EMERGENCY LIGHT PASSENGER SIDE MISSING RED LENS; R41 REPLACED RED LENS COVER.

NO PARTS USED

**Workorder: V35188**

In Date: 09/26/2010      Meter Reading: 113,795.40  
 Close Date: 12/22/2010

**Problem?**

Spot light on top of rescue is out. r41

<u>Parts</u>	<u>Quantity</u>
--------------	-----------------

**Task performed:**

FIXED CONNECTION ON SPOT LIGHT CONTROLER.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V37295**

In Date: 12/20/2010  
Close Date: 01/12/2011

Meter Reading: 114,792.00

**Problem?**

A INSPECTION BACK FROM 93

Parts

Quantity

**Task performed:**

A-Service. 2. Load tested btrys to chk amp output; all tested normal. 3. Ad air bags to level out rear of truck. 4. T-shoot rotators in light bar inop; traced problem to shorted wiring harness inside body; splice shorted ckts into adjacent ckt; all lights now working. j

68118206050BEND CAP RED SUPER ADV.PLUS LT.E
---

1



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V37897**

**In Date:** 01/19/2011  
**Close Date:** 01/31/2011

**Meter Reading:** 114,792.00

**Problem?**

**A INSPECTION**

**Task performed:**

1. Road test & A-Inspection 2. A/C cab 10-7; dia fault; fnd clutch lock up; replc A/C compressor, dryer & expansion valve. 3. A/C operating intermittly; dia fault; fnd control switch wire burnt; clip ends & replc connector. 4. Pat compt A/C filter clogged; rem/install new filter. 5. Driver window modling brkn; rem/install new molding. 6. Loose cables on floor officers side; secure electrical cables. 7. L-2 door guard & weatherstrip msng; cln area & install replacement srip. 8. Install new A/C c ompressor charge sys; operate sys press hi-side \_\_\_ lo-side normal not cycling. 9. T-shoot A/C problem; traced problem to faulty radiator fan relay; replcd relay A/C & fan opn now normal. 10/ Completed installation of A/C cntrl in dash; (started by Ma). 11. T-shoot door adjar warning light on; traced problem to faulty btry compt sensor; replcd sensor; alarm now works normally. j

Parts	Quantity
1501450007750USE 0775145	1
160012-2012A EXPANSION VALVE 71R8301	1
22512960001498 SWITCH BINA	1
23-11345-710SCREW DASH	4
3505300C1RELAY	1
404-100 VALVE CORE	2
440-5 VALVE EXT.	4
532703-0602 COMPRESSOR U4735 4471	2
716907-0610A DRYER	1
A1834388002MOLD L/H	1
A22451940011499 SWITCH A/C HIGH PRESSURE NC	1
ABPN83322930CONTROL HEAD AC/HEAT	1
FREIGHTSHIPPING CHARGES	15
KN20901KN20901 KNOB PARKING BRAK	1
RN60JDRYER KIT	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10142536 FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V38616**

In Date: 02/18/2011 Meter Reading: 114,993.00  
Close Date: 03/07/2011

**Problem?**

A INSPECTION SR1

**Task performed:**

1. A-Inspection 2. Chk for A/C leak; fnd lo-side fitting on compressor max-fold leaking; install new o-ring & tighten; C/O ok. 3. Tighten & adj all nader pins. j

Parts ----- Quantity -----

NO PARTS USED

**Workorder: V39257**

In Date: 03/16/2011 Meter Reading: 115,434.20  
Close Date: 03/18/2011

**Problem?**

R451 needs a new placard for both sides of the truck, it still has R45 instead of the R451. Can we get the 451 placards made for the rescue please...

**Task performed:**

1. travel to c/shop pick up placards, travel to sta-45, rescue not in station, gave placards to R. HOCH and was told he would install when rescue returned.

Parts ----- Quantity -----

L PLACARDLARGE SIDE PLACARD	2
L PLACARD INSERTLARGE PLACARD INSERT CAR	2
S PLACARDFRONT AND BACK PLACARD	2
S PLACARD INSERTFRONT AND BACK INSERT CAR	2

**Workorder: V39297**

In Date: 03/19/2011 Meter Reading: 115,891.10  
Close Date: 03/28/2011

**Problem?**

biohazard drawer will not latch. R73

**Task performed:**

1. Travel to Stn73; R/R bio door latch & adj latch ok. 2. Travel to Stn73; horns low; adj horns. j

Parts ----- Quantity -----

LTC5993SSM1-63-8 LATCH STAINLESS	1
----------------------------------	---



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V39392**

**In Date:** 03/23/2011      **Meter Reading:** 115,976.00  
**Close Date:** 03/28/2011

**Problem?**

the a/c up front is blowing warm/hot, sta 73.

**Task performed:**

travel to Stn73; C/O A/C; chk freon; add to test for leaks; still not cold; chk h-block cores btwn fans; fnd heater valve bypassing; adj heat cntrl cable; ok for now. j

Parts ----- Quantity

NO PARTS USED
---------------

**Workorder: V39160**

**In Date:** 03/14/2011      **Meter Reading:** 115,794.00  
**Close Date:** 03/29/2011

**Problem?**

B INSPECTION

**Task performed:**

B-Inspection 2. Svc cooling sys. 3. Svc P/S; sys still has oil frm prev repair; flush sys w/fresh fluid. 4. R/R belts. 5. Rep entry lights on cab doors; fnd faulty wiring at \_\_\_\_\_. 6. Reattach gskt under hood above firewall. 7. Wiper washer inop; fnd corrosion on wire to motor; clnd wiring; pump working. 8. Shim slides brkn; R/R slides & to drive new mntng & mk adjustments for drawer to work porperly. j

Parts ----- Quantity

15W40BSYN OIL BULK QTS	16
5632-1010 IN DRAWER SLIDES PR	2
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V39274**

**In Date:** 03/17/2011      **Meter Reading:** 115,891.10  
**Close Date:** 04/01/2011

**Problem?**

the frame that holds the unit designation tag/sign on the side of the truck broke and one side fell off. The truck no longer is able to support and ID tag on the drivers side. SR at 73

Parts ----- Quantity -----

**Task performed:**

Travel to 73; C/O #plate holder brke off; R/R holder #plate is too wide; needs to trim to fit; isntall new style plate sys & #plate; mk up new #. j

L PLACARDLARGE SIDE PLACARD	1
L PLACARD INSERTLARGE PLACARD INSERT CARL	1

**Workorder: V39505**

**In Date:** 03/28/2011      **Meter Reading:** 1,162,690.00  
**Close Date:** 04/13/2011

**Problem?**

LEFT FRONT HEADLIGHT OUT R73

Parts ----- Quantity -----

**Task performed:**

Travel to Stn73; R/R headlight. j

H6054USE CV TYPE SEALED BEAM	1
------------------------------	---

**Workorder: V39287**

**In Date:** 03/18/2011      **Meter Reading:** 115,891.10  
**Close Date:** 04/14/2011

**Problem?**

A bolt holding the back support at the hinge point broke. The stretcher should be taken out of service until repaired. R73 Repair stretcher (outside agency-medco equipt. repair)

Parts ----- Quantity -----

**Task performed:**

Rep stretcher - Medco j

NO PARTS USED	
---------------	--

**Vendor?** MEDCO



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V39842**

In Date: 04/11/2011      Meter Reading: 116,991.60  
 Close Date: 04/22/2011

**Problem?**

shoreline power plug eject mode does not function when uint is truned on R73

Parts	Quantity
-------	----------

**Task performed:**

Dia auto-eject; R/R auto-eject asy. j

NO PARTS USED

**Workorder: V39991**

In Date: 04/18/2011      Meter Reading: 117,153.00  
 Close Date: 04/25/2011

**Problem?**

A inspection (from 73)

Parts	Quantity
-------	----------

**Task performed:**

A-Inspection 2. Adj tire press. 3. Add 1-1/2 qts eng oil. 4. Replc w/washer reservoir door latch attaching brkt & screw. 5. Dia 110V A/C sys not cold; discharge evac & recharge sys. j

0915520120AUTO EJECT 20 AERO OTL3925	1
5531R12 CAP 1/4	2

**Workorder: V40338**

In Date: 05/02/2011      Meter Reading: 117,271.00  
 Close Date: 05/04/2011

**Problem?**

A inspection.

Parts	Quantity
-------	----------

**Task performed:**

A-Inspection 2. Rep latch on squad bench. 3. Replc faulty A/C vent. j

6808300174VENT A/C RH	1
-----------------------	---





4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

**10142536**  
**FL60 ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V40869**

In Date: 05/25/2011  
Close Date: 06/07/2011

Meter Reading: 117,391.00

**Problem?**

A inspection.

**Task performed:**

A-Inspection 2. R/R parking brake light in overhead. 3. Tighten rear jump seat. 4. Cln old tape off placard holder; reinstall new double sided tape. j

Parts	Quantity
HA141LIGHT RED WARNING	1

**Workorder: V39803**

In Date: 04/08/2011  
Close Date: 06/13/2011

Meter Reading: 1,162,690.00

**Problem?**

Auto eject for the shoreline plug does not function. As a result the shoreline plug has been broken several times. Sta.73.

**Task performed:**

work completed on WO 39842

Parts	Quantity
NO PARTS USED	

**Workorder: V41155**

In Date: 06/06/2011  
Close Date: 06/17/2011

Meter Reading: 25,629.00

**Problem?**

patient compartment a/c broken.

**Task performed:**

T-shoot A/C inop; fnd bad switch; did not have new switch; took switch apart & resoldered wires; C/O ok. j

Parts	Quantity
SWT54918SW ROCKER DPDT RED/AMBER	1
SWT54925ACTUATOR-GREY	1



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V41581**

In Date: 06/24/2011  
Close Date: 09/08/2011

Meter Reading: 25,629.00

**Problem?**

A inspection.

**Task performed:**

Start A-Inspection on veh. 2. R/R dash panels; rep heat/AC cntrls/cables; rep brkn wires. 3. Add windshield washer fluid. 4. Rem fuse panel cvr in cab; move/secure all excess wiring harnesses; replc msng fastener; instal cvr correctly. 5. Rep car dome light. 6. Dia/rep windshield wipers; no hi/low opn; R/R switch. 7. R/R drawer slide tracks on drawer in pat area. 8 Rep dia port cvr under dash. j

Parts	Quantity
064615900006-46159-001 SWITCH WIPER	1
1156BULB	2
381 838 02 19DASH VENT	1
6808310398SEAL AIR DUCT	1
6809881078DZ STUD	1
72R311018-2640 VENT A/C NEW # 1719	1
SLD5366HT4932-16 DRAWER SLIDE 16	2

**Workorder: V43553**

In Date: 09/09/2011  
Close Date: 09/13/2011

Meter Reading: 117,401.00

**Problem?**

Replace tire Right front.

**Task performed:**

Replace tire right frnt - Boulevard j

Parts	Quantity
NO PARTS USED	

Vendor? BOULEVARD



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V43676**

In Date: 09/14/2011  
Close Date: 09/15/2011

Meter Reading: 117,401.00

**Problem?**

turbo inop.

Parts	Quantity
-------	----------

**Task performed:**

1. Travel to stn; A/C inop; Shrader valve stuck; replc & recharged; all tested for leaks - ok. 2. Air horn inop; poor contact at switch; rep air horn.  
j

NO PARTS USED

**Workorder: V43758**

In Date: 09/19/2011  
Close Date: 09/20/2011

Meter Reading: 117,556.00

**Problem?**

A inspection.

Parts	Quantity
-------	----------

**Task performed:**

a inspection patient compartment a/c filter dirty remove and install new filter

1501450007750USE 0775145	1
--------------------------	---

**Workorder: V43842**

In Date: 09/22/2011  
Close Date: 09/23/2011

Meter Reading: 117,401.00

**Problem?**

burnt oil smell and shore a/c inop.

Parts	Quantity
-------	----------

**Task performed:**

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V44050**

In Date: 09/30/2011  
Close Date: 10/05/2011

Meter Reading: 118,138.00

**Problem?**

A inspection.

**Task performed:**

a inspection repair rear entry light replaced both windshield squirters and adj drain ovrfull transmission, drive vehicle untill at operating temp and check trans level add 1 qt

Parts	Quantity
322502BULB PATIENT GH22	1
SPRGW2612WASHER NOZZLE W/RELIEF	3

**Workorder: V44231**

In Date: 10/08/2011  
Close Date: 10/21/2011

Meter Reading: 118,170.90

**Problem?**

red "passenger door ajar" light and alarm on while driving. made sure all doors were closed R41

**Task performed:**

repaired l-1 compt door switch

Parts	Quantity
NO PARTS USED	

**Workorder: V44726**

In Date: 10/27/2011  
Close Date: 11/02/2011

Meter Reading: 119,556.00

**Problem?**

A Inspection.

**Task performed:**

Perform A-Inspection j

Parts	Quantity
NO PARTS USED	



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V44691**

In Date: 10/26/2011  
Close Date: 11/07/2011

Meter Reading:

**Problem?**

rescue having trouble starting up. sounds like battery problem SR AT 41

Parts	Quantity
-------	----------

**Task performed:**

Fnd loose btry cable. j

NO PARTS USED

**Workorder: V45050**

In Date: 11/08/2011  
Close Date: 11/15/2011

Meter Reading: 119,622.00

**Problem?**

C INSPECTION AND REPAIRS SR1

Parts	Quantity
-------	----------

**Task performed:**

C-Inspection 2. Tires over inflated by 25 lbs; adj tire press to mfr specs. 3. Trans oil/filter svc schedule. 4. A/C 110 sys low on freon; charge sys; chk for leak - none fnd; operating at lo-side 70 PSI; hi-side 220 PSI; cabin temp 38F. 5. windshield wiper blade & fluid svc. 6. Washer fluid nozzle inop; rem nozzle, cln port holes; reinstall & operate. 7. Crankcase vent; venting excess oil; rem cln filter screen & reinstall. 8. Placard holder L/side falling off; rem, cln surface, cln card holder, install 2-sided tape & remnt. 9. Compt door panels loose; secure all loose screws. 10. Quality check - J. George j

15W40BSYN OIL BULK QTS	17
29526898 29548988 TRANS FILTER ALLISON	1
30-24WIPER BLADE	2
CA8193AIR FILTER 46744 WIX	1
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1
TRANSYNDALLISON TRANS FLUID GAL	5



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V45690**

In Date: 12/07/2011  
Close Date: 12/12/2011

Meter Reading: 119,914.80

**Problem?**

Hard starting, Sta 45

Parts	Quantity
-------	----------

**Task performed:**

repaired bad connection on starter

NO PARTS USED

**Workorder: V46104**

In Date: 12/27/2011  
Close Date: 01/03/2012

Meter Reading:

**Problem?**

medical compartment drawer off the track, Sta 45.

Parts	Quantity
-------	----------

**Task performed:**

replaced slides in med drawer

NO PARTS USED

**Workorder: V46269**

In Date: 01/04/2012  
Close Date: 01/13/2012

Meter Reading: 121,117.00

**Problem?**

Truck will not charge off shoreline - three different plugs were tried. Sta 45

Parts	Quantity
-------	----------

**Task performed:**

FOUND NO PROBLEM WITH CHARGER.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10142536 FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V46417**

**In Date:** 01/09/2012  
**Close Date:** 01/26/2012

**Meter Reading:** 121,614.50

**Problem?**

overheating. SR-1

**Task performed:**

1. travel to sta-45, check vehicle for overheating. found fan clutch wires broken, drive vehicle to s/shop 3. remove fan, and a/c belts, remove fan shroud, drain coolant, and remove fan and clutch, found 1 fan blade cracked, order new fan 4. install new fan clutch and new fan strap on new fan, install on engine reinstall fan shroud. install new a/c belts and adjust. refill coolant run engine to operating tempture, road test ok.

Parts	Quantity
473514139234FAN ASSBLY AIR LIGHT	1
9485BELT	1
996019FAN CLUTCH 680-200-06-26	1
A0516228002FAN STRAP	1

**Workorder: V48305**

**In Date:** 03/30/2012  
**Close Date:** 04/02/2012

**Meter Reading:** 122,508.00

**Problem?**

WONT START AT STA 42

**Task performed:**

1. mac was called to sta-42 to check for no start, had to hit starter with hammer, disconnect battery's, r&r starter, reconnect battery's start's ok 2. check u joint cap screws, all tight, found rear tire's down to the wear bars, ordered 4 new tires for rear

Parts	Quantity
11132766583 STARTER 28MT 5.9 10 TOOTH 104650	1



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V48388**

In Date: 04/03/2012  
Close Date: 04/03/2012

Meter Reading:

**Problem?**

a/c in the front does not work blows warm air SR AT 47

Parts	Quantity
-------	----------

**Task performed:**

1. check cab a/c found heater control valve cracked open, close valve a/c cold

NO PARTS USED

**Workorder: V48476**

In Date: 04/05/2012  
Close Date: 04/09/2012

Meter Reading: 122,508.00

**Problem?**

replace rear tires

Parts	Quantity
-------	----------

**Task performed:**

REPLACE REAR TIRES.

NO PARTS USED

Vendor? ELPEX

**Workorder: V48486**

In Date: 04/06/2012  
Close Date: 04/09/2012

Meter Reading: 122,508.00

**Problem?**

won't start at sta 42.

Parts	Quantity
-------	----------

**Task performed:**

DRIVE TO STATION 42 - RESCUE NOT STARTING - CHECK BATTERII ALL GOOD - CHECK STARTING SYSTEM FOUND STARTER HANGINC UP. START UNIT MOVE TO SHOP PARKING AREA.

NO PARTS USED





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10142536 FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V47465**

In Date: 02/21/2012  
Close Date: 04/11/2012

Meter Reading: 31,593.00

**Problem?**

A INSPECTION

**Task performed:**

1. A-INSPECTION. 2. CHECK PRESSURE BECAUSE COMPRESSOR WAS CYCLEINS FOUND LOW ADD 8 OZ. TWO TIME AND PRESSURE WERE GOOD AND A/C WAS COLD. 3. FOUND DRIVER SIDE WHEEL SEAL LEAKING REMOVE TIRE AND HUB TO REPLACE SEAL. CLEAN AND INSPECT BEARINGS REINSTALL BEARING AND ADJUST AND INSTALLED TIRE AND CHECK AIR PRESSURE TEST DRIVE.

Parts	Quantity
1229H4636LOCKRING WITH TABS	1
370047ASEAL 34387	1
ABPN8330101701-0604 3924 BLOWER A/C BOA 852	1
E-2436R002436 GASKET-REAR AXLE	1

**Workorder: V49526**

In Date: 05/22/2012  
Close Date: 06/04/2012

Meter Reading: 124,192.40

**Problem?**

Medical drawer in Rescue is falling from cabinet every time the brakes are applied with any force and has nearly struck the medic twice. It is the second drawer from the top. Please correct. at 41

**Task performed:**

REPAIRED DRAWER OF RESCUE.

Parts	Quantity
NO PARTS USED	



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V50472**

**In Date:** 06/29/2012  
**Close Date:** 07/02/2012

**Meter Reading:** 124,657.00

**Problem?**

A INSPECTION SR1

**Task performed:**

1. PERFORM "A" SERVICE.
2. REPLACED WIPER BLADES.
3. REPLACED TWO PATIENT COMPARTMENT DOME LIGHTS.
4. CLEANED DEBRIS FROM WINDSHIELD WASHER SQUIRTERS.
5. REPLACED WIPER CONTROL SWITCH ON DASH. (SEIZED).
6. REPLACED REAR BRAKE PADS.
7. REPLACED REAR BRAKE PADS.
8. REPLACED LEFT FRONT TIRE WITH USE TIRE FROM BUILDING 3. (WORN OUT).

Parts	Quantity
064615900006-46159-001 SWITCH WIPER	1
322502BULB PATIENT GH22	2
52-24WIPER BLADES ANCO 24	2
E-600013-3052 NUT	4
MK184HDBRAKE PADS	1

**Workorder: V51058**

**In Date:** 07/23/2012  
**Close Date:** 07/30/2012

**Meter Reading:** 124,657.00

**Problem?**

B INSPECTION OIL CHANGE SERVICES

**Task performed:**

- B INSPECTION OIL CHANGE SERVICES

Parts	Quantity
NO PARTS USED	

**Vendor?** OIL CHANGE SERVICES



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10142536 FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V51222**

In Date: 07/30/2012  
Close Date: 09/14/2012

Meter Reading: 124,657.00

**Problem?**

make repairs from b inspection SR 1

**Task performed:**

1. OIL PAN WET CHK TORQUE SPECS ON OIL PAN BOLT TORQUE TO 18 FT. 2. ENGINE MOUNT BOLTS TORQUE TO 92LBS AS SPECIFIED MANUEL MBE 900ENGINE. 3. P MEASURE WATCH UNIT TO FIND IOL LEAK OF ROAD TEST TO GET UNIT UP TO TEMP OF OPERATING P MEASURES NO EXCESSIVE LEAKS FOUND. 4. SECURE LOOSE SEA AIR SWITCH.

Parts

Quantity

NO PARTS USED

**Workorder: V52170**

In Date: 09/05/2012  
Close Date: 09/24/2012

Meter Reading: 125,228.30

**Problem?**

A INSPECTION SR1

**Task performed:**

1. A INSPECT 2. CHK A/C SYST WITH OLD SPAN-ON MACHINE. GOT A BOTTLE OF FREON AND CHARGED MACHINE RECOVER FREON FRON TRUCK, IT WAS LOW VACC AND CHARGER SYSTEM COOLED GOOD NO LEAK FOUND. 3. ASSIST W/ A/C MACHINE. 4. R&R SHOCKS MED COMP DOORS AND TIGHTEN UP SCREW ON HEAD SET.

Parts

Quantity

HLD3999GSS1715UV 30LB STRUT GAS

4



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142536

**FL60 ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V54461**

In Date: 12/17/2012  
Close Date: 12/17/2012

Meter Reading: 125,406.50

**Problem?**

ON CALL AIR LEAK R 56

**Task performed:**

TRAVEL TO ST 56 CHECK BIG AIR LEAK, REPLACE DRAIN VALVE ON REAR AIR TANK.

Parts

Quantity

NO PARTS USED

**Workorder: V54983**

In Date: 01/10/2013  
Close Date: 01/14/2013

Meter Reading: 126,430.30

**Problem?**

A inspection

**Task performed:**

1. A INSP 2. RIGHT WINDOW SQUIRTER WON'T SPRAY FROM BOTTOM. REMOVED WIPER BLADE AND CLEANED NOZZLE. TEST OK. 3. REMOVE DAMAGE BOLT FROM ELECTRICAL BRACKER FOR FAN CLUTCH. 4. REPLACE BELTS. 5. DIAGNOSE REAR A/C FOUND OIL ON FITTINGS BY HIGH SIDE COMPRESSOR. LEAK CHECK FITTINGS. REMOVE FREON AND CHARGE WITH HIDROGEN AND FREON.LEAK CHECK AGAIN FOND LEAK AT COMPRESSOR FITTING AND SPLICE. REMOVE SECTION OF HOSE AND FITTING FOR REPLACEMENT. 6. BRAKE ROTORS WORN DISHED. NOT TO BE REPAIRED AT THIS TIME PER STEVE REINES. WANTS 2 DOOR SPARE FOR WEEKEND. 7. LFT SIDE OF ENGINE OIL AND FIT COVER NOT TO BE REPAIRED PER STEVE REINES AT THIS TIME. 8. PRESSURE TEST SYSTEM AND WHEEL FOR COOLANT LEAKS TIGHTEN UPPER RADIATOR HOSE CLAMP. CHECK COMPRESSOR FITTING FOR LEAK (OK).

Parts

Quantity

426821HOSE & FITTING ASSY	1
9451BELT	1
9485BELT	1
K080733BELT	1



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V55553**

In Date: 02/05/2013  
Close Date: 02/07/2013

Meter Reading: 126,544.60

**Problem?**

siren inop, R-411

Parts	Quantity
-------	----------

**Task performed:**

1. check out siren, found speaker inop, install new speaker. had to modify speaker to housing.

SD-210RSIREN DRIVER	1
---------------------	---

**Workorder: V55736**

In Date: 02/12/2013  
Close Date: 02/12/2013

Meter Reading:

**Problem?**

A/C IN PATIENT COMPARTMENT NOT WORKING RIGHT BLOWING HO AIR. R400

Parts	Quantity
-------	----------

**Task performed:**

1. check pat. a/c, found low on freon. evacaute system and check for leak, found low pressure switch on compressor line loose and leaking tighten switch, refill system and recheck for leaks none found at this time.

NO PARTS USED	
---------------	--

**Workorder: V56170**

In Date: 03/05/2013  
Close Date: 03/05/2013

Meter Reading: 129,313.30

**Problem?**

r/side headlight inop, R-400

Parts	Quantity
-------	----------

**Task performed:**

1. check r/side headlight remove headlight, headlight assy. fell out of hooc reinstall adj. screws and assy. replace new headlight.

H6054USE CV TYPE SEALED BEAM	1
------------------------------	---



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V54688**

**In Date:** 12/29/2012  
**Close Date:** 03/16/2013

**Meter Reading:** 125,858.70

**Problem?**

R56 lost power steering

**Task performed:**

power steering hose worn through and leaking. came to shop for hose, went back to station and replaced.

Parts	Quantity
14-12743-000HOSE ASSY POWER STEERING	1
ALA00350-50 EXTENDED LIFE COOLANT GAL	3
TRANSYND-GGAL CONTAINER TRANS FLUID	1

**Workorder: V46738**

**In Date:** 01/21/2012  
**Close Date:** 04/03/2013

**Meter Reading:**

**Problem?**

R451's bay door opener is broken and will not open doors, sta 45

**Task performed:**

Parts	Quantity
NO PARTS USED	



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V56695**

**In Date:** 03/28/2013  
**Close Date:** 04/08/2013

**Meter Reading:** 130,470.00

**Problem?**

A-inspection

**Task performed:**

1. REPAIR FUEL LEAK AT FUEL FILTER HOUSING AND PRIME FUEL SYSTEM. 2. A-INSPECTION. 3. REMOVE FADED/DAMAGE ASSET TYAG AND INSTALL NEW TAG. 4. REAR LIGHT BAR ROTATOR INOP DISASSEMBLE LIGHT BAR - REMOVE ROTATOR ASSEMBLY - REMOVE BLOWN BULB AND LUBRICATE ROTATOR GEAR WITH ELECTRICAL GREASE. REASSEMBLE - OPERATE.

Parts	Quantity
3926759-SDRAIN KIT	1
H27SN12BULB	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10142536 FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V56757**

**In Date:** 04/01/2013  
**Close Date:** 04/17/2013

**Meter Reading:** 130,470.00

**Problem?**

C-inspection

**Task performed:**

1. C-INSPECTION. 2. SERVICE DRYER. 3. TIGHTEN FRONT COVER BOLTS. 4. ADJUST HOOD. 5. SWAP FRONT TIRES. 6. CHARGE 110V A/C. 7. START R&R ALL BRAKES AND ROTORS. 8. R&R REAR PADS AND ROTORS. 9. START R&R FRONT PADS AND ROTORS. 10. FINISH FRONT PADS AND ROTORS. 11. ADJUST AIR BAGS. 12. REINSTALL BOTH REAR DOOR UPPER WINDOW SEALS. 13. REPAIR BATTERY STATUS LIGHTS. 14. REPAIR CITY HORNS. 15. TEST DRIVE TRUCK.

**Parts**

**Quantity**

032-0116549297 BATTERY INDICATOR	1
07-14488-000DIPSTICK	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
370047ASEAL 34387	2
370150ASEAL	2
52-24WIPER BLADES ANCO 24	2
800405PURGE VALVE KIT	1
A0631117000HORN HIGH NEW # 06-52125-039	1
D6176M121-83014 ROTORS RESCUE	4
E-2436R002436 GASKET-REAR AXLE	2
E-600013-3052 NUT	2
L1261F33585XE FUEL FILTER WIX	1
MK184HDBRAKE PADS	2
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1





4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V57121**

**In Date:** 04/18/2013      **Meter Reading:** 131,014.90  
**Close Date:** 04/25/2013

**Problem?**

Flashlight mount is not working. Looks like it is broken and rotten. Need a new mount. R300 at ST 30

Parts	Quantity
-------	----------

**Task performed:**

TRAVEL TO 30 REPLACED CHARGER BASE FOR HAND LIGHT.

NO PARTS USED

**Workorder: V57721**

**In Date:** 05/14/2013      **Meter Reading:**  
**Close Date:** 05/20/2013

**Problem?**

Foul smell while vehicle running R300

Parts	Quantity
-------	----------

**Task performed:**

TRAVEL TO STATION 30 RD STATION.

BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER B/	4
HP-31D BATTERY 950CCA HP-31D	4

**Workorder: V57722**

**In Date:** 05/14/2013      **Meter Reading:**  
**Close Date:** 05/20/2013

**Problem?**

Passenger door difficult to open. R300

Parts	Quantity
-------	----------

**Task performed:**

ADJUSTED OFFICERS DOOR LATCH.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V57780**

In Date: 05/16/2013  
Close Date: 05/21/2013

Meter Reading: 13,288.10

**Problem?**

REPLACE STEER TIRES

Parts	Quantity
-------	----------

**Task performed:**  
REPLACE STEER TIRES.

NO PARTS USED

**Vendor?** ELPEX

**Workorder: V56289**

In Date: 03/10/2013  
Close Date: 05/29/2013

Meter Reading:

**Problem?**

air conditioning blowing only hot air in driver cab. Front air bottle storage on officer side on R400 is loose. There a 2 screws missin.g

Parts	Quantity
-------	----------

**Task performed:**  
RECHARGED SYSTEM AND REPAIRED LEAK.

NO PARTS USED

**Workorder: V58665**

In Date: 06/25/2013  
Close Date: 06/28/2013

Meter Reading: 135,362.10

**Problem?**

the parking brake indicator light does not comeon when the brake is applied, Also the truck shakes and some times pulles to one side. The air ir the pt compartment blows at best cool air. The truck should be retired. R300

Parts	Quantity
-------	----------

**Task performed:**  
1. TRAVEL TO 30 THE PARKING BRAKE LIGHT WIRES ARE CUT AND DISCONNECTED. TRUCK NEED TO BE REPAIRED AT SHOP. 2. REAC TESTED TRUCK DRIVES FINE. 3. RECHARGED A/C IN REAR UNIT.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V58374**

In Date: 06/12/2013      Meter Reading: 134,612.30  
 Close Date: 07/09/2013

**Problem?**

r300 is leaking oil and AC is only working on the highest setting.

**Task performed:**

REPLACED A/C SWITCH FOR BLOWER.

Parts	Quantity
ABPN8332229011-3050 SWITCH BLOWER	1

**Workorder: V59389**

In Date: 07/28/2013      Meter Reading: 137,412.00  
 Close Date: 07/31/2013

**Problem?**

Driver side head light out. No spare headlights at the station. R300

**Task performed:**

TRAVEL TO ST 30 R300 ON CALL LEFT STATION. A LIGHT WILL INSTALL LATER.

Parts	Quantity
H6054USE CV TYPE SEALED BEAM	2

**Workorder: V59435**

In Date: 07/30/2013      Meter Reading: 137,482.70  
 Close Date: 07/31/2013

**Problem?**

truck is approx 2 qts low on oil and we ran out of oil here at st30, also water was added to the radiator, and the head light was dropped off yesterday bu we dont have the tool to replace it (star tip screw head)

**Task performed:**

1. TRAVEL TO 30 ADDED OIL AND COOLANT TO RESCUE AND 2. REPLACED HEADLIGHT.

Parts	Quantity
NO PARTS USED	



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

**10142536**

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V59590**

In Date: 08/05/2013      Meter Reading: 137,482.70  
 Close Date: 08/07/2013

**Problem?**

Front cab A/C blowing warm air. R300

Parts	Quantity
-------	----------

**Task performed:**

CHECKED PRESSURE ON FT A/C FREON OK. CLEANED OUT CONDENSOR AND CHECKED TEMP OK.

NO PARTS USED

**Workorder: V59592**

In Date: 08/05/2013      Meter Reading: 137,482.70  
 Close Date: 08/08/2013

**Problem?**

in addition to WO # P60098 (Front cab A/C)... The rear pt compartment has insufficient A/C... R300

Parts	Quantity
-------	----------

**Task performed:**

Checked patient compt. a/c pressure's good. cleaned out condenser ok.

NO PARTS USED

**Workorder: V59604**

In Date: 08/05/2013      Meter Reading: 137,915.00  
 Close Date: 08/13/2013

**Problem?**

hand light inop. R300

Parts	Quantity
-------	----------

**Task performed:**

CHECKED LIGHTS REPLACED R/F HEADLIGHT.

H6054USE CV TYPE SEALED BEAM	1
------------------------------	---



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10142536 FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V59731**

In Date: 08/11/2013      Meter Reading: 138,199.20  
Close Date: 08/14/2013

**Problem?**

siren knob stripped and unable to turn. R300

Parts ----- Quantity -----

**Task performed:**

TRAVEL TO STATION 30 REPAIRED LOOSE KNOB FOR SIREN.

NO PARTS USED

**Workorder: V60085**

In Date: 08/26/2013      Meter Reading: 138,872.90  
Close Date: 08/30/2013

**Problem?**

coolant level below sight glass. no coolant in the station.

Parts ----- Quantity -----

**Task performed:**

DEREK DELIVERED TO STATION.

ALA00350-50 EXTENDED LIFE COOLANT GAL      2

**Workorder: V60223**

In Date: 09/02/2013      Meter Reading: 139,478.30  
Close Date: 09/05/2013

**Problem?**

Low voltage alarm. Rear radio not working. R300

Parts ----- Quantity -----

**Task performed:**

TRAVEL TO ST 30 CHECKED VOLTAGE ON R300 FOUND ALTERNATOR NOT CHARGING REMOVED ALTERNATOR AND FOUND BELT TENSIONER AND WATER PUMP BAD. CALLED SHOP FOR PARTS. REPLACED WATER PUMP, COOLANT, BELT TENSIONER, ALTERNATOR PULLEY AND ALTERNATOR TESTED SYSTEM OK.

3286278WATER PUMP ISB      1  
39258523925852 PULLEY      1  
39768315259022 GROOVED TENSIONER OLD#39      1  
ALA00350-50 EXTENDED LIFE COOLANT GAL      6  
EXO3AH00015SPLUG RAD. DRAIN      1



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

**10142536**

**FL60 ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V60408**

**In Date:** 09/10/2013      **Meter Reading:** 139,997.40  
**Close Date:** 09/10/2013

**Problem?**

check o2 leak and water leak

Parts	Quantity
-------	----------

**Task performed:**

TRAVEL TO ST 30 DRIVER COMPLAINT O2 LEAK AND COOLANT LEAK  
FOUND NO O2 LEAK AND FOUND HEAD GASKET LEAK ON ENGINE.

NO PARTS USED

**Workorder: V60530**

**In Date:** 09/16/2013      **Meter Reading:** 140,475.50  
**Close Date:** 09/24/2013

**Problem?**

Belt noise

Parts	Quantity
-------	----------

**Task performed:**

TRAVEL TO ST 39 CHECK OUT BELTS MAKING NOISE. BELTS LOOSE  
TRY TO ADJUST EARS BROKEN OFF COMPRESSOR AND METAL  
BKTS ARE BENDING NEEDS REPLACE SEND TO SHOP.

NO PARTS USED



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142536

**FL60 ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V61300**

**In Date:** 10/16/2013

**Meter Reading:** 124,900.50

**Close Date:** 10/24/2013

**Problem?**

Quality check back from Cummins

Parts

Quantity



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142536

**FL60 ADVANCED LIFE SUPPORT VEHICLE**

**Task performed:**

1. Q&A, REPAIR TIRE LEAK R FRONT REPLACED VALVE CORE AND AIR TO 90 PSI. 2. DIAGNOSE LF STROBE IN/OP - FOUND BAD CONNECTOR IN HARNESS. REPAIR CONNECTION TEST (OK) 3. DIAGNOSE SIREN SPEAKER R. SIDE IN/OP - FOUND BAD DRIVER. REPLACED DRIVER TEST OK AFTER REMOVING AGAIN AND ARRANGE PLACEMENT OF WIRES. 4. SQUIRTERS BAD. REPLACED WINDOW SQUIRTERS AND WIPER BLADES. ADJ. NOZELS. 5. DEFROSTER IN/OP - REMOVED DASH AND REPOSITION DEFROSTE CABLE. 6. TOP OFF OIL AND COOLANT. 7. DIAGNOSE COOLANT LOSS PRESSUREIZE SYSTEM AND FOUND LEAK AT REAR COOLAN TO BE FITTING FOR AIR COMPRESSOR. TIGHTEN FITTING. 8. TIGHTEN AIR HORN BRACKETS. INSTALL LOCK NUTS AND WASHEF WHERE MISSING. REBUILD R AIR HORN TWICE AND ADJ AIR HORN: FOR SOUND QUALITY. 9. FRONT TIRES WSORN ON OUTSIDE. REAF TIRES WORN. REMOVE ALL WHEELS. INSTALL FRONT WHEELS ON REAR OUTSIDE AND NEW TIRES AND WHEELS ON FRONT AND REA INSIDE AIR TIRES TO 90 PSI. TIME SPENT LOOKING FOR GOOD TIRES ON STEEL WHEELS. MOVING HOIST TO BAY AND STORING AND LABELING USED WHEELS. 10. CHECK AND ADJ TOE ANGLE. 11 SCBA DOOR FALLING OFF. 3 BROKEN BOLTS. DRILL AND TAP HOLES. 12. DEGREASE MOTOR - TEST DRIVE - RAISE VEHICLE ANC CHECK FOR LEAKS. FOUND LEAKS FRONT LEFT BY AIR COMPRESSOR AND REAR LEFT TOP AREA. SPOT CLEAN AREAS AND RUN VEHICLE AT HIGH IDLE. CHECK FOR LEAKS. FOUND SMALL LEAK AT SWITCH BEHIND COMPRESSOR AND #S INJECTOR LINE AT INJECTOR LEAKING. 13. ROAD TEST AND RECHECK OIL LEAKS TO VERIFY AND CHECK DEGREE OF LEAK. ED E. INSPECTEI OIL AND FUEL LEAK. CUMMINS TO REPAIR AT SHOP TOMORROW. 14. REPLACE FILTERS. 15. REMOVE STEEL PLACKARD FRAME AND GLUE. INSTALL NEW PLASTIC. 16. BELT SQUEAL. TIGHTEN BELTS. 17. DEGREASE AREAS LEAKING OIL AND FUEL AFTER VENDOR REPAIR. ROAD TEST AND CHECK FOR LEAKS. FUEL LEAK OK. OIL LEAK STILL AT FRONT LEFT SIDE OF ENGINE. 18. CLEAN AREA FOF VENDOR AND ROAD TEST FOR VENDOR. OIL LEAK AT BACK OF FRONT GEAR COVER.

1094KIT-AIR HORN-GROVER	2
404-100 VALVE CORE	1
52-24WIPER BLADES ANCO 24	2
S PLACARDFRONT AND BACK PLACARD	1
SD-210RXSIREN DRIVER SMALL	1
SPRGW2612WASHER NOZZLE W/RELIEF	2





4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V61493**

In Date: 10/24/2013  
Close Date: 10/31/2013

Meter Reading: 124,900.50

**Problem?**

engine oil and fuel leaks

Parts	Quantity
-------	----------

**Task performed:**

NO PARTS USED

Vendor? CUMMINS

**Workorder: V61984**

In Date: 11/13/2013  
Close Date: 11/18/2013

Meter Reading: 124,900.50

**Problem?**

REPAIR OIL LEAK

Parts	Quantity
-------	----------

**Task performed:**

REPAIR OIL LEAK.

NO PARTS USED

Vendor? CUMMINS

**Workorder: V62442**

In Date: 12/03/2013  
Close Date: 12/04/2013

Meter Reading: 124,900.50

**Problem?**

repair head gasket and oil leak

Parts	Quantity
-------	----------

**Task performed:**

REPAIR HEAD GASKET AND OIL LEAK.

NO PARTS USED

Vendor? CUMMINS POWER SOUTH



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V62629**

**In Date:** 12/10/2013  
**Close Date:** 12/13/2013

**Meter Reading:** 141,094.50

**Problem?**

siren 10-7 r21

Parts

Quantity

**Task performed:**

TRAVEL TO 21 DRIVER COMPLAINT NO SIREN REPLACED AND  
REWired SIREN HEAD AND REPLACED.

SD-210RXSIREN DRIVER SMALL
----------------------------

1
---



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142536

**FL60 ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V60725**

**In Date:** 09/23/2013

**Meter Reading:** 140,500.00

**Close Date:** 01/03/2014

**Problem?**

B inspection R300

### Task performed:

1. B INSP. 2. DIFFERENTIAL OIL SERVICE. 3. LIGHT L/S LIGHT BAR FAULT, L/REAR LIGHT BAR, PACENT COMP HI, RIGHT FENDER LIGH CAB MARKER LIGHT INOP-REMOVE INSTALL NEW BULBS LED ASSEMBLY AND SECURE. 4. PACENT COMP A/C FILTER- REMOVE AND INSTALL NEW FILTER. 5. CAB AND PACENT COMP A/C SMOKING CLUTCH AND SEIZED UP COMPRESSOR RECIEVER FREON, REMOVE COMPRESSOR, INSTALL 2 NEW COMPRESSORS AND DRYER, VACUUM AND CHECK FOR LEAK, CHANGE BOTH SYSTEM AND OPERATION. 6. TOP OFF LOW COOLANT- PRESSURE TEST, NO LEAK FOUND. 7. DRIVER WINDOW HOLDING BROKEN-REMOVE DAMAGE PART AND INSTALL NEW REPLACEMENT PART. 8. L-2 DRY LIGHT CHARGING LOCKING TABS- REMOVE CHARGER AND INSTALL AND HARDWIRE IN PLACE. 9. NIGHT SIDE BOX STROBE INOP- FOUND BULB BLOWN-REMOVE AND INSTALL NEW LINEAR BULB/TUBE. 10. S. PACENT OPEN PANEL COMING OFF-INSTALL NEW FASTENER AND SECURE. 11. CLEAN CUT OUT OLD WELD, REWELD STEP WITH NEW WELDS READY.. 12. STATION # AND HOLD- ASSEMBLE # HOLDER REFLECTOR AND # INSTALL ON UNIT AFTER RECEIVING OLD METAL HOLDERS AND CLEANING SURFACE. 13. FLIP UP TAILBOARD WELDS CRACK-REMOVE TAILBOARD FOR WELDER- INSTALL REPAIRED TAILBOARD. 14. BRAKE NOISE-INSPECT BRAKES AND BRAKING APPLICATION- PARTS WORKING NORMAL-NOISE CAUSE BY BRAKE DUST AND ROAE DIRT ON LINER AND MOVING PARTS. 15. L-4 COMPARTMENT VENT DAMAGE- CUT PLATE- DRILL HOLES IN PLATE AND DRILL TAF COMPARTMENT WALL, ATTACH PLATE TO COVER HOLE. 16. EXCESSIVE OIL LEAK FROM CRANK CASE BREATHER- REMOVE BREATHER FILTER HOUSING- SERVICABLE SCREEN- CLEAN AND REINSTALL.

### Parts

### Quantity

08-3492HFITTING A/C 5514	1
1501450007750USE 0775145	1
194BULB	1
322502BULB PATIENT GH22	1
532703-0602 COMPRESSOR U4735 4471	2
5499FRE801910 REPAIR BRACKET A/C COMPRESSOR	3
68118206050BEND CAP RED SUPER ADV.PLUS LT.E	1
716907-0610A DRYER	1
9451BELT	1
9485BELT	1
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
ICC5ALLED CLEARANCE LIGHT AMBER	1
L PLACARDLARGE SIDE PLACARD	1
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
S PLACARDFRONT AND BACK PLACARD	1
S3225PFUEL FILTER 33630 LFF5849	1



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V62950**

In Date: 12/26/2013      Meter Reading: 141,884.00  
 Close Date: 01/07/2014

**Problem?**

Replace rear tires [Vibration]

**Task performed:**

REPLACE REAR TIRES [VIBRATION].

Vendor? GOOD YEAR

Parts	Quantity
-------	----------

NO PARTS USED

**Workorder: V63338**

In Date: 01/13/2014      Meter Reading: 141,995.50  
 Close Date: 01/14/2014

**Problem?**

a inspection

**Task performed:**

1. A INSP. 2. P/STEERING FILL POWER STEERING RES TO PROPER LEVEL. 3. W/WASHERS WNDSHIELD, WASHERS- INOP-CHECK OUT PROBLEM FOUND "T" CONNECTOR FOR HOSES BROKEN- REPLACE "T" FITTING. 4. ALL TIRE PRSSURES LOW- FILL TO PROPER LEVEL- NOTE: L/Front VALVE STEM BENT INTO SIMULATOR COVER SO PRESSURE COULDNT BE CHECKED- BEND DOWNMN VALVE STEM FOR CLEARANCE AND FILL TIRE. 5. ENG OIL WAS 4 QTS LOW- FILL TO PROPER LEVEL. 6. REMOVE LENS AND REPLACE BULB IN R/SID ROOF CLEARANCE LT. 7. WASHER FLUID COMPT DOOR VERY LOOSE AND RATTLING- ADJUST LOOK DOWN LATCH FOR TIGHTER FIT. 8. SIDE ENTRY DOOR- PATIENT SIDE ENTRY DOOR SCRAPPING AND BINDING BADLY- LOOSEN ALL FINGE SCREWS AND JACK UP DOOR TO CLEAR STEP AND TIGHTEN SCREWS- NOW ADJUST STRIKERS TO MATCH LATCHES.

Parts	Quantity
-------	----------

S PLACARDFRONT AND BACK PLACARD	1
SPR-W58-1TEE PLASTIC	1



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V65523**

In Date: 04/07/2014  
Close Date: 04/30/2014

Meter Reading: 144,235.00

**Problem?**

A inspection

**Task performed:**

1. A INSP. 2. ADJUST AIR HORNS. 3. CHECK SHORELINE CHARGER, INOP FOUND FUSE ON CHARGER BLOWN. 4. REPLACE PARKING BRAKE LIGHT.

Parts	Quantity
HA143HA143 LIGHT AMBER WARNING	1

**Workorder: V66145**

In Date: 05/01/2014  
Close Date: 05/07/2014

Meter Reading: 145,563.00

**Problem?**

Air brake has an audible slow leak. Psi won't read over 70-75.

**Task performed:**

1. travel to sta.-44 check for air leak, found steel braided line has hole in it travel back to s/shop for air line, return to sta-44, not enough room under vehicle to disconnect line on brackets, ran new line along side old line, start vehicle now builds air, travel back to s/shop \* notified steve reines and told him about running braided line along side old one. vehicle needs to come to shop and put on lift to remove old line from brackets and attach new line to brackets

Parts	Quantity
A1211593054HOSE DISCHG	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10142536 FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V66410**

**In Date:** 05/12/2014  
**Close Date:** 07/22/2014

**Meter Reading:** 146,263.50

**Problem?**

A inspection SR16

**Task performed:**

A-insp. Add transit coolant fluids. Suction bottle not bolted to wall. Install sheet metal screws and secure frame. L-3 hinge bolts loose, tightened bolts. Battery handle broken, swapped handle from parts truck. Protect P/S hoses and a/c lines with loom. Diagnose problem with city horns inop. Found both horns bad and horn contact horns inop. Found both horns bad and horn contact dirty. Replaced horns and clean contact. Air horns sound quality. Rebuild air horns. Replaced stripped screws with longer ones. Remove frozen trumpet. Clean and lubricate threads. Adj left airhorn. Right still sounds bad. Found air line leak where rubbing. Replaced line. Re-adj secure line Siren HF inop- found single unit installed where o/p remote and amp. Plug on siren color coding not consistent with HF function. Determine wiring. Locate horn relay and determine wiring for relay. Wire relay and run wire to correct terminal at siren plug. Test ok. Reinstall siren speakers, protective breaker cover and counsel Tand P piece. Protect and heat shrink wiring. Test ok. Wash cab of bird droppings. Diagnose air leak. Found line at dash at gauge fitting bad. R and R instrumental cluster and replaced gauge fitting.

Parts	Quantity
1094KIT-AIR HORN-GROVER	2
A0631117000HORN HIGH NEW # 06-52125-039	1
A0631117003HORN LOW NEW #06-52125-041	1

**Workorder: V67819**

**In Date:** 07/10/2014  
**Close Date:** 08/14/2014

**Meter Reading:** 147,398.00

**Problem?**

A-inspection

**Task performed:**

WORK BEING DONE ON C-SER, AT SHOP W/O V67906 FOR A SER.

Parts	Quantity
58ELTUBE58L4TUBE STROBE/REFLECTOR ASSY. 5	1



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10142536 FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V68842**

In Date: 08/21/2014  
Close Date: 09/09/2014

Meter Reading: 148,640.20

**Problem?**

B inspection R18 by OCS

**Task performed:**

B inspection

Vendor? OCS

Parts	Quantity
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1

**Workorder: V69249**

In Date: 09/09/2014  
Close Date: 09/11/2014

Meter Reading:

**Problem?**

Left headlight high and low beam out, right headlight low beam out. No light found around station. SR@18

**Task performed:**

TRAVEL TO STA,18 CK, OUT NO HEAD LIGHTS ON TRUCK CK, POWER AND GROUND AT LIGHTS R&R BULBS RETESTED OK.

Parts	Quantity
H6054USE CV TYPE SEALED BEAM	3

**Workorder: V69073**

In Date: 08/31/2014  
Close Date: 10/01/2014

Meter Reading: 150,180.00

**Problem?**

front vista screen faulty

**Task performed:**

1. Road Call - Went to shop for parts. Went to 18. Repair and replace screen. Check operation. Check OK. Went to 68. 2. In Shop - Replace screen on donor truck. Programmed screen. Mounted and check operation. Check OK.

Parts	Quantity
6201-0010-00VISTA I	1



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V70094**

In Date: 10/13/2014  
Close Date: 10/30/2014

Meter Reading: 150,975.90

**Problem?**

won't start

Parts	Quantity
-------	----------

NO PARTS USED

**Task performed:**

Went to 18 Check battery and connections moved engines by hand started 10 times. Check ok.

**Workorder: V69939**

In Date: 10/06/2014  
Close Date: 11/06/2014

Meter Reading: 150,180.00

**Problem?**

trans not shifting

Parts	Quantity
-------	----------

NO PARTS USED

**Task performed:**

Travel to station 18 , check out truck trans. inop. Check codes ,check out plugs on trans. and shifter fuses. Possible water in plug or wiring; unknown at this time.

**Workorder: V67906**

In Date: 07/14/2014  
Close Date: 11/07/2014

Meter Reading: 147,398.00

**Problem?**

fuel leak

Parts	Quantity
-------	----------

L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1

**Task performed:**

WORK WAS COMPLETE ON W/O V66410





4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10142536 FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V71087**

In Date: 11/20/2014      Meter Reading: 151,552.00  
Close Date: 11/20/2014

**Problem?**

replace drivers door handle

**Task performed:**

1. Driver's door handle broken. R/R door handle.

Parts	Quantity
6807200575HANDLE DOOR	1

**Workorder: V71257**

In Date: 11/29/2014      Meter Reading:  
Close Date: 12/04/2014

**Problem?**

Air leaking from hose in Engine

**Task performed:**

Travel to 16, checked for air leak on engine-no problem found

Parts	Quantity
NO PARTS USED	

**Workorder: V69888**

In Date: 12/02/2014      Meter Reading:  
Close Date: 12/11/2014

**Problem?**

Air horn solenoid leaking R400

**Task performed:**

Air horn solenoid leaking

Parts	Quantity
NO PARTS USED	



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V71596**

In Date: 12/11/2014      Meter Reading: 153,155.90

Close Date: 01/06/2015

**Problem?**

driver side headlight completely out, no replacements at station

Parts	Quantity
-------	----------

**Task performed:**

Removed and replaced headlight

NO PARTS USED
---------------

**Workorder: V72015**

In Date: 01/02/2015      Meter Reading: 153,308.00

Close Date: 01/06/2015

**Problem?**

A inspection

Parts	Quantity
-------	----------

**Task performed:**

1. A inspection 2. Check for air leak-Found air horn solenoid leaking 3. Check for air leak continued-removed air lines and replaced solenoid-check ok

HDY-H005700SOLENOID HORN AIR	1
------------------------------	---



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V73359**

**In Date:** 02/23/2015  
**Close Date:** 03/05/2015

**Meter Reading:** 155,253.90

**Problem?**

A inspection SR16

**Task performed:**

1. A Inspection. 2. Frnt and rear brakes. Pads service. 3. Coolant low. Add 2 quarts codant to recover. 4. Engine oil low- Add 2 quarts oil to engine. 5. Driver door light inop. Check system voltage good, check bulb good. Check switch/ switch connection loose. Repair and reassemble. 6. Rear light bar Amber light inop. Diassemble light bar. Remove blown buld and install new buld. Reassemble- Operate. 7. L/rear side warning inop- remove assembly- Remove blown buld- Install new bulb- Operate. 8. After brake job- Read test unit.

Parts	Quantity
02036317300STROBE LINEAR REFLECTOR 6ELTUBI	1
MK184HDBRAKE PADS	2
TURBO5TUBE - STROBE	1



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

**Workorder: V73564**

**In Date:** 03/02/2015

**Close Date:** 04/17/2015

**Meter Reading:** 155,253.90

**Problem?**

C inspection SR16

Parts

Quantity



4/10/2017

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10142536 FL60 ADVANCED LIFE SUPPORT VEHICLE

### Task performed:

1. C-Inspection. 2. Service air dryer and purge valve. 3. Replace air tank drain fittings. 4. Service transmission. 5. P/S service. 6. Replaced L drivers door trim piece. Replaced rusted screw. 7. Splice in piece of weather strip on drivers door. Clean area below rocker cover. 8. Clean and paint fuel cap. 9. Install missing bolt for air charge cooler to radiator. 10. Squirters not spraying correctly. Adj left side. Replaced right side and adj right side. 11. City horns inop. Diagnose problem, found one horn bad and steering wheel contact dirty. Replaced horn and cleaned contacts. 12 L-2 Door hold opens worn. Replaced both hold opens drill out stripped threads and install nut certs. Lubricate pivot points. Bend arm for correct angle. 13. Tighten compt door panels. Install missing screws lubricate doc latches, hold opens and hinges. 14. Weather strip missing on, bottom of L-4 door clean door frame and install new weather strip. 15. Right front wheel missing 3 lugnut covers. Install new covers. 16. Side patient door sticks when opening. Adj door striker and lubricate. 17. Rear dome light inop. Found bad bulb replaced buld. 18. Two patient compt doors wont stay open. Replaced compt shocks. Adj strikers to lock. 19. Diagnose air leaks replaced fittings on governor. Replaced another tank drain and instal new pressure protection valve. 20. Compt drawer fitting frame. Removed drawer and repositioned track. Test (ok). 21. Remove rear door glass weather stripping. Clean weather strip moldings and window chanel. Reinstall moldings. Clean windows. 22. Replaced rear door reflectors. 23. Repair rear door panel screws. Install sheet metal screws where needed. 24. Replaced left rear mud flap. Cut to size and drill holes for mounting. 25. Test drive vehicle for out of balance tires after replacing front tires. Ou of balance front rear tires of wheels. Check for vehicle drift (ok). 26. Top off trans fluid after checking hot. 27. Replaced R and left A/C vent difusers. 28. Removed nail RRI tire. Check for leak ok. 29. Drivers seat belt twisted. Remove bolt from seat bracket and install corectly to untwist seat belt. 30. Out of balance vibration when driving. Re-inspect drive shaft and center bearing. Remove rear wheels. Remove wheel weights and reposition on hubs differently. Road test- stin vibrates at 60-65 mph. 31. Air horn sound qulity poor. Adj air horns for good sound quality. 32. Trans shifting erratic and trans light came on momentarily. Check trans for codes- None. Ran fast adaptive reset and test drove vehicle until shifts became smooth. 33. 110V A/C warm. Could not find R22/R12 guage set.

0775145PANEL FILTER	1
103385NDRAIN COCK	3
107796DRYER KIT AD9 -NEW	1
15W40BSYN OIL BULK QTS	34
223-485V91-8301 85 PSI CLOSED 67 OPEN PREE5	1
29526898 29548988 TRANS FILTER ALLISON	1
295SLSA1SIREN	1
3911638PLUG OIL DRAIN C	1
3920773WASHER DRAIN PLUG	1
6808300074VENT A/C LH	1
6808300174VENT A/C RH	1
800405PURGE VALVE KIT	1
98003RREFLECTOR RED 40132 GROTE	2
A0631117000HORN HIGH NEW # 06-52125-039	1
A1834388002MOLD L/H	1
ACX-84534LUG NUT COVER PK10	3
B2420LP-SMUD FLAP 24 X 24	1
CA8193AIR FILTER 46744 WIX	1
E-600013-3052 NUT	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
HLD39917DC23-5011 50 # HOLD-OPEN RESCUE	2
HLD3999GSS1715UV 30LB STRUT GAS	4
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1
SPRGW2612WASHER NOZZLE W/RELIEF	1
TRANSYNDALLISON TRANS FLUID GAL	6



4/10/2017

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142536

### FL60 ADVANCED LIFE SUPPORT VEHICLE

Used John Vasko's road truck. Top off system and performance. Test ok.  
 34. Diagnose siren inop. Found bad siren unit. Replaced unit.

**Workorder: V74505**

**In Date:** 04/08/2015      **Meter Reading:** 155,253.90  
**Close Date:** 04/20/2015

**Problem?**

REPLACE STEER TIRES

Parts	Quantity
-------	----------

**Task performed:**

Replace steer tires

NO PARTS USED

**Vendor?** ELPEX

**Workorder: V74300**

**In Date:** 03/30/2015      **Meter Reading:** 155,253.90  
**Close Date:** 05/13/2015

**Problem?**

A-inspection

Parts	Quantity
-------	----------

**Task performed:**

1. A-Inspection.

NO PARTS USED