



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V123

In Date: 10/11/2005
Close Date: 10/13/2005

Meter Reading:

Problem?

FLUORESCENT LIGHTS IN PAT, COMPT, INOP, R-55

Parts

Quantity

Task performed:

NO PARTS USED

Workorder: V367

In Date: 10/27/2005
Close Date: 11/15/2005

Meter Reading:

Problem?

multiple warning and strobes out R55

Parts

Quantity

Task performed:

0104163330001-0416333-00 LIGHT	1
020382416-00USE 01-0416333-00	1
TURBO5TUBE - STROBE	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V526

In Date: 11/09/2005
Close Date: 11/17/2005

Meter Reading:

Problem?

REMOUNT LIGHT BAR R55

Task performed:

Parts	Quantity
02-0363596250400 LED / RED	1
22-53483-000ANTENNA RADIO S/O	1
800405PURGE VALVE KIT	1
RMKEZ7LIGHT BAR MOUNT PERMENET MKEZ29	1
SPT6008146SL LIGHT-REMOTE SPOT	1

Workorder: V758

In Date: 12/01/2005
Close Date: 12/02/2005

Meter Reading:

Problem?

REAR DOORS WILL NOT OPEN R55

Task performed:

Parts	Quantity
HA24014HA24014 DOOR LATCH	1
HA24016HA24016 LATCH	1
HA24214 LATCH SET WHEEL COACH	1
HND5946N HANDLE CHROME	1
HND5947NONLY LOCKING AVAIL L/H HANDLE CHI	1
HND5948TM22676-02 HANDLE DOOR ENTRY	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V705

In Date: 11/28/2005
Close Date: 12/12/2005

Meter Reading:

Problem?

BROKEN IV COMPT, R-55

Parts	Quantity
-------	----------

Task performed:

LTC5993SSM1-63-8 LATCH STAINLESS	2
----------------------------------	---

Workorder: V821

In Date: 12/06/2005
Close Date: 12/12/2005

Meter Reading:

Problem?

REAR DOOR HARD TO OPEN, R-55

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED	
---------------	--

Workorder: V1464

In Date: 02/09/2006
Close Date: 02/13/2006

Meter Reading:

Problem?

COMPT. DOOR HIT BAY DOOR, R-55

Parts	Quantity
-------	----------

Task performed:

HLD374211 IN HOLD-OPEN 30LB	1
-----------------------------	---



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V1326

In Date: 01/27/2006
Close Date: 02/23/2006

Meter Reading: 43,466.00

Problem?

B INSPECTION R55

Task performed:

See B Inspection pre-printed form

Parts

Quantity

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
0127110042BELT MERCEDES MOTORS	1
091-3YWCOVER KUSSMAUL AUTO EJECT	1
19282TAPE ANTI-SLIP PER FT 60FT ON ROLL	10
4923090025DASH BULB VDO	1
52-24WIPER BLADES ANCO 24	2
6806970098SEAL DOOR	2
6807680003PLATE DOOR HANDLE	1
78R536078R5360M 2PK FILTER AIR COND	1
91513AMBER LENS	2
91823SWITCH SWT5499 MED MASTER	1
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	2
DEC6100DECAL REFLECTIVE STRIPE	7
MFG9928PL17008 VERSACELL DECAL BACKING	7
RBR7862GA48800 RUBRAIL INSET	7
UNT7744USE PINK A/C FILTER MEDIC MASTER	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V1478

In Date: 02/13/2006
Close Date: 02/28/2006

Meter Reading:

Problem?

A/C BELT BROKE R-55

Task performed:

Parts	Quantity
9425BELT MERCEDES RESCUE 12.5X1075 OE	1

Workorder: V1433

In Date: 02/06/2006
Close Date: 03/02/2006

Meter Reading:

Problem?

AIR BAGS IN REAR WILL NOT RAISE, AIR LEAK FROM UNDER TRUCK R-55

Task performed:

Parts	Quantity
800405PURGE VALVE KIT	1

Workorder: V1719

In Date: 03/03/2006
Close Date: 03/06/2006

Meter Reading:

Problem?

REAR DOOR WILL NOT OPEN R55

Task performed:

Parts	Quantity
HND5948TM22676-02 HANDLE DOOR ENTRY	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V1662

In Date: 02/28/2006
Close Date: 03/21/2006

Meter Reading:

Problem?

BATTERY SWITCH HARD TO TURN, CHECK FRONT TIRES, R-55

Parts	Quantity
-------	----------

Task performed:

75908SWITCH BATTERY MASTER 300A	1
---------------------------------	---

Workorder: V1930

In Date: 03/22/2006
Close Date: 04/05/2006

Meter Reading:

Problem?

REAR A/C INOP, R-55

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED	
---------------	--

Workorder: V2032

In Date: 03/30/2006
Close Date: 04/10/2006

Meter Reading:

Problem?

REAR DOOR NOT CLOSING, R-55

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED	
---------------	--



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V2192

In Date: 04/11/2006
Close Date: 04/20/2006

Meter Reading:

Problem?

NEED 20 LB ABC EXTINGUISHER, R-55

Parts

Quantity

Task performed:

NO PARTS USED

Workorder: V2275

In Date: 04/18/2006
Close Date: 04/21/2006

Meter Reading:

Problem?

VEHICLE IN ACCIDENT R-55

Parts

Quantity

Task performed:

NO PARTS USED

Workorder: V2198

In Date: 04/11/2006
Close Date: 05/02/2006

Meter Reading:

Problem?

replace flat tire on r/front (outside vender) R55

Parts

Quantity

Task performed:

NO PARTS USED

Vendor? TCI



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V2258

In Date: 04/17/2006
Close Date: 05/11/2006

Meter Reading:

Problem?

TOW R-55 FROM STA55 TO SHOP, (SISTERS TOWING)

Parts

Quantity

Task performed:

NO PARTS USED

Vendor? SISTERS TOWING

Workorder: V3116

In Date: 06/02/2006
Close Date: 06/23/2006

Meter Reading:

Problem?

repair seat R55 (outside agency- central auto trim)

Parts

Quantity

Task performed:

NO PARTS USED

Vendor? CENT0002

Workorder: V2640

In Date: 05/16/2006
Close Date: 08/10/2006

Meter Reading:

Problem?

TOW R-55 FROM SHOP TO SEBOCK AUTO BODY, (SISTERS TOWING)

Parts

Quantity

Task performed:

NO PARTS USED

Vendor? SISTERS TOWING



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V4059

In Date: 08/22/2006
Close Date: 08/31/2006

Meter Reading:

Problem?

oxygen guage in the inside o2 compartment broken, and interior pt. compartment large bottom of door button broken, prohibiting door from being open. R55

Parts ----- Quantity -----

Task performed:

680-880-01-60LATCH	1
--------------------	---

Workorder: V4175

In Date: 08/29/2006
Close Date: 09/01/2006

Meter Reading:

Problem?

front A/C only has one setting, and it is the #1 (low) setting on the fan R55

Parts ----- Quantity -----

Task performed:

ABPN8332229011-3050 SWITCH BLOWER	1
-----------------------------------	---

Workorder: V4174

In Date: 08/29/2006
Close Date: 09/13/2006

Meter Reading:

Problem?

rescue's main Oxygen line seems to have a leak R55

Parts ----- Quantity -----

Task performed:

NO PARTS USED	
---------------	--



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V4325

In Date: 09/07/2006

Meter Reading:

Close Date: 09/13/2006

Problem?

FRONT A/C BLOWING HOT AIR R55

Parts

Quantity

Task performed:

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V3932

In Date: 08/15/2006

Meter Reading: 47,000.00

Close Date: 09/14/2006

Problem?

B INSPECTION, A/C INOP, WIRE HANGING FROM FRONT DRIVER SEAT, (BACK FROM SEBOCK)

Task performed:

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
00009247080000925208 FILTER HEAD CAP NEW NU	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
032-0116549297 BATTERY INDICATOR	1
05-17223-000CAP RADIATOR 10 LB	1
22512960001498 SWITCH BINA	1
533103-0607 A/C COMPRESSOR U4482 USE 7169 D	1
60R00BRRLED BRAKE/TURN LIGHT	1
6809880678STUD DZ	2
6809940145CLIP	2
6EFLANGE600 CHROME FLANGE	1
716907-0610A DRYER	1
78R536078R5360M 2PK FILTER AIR COND	1
A1834388002MOLD L/H	1
A22451940011499 SWITCH A/C HIGH PRESSURE NC	1
DEC6100DECAL REFLECTIVE STRIPE	3
EXT4534RUBRAIL EXTRUSION PER FT	3
FG87904MFG3937557S FILTER P/S NEW STYLE	1
HND5941USE HAN-1L METAL LATCH INTERIOR LOC	1
LTC5993SSM1-63-8 LATCH STAINLESS	3
MFG9928PL17008 VERSACELL DECAL BACKING	3
R90PFILTER FUEL 33231	1
RBR7862GA48800 RUBRAIL INSET	3



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V4350

In Date: 09/09/2006
Close Date: 09/25/2006

Meter Reading: 47,742.00

Problem?

Rescue is starting sluggish. Possible weak batteries. R55

Task performed:

1. R/R LOW BATTERY.

Parts	Quantity
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
HP-31DBATTERY 950CCA HP-31D	4

Workorder: V4176

In Date: 08/29/2006
Close Date: 10/03/2006

Meter Reading:

Problem?

front hood handle to open hood missing, came back from the shop that way
R55

Task performed:

1. TRAVELED TO STN 55 INSTALLED NEW HANDLE ON HOOD.

Parts	Quantity
681-887-00-27HOOD HANDLE	1

Workorder: V4850

In Date: 10/10/2006
Close Date: 11/06/2006

Meter Reading: 3,139.20

Problem?

dash a/c blowing hot air R-55

Task performed:

1. TRAVELED TO STN 55. FOUND UNIT BLOWING COLD AIR.

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V5240

In Date: 11/03/2006
Close Date: 11/08/2006

Meter Reading: 4,724.00

Problem?

Need to replace rear passenger side corner lense cover R55

Task performed:

- 1. REPLACE REAR A/C BLOWER MOTOR

Parts ----- Quantity -----

UNT1400BLOWER MTR. + SQU IRREL CAGE ASSY.	1
---	---

Workorder: V5260

In Date: 11/06/2006
Close Date: 11/08/2006

Meter Reading:

Problem?

patient compartment ac fan, and left side dome lights and fluorecent r55

Task performed:

- 1. REPLACE 2 PT LIGHT BULBS

Parts ----- Quantity -----

322502BULB PATIENT GH22	2
-------------------------	---

Workorder: V5265

In Date: 11/06/2006
Close Date: 11/08/2006

Meter Reading: 50,152.00

Problem?

WHILE BACKING VEHICLE DRIVER HIT FRONT APRON AND TRUCK HAD DAMAGE TO REAR LIGHT BAR, R-55

Task performed:

- 1. REPLACE RIGHT REAR LIGHT BAR LENS

Parts ----- Quantity -----

02034293300DIVIDER 4500 LITE BAR	1
02034293401DIVIDER 4500 LITE BAR	1
02034294100LENS RETNR 4500 LITE BAR	1
68398381350LENS END 4500 LITE BAR RED	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V5658

In Date: 12/04/2006
Close Date: 12/06/2006

Meter Reading: 4,856.00

Problem?

ac is blowing hot airt despite being off R55

Parts ----- Quantity -----

Task performed:

1. TRAVELED TO STN 55. FOUND NO PROBLEM WITH A/C.

NO PARTS USED

Workorder: V5589

In Date: 11/28/2006
Close Date: 12/12/2006

Meter Reading: 51,128.00

Problem?

FLAT REPAIR AT STA 55 CALLAGHAN ENT R55

Parts ----- Quantity -----

Task performed:

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V5825

In Date: 12/15/2006
Close Date: 12/19/2006

Meter Reading: 4,885.20

Problem?

DRIVER'S COMPARTMENT DOOR IS LOOSE R-55

Parts ----- Quantity -----

Task performed:

1. TRAVELED TO STN 55. REMOVED ALL SCREWS AND DOOR NUT
SERTED DOOR POST AND REINSTALLED DOOR.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V6025

In Date: 12/31/2006
Close Date: 01/04/2007

Meter Reading:

Problem?

radio console loose on driver's side in the cab R-55

Parts _____ Quantity _____

Task performed:

- 1. Replaced radio console

NO PARTS USED

Workorder: V6063

In Date: 01/02/2007
Close Date: 01/04/2007

Meter Reading: 5,000.00

Problem?

Shoreline stick in charger will not pop out all the time R-55

Parts _____ Quantity _____

Task performed:

- 1. Replaced auto eject

NO PARTS USED

Workorder: V6362

In Date: 01/19/2007
Close Date: 01/29/2007

Meter Reading: 53,755.00

Problem?

water in fuel lt on r55

Parts _____ Quantity _____

Task performed:

- 1. TRAVELED TO STN 55. FOUND NO LIGHT ON CHECK LAP TOP AN TESTED/ OK.

RAIRK30880N122WSKL4000 SENSOR WATER IN FU 1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V6641

In Date: 02/06/2007
Close Date: 02/14/2007

Meter Reading: 5,164.00

Problem?

MISSING TWO BOLTS ON THE PLATE COVERING THE EXHAUST ON THE OFFICER SIDE TO R55. THE NEW RESCUE

Parts ----- Quantity -----

Task performed:

Repaired diamond plate cover

NO PARTS USED

Workorder: V6666

In Date: 02/08/2007
Close Date: 02/14/2007

Meter Reading: 5,172.50

Problem?

unit has not had pm since 01/06, also front left brakes grab if hard braking is required recods show unit serviced in 9/06

Parts ----- Quantity -----

Task performed:

Check brakes checked out ok

NO PARTS USED

Workorder: V6776

In Date: 02/15/2007
Close Date: 02/22/2007

Meter Reading: 5,197.00

Problem?

Check highbeam headlights.

Parts ----- Quantity -----

Task performed:

1. TRAVELED TO STN 55. FOUND NO PROBLEM WITH HIGH BEAMS.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V6901

In Date: 02/23/2007
Close Date: 02/27/2007

Meter Reading: 5,229.50

Problem?

air horn not working R55

Parts ----- Quantity -----

Task performed:

1. TRAVELED TO STN 55. ADJUSTED AIR HORNS. TEST/ OK.

NO PARTS USED

Workorder: V6926

In Date: 02/25/2007
Close Date: 02/27/2007

Meter Reading: 5,275.00

Problem?

R55 AIR HORN INOP R55

Parts ----- Quantity -----

Task performed:

1. TRAVELED TO STN 55. ADJUSTED AIR HORNS, TEST/ OK.

NO PARTS USED

Workorder: V6940

In Date: 02/26/2007
Close Date: 03/08/2007

Meter Reading: 5,275.00

Problem?

spring rod for door is bent causing door to open with difficulty R55

Parts ----- Quantity -----

Task performed:

Replaced rod on L2 door

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V7019

In Date: 03/01/2007

Meter Reading: 55,832.00

Close Date: 03/09/2007

Problem?

B INSPECTION AND REPAIRS AS NEEDED R55

Parts

Quantity



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* ADVANCED LIFE SUPPORT VEHICLE

Task performed:

1. B Inspection 2. Removed rear right tires to inspect frame 3. service cooling system 4. Service air dryer 5. Service power steering 6. R&R stretcher lock 7. Repaired or replaced compt. door latches, locks, hold opens, and panals. Replaced squad bench struts 8. R&R door moldings and seals 9. Repaired or replaced lights in action area, dome, cab door, marker, and signal 10. Diagnosed and repaired front light bar 11. Prepare for on call 12. Replaced wiper blades and added solvent 13. Replaced broken a/c vents and cleaned out e-core 14. Repaired bad ground to city horn 15. Replaced missing wheel nut covers 16. Front a/c warm. Adjusted heater cable 17. Removed tailboard and welded. Reinstalled tailboard 18. Found leaking shrader valve in rear a/c. Evacuate system repair and recharge. secured loose drip pan and replaced uv light 19. Clean work area

00000001085OIL DRAIN GASTKET M2	1
000090155133634 FUEL FILTER WIX MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
000908022011OIL DRAIN PLUG M2	1
0106837849C8COMP LIGHT WHITE LED 200	1
02-0363596250400 LED / RED	1
090-0278STRECHER BAR NEW	1
16-31438915 VALVE CORE A/C 3544706C1	1
16-31465533 CAPS HIGH SIDE	1
16-3445CAP-BLACK 134A 5579 KOOL TEMP	1
381 838 02 19DASH VENT	1
5008414CARTRIDGE DC100	1
6808300074VENT A/C LH	1
6808300174VENT A/C RH	1
91513AMBER LENS	2
A0048201010SWITCH DOOR	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	2
ACX-84534LUG NUT COVER PK10	31
CA8193AIR FILTER 46744 WIX	1
CYBS21237011CYBS21237011 STRAP	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
HLD3999GSS1715UV 30LB STRUT GAS	2
HND5941USE HAN-1L METAL LATCH INTERIOR LO	2
HND5948TM22676-02 HANDLE DOOR ENTRY	1
LTC1020606LATCH	1
R90PFILTER FUEL 33231	1
U-24RWIPER REFILL	1
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V6959

In Date: 02/27/2007
Close Date: 03/14/2007

Meter Reading: 55,832.00

Problem?

REPLACE TIRES AT STA 55

Parts ----- Quantity -----

Task performed:

Replaced tires at station 55 Callaghan Ent

NO PARTS USED

Vendor? CALLAGHAN ENT

Workorder: V7447

In Date: 03/30/2007
Close Date: 04/02/2007

Meter Reading: 5,285.00

Problem?

rear drivers side brake light out, rear drivers sire door latch loose and coming out of door r55

Parts ----- Quantity -----

Task performed:

Replaced L/R taillight assy Repaired L/R door handle latch

60R00XRRBRAKE/TAILLIGHT LED 1

Workorder: V7538

In Date: 04/04/2007
Close Date: 04/06/2007

Meter Reading: 5,314.10

Problem?

low voltage light and buzzer going on. smoke coming out from engine. r55

Parts ----- Quantity -----

Task performed:

Road call to station 55. Checked truck found bad alt. Swapped out unit

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V7552

In Date: 04/05/2007
Close Date: 04/10/2007

Meter Reading: 56,146.00

Problem?

check and repair charging system r55

Task performed:

1. R&R altenator 2. Front a/c not cooling stuck in defrost position and low on refrigerant. Installed new a/c deflectors 3. A Inspection 4. Repaired marker and clearance lights

Parts

Quantity

4867JB320 UPGRADE ALTERNATOR	1
6808300074VENT A/C LH	1
6808300174VENT A/C RH	1

Workorder: V7542

In Date: 04/05/2007
Close Date: 04/12/2007

Meter Reading: 56,146.00

Problem?

tow unit from sta 55 to cs sisters towing

Task performed:

Tow unit from station 55 to CS Sisters Towing

Parts

Quantity

NO PARTS USED	
---------------	--

Vendor? STSTERS TOWING

Workorder: V7719

In Date: 04/15/2007
Close Date: 04/17/2007

Meter Reading: 34.80

Problem?

Heater in cab not turning off stuck in the low heat position. R55

Task performed:

Spoke with Ed Woodland, manufacture does not reccomend side unit ove flow FNP with heater control. Repaired cab door locks that would not lock.

Parts

Quantity

NO PARTS USED	
---------------	--



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V7779

In Date: 04/17/2007
Close Date: 04/25/2007

Meter Reading: 56,764.00

Problem?

front passenger side door hard to open from the outside. you have to push the door in and pull on the handle to open the door.r55

Parts ----- Quantity -----

Task performed:

Lube & adjust door latch. Adjusted rear door latch linkage. Checked & repaired O2 leak.

NO PARTS USED

Workorder: V8223

In Date: 05/12/2007
Close Date: 06/05/2007

Meter Reading: 5,490.80

Problem?

Right tail light's two center rows of LEDS not functioning. R-55

Parts ----- Quantity -----

Task performed:

1. Replaced tail light

60R00XRRBRAKE/TAILLIGHT LED 1

Workorder: V8333

In Date: 05/21/2007
Close Date: 06/05/2007

Meter Reading: 5,532.70

Problem?

ac not blowing cold air r55

Parts ----- Quantity -----

Task performed:

1. Traced out problem with A/C, found H-Block needs to be replaced 2. Readjusted strecher mount 3. Repaired 110V A/C unit, adjusted fan alignment

A22454320011602 EXPANSION VALVE 1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V8293

In Date: 05/16/2007
Close Date: 06/11/2007

Meter Reading: 5,512.00

Problem?

old rescue was rear ended and the step needs to be adjusted/repared. B/C 5 requested a tech come and look at it. Again this is the old rescue truck at station 55

Parts ----- Quantity -----

Task performed:

- 1. Adjusted rear step

NO PARTS USED

Workorder: V9065

In Date: 06/29/2007
Close Date: 07/06/2007

Meter Reading: 59,963.00

Problem?

Interior lights in pt compartment are out r55

Parts ----- Quantity -----

Task performed:

- 1. Replaced pt light in rear

322502BULB PATIENT GH22 4

Workorder: V10139

In Date: 08/27/2007
Close Date: 09/17/2007

Meter Reading: 5,951.00

Problem?

Passenger side headlight intermittenly going out as reported by other shifts
Possibly short in wiring.r55

Parts ----- Quantity -----

Task performed:

- 1. Went to Stn55; chkd headlight & wire on problem fnd 2. Rep intermitten problem w/headlights; fnd bad connection

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V10187

In Date: 08/31/2007
Close Date: 09/17/2007

Meter Reading: 62,107.00

Problem?

patient a/c 10-7

Task performed:
Replaced A/C belt

Parts	Quantity
9550 BELT	2

Workorder: V10390

In Date: 09/12/2007
Close Date: 09/24/2007

Meter Reading: 62,685.00

Problem?

drivers side front turn sigal out r55

Task performed:
1. FOUND R55 AT STA 57 R/R BULB IN TURN SIGNAL ON DRIVERS SIDE.

Parts	Quantity
NO PARTS USED	

Workorder: V4887

In Date: 10/13/2006
Close Date: 10/15/2007

Meter Reading: 3,139.20

Problem?

front a/c blowing hot. was checked by tommy on 10/12 and was fine but lastnight started to blow hot again. R-55

Task performed:
RECHARGE A/C REAR BLOWER NEEDS TO BE REPLACED.

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V10735

In Date: 09/28/2007
Close Date: 10/23/2007

Meter Reading: 63,117.00

Problem?

replace tires at sta 55 r55

Parts ----- Quantity -----

Task performed:

REPLACE TIRES - CALLAGHAN

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V11276

In Date: 10/27/2007
Close Date: 11/09/2007

Meter Reading: 6,211.00

Problem?

The front cab/ Passenger compartment, and climate control A/C are all blowing hot. The Check out ligts in passenger area not working. R55

Parts ----- Quantity -----

Task performed:

1. CHK OUT LIGHT NOT WORKING; INSTALLED NEW BULB IN LIGHT;
2. FRNT a/c INOP; REPLC AIR DRYER AND EXPANSION VALVE; RECHRGED SYS; FND CAM PRESSURE N/G 3. R/R A/C COMPRESSOR; FRNT NOT PUMP-NO PRESSURE; R/R OLDER PULLEY-BAD BEARING; a/c OUT OF OIL, LOCKED UP

533103-0607 A/C COMPRESSOR U4482 USE 7169 D	1
716907-0610A DRYER	1
78R536078R5360M 2PK FILTER AIR COND	1
9062001170IDLER MERCEDES	1
A22454320011602 EXPANSION VALVE	1
LPVM-7LG MOUNT	2
UMVS-0811-11STRAP ZICO	2



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V11419

In Date: 11/04/2007
Close Date: 11/14/2007

Meter Reading: 65,229.00

Problem?

stretcher has a sheared off screw at the base of the head-elevating system R55

Parts ----- Quantity -----

Task performed:

1. Installed new screw in stretcher.

NO PARTS USED

Workorder: V11583

In Date: 11/13/2007
Close Date: 11/27/2007

Meter Reading: 65,308.00

Problem?

b inspection and repairs as needed r55

Parts ----- Quantity -----

Task performed:

B-Inspection 2. Trans Svc; filters/fluid 3. R/R belts & adjust 4.LR cab molding broke5. Window tracks loose frm slamming door; ness to drill/secure to frame; rem panel/rep door & install molding 5. Rear brakes low; R/R drums & shoes; adjust 6. Rear pat drawer ltch loose; tighten/adj Drill/remount door holdopn on L3 comp 8. Floor lighting inop; ness to R/R/ bulbs 9. Diff svc; R/R/ oil 10. R-frnt shock loose; LF spring hanger loose; ness to R/R bolt & torque 11. Torque all U-bolts frnt/rear 12. Broken exh bolts to head; diss to R/R broken bolts & replc j

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
0127110042BELT MERCEDES MOTORS	1
29526898 29548988 TRANS FILTER ALLISON	1
3744BRAKE DRUM REAR	2
4909SCUT AND FAB FITTING	1
6808300174VENT A/C RH	1
78R536078R5360M 2PK FILTER AIR COND	1
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
A1834388002MOLD L/H	1
CA8193AIR FILTER 46744 WIX	1
DDE/9049900412EXHAUST BOLTS	2
KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2
R90PFILTER FUEL 33231	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V11687

In Date: 11/20/2007
Close Date: 11/29/2007

Meter Reading: 6,286.60

Problem?

patient area climate control A/C not coming on when plugged in. r55

Parts

Quantity

Task performed:

- 1. No rear 110 A/C, found breaker off.

NO PARTS USED

Workorder: V11705

In Date: 11/20/2007
Close Date: 11/29/2007

Meter Reading: 65,610.00

Problem?

repair air line to fan clutch r55

Parts

Quantity

Task performed:

- 1. Truck over heating found broken air line to engine fan, repaired.

NO PARTS USED

Workorder: V6297

In Date: 01/16/2007
Close Date: 12/10/2007

Meter Reading: 5,071.10

Problem?

front ac blowing only hot air R-55

Parts

Quantity

Task performed:

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V12146

In Date: 12/18/2007
Close Date: 12/31/2007

Meter Reading: 6,427.00

Problem?

air horn not working and the horn button not working the electronic siren.
R-55

Parts ----- Quantity -----

6804640043HORN CONTACT	1
------------------------	---

Task performed:

1. Repaired broken wire for horn siren button. 2. Coolent leak presure tested and found leak at coolent tank sender, repaired.

Workorder: V11451

In Date: 11/05/2007
Close Date: 01/15/2008

Meter Reading: 65,308.00

Problem?

repair flat tire r41 callaghan

Parts ----- Quantity -----

NO PARTS USED	
---------------	--

Task performed:

Repair flat tire R41 - Callaghan j

Vendor? *

Workorder: V12434

In Date: 01/08/2008
Close Date: 01/16/2008

Meter Reading: 68,058.00

Problem?

air dump malfunctioning R55

Parts ----- Quantity -----

NO PARTS USED	
---------------	--

Task performed:

1. Adjusted air bag switch and tested.



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V12461

In Date: 01/09/2008
Close Date: 01/25/2008

Meter Reading: 68,058.00

Problem?

air dump10-7 r55

Parts

Quantity

Task performed:

1. Rear dump Inop. Cleaned switches and tested.

NO PARTS USED

Workorder: V5345

In Date: 11/10/2006
Close Date: 02/07/2008

Meter Reading: 4,760.00

Problem?

main oxygen tank has a slow leak R55

Parts

Quantity

Task performed:

NO PARTS USED

Workorder: V13540

In Date: 02/27/2008
Close Date: 02/29/2008

Meter Reading: 70,382.00

Problem?

repair stretcher at sta 55 emsar

Parts

Quantity

Task performed:

Repair stretcher at Stn55 - Emsar j

NO PARTS USED

Vendor? MEDCO EQPMT



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V13592

In Date: 02/29/2008
Close Date: 03/04/2008

Meter Reading: 70,382.00

Problem?

REAR STEP 10-7

Parts ----- Quantity -----

Task performed:

1. NOT SERTED REAR STEP THAT WAS FALLING OFF.

NO PARTS USED

Workorder: V13600

In Date: 02/29/2008
Close Date: 03/13/2008

Meter Reading: 6,771.00

Problem?

the LED step light on the passenger side fell off. We have the light and the housing. It just needs to be put up again.

Parts ----- Quantity -----

Task performed:

1. Reconnected step light

NO PARTS USED

Workorder: V14112

In Date: 03/26/2008
Close Date: 04/18/2008

Meter Reading: 15,482.90

Problem?

left rear tire tread low on the bravo rescue Replace all 6 tires (outside agency-Callaghan tire)

Parts ----- Quantity -----

Task performed:

Left rear tire tread low on Bravo rescue; replace all (6) tires - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V14696

In Date: 04/25/2008
Close Date: 04/28/2008

Meter Reading: 73,489.00

Problem?

driver door handle exterior not working r55

Parts	Quantity
-------	----------

Task performed:

1. looked at door handle -not opening.drivers door lubed mec at this time.
2. lubed all doors. drove down and back.

6807600070HANDLE DOOR EXT L/H	1
-------------------------------	---

Workorder: V14597

In Date: 04/21/2008
Close Date: 04/30/2008

Meter Reading: 7,051.00

Problem?

R55B is idling very high while in park.

Parts	Quantity
-------	----------

Task performed:

1. checked operation of idel and found no problem.

NO PARTS USED	
---------------	--

Workorder: V12782

In Date: 01/23/2008
Close Date: 05/09/2008

Meter Reading: 68,882.00

Problem?

HORN ON STEERING WHEEL NOT WORKING THE SIREN. R55

Parts	Quantity
-------	----------

Task performed:

1. Replaced Horn/siren button on steering wheel.
2. Side entry door hard to open, readjusted door linkage.
3. Air leak found on brake fitting, removed and replaced.
4. Air packs falling out of brackets, readjusted brackets.

6804640043HORN CONTACT	1
------------------------	---



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V14650

In Date: 04/23/2008
Close Date: 05/14/2008

Meter Reading: 7,051.00

Problem?

whelen traffic advisor falling though console R-55

Task performed:

1. replaced traffic advisor that fell in dash

Parts	Quantity
01068234000CTACTLD1 CONTROL PANEL TRAFFIC	1

Workorder: V15338

In Date: 05/27/2008
Close Date: 06/02/2008

Meter Reading: 73,124.00

Problem?

ON CALL R55 DOOR LATCH 10-7

Task performed:

Call out to Stn55 to replc patient compt door handle/latch. j

Parts	Quantity
HND5948TM22676-02 HANDLE DOOR ENTRY	1

Workorder: V15235

In Date: 05/21/2008
Close Date: 06/05/2008

Meter Reading: 73,124.00

Problem?

repair stretcher lock r55

Task performed:

Replc stretcher latch that was broken. j

Parts	Quantity
090-0278STRECHER BAR NEW	2



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V15048

In Date: 05/13/2008

Meter Reading: 74,140.00

Close Date: 06/10/2008

Problem?

B INSPECTION AND REPAIRS AS NEEDED R55

Task performed:

1. B-Service 5/14/08 3.0 hrs 5/16/08 .5 hrs Total 3.5 hrs 2. Replcd all (4) btrys; rep positive jumper cable; recpld term end for negative ECM lead. 3 Replcd wiper blades. 4. Replcd T/S side marker lenses (cracked). 5. Replcd rear cab A/C filter. 6. Replcd pat compt A/C filter. 7. Replcd non skid on driver/pass steps. 8. Replcd flip up step on rear bumper. (bent/broken). 9. Replcd frt brake shoes. 10. Assist in 110V A/C unit replacement. 11. Replc 110V A/C roof unit for pat compt. 12. Troubleshoo long start times; Replcd primary fuel filter hsng cap. 13. Clean shop. j

Parts

Quantity

0000900087DDE/A0000900087 FILTER HEAD SM MEI	1
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	2
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
15W40BSYN OIL BULK QTS	24
52-24WIPER BLADES ANCO 24	2
78R536078R5360M 2PK FILTER AIR COND	1
91513AMBER LENS	2
ACX-84534LUG NUT COVER PK10	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
HP-31DBATTERY 950CCA HP-31D	4
KSMA2124703QFRONTBRAKE KIT RUMPER AND 4D	2
MFG9980B351262 FOLDING STEP 45.25	1
R90PFILTER FUEL 33231	1
UNT620515USE CARRIER	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V16576

In Date: 07/24/2008
Close Date: 08/04/2008

Meter Reading: 7,408.00

Problem?

need new stretcher hook installed r55

Task performed:

Installed by shop. j

Parts	Quantity
HA49102C2-32-15 LATCH NON LOCKING	2

Workorder: V16822

In Date: 08/04/2008
Close Date: 08/20/2008

Meter Reading: 76,970.60

Problem?

Move Stryker stretcher bracket over and add additional bracket to R56 (old r55b) Per BC5.

Task performed:

1. Met with Chief & chkd problem with stretcher. 2. Air leak; air bag air valve sent to shop to have valve replaced. j

Parts	Quantity
NO PARTS USED	

Workorder: V17895

In Date: 09/23/2008
Close Date: 10/07/2008

Meter Reading: 725.00

Problem?

dash a/c not blowing cold. please have checked. R-55

Task performed:

1- RAN CAB AC AND FOUND WORKING AT THIS TIME. 2- AIR HORN INOP- REPAIRED AIR HORN SOLONID THAT WAS LEAKING WHEN ACTIVATED.

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V17993

In Date: 09/28/2008
Close Date: 10/07/2008

Meter Reading: 7,676.00

Problem?

CHECK OUT TIMER LIGHTS NOT WORKING IN BACK OF RESCUE 55B

Parts ----- Quantity -----

Task performed:

1- INSTALLED NEW BULBS FOR PT LIGHTS THAT WERE OUT. 2- REAR PT AC SHUTS ON AND OFF, TRACE OUT PROBLEM FOUND, BAD CONNECTION ON BREAKERS.

NO PARTS USED

Workorder: V18684

In Date: 10/29/2008
Close Date: 11/06/2008

Meter Reading: 7,798.00

Problem?

Replace front two tires on R55b. Low tire tread. Drivers side tire is wearing out sooner than the other tires.

Parts ----- Quantity -----

Task performed:

Chkd tires & needs all six. j

NO PARTS USED

Workorder: V19122

In Date: 11/17/2008
Close Date: 11/26/2008

Meter Reading: 7,889.00

Problem?

R55b will not start

Parts ----- Quantity -----

Task performed:

No Start; defective fuel pump T-shoot & replc fuel pump. j

0000900087DDE/A0000900087 FILTER HEAD SM MEI	1
0000902051FILTER FUEL 03 MERCEDES	1
359-5915359-5915 OIL PLUG	2
9060910580FUEL PUMP GASKET M2	1
DDE-R0040910501FUEL PUMP M2	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V19133

In Date: 11/18/2008

Meter Reading: 81,278.00

Close Date: 12/04/2008

Problem?

C INSPECTION AND REPAIRS AS NEEDED R55

Parts

Quantity



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Task performed:

C-Inspection (Murray) 2. Svc air dryer & purge valve. 3. C-Inspection (Hoover) 4. UV lights inop; installed new bulb & cldn evaporator. 5. L/R ca door handle falling off; wedge fell out; isntalled wedge. 6. Pain fuel cap. 7. Install new wiper blades & washer fluid. 8. Replcd 110V btry charge indicator. 9. Trans interlock switch brokn; installed new. 10. Cab A/C low/med fan inop;; installed new resistor. 11. Electric horn inop; lost communication w/node #1; cleared & inspect connections & reprogram node. 12. Washers inop; tank leaks; replcd washer tank. 13. Replcd side pat compt door handle; insert & bolt. 14. Replce O2 fitting. 15. Replcd RF door swtch; fish wiring stuck in post; replcd LR door swtch. 16. replcd water pump. j

0127110042BELT MERCEDES MOTORS	1
032-0116549297 BATTERY INDICATOR	1
109995PURGE VALVE KIT	1
11-06131229 RESISTER BLOWER	1
1654-8FERRULE .718	2
22-40867-000RESERVOIR	1
4626BPMR7A SPARK PLUG	1
5008414CARTRIDGE DC100	1
52-24WIPER BLADES ANCO 24	2
605-2HOSE END-FEMALE	1
6806890001LOCK DASH	2
78R536078R5360M 2PK FILTER AIR COND	1
9062010080GASKET M2 WATER PUMP	1
9062030015PIPE SOCKET TO WP	1
91823SWITCH SWT5499 MED MASTER	2
921LIGHT BULB	2
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
A1834388002MOLD L/H	1
AEVDOOR LOCK BEZEL	1
DDE-0052035975A0052032675 THERMOSTAT ELEMI	2
DDE-9062030180GASKET SOCKET TO HEAD M2	2
DDE/0209971148A0249972848 SEAL RING	2
DDE/R9062006201RA906200620 WATER PUMP REM	1
DOOR5LEXAN 9 X 38 1/2 IN	1
EXO3AH00015SPLUG RAD. DRAIN	1
M54-13SPM5413 NIPPLE	1
N917003022003GASKET/SEAL M2 WATER PUMP	1
S777COUPLING NIPPLE	1
SWT5492744435 ACTUATOR-BLACK	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V19140

In Date: 11/18/2008 Meter Reading: 81,278.00
Close Date: 12/05/2008

Problem?

TOW UNIT FROM STA 55 TO SHOP

Parts ----- Quantity -----

Task performed:

Tow unit from Sta 55 to Shop Sisters Towing MG

NO PARTS USED

Vendor? SISTERS TOWING

Workorder: V19335

In Date: 11/25/2008 Meter Reading: 81,278.00
Close Date: 12/08/2008

Problem?

REPAIR SEATS CENTRAL AUTO TRIM

Parts ----- Quantity -----

Task performed:

Repair seats - Central Auto Trim j

NO PARTS USED

Vendor? CENTRAL AUTO

Workorder: V19344

In Date: 11/25/2008 Meter Reading: 81,278.00
Close Date: 12/08/2008

Problem?

REPLACE TIRES AT SHOP

Parts ----- Quantity -----

Task performed:

Replace tires at shop - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V19119

In Date: 11/17/2008
Close Date: 12/09/2008

Meter Reading: 81,278.00

Problem?

FRONT END ALIGNMENT R55

Parts

Quantity

Task performed:

Front end alignment R55 - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V20868

In Date: 02/04/2009
Close Date: 02/23/2009

Meter Reading: 84,434.00

Problem?

slide-in signs too large-cut to fit bracket R56

Parts

Quantity

Task performed:

Cut off 3/8" from slide in in signs to fit frame; modify frame. j

NO PARTS USED

Workorder: V21031

In Date: 02/10/2009
Close Date: 02/25/2009

Meter Reading: 8,237.30

Problem?

front cab a.c. blowing hot air and rear front cab a.c. also blowing hot air R-55

Parts

Quantity

Task performed:

1. A/C blowing warm; fnd heater valve on; adj valve. 2. Fan speed inop; replcd blower swtch. j

ABPN8332229011-3050 SWITCH BLOWER

1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V21391

In Date: 02/27/2009
Close Date: 03/05/2009

Meter Reading:

Problem?

mechanism which retains the stretcher in the rescue is being difficult when securing stretcher R55

Parts ----- Quantity -----

Task performed:

Stretcher not latching; replcd latch for stretcher. j

090-0278STRECHER BAR NEW	1
--------------------------	---

Workorder: V21430

In Date: 03/01/2009
Close Date: 03/09/2009

Meter Reading: 85,680.00

Problem?

120 volt ac connection on truck not working for camper ac. Shore power good, problem in in the truck We verified this by switching the trucks in the bay. R-55

Parts ----- Quantity -----

Task performed:

110 A/C inop; fnd breaker needed to be reset. j

NO PARTS USED	
---------------	--

Workorder: V22362

In Date: 04/06/2009
Close Date: 04/17/2009

Meter Reading: 8,497.00

Problem?

driverside headlight out on rescue 55

Parts ----- Quantity -----

Task performed:

Replcd headlight j

NO PARTS USED	
---------------	--



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V22893

In Date: 04/29/2009
Close Date: 05/08/2009

Meter Reading: 8,622.70

Problem?

check veh. for air leak...R-55

Parts

Quantity

Task performed:

1. Air leak; chkd for air leaks & chkd ok. 2. Rear load lights inop; rep bad connection in light bar. j

NO PARTS USED

Workorder: V23302

In Date: 05/15/2009
Close Date: 05/15/2009

Meter Reading: 89,374.90

Problem?

repair seat R55 (outside agency-central auto trim)

Parts

Quantity

Task performed:

NO PARTS USED

Vendor? CENTRAL

Workorder: V22997

In Date: 05/04/2009
Close Date: 05/20/2009

Meter Reading: 89,093.00

Problem?

AIR LEAK, R-56

Parts

Quantity

Task performed:

Traced out air leaks & rep where needed. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V23231

In Date: 05/12/2009

Meter Reading: 89,374.90

Close Date: 05/26/2009

Problem?

B inspection and related repairs R55

Task performed:

Perform B-Service 2. R/R driver's seat to be sent to upholstery shop. 3. Peicer inop; tried to fix; had to replc (shorted). 4. Replcd rear cab A/C filter. 5. Replcd T/S side marker lens & bulb. 6. Replcd wiper blades. 7. Replcd exh flex pipe at muffler. 8. Svc air brake dryer. 9. Replcd D-2 air gov. 10. Replcd rear axle drums/shoes. 11. Replcd left/right A/C vents 12. Replcd squad bench shocks. 13. Replcd driver's door out handle/latch (brokn). 14. Replcd left/right flag stickers on rear of body. 15. Cln shop after PM. j

Parts

Quantity

0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
02-0361112-00MICRO SIDE BEAM STROBE ASSY	1
109995PURGE VALVE KIT	1
194BULB	10
20A-400CLAMP 4" 33969	2
284358GOVERNOR D-2	1
3744BRAKE DRUM REAR	2
40022STAINLESS FLEX PIPE 4"	1
5008414CARTRIDGE DC100	1
52-24WIPER BLADES ANCO 24	2
680-10LAMERICAN FLAG W UV CLEAR LEFT	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
6807600070HANDLE DOOR EXT L/H	1
6808300074VENT A/C LH	1
6808300174VENT A/C RH	1
78R536078R5360M 2PK FILTER AIR COND	1
91513AMBER LENS	1
ACX-84534LUG NUT COVER PK10	2
GSS1717UL1717UL0270N 343/09 GAS SHOCK 60 LB	2
KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2
PRMISCCNLA PIERCER 2 DUAL STROBE	1
R90PFILTER FUEL 33231	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V23470

In Date: 05/22/2009
Close Date: 06/02/2009

Meter Reading: 8,695.10

Problem?

front headlight out passenger side R-55

Parts ----- Quantity -----

Task performed:

Headlight inop; replcd headlight. j

H6054USE CV TYPE SEALED BEAM	6
------------------------------	---

Workorder: V23696

In Date: 06/01/2009
Close Date: 06/04/2009

Meter Reading: 90,218.00

Problem?

repair flat tire callaghan

Parts ----- Quantity -----

Task performed:

NO PARTS USED	
---------------	--

Vendor? CALLAGHAN

Workorder: V23241

In Date: 05/12/2009
Close Date: 06/05/2009

Meter Reading: 89,374.90

Problem?

replace 2 front tires R55 (outside agency-callaghan tire)

Parts ----- Quantity -----

Task performed:

NO PARTS USED	
---------------	--

Vendor? CALLAGHAN



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V23637

In Date: 05/29/2009
Close Date: 06/19/2009

Meter Reading: 8,717.00

Problem?

The box doesn't lift out of the dumped position. r55

Parts ----- Quantity -----

Task performed:

1. Rear dump; installed two level valves & retested. 2. Rear A/C; recharge rear A/C. j

S4640024430VALVE LEVELIN 2

Workorder: V23767

In Date: 06/03/2009
Close Date: 06/19/2009

Meter Reading: 8,742.00

Problem?

Rear passanger side dump not rising up completely. Rear door weather molding on drivers side came apart needs a new one. r55

Parts ----- Quantity -----

Task performed:

1. Readj rear linkage for air bags & road tested. 2. Rep molding arnd rear door. j

NO PARTS USED

Workorder: V23773

In Date: 06/03/2009
Close Date: 06/19/2009

Meter Reading: 90,218.00

Problem?

ON CALL PAITIENT DOOR WONT OPEN R55

Parts ----- Quantity -----

Task performed:

Rear door not opening; readj rear door linkage. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V24181

In Date: 06/18/2009
Close Date: 06/29/2009

Meter Reading: 90,848.00

Problem?

TURBO 10-7 R55

Task performed:

1. Ck turbo; fnd turbo bad & blowing oil; rem clnr, tubes, oil lines, brkts, inter cooler, hood springs & cables & turbo asy; replcd turbo & reinstalled all parts; test drive; ck for leaks & opn; ck ok. 2.A-Inspection 3. Ck for coolant leak; fnd level low; added antifreeze; press test cooling sys; ck for leak;s none fnd; press test rad cap; cap bad; replcd cap. 4. Windhsiedl washer inop; fnd hose fitting brkn; R/R hose fitting; ck opn; ck ok. 5. Replcd (3) door seals. 6. Replcd pass frnt door latch & pass rear door latch. 7. Fnd (2) cyl lights out; R/R bulbs; rep grnd; ck ok. 8. Ck door adjustment on pat doors; adj door pins; fnd L. rear compt door damaged; bent on top; straighten door & rep , glued weatherstrip. 9. Adj bake travel adj brake rod; ck opn; ck ok. 10. Ck alignment; ck Toe; 11. Ck for noise in cab; fnd center console fan making noise; clnd ran; ck ok. j

Parts

Quantity

05-17223-000CAP RADIATOR 10 LB	1
18-29935-001RH DOOR LATCH NEW	2
6806970098SEAL DOOR	1
CLEAN AND TESTCOOLER/RADIATOR	4
DDE-00000001069USE V007603014104 SEAL WASH-	2
DDE-5411870080GASKET OIL RETURN TUBE TURB(1
DDE/A0039973352EGR COOLING HOSE	1
RA9060968899TURBOCHARGER	1
SPR-W58-1TEE PLASTIC	1

Workorder: V24006

In Date: 06/11/2009
Close Date: 07/06/2009

Meter Reading: 8,775.00

Problem?

auto eject for the shoreline charger not ejecting correctly r55

Task performed:

1. Auto-eject inop; replcd aut-eject. 2. Rear A/C warm; recharged sys. j

Parts

Quantity

NO PARTS USED	
---------------	--



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V24159

In Date: 06/17/2009
Close Date: 07/06/2009

Meter Reading: 8,806.00

Problem?

Vehicle had a pop/banging sound from the engine followed by a whining noise (poss turbo) upon repending to call. crews checked uder the vehicle and found oil leaking from bottom of motor. vehicle is currently oos. r55

Parts ----- Quantity -----

Task performed:

road tested; swapout truck due to bad turbo. j

NO PARTS USED

Workorder: V24162

In Date: 06/17/2009
Close Date: 07/10/2009

Meter Reading: 90,848.00

Problem?

tow unit to shop sisters

Parts ----- Quantity -----

Task performed:

Tow unit to shop - Sisters j

NO PARTS USED

Vendor? SISTERS

Workorder: V24759

In Date: 07/14/2009
Close Date: 07/29/2009

Meter Reading: 9,094.00

Problem?

Spring in drivers seat poking out about quarter inch bottom cushion. Drivers getting their pants caught on it. r55

Parts ----- Quantity -----

Task performed:

1. Dri vers spring out of seat; rep seat. 2.)2 leak; chkd for O2 leak & rep.
3. Rear light bar inop; rep bad connection. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V25314

In Date: 08/05/2009
Close Date: 08/24/2009

Meter Reading: 8,970.00

Problem?

Patient enter/exit door on the rear box can't open from the inside. R-55

Parts ----- Quantity -----

Task performed:

Rear door inop; rep rear door latch. j

HAN-1LBEZEL AND HANDLE	2
------------------------	---

Workorder: V25523

In Date: 08/14/2009
Close Date: 09/11/2009

Meter Reading: 955.30

Problem?

Horn will not activate the change of the siren. R-55

Parts ----- Quantity -----

Task performed:

1. Air horn inop; rep hrn botton. 2. Air leak; fnd no air leaks. j

NO PARTS USED	
---------------	--

Workorder: V25559

In Date: 08/16/2009
Close Date: 09/11/2009

Meter Reading: 955.30

Problem?

Poss. A/C freon leak at fire wall in front of the drive. Fumes coming into the cab. Also steering wheel horn not working during noraml operation and will not change siren/sounds during emergency operations R55

Parts ----- Quantity -----

Task performed:

1. Fuel leak; chkd for fuel leak; fnd at injectors; rep/tested. 2. Horn button inop; rep brkn wires. j

NO PARTS USED	
---------------	--



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V26101

In Date: 09/08/2009
Close Date: 09/21/2009

Meter Reading: 93,767.00

Problem?

ON CALL R55 A/C 10-7

Parts ----- Quantity -----

Task performed:

A/C harness melted at inline fuse; cut out faulty wirind; rep harness & ran A/C to observe; all ok. j

NO PARTS USED

Workorder: V26487

In Date: 09/27/2009
Close Date: 09/30/2009

Meter Reading: 1,138.60

Problem?

Trucks air tanks leaking. While truck sits in the bay. Trucks air tanks are full when shut down. It taking time on our response to a call. E55

Parts ----- Quantity -----

Task performed:

1. Air leak; replc air horn solenoid. 2. Replcd both rear axle air bags. 3. Replc R/R mud flap. 4. Realigned air b ag linkage; cut off access rod; adj ride height. j

16-15762-00016-19471-000 AIR BAG	2
B2420LP-SMUD FLAP 24 X 24	1
HDY-H005700SOLENOID HORN AIR	1

Workorder: V26498

In Date: 09/28/2009
Close Date: 10/06/2009

Meter Reading: 1,138.60

Problem?

This morning both air tanks at 25 psi for the brakes and the dump on the rescue SR AT 25

Parts ----- Quantity -----

Task performed:

drive to Stn; tightene fitting on air brake valve & look for more air leaks; fitting in dash leaking replced test ok. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V26544

In Date: 09/29/2009 Meter Reading: 94,506.80
Close Date: 10/15/2009

Problem?

replace rear tires at 55 callaghan

Parts ----- Quantity -----

Task performed:

Replace reaar tires at 55 - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V26720

In Date: 10/07/2009 Meter Reading: 1,184.70
Close Date: 10/21/2009

Problem?

Air leak in the system. R55 air tanks both leak down to 75psi in both tanks overnight. Our last call both tanks were full and the relief valves went off, th truck was shut down no one entered the rear of the rescue. R55

Parts ----- Quantity -----

Task performed:

Air horn valve leaking; rem/replc. j

NO PARTS USED

Workorder: V26785

In Date: 10/09/2009 Meter Reading: 95,148.00
Close Date: 10/21/2009

Problem?

Brake air pressure drops more than normal on brake application R55

Parts ----- Quantity -----

Task performed:

1. Traced air problem to faulty valve in air dryer; rebuilt air dryer & replcd faulty valve. 2. Rep numerous leaks in air tanks; replcd pull type drains w/Petcock type drains. j

109995PURGE VALVE KIT	1
5005624SINGLE CHECK VALVE KIT	1
5008414CARTRIDGE DC100	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V26356

In Date: 09/21/2009
Close Date: 11/06/2009

Meter Reading: 94,282.90

Problem?

REAR A/C 10-7 R55

Parts ----- Quantity -----

Task performed:

1. Recharged rear A/C & tested. 2. Stretcher latch inop; rep/tested. j

NO PARTS USED

Workorder: V26455

In Date: 09/24/2009
Close Date: 11/06/2009

Meter Reading: 1,138.60

Problem?

check transmission light come on after truck has been running during a call
Transmission fluid shows full on the dip stick R-55

Parts ----- Quantity -----

Task performed:

Road tested; fnd no problem w/trans. j

18-36797-000HOUSING SHIFT PAD ASSY	1
2953837329538373 TRANS KEY PAD	1

Workorder: V26838

In Date: 10/13/2009
Close Date: 11/12/2009

Meter Reading: 95,324.00

Problem?

R55 a/c front/back not blowing cold air

Parts ----- Quantity -----

Task performed:

1. Air gov inop; replc air gov. 2. Recharged rear A/C. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V26445

In Date: 09/24/2009
Close Date: 11/23/2009

Meter Reading: 1,138.60

Problem?

one set of Flourescent lights out inside Patient compartment r55

Parts _____ Quantity _____

Task performed:

1. Installed new lights in rear for pat compt. 2. Recharged rear A/C. j

NO PARTS USED

Workorder: V27278

In Date: 10/29/2009
Close Date: 12/09/2009

Meter Reading: 1,270.50

Problem?

R55 alignment significantly off to the right. r55

Parts _____ Quantity _____

Task performed:

1. road tested for alignment & tested ok. 2. Rear dome lights out; rep connection. j

NO PARTS USED

Workorder: V27361

In Date: 11/02/2009
Close Date: 12/09/2009

Meter Reading: 9,352.00

Problem?

lights out in patient compartment r55

Parts _____ Quantity _____

Task performed:

Replcd lights in rear. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V27867

In Date: 11/23/2009

Meter Reading: 97,265.40

Close Date: 01/05/2010

Problem?

C INSPECTION AND REPAIRS AS NEEDED R55

Task performed:

C-Inspection 2. Not bldg air in secondary 80 PSI-chk valve in split tank betwn. 3. Replc inner cabinet struts-worn; replcd/adj latch mechanism. 4. Svc air dryer. 5. Btry tray wont open; clnd dirt/grease. 6. Replc air dryer asy - loaded w/trash. 7. A/C filters dirty; replc/clnd A/C filters as needed. 8. Air gov hanging down-bolt msng; reinstalled gov. 9. Replc air tank; chk valve hanging up; replc split tank. 10. Replc grille-brkn; swapped LEDs/nb placard; replc well nuits as needed. 11. Horn inop-electric ; contactor in horn buttons loose; rep. 12. R/R cab door light inop; wire off @swtch; rep wiring connector. 13. Medic drawers difficult to open; slider screws loose; rep mntng. 14. Air leaks down dash valve; replc parking brake valve. 15. Svc rear doors & tighten panels; replcd loose msng/stripped screws. 16. Made/installed cvr for fan in cab compt. 17. Cab light bar rear facing LEDs inop; fnd wire cut frm node; rep wiring/replc brkn light hodlers in light bar. 18. Lug nug cvrs msng; installed used lug nut cvrs. 19. L/R/I tire low-valve core loose; locate leak/tightened valve core. 20. Adj toe in/out 1/32. 21. Pat compt 110V A/C inop; unit not turning on; T-shoot; fnd problem; replc 110V A/C. 22. UV light inop-socket; replc UV asy. 23. Air pack brkts loose; bolts loose/msg; tightened air pack brkts. 24. Paint fuel cap. j

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
02034293401DIVIDER 4500 LITE BAR	2
109995PURGE VALVE KIT	1
15W40BSYN OIL BULK QTS	28
194BULB	10
5008414CARTRIDGE DC100	1
52-24WIPER BLADES ANCO 24	2
6804320901AIR TANK	1
78R536078R5360M 2PK FILTER AIR COND	1
800034VALVE PARKING BRK.	1
800887AD-SP DROP IN DRYER COMPLETE	1
A17-14768-000FL60 GRILLE	1
CA8193AIR FILTER 46744 WIX	1
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
HLD3999GSS1715UV 30LB STRUT GAS	8
R90PFILTER FUEL 33231	1
TRANSYNDALLISON TRANS FLUID GAL	5
UNT620515USE CARRIER	1
UVAPS253 UNIT UV LIGHT A/C RESCUES	1
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V28169

In Date: 12/07/2009
Close Date: 01/15/2010

Meter Reading: 97,265.40

Problem?

replace front tires callaghan

Parts ----- Quantity -----

Task performed:

Replace front tires - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V29208

In Date: 01/17/2010
Close Date: 02/10/2010

Meter Reading: 1,596.90

Problem?

Front cab A/C not blowing cold air R55

Parts ----- Quantity -----

Task performed:

Chk A/C; add 1 lb freon; chk for leaks; fnd suction line on expansion valve loose; tighten & rechk; ok. j

NO PARTS USED

Workorder: V29574

In Date: 02/01/2010
Close Date: 02/18/2010

Meter Reading: 9,929.20

Problem?

passenger side head light out, no replacement at the station. low beam out hign beam still works. r55

Parts ----- Quantity -----

Task performed:

1. Replcd headlight & relined headlights. 2. Right side door molding brkn; rem/replcd. j

A1834388003MOLD R/H	1
H6054USE CV TYPE SEALED BEAM	4



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V28741

In Date: 01/01/2010
Close Date: 02/22/2010

Meter Reading: 9,772.50

Problem?

officer's seat air pressure will not stay inflated R55

Parts ----- Quantity -----

Task performed:

Rep air line under seat. j

NO PARTS USED

Workorder: V28747

In Date: 01/02/2010
Close Date: 02/22/2010

Meter Reading: 9,772.50

Problem?

Officer's air seat will not stay inflated E55

Parts ----- Quantity -----

Task performed:

Rep air line. j

NO PARTS USED

Workorder: V29818

In Date: 02/08/2010
Close Date: 03/01/2010

Meter Reading: 10,013.90

Problem?

AC IS BLOWING HOT AIR.. r55

Parts ----- Quantity -----

Task performed:

Chk A/C in cab- blows warm; fnd red dot A/C fans inop; chk wiring; fnd relay wire not secure in butt connection; install new connector; rechk - blows cold. j

X170DECK GUN ROTATION LOCK INSERT 1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V29656

In Date: 02/02/2010 Meter Reading: 10,013.90
Close Date: 03/02/2010

Problem?

repair electrical problem r55 atlantic truck

Parts ----- Quantity -----

Task performed:

Rep electrical problem R55 - Atlantic Truck j

NO PARTS USED

Vendor? ATLANTIC TRUCK

Workorder: V29849

In Date: 02/10/2010 Meter Reading: 10,013.90
Close Date: 03/03/2010

Problem?

Front A/C fan no working, not blowing any air. R55

Parts ----- Quantity -----

Task performed:

Installed new cab A/C fan switch. j

NO PARTS USED

Workorder: V29413

In Date: 01/25/2010 Meter Reading: 1,596.90
Close Date: 03/19/2010

Problem?

One set of fluorescent lights out in patient compartment R55

Parts ----- Quantity -----

Task performed:

1. Installed new lights in pat compt. 2. Coolant leak; rep hose clamps. j

F30T8-CWUSE F25T8 4V439 BULB 2



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V29589

In Date: 02/01/2010
Close Date: 03/19/2010

Meter Reading: 10,013.90

Problem?

WIRE BURNT IN HARNESS R55

Parts ----- Quantity -----

Task performed:

Eng fire wires melted; towed to shop. j

NO PARTS USED

Workorder: V30041

In Date: 02/18/2010
Close Date: 03/26/2010

Meter Reading: 102,459.90

Problem?

grinding noise in engine r53

Parts ----- Quantity -----

Task performed:

Noise from eng; replcd A/C bearing. j

203FFBEARING PULLEY 1

Workorder: V30344

In Date: 03/01/2010
Close Date: 03/26/2010

Meter Reading: 101,917.00

Problem?

cannot get heater off... a/c is stuck on heat R55

Parts ----- Quantity -----

Task performed:

Readj heater cable. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V24543

In Date: 07/02/2009

Meter Reading: 8,837.00

Close Date: 04/13/2010

Problem?

Side enter/ext door of patient compartment will not open to exit R55

Parts

Quantity

Task performed:

see 25314

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V31331

In Date: 04/07/2010

Meter Reading: 104,034.10

Close Date: 05/03/2010

Problem?

B INSPECTION AND REPAIRS AS NEEDED R55

Task performed:

B-Inspection 2. Secured lower shock bolts. 3. rem (4) rear tires. 4. Replcd brkn support clamp for heater hoses. 5. Too much free trael in brake peda; adj free travel. 6. Replcd driveers door molding; L/R molding & RF door molding. 7. Replcd LF & RF outer doorhandle. 8. Replcd RF & LF inner door handle. 9. lube all body & cab doors. 10. Rear tires worn; R/R rear tires. 11. Secured body damage on L-3 rear door. 12. Pat compt doors hard to open; adj linkage on all (3) doors. 13. Door handle cvrs brkn; replc both rear handle cvrs. 14. Adj/tightened rear door hold open. 15. Replcd drawer latch in pat compt. 16. Replc RFsignal lens. 17. Replcd btry switch. 18. Started replcng belts/tensioner completed. 19. Replcd A/C vents in cab. 20. Replcd rear A/C filter. 21. Air line to fan clutch had a quick connect hitting inside fan shroud; replc line & made connection outside of fan shroud. 22. Replcd cab spotlight; old lite inop. 23. replcd inop maplite. 24. Brk valve in dash loose; rem dash panel & secured brkt for valve ok. 25. Adj tire press. 26. Evac/recharge cab & rear A/C. 27. Adj air horns. 28. Replcd LF headlite bezel & dash lite sockets. j

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
0127110042BELT MERCEDES MOTORS	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	24
4923090025DASH BULB VDO	3
68054400K0BEZEL HEADLIGHT	1
6807200575HANDLE DOOR	2
6807600070HANDLE DOOR EXT L/H	1
6807600170HANDLE DOOR EXT. R/H	1
6808300074VENT A/C LH	2
6808300174VENT A/C RH	2
72R311018-2640 VENT A/C NEW # 1719	2
75908SWITCH BATTERY MASTER 300A	1
9150391503 LENS AMBER	1
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	1
DDE/9062002470BELT TENSIONER MERCEDES	1
HAN-1LBEZEL AND HANDLE	2
LF18TS-LEDMAP LIGHT LED 18 IN	1
LTC5993SSM1-63-8 LATCH STAINLESS	1
R90PFILTER FUEL 33231	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V31391

In Date: 04/09/2010 Meter Reading: 104,034.10
Close Date: 05/11/2010

Problem?

replace rear tires r55 boulevard

Parts ----- Quantity -----

Task performed:

Replace rear tires R55 - Boulevard j

NO PARTS USED

Vendor? BOULEVARD TIRE

Workorder: V32321

In Date: 05/19/2010 Meter Reading: 105,749.30
Close Date: 06/10/2010

Problem?

pt compartment check-out lights inop R55

Parts ----- Quantity -----

Task performed:

Replcd bulb in rear. j

NO PARTS USED

Workorder: V31390

In Date: 04/09/2010 Meter Reading: 104,034.10
Close Date: 06/14/2010

Problem?

repair seat central

Parts ----- Quantity -----

Task performed:

Repair seat - Central Auto j Repair flat tire - Boulevard j

NO PARTS USED

Vendor? BOULEVARD TIRE



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V32950

In Date: 06/16/2010
Close Date: 06/22/2010

Meter Reading: 106,936.00

Problem?

PAITIENT A/C 10-7

Task performed:

1. Fnd clutch coming apart component A/C compressor; R/R compressor.
2. Assisted in finishing A/C repair. Reines j

Parts	Quantity
-------	----------

532703-0602 COMPRESSOR U4735 4471	1
-----------------------------------	---

Workorder: V32945

In Date: 06/16/2010
Close Date: 07/21/2010

Meter Reading: 106,936.00

Problem?

Smell of burning rubber from the A/C vents of R55.

Task performed:

Fnd A/C compressor locked up; sent to shop. j

Parts	Quantity
-------	----------

NO PARTS USED	
---------------	--

Workorder: V33440

In Date: 07/09/2010
Close Date: 08/02/2010

Meter Reading: 107,984.30

Problem?

stretcher horn lock broken R55

Task performed:

Stretcher horn brkn; Replcd stretcher horn. ja

Parts	Quantity
-------	----------

0200271ANTLER BAR	1
-------------------	---



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V33720

In Date: 07/22/2010
Close Date: 08/16/2010

Meter Reading: 108,486.70

Problem?

REAR DRIVER-SIDE PASSENGER SEAT SEATBELT WILL NOT SECURLY CLIP-IN. PERSONNEL HAD HARD TIME SECURING SEATBELT YESTERDAY DURING EVOC. r55

Parts ----- Quantity -----

Task performed:

1. Seat belt inop; tested seat belt & fnd unit working. 2. Air leak; tested for air leaks; fnd none at this time. ja

NO PARTS USED

Workorder: V34253

In Date: 08/13/2010
Close Date: 08/26/2010

Meter Reading: 109,442.00

Problem?

a inspection and repairs

Parts ----- Quantity -----

Task performed:

A-Inspection 2. Replc wiper blades. 3. Replc btrys. ja

R90PFILTER FUEL 33231 1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V34514

In Date: 08/25/2010

Meter Reading: 109,717.00

Close Date: 09/13/2010

Problem?

C INSPECTIOJN AND REPAIRS AS NEEDED R58

Task performed:

C-Inspection 2. Replc eng air filter. 2. Svc diff. 4. Svc trans. 5. Svc air brake dryer. 6. Rep door latch on Left/rear SCBA door & installed new rubber bumper. 7. Replc read cab A/C filter. 8. Replcd wiper blades. 9. Painted fuel cap. 10. Rem station logo stickers. 11. Replcd both R/side door trims-brkn. 12. Replcd rear axle brake shoes/hardware - worn. 13. C/O air leak; traced leak to ABS tripple valve on rear axle; changed valve asy & rechkd; no addiitonal leaks fnd. 14. Replcd non-skid on cab steps both sides - worn. 15. Replcd msgng lugnut cvrs. 16. Rem/clnd/reinstall gskts frm all (4) rear entry door windows-fall off. 17. Lube/adj/tightened all door latches, hinges & holdopens-loose/misadju/seized. 18. Remntd/sec SCBA brkts in both rear seats-improperly mntd. 19. Straightened out drivers seat belt-twisted. 20. Replcd R/rear pat compt dome light bult-burn. 21. Replcd left, frnt siren speaker. 22. Replcd both air horn stabilizer brkt insulators-rotted/msgng. 23. Rem squad bench seat belts; untwist/reinstall.

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
109995PURGE VALVE KIT	1
15W40BSYN OIL BULK QTS	24
29526898 29548988 TRANS FILTER ALLISON	14
322502BULB PATIENT GH22	1
472-500-121-0ABS ASSBLY	1
5008414CARTRIDGE DC100	1
52-24WIPER BLADES ANCO 24	2
78R536078R5360M 2PK FILTER AIR COND	1
A1834388003MOLD R/H	2
ACX-84534LUG NUT COVER PK10	3
CA8193AIR FILTER 46744 WIX	1
CH27007BUMPER DOOR	1
GRV1720244770R1 HORN SUPPORT BRKT	2
KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2
R90PFILTER FUEL 33231	1
SD-210RXSIREN DRIVER SMALL	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V34671

In Date: 09/01/2010
Close Date: 09/27/2010

Meter Reading: 109,214.00

Problem?

SET UP UNIT FOR SERVICE R58

Task performed:

Set unit up for svc. j

Parts	Quantity
L PLACARDLARGE SIDE PLACARD	1
L PLACARD INSERTLARGE PLACARD INSERT CARL	2
S PLACARDFRONT AND BACK PLACARD	1

Workorder: V34257

In Date: 08/13/2010
Close Date: 09/28/2010

Meter Reading: 97,265.40

Problem?

replace front tires (outside agency-boulevard tire)

Task performed:

Replc frnt tires - Boulevard j

Parts	Quantity
NO PARTS USED	

Vendor? BOULEVARD

Workorder: V33832

In Date: 07/27/2010
Close Date: 10/19/2010

Meter Reading: 108,938.00

Problem?

Dash warning light on, Water in Fuel R55

Task performed:

completed j

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V35117

In Date: 09/22/2010
Close Date: 11/01/2010

Meter Reading: 109,214.00

Problem?

install regulator on m tank in L1 and mount haligan in L2 R58

Parts ----- Quantity -----

Task performed:

1 Mount haligan in L2 of R58 2 REPLACE REG ON M TANK in L1 THAT I
LEAKING O2

NO PARTS USED

Workorder: V35942

In Date: 10/26/2010
Close Date: 12/22/2010

Meter Reading: 109,780.70

Problem?

plastic trim around r/f headlight missing screw; cannot put another
in;possibly broken e58

Parts ----- Quantity -----

Task performed:

NO PARTS USED

Workorder: V36962

In Date: 12/07/2010
Close Date: 01/11/2011

Meter Reading: 110,385.00

Problem?

front drivers side head light is burned out. r58

Parts ----- Quantity -----

Task performed:

1. Replcd headlight. 2. Readj all cab doors that was hard to open. j

H6054USE CV TYPE SEALED BEAM 2



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V37524

In Date: 12/31/2010
Close Date: 02/08/2011

Meter Reading: 110,609.00

Problem?

A/C in front cab blowing hot air. R58 Thanks Barry

Parts ----- Quantity -----

Task performed:

Recharged sys & rep leak. j

NO PARTS USED

Workorder: V37891

In Date: 01/19/2011
Close Date: 02/08/2011

Meter Reading: 110,609.00

Problem?

R58 has significant leak in main o2.

Parts ----- Quantity -----

Task performed:

Rep O2 leak at bottle. j

NO PARTS USED

Workorder: V38529

In Date: 02/15/2011
Close Date: 03/10/2011

Meter Reading: 111,448.70

Problem?

INSTALL NUMBER PLATES ON UNIT

Parts ----- Quantity -----

Task performed:

installed number plates. j

L PLACARDLARGE SIDE PLACARD	2
L PLACARD INSERTLARGE PLACARD INSERT CAR	2
S PLACARDFRONT AND BACK PLACARD	2
S PLACARD INSERTFRONT AND BACK INSERT CAR	2



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V38716

In Date: 02/23/2011
Close Date: 03/15/2011

Meter Reading: 111,543.80

Problem?

Air noise when pressing brakes. Noise appears to be coming from dash.
R58

Parts ----- Quantity -----

Task performed:

Replcd air solenoid that was leaking. j

800405PURGE VALVE KIT	1
UMVS254411STRAP 46 IN	4

Workorder: V39195

In Date: 03/15/2011
Close Date: 03/24/2011

Meter Reading: 112,046.80

Problem?

One of the clips to the inside door where we keep the trauma bags and ped
box has fallen off. r56

Parts ----- Quantity -----

Task performed:

Travel to Stn56; C/O door latches on inside door - FNP; adj & lube latches
j

NO PARTS USED	
---------------	--

Workorder: V39737

In Date: 04/06/2011
Close Date: 05/10/2011

Meter Reading: 113,134.40

Problem?

Red Button on the rear inside doors that turn on the temporary work lights in
the back cabin is not working. Please fix when you have a minute. Sta 56.

Parts ----- Quantity -----

Task performed:

1. Replcd bulbs for compt lights. 2. Adj stretcher latch & tested. j

NO PARTS USED	
---------------	--



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V40126

In Date: 04/25/2011
Close Date: 05/10/2011

Meter Reading: 114,159.00

Problem?

Coolant low, no coolant visible in looking glass on reservoir tank. R500

Parts

Quantity

Task performed:

Top off tank. j

NO PARTS USED

Workorder: V39566

In Date: 03/30/2011
Close Date: 05/13/2011

Meter Reading: 112,762.50

Problem?

R500 NEEDS STANDARD SIZE BRACKETS INSTALLED FOR THE PUBLIC AWARENESS SIGNS. EXAMPLE: SMOKE ALARMS, DROWNIN(PREVENTION, ETC. THE CURRENT BRACKETS ARE TOO LARGE, SIGNS FALL OUT. R500

Parts

Quantity

Task performed:

installed brackets. j

L PLACARDLARGE SIDE PLACARD

2

L PLACARD INSERTLARGE PLACARD INSERT CARE

2



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V40874

In Date: 05/25/2011

Meter Reading: 115,621.00

Close Date: 06/02/2011

Problem?

B INSPECTION AND REPAIRS AS NEEDED R500

Task performed:

1. b inspection 2. travel to central shop for parts, travel back to south shop
3. replace r/side headlight 4. cab a/c blows warm, check a/c found low on freon and a/c drier NG, evacuate system replace drier recharge a/c found leak on hose crimp at a/c condensor fans, retrim hose recheck for leak ok. 5. replace wiper blades 6. air leak coming from rear of vehicle, check for leak, found r/side leveling valve leaking, replace both leveling valves and adjust road test vehicle and readjust valves. 7. refill windshield washer fluid 8. r/side air horn inop, remove both air horns and install new kits, reinstall horns and adjust 9. service p/s 10. replace front shocks 11. replace rear shocks 12. travel to c/shop to pick up parts for vehicle, travel back to s/shop

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
1094KIT-AIR HORN-GROVER	2
1501450007750USE 0775145	1
161657700065489 SHOCK REAR NEW RESCUE	2
52-24WIPER BLADES ANCO 24	2
716907-0610A DRYER	1
78R536078R5360M 2PK FILTER AIR COND	1
C2-32-15TRIGGER LATCH	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
H6054USE CV TYPE SEALED BEAM	1
R90PFILTER FUEL 33231	1
SA66613SHOCK FRONT RESC	2



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V40457

In Date: 05/06/2011
Close Date: 06/03/2011

Meter Reading: 114,692.60

Problem?

Front cab dashboard AC Fan not working. R56

Task performed:

Replc blower motor in cab A/C. j

Parts	Quantity
132R086DECAL/LABEL	1
132R087DECAL/LABEL	1
ABPN8330101701-0604 3924 BLOWER A/C BOA 852	1
HLD3999GSS1715UV 30LB STRUT GAS	8

Workorder: V40568

In Date: 05/12/2011
Close Date: 06/03/2011

Meter Reading: 114,811.00

Problem?

R500 has issues with the Dump (air) when vehicle is started. Sta 56.

Task performed:

1. Readj leveling valves & tested ok. 2. Readj rear doors that was hard to open. j

Parts	Quantity
NO PARTS USED	

Workorder: V40915

In Date: 05/27/2011
Close Date: 06/08/2011

Meter Reading: 115,521.70

Problem?

replace four rear tires.

Task performed:

Replace (4) rear tires - Boulevard j

Parts	Quantity
NO PARTS USED	

Vendor? BOULEVARD



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V41538

In Date: 06/22/2011
Close Date: 06/23/2011

Meter Reading: 116,263.90

Problem?

AC not blowing cold in front cab and in patient compartment, a/c, Sta 56.

Parts _____ Quantity _____

Task performed:

1. check front and rear a/c, top off front a/c with 1 lb freon, evacaute and recharge rear a/c, both systems blow cold

NO PARTS USED

Workorder: V41686

In Date: 06/30/2011
Close Date: 07/19/2011

Meter Reading: 116,568.50

Problem?

rear a/c inop.

Parts _____ Quantity _____

Task performed:

REPAIRED BAD CONNECTION FOR CO-FANS AK

NO PARTS USED

Workorder: V41769

In Date: 07/03/2011
Close Date: 07/19/2011

Meter Reading: 116,951.00

Problem?

Water leaking on the floor from under the dashboard on the officers side of the truck R 500

Parts _____ Quantity _____

Task performed:

CLEANED OUT DRAINS ON CONDENSER UNIT READJUSTED REAR DOOR LATCH THAT WAS HARD TO OPEN AK

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V41818

In Date: 07/05/2011
Close Date: 07/20/2011

Meter Reading: 116,951.00

Problem?

Passenger headlight out. R500

Parts ----- Quantity -----

Task performed:

AC INOP 110AC RECHARED UNIT AND TESTED REPLACED HEAD LIGHT AK

NO PARTS USED

Workorder: V41894

In Date: 07/08/2011
Close Date: 08/08/2011

Meter Reading: 117,407.80

Problem?

Naderpin on driver side is not lining up with door latch. Hard to close door. R56

Parts ----- Quantity -----

Task performed:

readjusted pin and tested

NO PARTS USED

Workorder: V41928

In Date: 07/11/2011
Close Date: 08/08/2011

Meter Reading: 117,494.20

Problem?

After 2 calls the truck is now high idling when placed in neutrol w/ parking brake applied. Sta 56.

Parts ----- Quantity -----

Task performed:

tested chring system and batteries all tested good repaired rear door latch that would not lock

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V42205

In Date: 07/21/2011
Close Date: 08/08/2011

Meter Reading: 118,014.70

Problem?

Check for air leak. Difficulty building pressure to put truck in gear. Sta 56.

Parts _____ Quantity _____

Task performed:

checked for air leak found none at this time repaired rear step that was falling off

NO PARTS USED

Workorder: V42245

In Date: 07/23/2011
Close Date: 08/25/2011

Meter Reading: 118,014.70

Problem?

Shore power outlet is not ejecting plug. R56

Parts _____ Quantity _____

Task performed:

1. Auto-eject inop; replc auto-eject. 2. Cab A/C warm; recharged unit & rep leak. j

NO PARTS USED

Workorder: V42385

In Date: 07/29/2011
Close Date: 08/25/2011

Meter Reading: 118,378.20

Problem?

Nader pin guard left side rear door is broken. Rescue is not lowering down enough for stretcher operation. Sta 56.

Parts _____ Quantity _____

Task performed:

repaired pin and adjusted air bags

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V42398

In Date: 07/30/2011
Close Date: 08/25/2011

Meter Reading: 118,378.20

Problem?

Shoreline connection is working intermittently R56

Task performed:

Replcd unit. j

Parts	Quantity
0915520120AUTO EJECT 20 AERO OTL3925	1

Workorder: V42452

In Date: 08/01/2011
Close Date: 08/25/2011

Meter Reading: 118,378.20

Problem?

Windshield wipers are not working. Shore power outlet is not ejecting plug.
56

Task performed:

repaired bad connection for wipers replaced auto eject plug

Parts	Quantity
NO PARTS USED	

Workorder: V43372

In Date: 09/01/2011
Close Date: 09/01/2011

Meter Reading: 119,775.30

Problem?

REPAIR AIR LEAK / A/C DRAIN PLUGGED R 500

Task performed:

install air hose from metal comp-- hose to air dryer unplug a/c drain

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V43408

In Date: 09/04/2011
Close Date: 09/07/2011

Meter Reading: 119,886.40

Problem?

Cab is leaking from ceiling. R 56

Parts ----- Quantity -----

Task performed:

sprayed water on roof could not determine leak used silicone on roof at locations near where ff mentioned water came in

NO PARTS USED

Workorder: V43438

In Date: 09/06/2011
Close Date: 09/07/2011

Meter Reading: 119,886.40

Problem?

With battery on a few minutes, upon turning the ignition on, the truck sounded like it was going to stall and the truck would only idle, would not accelerate. Had to turn ignition & battery off then on again to work. R 56

Parts ----- Quantity -----

Task performed:

found fault code 248 comm loss checked data link connectors at module under officer side cleared pins of ---test drive all ok

NO PARTS USED

Workorder: V42149

In Date: 07/20/2011
Close Date: 09/12/2011

Meter Reading: 117,935.30

Problem?

Need a bracket for the halligan tool and fire extinguisher in the side compartment. Need hooks for radio and helmet inside front cab along with glove box holders. Need an articulating arm for the MDT. Sta 56.

Parts ----- Quantity -----

Task performed:

installed air bottle holders glove box holders ext holder

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V42638

In Date: 08/08/2011
Close Date: 09/12/2011

Meter Reading: 118,885.80

Problem?

Scba and fire exting. brackets inside of driver side compart. Two glove box holders on center console between driver and officer(remove velcro top). Articulating arm for the MDT.

Parts ----- Quantity -----

Task performed:

b-inspection will install at b

NO PARTS USED

Workorder: V42864

In Date: 08/17/2011
Close Date: 09/12/2011

Meter Reading: 119,119.00

Problem?

Air dump has a leak, sta 56.

Parts ----- Quantity -----

Task performed:

checked and repaired air leaks

NO PARTS USED

Workorder: V42924

In Date: 08/19/2011
Close Date: 09/16/2011

Meter Reading: 119,202.10

Problem?

replace front tires

Parts ----- Quantity -----

Task performed:

Replace front tires - Boulevard j

NO PARTS USED

Vendor? BOULEVARD



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V42941

In Date: 08/20/2011
Close Date: 09/19/2011

Meter Reading: 119,254.70

Problem?

The bracket that keeps the right door of L2 from swinging all the way open is bent. It was bent coming out of station and L2 door popped open and was opened past its stopping point. Springs are still in tact. R500

Parts ----- Quantity -----

Task performed:

stretcher latch inop - readjusted latch replaced door spring

NO PARTS USED

Workorder: V44213

In Date: 10/07/2011
Close Date: 10/21/2011

Meter Reading: 121,302.10

Problem?

PA system not working...speaker one not working

Parts ----- Quantity -----

Task performed:

replaced siren speaker

SD-210RXSIREN DRIVER SMALL 1

Workorder: V44346

In Date: 10/12/2011
Close Date: 10/24/2011

Meter Reading:

Problem?

AIR LEAK FROM REAR OF R500. Sta 56.

Parts ----- Quantity -----

Task performed:

check, found dump valve leaking, removed, did not have, took one off spare, put on left side, now right side leaks, let go for now per steve r, order part weld a/c bracket to fan remove and reinstall

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V42920

In Date: 08/19/2011 Meter Reading: 119,202.10
Close Date: 11/02/2011

Problem?

Uneven wear on front passenger tire. Tire looks low.

Parts ----- Quantity -----

Task performed:

ref to wo 42924 for outside agency replacement of tires

NO PARTS USED

Workorder: V44792

In Date: 10/31/2011 Meter Reading: 122,226.30
Close Date: 11/07/2011

Problem?

Rear a/c inop, sta 56.

Parts ----- Quantity -----

Task performed:

Rep condensor fans & tested. j

NO PARTS USED

Workorder: V44250

In Date: 10/09/2011 Meter Reading: 121,377.70
Close Date: 11/14/2011

Problem?

Rescue 500 air tanksfor the dump will not hold air leak down.

Parts ----- Quantity -----

Task performed:

Chkd for leaks; sent to shop for rep. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V44635

In Date: 10/24/2011
Close Date: 11/21/2011

Meter Reading:

Problem?

Nader pin on guard on back door is bent. Sta 56.

Parts

Quantity

Task performed:

replcd guard on door pin. j

NO PARTS USED

Workorder: V44330

In Date: 10/12/2011
Close Date: 12/02/2011

Meter Reading:

Problem?

two gloves box brackets on the center console, remove velcro cushion. helmet/ radio hooks inside the cab. Bracket strap for extingsuigher and scba bracket inside driver side compart. Sta56.

Parts

Quantity

Task performed:

INSTALLED GLOVE BOXES IN CAB REPAIRED REAR DOOR

NO PARTS USED

Workorder: V44989

In Date: 11/05/2011
Close Date: 12/02/2011

Meter Reading:

Problem?

Cab A/C is stuck on high heat. R56

Parts

Quantity

Task performed:

adjusted heater valve

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V45185

In Date: 11/15/2011
Close Date: 12/02/2011

Meter Reading:

Problem?

blowing only hot air. sta56

Parts

Quantity

Task performed:

adjusted heater control valve

NO PARTS USED

Workorder: V45231

In Date: 11/16/2011
Close Date: 12/02/2011

Meter Reading:

Problem?

AC not working in the the front CAB, Sta 56.

Parts

Quantity

Task performed:

recharged a/c and repaired cab leak repaired right side head light frame

NO PARTS USED

Workorder: V45763

In Date: 12/09/2011
Close Date: 12/09/2011

Meter Reading: 124,353.40

Problem?

Replace tires, Boulevard.

Parts

Quantity

Task performed:

tires replaced- 4 rear tires

NO PARTS USED

Vendor? BOULEVARD TIRE



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V45638

In Date: 12/05/2011

Meter Reading: 124,168.90

Close Date: 12/14/2011

Problem?

C INSPECTION AND REPAIS AS NEEDED R500

Task performed:

c inspection x 3 days (took extratime for c and repairs - my tools are at st 81) service air dryer found excessive water sludge and corrosion in dryer after disassembly installed new dryer assy r&r cab aux a/c filter and filter guard installed new filter r&r patient a/c air filter Replace 110v patient a/c vent louver filter assy inflate 6 tires to 110 psi diagnose and repair uv light assy for patient a/c mmating half of latach gone none instock fabricate a latch that will work and chim to align tighten and check bolts on compt l3 hold open mounts tighten allen screws on both cab aux a/c control knobs repair o2 leak at regulator threaded fitting o2 pressure display in action area inaccurate diagnose and repair and test secure loose hanging wires at steering column to dash area diagnose and repair no turn signals no hazard flashers repair connctor at turn sig switch r&r campaign sign bracket from veh remove all adhesive from bracket and veh body apply new adhesive and install r&r center console r&r dash r&r dash a/c control assy r&r one cable r&r foam seal adj acc cables install missing dash screws replace --ined console screws and --- diagnose and repair city horns r&r 2 horn assy clean ground brush and slip ring at steering column go over campaign signs dent fit veh with steve reines trouble shoot and hook up new power wire to traffic adviser controller qc truck replace missing lug nut covers

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
032-0116549297 BATTERY INDICATOR	1
05-17223-000CAP RADIATOR 10 LB	1
22-51374-000SENSOR AIR RESTRICTION	1
23-11345-710SCREW DASH	2
6808310398SEAL AIR DUCT	1
800887AD-SP DROP IN DRYER COMPLETE	1
A0631117000HORN HIGH NEW # 06-52125-039	1
A0631117003HORN LOW NEW #06-52125-041	1
ABPN83322930CONTROL HEAD AC/HEAT	1
ACX-84534LUG NUT COVER PK10	2
CA8193AIR FILTER 46744 WIX	1
R90PFILTER FUEL 33231	1
UVAPS253 UNIT UV LIGHT A/C RESCUES	1
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V45720

In Date: 12/08/2011
Close Date: 12/16/2011

Meter Reading:

Problem?

1. Rear Airbags ar OOC. 2. Front/Dash A/C cable was sticking. Staying heat. 3. Steering columb is making a loud metallic banging noise. Thank you.

Parts ----- Quantity -----

Task performed:

REAR AIR BAGS LEAKING, ADJUSTED LINKAGE AND REPAIRED FITTING. FRONT DASH A/C INOP, REPAIRED ALL MELTED WIRE IN DASH FROM BLOWER. STEERING MAKING NOISE, FOUNDNO NOISE

NO PARTS USED

Workorder: V46206

In Date: 01/02/2012
Close Date: 01/13/2012

Meter Reading:

Problem?

passenger side head light is out. Dim setting only. Brights are working. R 56

Parts ----- Quantity -----

Task performed:

REPLACED LIGHT.

NO PARTS USED

Workorder: V46923

In Date: 01/30/2012
Close Date: 02/03/2012

Meter Reading: 126,639.80

Problem?

rescue 500 driver side head light is out. Sta 56

Parts ----- Quantity -----

Task performed:

1. REPLACED HEADLIGHT. 2. AIR HORNS INOP - READJUSTED AIR HORNS AND REBUILT RIGHT SIDE.

1094KIT-AIR HORN-GROVER 2



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V47169

In Date: 02/08/2012
Close Date: 02/10/2012

Meter Reading: 126,902.70

Problem?

R500 has an audible air leak coming from the rear of the truck.

Task performed:

1. REPAIRED LEAK AT AIR TANK AND REPAIRED SECOND LEAK. 2. REPAIRED REAR DOOR LATCH THAT WAS HARD TO OPEN.

Parts ----- Quantity -----

401148DUMP VLVE AIR SLOAN	1
---------------------------	---

Workorder: V47398

In Date: 02/17/2012
Close Date: 03/01/2012

Meter Reading:

Problem?

-Rear audible air leak present after shutting down the unit -Driver side front turn signal cracked, needs to be replaced, Sta 56

Task performed:

SEE W/O #47660 for repairs

Parts ----- Quantity -----

NO PARTS USED	
---------------	--



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V47660

In Date: 03/01/2012
Close Date: 03/01/2012

Meter Reading:

Problem?

-i wrote up a few weeks ago about a big air leak coming from the rear for 30+ minutes after truck is turned off, still needs repair -also tilted to the right
-L front blinker cracked R500

Parts ----- Quantity -----

401148DUMP VLVE AIR SLOAN	1
---------------------------	---

Task performed:

1. check for rear air leak, found r/side dump valve leaking, replace valve, adjust air bags and road test come back and readjust air bags 2. replace l/side front turn signal lens, (lens was a DNI,) 3. check and adjust heater control cable 4. driver stated loud noise comming from front end or sterring column, check front end found l/side spring hanger bolts loose, tighten bolts and retighten r/side bolts

Workorder: V47933

In Date: 03/13/2012
Close Date: 04/02/2012

Meter Reading: 128,898.40

Problem?

Diagnostic error node 3 pin N. R500

Parts ----- Quantity -----

15W40QSYN OIL QT	12
60027FAN A/C COND 12IN 860026-2-W	2

Task performed:

FOUND A/C CONDENSER FANS NOT WORKING - REMOVED AND INSTALLED NEW ONES.



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V48598

In Date: 04/11/2012
Close Date: 04/12/2012

Meter Reading:

Problem?

R500's pt compartment ac is not blowing cold. It usually is ice cold

Parts

Quantity

Task performed:

1. check pat. compt. a/c, could not find anything wrong with unit, both cond. fans working, temp. is blowing out at 38deg. also checked front and rear cab a/c both work ok, blowing out 33deg.

NO PARTS USED

Workorder: V48299

In Date: 03/30/2012
Close Date: 04/16/2012

Meter Reading: 129,727.10

Problem?

R500's front dash AC is blowing hot

Parts

Quantity

Task performed:

RECHARGE SYSTEM AND REPAIRED LEAK.

NO PARTS USED

Workorder: V48313

In Date: 03/31/2012
Close Date: 04/16/2012

Meter Reading: 129,727.10

Problem?

a/c in front cab of R500 not working, blower is working, not cold.

Parts

Quantity

Task performed:

RECHARGED SYSTEM AND REPAIRED LEAK.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V48367

In Date: 04/02/2012
Close Date: 04/16/2012

Meter Reading: 129,727.10

Problem?

driver side siren speaker not working on R500 @ 56

Parts ----- Quantity -----

Task performed:

REPAIRED BAD CONNECTION ON SIREN.

NO PARTS USED

Workorder: V48525

In Date: 04/08/2012
Close Date: 04/16/2012

Meter Reading: 130,246.60

Problem?

R-500's small upper step below drivers door is loose. It appears that the weld is loose.

Parts ----- Quantity -----

Task performed:

REPAIRED SIDE STEP THAT WAS BROKEN.

NO PARTS USED

Workorder: V48423

In Date: 04/04/2012
Close Date: 04/20/2012

Meter Reading: 129,997.60

Problem?

Nader pin cover broke off the passenger side back door (patient compartment.) R500

Parts ----- Quantity -----

Task performed:

REPLACED REAR PIN AND REPAIRED DOOR.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V48962

In Date: 04/27/2012
Close Date: 05/04/2012

Meter Reading: 130,795.00

Problem?

R500 right headlight is out.

Parts ----- Quantity -----

Task performed:

INSTALLED NEW HEADLIGHT.

NO PARTS USED

Workorder: V49180

In Date: 05/08/2012
Close Date: 05/18/2012

Meter Reading: 131,349.00

Problem?

R500 transport compartment a/c is not blowing cold air.

Parts ----- Quantity -----

Task performed:

1. CHECKED A/C AND CLEANED CONDENSER FANS. 2. MOUNTED TOOLS IN L-1 COMPARTMENT.

NO PARTS USED

Workorder: V49301

In Date: 05/12/2012
Close Date: 05/18/2012

Meter Reading: 131,446.50

Problem?

Engine coolant low, needs refilling R 500

Parts ----- Quantity -----

Task performed:

1. PRESSURE TESTED FOR LEAKS AND REFILLED. 2. 110 A/C INOP, REPAIRED POWER CORD THAT WAS SHORTED OUT.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V49447

In Date: 05/17/2012
Close Date: 06/05/2012

Meter Reading: 131,804.90

Problem?

B INSPECTION R 500

Task performed:

1. B INSPECTION 2. B SERVICE TORQUE U-BOLTS. 3. R&R BOTH DOOR PANEL AND REPLACE BOTH DOOR LEDGES BROKEN, REPLACE RIGHT REAR DOOR LATCH NOT LATCHING WITH DOOR CLOSE. 4. R&R TWO SEATS THEY NEED REWORKED, RIP AND SPRING BROKEN. 5. REWORK BATTERY CABLES, SOME TO LONG FROM BATTERY TO BATTERY, CUT AND SOLDER END BACK ON TO FIT BATTERY CHECK SHORE LINE CHARGER WORK BATTERY GOOD. 6. REPLACE BOTH SEAT AFTER REPAIR WERE DONE INSTALLED AND CHECK OK. 7. R&R ENGINE BELTS, REMOVE FAN BLADE, REMOVE ENGINE BELTS, REPLACE BELT TENSIONER ALSO, REPAIR BELTS REINSTALL FAN TEST OK. 8. REPAIR DOOR HOLD OPEN LATCH ON L-2/L-3 DOOR; REPLACE A/C VENT IN CAP/ADJUST LATCH IN PATENT COMPARTMENT. 9. CHECK AND TIGHTEN ALL FRONT SPRING HANGER BOLTS ALL LOOSE. TIGHTEN CHECK OK; REPAIR WASHER ON FRONT OK. 10. R&R DASH REPLACE LIGHT THAT WERE OUT, ALSO REPAIR AIR LEAKS ON HOSES IN DASH ALSO REINSTALLED DASH CHECK LIGHT AND LEAK OK. 11. REMOVE DOOR PANEL IN REAR DOOR, BRAKES OFF SCREW CUT OFF; INSTALLED NEW NUT ZURT AND ALL NEW SCREW REINSTALL WORKING OK. 12. CHECK AND REPLACE RIGHT FRONT OVER HEAD LIGHT ON RIGHT SIDE HIGH LOW, BAD PLUG IN LIGHT. IN PATENT COMPARTMENT. 13. REPLACE ALL 8 LENSES OF SIDE OF BOX, ALL BROKEN SCREW HOLES. ALL NEW BUFF OUT ALL OTHER LENSES ON FRONT AND REAR LIGHT BAR. 14. CHECK AND ADJUST PRESSURE IN FRONT A/C UNIT. LITTLE LOW TOP OFF RECHECK OK. 15. R&R REAR BRAKE, COMPLETE ON REAR DRUM, SHOES, SPRING, ADJUST AND RECHECK. 16. QUALITY CHECK. 17. REPAIR AFTER Q.A. REPLACE TWO FRONT TIRES PER EDDIE, REPAIR RIGHT HEADLIGHT. NEW WINDOW ID NO ALSO.

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
0127110042BELT MERCEDES MOTORS	1
18-29935-001RH DOOR LATCH NEW	1
322502BULB PATIENT GH22	1
3744BRAKE DRUM REAR	2
4923090025DASH BULB VDO	4
52-24WIPER BLADES ANCO 24	2
6808300074VENT A/C LH	1
6811813493LENS CLEAR 68-1181349-3	3
68118354250900 SERIES RED LENS	3
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
A1834388002MOLD L/H	1
A1834388003MOLD R/H	1
AMH-1AMH-1 VALVE EXTENSION	1
DDE/9062002470BELT TENSIONER MERCEDES	1
KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2
R90PFILTER FUEL 33231	1
WKL0381DOME LIGHT WELDON 8046	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V50012

In Date: 06/09/2012
Close Date: 06/13/2012

Meter Reading: 132,458.40

Problem?

R500 had Driver side rear outer tire valve stem repaired tonight due to tire having low air. Per company, the valve stem hose is worn and needs to be replaced soon R 500

Parts ----- Quantity -----

NO PARTS USED

Task performed:

1. TRAVEL TO ST 56 AIR UP TIRE TEST FOR LEAKS FOUND EXTENSION HOSE LEAKING REMOVED HOSE TEST VALVE STEM OI
2. CHECK PATIENT A/C PRESSURE A LITTLE HIGH BLOWING COLD NO REPAIRS MADE.

Workorder: V50079

In Date: 06/12/2012
Close Date: 06/13/2012

Meter Reading: 132,558.90

Problem?

REPAIR FLAT R 56

Parts ----- Quantity -----

NO PARTS USED

Task performed:

REPAIR FLAT R56

Vendor? BOULEVARD TIRE CENTE



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V50161

In Date: 06/15/2012
Close Date: 06/18/2012

Meter Reading: 132,772.00

Problem?

Air system leaking very bad. Makes it difficult to leave for calls.

Task performed:

CHECK FOR AIR LEAKS - FOUND RT. AIR LEVEL VALVE - R&R RT. VALVE - FOUND L. LEVEL VALVE LEAKING - R&R VALVE - WET TANK FULL OF WATER - CLEANED GOV. AND PURGE VALVE LINES - RAN AND CHECK OK.

Parts ----- Quantity

S4640024430VALVE LEVELIN	2
--------------------------	---

Workorder: V50013

In Date: 06/09/2012
Close Date: 06/22/2012

Meter Reading: 132,458.40

Problem?

pt compart ac not blowing cold enough R 500

Task performed:

1. RECHARGED AND REPAIRED LEAK FOR A/C 2. ADJUSTED ALL CAB DOORS THAT WERE NOT CLOSING.

Parts ----- Quantity

NO PARTS USED	
---------------	--

Workorder: V50137

In Date: 06/14/2012
Close Date: 06/25/2012

Meter Reading: 132,641.90

Problem?

Air system leaking very bad. Makes it difficult to leave for calls.

Task performed:

ADJUSTED VALVES, VALVES KEEP LEAKING - UNIT SENT TO SHOP, FOR LEAKING VALVES.

Parts ----- Quantity

NO PARTS USED	
---------------	--



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V50178

In Date: 06/16/2012
Close Date: 06/25/2012

Meter Reading:

Problem?

pink reddish fluid with a slow steady drip from underneath ...appears to be coolant, not transmission fluid R 500

Task performed:

1. check for coolant leak, pressure test, on lift, found air compressor leaking at head. remove p/s pump from compressor, drain coolant, remove air lines and coolant lines from compressor, remove compressor, install new compressor and gasket, install p/s pump and gasket, coolant lines were brittle and broke when installing, remove banjo fittings and hose install new hose on banjo fittings, replace broken governor air line to compressor. refill p/s, refill coolant, start unit and run, check for leaks and road test. ok

Parts	Quantity
N007603014104WASHER SEAL	4
RA9061301415AIR COMPRESSOR	1

Workorder: V50325

In Date: 06/22/2012
Close Date: 06/25/2012

Meter Reading:

Problem?

R500 is currently at the south shop i'm told for a leak issue.. while its there, please check and fix the squeaky brakes. They began squeaky and few weeks ago, repaired and squeak returned soon after.

Task performed:

1. check brakes, new brakes in rear, front 60%, road test did not hear any noise.

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V50844

In Date: 07/13/2012
Close Date: 08/03/2012

Meter Reading: 134,032.80

Problem?

R500 has a headlight out

Task performed:
REPLACED HEADLIGHT.

Parts	Quantity
H6054USE CV TYPE SEALED BEAM	1

Workorder: V51124

In Date: 07/25/2012
Close Date: 08/06/2012

Meter Reading: 134,482.20

Problem?

R500's entire AC system not blowing as cold as it usually does, spoke with tommy via phone about coming by r 56

Task performed:
SENT UNIT TO SOUTH SHOP.

Parts	Quantity
NO PARTS USED	

Workorder: V51487

In Date: 08/09/2012
Close Date: 08/09/2012

Meter Reading: 135,044.70

Problem?

R500's front passenger side tire has a nail in it, unknown depth of nail. Appears to be holding air adequately

Task performed:
NAIL PULLED FROM TIRE BY CREW NO LEAK.

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V51309

In Date: 08/02/2012
Close Date: 08/13/2012

Meter Reading: 134,598.20

Problem?

REPLACE FRONT TIRES

Parts ----- Quantity -----

Task performed:
REPLACE FRONT TIRES.

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE

Workorder: V51605

In Date: 08/15/2012
Close Date: 09/17/2012

Meter Reading:

Problem?

entire AC system not cooling like it use to, can you have an on duty mechanic call us..this may have been looked at already by tommy

Parts ----- Quantity -----

Task performed:
RECHARGED SYST AND REPAIRED LEAK.

NO PARTS USED

Workorder: V51711

In Date: 08/20/2012
Close Date: 09/17/2012

Meter Reading: 135,529.80

Problem?

ON CALL WONT START R 500

Parts ----- Quantity -----

Task performed:
TRACED OUT PROB FOUND BAD STARTER SOLENOID-REMOVED AND REPLACED.

ESX120105112STARTER RELAY ESX-120-105112 2



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V52408

In Date: 09/16/2012
Close Date: 09/25/2012

Meter Reading:

Problem?

Coolant level is not showing in the site flow. r 56

Parts

Quantity

Task performed:

1. PRESSURE TESTED FOR COOLANT LEAK FOUND NO LEAK. LEAK IN AIR RIDE SEAT, REPAIRED AIR LEAK. 2. CAB A/C WARM, CLEANED CONDENSER FANS AND CHECKED FOR LEAKS, AIR HOR INOP, REPAIRED UNIT.

NO PARTS USED

Workorder: V52412

In Date: 09/16/2012
Close Date: 09/25/2012

Meter Reading:

Problem?

Please install a hook for stretcher per Batallion Chief Horowitz. R 500

Parts

Quantity

Task performed:

INSTALLED HOOK IN REAR.

NO PARTS USED

Workorder: V52435

In Date: 09/17/2012
Close Date: 09/25/2012

Meter Reading:

Problem?

Tommy is here checking the ac, brakes, coolant, and air leak in officer's seat. R56

Parts

Quantity

Task performed:

REPAIRED ALL ON ANOTHER TICKET.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V52320

In Date: 09/11/2012
Close Date: 10/02/2012

Meter Reading: 10,154,111.00

Problem?

repair flat r 500

Parts ----- Quantity -----

Task performed:
REPAIR FLAT R-500

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE

Workorder: V52767

In Date: 10/01/2012
Close Date: 10/04/2012

Meter Reading: 137,032.00

Problem?

REPLACE REAR TIRES

Parts ----- Quantity -----

Task performed:
REPLACE REAR TIRES.

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE

Workorder: V52583

In Date: 09/23/2012
Close Date: 10/16/2012

Meter Reading:

Problem?

R500 & R56 both have the same tire low on tread. Both trucks have the REAR DRIVER SIDE OUTER TIRE LOW ON TREAD. All other tires appear adequate. R 56 AND 500

Parts ----- Quantity -----

Task performed:
CHKD BOTH TRUCK WILL MONITOR FOR ANOTHER 2 WEEKS.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V52703

In Date: 09/28/2012
Close Date: 10/16/2012

Meter Reading:

Problem?

Driver side siren speaker not working. Replaced by mech Tommy at ST53 on 9-28-12.

Parts ----- Quantity -----

Task performed:

REMOVED AND REPLACED SIREN SPEAKER. REPAIRED STREACHER LATCH AND TESTED.

SD-210RXSIREN DRIVER SMALL	1
----------------------------	---

Workorder: V53014

In Date: 10/11/2012
Close Date: 10/26/2012

Meter Reading: 137,637.00

Problem?

station 56 needs spare motor oil dropped off..thanks R56

Parts ----- Quantity -----

Task performed:

1. RECHARGED A/C AND REPAIRED LEAK AT DRYER. 2. REPAIRED STRETCHER LATCH AND TESTED.

NO PARTS USED	
---------------	--



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V53829

In Date: 11/16/2012

Close Date: 12/13/2012

Meter Reading: 138,992.00

Problem?

C INSPECTION

Parts

Quantity



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* **ADVANCED LIFE SUPPORT VEHICLE**

Task performed:

1. STARTED C INSPECTION- CHANGED TO C INSPECTION. 2. REPLACED BATTERIES. 3. C-INSPECTION AIR TIRES FILL WASJER FLUID, TAKE ENGINE OIL SAMPLE. 4. TRANS SERVICE. 5. PULLED PARTS, DRAIN AIR TANKS. REMOVE DRYER CATRIDGE. INSTALL NEW CARTIDGE. 6. REMOVED AND CLEANED AIR FILTER. INSTALL MISSING NOT ON FILTER HOUSING. 7. CLEAN ENGINE TIGHTEN VALVE COVER AND RECHECK LEAKS OK AT THIS TIME CHECK NEX SERVICE. 8. REDUCE REAR PATIENT COMPARTMENT LATCH. 9. REPLACE WIPERBLADES. 10. REPLACE BOTH LEFT SIDE DOOR SEALS. 11. REMOVE R/F DOOR PANEL AND TIGHTEN OUTSIDE DOC HANDLE. 12. DRAIN AIR TANKS AND REPLACE AIR DRIER PURGE VALVE. 13. PULL FRONT BRAKES APART REPLACE SHOES SPRING; DRUMS AND SLACK ADJUST REAR BRAKES. 14. REPLACE BOTH FRONT SEAT BELTS AND BUCKLES. 15. TRACE WIRING FOR TRAFFIC ADVISOR AND REPAIR OPEN WIRE. 16. REPLACE TURBO OIL DRAIN HOSE AND GASKET CLEAN MOTOR AND TEST DRIVE. 17. DIAGNOSE CAB A/C RECOVER FREON AND REMOVE HIGH PRESSURE DISCHARGE HOSE. 18. INSTALL DISCHARGE HOSE ANC A/C DRIER EVACUTE AND RECHARGE SYSTEM.

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
090-0278STRECHER BAR NEW	1
109995PURGE VALVE KIT	2
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	26
29526898 29548988 TRANS FILTER ALLISON	1
3753BRAKE DRUM RUMPER FRONT	2
424664HOSE&FITTING ASSY	1
4411S08-6962BS 90 DEGREE SB1322	1
5008414CARTRIDGE DC100	1
52-24WIPER BLADES ANCO 24	2
6806970098SEAL DOOR	2
716907-0610A DRYER	1
78R536078R5360M 2PK FILTER AIR COND	1
90-100-10HOSE 90 DEG 1 IN	1
A0000160521GASKET VALVE COVER	1
A63275M1183SLACK ADJ. FRONT M2	2
A9069970382OIL DRAIN TUBE	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
C2-32-15TRIGGER LATCH	1
DDE-5411870080GASKET OIL RETURN TUBE TURBO	1
HP-31DBATTERY 950CCA HP-31D	4
IMMF11358SEAT BELTS	2
KSMA2124703QFRONTBRAKE KIT RUMPER AND 4D	2
P119325AIR FILTER NUT	1
R90PFILTER FUEL 33231	1
TRANSYNDALLISON TRANS FLUID GAL	7



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V54576

In Date: 12/23/2012
Close Date: 01/02/2013

Meter Reading:

Problem?

Spare rescue at 53 has multiple red led lights out on rear box. R53

Parts

Quantity

Task performed:

CHECK ALL LIGHTS, NO PROBLEM FOUND.

NO PARTS USED

Workorder: V54675

In Date: 12/28/2012
Close Date: 01/02/2013

Meter Reading: 139,483.70

Problem?

repair cab a/c

Parts

Quantity

Task performed:

1. FOUND CAB A/C COMPRESSOR BAD- RECOVER FREON-REMOVE LINES STEP, BELT; COMPRESSOR AND DRIES- ADJ OIL LEVEL IN NEW COMPRESSOR- REPLACED COMP- R&R BOTH DRIES- REASSEMBLED- VAC AND CHARGE- CHK OK. 2. ASSIST WITH A/C.

02-0383709-10700 SERIES SCENE	1
533103-0607 A/C COMPRESSOR U4482 USE 7169 D	1
716907-0610A DRYER	1
H35SN12BULB	1
RD-5-7063-OP07-2618A A/C DRIER 7155	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V55216

In Date: 01/22/2013

Meter Reading: 140,992.70

Close Date: 01/24/2013

Problem?

A inspection

Parts

Quantity

Task performed:

1. A-INSPECTION. 2. ADJUST SPRAY NOZZLES ON WIPERS TO SPRAY ON WINDSHIELD. 3. SIDE ENTRY GRAB RAIL - SIDE ENTRY GRAB RAIL LOOSE ON DOOR - TWO BOLTS MISSING INSTALL NEW BOLTS AND FOUND THREADS STRIPPED OUT - REMOVE DOOR PANEL AND REPAIR THREADS - REINSTALL PANEL AND GRAB RAIL 4. LOAD LIGHT - INOP - R/REAR UPPER COMB LT (LOAD, SCENE ANI BACK UP)- INOP REMOVE LIGHT FIXTURE FROM INSIDE REAR EMERG LIGHT BAR - CHECK BULB - (OK) - CHECK POWER TO FIXTURE- (OK) - FOUND WIRING IN THIS NEW FIXTURE DOESN'T MATCH CONNECTOR WIRING OF VEHICLE - SWITCH WIRING AROUND IN CONNECTOR TO MATCH VEHICLE WIRING - REASSEMBLE - (NO OK).

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V55547

In Date: 02/05/2013
Close Date: 02/06/2013

Meter Reading: 141,618.00

Problem?

A INSPECTION

Task performed:

1. A-INSPECTION. 2. DIAGNOSE ONE CONDENSER - FAN IN/OP. CHECK FOR POWER (NONE). CHECK FOR RELAYS OR FUSES. CONTROLLED BY U-MAX. SUPPLIED POWER TO NODE 3 OUT PUT. FAN WORKING. CHECKED AMP DRAW OFF FAN 3.8 - 4.0 AMPS. REPLACED NODE AND REPROGRAMMED CHECK OPERATIONS (NC GOOD) REPLACED FAN AND RECHECK FAN (OK). 3. FLOURESCENT LIGHTS INOP - FOUND BAD BURNT TERMINAL REPLACED TERMINA
4. ADJ LATCH AND LOCK NOT FOR DIAMOND PLATE ACCESS PANE LATCH. 5. WIPER SWITCH INTERMITTANT AND REPLACED SWITCH. 6. DIAGNOSE FRONT A/C INOP. FOUND FREON LOW. ADD FREON AND LEAK CHECK - FOUND LEAK AT CONDENSER FITTING. REPLACED FITTING ANDD CRIMPED. CHARGE SYSTEM.

Parts

Quantity

064615900006-46159-001 SWITCH WIPER	1
4411S08-6962BS 90 DEGREE SB1322	1
60027FAN A/C COND 12IN 860026-2-W	1

Workorder: V55600

In Date: 02/07/2013
Close Date: 02/08/2013

Meter Reading: 141,618.00

Problem?

fAN CLUTCH 10-7

Task performed:

TRAVEL TO 23 FOUND FRONT BEARING ON FAN CLUTCH SEIZED REPAIRED FAN CLUTCH.

Parts

Quantity

HOR/991450HT 650 FAN ASY.	1
---------------------------	---



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V55812

In Date: 02/17/2013
Close Date: 02/20/2013

Meter Reading: 142,299.30

Problem?

one head light out. SR@ ST-23 Lt. McLaughlin

Task performed:

TRAVEL TO 23 R&R HEADLIGHT..

Parts	Quantity
H6054USE CV TYPE SEALED BEAM	1

Workorder: V44329

In Date: 10/12/2011
Close Date: 04/02/2013

Meter Reading:

Problem?

articulating arm for the mdt. please forward to the communications shop.
Sta 56.

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V50988

In Date: 07/19/2012
Close Date: 04/08/2013

Meter Reading:

Problem?

R500's ac in pt compartment is not blowing cold

Task performed:

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V56030

In Date: 02/26/2013
Close Date: 04/12/2013

Meter Reading: 142,633.90

Problem?

A inspection

Task performed:

1. A-INSPECTION. 2. DOOR PANELS HOLD OPEN AND COMP TOOL HOLDERS LOOSE - SECURE LOOSE PANELS, TOOL HOLDER AND HOLD OPEN - REPLACE MISSING O BENT SCREWS. 3. PATIENT COMP DOME LIGHT INOP - REMOVE BLOWN BULB INSTALL NEW BULB; PATIENT COMP EXHAUST VENT BROKEN INSTALL NEW VENT WINDOW. 4. GLOVE BOX BROKEN SHARP EDGES - REMOVE, CLEAN ADHESIVE - INSTALL NEW GLOVE BOX. 5. PA INOP - REMOVE CONSOLE COVER AND REMOVE PA//SIREN UNIT INSTALL REPLACEMENT UNIT AND REASSEMBLE.

Parts	Quantity
322502BULB PATIENT GH22	1
600750VENT LOUVER	1

Workorder: V57159

In Date: 04/20/2013
Close Date: 05/02/2013

Meter Reading:

Problem?

Crew changed out front rt headlight. Requesting a replacement headlight for the one used to fix the damaged one. St 73

Task performed:

DROP OFF HEADLIGHT.

Parts	Quantity
H6054USE CV TYPE SEALED BEAM	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V57557

In Date: 05/07/2013
Close Date: 05/13/2013

Meter Reading: 145,866.30

Problem?

B inspection SR19

Task performed:

1. B INSP. 2. CHECK AND RECHARGE CAB A/C REPLACE FILTER. 3. ADJUST AIR HORNS. 4. CHECK CITY HORNS, REPLACE BAD HORN. 5. CHECK AIR LEAKS REPLACE GOVERNOR FITTINGS. 6. REPLACE MISSING DOOR LATCHES IN PATIENT COMP CABINETS. 7 RESECURE L-3 COMP. HINGE MOUNTS. 8. TIGHTEN POWER STEERING PUMP AND LINE.

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
252189LATCH TRIGGER W/LOCK	2
78R536078R5360M 2PK FILTER AIR COND	1
A0631117000HORN HIGH NEW # 06-52125-039	1
DRC401202840048 DOOR GRABBER	3
R90PFILTER FUEL 33231	1

Workorder: V56619

In Date: 03/25/2013
Close Date: 05/29/2013

Meter Reading: 144,123.00

Problem?

a/c inop S.R. @ 36

Task performed:

RECHARGED SYSTEM AND CHECKED AND REPAIRED LEAKS.

Parts

Quantity

NO PARTS USED	
---------------	--



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V58960

In Date: 07/09/2013
Close Date: 08/15/2013

Meter Reading: 147,531.40

Problem?

replace fuel cap

Task performed:

1. REPLACED FUEL CAP. 2. RECHARGED REAR A/C AND CLEANED CONDENSOR FANS.

Parts	Quantity
03-29016-000FUEL CAP	1

Workorder: V59849

In Date: 08/16/2013
Close Date: 08/21/2013

Meter Reading: 148,690.80

Problem?

A inspection SR7

Task performed:

1. PERFORM A-INSPECTION. 2. ADD 1 LBS. OF FREON TO A/C. WORKS NICE. DONE. 3. CHECK HORN. WORKING. RUFF. FOUND BAD CONNECTION. FIX CONNECTION IS OK.

Parts	Quantity
02-0383709-10700 SERIES SCENE	1
A1712756000HOOD CABLE	1
H50SN12BULB	1

Workorder: V60117

In Date: 08/27/2013
Close Date: 08/28/2013

Meter Reading: 149,373.10

Problem?

Severe air leak, very loud hissing noise. Breaks are very stiff.

Task performed:

TRAVEL TO 24 FOUND PURGE VALVE LEAKING REBUILT VALVE ANI TESTED OK.

Parts	Quantity
109995PURGE VALVE KIT	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V60478

In Date: 09/13/2013
Close Date: 09/20/2013

Meter Reading: 149,969.10

Problem?

A-inspection

Task performed:

1. A-INSPECTION. 2. GLOVE BOX BROKEN - INSTALL NEW GLOVE BOX. 3. PATIENT COMP. FLORSCENT BULBS BLOWN - REMOVE BULBS AND INSTALL NEW ONE. 4. SCBA BRACKET LOOSE OFFICERS SEAT - SECURE SCBA BRACKET AND REPLACE MISSING FASTENERS. 5. FRONT DRIVER TIRE 1/32ND REMOVE TIRE INSTALL GOOD BUT USE TIRE FROM BLDG. 3.

Parts

Quantity

NO PARTS USED

Workorder: V60773

In Date: 09/25/2013
Close Date: 09/26/2013

Meter Reading: 149,969.10

Problem?

rear air bag support system seems to have a leak, truck tilting to the left @ angle -new spare R68

Task performed:

AIR BAG SYSTEM - CHECK OUT REAR SUSPENSION SYSTEM (AIR BAGS) FOUND LEFT SIDE DUMP VALVE LEAKING AIR CONSTANTLY LETTING LEFT SIDE AIR BAG DUMP COMPLETELY OUT - REPLACE VALVE AND RECHARGE AIR TO SYSTEM - NOW HOLD AIR.

Parts

Quantity

401148DUMP VLVE AIR SLOAN

1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V60768

In Date: 09/24/2013
Close Date: 09/30/2013

Meter Reading: 149,969.10

Problem?

spare rescue compartment 5 [rear] caution open light going on and off w/
no silence switch, also shore line ac not working -added 2 quarts of oil to
engine SR@68

Parts ----- **Quantity** -----

NO PARTS USED

Task performed:

1. TRAVEL TO ST 68 CHECK OUT 110V A/C AND CHARGER INOP
FOUND STATION BRAKER OFF RESET RUN 110V A/C BLOWER BAD
POP BRAKER RESET AGAIN NEEDS UNIT. 2. CHECK OUT TRUCK
LEANING AIR LEAK ON DUMP VALVE AND SIDE VALVE LEAKING
NEEDS REPLACEMENT AND READJUSTED SENT TO SHOP.

Workorder: V61703

In Date: 11/01/2013
Close Date: 11/04/2013

Meter Reading:

Problem?

Nader pin cover in patient compartment needs to be replaced. Stretcher
lock handle is sticking. SR@72

Parts ----- **Quantity** -----

NO PARTS USED

Task performed:

1. TRAVEL TO 72 DRIVER COMPLAINT NADAR PIN COVER BROKEN,
REPLACED COVER. 2. DRIVER COMPLAINT STRETCHER LATCH
BINDING LUBRICATED LATCH AND TESTED OK.



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V62312

In Date: 11/27/2013
Close Date: 11/27/2013

Meter Reading: 153,621.80

Problem?

replace rear tires

Parts

Quantity

Task performed:
REPLACE REAR TIRES

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE

Workorder: V62317

In Date: 11/27/2013
Close Date: 11/27/2013

Meter Reading: 153,621.80

Problem?

replace front tires

Parts

Quantity

Task performed:
REPLACE FRONT TIRES

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V62332

In Date: 11/28/2013
Close Date: 12/04/2013

Meter Reading: 153,839.00

Problem?

Spare Rescue will not hold air in rear suspension while the truck is not running. Truck has no air pressure if it sits for a while and then started for a call. R36

Parts ----- Quantity -----

Task performed:

1. AIR LEAK AT ABS RELAY VALVE. CARRY TO SHOP FOR PARTS REPLACE RELAY VALVE AND RETEST FOR AIR LEAKS. 2. CHECKED REAR DUMP. WORKING PROPERLY. RIDE HIGHT TOO LOW. ADJUSTED RIDE HEIGHT AND CHECKED ALL OVER FOR AIR LEAKS

472-500-121-0ABS ASSBLY	1
-------------------------	---

Workorder: V61955

In Date: 11/12/2013
Close Date: 12/12/2013

Meter Reading:

Problem?

The two outside rear tires have very little tread. R72

Parts ----- Quantity -----

Task performed:

REPAIRED ON WO 62312.

NO PARTS USED	
---------------	--

Workorder: V62547

In Date: 12/07/2013
Close Date: 12/31/2013

Meter Reading:

Problem?

Truck is spare being used at station 36. front cab A/C is blowing very hot air (heat)!!

Parts ----- Quantity -----

Task performed:

CLEANED CONDENCER FAN AND RECHARGED UNIT.

NO PARTS USED	
---------------	--



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V59621

In Date: 08/06/2013
Close Date: 03/03/2014

Meter Reading: 148,690.80

Problem?

*

Parts ----- Quantity

Task performed:

NO PARTS USED

Workorder: V64644

In Date: 03/03/2014
Close Date: 03/03/2014

Meter Reading: 157,091.90

Problem?

check for air leak

Parts ----- Quantity

Task performed:

WENT TO 33- FOUND AIR LEAK IN DASH- R&R SWITCH RAN AND
CHK OK- RETURN HOME.

FSC17492134NC SW PARK BK SPADE TYPE CONNE 1

Workorder: V65078

In Date: 03/20/2014
Close Date: 03/24/2014

Meter Reading: 158,389.70

Problem?

RRI flat

Parts ----- Quantity

Task performed:

R/R/I FLAT.

NO PARTS USED

Vendor? BOULEVARD TIRE



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V62649

In Date: 12/11/2013

Close Date: 03/31/2014

Meter Reading: 155,860.00

Problem?

C inspection SR7

Parts

Quantity



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* **ADVANCED LIFE SUPPORT VEHICLE**

Task performed:

1. C-INSP. 2. ASSIST NORRIS WITH C-INSP. 3. REPLACE BATTS FAILED LOAD TEST. 4. REPLACE ENGINE AIR INTAKE FILTER. 5. REMOVE ACCREDITATION DECALS AND BUFF OUT SIDES. 6. CHECKED ENGINE CODES COOLANT LOW AND PLD MISCALIBRATED ERASE CODES. 7. CHECK STEERING COLUMN LOOSENESS, NORMAL IN TILT MECHANISM. 8. REPLACE RADIATOR REPLACE RADIATOR RESEVOIR SIGHT GLASS. 9. RETHREAD HOLE IN RADIATOR SIDE FRAME FOR SHROUD, INSTALL MISSING BOLT AND WASHER REPLACE MISSING FASTNERS FOR FENDER WALL SPLASH GAURD. 10. REPLACE ROOF CLEARANCE LIGHT BULB. 11. SPOT LIGHT WONT GO UP OR DOWN. REMOVE SPOT LIGHT TO GA ACCESS. TO COVER SCREWS. REMOVED COVER. FOUND SADDLE HOLDING LIGHT BROKEN KEEPING GEARS FROM MESHING. REPLACED SPOT LIGHT ASSEMBLY. SPLICE WIRES TO HARNESS. TEST UP AND DOWN (NO GOOD). REMOVED CENTER CONSOL AND CHECKED PINS AND PLUG (OK). PLUG IN ANOTHER CONTROLLER AND TEST (NO GOOD). CHECK FOR POWER AT CONTROLLER FOR UP AND DOWN (OK). CHECK POWER AT SPOT LIGHT ON ROOF FOF UP AND DOWN POWER (OK). REMOVED SPOT LIGHT AND COVER. FOUND NEW SPOTLIGHT NOT LOCATED IN SADDLE AND SADDLE INSTALL LIGHT CORRECTLY AND INSTALL COVER INSTALL SPOTLIGHT. TEST (OK). HEAT SHRINK CONNECTIONS AND SEAL ROOF WITH SILICONE AT HARNESS CLEAN ROOF OF DEBRIS AND FINGERPRINTS OFF SPOT LIGHT. 13. REPLACE WIPER BLADES. 14. TIGHTEN L-2 COAT HOOKS REPLACED ONE STRIPPED OUT WITH LARGE SHEETMETAL SCREWS. 15. REMOVE NAIL FROM L/REAR INSIDE TIRE. CHECK FOR LEAKS (OK). 16. REPLACED SQUAD BENCH SHOCKS. 17. REPLACED O2 WRENCH. CUT AND ATTACH CABLE AND CELCO. 18. DRAIN AIR SYSTEM. REMVE AIR DRYER AND DISASSEMBLE CLEAN OUT CONTAMINATION AND REBUILD CLEAN SYSTEM OF CONTAMINATION. 19. TRAVEL TO MAKO FOR CORRECT TRANS FLUID. START VEHICLE AND CHECK FOR LEAKS. 20. REPLACED LEFT FRT DOOR TRIM PIECE. R DOOR PANEL HANDLE AND WINDOW CRANK. LUBRICATE LATCHES REPLACED SCREWS WITH WAASHED SCREWS. 21. DIAGNOSE AIR LEAKS- FOUND LEAK BEHIND DASH, REMOVED DASH AND PARK BRAKE

000000-003175NUT	1
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
04-20003-000PIPE TURBO OUTLET	1
103385NDRAIN COCK	6
20A-400CLAMP 4" 33969	2
23-12528-055SCREW	1
286171BRAKE VALVE E-6 NEW	1
29541736 SEAL-TRANS. REAR	1
40022STAINLESS FLEX PIPE 4"	2
443758C2-32-25 LATCH LEVER LOCKING	1
459217HOSE & FITTING ASSY	1
52-24WIPER BLADES ANCO 24	2
620-997-05-90CLAMP TURBO	1
63152HVAC UNIT ROOF MOUNTED	1
6809881078DZ STUD	2
A0516058001F10 RESCUE C RADIATOR	1
AS75807OXM1757-01 OXYGEN WRENCH	1
GSS1717UL1717UL0270N 343/09 GAS SHOCK 60 LB	2
R90PFILTER FUEL 33231	1
SPT6008146SL LIGHT-REMOTE SPOT	1
SU68088VALVE DUMP 310 HUMPHREY	1
VML-T1413T3248 SIGHT GLASS	1



4/10/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

VALVE. REMOVE INSTRUMENT CLUSTER. REPLACED DUMP VALVE SOLENOID AIR VALVE. REINSTALL AND TEST (OK). 22. CHECK OPERATION OF UV LIGHT (OK). 23. DIAGNOSE 110V A/C INOP- FOUND BLOWER FAN BOUND UP DUE TO MOUNTING BOLTS BROKE AND MISSING TRIED TO SECURE FAN MOTOR TO BRACKET BUT BOLT BROKEN. REMOVED UNIT FROM ROOF. INSTALL NEW UNIT ON ROOF DRILL HOLE FOR 110V A/C CABLES TO MODIFY UNIT FROM OLD BOLTS NOT LONG ENOUGH. CUT ALL THREAD TO LENGTH AND INSTALL WITH NUTS AND WASHERS. CUT BODY HOLE LARGER. CUT METAL FROM ROOF HAND HOLD RAILS CUT LOWER PAN AT CHANNEL AND WHERE MOLDING MEET ON CEILING CUT OVER DIVIDER TO SIZE. INSTALL WIRE 110V WIRES AND INSTALL BOX COVER. REMOVE OLD BOX CUT AND SECURE THERMOSTAT WIRING. INSTALL COVER AND TEST (OK), CLEAN COVER AND FILLINGS FROM PATIENT AREA. 24. REMOVE REAR SHACKS AND CLOCK BOTTOM OF SHOCK 180 DEGREES (INSTALLED INCORRECTLY). 25. FRONT A/C BLOWING WARM, CHECKED FREON CHARGE (LOW) REMOVED SIDE STEP AND CONDENSER COVER AND INSPECT HOSES AND FITTINGS CHARGE A/C AND REINSTALL CONDENSER COVERS AND STEP. 26. EXHAUST LEAK AT CLAMP. TIGHTENED CLAMP NO GOOD. REMOVE CLAMP AND EXHAUST PIPE FLANGE DAMAGED. ORDER PART (1-29-14). 27. LOOSEN REAR U-BOLT AND MOVE AIR BAG FRAMES OVER CHASSIS FRAME TO CENTER AIR BAGS. TORQUE U-BOLTS TO SPEC. ADJUST AIR BAG LEVEL VALVES. 28. REPLACE ALL TANK DRAIN VALVES. 29. LOW CRANKING SPEED. CHECKED STARTER AMP DRAW (OK) CHECK VOLTAGE DRAWS FOR STARTER AND IGN CIRCUITS (OK) CHECK BATTERIES (OK). NO PROBLEM FOUND. ERASE CODES CREATED AND TESTED. 30. DEGREASE MOTOR. SET UP AND TEAR DOWN PRESSURE CLEANING MACHINE. 31. CHECK ENGINE FOR OIL LEAK AFTER ROAD TEST SPOT CLEAN MOTOR WITH BRAKE CLEAN AND DRIVE AGAIN. OIL LEAK ON REAR FROM CLAMPING OIL FILTER OK 32. ADJUST CUT AND CUT GOV. PRESSURE. 33. P/S PUMP LEAK CLEAN AREA. TIGHTEN COVER BOLTS. TEST DRIVE AND RECHECK OK.



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V65713

In Date: 04/15/2014
Close Date: 04/15/2014

Meter Reading: 159,597.80

Problem?

Low voltage alarm

Task performed:

LOW VOLTAGE ALARM, ALTERNATOR BAD. REPLACED ALTERNATOR.

Parts	Quantity
4867JB320 UPGRADE ALTERNATOR	1

Workorder: V65678

In Date: 04/13/2014
Close Date: 05/09/2014

Meter Reading:

Problem?

AC in the front cab doesn't cool and AC in the patient compartment works on and off. R46

Task performed:

UNIT WILL NEED TO COME TO SHOP FOR A/C REPAIR.

Parts	Quantity
NO PARTS USED	

Workorder: V65736

In Date: 04/15/2014
Close Date: 05/13/2014

Meter Reading:

Problem?

Air conditioner is not blowing cold in front cab of rescue. Blowing warm.

Task performed:

RECHARGED SYSTEM AND CHECKED FOR LEAKS AND TESTED OK

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V66366

In Date: 05/09/2014
Close Date: 05/21/2014

Meter Reading: 160,800.00

Problem?

A inspection SR7

Task performed:

1. A INSPECTION- LEVELING VALVES- AIR BAGS. 2. FUEL PUMP
IDELER PULLY- REPLACE/FAN BELT CRACKING/ BULBS OUT.

Parts

Quantity

0127110042BELT MERCEDES MOTORS	1
16-15762-00016-19471-000 AIR BAG	2
194BULB	1
52-24WIPER BLADES ANCO 24	2
9062001170IDLER MERCEDES	1
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
H35SN12BULB	1
S448GAUGE TIRE TREAD DEPTH	2
S4640024430VALVE LEVELIN	2
UMVS162511STRAP	1

Workorder: V66698

In Date: 05/23/2014
Close Date: 06/12/2014

Meter Reading: 160,800.00

Problem?

replaced Left rear tires

Task performed:

Replaced left rear tires.

Parts

Quantity

NO PARTS USED

Vendor? BOULEVARD TIRE



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V65016

In Date: 05/30/2014
Close Date: 06/16/2014

Meter Reading: 158,389.70

Problem?

Cab a/c inop

Parts	Quantity
-------	----------

Task performed:

a/c only blows out of defroster vents frezon low disassembled dash adjust cables to defroster and blend doors found leak and repaired ok.

716907-0610A DRYER	1
--------------------	---

Workorder: V61176

In Date: 10/11/2013
Close Date: 07/01/2014

Meter Reading: 150,670.20

Problem?

A inspection

Parts	Quantity
-------	----------

Task performed:

A1834388002MOLD L/H	1
DOMFILTGDOMFILTG A/C FILTER FRAME NEW MEC	1
S PLACARDFRONT AND BACK PLACARD	1

Workorder: V67765

In Date: 07/08/2014
Close Date: 07/25/2014

Meter Reading: 161,110.00

Problem?

B inspection SR7

Parts	Quantity
-------	----------

Task performed:

1-2."B" Inspection 3.L-3 hold open loose. 4.L-2 door outer skin weld broken at bottom. 5.Patient compartment E-core dirty and clooging air flow. 6.Patient compartment A/C compressor support bracket bolt. Missing screw.

000090155133634 FUEL FILTER WIX MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
R90PFILTER FUEL 33231	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V67909

In Date: 07/14/2014
Close Date: 07/28/2014

Meter Reading: 161,285.00

Problem?

A inspection SR7

Parts ----- Quantity

Task performed:

- 1."A" Inspection
- 2.Assist in "A" Inspection
- 3.Assist in cab A/C repair.
- 4.Repair A/C

NO PARTS USED

Workorder: V68237

In Date: 07/29/2014
Close Date: 08/01/2014

Meter Reading:

Problem?

Air-conditioning in the front section of cab blows hot air... R48

Parts ----- Quantity

Task performed:

- 1.Recharge cab AC and cleaned rear AC condensor fans and checked rear.

NO PARTS USED

Workorder: V68472

In Date: 08/07/2014
Close Date: 08/07/2014

Meter Reading: 161,932.00

Problem?

pat a/c inop

Parts ----- Quantity

Task performed:

- Found patient AC not very cold. Ran unit. Cleaned condensor topped off system. Ran and checked ok. Check shoreline and checked ok.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V68590

In Date: 08/11/2014
Close Date: 08/12/2014

Meter Reading: 161,932.00

Problem?

A inspection SR7

Task performed:

1.Performed "A" service. 2.Performed rear axle brake job. 3.Replaced left front upper body marker light assembly. 4.Repalced left and right front turn signal side marker light bulbs. (burnt) 5.Replaced left rear strobe and repaired wiring, 6.Road tested truck after brake job and repairs. All good.

Parts	Quantity
01-0683738570BLAMP LED RED AMBER 900SERIES	1
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2

Workorder: V68671

In Date: 08/14/2014
Close Date: 08/15/2014

Meter Reading: 161,932.00

Problem?

Patient a/c not cooling well

Task performed:

Check A/C system. Found compressor cycling on and off due to high head pressure. Low side high also. Checked candelar for operating (ok). Recover freon to check for over charge. (ok) Charge system with correct amount of freon. Blow out condensor with compressed air and washed with water hose. Reconnect gauges and recheck pressures. Check pressures at high RPM. High side creped up to 300 PSI but ok art low RPM now. Front condensor fan spped seems to be slower. Replaced fan and checked pressures(same). Need to replace expansion valve and recheck. Not to be repaired.(JM) vehicle A/C is now marginally adequate.

Parts	Quantity
60027FAN A/C COND 12IN 860026-2-W	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V71474

In Date: 12/08/2014
Close Date: 12/08/2014

Meter Reading: 162,603.20

Problem?

battery cables loose

Parts

Quantity

Task performed:

Checked all connection-found lose wire on battery

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V72072

In Date: 01/06/2015

Close Date: 01/15/2015

Meter Reading: 162,894.00

Problem?

C inspection SR7

Parts

Quantity



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

* **ADVANCED LIFE SUPPORT VEHICLE**

Task performed:

1. Perform C Inspection. 2. Continued/Completed C Inspection. 3. Checked patient a/c warm, recovered system, found system low. Recharged system with Proper amount of freon. Compressor was cycling continuously. Traced problem to faulty low side switch. Replaced switch. System now operates normally and cools well. 4. Checked cab a/c warm, recovered system, found system low. Recharged system and leak checked. Found leak at low side service port. Recovered system again. Tried to replace Shrader core but found core rusted solid in fitting. 5. Cab a/c repair continued: Recovered system once again. Cut damaged a/c line from system and took line to Mako for repair. Returned from Mako and installed newly repaired a/c line. 6. Cab a/c repair continued: After new line was installed, vacuumed system and recharged. Ran system and rechecked for leaks. No further leaks found and a/c is cooling normally. 7. Installed door glass weather strip in driver's side rear door (fallen out). 8. Serviced P/S. also had to cut P/S resevoir cap off of resevoir (seized/frozen). Ordered new cap assembly. 9. Replaced rear cab a/c filter. 10. Replaced patient compartment a/c filter. 11. Painted fuel cap. 12. Fabbbed new cable and reattached oxygen wrench inside compartment. 13. Repaired light socket connections on right front turn signal side marker light assembly. 14. Replaced wiper blades. Cleaned debris from windshield squirters and topped off washer fluid. 15. Replaced broken glove butlers. Scraped off old double-sided tape, applied new tape and new glove butlers. 16. Replaced 3 cab door weatherstrips (ripped/torn). 17. Replaced compartment door reflector (broken L-4). 18. Lubed and adjusted all cab and body door latches, strikers, hinges and hold opens. 19. Replaced patient compartment door shocks. 20. Serviced air brake dryer. 21. Fabbbed new mud flap and installed. Also straightened mounting bracket and drilled new mounting holes. 22. Searched for air leaks causing overnight leak down. Found repaired fitting and airline to leveling valve. Sealed fitting on protection valve at air tank. 23. Began removing 110V roof a/c unit. 24. Completed removal and installation of 110V a/c roof unit. Unit required large amount of fabrication to fit Rescue at interior hold down plate.

000090155133634 FUEL FILTER WIX	MERCEDES	1
0001801709OIL FILTER 03 57215 WIX	MERCEDES	1
0775145PANEL FILTER		1
109995PURGE VALVE KIT		1
142211-2028 SWITCH PRESS OPEN-6 CLOSE-34		1
491576HOSE & FITTING ASSY		1
5008414CARTRIDGE DC100		1
52-24WIPER BLADES ANCO 24		2
63152HVAC UNIT ROOF MOUNTED		1
6737200054673-720-00-54 SEAL WINDOW		1
6806970098SEAL DOOR		1
681-291-00-82BRAKE PEDAL PAD		1
78R536078R5360M 2PK FILTER AIR COND		1
8201L17-3428 ESTER OIL E7		1
B2420LP-SMUD FLAP 24 X 24		1
FG87904MFG3937557S FILTER P/S NEW STYLE		1
HLD3999GSS1715UV 30LB STRUT GAS		2
NMC Q347367CAP POWER STEERING		1
R90PFILTER FUEL 33231		1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V72278

In Date: 01/13/2015

Meter Reading:

Close Date: 01/16/2015

Problem?

Vehicle hesitates to go into gear. Press N then D. D flashe . Put in N then F . R flashes. Repeat and does not ingauge . Put in D and hit manual arrow up shift goes into gear. Trans fluid just below low line

Parts ----- Quantity -----

NO PARTS USED

Task performed:

1. Checked fluid level. Found fluid good. Road tested truck several times. Could not reproduce concern. Checked transmission for codes. Found no codes. Attempted fast adapt. Could not complete. No further diagnosis wa attempted.

Workorder: V72647

In Date: 01/27/2015

Meter Reading: 163,653.10

Close Date: 01/29/2015

Problem?

A-inspection

Parts ----- Quantity -----

6806870407A/C VENT DASH COVER 1

Task performed:

1. A Inspection. 2. Dash right side a/c vent assembly broken. Remove anc install new one.



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10154111

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V73665

In Date: 03/05/2015
Close Date: 03/17/2015

Meter Reading: 164,144.00

Problem?

SR7 A inspection

Task performed:

1. A- Inspection. 2. Left rear cab window molding broken- Remove and install new molding. 3. Ca A/C inop- Check pressure- low- recover freeon is 0z- use nitrogen to check for system leak-check and found no leak- no nitrogen psi loss vacuum system- remove expansion block- intall new one change system cooling to 28 degrees.

Parts	Quantity
A1834388002MOLD L/H	1
A2245482000 12-0615A VALVE EXPANSION FTRLNF	1

Workorder: V74465

In Date: 04/06/2015
Close Date: 04/23/2015

Meter Reading: 164,144.00

Problem?

A inspection SR7

Task performed:

1. A- Inspection.

Parts	Quantity
NO PARTS USED	