



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V310

In Date: 10/19/2005
Close Date: 10/20/2005

Meter Reading:

Problem?

REAR A/C INOP, R-51

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED

Workorder: V393

In Date: 11/01/2005
Close Date: 11/07/2005

Meter Reading:

Problem?

TRUCK LEANS TO ONE SIDE, R-51

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED

Workorder: V552

In Date: 11/14/2005
Close Date: 12/12/2005

Meter Reading:

Problem?

EXHAUST STACK FLIP TOP IS MISSING R51

Parts	Quantity
-------	----------

Task performed:

20A-400CLAMP 4" 33969	1
29206CHROME STACK 24 IN 4 IN	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V888

In Date: 12/12/2005
Close Date: 12/27/2005

Meter Reading:

Problem?

CAB A/C INOP, BLOWS WARM AIR, R-51

Parts	Quantity
-------	----------

Task performed:

CM1000MODKITCIRCUT BRD CM1000 TO CM3000	1
---	---

Workorder: V943

In Date: 12/15/2005
Close Date: 12/27/2005

Meter Reading:

Problem?

CAB A/C INOP, R-51

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED	
---------------	--

Workorder: V1114

In Date: 01/04/2006
Close Date: 01/10/2006

Meter Reading:

Problem?

BACK DOOR STICKING SHUT HARD TO OPEN, R-51

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED	
---------------	--



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V1184

In Date: 01/13/2006
Close Date: 01/23/2006

Meter Reading:

Problem?

starter for service unit

Parts	Quantity
-------	----------

Task performed:

190114036842 29MT 9 TOOTH STARTER	1
-----------------------------------	---

Workorder: V1162

In Date: 01/10/2006
Close Date: 01/24/2006

Meter Reading:

Problem?

front a/c stuck on heat- rear CAB a/c blows hot R51

Parts	Quantity
-------	----------

Task performed:

22-43249-0001513 SW PRES.A/C	1
22-49905-000CABLE HEATER	1
22512960001498 SWITCH BINA	1
52-24WIPER BLADES ANCO 24	4
A22451940011499 SWITCH A/C HIGH PRESSURE NC	1
FTT5392USE 1432 SWITCH PRESSURE AC LO LIMIT	1
FTT53931491 SW PRESS. HI SIDE NC OPEN-350 CL	1
RD546400P11-2630 SWITCH BINARY	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V1773

In Date: 03/07/2006
Close Date: 03/17/2006

Meter Reading: 21,368.00

Problem?

B INSPECTION R51

Task performed:

See B Inspection pre-printed form

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
0127110042BELT MERCEDES MOTORS	1
032-0116549297 BATTERY INDICATOR	1
05-17223-000CAP RADIATOR 10 LB	1
101281012GSS6298UH STRUTS 90#	2
203FFBEARING PULLEY	1
78R536078R5360M 2PK FILTER AIR COND	1
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
R90PFILTER FUEL 33231	1

Workorder: V2023

In Date: 03/29/2006
Close Date: 04/12/2006

Meter Reading:

Problem?

NEED 5 TIRES R-51

Task performed:

Parts

Quantity

NO PARTS USED	
---------------	--

Vendor? TCI



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V2807

In Date: 06/06/2006
Close Date: 06/06/2006

Meter Reading:

Problem?

6 DOME LIGHTS INOP, R-51

Parts	Quantity
-------	----------

Task performed:

322502BULB PATIENT GH22	8
-------------------------	---

Workorder: V4020

In Date: 08/20/2006
Close Date: 08/23/2006

Meter Reading:

Problem?

water in fuel light coming on. R51

Parts	Quantity
-------	----------

Task performed:

RAIRK30880N122WSKL4000 SENSOR WATER IN FU	1
---	---

Workorder: V4197

In Date: 08/31/2006
Close Date: 09/01/2006

Meter Reading: 12,653.00

Problem?

LIGHT BAR FALLING OFF R51

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED	
---------------	--



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V4206

In Date: 09/01/2006

Close Date: 09/07/2006

Meter Reading: 12,653.00

Problem?

repair paitent a/c r51

Parts

Quantity

Task performed:

CM3000DISPLAY BOARD HOSELINE

1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V4318

In Date: 09/07/2006
Close Date: 10/02/2006

Meter Reading: 12,653.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED R51

Parts

Quantity



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* ADVANCED LIFE SUPPORT VEHICLE

Task performed:

1. REPLACED BATTERIES + CLEANED & TIGHTENED CONNECTIONS.
2. REPLACED 4 SIREN.
3. FABRICATED + INSTALLED R/R MUDFLAP.
4. REPAIRED BROKEN O2 HOLD OPEN DEVICE & REPLACED O2 WRENCH.
5. PERFORMED "B" SERVICE.
6. SERVICED AIR DRYER AND REBUILT UNIT.
7. REPLACED BELTS & IDLER PULLEY BEARING.
8. REPLACED REAR BRAKES & DRUMS, INSPECTED SEALS ADJUSTED BRAKES.
9. REPLACED 4 CAB DOOR MOULDING.
10. REPLACED HEATER TEMP CONTROL ASSEMBLY & REPLACED LIGHT, REPLACED 3 A/C DIFFUSERS.
11. TROUBLE SHOOT ELECTRICAL PROBLEM ON REAR A/C SYSTEM DISASSEMBLE R/F OF ENGINE REPLACE OIL PRESSURE SWITCH.
12. REPLACE ALTERNATOR.

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
0127110042BELT MERCEDES MOTORS	1
0332002156USE 380830 RELAY 12V 75A RLY5491	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
203FFBEARING PULLEY	1
2436A432436A43 MUD FLAP 24X36	1
29526898 29548988 TRANS FILTER ALLISON	1
3744BRAKE DRUM REAR	2
435 VALVE CAP	6
4867JB320 UPGRADE ALTERNATOR	1
50R03ZCRLIGHT LED RED TIR 6	1
52-24WIPER BLADES ANCO 24	2
6806970098SEAL DOOR	2
6808300074VENT A/C LH	2
6808300174VENT A/C RH	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
91513AMBER LENS	2
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
98003RREFLECTOR RED 40132 GROTE	1
A0631087000CABLE BATT. POS.	1
A0631088000CABLE BATT. NEG.	1
AS75807OXM1757-01 OXYGEN WRENCH	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
CA46362CA46362 RUBBER D-GRABBER	1
CA8193AIR FILTER 46744 WIX	1
DDE-000000001069USE V007603014104 SEAL WASH	1
DDE-0041534228OIL TEMP SENDER MERCEDES	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

DDE-0041534928A0071530828 OIL PRESSURE SENS	1
DOMFILTGDOMFILTG A/C FILTER FRAME NEW MEC	2
HND5941USE HAN-1L METAL LATCH INTERIOR LO	1
HP-31DBATTERY 950CCA HP-31D	4
KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2
NTE125USE 091-84-022 DIODE	2
R90PFILTER FUEL 33231	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1

Workorder: V5141

In Date: 10/29/2006 Meter Reading: 3,240.00
Close Date: 11/06/2006

Problem?

A/C in rescue is broken. Front A/C in cab blowing hot air. Rear A/C in cab also blowing hot air. R51

Parts ----- Quantity

Task performed:

1. TRAVELED TO STN 51. CHECKED CAB A/C. CLEANED CONDENSOR FAN AND CHECKED, TESTED/OK.

NO PARTS USED

Workorder: V5504

In Date: 11/23/2006 Meter Reading: 28,327.00
Close Date: 12/01/2006

Problem?

Back door latch broken,vech must be opened from inside. R-51

Parts ----- Quantity

Task performed:

1. TRAVELED TO STN 51. INSTALLED NEW REAR DOOR HANDLE.

HND5941USE HAN-1L METAL LATCH INTERIOR LO	1
HND5948TM22676-02 HANDLE DOOR ENTRY	2



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V5515

In Date: 11/24/2006
Close Date: 12/01/2006

Meter Reading: 3,340.40

Problem?

Light Bar on R51 cracked on the front right side.

Parts ----- Quantity -----

Task performed:

- 1. TRAVELED TO STN 51. FOUND SMALL CRACK IN LENS, REPAIRED LENS.

NO PARTS USED

Workorder: V5607

In Date: 11/29/2006
Close Date: 12/04/2006

Meter Reading: 3,340.40

Problem?

A/C in front intermittently not working , possibly fan motor or switch. r51

Parts ----- Quantity -----

Task performed:

- 1. REPLACED BAD BLOWER SWITCH

ABPN8332229011-3050 SWITCH BLOWER 2

Workorder: V5824

In Date: 12/15/2006
Close Date: 12/19/2006

Meter Reading: 28,327.00

Problem?

fix leak in rear passager ceilig light R-51

Parts ----- Quantity -----

Task performed:

- 1. TRAVELED TO STN 51. RESEALED ROOF AT RADIO ANTS WAS INSTALLED.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V6039

In Date: 01/02/2007
Close Date: 01/02/2007

Meter Reading: 30,188.00

Problem?

ON CALL R51 WONT START

Task performed:

Parts	Quantity
190114036842 29MT 9 TOOTH STARTER	1
ESX120105112STARTER RELAY ESX-120-105112	1

Workorder: V6040

In Date: 01/02/2007
Close Date: 01/02/2007

Meter Reading: 30,188.00

Problem?

ON CALL R51 NO START

Task performed:

Parts	Quantity
NO PARTS USED	

Workorder: V6014

In Date: 12/29/2006
Close Date: 01/03/2007

Meter Reading: 28,327.00

Problem?

Cab a/c not working. R51

Task performed:

1. Found blown fuse for condensor fans. Replaced fuse and cleaned fans checked operation ok

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V5946

In Date: 12/25/2006
Close Date: 01/04/2007

Meter Reading: 28,327.00

Problem?

weather stripping on drivers door fell off R51

Parts ----- Quantity -----

Task performed:

- 1. Rsealed door

NO PARTS USED

Workorder: V6162

In Date: 01/08/2007
Close Date: 01/16/2007

Meter Reading: 3,597.90

Problem?

o2 guage inside truck alarm sounding when bottle guage is off by 400 psi, when checked by manual guage. Sounding intermitently. r51

Parts ----- Quantity -----

Task performed:

- 1. Installed new O2 sensor and tested

AS75600MONI-A01 O2 MINDER KIT	1
M54-13SPM5413 NIPPLE	3
MG-C23SPMGC23 GAUGE	2

Workorder: V6977

In Date: 02/28/2007
Close Date: 03/08/2007

Meter Reading: 3,827.80

Problem?

rescue truck needs front tires r51

Parts ----- Quantity -----

Task performed:

- Tires installed

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V7020

In Date: 03/01/2007
Close Date: 03/23/2007

Meter Reading: 32,428.00

Problem?

REPLACE TIRES AT 51 CALLAGHAN ENT R51

Parts ----- Quantity -----

Task performed:

Replaced tires at station 51 R51 Callaghan Ent

NO PARTS USED

Vendor? CALLAGHAN ENT

Workorder: V7631

In Date: 04/10/2007
Close Date: 04/13/2007

Meter Reading: 4,020.50

Problem?

door ajar alarm will not shut off front seat passenger door sensor not working R51

Parts ----- Quantity -----

Task performed:

1. Drive to station 51 at 57 training. Drive to 58 to drop off saw. 2. R&R rf cab door switch 3. R&R cab door switch

91823SWITCH SWT5499 MED MASTER 1
A0048201010SWITCH DOOR 1

Workorder: V7693

In Date: 04/13/2007
Close Date: 04/25/2007

Meter Reading: 33,896.00

Problem?

need 02 alarm transducer- unit with 1,000 psi bottle will read 500 and set of alarm R51

Parts ----- Quantity -----

Task performed:

Found all bottles low @ station; system is working.

AS8069702 REGULATOR-TRANSDUCER 1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V7822

In Date: 04/19/2007
Close Date: 04/30/2007

Meter Reading: 34,688.00

Problem?

b inspection and repairs as needed r51

Task performed:

B-Inspection 1. Rep L2 door opn brkt; L2 helmet hook, L2 door open; drill & nut; L3 brkt blts & faskten; tighten L4 loose ltch; replc pat compt hldopn brkt/rod; Tighten R1 striker; lube ltches & hldopns; 2. Press chk cooling sys; fnd bad hse clmp; replc clmp & refill coolant; add (4) qts trans fluid; tighten frm antenna; replc rear A/C filter cab. 3. rem LF & RF seats for repair; install setas 4. Svc Batteries 5. Torque u-bolts 6. R/R L. frnt door pnl; sec brkn trim piece; not able to obtain new part; on B/O. 7. Tighten ...brkt bolts 8. Adj brakes 9. Rem exh flex pipe; chk for crack-ok; Cln/reinstall with new clamps. 10. Rem road draft hse & replc with 1" hose 11. Chk all computers for codes. 12. Dia O2 leak; replc valve stem; rewired gauge. 13. Adj washer squirter. 14. Replc rear pat compt high beach bulbs 15. Dia LR dome lite-inop; rem hnd brkts seat belt retractor; door wtherstip & pnl; fnd wire off & taped; Cut wire/install new terminal. 16. Replc msng lug nut cvrs & tighten all loose ones. 17. Rep rear tires 18. re seat SCBA; insert pads

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
20A-400CLAMP 4" 33969	2
322502BULB PATIENT GH22	2
78R536078R5360M 2PK FILTER AIR COND	1
ACX-84534LUG NUT COVER PK10	3
HLD374211 IN HOLD-OPEN 30LB	1
M54-13SPM5413 NIPPLE	1
R90PFILTER FUEL 33231	1
RP00126BRACKET - HOLD OPEN	2
S777COUPLING NIPPLE	1

Workorder: V7996

In Date: 04/30/2007
Close Date: 05/02/2007

Meter Reading: 34,364.00

Problem?

check engine light on- guages innoperative R51

Task performed:

Fnd alternator overcharging; replc alternator.

Parts	Quantity
4867JB320 UPGRADE ALTERNATOR	1
AS77909SENDER TRANSDUCER	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V7997

In Date: 04/30/2007
Close Date: 05/02/2007

Meter Reading: 34,364.00

Problem?

oxygen warning alarm on R51

Parts ----- Quantity -----

Task performed:

O2 warning goes off sometimes; transducer defective. Replace transducer.

NO PARTS USED

Workorder: V7909

In Date: 04/24/2007
Close Date: 05/04/2007

Meter Reading: 34,688.00

Problem?

repair seats at central r51

Parts ----- Quantity -----

Task performed:

Repair seats

NO PARTS USED

Vendor? CENTRAL AUTO TRIM

Workorder: V8060

In Date: 05/02/2007
Close Date: 05/17/2007

Meter Reading: 4,073.20

Problem?

a/c inside patient compartment is leaking lots of water onto stretcher. R-51

Parts ----- Quantity -----

Task performed:

Replc drain fitting on A/C unit Adjusted stretcher mount

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V7847

In Date: 04/20/2007
Close Date: 07/03/2007

Meter Reading: 34,688.00

Problem?

replace tires at callaghan ent r51

Parts ----- Quantity -----

Task performed:

Replace tires - Callaghan

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V10257

In Date: 09/05/2007
Close Date: 09/25/2007

Meter Reading: 38,866.00

Problem?

check tires r51

Parts ----- Quantity -----

Task performed:

1. Need 2 front tires.

NO PARTS USED

Workorder: V10591

In Date: 09/21/2007
Close Date: 09/27/2007

Meter Reading: 4,743.40

Problem?

A/C works intermediate and bracket. R51

Parts ----- Quantity -----

Task performed:

1. REPAIRED AIR PACK BRACKET. 2. CHECKED PROBLEM WITH A/C FOUND BAD CONNECTION FOR BLOWER MOTOR.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V10240

In Date: 09/04/2007
Close Date: 09/28/2007

Meter Reading: 38,866.00

Problem?

replace front tires at sta 51

Parts ----- Quantity -----

Task performed:

Replc front tires - Callaghan

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V10767

In Date: 10/01/2007
Close Date: 10/03/2007

Meter Reading: 4,840.70

Problem?

a/c in rear compartment of r51 not working

Parts ----- Quantity -----

Task performed:

1. A/C INOP- REPLACED BELT

9425BELT MERCEDES RESCUE 12.5X1075 OE 1

Workorder: V9415

In Date: 07/19/2007
Close Date: 10/15/2007

Meter Reading: 1,069.90

Problem?

FRONT PASSENGER SIDE AIRSEAT DOES NOT FUNCTION R51

Parts ----- Quantity -----

Task performed:

repaired air line under seat

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V10744

In Date: 09/29/2007
Close Date: 10/22/2007

Meter Reading: 4,840.70

Problem?

molding on top of front passenger door is broken R51

Parts ----- Quantity

Task performed:

installed new molding on right front door

A1834388003MOLD R/H	1
---------------------	---

Workorder: V10834

In Date: 10/04/2007
Close Date: 10/23/2007

Meter Reading: 40,008.00

Problem?

repair rt side molding

Parts ----- Quantity

Task performed:

1. repaired drivers side door panel

NO PARTS USED	
---------------	--

Workorder: V11423

In Date: 11/05/2007
Close Date: 11/05/2007

Meter Reading: 1,588.80

Problem?

siren 10-7 R51

Parts ----- Quantity

Task performed:

Drove from Okeechobee to Stn51; fnd bad siren head;went to shop to get siren & back to Stn51; installed siren & check speaker-ok

NO PARTS USED	
---------------	--



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V10922

In Date: 10/09/2007
Close Date: 11/13/2007

Meter Reading: 40,008.00

Problem?

repair stretcher R51 (outside agency-medco equipment repair)

Parts ----- Quantity -----

Task performed:

Rep stretcher R51 - Medco Eqpmt

NO PARTS USED

Vendor? MEDCO

Workorder: V11636

In Date: 11/16/2007
Close Date: 11/29/2007

Meter Reading: 41,533.00

Problem?

air leak r51

Parts ----- Quantity -----

Task performed:

1. Replaced purge valve.

800405PURGE VALVE KIT 1

Workorder: V11690

In Date: 11/20/2007
Close Date: 11/30/2007

Meter Reading: 4,999.00

Problem?

Patient compartment a/c in R51 is 10-7. r51

Parts ----- Quantity -----

Task performed:

1. Removed and replaced blower motor. 2. Readjusted rear door latch that would not open door.

UNT1400BLOWER MTR. + SQU IRREL CAGE ASSY. 1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V11825

In Date: 11/30/2007
Close Date: 12/11/2007

Meter Reading: 42,190.00

Problem?

repair siren r51

Parts ----- Quantity -----

Task performed:

1. Traced out problem with gauge found discharge sencer N/G removed and repaired.

NO PARTS USED

Workorder: V12061

In Date: 12/13/2007
Close Date: 12/19/2007

Meter Reading: 5,110.00

Problem?

tread low on back tires of rescue- and- check out lights in back pt compartment not working. R51

Parts ----- Quantity -----

Task performed:

1. Installed new bulbs in check out lights. 2. Checked tires and checked OK.

NO PARTS USED

Workorder: V12737

In Date: 01/22/2008
Close Date: 01/29/2008

Meter Reading: 5,294.00

Problem?

rear left scene light not working. R51

Parts ----- Quantity -----

Task performed:

1. Removed bulb for right rear back up and replaced. 2. O2 alarm going off- traced out problem found O2 guage on bottle was N/G

H35SN12BULB	2
MG-C23SPMGC23 GAUGE	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V12710

In Date: 01/21/2008 Meter Reading: 44,584.00
Close Date: 02/01/2008

Problem?

rear light bar one white light (left) R51

Parts ----- Quantity -----

Task performed:

Truck not stopping after new tires installed; adj brakes. j

NO PARTS USED

Workorder: V12738

In Date: 01/22/2008 Meter Reading: 5,294.00
Close Date: 02/01/2008

Problem?

Drivers keyhole does not accept key R51

Parts ----- Quantity -----

Task performed:

1.Kon drivers door not locking; rem door panel & reconn linkage. 2. Truck not stopping; adj brakes & took free play out of foot pedal. j

NO PARTS USED

Workorder: V12734

In Date: 01/22/2008 Meter Reading: 5,294.00
Close Date: 02/05/2008

Problem?

rear tires need to be replaced, wear bars and bold.

Parts ----- Quantity -----

Task performed:

Rear tires need to be replaced, wear bards and bold. Callaghan j

NO PARTS USED

Vendor? *



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V12921

In Date: 01/30/2008
Close Date: 02/06/2008

Meter Reading: 44,885.00

Problem?

B INSPECTION R-51

Task performed:

1. Perform "B" service 2. Replaced all 4 batteries 3. Replaced wiper blades 4. Replaced front tires 5. Cleaned shop 6. R & R comp. lights 7. R & R front fender turn signal lens 8. Remove non-skid tape and glue, installed new tape on passanger side. 9. Replace dome light, check out and rewire unit. 10. R & R cab a/c filter and box filter 11. R & R front tire and put back old tires 12. replaced engine air filter

<u>Parts</u>	<u>Quantity</u>
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
15W40BSYN OIL BULK QTS	24
322502BULB PATIENT GH22	4
52-24WIPER BLADES ANCO 24	2
78R536078R5360M 2PK FILTER AIR COND	1
91513AMBER LENS	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
CA8193AIR FILTER 46744 WIX	1
HP-31DBATTERY 950CCA HP-31D	4
R90PFILTER FUEL 33231	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	2

Workorder: V3836

In Date: 08/08/2006
Close Date: 02/07/2008

Meter Reading:

Problem?

filter minder graduated indicator broken

Task performed:

<u>Parts</u>	<u>Quantity</u>
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V4305

In Date: 09/07/2006
Close Date: 02/07/2008

Meter Reading:

Problem?

Air condition unit in the patient compartment is shorting out and works very intermittently. R51

Task performed:

Parts	Quantity
RCB BOXBOX/COVER FOR RCB3000	1
RCB-3000CONTROL BOARD USE WITH CM3000	1

Workorder: V13326

In Date: 02/19/2008
Close Date: 02/20/2008

Meter Reading: 5,434.40

Problem?

Unable to lock drivers compartment on r51

Task performed:

1. Readjusted door lock linkage and tested 2. Rear air bag out of adjustment, readjusted bags and road tested

Parts	Quantity
NO PARTS USED	

Workorder: V13476

In Date: 02/25/2008
Close Date: 03/04/2008

Meter Reading: 46,001.00

Problem?

r51 leaking fluid

Task performed:

1. CHECKED FOR LEAKS NONE FOUND. 2. MED DOOR NOT LOCKING CLEANED AND ADJUSTED LATCH.

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V13797

In Date: 03/10/2008
Close Date: 03/14/2008

Meter Reading: 46,344.00

Problem?

Battery switch malfunctioning R51

Parts ----- Quantity -----

Task performed:

- 1. Replaced battery switch that was staying on

Parts	Quantity
75908SWITCH BATTERY MASTER 300A	1

Workorder: V13829

In Date: 03/11/2008
Close Date: 03/20/2008

Meter Reading: 5,536.30

Problem?

Air pressure gauge to main O2 cylinder is not reading appropriately. Gauge is stuck on 1500 PSI, even when tank is empty. R-51

Parts ----- Quantity -----

Task performed:

- 1. Replaced main pressure guages on main tank

NO PARTS USED	
---------------	--

Workorder: V14080

In Date: 03/25/2008
Close Date: 04/11/2008

Meter Reading: 47,113.00

Problem?

Fire extinguisher mount in pt compartment broken r51

Parts ----- Quantity -----

Task performed:

- need brackets in pt compartment for fire exting.

101305009SS0001 CPI SHELF BRACKET ONE HOLE	6
--	---



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V14604

In Date: 04/21/2008
Close Date: 04/30/2008

Meter Reading: 5,738.10

Problem?

Not working R51

Parts ----- Quantity -----

Task performed:

1. checked out problem with back up cam. found no problem at this time.

NO PARTS USED

Workorder: V14838

In Date: 05/03/2008
Close Date: 05/13/2008

Meter Reading: 5,792.00

Problem?

light box chargers are not charging hand lights R51

Parts ----- Quantity -----

Task performed:

1. checked hand light charger-tested ok

NO PARTS USED

Workorder: V15148

In Date: 05/17/2008
Close Date: 06/05/2008

Meter Reading: 5,852.00

Problem?

bottom supply drawer track broken- pt compartment of rescue truck. R51

Parts ----- Quantity -----

Task performed:

1. Replc slides in med drawer. 2. Rear door hard to open; adj linkage. 3. Installed hook in cab. j

14-7014HGR-1 HELMET HOOK	4
SLD5366HT4932-16 DRAWER SLIDE 16	4



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V12957

In Date: 01/31/2008
Close Date: 06/12/2008

Meter Reading: 44,885.00

Problem?

replace front tires callaghan

Parts ----- Quantity -----

Task performed:

Replace front tires - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V14169

In Date: 03/30/2008
Close Date: 06/17/2008

Meter Reading: 5,670.10

Problem?

passenger side headlight out, lightbar is cracked on passenger side and there are 2 lights on this bar (2nd from center) that dont light r51

Parts ----- Quantity -----

Task performed:

1. crew replaced headlite.

FZ51368FEET RUBBER RAM-FAN 2

Workorder: V15805

In Date: 06/17/2008
Close Date: 07/11/2008

Meter Reading: 159.70

Problem?

AC Unit in pt. compartment does not blow cold air, also crack on plastic dashboard board getting bigger. r51

Parts ----- Quantity -----

Task performed:

1. Cld condensor fans & coils tested & tested ok. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V16168

In Date: 07/05/2008
Close Date: 07/18/2008

Meter Reading: 266.60

Problem?

brackets for infectious draw are broken, drawer fell out when opened. R51

Parts ----- Quantity

Task performed:

1. Installed new slides for bio door. 2. Air leak; rep air leak in seat. j

2220-10SLIDE 10 IN	2
--------------------	---

Workorder: V16532

In Date: 07/23/2008
Close Date: 07/30/2008

Meter Reading: 51,427.00

Problem?

ON CALL R51 AIR LEAK

Parts ----- Quantity

Task performed:

Air leak dia for air sender leaking; replc unit. j

76575-4-NOSWITCH	1
FSC17492134NC SW PARK BK SPADE TYPE CONNE	2

Workorder: V16667

In Date: 07/29/2008
Close Date: 08/14/2008

Meter Reading: 6,169.00

Problem?

front ac unit working intermediate R-51

Parts ----- Quantity

Task performed:

1. Blower A/C switch inop; replace blower switch. 2. Chk out lights inop; replcd bulbs. j

ABPN8332229011-3050 SWITCH BLOWER	2
RV17YCUSE 25 AUTOLITE SPARK PLUG NGK 6630	4



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V16987

In Date: 08/12/2008
Close Date: 08/15/2008

Meter Reading: 6,285.70

Problem?

Rear Traffic Advisor light. The screws on the right side coming out and light become unsecure to the Rescue R51

Parts _____ Quantity _____

Task performed:

Rep rear traffic advisor that was falling off. j

NO PARTS USED

Workorder: V16546

In Date: 07/23/2008
Close Date: 08/22/2008

Meter Reading: 51,427.00

Problem?

replace all tires at sta 51 callaghan

Parts _____ Quantity _____

Task performed:

Replace all tires at Stn51 - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V17237

In Date: 08/22/2008
Close Date: 08/29/2008

Meter Reading: 6,246.30

Problem?

drivers side window won't crank window up. R51

Parts _____ Quantity _____

Task performed:

Replc door window crank left door. j

A1818557002HANDLE-WINDOW 1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V17367

In Date: 08/28/2008
Close Date: 09/02/2008

Meter Reading: 6,302.80

Problem?

AC in pt compartment blowing warm R51

Parts ----- Quantity -----

Task performed:

Pat compt A/C inop; low refrigerate; leak tested; rep leak at Shrader; recharged; cld condensor. j

NO PARTS USED

Workorder: V17588

In Date: 09/08/2008
Close Date: 09/29/2008

Meter Reading: 6,418.20

Problem?

turn signal don't work at all. Hazards light up fine. Nothing displays on dash or front or back for both signals. R51

Parts ----- Quantity -----

Task performed:

Found bad connection at steering column and repaired.

6805450124SWITCH TURN SIGNAL 1

Workorder: V17789

In Date: 09/18/2008
Close Date: 10/07/2008

Meter Reading: 53,081.60

Problem?

biohazard drawer 10-7 r51

Parts ----- Quantity -----

Task performed:

1- installed new slides for med compartment.

2220-12USE 5632-12 DOOR SLIDE 2
SLD5362USE 12 IN DRAWER SLIDE 10 IN 2



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V17841

In Date: 09/21/2008
Close Date: 10/07/2008

Meter Reading: 6,418.20

Problem?

Driver side of vehicle. Front alley light (closest to the cab) 10-7. R51

Parts -----

Quantity -----

Task performed:

1- found no lighth out on rescue.

NO PARTS USED

Workorder: V16477

In Date: 07/21/2008
Close Date: 10/17/2008

Meter Reading: 6,140.50

Problem?

R51 needs front tires and possibly rear tires.

Parts -----

Quantity -----

Task performed:

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V18497

In Date: 10/22/2008

Meter Reading: 54,766.00

Close Date: 11/05/2008

Problem?

C INSPECTION AND REPAIRS AS NEEDED R51

Parts

Quantity



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* ADVANCED LIFE SUPPORT VEHICLE

Task performed:

1. C-Inspection
2. C-Inspection
3. R/R/ air dryer.
4. Svc cooling sys.
5. Svc rear end.
6. Rep cabinet door latch.
7. Resecure headboard over rear doors.
8. tighten all steering colun bolts.
9. R/R belts.
10. Svc power steering.
11. r/R air filter.
12. torque U-bolts.
13. R/R rear brakes & drums.
14. Start installing fish plate.
15. Finish installing frame fish plate.
16. Finish up fish plate.
17. Rem door panels; tighten outside door handles.
18. C/O repair broken wires for all door warning lights.
19. C/O replace L/F pat compt light asy.
20. R/R pat compt steps grip tape.
21. r/R door seals.
22. electrical test.
23. tighten & lube all door latches.
24. Rem R/R wheel & adjust ab s sensor.

0000900087DDE/A0000900087 FILTER HEAD SM MEI	1
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
0127110042BELT MERCEDES MOTORS	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	2
15-22150-06OIL PLUG ADAPTER MBE900	1
15W40BSYN OIL BULK QTS	24
161657700065489 SHOCK REAR NEW RESCUE	2
25-SF350-002L-SERT REINFORCEMENT	1
322502BULB PATIENT GH22	1
3744BRAKE DRUM REAR	2
55021-07SWITCH	1
6806970098SEAL DOOR	2
800405PURGE VALVE KIT	1
921LIGHT BULB	1
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
ACX-84534LUG NUT COVER PK10	3
AEVDOOR LOCK BEZEL	1
AMH-1AMH-1 VALVE EXTENSION	1
CA8193AIR FILTER 46744 WIX	1
DOOR5LEXAN 9 X 38 1/2 IN	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
HLD39914GSS7139UK STRUT 90#	2
KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2
R90PFILTER FUEL 33231	1
WKL0381DOME LIGHT WELDON 8046	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V18648

In Date: 10/28/2008
Close Date: 11/10/2008

Meter Reading: 547,667.00

Problem?

REPAIR SEAT CENTRAL AUTO TRIM

Parts ----- Quantity -----

Task performed:

Repair seat - Central Auto j

NO PARTS USED

Vendor? CENTRAL AUTO TRIM

Workorder: V18950

In Date: 11/09/2008
Close Date: 12/01/2008

Meter Reading: 547,667.00

Problem?

the biohazard draw in the back of r51 fell out again

Parts ----- Quantity -----

Task performed:

1. Rep bio draw that was brkn; rep slides. 2. Adj air pack brkts that were out of adjustment. j

2220-12USE 5632-12 DOOR SLIDE 4

Workorder: V19436

In Date: 12/01/2008
Close Date: 12/12/2008

Meter Reading: 6,682.00

Problem?

siren is jammed on and has to be turned off at the power switch on the console, if not the siren turns on when you turn the truck on. Red button seems to be jammed in the console. R51

Parts ----- Quantity -----

Task performed:

Siren inop; replcd siren head. j

01-0862064-00SIREN FRONT SIDE 1
295SLSA1SIREN 1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V19558

In Date: 12/05/2008
Close Date: 01/05/2009

Meter Reading: 6,698.30

Problem?

REAR RIGHT SCENE LIGHT DOES NOT WORK. E-51

Parts ----- Quantity -----

Task performed:

Rep bad connection on rear scene light. j

NO PARTS USED

Workorder: V19797

In Date: 12/16/2008
Close Date: 01/06/2009

Meter Reading: 6,763.50

Problem?

bracket that holds tube used to fill inner tire on left rear tire is broken. r51

Parts ----- Quantity -----

Task performed:

Rem brkt from rear wheels. j

NO PARTS USED

Workorder: V19978

In Date: 12/27/2008
Close Date: 01/06/2009

Meter Reading: 6,825.80

Problem?

The A.C is leaking water into the pt. compartment, (alot of water). R51

Parts ----- Quantity -----

Task performed:

cLN a/c DRAIN IN REAR; LEAKING WATER IN BACK. J

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V20521

In Date: 01/22/2009
Close Date: 01/28/2009

Meter Reading: 9,665.80

Problem?

R51 biohazard drawer was just repaired and it flew out of track again today.

Parts ----- Quantity -----

NO PARTS USED

Task performed:

1- checked bio drawer and found no problem with drawer.

Workorder: V20447

In Date: 01/19/2009
Close Date: 02/13/2009

Meter Reading: 9,665.80

Problem?

rescue 51, map light (red plastic casing cracked off, bulb replacement- two of the cabinets inside pt compartment air pistons do not hold up cabinets. Biohazard drawer flies out of track during driving.

Parts ----- Quantity -----

1012910235619A STRIKER PLATE 1

Task performed:

1. Maplight inop; replcd bulb in maplight. 2. Bio drawer slides out; rep stop on bid drawer. 3. Replcd pistons on cabinents in rescue. 4. Compt lights inop; fnd bad connection on relay grnd. j

Workorder: V20625

In Date: 01/27/2009
Close Date: 02/18/2009

Meter Reading: 7,036.00

Problem?

the head light is out on r51

Parts ----- Quantity -----

NO PARTS USED

Task performed:

1. Replcd headlight that was out. 2. Rear door hard to open; adj door linkage. 3. Pat lights go on/off at times; fnd bad connecton on board. 4. A/C making noise in rear; ran A/C & fnd no noise at this time. j



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V20982

In Date: 02/09/2009
Close Date: 02/28/2009

Meter Reading: 58,918.00

Problem?

REPLACE 2 FRONT TIRES, R-51

Parts ----- Quantity -----

Task performed:

Replace (2) front tires r51 - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V20594

In Date: 01/26/2009
Close Date: 03/10/2009

Meter Reading: 6,955.90

Problem?

request 3 glove holders in cab and 3 in patient compartment. thankyou r51

Parts ----- Quantity -----

Task performed:

1. Rear compt door pistons; replcd door pistons. 2. Installed glove holder in cab. j

HLD3999GSS1715UV 30LB STRUT GAS 4

Workorder: V21965

In Date: 03/20/2009
Close Date: 04/03/2009

Meter Reading: 1,411.40

Problem?

front two patient compartment flourescent lights burned out. R-51

Parts ----- Quantity -----

Task performed:

Installed new bulbs in pat light that was out. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V22161

In Date: 03/28/2009
Close Date: 04/13/2009

Meter Reading: 1,469.30

Problem?

emergency light lens cracked on upper rear on r-51.

Task performed:

1. Brkn rear light bar; rep rear light bar. 2. Brkn frnt turn signals; replcd lense. 3. Rear dome lights inop; rep bad grd. 4. Air leak; chkd for air leaks. j

Parts	Quantity
02034293401DIVIDER 4500 LITE BAR	4
02034294100LENS RETNR 4500 LITE BAR	4
6839837995068-3983799-50 LENS RED	2
68398381350LENS END 4500 LITE BAR RED	1

Workorder: V22488

In Date: 04/12/2009
Close Date: 04/29/2009

Meter Reading: 7,329.00

Problem?

Rescue 51 headlight is out

Task performed:

rem headlight & installed new one. j

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V22940

In Date: 04/30/2009

Close Date: 06/15/2009

Meter Reading: 62,354.80

Problem?

B inspection...R-51

Parts

Quantity



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* ADVANCED LIFE SUPPORT VEHICLE

Task performed:

1. Road test & B-Inspection. 2. Test btry-failed; cln btry post; fnd excessive oil/dirt on LED screw on test post; cln/perform carbon load test on each btry; passed. 3. Cab A/ C condensor fan inop; dia fault; fnd fan motor seized up; rem fan motor & install new motor; operate unit. 4. water pump failed; diss/rem water pump; replcd leaking fuel strainer cap. 5. Swapout of on-call unit; fuel/cln unit; transport to home fro personal vehicle. 6. Cln water pump surface; install water pump. 7. Rem alt tensioner & install new tensioner. 8. Rem brkn air compressor coolant line & install new coolant line. 9. Rem fuel pump; waiting for parts. 10. Rem fuel return line; waiting for parts. 11. Rem A/C compressor tensioner pulley for bearing replacement; waiting for parts. 12. Install A/C tensioner pulley bearing & install on unit. 13. Install fuel return line & sec to specs. 14. Install fuel pump & sec as to mfrg specs. 15. Install new air compressor cooling line. 16. (3) window molding brkn rem/install new moldings. 17. Rem fuel return; chk valve & install new chk valve. 18. Wiper blades (windshield) bad; rem/install new blades. 19. Brkn tire valve stem support; R/R brkn valve stem support. 20. Flags faded; rem/install new flags. 21. Rem bad cabient struts & install new ones; Sec loose pat compt cabient door molding. 22. Driver door, L-rear pass door & frnt pass door light inop; fnd loose grnd L-rear door; rep fault; blown frnt doors light; replc/rewire chassis; grounded LED. 23. Med wastbin - rem partition frm stainless brkt. 24. Clnup work area. 25. Diff installation of high water; protection breather 26. Install new updated fuel injector lines & torque to mfrg specs of 18 ft. lbs; bleed air from fuel sys & operate eng & road test. 27. Reassemble water pump & associated parts. 28. Change coolant. 29. Pat compt light; change out (3) blown bulbs & secure on loose grnd butt connection. 30. Pat compt exh vent inop; dia fault; fnd fan blade msgng; rem motor & install new fan & motor. 31. Cln up work area. j

0000900087DDE/A0000900087 FILTER HEAD SM MEI	1
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
15W40BSYN OIL BULK QTS	24
322502BULB PATIENT GH22	3
52-24WIPER BLADES ANCO 24	2
607141-05USE 61H01 COPMPARTMENT LIGHT	2
680-10LAMERICAN FLAG W UV CLEAR LEFT	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
6805450005RELAY NEW # POT-BFMA-15F41	2
9060910580FUEL PUMP GASKET M2	1
9060920510FUEL CHECK VALVE	1
9062010080GASKET M2 WATER PUMP	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	1
A9060702333FUEL LINE TUBES	6
A9060901276A9060903376 FUEL LINE	1
A9062030102A9062037102 COOLANT LINE	1
AMH-1AMH-1 VALVE EXTENSION	1
DDE-0052035975A0052032675 THERMOSTAT ELEMI	2
DDE-9062030180GASKET SOCKET TO HEAD M2	1
DDE-R0040910501FUEL PUMP M2	1
DDE/0209971148A0249972848 SEAL RING	2
DDE/9062002470BELT TENSIONER MERCEDES	1
DDE/R9062006201RA906200620 WATER PUMP REM	1
ELB56711446175 BLOWER 4 IN	1
EXO3AH00015SPLUG RAD. DRAIN	1
HLD3999GSS1715UV 30LB STRUT GAS	2
R90PFILTER FUEL 33231	1
RD571290 01-2616 MOTOR 12V 73R-0542 3512	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

S777COUPLING NIPPLE

1

Workorder: V23875

In Date: 06/06/2009

Meter Reading: 7,535.30

Close Date: 06/19/2009

Problem?

Water is leaking into pt compartment through A/C R51

Parts

Quantity

Task performed:

1. Water leak in rear; fnd no leak at this time. 2. Maplight inop; replcd maplight. 3. Pat lights not working; rep bad connection. 4. Air leak; traced out air leaks & rep where needed. j

LF18TS-LED MAP LIGHT LED 18 IN

1

Workorder: V23959

In Date: 06/10/2009

Meter Reading: 63,394.90

Close Date: 07/06/2009

Problem?

REAR A/C 10-7 R51

Parts

Quantity

Task performed:

1. Rear A/C inop; recharged sys & clnd coil/condensor. 2. Side door hard to open; readj door linkage. j

NO PARTS USED

Workorder: V24953

In Date: 07/21/2009

Meter Reading: 449.90

Close Date: 07/28/2009

Problem?

R51's cab AC (the front) is not working at all tonight. It is not blowing air.

Parts

Quantity

Task performed:

A/C not working in cab; recharged A/C & chkd for leaks. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V25394

In Date: 08/08/2009 Meter Reading: 7,818.00
Close Date: 08/27/2009

Problem?

Requesting short halligan for R51

Parts ----- Quantity -----

Task performed:

BC5 needs to ok this insulation. j

NO PARTS USED

Workorder: V25424

In Date: 08/10/2009 Meter Reading: 65,440.00
Close Date: 08/27/2009

Problem?

passenger side seat belt will not clip

Parts ----- Quantity -----

Task performed:

1. Replcd seat belt latch; & tested. 2. Rear door hard to open; adj rear door. j

IMMF11358SEAT BELTS 1

Workorder: V25798

In Date: 08/26/2009 Meter Reading: 7,960.20
Close Date: 09/14/2009

Problem?

replace all 6 tires R51 (outside Agency- callaghan tire)

Parts ----- Quantity -----

Task performed:

Replace all (6) tires R51 - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V25531

In Date: 08/14/2009
Close Date: 09/30/2009

Meter Reading: 7,907.30

Problem?

Front right tire wearing improper. R-51

Parts ----- Quantity -----

Task performed:

Chkd tires & chkd ok. j

NO PARTS USED

Workorder: V27028

In Date: 10/20/2009
Close Date: 10/27/2009

Meter Reading: 68,229.00

Problem?

front a/c innop R51

Parts ----- Quantity -----

Task performed:

1. Replcd lo-side line fitting at compressor; vac/recharged. 2. Replcd condensor fan behind driver's side rear cab step. 3. R/R A/C compressor/dryer & exp valve pump down & charger. 4. R/R all press switch; mod brkt to install; T-shoot check engine light. 5. Ck/adj rear air bags; assist on rep for ck eng light on & went for A/C fittings at Mako. j

346718HOSE FITTINGS	1
533103-0607 A/C COMPRESSOR U4482 USE 7169 D	1
716907-0610A DRYER	1
A22454320011602 EXPANSION VALVE	1
DDE-0041534928A0071530828 OIL PRESSURE SENC	1
DDE/007603016102RING FUEL PUMP	1
RD571290 01-2616 MOTOR 12V 73R-0542 3512	1
S1818COUPLING	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V26484

In Date: 09/27/2009
Close Date: 11/06/2009

Meter Reading: 8,089.60

Problem?

cab of rescue 51 second top running light on officers side is out.

Parts ----- Quantity -----

Task performed:

1. Rep all marker lights that were out. 2. Recharged rear A/C. j

NO PARTS USED

Workorder: V27078

In Date: 10/22/2009
Close Date: 11/23/2009

Meter Reading: 8,203.70

Problem?

R51 will be in for repairs and PM starting today. R51 will also needan alignment as has been previously reported due to severe pulling to the right

Parts ----- Quantity -----

Task performed:

1. Ck frnt end alignment; fnd axle toed in 12mm; adj toe; test drove; ck ok.
2. Fnd pat dome lts out; R/R (3) dome lt bulbs. 3. Fnd inside door panel latches brkn; rem stainless door panels; had to grind plate to frt new latches; replc latches; reassembled/ck opn; ck ok. 4. Fnd pat compt door shocks worn; R/R (6) shocks; R/R door locks; ck ok. j

322502BULB PATIENT GH22	3
921LIGHT BULB	2
HAN-1LBEZEL AND HANDLE	2
HLD3999GSS1715UV 30LB STRUT GAS	6



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V27073

In Date: 10/22/2009

Meter Reading: 8,203.70

Close Date: 11/30/2009

Problem?

Back up camera goes out intermittantly, right now back up camera not working for rear of truck. R51

Parts

Quantity

Task performed:

1. Perform quality control check. 2. Fnd drivers door outside latch not working; rem inside door panel; rem latch asy; rep rods/linkages; reassembled all parts; ck ok. 3. Fnd holddown straps loose in compts; tightened. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V27085

In Date: 10/22/2009

Meter Reading: 68,282.00

Close Date: 11/30/2009

Problem?

C INSPECTYION AND REPAIRS AS NEEDED R51 / CHECK ENG LT ON

Parts

Quantity

Task performed:

C-Inspection 2. Load test btry; R/R btrys; clnd cables, (4) btrys. 3. Fnd window rubber out of window on Rt side; reinstalled rubber seal; ck opn; ck ok. 4. R/R (2) door catch latches. 5. Fnd compt doors/inside panels loose; adj all doors & tightened all inside door panels. 6. Rebuild air dryer. 7. Fnd windshield washer innnop on pass side; replc hse fitting; clnd hoses; ck compt-ck ok; R/R wiper blades. 8. Fnd air compressor leaking coolant; drained anti freeze; rem hoses, P/S pump, water lines, brkts, etc.; R/R air compt; reassembled all parts; filled cooling sys; ran/ck ok. 9. Fnd stretcher lock brkn; R/R stretcher lock; mnt bolt nut stripped; R/R nuts; adj/ck opn; ck ok. 10. Fnd exh fan noisy; rem shelf, inside panel & blower; drilled/remnt fan; reassembled all parts; ck ok. 11. Ck for air leaks sprayed all drains/lines; fnd air horn line leaking; rep leak; ran/ck ok. 12. R/R belts; eng & A/C belts. 13. Ck L.R.O. tire leaking; fnd extension hose leaking; rep leak; aired tire. 14. Fnd marker lts out; R/R (2) bulbs; ck ok. 15. Replc pat A/C filter; did not have new one; clnd/reinstalled filter. 16. Fnd fuse panel ____ panel loose; rem panel; rep clips & replc msgng screws; ck ok. j

0000900087DDE/A0000900087 FILTER HEAD SM MEI	1
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
0127110042BELT MERCEDES MOTORS	1
090-0278STRECHER BAR NEW	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
15W40BSYN OIL BULK QTS	28
18-29935-001RH DOOR LATCH NEW	1
18-45484-000LATCH L/H	1
194BULB	2
52-24WIPER BLADES ANCO 24	2
6809881078DZ STUD	1
800405PURGE VALVE KIT	1
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
ACX-84534LUG NUT COVER PK10	11
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
CA8193AIR FILTER 46744 WIX	1
ELB56711446175 BLOWER 4 IN	1
HP-31DBATTERY 950CCA HP-31D	4
R90PFILTER FUEL 33231	1
RA9061301415AIR COMPRESSOR	1
SPR-W58-1TEE PLASTIC	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V27770

In Date: 11/18/2009
Close Date: 12/08/2009

Meter Reading: 8,210.00

Problem?

Directional lights out R51

Parts ----- Quantity -----

Task performed:

No T-gisnals; fnd bad grd. j

NO PARTS USED

Workorder: V26581

In Date: 09/30/2009
Close Date: 12/09/2009

Meter Reading: 67,233.50

Problem?

Need to add coolant to R-51. There is none in the station. We need some sent down.

Parts ----- Quantity -----

Task performed:

1. Chkd for coolant leak; fnd none at this time. 2. Rep right side air pack holders. j

ALA00350-50 EXTENDED LIFE COOLANT GAL 2

Workorder: V28521

In Date: 12/22/2009
Close Date: 01/06/2010

Meter Reading: 70,201.70

Problem?

On call electrical problem pat compartment R51

Parts ----- Quantity -----

Task performed:

Electrical problem in pat compt. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V28613

In Date: 12/28/2009
Close Date: 01/08/2010

Meter Reading: 70,620.00

Problem?

ON CALL R51 CHECK ENG LT ON

Parts _____ Quantity _____

Task performed:

Chk eng light; fnd no codes; road tested & tested ok. j

NO PARTS USED

Workorder: V27782

In Date: 11/19/2009
Close Date: 01/13/2010

Meter Reading:

Problem?

Mount signs batt 5

Parts _____ Quantity _____

Task performed:

Installed Batt 5 signs. j

NO PARTS USED

Workorder: V28023

In Date: 12/01/2009
Close Date: 01/14/2010

Meter Reading: 69,484.40

Problem?

*

Parts _____ Quantity _____

Task performed:

Installed heat rap on exh. j

010102WRAP 2 IN WIDE 2



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V28595

In Date: 12/27/2009
Close Date: 01/14/2010

Meter Reading: 8,439.30

Problem?

NEWLY INSTALLED NADER PIN SAFETY DEVICE JAMMED REAR VEHICLE DOOR. SAFETY DEVICE IS NO LONGER IN ITS ORIGINALLY INSTALLED POSITION.R51

Parts ----- Quantity -----

Task performed:

1. Rep nader pin cover. 2. Adj rear door linkage that was hard to open door. j

NO PARTS USED

Workorder: V29059

In Date: 01/13/2010
Close Date: 02/01/2010

Meter Reading: 8,440.20

Problem?

the stretcher remains in the declined position. it will not stay in the seated position.R51

Parts ----- Quantity -----

Task performed:

Contacted Emsar for repair. j

NO PARTS USED

Workorder: V29214

In Date: 01/17/2010
Close Date: 02/17/2010

Meter Reading: 325.70

Problem?

BACK BOARD DOOR IS JAMMED. R51

Parts ----- Quantity -----

Task performed:

Rep back board compt. j

HLD39917DC23-5011 50 # HOLD-OPEN RESCUE 1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V29153

In Date: 01/14/2010
Close Date: 02/18/2010

Meter Reading: 8,462.00

Problem?

mode pin 3 lights on r51

Parts ----- Quantity -----

Task performed:

Scene lights inop; rep bad connection. j

NO PARTS USED

Workorder: V29196

In Date: 01/16/2010
Close Date: 02/18/2010

Meter Reading: 325.70

Problem?

Front a/c 10-7, was first reported on 1/8/2010. R51

Parts ----- Quantity -----

Task performed:

1. Rear air bag low; adj air bags & tested. 2. A/C was rep on 1/8/10. j

NO PARTS USED

Workorder: V28506

In Date: 12/21/2009
Close Date: 02/22/2010

Meter Reading: 70,201.70

Problem?

REPAIR AIR LEAK R51

Parts ----- Quantity -----

Task performed:

Replcd air horn solenoid. j

HDY-H005700SOLENOID HORN AIR 1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V28976

In Date: 01/11/2010
Close Date: 02/22/2010

Meter Reading: 71,053.50

Problem?

ST51-r51 ac not working

Parts

Quantity

Task performed:

Recharge A/C & chkd for leaks. j

NO PARTS USED

Workorder: V29311

In Date: 01/21/2010
Close Date: 03/19/2010

Meter Reading: 71,625.50

Problem?

R51 ac not working, spotlight out

Parts

Quantity

Task performed:

1. Recharged A/C & tested. 2. Rep roof mntd spotlight. j

NO PARTS USED

Workorder: V29790

In Date: 02/08/2010
Close Date: 03/19/2010

Meter Reading: 72,189.00

Problem?

back door pt compartment -door latch sticks and can't open it from inside to exit vehicle/ After vehicle is turned off, sounds like air leaking from rear of vehicle for a great amount of time. R51

Parts

Quantity

Task performed:

1. Air leak; traced out aiur leaks & rep. 2. Rear door not opening; readj rear door linkage. 3. Cab door hard to open; adj door hinge & latch. 4. Roof spotlight inop; rep bad connection. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V29958

In Date: 02/14/2010
Close Date: 03/19/2010

Meter Reading: 72,605.90

Problem?

One of the custom nader pin covers for the rear pt compartment doors broke off. R51

Parts ----- Quantity -----

Task performed:

R/R nader pin cover. j

NO PARTS USED

Workorder: V30054

In Date: 02/18/2010
Close Date: 03/19/2010

Meter Reading: 72,605.90

Problem?

air leak coming from under dash, under yellow air brake handle r51

Parts ----- Quantity -----

Task performed:

Chk for air leak; fnd no air leaks. j

NO PARTS USED

Workorder: V30235

In Date: 02/25/2010
Close Date: 03/26/2010

Meter Reading: 73,229.50

Problem?

The safety covers for the rear nader pins in R51 are binding up the door mechanism, and then breaking off.

Parts ----- Quantity -----

Task performed:

installed new pin cvrs. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V31547

In Date: 04/15/2010
Close Date: 04/26/2010

Meter Reading: 74,917.20

Problem?

B INSPECTION AND REPAIRS AS NEEDED R51

Task performed:

B-Inspection 2. Fault code ons screen node 3 pic "C" was for A/C fans under truck; (1) fan was shorted out; replc both fans; sys ok. 3. Replc wiper blades. 4. Svc trans. 5. Svc air dryer. 6. Replc frnt shocks. 7. Replc frnt brakes & brake hardware; replc frnt drums. 8. Replc rear brakes/brake drums; replc brake hardware. 9. Replc A/C filters in cab/pat compt. 10. Replc plexi-glass drop down door in pat compt; drill new holes/mnt hardware. 11. Replc (3) pat compt lite bulbs. 12. Replc L/side rear top LED marker lite. 13. Rep O2 connection for "M" style bottle in L-1 compt.

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	24
29526898 29548988 TRANS FILTER ALLISON	1
322502BULB PATIENT GH22	3
3744BRAKE DRUM REAR	2
3753BRAKE DRUM RUMPER FRONT	2
52-24WIPER BLADES ANCO 24	2
60027FAN A/C COND 12IN 860026-2-W	2
6803230300 65482 SHOCK FRONT ENGINE	2
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
921LIGHT BULB	3
CLR9185109186-1500-10 MARKER LT. RED LED	1
DOOR5-1USE WIDE SLOTE LEXAN 9X38 NARROW S	1
KSMA2124703QFRONTBRAKE KIT RUMPER AND 4D	2
KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2
R90PFILTER FUEL 33231	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V30234

In Date: 02/25/2010
Close Date: 05/01/2010

Meter Reading: 73,229.50

Problem?

The red led light bezel/covers from the lights on the grille for R51 are broke and falling off. Can we replace them?

Parts _____ Quantity _____

Task performed:

Replc (2) LED lens on grill. j

NO PARTS USED

Workorder: V31245

In Date: 04/02/2010
Close Date: 05/01/2010

Meter Reading: 74,467.00

Problem?

check engine light came on 2x today.R51

Parts _____ Quantity _____

Task performed:

Chkd for codes; fnd no codes; fnd low on coolant; top off coolant. j

NO PARTS USED

Workorder: V31247

In Date: 04/02/2010
Close Date: 05/01/2010

Meter Reading: 74,467.00

Problem?

RED covers for emergency lights on the grille are broken and missing.R51

Parts _____ Quantity _____

Task performed:

Installed (2) new red lens on frnt of truck j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V31535

In Date: 04/14/2010
Close Date: 05/01/2010

Meter Reading: 74,917.20

Problem?

The window crank on the front right door is broken completely off. Cannot roll the window down. r51

Parts ----- Quantity -----

Task performed:

1. Replc window crank. 2. Air leaks? fnd none. j

Parts	Quantity
A1818557002HANDLE-WINDOW	1

Workorder: V31593

In Date: 04/16/2010
Close Date: 05/11/2010

Meter Reading: 74,917.20

Problem?

replace tires r51 boulevard

Parts ----- Quantity -----

Task performed:

Replace tires R51 - Boulevard j

Parts	Quantity
NO PARTS USED	

Vendor? BOULEVARD TIRE

Workorder: V31924

In Date: 05/03/2010
Close Date: 06/04/2010

Meter Reading: 76,005.00

Problem?

fix back door of r51 patient compartment

Parts ----- Quantity -----

Task performed:

Adj rear door linkage, so door wld open. j

Parts	Quantity
657843STRIKER EGS-FM-E500-106-ZN MT EONE	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V33098

In Date: 06/24/2010
Close Date: 06/29/2010

Meter Reading: 70,201.70

Problem?

air leak R51 (on-call)

Parts

Quantity

Task performed:

Rem air sender frm dash & replcd. j

NO PARTS USED

Workorder: V32680

In Date: 06/06/2010
Close Date: 07/20/2010

Meter Reading: 77,593.00

Problem?

onboard O2 gauge- not registering correct O2 supply. Bottle empty and registering 1200 r51

Parts

Quantity

Task performed:

Tested sys & tested ok. j

NO PARTS USED

Workorder: V33008

In Date: 06/19/2010
Close Date: 07/20/2010

Meter Reading: 77,923.00

Problem?

The shore line recepticle on R51 appears to not be working. There is no "charging" indicator light, and no a/c in the "box" of the rescue when it is plugged in. R51

Parts

Quantity

Task performed:

Reset breaker in rear. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V33526

In Date: 07/13/2010
Close Date: 07/22/2010

Meter Reading: 78,987.00

Problem?

The turn signals on the dash board light up intermittently. When this happens the exterior turn signals fail to work. If the dash lights are off the exterior lights work. R51

Task performed:

1. C/O - fnd it to work ok at this time; driver saidcheck eng light was coming on; fnd coolant low; fill up & bad radiator cap; ok at this time; chk next day. Rechk chk eng, oil press cut high; (1) count clear code; call Ed, he knows. j

Parts	Quantity
05-17223-000CAP RADIATOR 10 LB	1
EL12FLASHER ELECTRONIC	1

Workorder: V33527

In Date: 07/13/2010
Close Date: 07/22/2010

Meter Reading: 78,987.00

Problem?

Onboard O2 system. The guage at the bottle reads 2000psi, even with an empty bottle. R51

Task performed:

C/O gauges on larger bottle to rear right pressure. j

Parts	Quantity
MG-C23SPMGC23 GAUGE	2

Workorder: V33949

In Date: 08/02/2010
Close Date: 08/12/2010

Meter Reading: 79,243.00

Problem?

shoreline does not disconnect R51 (callout repair)

Task performed:

Auto-eject not king out shoreline; driver will disconnect frm truck; will put ir IBEM for rep; spoke to driver operator. ja

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V33659

In Date: 07/20/2010
Close Date: 08/16/2010

Meter Reading: 79,243.00

Problem?

check engine light comes on intermittently. r51

Parts

Quantity

Task performed:

Chk eng light on; connected laptop; fnd low coolant; refilled & tested. ja

NO PARTS USED

Workorder: V33660

In Date: 07/20/2010
Close Date: 08/18/2010

Meter Reading: 79,243.00

Problem?

the brake light cover panel in the pt compartment keeps falling off of the wall. r51

Parts

Quantity

Task performed:

Rep rear cvr in back of rescue. ja

NO PARTS USED

Workorder: V33766

In Date: 07/24/2010
Close Date: 08/18/2010

Meter Reading: 79,243.00

Problem?

inside cab truck leaking water onto MDT from outside, check engine light on, turn signals 10-7, check out lights don't work, lights on four corners of truck stay on constantly.R51

Parts

Quantity

Task performed:

1. Cableaking wtr; resealed roof. 2. T-signals inop; fnd bad connection under dash. 3. Rear scene lights stay on; reprogrammed node & tested. ja

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V33822

In Date: 07/27/2010
Close Date: 08/18/2010

Meter Reading: 79,243.00

Problem?

check out lights 10-7. Intermittantly they will work and then won't for a few days. Possibly related to other problems like turn signals that work and then don't. R51

Parts ----- Quantity -----

Task performed:

Lights inop in rear; fnd bad connection. ja

NO PARTS USED

Workorder: V34229

In Date: 08/12/2010
Close Date: 09/03/2010

Meter Reading: 79,243.00

Problem?

the pt compartment a/c keeps turning on and off. R51

Parts ----- Quantity -----

Task performed:

1. Travel to stn; dload program to node 3; fault still exists; A/C unable to rep in timely manner; enroute to shop swap out. Swap into SR6 - 10154105. 2. Dia A/C fault node; download program; assisted by Ed Ehrke; sys operating normal. 3. Volt fluctuates up/down .9 V; chk btry alt, chk center console distribution box volt; all good; dia shows volt drop. 4. Assist w/node reprogram - Levy. js

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V33931

In Date: 07/31/2010
Close Date: 09/08/2010

Meter Reading: 79,243.00

Problem?

shoreline does not disconnect when attempting to start rescue causing rescue not to start. R51

Parts ----- Quantity -----

Task performed:

1. installed new auto-eject plug. 2. Adj rear door latch. j

0915520120AUTO EJECT 20 AERO OTL3925	1
--------------------------------------	---

Workorder: V33972

In Date: 08/02/2010
Close Date: 09/09/2010

Meter Reading: 79,243.00

Problem?

turn signals both 10-7, check out lights 10-7

Parts ----- Quantity -----

Task performed:

1. Rep bad connection at t-signal switch. 2. Rep C/O light timer; ran new grd. j

NO PARTS USED	
---------------	--

Workorder: V33992

In Date: 08/03/2010
Close Date: 09/09/2010

Meter Reading: 79,243.00

Problem?

R51 has an error code on the digital display that reads"diagnostic error N1PB".r51

Parts ----- Quantity -----

Task performed:

1. Error code; fnd healight out; replc headlight. 2. Rep spotlight switch that was not working. j

NO PARTS USED	
---------------	--



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V34653

In Date: 09/01/2010

Meter Reading: 79,243.00

Close Date: 09/10/2010

Problem?

on call R 51 over heating

Parts

Quantity

Task performed:

R51 overheating; fnd air line to fan leaking at quick disconnect fitting; replc fitting; teste opn of fan. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V34268

In Date: 08/13/2010

Meter Reading: 79,243.00

Close Date: 09/15/2010

Problem?

C INSPECTION AND REPAIRS AS NEEDED R51

Parts

Quantity



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* ADVANCED LIFE SUPPORT VEHICLE

Task performed:

C-Inspection 2. Replcd btrys - failed load test. 3. Replc wiper blades. 4. Replc brkn stretcher mtng antlers. 5. Replc faulty btry tender LED harness 6. Replcd worn door gskts. 7. Replcd brkn door winder bezels. 8. IPC lens brkn; rem IPC & replc lens cvr. 9. Sterring column loose; fnd bolt/ajud hinge loose; tightened bolt. 10. Frnt flour bulbs cut in pat compt; replc bulbs. 11. Struts worn on inner pat comp; replc struts. 12. Nader pin cvrs bent/brkn; replc - made mmore acces for when door closes over them. 13. latch faulty on squad bench; replc latch. 14. Latch faulty on inside pat compt door. 15. Exh pipe leaking at flex pipe; R/R flex/clamps. 16. Svc air dryer. 17. Cln fuel cap - prime & repaint. 18. Truck leaning to right; adj air bag. 19. Chk eng light intermittent; fnd oil press sensor fault code; R/R oil press sensor; had to rem alt to gain acces to replc sensor. 20. Finished oil press sensor replacement; test drove; chk eng light came on; hooked laptop & took another test drive; light stayed off; t-shoot intermittent elect problem. 21. Cln pat evap coil. 22. T-shoot oil press fault; info on hand does not match sensor on veh. 23. Rem leaking exh manifold; (3) bolts brkn in head; used easyout air to rem bolts; clnd/prepped surfaces; started installing new manifold. 24. Volt reading eratic for test drive; may be cause of oil press fault & rear A/C problem; replc alt. 25. Confirmed oil press harness not faulty on right side of motor; Ed called Detroit; advisor recommended look at VIM & IPC; finished putting all compts back frm manifold/alt repair. 26. Cont'd to t-shoot oil press fault; after replcng alt, vc reading higher & more stable when test driving; oil fault not occuring any more; took multiple test drives to confirm repair; looked at VIM & wiring. j

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
0200271ANTLER BAR	1
032-0116549297 BATTERY INDICATOR	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
15W40BSYN OIL BULK QTS	24
20A-400CLAMP 4" 33969	2
2332920005SMASK LENS W/RST BUTTON VDO	2
40022STAINLESS FLEX PIPE 4"	3
4867JB320 UPGRADE ALTERNATOR	1
52-24WIPER BLADES ANCO 24	2
6806970098SEAL DOOR	1
6808300074VENT A/C LH	1
6808300174VENT A/C RH	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
9061421101EXHAUST MANIFOLD CENTER	1
9061421201EXHAUST MANIFOLD R/L	2
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
98003RREFLECTOR RED 40132 GROTE	2
A1834388002MOLD L/H	2
A1834388003MOLD R/H	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
DDE-0041534928A0071530828 OIL PRESSURE SENC	1
DDE-5411870080GASKET OIL RETURN TUBE TURBO	1
DDE/00009903150TURBO NUTS	4
DDE/0019904605TURBO STUD	2
DDE/9049900412EXHAUST BOLTS	12
DDE/9061420280USE A9261420080 EXHAUST MANIF	3



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

ESX120105112STARTER RELAY ESX-120-105112	1
HLD3999GSS1715UV 30LB STRUT GAS	2
HP-31DBATTERY 950CCA HP-31D	4
R90PFILTER FUEL 33231	1

Workorder: V34359

In Date: 08/18/2010
Close Date: 09/17/2010

Meter Reading: 79,243.00

Problem?

The cab doors on R51 only open from the inside.

Parts	Quantity

Task performed:

Readj door linkage. j

NO PARTS USED

Workorder: V35087

In Date: 09/21/2010
Close Date: 10/20/2010

Meter Reading: 81,146.00

Problem?

Light oil leak from a hose by the oil pan r51

Parts	Quantity

Task performed:

Oil leak is normal for breather tuber. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V35880

In Date: 10/25/2010
Close Date: 10/26/2010

Meter Reading: 82,280.00

Problem?

on call charging system 10-7 r51

Task performed:

1. replace altenerator 2. road call , inspect, found faulty alternator, swapped in to spare truck at station 42, 10136364. jab

Parts	Quantity
4867JB320 UPGRADE ALTERNATOR	1

Workorder: V35985

In Date: 10/28/2010
Close Date: 11/03/2010

Meter Reading: 822,622.00

Problem?

biohazard drawer flew out of tracks and now will not go back in- have had ongoing issues with this , drawer flies out in the pt compartment during operation of vehicle. R51

Task performed:

R/R slide tracks; drill out old tracks welder to box; reinstall new style - ok.]

Parts	Quantity
5632-1010 IN DRAWER SLIDES PR	2

Workorder: V35655

In Date: 10/14/2010
Close Date: 11/16/2010

Meter Reading: 82,074.00

Problem?

Engine oil leak.

Task performed:

1. removed a/c compressor and repaired air leak reinstall air compressor, ran truck and check for leaks. jab

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V35657

In Date: 10/14/2010
Close Date: 11/16/2010

Meter Reading: 82,074.00

Problem?

oil leak was supposed to have been fixed on 10-12. Its still leaking. R51

Task performed:

1. inspect truck for air leak, repaired oil leak , recheck truck for leaks. 2. inspect rear light bar, found light bar inop, repaired connection, test ok. jab

Parts

Quantity

NO PARTS USED

Workorder: V36503

In Date: 11/16/2010
Close Date: 11/30/2010

Meter Reading: 82,776.00

Problem?

turn signals/hazard lights are not working R51

Task performed:

(1) TRAVELED TO ST 51 TO REPAIR TURN SIGNAL PROMBLEM ON R51. CHECKED AND FOUND PROBLEM TO BE AT THE FIREWALL PLUG. CORROSION HAD BUILT UP. CLEANED CONTACTS AND REASSEMBLED PLUG. OK. J.W.

Parts

Quantity

EL12FLASHER ELECTRONIC 1

Workorder: V36415

In Date: 11/13/2010
Close Date: 12/03/2010

Meter Reading: 82,776.00

Problem?

replace tires r51 boulevard

Task performed:

Replc tires R51 - Boulevard j

Parts

Quantity

NO PARTS USED

Vendor? BOULEVARD TIRE



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V35386

In Date: 10/04/2010
Close Date: 12/22/2010

Meter Reading: 81,758.00

Problem?

A small amount of motor oil is leaking onto bay floor. R51

Task performed:

(1) TRAVELED TO ST 51 TO CHECK OUT OIL LEAK COMING FROM R51. CLEANED OIL OFF THE ENGINE. COULD NOT FIND A LEAK AFTER RUNNING ENGINE. J.W.

Parts

Quantity

NO PARTS USED

Workorder: V38406

In Date: 02/09/2011
Close Date: 02/18/2011

Meter Reading: 86,810.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED R51

Task performed:

1. B inspection 2. remove l/side rear cab step, replace condenser fan motor, reinstall step 3. replace pat. compt. bulb over emt seat

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
15W40BSYN OIL BULK QTS	24
322502BULB PATIENT GH22	1
R90PFILTER FUEL 33231	1
RD571290 01-2616 MOTOR 12V 73R-0542 3512	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V39193

In Date: 03/14/2011
Close Date: 03/15/2011

Meter Reading: 88,203.00

Problem?

R51 has a screw in the front right tire

Parts _____ Quantity _____

Task performed:

1. travel to sta-51 check tire found screw in r/side tire remove screw and tire started leaking, called tire co.

NO PARTS USED

Workorder: V39205

In Date: 03/15/2011
Close Date: 04/05/2011

Meter Reading: 88,203.00

Problem?

replace front tires r 51

Parts _____ Quantity _____

Task performed:

Replace frnt tires R51 - Elpex j

NO PARTS USED

Vendor? EXPEX

Workorder: V39885

In Date: 04/13/2011
Close Date: 05/13/2011

Meter Reading: 89,489.80

Problem?

CO MONITOR GOING OFF, STATES "REPLACE" R51

Parts _____ Quantity _____

Task performed:

replcd CO monitor. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V40291

In Date: 04/30/2011
Close Date: 05/13/2011

Meter Reading: 90,544.00

Problem?

Broken handle of side door leading to back compartment of rescue. R51

Parts

Quantity

Task performed:

Pat side door lock brkn; diss; fnd lock brkn; rem/install new lock; travel to shop for par. j

NO PARTS USED

Workorder: V41056

In Date: 06/02/2011
Close Date: 06/09/2011

Meter Reading: 91,983.00

Problem?

siren not working, Sta 51.

Parts

Quantity

Task performed:

Siren inop; fnd mic on PA was pushed in. j

NO PARTS USED

Workorder: V41211

In Date: 06/08/2011
Close Date: 06/13/2011

Meter Reading: 92,293.00

Problem?

AC not working R51

Parts

Quantity

Task performed:

RSI pat A/C blowing warm; fnd charge low; charged A/C & then reinstalled shore A/C cover plate on ckt. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V40958

In Date: 05/29/2011
Close Date: 06/28/2011

Meter Reading: 91,583.00

Problem?

front passenger weather stripping around window fell off and bracket that holds the scba bottle of front passenger bottom bracket screws are stripped and bracket is very loose, one side completely unattached R 51

Parts ----- Quantity -----

NO PARTS USED

Task performed:

Reinstalled weather striping on window ak

Workorder: V41403

In Date: 06/17/2011
Close Date: 07/11/2011

Meter Reading: 92,583.00

Problem?

onboard O2 system has leak, Sta 51.

Parts ----- Quantity -----

NO PARTS USED

Task performed:

1. Chkd/rep O2 leak. 2. Rep stretcher latch & tested. j

Workorder: V41756

In Date: 07/02/2011
Close Date: 07/13/2011

Meter Reading: 93,121.30

Problem?

All 4 rear tires on r51 need to be replaced per mechanic (tommy) Size 265/70 R19.5 bridgestone R51

Parts ----- Quantity -----

NO PARTS USED

Task performed:

Replc all (4) rear tires R51 - Boulevard j

Vendor? BOULEVARD



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V41541

In Date: 06/22/2011
Close Date: 07/14/2011

Meter Reading: 92,741.00

Problem?

interior check out lights for pt compartment 10-7 R51

Parts

Quantity

Task performed:

A/C inop. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V41918

In Date: 07/11/2011

Meter Reading: 93,745.00

Close Date: 07/25/2011

Problem?

C INSPECTION AND REPAIRS AS NEEDED R51

Parts

Quantity



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* ADVANCED LIFE SUPPORT VEHICLE

Task performed:

C-Inspection 2. Adj tire air press; chk LRI tire for leak - ok. 3. Dryer svc. 4. Install msgng O2 bottle brkt belts. 5. Secure L/rear seat belt to hand rail fastner. 6. Rep LR tool brkt thrads. 7. Secure frt pass trim piece. 8. Paint fuel cap. 9. Dia no city horns; fnd both horns bad; replc horns. 10. Install (6) msgng lugnut covers. 11. Secure L/rear & drivers door upper trim. 12. Svc btrys. 13. Dia low coolant; fnd leak at various hose clamps; tightened clamps; fill reservoir & retest - ok. 14. Rem seat for upholstery. 15. replc wiper blades. 16. Top off washer fluid. 17. Rem jump seat for upholstery. 18. Svc P/S. 19. Adj brakes. 20. Dia air leaks; fnd right air bag; fitting at dryer; chk valve & tank valves. 21. Secure/protect condensor fan wires. 22. Chk ABS eng & trans codes; fnd overtemp coolant code; erased inactive code. 23.Replc rear air bags; replc right air bag air line to tank; rem fitting at dryer; chk valve & seal threads; replc air bag tank drain valve/cable; fill sys & chk for leaks - ok. 24. Replc pat compt A/C filter. 25. Replc R/center clearance light. 26. replc R/rear clearance light asy. 27. Replc rear pat compt striker cvr; drill holes to fit. 28. Dia/rep wires for R/rear door light. 29. Rem pass SCBA brkt & replc stripped & msgng bolts. 30. Tighten all door panel screws; drill/tap new thrds in side pat compt doc panel; lube slide doors in pat compt. 31. Replc drawer tracks in pat compt area; adj to fit. 32. Install piece of weatherstrip on bottom of drivers door. 33. Recrimp O2 wrench to cable. 34. Rem instrument cluster & replc burnt out bulbs & aligned name labels; install msgng screw. 35. Adj striker on rea door. 36. Replcd R/cab strobe lens; installed larger screw to secure frt. 37 Dia air leak; fnd fittings at gauges leaking; replc fittings; rem dash & console cvr; replc parking brk valve. 38. Dia intermittant alarm going off or acceleration; fnd intermittant park brake switch & both park brake indicato bulbs out; replcd indicator on overhead dash & rem cluster; replc bulb inside cluster; test drive ok. 39. Tighten drivers convex mirror. 40. Replc protection valve on secondary tank; test for leaks - ok; still very slow leak on secondary side; cld not locate; talked to Mike Lehan - ok. 41. Install L/rear seat. 42. Install jump seat. 43. Test drive veh for overtemp - ok; chk computer for overtemp code returning - ok. 44. Quality inspection. j also see wo 41540

000090155133634 FUEL FILTER WIX MERCEDES	1
00009247080000925208 FILTER HEAD CAP NEW NU	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
103385NDRAIN COCK	2
107796DRYER KIT AD9 -NEW	1
1501450007750USE 0775145	1
16-15762-00016-19471-000 AIR BAG	2
223-455VUSE 223-485V VALVE CHECK -PRESSURE	1
23-11345-714INSTRUMENT CLUSTER SCREWS 1 1/	1
52-24WIPER BLADES ANCO 24	2
6819634283068-1963428-30 LENS CLR	1
800034VALVE PARKING BRK.	1
800405PURGE VALVE KIT	1
8126482-2106 TOGGLE GUARD	1
A0631117000HORN HIGH NEW # 06-52125-039	1
A0631117003HORN LOW NEW #06-52125-041	1
ACX-84534LUG NUT COVER PK10	6
CA8193AIR FILTER 46744 WIX	1
CLR9185109186-1500-10 MARKER LT. RED LED	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FSC17492134NC SW PARK BK SPADE TYPE CONNE	1
HA141LIGHT RED WARNING	1
LF18TS-LEDMAP LIGHT LED 18 IN	1
R90PFILTER FUEL 33231	1
SLD5366HT4932-16 DRAWER SLIDE 16	2



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V42314

In Date: 07/26/2011

Meter Reading: 93,635.00

Close Date: 08/01/2011

Problem?

A/C inop.

Task performed:

DIAGNOSE AC INOP FOUND LOCKED UP COMPRESSOR. REOVER REON REMOVE BELTS AND COMPRESSOR WITH BRACKET. CUT OF HEAD OF BOLT TO REMOVE BRACKET. MEASURED IT IN OLD COMPRESSOR AND ADD CORRECT AMOUNT TO NEW COMPRESSC INSTALL AIR COMPRESSOR MAKE UP 4 SPACERS FOR COMPRESSOR MOUNTING TO ALIGN PULLING REPLACED HIGH PRESSURE SWITCH WIRE SWITCH AND COMPRESSOR CRIMP AND HEAT SHRINK WIRING PROTECT WIRES WITH LOOM CUT AND SPLICE HIGH PRESSUR E DISCHARGE LINE REPLACED FITTINGS REMOVED EVAPORATOR DIFFUSER AND REMOVED RECIEVER DRYER INSTALL NEW WASHERS AND BOLTS FOR BRACKETS INSATLL DRYER AND EVAP DIFFUSER EVACUATE SYSTEM AND CHARGE LEAK TEST -- WIRE AND HOSES WITH LOOM AND SECURE AK

Parts

Quantity

0127110042BELT MERCEDES MOTORS	1
071601A07-0602A DRIER A/C 7118	1
16-31455533 CAP LOW SIDE BLUE	1
387901HOSE & FITTING	1
4507SFITTING AC SB1312-3	1
532703-0602 COMPRESSOR U4735 4471	1
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
A22309300011490 A/C SWITCH	1

Workorder: V39934

In Date: 04/14/2011

Meter Reading: 89,842.00

Close Date: 08/02/2011

Problem?

MDC not working. Sta.51. gave to radio shop.

Task performed:

turned over to radio shop nothing in files

Parts

Quantity

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V42387

In Date: 07/29/2011
Close Date: 08/03/2011

Meter Reading: 94,021.90

Problem?

check rear a/c.

Parts

Quantity

Task performed:

Chk rear A/C; fnd compressor turning off when at high RPM frm hi-press switch when press reaches 260 PSI; cln condensor & rechk ok. j

NO PARTS USED

Workorder: V42433

In Date: 08/01/2011
Close Date: 08/30/2011

Meter Reading: 94,021.90

Problem?

Door buzzer is working. Does not alert you to door being opened. Sta 51.

Parts

Quantity

Task performed:

Reconnected wires. j

NO PARTS USED

Workorder: V42235

In Date: 07/22/2011
Close Date: 09/06/2011

Meter Reading: 93,635.00

Problem?

A/c compressor froze and belt broke. already swapped into spare and truck is at station 51

Parts

Quantity

Task performed:

LEAK AT PUMP PANEL FITTING AT METERING BLOCK REPAIRED
LEAK AT PUMP PANEL AK

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V42616

In Date: 08/07/2011
Close Date: 09/12/2011

Meter Reading: 94,299.90

Problem?

dash board light turn signal on left does not illuminate on dash board only.
Turn signal does appear on the exterior. R 51

Parts _____ Quantity _____

Task performed:

repaired turn signal and tested

NO PARTS USED

Workorder: V43692

In Date: 09/15/2011
Close Date: 10/03/2011

Meter Reading: 95,961.90

Problem?

onboard regulator reads 1000 PSI all the time. R 51

Parts _____ Quantity _____

Task performed:

repaired l2 gauge and tsted for leaks

NO PARTS USED

Workorder: V44318

In Date: 10/11/2011
Close Date: 10/12/2011

Meter Reading: 96,826.00

Problem?

Patient and passenger cab compartment a/c not running cool air R 51

Parts _____ Quantity _____

Task performed:

Front/rear A/C low on freon; charge pat compt A/C; cld not find leak;
charge cab A/C; unit needs to go to shop for proper repair & find leak. j

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V44029

In Date: 09/29/2011

Meter Reading: 96,974.00

Close Date: 10/17/2011

Problem?

Coolant leak.

Parts

Quantity

Task performed:

replace radiator X 3 days travel to make for fittings

393573HOSE AND FITTING ASSY

1

BHT-B0184USE F10 RADIATOR

1

Workorder: V41540

In Date: 06/22/2011

Meter Reading: 92,741.00

Close Date: 11/02/2011

Problem?

patient compartment and front interior cab a/c running warm R 51

Parts

Quantity

Task performed:

see wo 41918 c inspection

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V44356

In Date: 10/13/2011

Meter Reading: 97,013.00

Close Date: 11/03/2011

Problem?

B INSPECTION R 51

Task performed:

B-Inspection 2. Assist with B-Svc 3. Replc wipers - worn; top off washer fluid. 4. Frnt A/C ompt discharge fitting leaking. 5. Diff over full; adj diff lever. 6. Exh leak; (1) study brkn, also loose. 7. Clamp after tur bo; rep ext leak, replc studs & exh manhold gskts. 8. Turbo boost outlet clmp bolt stripped; rem bent stripped bolt; realigned outlet for boost pipe. 9. Air horn mnts loose; tightened mnts. 10. (2) pat compt dome lights inop; installed new bulbs. 11. L/F tire worn; replc with good used tire & road tested. 12. seat belts sticking; cldn seat belts. 13. Slow starting - losing fuel primer; replc fule pump. 14. Secondary air leaks down - leveling valves; t-shoot ai leak; replc leveling valves. 15. Drivers door handle loose; wedge fell out; replc door. j

Parts

Quantity

0000900087DDE/A0000900087 FILTER HEAD SM MEI	1
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
0127110042BELT MERCEDES MOTORS	1
322502BULB PATIENT GH22	2
52-24WIPER BLADES ANCO 24	2
6808300074VENT A/C LH	2
716907-0610A DRYER	1
9060910580FUEL PUMP GASKET M2	1
9061420057SEAL RING EXHAUST MANIFOLD	2
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
DDE-R0040910501FUEL PUMP M2	1
DDE/00009903150TURBO NUTS	4
DDE/9049900412EXHAUST BOLTS	12
DDE/9061420280USE A9261420080 EXHAUST MANIF	3
DDE/9062002470BELT TENSIONER MERCEDES	1
N000000001070SEAL RING BANJO	4
R90PFILTER FUEL 33231	1
S448GAUGE TIRE TREAD DEPTH	1
S4640024430VALVE LEVELIN	2



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V45800

In Date: 12/12/2011
Close Date: 01/03/2012

Meter Reading:

Problem?

The slind out for the sharps box came out and unable to get slide out back in. The bearings on the guides are stuck and the slide out would only open about 4 inches R 51

Parts ----- Quantity -----

Task performed:

replaced all slides in med drawer repaired rear door lock that would not lock

5632-1010 IN DRAWER SLIDES PR	2
-------------------------------	---

Workorder: V46419

In Date: 01/09/2012
Close Date: 01/10/2012

Meter Reading: 101,463.00

Problem?

headlight out.

Parts ----- Quantity -----

Task performed:

CHECK AND REPLACE L/F HEAD LIGHT. CHECK HARNESS CLEAN AND APPLY GREASE TO FIRE WALL PLUG. H6054 H/C

H6054USE CV TYPE SEALED BEAM	1
------------------------------	---

Workorder: V45918

In Date: 12/17/2011
Close Date: 01/13/2012

Meter Reading: 99,846.70

Problem?

medication drawer unable to lock. handle broken off, Sta 51

Parts ----- Quantity -----

Task performed:

INSTALLED NEW LOCK FOR DRAWER.

NO PARTS USED	
---------------	--



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V46459

In Date: 01/10/2012
Close Date: 01/13/2012

Meter Reading: 101,463.00

Problem?

REPAIR CHARGE COOLER HOSE R51

Parts	Quantity
NO PARTS USED	

Task performed:

1. REPAIRED CHARGE COOLER HOSE THAT FELL OFF. 2. A/C INOP RECHARGED AND REPAIRED LEAK.

Workorder: V46604

In Date: 01/16/2012
Close Date: 01/30/2012

Meter Reading: 101,812.50

Problem?

R51 needs front and rear tires. Sta 51

Parts	Quantity
NO PARTS USED	

Task performed:

R51 NEEDS FRONT AND REAR TIRES. STA 51. REPLACE ALL SIX TIRES. BP

Vendor? BOULEVARD TIRE CENTE

Workorder: V46977

In Date: 01/31/2012
Close Date: 02/03/2012

Meter Reading: 102,653.00

Problem?

electrical problem with front end of vehicle. Both headlights/10-7 brights/10-7 and hazzard lights 10-7, Sta 51

Parts	Quantity
15W40QSYN OIL QT	12
SLD5366HT4932-16 DRAWER SLIDE 16	2

Task performed:

1. HEADLIGHTS INOP. 2. MED DRAWER SLIDES BROKEN. 3. DOOR OPEN ALARM INOP. 4. REAR FLASHERS NOT SHUTTING OFF.



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V47122

In Date: 02/06/2012
Close Date: 02/10/2012

Meter Reading: 102,998.00

Problem?

rattle in engine compartment (constant) driver's window handle 10-7, Sta 5'

Parts _____ Quantity _____

Task performed:

SENT TO SHOP TO HAVE WELDED.

NO PARTS USED

Workorder: V47199

In Date: 02/09/2012
Close Date: 02/10/2012

Meter Reading: 103,105.00

Problem?

Repair a/c bracket

Parts _____ Quantity _____

Task performed:

REMOVE BRACKET FROM VEHICLE - FOUND ONE BOLT MISSING AND ONE BROKEN OFF IN CYLINDER HEAD. MAKE UP A SPECIAL BOLT TO REPLACE MISSING ONE - REINSTALL BRACKET USING ONLY THE ONE BOLT - COMPLETE REPAIR NEEDED WHEN VEHICLE COMES IN FOR SERVICE.

NO PARTS USED

Workorder: V46278

In Date: 01/04/2012
Close Date: 02/13/2012

Meter Reading: 100,892.00

Problem?

Driver on R51 # 10156658 Headlight is out no replacement light ST51

Parts _____ Quantity _____

Task performed:

REPLACED HEADLIGHT AND REPAIRED BAD GROUND

H6054USE CV TYPE SEALED BEAM 4



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V47281

In Date: 02/13/2012
Close Date: 02/14/2012

Meter Reading: 103,482.30

Problem?

REAR TIRE FLAT R 51

Parts ----- Quantity -----

Task performed:
REAR TIRE FLAT R 51.

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE

Workorder: V47264

In Date: 02/13/2012
Close Date: 02/27/2012

Meter Reading: 103,482.30

Problem?

ON CALL R 51 CHARGE COOLER HOSE OFF

Parts ----- Quantity -----

Task performed:
INSTALLED NEW CLAMP AND ROAD TESTED.

NO PARTS USED

Workorder: V47310

In Date: 02/14/2012
Close Date: 02/28/2012

Meter Reading: 103,501.00

Problem?

Cab A/C out again. Blowing warm. Last time needed freon. Sta 51

Parts ----- Quantity -----

Task performed:
1. REPAIRED DOOR LATCH THAT WAS HARD TO CLOSE. 2.
REPLACED A/C SWITCH IN CAB AND TESTED.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V47378

In Date: 02/16/2012

Meter Reading: 103,560.50

Close Date: 02/28/2012

Problem?

The AC in the cab of R51 is not working. Sta 51

Parts

Quantity

Task performed:

TRACED OUT PROBLEM FOUND CAB BLOWER MOTOR N/G,
REPLACED AND TESTED.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V47506

In Date: 02/22/2012

Close Date: 03/20/2012

Meter Reading: 103,897.20

Problem?

C INSPECTION R 51

Parts

Quantity



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Task performed:

1. C inspection 2. Dash board left turn signal lite ino, remove dash and replace bulb, reinstall dash 3. both cab a/c's inop, written up mutiple times replace blower motor,check for leak aks in hoses and bulk head connecto at red dot system, remove and replace hoses and bulk head connector replace drier and binary switch, remove bad connectors for a/c fans and replace with heat shrink connectors. replace drier and o rings on freightliner system, evecaute system kept gauges hooked up over night t check for leak in cab a/c system held vac. overnight, recharge system. both cab front and rear a/c systems blowing 29 deg. 4. check for air leak, rear tank leaks down overnight, use soap and water to check, found humpries valve in dash leaking. replace valve, recheck for leaks held air ir system overnight. 5. r/side headlight aming upwards, adjust headlights. 6. a/c and heat controls on dash inop, remove a/c dash control unit and replace with new control, adjust all cables for control 7. replace worn wipe blades 8. windshield washer inop, clean out lines 9. d/door top molding broken, replace door molding and secure door panel that was falling off. 10. d/door entry lite inop, found wires broken on A post repair broken wiring 11. replace missing red dot a/c control knobs on unit in cab 12. replace cab a/c filter 13. replace pat. compt. a/c filter 14. l/side rear cab door top molding broken, replace top molding and secure door panel that was falling off 15. r/side cab door molding on top broken, replace molding and secure door panel falling off, 16. r/side air horn falling off of hood, reattach air horn to hood 17. L-4 inner door will not close properly, replace bent spring door hold open 18. med compt door struts will not hold up the door, replace struts 19. plexi glass door above bench seat cracked, remove frame and remove plexi glass and install new glass and reinstall ti frame 20. 110v a/c cover assy in pat comt. (dueo-therm) cracked, falling down and missing vents replace cover assy. this was a DNI part from the parts dept. 21. service air drier 22. degrease engine compt., dirty 23. r/side rear entry door stricker cover broken, and 1 hole was stripped, replace cover and use rivits to install 24. cab to pat. compt. bellow torn, remove trim and install new bellow, seal new bellow and replace trim 25. paint fuel cap, color faded 26. driver seat torn remove and send out for repair, install repaired seat 27. driver side round convex mirror broken, replace mirror 28. load test battery's all 4 were bad, replace all 4 battery's, battery tray very hard to open, clean tracks and lube 29. service rear axel

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
08-6962BFITTING A/C USE SB1322	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1501450007750USE 0775145	1
1512BINARY SWITCH 22-36474	1
15W40BSYN OIL BULK QTS	28
22-43249-0001513 SW PRES.A/C	1
403185HOSE & FITTING ASSY	1
4410S 08-6961B FITTING	1
4923090025DASH BULB VDO	4
52-24WIPER BLADES ANCO 24	2
716907-0610A DRYER	1
71R406018-2664 KNOB	2
75W90GEAR OIL SYN QT	18
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
980-412173 MIRROR 8 IN	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	1
ABPN83322930CONTROL HEAD AC/HEAT	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
DOORPOLY WINDOW/DOOR	1
DOOR2LEXAN 14.5 X 8.5	1
GASK-BEL0110002439 WINDOW BELLOWS 6 IN WID	12
GRO716SGRO716S MIRROR S/S	1
HLD374211 IN HOLD-OPEN 30LB	1
HLD39917DC23-5011 50 # HOLD-OPEN RESCUE	1
HLD3999GSS1715UV 30LB STRUT GAS	2



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* ADVANCED LIFE SUPPORT VEHICLE

30. middle amber marker lite on cab roof inop, replace bulb 31. r/side wes coast mirror damaged, replace mirror 32. top med draw in pat compt. falling out of tracks, remove draw replace l/side track and adjust draw

HP-31DBATTERY 950CCA HP-31D	4
R90PFILTER FUEL 33231	1
RD-4-3804-0BRACKET ASSY RED DOT	1
RD-5-7063-OP07-2618A A/C DRIER 7155	1
SU68088VALVE DUMP 310 HUMPHREY	1

Workorder: V48750

In Date: 04/18/2012 Meter Reading:

Close Date: 04/24/2012

Problem?

TURN SIGNAL NOT WORKING R 51

Parts ----- Quantity

Task performed:

work repaired on w/o#48797

NO PARTS USED

Workorder: V48797

In Date: 04/21/2012 Meter Reading:

Close Date: 04/24/2012

Problem?

No turn signals or 4 way hazards R41

Parts ----- Quantity

Task performed:

work completed on w/o#48800

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V48800

In Date: 04/21/2012
Close Date: 04/24/2012

Meter Reading:

Problem?

Front drivers side headlight not working. Put new light in and still not working.R51

Parts

Quantity

NO PARTS USED

Task performed:

1. travel to sta-51 2. check out no driver side headlight and no turn signals also found turn signals indicator lites on dash lite up, written up mutilpe times, trace out wiring harness, check bulk head connector on fire wall, ok, found ground wires on ground stud along side of bulkhead conn. on fire wall loose, wiggle wires and headlight comes on tighten nut,

Workorder: V48515

In Date: 04/08/2012
Close Date: 05/09/2012

Meter Reading: 105,423.00

Problem?

hazard and directional blinkers do ot work switch does not feel right

Parts

Quantity

6808200020LIGHT ASSY. TURN SIGNAL

1

Task performed:

FOUND SHORT AND REPLACED MARKER LIGHT.

Workorder: V49568

In Date: 05/22/2012
Close Date: 05/31/2012

Meter Reading: 107,572.20

Problem?

engine coolant leak. mechanic was notified r51

Parts

Quantity

A9062030102A9062037102 COOLANT LINE

1

A9062030702A9062037302 COMPRESSOR LINE

1

ALA00350-50 EXTENDED LIFE COOLANT GAL

4

Task performed:

REPAIRED COOLANT LEAK - REPLACED ENGINE COOLING TUBE TC AIR COMPRESSURE.



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V49757

In Date: 05/31/2012
Close Date: 05/31/2012

Meter Reading:

Problem?

AC in patient compartment not blowing cold air.

Parts

Quantity

NO PARTS USED

Task performed:

1. check pat. a/c, complaint came from A shift the day before, run a/c for 45min. check fans, check low and high pressure switches, no problem found,cools at 43deg.

Workorder: V50395

In Date: 06/26/2012
Close Date: 06/28/2012

Meter Reading: 109,089.00

Problem?

Read AC out again! r51

Parts

Quantity

NO PARTS USED

Task performed:

1. PULL DOWN SYSTEM, CHARGE AND CHECK FOR LEAKS. FOUND HIGH SIDE HOSE LEAKING AT FITTING FOR SWITCH, REMOVE HOSE AND RECRIMP FITTING. 2. FINISH RECHARGE SYSTEM.

Workorder: V50245

In Date: 06/19/2012
Close Date: 07/09/2012

Meter Reading:

Problem?

REAR A/C IS 10-7 BLOWING ONLY WARM AIR

Parts

Quantity

NO PARTS USED

Task performed:

1. check rear a/c found low on freon, fill system and check for leaks, found crimp on high side compressor hose with high side switch leaking, order new crimp will install when part comes in



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V50612

In Date: 07/05/2012
Close Date: 07/10/2012

Meter Reading:

Problem?

AC not blowing cold in back of truck. R-51

Task performed:

1. check a/c for pat. compt. found system low, evacuate and charge a/c, check for leaks found high side pressure hose crimp with switch on it leaking, this was sent to c/shop for new crimp to be installed but not done. get with Ed woodland and order new splice crimp (had to be made up because of switch) 2. recieved new splice w/switch port, evacuate system remove high side hose from compressor and cut out old splice, remove 45 deg fitting on compressor side, install new splice, switch, hose, and 45deg fitting. vacuum system down, recharge, and check for leaks. no leaks found

Parts	Quantity
1468NO 300/210 1/4FF SWITCH	1
4507SFITTING AC SB1312-3	1
BL6102-1NO 8 SPLICE WITH 1/4FF	1

Workorder: V50659

In Date: 07/07/2012
Close Date: 07/10/2012

Meter Reading: 109,725.00

Problem?

patient compartment A.C. Is not working. It is actually blowing hot air. Patient asked us to turn the heat off. Please repair. R51

Task performed:

PATIENT COMPARTMENT A/C INOP/LOW REFRIGERANT/CHARGED UNIT TESTED OK.

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V50926

In Date: 07/17/2012
Close Date: 07/17/2012

Meter Reading:

Problem?

A/C blow hot in Pt compartment R-51

Task performed:

1. check rear pat. a/c, low on freon, evacaute system will not hold vacumn add freon check for leaks with electronic leak detector and did not find any leaks, ordered a/c leak detector dye. when it comes in i will add to system and recheck for leaks.

Parts

Quantity

NO PARTS USED

Workorder: V51123

In Date: 07/25/2012
Close Date: 07/30/2012

Meter Reading:

Problem?

Rear ac blowing warm. r 51

Task performed:

1. check pat. compt a/c, add dye to system found a/c compressor leaking, remove a/c belt, remove air filter housing , remover turbo pipe and hose, remove ari intake pipe and hose remove a/c compressor, check new comp. for correct amount of oil, ok. install new compressor, reinstall all the above, evacaute system holds vacumn now, recharge system. low side gauge high, high side normal, pat. compt a/c cool's only to 57deg. bad expansion valve. 2. evacaute system, remove pat. compartment a/c unit, replace drier, found expansion valve fitting's rusted and 1 fitting cross threaded on valve, remove fitting's and cut 1 90deg fitting off of hose and rerimp new fitting on to hose, replace expansion valve, and all O rings, reinstall unit, evacaute and recharge system, gauge reading's are now normal and a/c unit cool's down to 32deg.

Parts

Quantity

071601A07-0602A DRIER A/C 7118	1
160012-2012A EXPANSION VALVE 71R8301	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V51445

In Date: 08/07/2012
Close Date: 08/14/2012

Meter Reading: 111,333.00

Problem?

B INSPECTION OIL CHANGE SERVICES

Parts

Quantity

Task performed:

B INSPECTION OIL CHANGE SERVICES

NO PARTS USED

Vendor? OIL CHANGE SERVICES

Workorder: V51285

In Date: 08/01/2012
Close Date: 09/13/2012

Meter Reading:

Problem?

A/C in pt compartment seems to not be blowing as cold as normal.

Parts

Quantity

Task performed:

1. RAN SYSTEM AND TESTED OK.

NO PARTS USED

Workorder: V52836

In Date: 10/03/2012
Close Date: 10/26/2012

Meter Reading: 113,997.80

Problem?

need bracket for 3 gallon sharps container R51

Parts

Quantity

Task performed:

INSTALLED NEW BRACKET.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V53052

In Date: 10/12/2012
Close Date: 10/26/2012

Meter Reading: 114,385.00

Problem?

driver side headlight not working. We replaced recently. Believe possible loose wiring. No extra headlights at station to test it out. r51 getting ALS inspection on Monday need repaired before, please. Thanks R51

Parts ----- Quantity -----

Task performed:

1. REPAIRED SHORT IN WIRE FOR HEAD LIGHT. 2. REPAIRED CAB A/C THAT WAS BLOWING WARM.

NO PARTS USED

Workorder: V54278

In Date: 12/06/2012
Close Date: 12/07/2012

Meter Reading:

Problem?

passenger side ligt switch on door frame is broken. R51

Parts ----- Quantity -----

Task performed:

REPORTED TO RADIO SHOP FOR REPAIR WORK REQUEST 469.

15W40QSYN OIL QT	12
516TIRE INFLATOR	1
S448GAUGE TIRE TREAD DEPTH	1

Workorder: V54452

In Date: 12/15/2012
Close Date: 12/17/2012

Meter Reading:

Problem?

vehicle leaking fluid slowly all day. possible radiator fluid. R51

Parts ----- Quantity -----

Task performed:

TRAVEL TO ST 51 PRESSURE TEST COOLING SYSTEM LOOK LIKE FREEZE PLUGS LEAKING, TRAVEL TO 42 SWAP OUT UNIT.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V54110

In Date: 11/30/2012

Meter Reading:

Close Date: 01/03/2013

Problem?

door switch for overhead lights on door frame of front passenger side. R51

Parts

Quantity

Task performed:

REMOVED AND REPLACED SWITCH.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V54472

In Date: 12/17/2012

Close Date: 01/25/2013

Meter Reading: 117,510.00

Problem?

C inspection R51

Parts

Quantity



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Task performed:

1. C-INSPECTION. AIR ALL TIRES TO PROPER PSI. 2. REPLACED BATTERIES, CLEAN CABLES AND TERMINALS. REPLACED WIRE TERMINAL END AND PROTECT WITH LOOM. TIE STRAP LOOM. 3. C-INSPECTION. 4. C-INSPECTION. REPLACED AUX A/C FILTER, TIGHTEN LEAKING COOLANT HOSE CLAMPS. REPLACED AIR FILTE CLEAN REAR A/C FILTER. 5. WINDSHIELF WIPE BLADE, FLUID AND SPRAY NOZZLE SERVICE. 6. DOOR LIGHTS - DRIVER DOOR LIGHT, RIGHT REAR CAB DOOR LIGHT, PATIENT COMP FLORENCENT LIGH BULBS, PATIENT COMP DOME LIGHTS. 7. LIGHTS R/FENDER LIGHT, MOD L/SIDE MARKER LIGHT, CENTER ROOF MARKER LIGHT. 8. TRAFFIC ADVISER INOP ON HI SIDE - REMOVE CENTER CONSOLE COVER, REMOVE TRAFFIC ADVISER, INSTALL DNI ADVISER MODULE - OPERATE UNIT. 9. ENGINE COMP SUPPORT STRAP (HOOD) BROKEN - REMOVE AND INSTALL REPLACEMENT STRAP. 10. OFFICER AND DRIVER SEAT BELTS DAMAGE. REMOVE AND INSTAL NEW SEAT BELTS. 11. REAR BRAKES. SERVICE - DRIVER, SHOES AND HARDWARE. INSPECT AND INSTALL NEW PARTS. ADJUST SLACK ADJUSTER ROAD TEST ADJUST SLACK ADJUSTER TRAVEL. 12. LEFT AND RIGHT DOOR WEATHERSTRIP, LEFT AND RIGHT WINDOW MOLDING INSTALL NEW DOOR WEATHER STRIP AND WINDOW MOLDING. 13. POWER STEERING FLUID AND FILTER SERVICE. 14. RIGHT OFFICERS DOOR HARD TO OPEN - FOUND LOCKING SUPPORT MOUNT PIN LOOSE. SECURE MOUNTING PIN A LUBRICATE LOCK. 15. FUEL CAP NEED PAINTING - CLEAN, PRIME AND PAINT FUEL CAP. 16. REMOUNT STRETCHER ANTLERS. FOUNI LOOSE ON FLOOR. 17. PATIENT COMP - CABINET SLIDING GLASS DOORS HARD TO MOVE. CLEAN CHANNELS OF DUST AND DIRT, SPRAY SILECONE ON SLIDERS AND OPERATE. 18. EXCESIVE AIR PRESSURE BUILD UP AIR GOVERNOR ADJUSTMENT TAB BROKEN. REMOVE GOVERNOR AND INSTALL NEW GOVERNOR, PSI BUILDS T APPROX 138 PSI. 19. DIAGNOSING OIL LEAK AND AIR COMPRESSOI AND POWER STEERING FLANGE. REMOVE POWER STEERING PUMP, PUMP NOT LEAKING AIR COMPRESSOR LEAKING AT SEAL A PER MANUEL EXCESSIVE AIR BUILD UP COMPRESSOR FAULTY AFTER GOVERNOR REPLACEMENT, REMOVE COOLANT. REMOVE COMPRESSOR. PART ON ORDER. CLEAN ALL SURFACES AND

000090155133634 FUEL FILTER WIX	MERCEDES	1
0001801709OIL FILTER 03 57215 WIX	MERCEDES	1
0200271ANTLER BAR		1
05-17223-002RAD CAP 20 LB		1
15W40BSYN OIL BULK QTS		26
284358GOVERNOR D-2		1
322502BULB PATIENT GH22		2
3744BRAKE DRUM REAR		2
6806970098SEAL DOOR		1
78R536078R5360M 2PK FILTER AIR COND		1
91-22WIPER BLADE		2
91823SWITCH SWT5499 MED MASTER		1
A0249972148SEAL		1
A1712756000HOOD CABLE		1
A1834388002MOLD L/H		2
A1834388003MOLD R/H		2
AMH-1AMH-1 VALVE EXTENSION		1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/		4
CA8193AIR FILTER 46744 WIX		1
CLR9185209186-1500-20 MARKER LT.AMBER LED		1
DDE-9062030180GASKET SOCKET TO HEAD M2		1
FG87904MFG3937557S FILTER P/S NEW STYLE		1
FGQ79699GASKET-P/S FILTER NEW STYLE		1
HP-31DBATTERY 950CCA HP-31D		4
IMMF11358SEAT BELTS		2
KSMA3124710QKSMA3124710QP REAR BRAKE SHC		2
N000000001069SEAL BANJO		4
N910142010001SCREW AIR COMPRESSOR MTG		4
R90PFILTER FUEL 33231		1
RA9061301415AIR COMPRESSOR		1
VML-T1413T3248 SIGHT GLASS		1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

REASSEMBLE. 20. BATTERY TRAY HARD TO SLIDE - CLEAN SLIDER AND LOCKING MECHANISM LUBRICATE SLIDERS AND LOCKING MECHANISM - OPERATE UNTIL TRAY MOVES FREELY. 21. CLASS #1 LEAK L/SIDE REAR MOTOR MOUNT CLEAN AREA UNABLE TO LOCATE LEAK. 22. NO CITY HORN DIAGNOSE FAILURE - HI AND LOV HORN OPERATING NORMAL, HORN BUTTON OPERATING NORMAL, FOUND PINCH WIRE ON HARNESS WRAP WILL LOOM - REPAIR FAULT. 23. BACK UP CAMERA INOP. CHECK CAMERA FOR WATER INTRUSION NONE IN CASING, CHECK CABLES, CONNECTOR, SCREEN, REASSEMBLE UNIT NOW WORKING NOT ABLE TO DETERMING CAUSE UNIT OPERATING NORMAL 24. Q & A VETT.

WKL0381DOME LIGHT WELDON 8046

1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V54470

In Date: 12/17/2012

Meter Reading: 117,510.00

Close Date: 02/01/2013

Problem?

CHECK AND REPAIR COOLANT LEAK

Task performed:

1. COOLANT LEAK- DIAGNOSE COOLANT LEAK FOUND HEAD GASKET LEAKING- DRAIN COOLANT AND DISASSEMBLE ASSOCIATED PARTS AND CONNECTION TO HEAD, REMOVE HEAD FOUND EXHAUST MANIFOLD LEAKING. 2. CLEAN ALL PARTS CHECK HEAD AND BLOCK SURFACE FOR DAMAGE ON WARP. 3. REASSEMBLE HEAD NEW PARTS ADJUST LASH RACK REAR FRT AND REAR CLEARANCE AS PER MANUFACTORY SPECS. 4. REASSEMBLE AND TORQUE TO SPECS FUEL LINE BLEED AND START UNIT CHECK FOR FUEL 5. ASSIST IN HEAD INSTALLATION. 6 ASSIST IN VALVE ADJUSTMENT.

Parts

Quantity

23-12080-150BOLT BUMPER	2
9061420057SEAL RING EXHAUST MANIFOLD	2
9061421101EXHAUST MANIFOLD CENTER	1
9061421201EXHAUST MANIFOLD R/L	2
9062030015PIPE SOCKET TO WP	2
A0000160521GASKET VALVE COVER	1
A9060109221GASKET KIT	1
A9060160721SIDE GASKET	1
A9060160769HEAD BOLT MBE906	14
A9060170524PIPE CONN	6
A9060702433FUEL LINE	6
A9261420080EXHAUST GASKET	3
DDE/00009903150TURBO NUTS	2
DDE/0019904605TURBO STUD	2
DDE/9049900412EXHAUST BOLTS	12



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V55314

In Date: 01/26/2013
Close Date: 02/12/2013

Meter Reading: 117,652.00

Problem?

pneumatic lift on officer's seat is 10-7. seat sits at the super low mark and can't be raised at all. Affects position when donning airpack from seat.
R-51

Parts ----- Quantity -----

Task performed:
REPAIRED AIR RIDE SEAT.

NO PARTS USED

Workorder: V55365

In Date: 01/29/2013
Close Date: 02/12/2013

Meter Reading: 117,734.00

Problem?

officer exterior door handle does not grab and open door...needs to be pulled 3 to 5 times to open door and it's loose.

Parts ----- Quantity -----

Task performed:
ADJUSTED DOOR HANDLE.

NO PARTS USED

Workorder: V55815

In Date: 02/18/2013
Close Date: 02/22/2013

Meter Reading: 118,692.50

Problem?

Headlight out

Parts ----- Quantity -----

Task performed:
REPLACED.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V55813

In Date: 02/18/2013 Meter Reading: 118,692.50
Close Date: 03/05/2013

Problem?

Passenger side headlight is out. R-51

Parts ----- Quantity

Task performed:
REPLACED HEADLIGHT AND REPAIRED WIRING.

H6054USE CV TYPE SEALED BEAM	2
------------------------------	---

Workorder: V55814

In Date: 02/18/2013 Meter Reading: 118,692.50
Close Date: 03/05/2013

Problem?

LT side door handle is not working right

Parts ----- Quantity

Task performed:
ADJUSTED DOOR HANDLE.

NO PARTS USED	
---------------	--

Workorder: V51593

In Date: 08/14/2012 Meter Reading: 111,676.70
Close Date: 04/04/2013

Problem?

REPAIRS FROM B INSPECTION R 51

Parts ----- Quantity

Task performed:
1. POWER STEERING PUMP LEAK FOUND NO LEAK. 2. CAB SEAT BELT FRAYED-FOUND NO PROB W/ SEAT BELTS. 3. ROAD TESTED AND CHK STEERING TESTED.

NO PARTS USED	
---------------	--



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V56180

In Date: 03/05/2013
Close Date: 04/05/2013

Meter Reading: 119,514.30

Problem?

Air dump malfunctioning. R-51

Parts _____ Quantity _____

Task performed:

REPAIRED AIR PUMP SWITCH.

NO PARTS USED

Workorder: V46716

In Date: 01/19/2012
Close Date: 04/08/2013

Meter Reading:

Problem?

Audible door open alarm not working R 51

Parts _____ Quantity _____

Task performed:

NO PARTS USED

Workorder: V54442

In Date: 12/14/2012
Close Date: 04/08/2013

Meter Reading:

Problem?

ONE SET OF FLUORESCENT LIGHTS IN STRETCHER COMPARTMENT
NO LONGER WORKING. R51

Parts _____ Quantity _____

Task performed:

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V56649

In Date: 03/26/2013
Close Date: 04/10/2013

Meter Reading: 120,589.00

Problem?

Rubber boot that connects cab with pt compartment falling off R 51

Parts ----- Quantity -----

Task performed:

REPAIRED RUBBER BOOT.

NO PARTS USED

Workorder: V53278

In Date: 10/24/2012
Close Date: 04/24/2013

Meter Reading: 114,955.00

Problem?

R51 needs rear outter tires

Parts ----- Quantity -----

Task performed:

R51 NEEDS REAR OUTER TIRES.

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE

Workorder: V57480

In Date: 05/04/2013
Close Date: 05/09/2013

Meter Reading:

Problem?

rubber weather stripping that goes between pt compartment and cab keeps falling off preventing seal. Crew states the can smell exhaust.R51

Parts ----- Quantity -----

Task performed:

1. TRAVEL TO STATION LOOK AT PASS THROUGH BOOT ORDER MATERIAL-SCHEDULE TRCUK TO SHOP. 2. TRUCK CAME TO SHOP CHANGED PASS THROUGH BOOT.

GASK-BEL0110002439 WINDOW BELLOWS 6 IN WID 10



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V57962

In Date: 05/24/2013
Close Date: 06/07/2013

Meter Reading:

Problem?

R51 A/C blowing warm. Mechanic recharged system.

Parts

Quantity

Task performed:

1. RECHARGED SYSTEM AND CHECKED FOR LEAKS AND REPAIRED. 2. REPAIRED REAR DOORS THAT WOULD NOT LOCK.

NO PARTS USED

Workorder: V58287

In Date: 06/10/2013
Close Date: 06/10/2013

Meter Reading:

Problem?

Stretcher has two broken wheels that fell off. The stretcher is located now a 55in the shed. R51

Parts

Quantity

Task performed:

EMSAR CONTACTED FOR REPAIR

NO PARTS USED

Workorder: V58578

In Date: 06/20/2013
Close Date: 06/28/2013

Meter Reading: 125,036.00

Problem?

B inspection R51 OCS

Parts

Quantity

Task performed:

B inspection by OCS replaced oil and fuel filters

NO PARTS USED

Vendor? OIL CHANGE SERVICES



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V58636

In Date: 06/24/2013
Close Date: 06/28/2013

Meter Reading: 125,259.60

Problem?

Hector from Boulevard Tire was in to replace right rear exterior tire on R51 last night. He advised that R51 is in need of 5 new tires. and to let Fast Ed Erke know.

Parts ----- Quantity -----

NO PARTS USED

Task performed:

HECTOR FROM BOULEVARD TIRE WAS IN TO REPLACE RIGHT REA EXTERIOR TIRE ON R51 LAST NIGHT. HE ADVISED THAT R51 IS IN NEED OF 5 NEW TIRES. AND TO LET FAST ED EHRKE KNOW.

Vendor? BOULEVARD TIRE CENTE

Workorder: V58941

In Date: 07/08/2013
Close Date: 07/19/2013

Meter Reading: 125,779.00

Problem?

BACK UP CAMERA NOT WORKING 100% OF THE TIME, ONLY WORKS INTERMITTENTLY. R51

Parts ----- Quantity -----

NO PARTS USED

Task performed:

1. REPAIRED BAD CONNECTION ON BACK OF CAMERA. 2. REPAIRE COOLANT LEAK.

Workorder: V58931

In Date: 07/08/2013
Close Date: 08/07/2013

Meter Reading: 125,779.00

Problem?

SPOTLIGHT ON TOP OF CAB ROOF OF R51 NO LONGER WORKING.

Parts ----- Quantity -----

18753-0455H7935-1 SPOT LIGHT BULB SPT6008 1

Task performed:

1. READJUSTED REAR CAB DOORS. 2. REMOVED LIGHT AND REPAIRED BAD GROUND WIRE IN LIGHT.



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V60190

In Date: 08/30/2013
Close Date: 09/04/2013

Meter Reading: 127,951.00

Problem?

Engine overheating at fire scene

Parts ----- Quantity -----

Task performed:

ENGINE A/C HEATING/FAN CLUTCH WORN OUT/GET FAN WORKING
TEMPORARILY BACK TO STATION HAD TO SWAP OUT WITH SPARE

NO PARTS USED

Workorder: V59662

In Date: 08/07/2013
Close Date: 09/05/2013

Meter Reading:

Problem?

R51 stretcher needs maintenance. R51 stretcher head rest piston is not working. EMSAR has been contacted. R51's broken stretcher is located in STATION 55's shed.

Parts ----- Quantity -----

Task performed:

NO PARTS USED

Workorder: V60186

In Date: 08/30/2013
Close Date: 09/06/2013

Meter Reading: 127,951.00

Problem?

repair faulty fan clutch

Parts ----- Quantity -----

Task performed:

INSTALLED NEW FAN CLUTCH AND TESTED.

07-14488-000DIPSTICK	1
HOR/991450HT 650 FAN ASY.	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V60285

In Date: 09/05/2013
Close Date: 09/06/2013

Meter Reading: 127,951.00

Problem?

Install N.Y. hook brackets

Task performed:

INSTALLED BRACKETS.

Parts	Quantity
5269LPVM-5 SM MOUNT	2

Workorder: V60295

In Date: 09/05/2013
Close Date: 09/06/2013

Meter Reading: 127,951.00

Problem?

L/R tires worn

Task performed:

1. REPLACED BOTH LEFT REAR TIRES (WORN OUT). 2. CHECKED OVER TRUCK BEFORE RETURN TO STATION. AIRED TIRES, CHECKED FLUIDS, CHECKED LIGHTS AND A/C. 3. REPLACED DRIVER'S DOOR TRIM.

Parts	Quantity
A1834388002MOLD L/H	1

Workorder: V60488

In Date: 09/13/2013
Close Date: 10/09/2013

Meter Reading: 128,380.00

Problem?

rear pt compartment door handle broken. Can only access from inside.

Task performed:

DOOR HANDLE BROKEN REMOVED BROKEN DOOR HANDLE AND INSTALLED NEW HANDLE.

Parts	Quantity
HND5948TM22676-02 HANDLE DOOR ENTRY	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V60655

In Date: 09/20/2013
Close Date: 10/11/2013

Meter Reading:

Problem?

replace 2 front tires replace drivers side wiper blade

Parts ----- Quantity -----

Task performed:

REMOVED AND REPLACED WIPER BLADES AND REPAIRED WIPER ARM.

NO PARTS USED

Workorder: V61368

In Date: 10/18/2013
Close Date: 11/04/2013

Meter Reading:

Problem?

Tire wearing uneven, needs a alignment and possibly new front tires.R51

Parts ----- Quantity -----

Task performed:

CHECKED TIRES AND NEED TWO FRONT TIRES INSTALLED.

NO PARTS USED

Workorder: V61840

In Date: 11/06/2013
Close Date: 11/06/2013

Meter Reading:

Problem?

Both turn signals not working. SP9893 R51

Parts ----- Quantity -----

Task performed:

1. travel to sta-51, check for no turn signals, replace turn signal switch, travel back to s/shop.

6805450124SWITCH TURN SIGNAL 1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V61705

In Date: 11/01/2013
Close Date: 11/15/2013

Meter Reading: 130,369.10

Problem?

replace batteries

Task performed:

1. BATTERIES SHORTED OUT- REMOVED ALL BATTERIES AND REPLACED ALL. 2. BATTERY SWITCH INOP- REPLACED BATTERY SWITCH.

Parts	Quantity
75908SWITCH BATTERY MASTER 300A	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
HP-31DBATTERY 950CCA HP-31D	4

Workorder: V61718

In Date: 11/02/2013
Close Date: 11/15/2013

Meter Reading:

Problem?

The window frame behind the driver on R51 is loose out of the door frame and will not snap back in. The panel on the inside appears to be unservicable.

Task performed:

REMOVED WINDOW FRAME AND INSTALLED ALL NEW SCREENS.

Parts	Quantity
NO PARTS USED	

Workorder: V61900

In Date: 11/08/2013
Close Date: 11/25/2013

Meter Reading:

Problem?

Right rear tire on E51 has a slow leak. Was mounted two days ago.

Task performed:

SENT TIRE COMPANY TO CHECK SMALL LEAK IN TIRE.

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V62103

In Date: 11/18/2013
Close Date: 12/17/2013

Meter Reading:

Problem?

air leak when brake is pushed on. Everytime. r51

Parts

Quantity

Task performed:

CHECKED FOR AIR LEAK FOUND AIR SOLENOID REMOVED AND REPLACED.

FSC17492134NC SW PARK BK SPADE TYPE CONNE

1

Workorder: V62680

In Date: 12/12/2013
Close Date: 12/23/2013

Meter Reading: 132,908.00

Problem?

All back tires need replacement. R51

Parts

Quantity

Task performed:

ALL BACK TIRES NEED REPLACEMENT. R51.

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V62757

In Date: 12/17/2013

Meter Reading: 132,908.00

Close Date: 01/06/2014

Problem?

C INSPECTION R51

Task performed:

1. C insp 2. l/side driver door entry lite inop, remove door panel found broken wires inside door panel, repair wiring 3. replace wiper blades 4. adjust headlights 5. l/side and r/side dash a/c vents broken, replace vents 6. replace red dot a/c filter in cab 7. r/side turn signal marker lite inop, replace bulb 8. battery comt draw will not open, pry open and clean slides and grease 9. r/side cab entry door lite inop, repair wiring on door switch 10. r/side diamond plate on door panel bent, reattach panel 11. r/side window molding broken, remove door panel and replace top window molding 12. replace pat. compt a/c filter 13. replace compt. struts above emt seat 14. replace comt struts on bear cave compt. door 15. floursent lite above emt seat inop, remove assy. found wires burnt, repair wire connector's 16. remove and clean non skid tape, and replace non skid tape on side entry walk way 17. remove and clean non skid tape on rear entry walk way, and install new tape 18. r/side striker pin cover broken, replace pin cover 19. weather stripping for rear entry doors falling off, reinstall with scilione 20. remove fan and replace new fan belt, reinstall far 21. remove and install new a/c belt. run engine and readjust belt 22. service transmission 23. service air dryer 24. found heater shut off valve leaking, tighten hose clamps and pressure chek for leaks, ok 25. l/side, r/side and middle cab marker lites inop, replace bulbs 26. air system leaks down overnight, use soap and water to trace out leaks, found push on fittings leaking on foot valve, replace fittings, recheck for leaks, found humphrey valve leaking behind dash, remove dash and replace valve, recheck for leaks, non found and now holds air overnight. 27. road test vehicle after p.m, recheck all fluids.

Parts

Quantity

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
0127110042BELT MERCEDES MOTORS	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	24
29526898 29548988 TRANS FILTER ALLISON	1
52-24WIPER BLADES ANCO 24	2
6808300074VENT A/C LH	2
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
A1834388003MOLD R/H	1
HLD3999GSS1715UV 30LB STRUT GAS	4
R90PFILTER FUEL 33231	1
SU68088VALVE DUMP 310 HUMPHREY	1
TRANSYNDALLISON TRANS FLUID GAL	5



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V59560

In Date: 08/05/2013
Close Date: 01/21/2014

Meter Reading:

Problem?

R51 stretcher hydraulic head will not stay in place for pt head. Stretcher is located in Station 55 shed.

Parts ----- Quantity -----

Task performed:
REPAIRES COMPLETED.

NO PARTS USED

Workorder: V63945

In Date: 02/03/2014
Close Date: 02/04/2014

Meter Reading: 134,293.60

Problem?

SR18 a inspection

Parts ----- Quantity -----

Task performed:
1. A INSP. 2. PACENT REAR ENTRANCE NATAR OIN COVER- REMOV
DAMAGE PIN- DRILL TAPNEW SUPPORT HOLES AND INSTALL NEW
NATAR PIN COVER. 3. PACENT COMP- FLOURESCNET LIGHT INOP-
REMOVE BLOWN BULBS AND INSTALL NEW BULBS.

SPT6008146SL LIGHT-REMOTE SPOT 1

Workorder: V64403

In Date: 02/20/2014
Close Date: 02/26/2014

Meter Reading: 135,236.00

Problem?

Replace front tires R51 Boulevard Tire

Parts ----- Quantity -----

Task performed:
REPLACE FRONT TIRES R51 BOULEVARD TIRE.

NO PARTS USED

Vendor? BOULEVARD TIRE



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V64486

In Date: 02/24/2014
Close Date: 02/26/2014

Meter Reading: 135,711.50

Problem?

a/c not cold and low flow

Parts

Quantity

Task performed:

A/C IN PAT AND CAB LOW CHARGED A/C. FOUND A/C LOW ON CHARGE. CHARGED A/C LOW FLOW IN DASH VENTS. TOOK APART DASH. FOUND DUCTS NOT CONNECTED AND REFROST STUCK.

NO PARTS USED

Workorder: V64146

In Date: 02/11/2014
Close Date: 03/12/2014

Meter Reading:

Problem?

need stretcher hook device to secure stretcher from falling out of back of truck and falling to ground installed on the floor in the back of the truck SR@ 32

Parts

Quantity

Task performed:

INSTALLED YELLOW STRETCHER LATCH IN REAR OF RESCUE.

NO PARTS USED

Workorder: V64641

In Date: 03/02/2014
Close Date: 03/19/2014

Meter Reading:

Problem?

Officers side head light is out. R51

Parts

Quantity

Task performed:

REPLACED HEADLIGHT AND REPAIRED WIRES.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V58540

In Date: 06/19/2013
Close Date: 04/07/2014

Meter Reading:

Problem?

stretcher. Piston that raises and lowers head of stretcher gets locked up and won't move.

Parts _____ Quantity _____

Task performed:

REPAIRED ON WORK ORDER #59560.

NO PARTS USED

Workorder: V65108

In Date: 03/21/2014
Close Date: 04/08/2014

Meter Reading:

Problem?

Need shore line plug looked at for the rescue. We can't plug in the shore line to the rescue truck to keep it charged. R32

Parts _____ Quantity _____

Task performed:

REPAIRED SHORE LINE PLUG AND TESTED.

NO PARTS USED

Workorder: V65552

In Date: 04/08/2014
Close Date: 04/08/2014

Meter Reading:

Problem?

screw in driver front tire

Parts _____ Quantity _____

Task performed:

CALLED CREW- PULLED SCREW OUT AND NO LEAK. ALL OK AT THIS TIME.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V65703

In Date: 04/14/2014
Close Date: 04/17/2014

Meter Reading: 139,759.90

Problem?

pat a/c inop

Parts

Quantity

Task performed:

VACUUMED UNIT FOUND LOW ON FREON. CHECKED FOR LEAKS
CHARGED OK.

NO PARTS USED

Workorder: V64168

In Date: 02/12/2014
Close Date: 04/25/2014

Meter Reading:

Problem?

TIC charger for Rescue SR@32

Parts

Quantity

Task performed:

TIC charger for Rescue SR@32

NO PARTS USED

Workorder: V65546

In Date: 04/08/2014
Close Date: 04/25/2014

Meter Reading: 139,278.70

Problem?

Rear door inop

Parts

Quantity

Task performed:

REPAIRED LINKAGE FOR REAR DOOR.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V65956

In Date: 04/25/2014
Close Date: 05/05/2014

Meter Reading: 140,695.60

Problem?

Use for another job

Task performed:
ticket not used

Parts ----- Quantity -----

NO PARTS USED

Workorder: V64157

In Date: 02/12/2014
Close Date: 05/09/2014

Meter Reading:

Problem?

Station 32- SCBA bracket in driver's compartment :)

Task performed:
REMOUNTED TOOLS IN L-1 & CAB.

Parts ----- Quantity -----

01-29866-118BELT ALT. M2	1
CQ5251JURADIO	1

Workorder: V65730

In Date: 04/15/2014
Close Date: 05/09/2014

Meter Reading: 139,759.90

Problem?

No start

Task performed:
TRACED OUT PROBLEM WITH NO START FOUND LOSE WIRE-
REPAIRED AND TESTED.

Parts ----- Quantity -----

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V65658

In Date: 05/23/2014
Close Date: 06/16/2014

Meter Reading:

Problem?

Rear compartment door inop

Parts

Quantity

Task performed:

Q/A truck & fix doors buzzer alarm.

NO PARTS USED

Workorder: V66262

In Date: 05/05/2014
Close Date: 07/01/2014

Meter Reading: 141,153.40

Problem?

B inspection SR18, cab a/c, cab door alarm, cracked radiator

Parts

Quantity

Task performed:

1. C-INSPECTION. 2. REPAIRS ON LIST. 3. REPAIR ON TICKET A/C.

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
284358GOVERNOR D-2	1
470790HOSE AND FITTING	1
A1834388002MOLD L/H	1
A1834388003MOLD R/H	1
R90PFILTER FUEL 33231	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V65959

In Date: 04/24/2014
Close Date: 07/07/2014

Meter Reading:

Problem?

R32 warning 1 low ampage and constatnt alarm going off in PT compartment. Amps ranging from 5 to -6.

Parts ----- Quantity -----

Task performed:

ALL REPAIRS DONE ON B SER, AT SHOP SEE TICKET V66262

NO PARTS USED

Workorder: V67714

In Date: 07/07/2014
Close Date: 07/09/2014

Meter Reading: 141,333.00

Problem?

replace stretcher latch and slides for sharps drawer. R231

Parts ----- Quantity -----

Task performed:

1. TRAVEL TO 23 REPLACED STRETCHER LATCH. 2. REPLACED DRAWS SLIDES.

090-0278STRECHER BAR NEW	1
5632-1010 IN DRAWER SLIDES PR	1

Workorder: V68726

In Date: 08/17/2014
Close Date: 08/20/2014

Meter Reading: 144,984.00

Problem?

Front right head light out on R231

Parts ----- Quantity -----

Task performed:

Travel to 23. Replaced blown bulb R231.

H6054USE CV TYPE SEALED BEAM	1
------------------------------	---



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V69393

In Date: 09/15/2014

Meter Reading: 91,996.00

Close Date: 09/18/2014

Problem?

A inspection SR18

Task performed:

1. "A" inspection. 2. Remove decals, glue and buff out body. 3. Replace front fire extinguisher bracket. 4. Replaced L front marker bulb. Clean and bend contacts for fit. 5. Replaced stripped screws for side patient compartment door reflector. 6. Replaced rear dome light bulb. 7. Install missing fasteners for fenders skirt. 8. Air L R I tire and check for leaks. (ok) 9. Rear camera inoperable. Diagnose problem, remove interior trim and rear plywood. Found bad connection in cable connection. Repair connection , reinstall plywood and trim. Test ok. 10. City horns inoperable. Diagnose problems, found high resistance in horns and horn button. Replaced horns and clean contact in steering wheel column. 11. Battery charger inoperable. Reset breaker and checked charger, ok. 12. Coolant low. Pressure check system. Found radiator lower tank leaking. 13. Replaced rear brakes and drums. Drums frozen on hubs. Adjusted brakes 14. Rotate front tires to rear and install new tires on front. 15. Batteries low from shoreline inop. Charge batteries and load, test ok. Clean terminals. 16. Replaced L and R rear mud flaps. Cut to size. Drill holes and mount to body. 17. Drain cooling system 18. Wash front and rear wheels. 19. Diagnose air leaks. Replaced drain valves and push on air fittings. Cut old pull cables. 20. Drain cooling system. Flush system until water runs clean. Clean radiator tank at pin hole leak. Apply JB weld to area 21. Fill cooling system. Road test for breaks and to pressurize system. Check for any leak at radiator repair. Recheck coolant level.

Parts

Quantity

103385NDRAIN COCK	2
322502BULB PATIENT GH22	1
3744BRAKE DRUM REAR	2
A0631117000HORN HIGH NEW # 06-52125-039	1
A0631117003HORN LOW NEW #06-52125-041	1
ANTICOOLANT ANTIFREEZE GAL	7
B2420LP-SMUD FLAP 24 X 24	2
KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V69065

In Date: 08/30/2014
Close Date: 09/19/2014

Meter Reading:

Problem?

Air leak in dash when parking brake off only. Compressors seem to have no problem keeping up.R52

Parts ----- Quantity -----

Task performed:

repaired brake line that was leaking.

NO PARTS USED

Workorder: V69098

In Date: 09/02/2014
Close Date: 09/19/2014

Meter Reading:

Problem?

spare at station 52 leaking air badly when air brake switch in off position. Leak stops when parking brake applied.

Parts ----- Quantity -----

Task performed:

R&R AIR SOLENOID.

FSC17492134NC SW PARK BK SPADE TYPE CONNE 1

Workorder: V69629

In Date: 01/01/1900
Close Date: 09/24/2014

Meter Reading: 91,996.00

Problem?

replace front tires

Parts ----- Quantity -----

Task performed:

Replace front tires.

NO PARTS USED

Vendor? BLVD TIRE CENTER



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V70852

In Date: 11/12/2014
Close Date: 11/14/2014

Meter Reading: 146,923.20

Problem?

cab a/c compressor sized up, R-41

Task performed:

remove belts remove a/c compressor, flush system, replace compressor and dryer, charge a/c

Parts	Quantity
533103-0607 A/C COMPRESSOR U4482 USE 7169 D	1
716907-0610A DRYER	1

Workorder: V70766

In Date: 11/07/2014
Close Date: 11/21/2014

Meter Reading:

Problem?

truck will not start

Task performed:

1. Checked batteries and tested ok-recharged and started 2. Readjusted strecher latch and tested

Parts	Quantity
NO PARTS USED	

Workorder: V71218

In Date: 11/26/2014
Close Date: 12/05/2014

Meter Reading: 146,923.20

Problem?

A inspection SR18

Task performed:

1. A inspection 2. R/R lens, R/R bulb, clean bulb contacts 3. R/R R/S top amber market LT assy 4. R/R dash panel, R/R 2 bulbs 5. R/R lens , clean bulb contacts and 4 F marker LT 6. Find good used tire in Bldg 7, R/R 4 router tire inflate to 110 PSI schrader valve stuck deflate tire. R/R shrader valve and reinfated 110 PSI

Parts	Quantity
404-100 VALVE CORE	6
4923090025DASH BULB VDO	2
CLR9185209186-1500-20 MARKER LT.AMBER LED	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V71904

In Date: 12/29/2014
Close Date: 12/31/2014

Meter Reading: 147,982.10

Problem?

wiper blades

Parts ----- Quantity -----

Task performed:

Travel to station 20, replaced wiper blades travel home

52-24WIPER BLADES ANCO 24	2
---------------------------	---

Workorder: V71951

In Date: 12/31/2014
Close Date: 01/02/2015

Meter Reading: 148,111.00

Problem?

truck stuck

Parts ----- Quantity -----

Task performed:

Travel to wellington winch out truck

NO PARTS USED	
---------------	--

Workorder: V71868

In Date: 12/25/2014
Close Date: 01/05/2015

Meter Reading: 147,894.60

Problem?

Driver seatbelt locks and has to be jiggled back and forth to get it to operate properly. R20

Parts ----- Quantity -----

Task performed:

Travel to station 20-check out seat belt inop, check out all seat belts and lube found no problem ok.

NO PARTS USED	
---------------	--



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V72109

In Date: 01/07/2015
Close Date: 01/20/2015

Meter Reading: 148,176.00

Problem?

A-inspection

Parts

Quantity

Task performed:

"A" inspection-could not complete needed rescue

NO PARTS USED

Workorder: V72163

In Date: 01/09/2015
Close Date: 01/28/2015

Meter Reading: 148,067.10

Problem?

R48 12 volt outlet inop

Parts

Quantity

Task performed:

Repaired 12 volt outlet.

NO PARTS USED

Workorder: V72317

In Date: 01/14/2015
Close Date: 01/28/2015

Meter Reading:

Problem?

Cover to electrical charging outlet broke off.

Parts

Quantity

Task performed:

Repaired cover for 110V outlet.

NO PARTS USED



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V72683

In Date: 01/28/2015
Close Date: 02/03/2015

Meter Reading: 149,132.00

Problem?

A INSPECTION SR12

Task performed:

1. A Inspection. 2. Cab marker light. Remove blown bulb and install new bulb. 3. Patient a/c low on freon. Check for leak. Found hi side fitting leaking. Recover freon. Cut out bad fitting and install new one. Reassemble, vacuum system and check for leaks. 4. Patient compartment lining cabinet lock broken. Remove latch and install new one. 5. Oxygen wrench missing. Attach support cable to wrench and mount on unit.

Parts	Quantity
08-3001B4479 SPLICER B/L	1
252189LATCH TRIGGER W/LOCK	1
493795HOSE & FITTINGS	1
AS75807OXM1757-01 OXYGEN WRENCH	1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V72741

In Date: 01/30/2015

Close Date: 02/12/2015

Meter Reading: 149,214.00

Problem?

C inspection SR18

Parts

Quantity



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

* **ADVANCED LIFE SUPPORT VEHICLE**

Task performed:

1. C Inspection. 2. Replaced aux. a/c filter. Clean expanded metal guard. 3. Remove left front and rear seats for repair. 4. Replaced missing auto eject cover, 5. Remove rocker covers, clean floor mat, splice in door weatherstripping on left front, left rear and right front cab doors. 6. Driver's door trim loose. Removed handle and door panel. Found missing screws and old trim under new. Removed old trim and install screws where missing. 7. Right front door trim broken. Remove door panel. Replaced trim. Glue door panel cover to panel where loose. Install missing push pin. Lube handle bolts and threads. 8. Left rear door trim broken. Remove handle and door panel. Replaced rim. Install larger sheet metal screw in stripped hole. Install washers and lube bolt and threads. 9. Right front cab door light inop. Found wire cut. Repair wire with heat shrink splice. Protect wire with loom. 10. Replaced light box charger bases. Splice in wiring. Drill holes in box to enlarge holes for mounting. Tie strap harness and install wire frame clamp. Test ok. 11. Clean and paint fuel cap. 12. Remove Placard frames, mastic and buff out body. 13. L-4 door panel loose. Found stripped out screws. Drilled and tapped new screw threads and installed new screws. 14. L-2 coat hooks loose and fire extinguisher bracket screw stripped out. Tighten coat hook screws and drill and tap new threads beside old hole. Install new machine screw. 15. Left rear door light inop. Found bad switch and threads in body too thin for switch. Install new switch with washer to space switch threads where absent. 16. Battery box slide tray hard to open. Clean and lubricate slide tracks. 17. Rebuild air dryer. Replace purge valve. 18. Torque U bolts. 19. Diagnose 110V a/c inop. Found bad compressor. Replaced roof top unit. Clean roof of silicone. Cut handrail frame for new different unit to fit. Cut divider channel. Wire unit and remove or cap old wires. Torque bolts to spec. Drill and secure frame unit to handrail frame. Test - ok. Clean unit and truck. 20. Install seats back from Central Auto Trim. 21. Front right seat won't raise. Diagnose problem. Found kinked line and bent fill valve pintle. Remove seat. Cut kinked line and changed direction of fitting. Install hose. Replaced fill valve with different line configuration. Install 90 degree block to make work. Test ok. Re-install seat. Replaced supply line splice. 22. A/c leak by high pressure switch. Remove switch and check mating with fitting. Clean area and reinstall and tighten. Check for leaks. Found crimp on hose fitting leaking. Recover freon, disconnect line from compressor and

000090155133634 FUEL FILTER WIX	MERCEDES	1
0001801709OIL FILTER 03 57215 WIX	MERCEDES	1
032110401150 VALVE AIR SEAT		1
107796DRYER KIT AD9 -NEW		1
1094KIT-AIR HORN-GROVER		2
15W40BSYN OIL BULK QTS		26
494577HOSE & FITTINGS		1
63152HVAC UNIT ROOF MOUNTED		1
6806970098SEAL DOOR		2
78R536078R5360M 2PK FILTER AIR COND		1
800405PURGE VALVE KIT		1
91823SWITCH SWT5499 MED MASTER		1
A1834388002MOLD L/H		1
A1834388003MOLD R/H		1
CA8193AIR FILTER 46744 WIX		1
GRV1720244770R1 HORN SUPPORT BRKT		1
R90PFILTER FUEL 33231		1



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

cut hose. Had Mako make up new hose splice. Splice in hose. Vacuum system and charge. 23. Oil leaks by power steering pump and vehicle air compressor. Clean area. Tighten pump cover bolts. Test drive vehicle and recheck - ok. 24. Oil by front a/c compressor fitting. Clean area. Run a/c and recheck for any leak - ok. 25. Air horns sound quality poor. Remove frozen parts. Install kits. Lubricate threads with silicone grease. Assemble and adjust for sound quality - ok. 26. Q and A vehicle.

Workorder: V73474

In Date: 02/26/2015 **Meter Reading:** 149,551.70
Close Date: 03/09/2015

Problem?

A inspection SR18

Task performed:

1. A-INSP 2. FRONT/R CAB DOOR LIGHT INOP. REPLACED SWITCH & CONNECTOR 3. BELLOW BETWEEN CAB & PAT BOX LOOSE. REPAIRED SEAM. SILICONES AIR SPACES 4. REAR A/C HI/PRESSURE SWITCH LEAKING. REPLACED SWITCH. CHECK FOR LEAKS. OK 5. REAR A/C BLOWER INOP. BURNT WIRE CONNECTION REPLACED WIRE CONNECTION 6. COMPT DRAWER TRACKS BROKEN. REPLACED R/TRACK FROM NEW DNI PARTS 7. FIRE EXTINGUISHER BRACKET BROKEN. REPLACED 8. CITY HORN INOP REPLACED WITH DNI HORN

Parts	Quantity
91822OBSOLETE USE SERV TKS SWITCH - DOOR	1
FTT53931491 SW PRESS. HI SIDE NC OPEN-350 CL	1

Workorder: V74839

In Date: 04/21/2015 **Meter Reading:**
Close Date: 04/21/2015

Problem?

Spare R28 having very difficult time starting.

Task performed:

Parts	Quantity
NO PARTS USED	



4/10/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156658

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V73684

In Date: 03/05/2015
Close Date: 04/30/2015

Meter Reading:

Problem?

Stretcher securing locking device locking in open position. Had to manually force closed on a run. Unable to open/exit rear doors from inside. Passenger side rear door.

Parts ----- Quantity -----

Task performed:

- 1. Readjusted rear stretcher arm and latch.

NO PARTS USED

Workorder: V74245

In Date: 03/27/2015
Close Date: 04/30/2015

Meter Reading: 150,184.30

Problem?

Quality check

Parts ----- Quantity -----

Task performed:

- 1. QC vehicle.

NO PARTS USED