

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 32169

**Problem:** REPLACE THE SEAT BELT

<b>Meter Reading:</b> 108637	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 01/03/2000	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Replace Driver Seat Belt. Replace Rf Door Latch.	<b>5.00</b>	T-4 WHITE PAINT	2.00
- Replace Am Fm Radio. Replace Backup Alarm,		NEW RADIO CRW200	1.00
Thermostat Switch For A/C And Dash Lite Bulbs.		DRIVER'S SEAT BELT 1684505C3	1.00
- Po-Parts Only.		9-2951 BACKUP ALARM ECCO 575 GROTE 73120	1.00
<b>Parts Charge:</b>	512.89	<b>Labor Charge:</b>	225.00

**Workorder:** 33197

**Problem:** REPAIR STARTING SYSTEM

<b>Meter Reading:</b> 109482	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 01/19/2000	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Wires Melted @ Ignition Switch Replace Switch Repair	<b>1.50</b>	IGN. SW. 429047C1	1.00
Wires And Connection.			
<b>Parts Charge:</b>	16.83	<b>Labor Charge:</b>	67.50

**Workorder:** 33545

**Problem:** 001 QUART OF OIL ISSUED OUT 01/21/00

<b>Meter Reading:</b> 0	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 01/21/2000	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- 001 Quart Of Oil Issued Out 01/21/00		15/40 OIL	1.00
<b>Parts Charge:</b>	1.62	<b>Labor Charge:</b>	0.00

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

Workorder: 33617

Problem: REPLACE THE SHIFT CABLE

Meter Reading: 110023	Labor	Parts	Quantity
In Date: 01/26/2000	Hours	Description	
- Hard To Shift Replace Cable Shift.	48.50	SLACK ADJUSTER R802487	1.00
- Hydraulic Supply And Back (Make Cable)		REAR BEARING FP594A	1.00
- Pm Service R&R Rear Axle And Drum And Tires.		SLACK ADJUSTER R802486	1.00
- Install New Existing Washer.		1819452C1 OIL FILTER FRM PH7138 WIX 51799	1.00
- Replace Wood Frame To Body.		P3380 FUEL FILTER LBF FP603 WIX 33338	1.00
- Replace Front And Rear Brakes.		4"X4"X16' PRESSURE TREATED WOOD	2.00
- Replace Gasoline Pump.		5LB FIREX ABC STOCK# 340280001	1.00
		TRANS. SHIFT CABLE 2040826C3	1.00
		1822313C1 COOLANT FILTER FRM PR3907 WIX 24206	1.00
		1259 HYDR FILTER LBF FRM P1653A WIX 51259	1.00
		09997 BRAKE CLEAN	2.00
		REAR GREASE SEALS CR47697	2.00
		2-T 2" GASKET FUEL PIPING	8.00
		FREIGHT \$24.68	1.00
		FRONT BRAKE DRUMS 2007012C2	2.00
		REAR BRAKE SHOE CNB4707DQ21	2.00
		15/40 OIL	30.00
		FRONT BRAKE SHOES CNB4702DQ1	2.00
		FRONT GREASE SEALS CR35102	2.00
		SHIFT CABLE, WRONG 1 2040826C3	-1.00
		L/F LAF9545 FRM CA1596 WIX 42253 AIR FILTER	1.00
		REAR BEARING FP592A	1.00
		REAR BRAKE DRUMS 1648360C2	2.00
	<b>Parts Charge:</b> 1,662.98	<b>Labor Charge:</b> 2,182.50	<b>Commercial Charge:</b> 61.03

Workorder: 33656

Problem: (PARTS ONLY)3 TIRES.

Meter Reading: 110131	Labor	Parts	Quantity
In Date: 01/26/2000	Hours	Description	
- Parts		138802903 11R22.5 G159 11R22.5 G159	3.00
	<b>Parts Charge:</b> 842.79	<b>Labor Charge:</b> 0.00	

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 34683                      **Problem:** DIESEL NOZZLE

<b>Meter Reading:</b> 110715	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 02/14/2000	<b>Close Date:</b> 02/24/2000	<b>Hours</b>	<b>Description</b>
<hr/>			
- Po-Parts Only			FREIGHT \$175.22
			DIESEL FUEL NOZZEL 7H
	<b>Parts Charge:</b> 124.67	<b>Labor Charge:</b> 0.00	
			<b>Quantity</b>
			1.00
			1.00

**Workorder:** 34798                      **Problem:** 001 QUART OF OIL ISSUED OUT 02/08/00

<b>Meter Reading:</b> 0	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 02/08/2000	<b>Close Date:</b> 02/16/2000	<b>Hours</b>	<b>Description</b>
<hr/>			
- 001 Quart Of Oil Issued Out 02/08/00			15/40 OIL
	<b>Parts Charge:</b> 1.62	<b>Labor Charge:</b> 0.00	
			<b>Quantity</b>
			1.00

**Workorder:** 34967                      **Problem:** ELPEX, INC. T-023609

<b>Meter Reading:</b> 0	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 01/26/2000	<b>Close Date:</b> 02/23/2000	<b>Hours</b>	<b>Description</b>
<hr/>			
- Elpex, Inc. T-023609			
	<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 0.00	<b>Commercial Charge:</b> 96.00

**Workorder:** 35899                      **Problem:** REPAIR FAN

<b>Meter Reading:</b> 112233	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 03/08/2000	<b>Close Date:</b> 03/10/2000	<b>Hours</b>	<b>Description</b>
<hr/>			
- Replace Ac Fan		<b>2.00</b>	A/C BLOWER MOTOR 1699291C1
	<b>Parts Charge:</b> 85.82	<b>Labor Charge:</b> 90.00	
			<b>Quantity</b>
			1.00

**Workorder:** 36613                      **Problem:** 001 QUART OF OIL ISSUED OUT 03/20/00

<b>Meter Reading:</b> 0	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 03/20/2000	<b>Close Date:</b> 03/22/2000	<b>Hours</b>	<b>Description</b>
<hr/>			
- 001 Quart Of Oil Issued Out 03/20/00			15/40 OIL
	<b>Parts Charge:</b> 1.62	<b>Labor Charge:</b> 0.00	
			<b>Quantity</b>
			1.00

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

<b>Workorder:</b> 37934		<b>Problem:</b> 001 QUART OF OIL ISSUED OUT 03/07/00			
<b>Meter Reading:</b> 0		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 03/07/2000	<b>Close Date:</b> 04/12/2000	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	001 Quart Of Oil Issued Out 03/07/00		15/40 OIL		1.00
	<b>Parts Charge:</b> 1.62	<b>Labor Charge:</b>	0.00		
<b>Workorder:</b> 37949		<b>Problem:</b> 002 QUARTS OF OIL ISSUED OUT 04/10/00			
<b>Meter Reading:</b> 0		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 04/10/2000	<b>Close Date:</b> 04/12/2000	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	002 Quarts Of Oil Issued Out 04/10/00		15/40 OIL		2.00
	<b>Parts Charge:</b> 3.25	<b>Labor Charge:</b>	0.00		
<b>Workorder:</b> 38613		<b>Problem:</b> 002 QUARTS OF OIL ISSUED OUT 04/26/00			
<b>Meter Reading:</b> 0		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 04/26/2000	<b>Close Date:</b> 04/26/2000	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	002 Quarts Of Oil Issued Out 04/26/00		15/40 OIL		2.00
	<b>Parts Charge:</b> 3.25	<b>Labor Charge:</b>	0.00		
<b>Workorder:</b> 39046		<b>Problem:</b> 001 QUART OF OIL ISSUED OUT 05/03/00			
<b>Meter Reading:</b> 0		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 05/03/2000	<b>Close Date:</b> 05/05/2000	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	001 Quart Of Oil Issued Out 05/03/00		15/40 OIL		1.00
	<b>Parts Charge:</b> 1.62	<b>Labor Charge:</b>	0.00		
<b>Workorder:</b> 41394		<b>Problem:</b> 001 QUART OF OIL ISSUED OUT 06/15/00			
<b>Meter Reading:</b> 0		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 06/15/2000	<b>Close Date:</b> 06/20/2000	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	001 Quart Of Oil Issued Out 06/15/00		15/40 OIL		1.00
	<b>Parts Charge:</b> 1.62	<b>Labor Charge:</b>	0.00		

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 41579

**Problem:** REPAIR AC

<b>Meter Reading:</b> 119732	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 06/22/2000	<b>Hours</b>		<b>Quantity</b>
- R&R Missing Bolts From A/C Compressor. Installed New Belt.	<b>1.00</b>	3515596C1 BELT A/C INT W/DT466 ENGINE	1.00
<b>Parts Charge:</b>	16.72	<b>Labor Charge:</b>	45.00

**Workorder:** 42366

**Problem:** 001 QUART OF OIL ISSUED OUT 07/06/00

<b>Meter Reading:</b> 0	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 07/06/2000	<b>Hours</b>		<b>Quantity</b>
- 001 Quart Of Oil Issued Out 07/06/00	1.62	15/40 OIL	1.00
<b>Parts Charge:</b>	1.62	<b>Labor Charge:</b>	0.00

**Workorder:** 43702

**Problem:** 001 QUART OF OIL ISSUED OUT 08/04/00

<b>Meter Reading:</b> 0	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 08/04/2000	<b>Hours</b>		<b>Quantity</b>
- 001 Quart Of Oil Issued Out 08/04/00	1.66	15/40 OIL	1.00
<b>Parts Charge:</b>	1.66	<b>Labor Charge:</b>	0.00

**Workorder:** 43906

**Problem:** 001 QUART OF OIL ISSUED OUT 08/04/00

<b>Meter Reading:</b> 0	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 08/04/2000	<b>Hours</b>		<b>Quantity</b>
- 001 Quart Of Oil Issued Out 08/04/00	1.66	15/40 OIL	1.00
<b>Parts Charge:</b>	1.66	<b>Labor Charge:</b>	0.00

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 44029

**Problem:** WASH THE TRUCK

<b>Meter Reading:</b> 122799	<b>Labor</b>	<b>Parts</b>		
<b>In Date:</b> 08/10/2000	<b>Hours</b>		<b>Description</b>	<b>Quantity</b>
- Parts Only	<b>10.00</b>		T-4 WHITE PAINT	1.00
- Steamclean,Engine And Entire Unit.			SEAT COVER 1698721C1	1.00
- Take To Alpex Pick Up At Alpex			CAR WASH SOAP STOCK #485360104	2.00
- Po-Spare Fuel Nozzles.			FUEL NOZZLE 11AP	2.00
- Fm-To Chuck Welding.			T-1 BLACK PAINT GLOSS	1.00
			DIESEL NOZZLE 7H	2.00
			BIG G DEGREASER STOCK# 485180002	4.00
<b>Parts Charge:</b>	496.55	<b>Labor Charge:</b>	450.00	

**Workorder:** 45948

**Problem:** TIRESOLES OF BROWARD INC T031189-221-218

<b>Meter Reading:</b> 0	<b>Labor</b>	<b>Parts</b>		
<b>In Date:</b> 09/06/2000	<b>Hours</b>		<b>Description</b>	<b>Quantity</b>
- Tiresoles Of Broward Inc T031189-221-218				
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b> 1,548.07

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 46816

**Problem:** PM SERVICE

Meter Reading: 124129 In Date: 10/04/2000	Close Date: 10/26/2000	Labor Hours	Description	Parts	Quantity
- Pm Service		<b>21.50</b>	GREASE NLGI 2		1.00
- Service Transmission			15/40 OIL		30.00
- Replace Windshield Washer Tank			L/F LAF9545 FRM CA1596 WIX 42253 AIR FILTER		1.00
- Replace Gear Box; Replace Steering Box; Adjust & Test;			1819452C1 OIL FILTER FRM PH7138 WIX 51799		1.00
Hangsat Center After Long Drive; Realign And Retest			31-16 WIPER BLADES 16" WIPER BLADE		2.00
- Replace Shocks			54 RED REFLECTOR OVAL REFLECTOR		1.00
- Repair Air Leak At Fuel Delivery Controls; Replace Line &			1066 WHITE LITHIUM (CRC 05037)		1.00
Fittings			WASHER RESOVIOR 2033902C91		1.00
- Repair Pto On Light; R&R Fuse Box; Install Socket & Ball			P/S GEAR BOX ZRXM100PCL		1.00
- Parts Only-Spare Fuel Nozzle			61A P/STEERING FLUID		3.00
			SHOCKS, AMS600129		2.00
			SHOCKS, 472412C91		2.00
			11AP, GAS NOZZLE		2.00
			7H, DIESEL NOZZLE		2.00
			ATFD TRANS FLUID MERCON V		18.00
			FT1051A TRANS FILTER LBF T153 WIX 58892		1.00
			P3380 FUEL FILTER LBF FP603 WIX 33338		1.00
			P/S FILTER HF6162		1.00
			1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
	<b>Parts Charge:</b>	1,569.91	<b>Labor Charge:</b>	967.50	

**Workorder:** 48102

**Problem:** REPAIR LIGHTS ON LIGHT BAR

Meter Reading: 125040 In Date: 11/01/2000	Close Date: 11/03/2000	Labor Hours	Description	Parts	Quantity
- Replace Outer Bulb In Beacon Rotator (Both Sides)		<b>1.00</b>	701-D/H1 BULB WAGNER 1255/H1		2.00
Note:-Housing Broken At Rt Side Lens Retainer.					
	<b>Parts Charge:</b>	12.93	<b>Labor Charge:</b>	45.00	

**Workorder:** 49143

**Problem:** AIR LINE

Meter Reading: 125723 In Date: 11/21/2000	Close Date: 11/27/2000	Labor Hours	Description	Parts	Quantity
- Repair Air Line To Auto Shutdown Diesel Loading.		<b>0.50</b>			
	<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	22.50	

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 50245

**Problem:** REPLACE THE FUEL PUMP APS DIESEL

Meter Reading: 126549 In Date: 12/18/2000	Close Date: 02/26/2001	Labor Hours	Description	Parts	Quantity
-	Checked Sys Op Checked Valve Op R&R Pump Assembly. Repaired Leak.	47.50	GASKET,AIR COMP. 1818727C1		1.00
-	Install Fuel Drains.		12105 QUICK DRAIN (USE ALSO 12104)		3.00
-	Air Tanks Full Of Oil Replace Compressor(R&R New Compressor Crank Left To Cut Key Shot) & Governor.		PTO IND. SWITCH 379639		1.00
-	Pto Lite Stays On At Times Order Switch.		FREIGHT		1.00
-	Won'T Hold Air Diaphragm Blown Out @ Diesel Vent.Rebuild Valve Try To Rebuild Solve On Shelf		FREIGHT,PTO SWITCH		1.00
-	Cont.Drill Out Old Screen.		SP3971 MTRCRFT FW16 COOLANT ADDITIVE WIX24056		1.00
-	Pick Parts At Fort Lauderdale.		GASKET,AIR COMP. 591597C2		1.00
-	Service Cooling System.		275491X GOVENOR D2 (BENDIX)		1.00
-	Performance Ck Ac 38 Deg. In Shop N.P.F. Advised Operator Tobring To Shop When Problem Is Present.		CYL HEAD GASKET,AIR COMP. 298715		1.00
			GREEN ANTIFREEZE STOCK #060030002		3.00
			FREIGHT,FUEL PUMP		1.00
			DIAPHRAM 17212HD		2.00
			AIR COMPRESSOR 5004613X		1.00
			SEAL KIT,AIR COMP 107969		1.00
			FUEL PUMP TXD2		1.00
			FUEL PUMP TXD2		1.00
	<b>Parts Charge:</b> 4,066.02	<b>Labor Charge:</b> 2,137.50	<b>Commercial Charge:</b> 275.83		

**Workorder:** 137058

**Problem:** REPAIR LIGHTS

Meter Reading: 128784 In Date: 04/03/2001	Close Date: 04/13/2001	Labor Hours	Description	Parts	Quantity
-	Parts Only	6.50	W/W RES 2033902C91		1.00
-	Parts Only		LIGHT LENS LH 1661761C93		1.00
-	Pm Service.		LIGHT LENS RH 1661762C93		1.00
-	W/S Washer Reservoir Leaks, Replaced.		15/40 OIL		30.00
			1819452C1 OIL FILTER FRM PH7138 WIX 51799		1.00
			P3380 FUEL FILTER LBF FP603 WIX 33338		1.00
			1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
			31-16 WIPER BLADES 16" WIPER BLADE		2.00
			GREEN ANTIFREEZE STOCK #060030002		1.00
	<b>Parts Charge:</b> 167.89	<b>Labor Charge:</b> 292.50	<b>Commercial Charge:</b> 153.08		



5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 137307

**Problem:** NEEDS SMALLER DIA PICK UP TUBE ON SUCTION PUMP.

<b>Meter Reading:</b> 128916		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 04/05/2001	<b>Close Date:</b> 04/09/2001	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Fleet Mgt. To Ace Hardware, Pahokee & Back.	<b>1.80</b>	PVC PIPE 1 1/4"		1.00
-	Fabricate & Install 1 1/4" Pvc Tube & Attach To Pick Up Tubefor Fuel Recovery Pump On Tanker.		COUPLER		1.00
<b>Parts Charge:</b>		6.52	<b>Labor Charge:</b>	81.00	

**Workorder:** 137662

**Problem:** REPAIR LIGHTS

<b>Meter Reading:</b> 129195		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 04/12/2001	<b>Close Date:</b> 04/24/2001	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Flasher Bad R&R Flasher. Wiring Burned Repaired Wiring Behindinstrument Panel.	<b>3.00</b>	MIRROR KIT ZEESA110		1.00
-	Po-Mirror-Parts Only		T/L 97804 8" BLACK SPOT GROTE # 12182 BLACK 3157 TAIL LIGHT BULBS 44530 FLASHER 12 VOLT 2 PRONG (GROTE)		1.00 1.00 2.00
<b>Parts Charge:</b>		117.94	<b>Labor Charge:</b>	135.00	

**Workorder:** 139666

**Problem:** DEAD BATTERY

<b>Meter Reading:</b> 129566		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 05/15/2001	<b>Close Date:</b> 05/23/2001	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Jump Start, Test Batt. Replace Batteries.	<b>1.00</b>	HP31D BATTERY GROUP 31 STUD		2.00
<b>Parts Charge:</b>		138.20	<b>Labor Charge:</b>	45.00	

**Workorder:** 140528

**Problem:** REPAIR STROBE LIGHT

<b>Meter Reading:</b> 129656		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 05/30/2001	<b>Close Date:</b> 06/01/2001	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Ck For Power To Module. Traced Leads Under Cab. Opened Harness By Trims, Repaired Open.	<b>3.50</b>			
<b>Parts Charge:</b>		0.00	<b>Labor Charge:</b>	157.50	

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 141291                      **Problem:** 002 QUARTS OF OIL ISSUED OUT 06/07/01

Meter Reading: 0	Labor	Parts	
In Date: 06/07/2001	Hours	Description	Quantity
- 002 Quarts Of Oil Issued Out 06/07/01	15/40	OIL	2.00
<b>Parts Charge:</b> 3.65	<b>Labor Charge:</b> 0.00		

**Workorder:** 141897                      **Problem:** REPAIR LIGHTS

Meter Reading: 130727	Labor	Parts	
In Date: 06/22/2001	Hours	Description	Quantity
- Replace Directional Switch.	17.00	3157 TAIL LIGHT BULBS	2.00
- Ck A/C For Leaks Charge Sys.Repl Comprssor		CLEAR LENS 920048	6.00
Dryer.Xvalve Evacuate & Recharge Modify Relay Wiring		CLUTCH 1687780C2	1.00
Per Xvalve Directions.(Order Parts)		A/C HOSE DRYER TOEXP VLV 2027246C91	1.00
- Install Strobe Lights.		20 FT CABLE LD-20	2.00
- Airleak Can'T Load Unread Replace Hose @ Bottom Tank Valve.		DRYER 1693117C1	1.00
		80865 FUSEHOLDER IMPERIAL 80865	1.00
		S660CCCC STROBE KIT 4 HEAD KIT	1.00
		EXP VALVE 2503783C91	1.00
		DIRECTIONAL SWITCH 1699606C91	1.00
		80865 FUSEHOLDER IMPERIAL 80865	1.00
		COMPRESSOR 2502459C91	1.00
		MIR4070 W/COAST MIRROR (INTERNATIONAL)	1.00
		DS-167 TOGGLE SWITCH (STANDARD)	1.00
		353873S GROMMET FORD TRACTORS	2.00
		CLEAR LENS 920048	-6.00
<b>Parts Charge:</b> 1,465.74	<b>Labor Charge:</b> 765.00		

**Workorder:** 142148                      **Problem:** 001 QUART OF OIL ISSUED OUT 06/21/01

Meter Reading: 0	Labor	Parts	
In Date: 06/21/2001	Hours	Description	Quantity
- 001 Quart Of Oil Issued Out 06/21/01	15/40	OIL	1.00
<b>Parts Charge:</b> 1.86	<b>Labor Charge:</b> 0.00		

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 147337                      **Problem:** TAKE TO RADIO SHOP

Meter Reading: 132227	Labor	Parts	Quantity
In Date: 09/25/2001	Hours	Description	
- Fm-Radio Shop	<b>1.00</b>		
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	45.00

**Workorder:** 147779                      **Problem:** REPAIR THE LIGHTS

Meter Reading: 132227	Labor	Parts	Quantity
In Date: 10/01/2001	Hours	Description	
- Repair Lights.	<b>0.50</b>	3157 TAIL LIGHT BULBS	1.00
- Po-Cones.			
<b>Parts Charge:</b>	0.87	<b>Labor Charge:</b>	25.00

**Workorder:** 148452                      **Problem:** RESEAL THE REAR DOORS

Meter Reading: 132408	Labor	Parts	Quantity
In Date: 10/15/2001	Hours	Description	
- Reseal Doors	<b>22.00</b>	09997 BRAKE CLEAN	1.00
- Pm Service		15/40 OIL	30.00
- R&R Alt.		L/F LAF9545 FRM CA1596 WIX 42253 AIR FILTER	1.00
- R&R Wipers & Washer Jug.		1259 HYDR FILTER LBF FRM P1653A WIX 51259	1.00
- R&R Belts.		P3380 FUEL FILTER LBF FP603 WIX 33338	1.00
- Rear Diff Serv		31-16 WIPER BLADES 16" WIPER BLADE	2.00
- Drain & Refill Trans		WEATHERSTRIP 9-1493	2.00
- Broken Grease Fiting On Pto Drive Shaft U-Joint.R&R Old		1841575C1 BELT INT 4700 W/DT466 ENGINE	1.00
Fitting & Install New Fitting.		WASHER RESOVIOUR 2033902C92	1.00
- Diag And Repair Airleaks.		1822313C1 COOLANT FILTER FRM PR3907 WIX 24206	1.00
		85/140 GEAR OIL GEAR LUBE	40.00
		ATFD TRANS FLUID MERCON V	16.00
		ALTERNATOR 10459013	1.00
		GREASE NLGI 2	2.00
		3515596C1 BELT A/C INT W/DT466 ENGINE	1.00
		USED FIREX REFURBED FIRE EXTINGSHERS	2.00
		1819452C1 OIL FILTER FRM PH7138 WIX 51799	1.00
		5LB FIREX ABC STOCK# 340280001	1.00
<b>Parts Charge:</b>	597.44	<b>Labor Charge:</b>	1,100.00

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 150630                      **Problem:** 001 QUART OF OIL ISSUED OUT 11/21/01

Meter Reading: 0	Labor	Parts	
In Date: 11/21/2001	Hours	Description	
Close Date: 11/26/2001		Quantity	
- 001 Quart Of Oil Issued Out 11/21/01	15/40	OIL	1.00
<b>Parts Charge:</b> 1.76	<b>Labor Charge:</b> 0.00		

**Workorder:** 151335                      **Problem:** REPAIR DIESEL PUMP

Meter Reading: 133550	Labor	Parts	
In Date: 12/06/2001	Hours	Description	
Close Date: 12/14/2001		Quantity	
- Removed Valve Assembly & Disassemble R&R Strainer	4.60		
- Fm-To Chucks			
<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 230.00	<b>Commercial Charge:</b> 266.35	

**Workorder:** 234335                      **Problem:** STEVE'S TOWING INC. 109058

Meter Reading: 0	Labor	Parts	
In Date: 02/05/2002	Hours	Description	
Close Date: 02/05/2002		Quantity	
- Steve'S Towing Inc. 109058 Tow From Boca Pit - Tow To			
<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 0.00	<b>Commercial Charge:</b> 62.40	

**Workorder:** 235945                      **Problem:** FLOOR MATS

Meter Reading: 136318	Labor	Parts	
In Date: 03/07/2002	Hours	Description	
Close Date: 03/27/2002		Quantity	
- Replace Floor Mats.	4.50	MAT SET 9-2669	1.00
- Hd Lights Out.Ck Wiring To Light.Pulled Id To Access		SWITCH 1661234C3	1.00
Relays Ck Relays & High Beam Switch.Ck Switch			
Op.Repair Leads R&R Switch.			
- R&R Bass Fuell Hose Connector.			
<b>Parts Charge:</b> 62.63	<b>Labor Charge:</b> 225.00		

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 237675                      **Problem:** 001 QUART OF OIL ISSUED OUT 03/26/02

Meter Reading: 0	Labor	Parts	
In Date: 03/26/2002	Hours	Description	Quantity
- 001 Quart Of Oil Issued Out 03/26/02	15/40	OIL	1.00
<b>Parts Charge:</b> 1.86	<b>Labor Charge:</b> 0.00		

**Workorder:** 237678                      **Problem:** 001 QUART OF OIL ISSUED OUT 03/28/02

Meter Reading: 0	Labor	Parts	
In Date: 03/28/2002	Hours	Description	Quantity
- 001 Quart Of Oil Issued Out 03/28/02	15/40	OIL	1.00
<b>Parts Charge:</b> 1.86	<b>Labor Charge:</b> 0.00		

**Workorder:** 238717                      **Problem:** PM SERVICE

Meter Reading: 137777	Labor	Parts	
In Date: 04/17/2002	Hours	Description	Quantity
- Repl Aps Gas Pump.Cleaned Strainer.Note:Gaskets On New Pump Already Torqued.No Other Gaskets Avail.Reused Gaskets As Per Russ White.	40.50	L/F LAF9545 FRM CA1596 WIX 42253 AIR FILTER	1.00
- Pm Serv.		15/40 OIL	30.00
- Order New Drive Shaft For Pto To Gasoling Pump.Remv/Clean Fomeasurements Shaft U-Joint Showing Signs Of Wear Excessive Free Play.		P3380 FUEL FILTER LBF FP603 WIX 33338	1.00
- R&R Wipers		PUMP,FUEL TXD2A	1.00
- Steam Wash.		31-16 WIPER BLADES 16" WIPER BLADE	2.00
- Trace/Repair Airleak On 1/4" Hose On Top Of Tank @ Gas Floatvalve.Hose Was Flattened & Had Small Split.		BIG G DEGREASER STOCK# 485180002	4.00
- R&R Dash Light Bulbs & Dash To Gain Access.Repair Pto Engagelight,Bulb Blown,Fuse Blown & Wire Grounded.		80865 FUSEHOLDER IMPERIAL 80865	1.00
- Ordered Foot Valve-Airleak.R&R Foot Valve-Had To Measure & Reset Fittings To Get Airlines Hooked Up Properly.Front Valve Defective Test		1819452C1 OIL FILTER FRM PH7138 WIX 51799	1.00
- Get Part From Hydraulic Supply.		54 RED REFLECTOR OVAL REFLECTOR	1.00
- R&R Belt Tensioner For Main Serp Belt.		1259 HYDR FILTER LBF FRM P1653A WIX 51259	1.00
		TENSIONER 1830033C1	1.00
		1/4"SYNFLEX C604BK	60.00
		VALVE BX101818	1.00
		FITTING 269X10	1.00
		1822313C1 COOLANT FILTER FRM PR3907 WIX 24206	1.00
		CAR WASH SOAP STOCK #485360104	2.00
<b>Parts Charge:</b> 2,206.42	<b>Labor Charge:</b> 2,025.00		

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 240297                      **Problem:** REPAIR FUEL HOSE

Meter Reading: 138307	Labor	Parts	
In Date: 05/13/2002	Hours	Description	Quantity
- Repair Fuel Hose.	3.50	56521 THREAD SEALANT HI TEMP THREAD SEALANT	1.00
- Hyd Supply And Back.		FITTING 2081-20-16S	1.00
<b>Parts Charge:</b> 19.50	<b>Labor Charge:</b> 175.00	<b>Commercial Charge:</b> 17.39	

**Workorder:** 241016                      **Problem:** 001 QUART OF OIL ISSUED OUT 05/20/02

Meter Reading: 0	Labor	Parts	
In Date: 05/20/2002	Hours	Description	Quantity
- 001 Quart Of Oil Issued Out 05/20/02		15/40 OIL	1.00
<b>Parts Charge:</b> 1.90	<b>Labor Charge:</b> 0.00		

**Workorder:** 241195                      **Problem:** FAN MOTOR

Meter Reading: 138935	Labor	Parts	
In Date: 05/29/2002	Hours	Description	Quantity
- R&R Blower Repair Wiring	11.50	BLWR MTR 1699291C1	1.00
- Gasoline Meter Leaks Parts Ordered Replace Meter		METER M5K1	1.00
<b>Parts Charge:</b> 5,324.98	<b>Labor Charge:</b> 575.00		

**Workorder:** 243824                      **Problem:** FIRE EXT.

Meter Reading: 139298	Labor	Parts	
In Date: 07/11/2002	Hours	Description	Quantity
- Fire Ext.	0.50	T-1 BLACK PAINT GLOSS	1.00
		USED FIREX REFURBED FIRE EXTINGSHERS	2.00
		10 LB FIRE EXTINGUISHER 340280004	1.00
<b>Parts Charge:</b> 95.32	<b>Labor Charge:</b> 25.00		

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 245501                      **Problem:** REPAIR THE LIGHTS

Meter Reading: 139498	Labor	Parts		
In Date: 08/07/2002	Hours	Description	Quantity	
- Replace Rr Marker Lens.	6.30	LENS 920116	2.00	
- Removed Counter Fr Gasoline Meter For Repair.Install Counterand Test.				
<b>Parts Charge:</b>	7.19	<b>Labor Charge:</b>	315.00	

**Workorder:** 247605                      **Problem:** REPAIR REAR DOOR

Meter Reading: 139921	Labor	Parts		
In Date: 09/10/2002	Hours	Description	Quantity	
- Po Dispenser Pump		BUNGIE CORD STOCK# 450240010	1.00	
		H200134 HYD PUMP LUBE TRK MAINTAINER 800 831-8588	1.00	
		GAS SHOCK	2.00	
		PULL RING	30.00	
		H200134 HYD PUMP LUBE TRK MAINTAINER 800 831-8588	-1.00	
<b>Parts Charge:</b>	161.65	<b>Labor Charge:</b>	0.00	

**Workorder:** 248920                      **Problem:** REAR DOOR SHOCKS

Meter Reading: 140476	Labor	Parts		
In Date: 10/01/2002	Hours	Description	Quantity	
- R&R Door Shocks.	1.00	FRT STRUTS	1.00	
- P.O.- Pull Rings. Parts Only.		STRT AVM100-150-MEWS	2.00	
		T-4 WHITE PAINT	2.00	
		REAR DOOR SHOCKS 777-7251	2.00	
		PULL RING R200SS	30.00	
<b>Parts Charge:</b>	307.69	<b>Labor Charge:</b>	50.00	

**Workorder:** 250877                      **Problem:** TIRESOLES OF BROWARD INC T054312/T054280

Meter Reading: 0	Labor	Parts		
In Date: 10/18/2002	Hours	Description	Quantity	
- Tiresoles Of Broward Inc T054312/T054280				
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b> 516.62

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 252956

**Problem:** PM SERVICE

<b>Meter Reading:</b> 142486		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 12/10/2002	<b>Close Date:</b> 12/18/2002	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Pm Service		<b>8.50</b>	15/40 OIL		30.00
- Trans Service			P3380 FUEL FILTER LBF FP603 WIX 33338		1.00
- Performance Test.			1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
			1822313C1 COOLANT FILTER FRM PR3907 WIX 24206		1.00
			KATHON PRESERVITIVE DIESEL FUEL 1.5 MICRBCIDE		2.00
			ATFD TRANS FLUID MERCON V		16.00
			09997 BRAKE CLEAN		1.00
			FT1051A TRANS FILTER LBF T153 WIX 58892		1.00
			1819452C1 OIL FILTER FRM PH7138 WIX 51799		1.00
<b>Parts Charge:</b> 136.68		<b>Labor Charge:</b> 425.00			

**Workorder:** 332239

**Problem:** REPLACE APS FUEL METER

<b>Meter Reading:</b> 142785		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 01/03/2003	<b>Close Date:</b> 01/30/2003	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Po			BUSHING 4110-32-24		1.00
			FUEL METER M5K1		1.00
			KAMLOCK A200		1.00
<b>Parts Charge:</b> 5,409.77		<b>Labor Charge:</b> 0.00	<b>Commercial Charge:</b> 1,107.08		

**Workorder:** 334048

**Problem:** APS FUEL METER

<b>Meter Reading:</b> 143054		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 02/04/2003	<b>Close Date:</b> 02/12/2003	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Install Meter. Clean Screening And Test.		<b>6.00</b>			
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 300.00	<b>Commercial Charge:</b> 352.32		



5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 335324                      **Problem:** FUEL TANK LEAKING

Meter Reading: 144060	Labor	Parts	
In Date: 02/26/2003	Hours	Description	Quantity
- R&R Seat Belt. Replace Lf Seat Belt.Note:Dt466 Vibrates & Locks Retractor.Raise Rrm Slightly To Release Belt.	12.50	SEATBELT 1684505C3	1.00
- Fm Chucks Welding.		ALUM.TUBE 8876-1224C 12"X24"	1.00
- Check Ac 48Deg.		ALUM.TUBE 8876-1224C 12"X24"	-1.00
- Or Pot Inspection On Fuel Tank And Repair At Chucks Welding		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Dot Inspetion And Repair		WEAR LINER 45230020B	-2.00
		WEAR LINER 45230020B	2.00
<b>Parts Charge:</b> 168.77		<b>Labor Charge:</b> 625.00	<b>Commercial Charge:</b> 1,080.00

**Workorder:** 336947                      **Problem:** FUEL LEAK ON APS AND REPAIR LIGHTS

Meter Reading: 144463	Labor	Parts	
In Date: 03/21/2003	Hours	Description	Quantity
- Remove Fuse Panel Repair Conn. For Flashers	6.50	15/40 OIL	3.00
- Repair Emergency Flashers		44530 FLASHER 12 VOLT 2 PRONG (GROTE)	1.00
- Repair Fuel Swivel Coupling. Order Parts, Rr Sivel Coupling.			
- Add Oil.			
<b>Parts Charge:</b> 15.76		<b>Labor Charge:</b> 325.00	

**Workorder:** 339053                      **Problem:** REOLACE HEAD LIGHT

Meter Reading: 245213	Labor	Parts	
In Date: 04/22/2003	Hours	Description	Quantity
- R&R Right Headlight.	0.50	H6054 SEALED BEAM	1.00
<b>Parts Charge:</b> 11.14		<b>Labor Charge:</b> 25.00	

**Workorder:** 339574                      **Problem:** WEATHER GUARD BOX

Meter Reading: 145538	Labor	Parts	
In Date: 04/30/2003	Hours	Description	Quantity
- Install Box	1.00	CUP HOLDER 8860-3	1.00
		FILE BOX 8861-3	1.00
<b>Parts Charge:</b> 202.08		<b>Labor Charge:</b> 50.00	

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 340257

**Problem:** REPAIR THE DIESEL PUMP

<b>Meter Reading:</b> 146000	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 05/09/2003	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Diesel Won'T Pump,Repl Pump & Meter.Gas Meter Skips	<b>19.00</b>	FRT,SWIVELS	1.00
Replace Meter,Gas Swivel Leak Replace Seal Order New Swivel		SWIVEL, APS FUEL REEL 9930.4610	2.00
- Replace Gasoline Reel Swivel			
<b>Parts Charge:</b> 647.87	<b>Labor Charge:</b> 950.00		

**Workorder:** 342787

**Problem:** THROTTLE LINKAGE

<b>Meter Reading:</b> 147297	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 06/19/2003	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Machined Throttle Linkage Using Spare Parts I Had On Truck. Order New Parts Installed.	<b>3.50</b>	BALL 398000C1	1.00
- Hooper Road And Back		SHOP SUPPLIES	1.00
- R/R Wipers		CABLE 2010529C91	1.00
- Shop Supplies		31-16 WIPER BLADES 16" WIPER BLADE	2.00
<b>Parts Charge:</b> 89.76	<b>Labor Charge:</b> 175.00		

**Workorder:** 343042

**Problem:** FUEL APS

<b>Meter Reading:</b> 147527	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 06/25/2003	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Gasoline Over Fill Doesn'T Work. Order Product Sensor	<b>6.00</b>	FRT,SENSOR	1.00
Install Sensor,Doesn'T Work On Diesel Or Gas Called		15/40 OIL	1.00
Dilman Will Send Sensor		SENSOR 801000200	1.00
<b>Parts Charge:</b> 1,389.41	<b>Labor Charge:</b> 300.00		

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 346397

**Problem:** PM SERVICE

Meter Reading: 149003	Labor	Parts	Quantity
In Date: 08/21/2003	Hours	Description	
- Pm	<b>12.50</b>	L/F LAF9545 FRM CA1596 WIX 42253 AIR FILTER	1.00
- No Signals Or Flashers Repair Top Clearence Lights		P3380 FUEL FILTER LBF FP603 WIX 33338	1.00
- Install Flasher In Remote Locationm Repair Pto Light		1822313C1 COOLANT FILTER FRM PR3907 WIX 24206	1.00
- Repair Driver Seat Install New Cushion And Cover Clean		44530 FLASHER 12 VOLT 2 PRONG (GROTE)	1.00
- Up Airlines		ATFD TRANS FLUID MERCON V	1.00
- Performance Test Vehicle		SEAT COVER 1698721C1	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		SEAT PAD 1698424C1	1.00
		1259 HYDR FILTER LBF FRM P1653A WIX 51259	1.00
		1819452C1 OIL FILTER FRM PH7138 WIX 51799	1.00
		15/40 OIL	30.00
		31-16 WIPER BLADES 16" WIPER BLADE	2.00
<b>Parts Charge:</b> 288.67		<b>Labor Charge:</b> 625.00	

**Workorder:** 347760

**Problem:** WATER PUMP

Meter Reading: 149444	Labor	Parts	Quantity
In Date: 09/12/2003	Hours	Description	
- R/R Water Pump	<b>5.00</b>	1830606C95 WATER PUMP INTERNATIONAL	1.00
- Truck Towed In Drive Shaft Dropped Clean Spines And		GREEN ANTIFREEZE STOCK #060030002	2.00
- Install		GREEN ANTIFREEZE STOCK #060030002	1.00
- Performance Test Truck		SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b> 174.79		<b>Labor Charge:</b> 250.00	

**Workorder:** 347792

**Problem:** 1 800 AUTO TOW FLORIDA INC 135176

Meter Reading: 0	Labor	Parts	Quantity
In Date: 09/11/2003	Hours	Description	
- 1 800 Auto Tow Florida Inc 135176 Tow From Forest Hill Blvd, Just East Of Jog Road - Tow To (Walmart Shopping Center)			
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 0.00	
		<b>Commercial Charge:</b> 120.00	

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

<b>Workorder:</b> 348461		<b>Problem:</b> REPLACE REAR TIRES			
<b>Meter Reading:</b> 10829		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 09/23/2003	<b>Close Date:</b> 09/23/2003	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
<hr/>					
-	Clean Rear Rims For Elpex Tire Replacement	<b>1.00</b>			
	<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b>	50.00		
<b>Workorder:</b> 349161		<b>Problem:</b> REPAIR FLASHERS			
<b>Meter Reading:</b> 150226		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 10/03/2003	<b>Close Date:</b> 10/08/2003	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
<hr/>					
-	Replace Flasher And Repair Connectors.	<b>1.00</b>	44530 FLASHER 12 VOLT 2 PRONG (GROTE)		1.00
	<b>Parts Charge:</b> 13.65	<b>Labor Charge:</b>	50.00		
<b>Workorder:</b> 349371		<b>Problem:</b> AC			
<b>Meter Reading:</b> 150398		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 10/07/2003	<b>Close Date:</b> 10/20/2003	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
<hr/>					
-	No Ac @ Times Ok In Shop Replace Ignition Switch.	<b>1.50</b>	IGN SW 468438C91		2.00
	<b>Parts Charge:</b> 40.05	<b>Labor Charge:</b>	75.00		
<b>Workorder:</b> 349527		<b>Problem:</b> REPLACE APS DIESEL PUMP			
<b>Meter Reading:</b> 150226		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 10/08/2003	<b>Close Date:</b> 10/27/2003	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
<hr/>					
-	Aps Diesel Pump Replace	<b>14.00</b>	EX VLV 2503783C91		1.00
-	Order Parts.Replace Ac Compressor,Expansion Valve,Receiver Drier,Evacuate,Vacuum,Recharge Sys.		DRIER 1693117C1		1.00
			COMP 2509451C91		1.00
-	Checked Power To Clutch From Switch.Checked Connection At Switch.				
-	Won'T Draft Diesel Replace Airlines.				
	<b>Parts Charge:</b> 493.94	<b>Labor Charge:</b>	700.00		

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 349627                      **Problem:** TIRESOLES OF BROWARD INC T063255/T063443

Meter Reading: 0	Labor	Parts
In Date: 09/23/2003	Hours	Description
Close Date: 10/09/2003		Quantity
- Tiresoles Of Broward Inc T063255/T063443		
<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 0.00	<b>Commercial Charge:</b> 900.96

**Workorder:** 350779                      **Problem:** ADD OIL

Meter Reading: 150973	Labor	Parts
In Date: 10/29/2003	Hours	Description
Close Date: 10/31/2003		Quantity
- Check Engine Oil And Replaced	0.50	15/40 OIL
<b>Parts Charge:</b> 3.37	<b>Labor Charge:</b> 25.00	2.00

**Workorder:** 351232                      **Problem:** APS FUEL PUMPS

Meter Reading: 151353	Labor	Parts
In Date: 11/06/2003	Hours	Description
Close Date: 12/02/2003		Quantity
- Po	1.00	APS FUEL PUMP TXD2A 2" VANE PUMP
- Install Shocks To Tail Gate.		
<b>Parts Charge:</b> 2,215.20	<b>Labor Charge:</b> 50.00	2.00

**Workorder:** 432430                      **Problem:** APS GAS PUMP

Meter Reading: 153030	Labor	Parts
In Date: 01/06/2004	Hours	Description
Close Date: 02/10/2004		Quantity
- Replace Gas Pump (Product Pump)Put 450 Gal From Tank #4 Intofront Compartment	5.00	PUMP TXD2A
<b>Parts Charge:</b> 1,430.65	<b>Labor Charge:</b> 250.00	1.00

**Workorder:** 437363                      **Problem:** HEAD LIGHT

Meter Reading: 155662	Labor	Parts
In Date: 03/09/2004	Hours	Description
Close Date: 03/19/2004		Quantity
- R&R Headlight.	2.00	H6054 SEALED BEAM
- Touch Up Point.		T-29 YELLOW PAINT SCHOOL BUS
<b>Parts Charge:</b> 18.04	<b>Labor Charge:</b> 100.00	1.00

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 440470

**Problem:** REPLACE FIRE EXT.

Meter Reading: 156672	Labor	Parts	Quantity
In Date: 04/06/2004	Hours	Description	Quantity
- Replace Fire Ext.	13.50	15/40 OIL	2.00
- Add Oil		S30HACP STROBE BULB FOR KIT S660CCCC	3.00
- Repair Short In Wire Harness To Lights Top Repair Strobe Lights.Replace Control Box & Bulbs		S30HACP STROBE BULB FOR KIT S660CCCC	-2.00
- Pm Service		S660CCCC STROBE KIT 4 HEAD KIT	1.00
- Steam Clean Truck		S30HACP STROBE BULB FOR KIT S660CCCC	-2.00
		BUSHING 3"X1"	4.00
		15/40 OIL	30.00
		L/F LAF9545 FRM CA1596 WIX 42253 AIR FILTER	1.00
		CAMLOCK 3" 30AAL	4.00
		COUPLER 10DAL	6.00
		SLACK ADJ R803201	1.00
		1259 HYDR FILTER LBF FRM P1653A WIX 51259	1.00
		31-16 WIPER BLADES 16" WIPER BLADE	2.00
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		RES 2033902C92	1.00
		P3380 FUEL FILTER LBF FP603 WIX 33338	1.00
		15/40 OIL	2.00
		CRANK 1649776C1	1.00
		SLACK ADJ 1694294C91	1.00
		ATFD TRANS FLUID MERCON V	16.00
		1819452C1 OIL FILTER FRM PH7138 WIX 51799	1.00
		FT1051A TRANS FILTER LBF T153 WIX 58892	1.00
		S30HACP STROBE BULB FOR KIT S660CCCC	1.00
	<b>Parts Charge:</b> 1,111.15	<b>Labor Charge:</b> 675.00	

**Workorder:** 447719

**Problem:** FUEL COUPLING

Meter Reading: 158507	Labor	Parts	Quantity
In Date: 06/14/2004	Hours	Description	Quantity
- Fuel Couplings			
	<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 0.00	<b>Commercial Charge:</b> 22.25

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 451365

**Problem:** REPAIR AC

<b>Meter Reading:</b> 158770		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 07/20/2004	<b>Close Date:</b> 08/16/2004	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Ac Comp. Acc Expanion Valve	<b>9.50</b>	LINE H/S 3521728C1		1.00
-	Replace Diaphragm @ Diesel Vent Valve Will Need Piston & Retainer & Screws Nest Time (Or New Valve)		SWITCH 3521728C1		1.00
			EX VLV 2503783C91		1.00
			DIAPHRAM KIT 17212HD		2.00
			COMP 2509451C91		1.00
			ACCUM 1693117C1		1.00
<b>Parts Charge:</b> 896.16		<b>Labor Charge:</b> 475.00			

**Workorder:** 453242

**Problem:** DIESEL FUEL LEAK

<b>Meter Reading:</b> 159012		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 08/06/2004	<b>Close Date:</b> 08/25/2004	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Temperature Repairs To Diesel Air Bleed Tank Vent Assy.	<b>3.00</b>			
-	Truck Won'T Pump Fuel. Check All Controls & Valves				
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 150.00			

**Workorder:** 455316

**Problem:** NO START

<b>Meter Reading:</b> 159034		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 08/26/2004	<b>Close Date:</b> 08/30/2004	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	R/R Batteries,Clean Tray, Check Charging System, Clean All Contacts	<b>2.00</b>	BAATTERY 31-900CT		1.00
-	Repair L/R Marker				
<b>Parts Charge:</b> 270.72		<b>Labor Charge:</b> 100.00			

**Workorder:** 455762

**Problem:** MAKE UP ADAPTER FOR FUEL HOSES

<b>Meter Reading:</b> 159035		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 08/31/2004	<b>Close Date:</b> 09/22/2004	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Make Up Coupler & Test For Leaks	<b>1.50</b>	COUPLER DX200AAL		2.00
-	Pick Up Parts In Belle Glade		NIPPLES 41680		1.00
<b>Parts Charge:</b> 32.44		<b>Labor Charge:</b> 75.00			

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 455972

**Problem:** NO START

<b>Meter Reading:</b> 159731		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 09/10/2004	<b>Close Date:</b> 09/21/2004	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Starter Doesn'T Always Engage,Replace Button Switch & Relay	1.00	SW,START 2007844C2		1.00
			RELAY 1678120C1		1.00
	<b>Parts Charge:</b> 89.67	<b>Labor Charge:</b> 50.00			

**Workorder:** 456618

**Problem:** APS FUEL SYSTEM

<b>Meter Reading:</b> 159057		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 09/16/2004	<b>Close Date:</b> 09/21/2004	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Replace Air Eliminator.	2.00			
	<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 100.00			

**Workorder:** 461224

**Problem:** 002 QUARTS OF OIL ISSUED OUT 09/07/04

<b>Meter Reading:</b> 0		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 09/07/2004	<b>Close Date:</b> 11/08/2004	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	002 Quarts Of Oil Issued Out 09/07/04		15/40 OIL		2.00
	<b>Parts Charge:</b> 3.72	<b>Labor Charge:</b> 0.00			



5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 463617

**Problem:** PM SERVICE

Meter Reading: 160110 In Date: 12/06/2004	Close Date: 01/07/2005	Labor Hours	Parts	Description	Quantity
- P M Service		17.50		FP603 FUEL FILTER USE FRM P3380	1.00
- R & R Wiper Blades And Fire Ext.				1819452C1 OIL FILTER FRM PH7138 WIX 51799	1.00
- Drain Fuel Tank Remove Fuel Tank Transfer All Fittings And Sending Unit Install Tank And Hoses Fill Tank And Run Unit				15/40 OIL	30.00
				CA1596 AIR FILTER LBF LAF9545 WIX 42253	1.00
				ATFD TRANS FLUID MERCON V	2.00
- R & R Dashboard Replace High Beam Indicator Bulb				DRUM 3600A	2.00
- Rear Brakes Remove Rear Tire And Wheels Remove Rear Drums R&R Rear Brake Shoes,Hardware,& Bushings Install Drums Instal Rear Tires&Wheel				31-16 WIPER BLADES 16" WIPER BLADE	2.00
				USED FIREX REFURBED FIRE EXTINGSHERS	1.00
				SCREEN 1825181C91	1.00
				TANK 1661790C92	1.00
				KIT MKT4515QHD	2.00
				1259 HYDR FILTER LBF FRM P1653A WIX 51259	1.00
				SHOE REXP4707Q	4.00
	<b>Parts Charge:</b> 1,519.35		<b>Labor Charge:</b> 875.00		

**Workorder:** 538067

**Problem:** LIGHTS

Meter Reading: 160671 In Date: 03/04/2005	Close Date: 05/04/2005	Labor Hours	Parts	Description	Quantity
- Directional Switch,Check And Replace.		5.50		H6054 SEALED BEAM	1.00
- Air Valve.Repair Pump.Order 3/4/05				1X1 ELBOW 90 GALV. (VARIOUS)	1.00
- Replace Left Mirror					1.00
- Replaced Rt Headlight.				BLK,CNTRL 806020200	2.00
- Strobe Lite Inop.Correct Open Circuit To Unit.Reinstall Proper Ground Wire.Note:Rr Necessary Hardware To Gain Access.				LIGHT 402113	1.00
				TUBING 5733	10.00
				LIGHT 402111	1.00
				MIR4070 W/COAST MIRROR (INTERNATIONAL)	1.00
				T/S SW 3566945C91	1.00
				1X3 NIPPLE (VARIOUS)	2.00
				LIGHT 402112	1.00
				15/40 OIL	1.00
				LIGHT 402110	1.00
	<b>Parts Charge:</b> 1,115.50		<b>Labor Charge:</b> 275.00		

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 547662

**Problem:** LIGHTS

Meter Reading: 161707	Labor	Parts	Quantity
In Date: 06/15/2005	Hours	Description	Quantity
- Repalce Taillights With L.E.D.S.	6.00		
- Replace Air Supply To Vent Valves Adopt Metric 6Mm Line To 1/4" Tubing			
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	300.00

**Workorder:** 548999

**Problem:** PTO CABLES

Meter Reading: 161707	Labor	Parts	Quantity
In Date: 06/29/2005	Hours	Description	Quantity
- Replace Pto Cables (2) Cut To Fit.	8.50	15/40 OIL	2.00
- Selector Shaft Seal Leaking.Replace Seal And Modulator "O" Ring.			
- Add Oil 1540			
<b>Parts Charge:</b>	3.20	<b>Labor Charge:</b>	425.00
		<b>Commercial Charge:</b>	94.61

**Workorder:** 549451

**Problem:** PM SERVICE

Meter Reading: 162089	Labor	Parts	Quantity
In Date: 07/06/2005	Hours	Description	Quantity
- Pm Service	7.00	15/40 OIL	30.00
- Wash		CA1596 AIR FILTER LBF LAF9545 WIX 42253	1.00
		1819452C1 OIL FILTER FRM PH7138 WIX 51799	1.00
		FP603 FUEL FILTER USE FRM P3380	1.00
		31-16 WIPER BLADES 16" WIPER BLADE	2.00
		AIR FRESHENER	1.00
		BIG G DEGREASER STOCK# 485180002	4.00
<b>Parts Charge:</b>	115.81	<b>Labor Charge:</b>	350.00

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 550163                      **Problem:** TRANS LEAK

Meter Reading: 162244	Labor	Parts	Quantity
In Date: 07/13/2005	Hours	Description	
- R&R Pto Switch	5.50	SWITCH,PTO 379639	1.00
- Won'T Draw Gasoline; Linkage Fell Off Meter; Install Linkageand Adjust Both Sides			1.00
- Water Inside Cab; Repair Drain System			
<b>Parts Charge:</b>	18.80	<b>Labor Charge:</b>	275.00

**Workorder:** 553951                      **Problem:** MIRROR

Meter Reading: 162779	Labor	Parts	Quantity
In Date: 08/25/2005	Hours	Description	
- R&R Mirror.	2.50	MIR4070 W/COAST MIRROR (INTERNATIONAL)	1.00
- Wash.		CAR WASH SOAP STOCK #485360104	4.00
<b>Parts Charge:</b>	56.80	<b>Labor Charge:</b>	125.00

**Workorder:** 555916                      **Problem:** AIR LEAK

Meter Reading: 163087	Labor	Parts	Quantity
In Date: 09/28/2005	Hours	Description	
- Rebuild Front Product Tank Air Vent	6.00		
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	300.00

**Workorder:** 556216                      **Problem:** AIR LEAK

Meter Reading: 163087	Labor	Parts	Quantity
In Date: 10/04/2005	Hours	Description	
- Vent Valve	3.00	VENT VALVE AV46864ALTS	2.00
- Replace Turbo Hose		HOSE,TURBO 2004161C1	1.00
- R&R Filters		SCREEN 1825181C91	1.00
- Install Used Firex		FP603 FUEL FILTER USE FRM P3380	1.00
- Shop Supplies		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		09997 BRAKE CLEAN	2.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	703.47	<b>Labor Charge:</b>	150.00

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 559111

**Problem:** LOW POWER

<b>Meter Reading:</b> 164047		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 12/06/2005	<b>Close Date:</b> 12/09/2005	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	R&R Fuel Filter; Replace F/F Screen	<b>1.50</b>	1817677C91 FUEL FILTER SCREEN ASSY		1.00
			FP603 FUEL FILTER USE FRM P3380		1.00
<b>Parts Charge:</b>		31.47	<b>Labor Charge:</b>		75.00

**Workorder:** 559486

**Problem:** REPLACE BUMPER

<b>Meter Reading:</b> 164226		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 12/12/2005	<b>Close Date:</b> 12/27/2005	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Rr Front Bumper	<b>4.50</b>	BUMPER 1657751C2		1.00
-	Reflectors/Stickers		47A AMBER REFLECTOR 3" ROUND STICK ON(GRT 40053		4.00
			54 RED REFLECTOR OVAL REFLECTOR		2.00
<b>Parts Charge:</b>		620.79	<b>Labor Charge:</b>		225.00

**Workorder:** 635533

**Problem:** CHECK AC

<b>Meter Reading:</b> 164226		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 03/09/2006	<b>Close Date:</b> 03/28/2006	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Check Ac Sys And Repair Leak.Recharge Sys.	<b>16.00</b>	R134A REFRIGERANT		2.00
-	Chucks Welding And Back Twice.		15/40 OIL		30.00
-	Or-Inspect Tank At Chucks Welding		GREASE NLGI 2		1.00
-	Pm Service		FP603 FUEL FILTER USE FRM P3380		1.00
			31-16 WIPER BLADES 16" WIPER BLADE		2.00
			AIR FRESHENER		1.00
			O/F 51799(1819452C1)		2.00
			6Y648 GRAPHITE LUBE (IMPERIAL 6590)		1.00
<b>Parts Charge:</b>		141.14	<b>Labor Charge:</b>		300.00
			<b>Commercial Charge:</b>		1,075.24

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 637802

**Problem:** REPAIR LIGHTS

Meter Reading: 164841		Labor		Parts	
In Date: 04/21/2006	Close Date: 05/22/2006	Hours	Description		Quantity
-	Repl Rear Light Bar	10.00	LIGHT BAR 200021		1.00
-	Replace Head Lghts				1.00
-	Repl Act. Ck Charged For Address				1.00
-	Repl Battery		LAMP,MRKR 215001		6.00
-	Ck Ac		HP31D BATTERY GROUP 31 STUD		2.00
			H6054 SEALED BEAM		1.00
			AIR FRESHENER		1.00
			ALT 19020310		1.00
			801-12-GRA 3/4" NEOPREME HYD SUPPLY #2556-12		5.00
			AIR FRESHENER		1.00
			H6054 SEALED BEAM		1.00
			LIGHT BAR 211003		1.00
	<b>Parts Charge:</b> 706.70	<b>Labor Charge:</b>	50.00	<b>Commercial Charge:</b> 90.00	

**Workorder:** 639851

**Problem:** TIRESOLES OF BROWARD INC

Meter Reading: 0		Labor		Parts	
In Date: 05/10/2006	Close Date: 05/24/2006	Hours	Description		Quantity
-	Tiresoles Of Broward Inc				
	<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b> 565.82	

**Workorder:** 639852

**Problem:** TIRESOLES OF BROWARD INC

Meter Reading: 0		Labor		Parts	
In Date: 05/10/2006	Close Date: 05/24/2006	Hours	Description		Quantity
-	Tiresoles Of Broward Inc				
	<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b> 72.00	

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 645962

**Problem:** AIR LEAK

<b>Meter Reading:</b> 167098		<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 09/21/2006	<b>Close Date:</b> 09/29/2006	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
-	Needs Vent Valve Cant Install Prev Ordered Parts Ont Fit	<b>4.50</b>	V5350 ACCESSORY PLUG	1.00
-	Install 12 V Power Point		PT5/S23 STANDARD PIGTAIL BORG WARNER # PT5	1.00
-	Repair Lines Rebuild Select Side Reqr Marker Rr Instrument Cluster And Replace Bulbs			
	<b>Parts Charge:</b> 12.24	<b>Labor Charge:</b>	150.00	

**Workorder:** 646536

**Problem:** AIR LEAK

<b>Meter Reading:</b> 167098		<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 10/03/2006	<b>Close Date:</b> 11/14/2006	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
-	Rebuilt Diesel Vent Valve Blown Diaphragm	<b>7.00</b>		1.00
-	Replace Air Governor Can'T Adjust To 120151		17212HD DIAPHRAM KIT	2.00
			9Q5892 SCREW	12.00
			17567AL MOUNTING RING	2.00
			26376AL PISTON	2.00
			17213F WEAR RING	2.00
			17196AL RETAINER PLATE	2.00
	<b>Parts Charge:</b> 311.25	<b>Labor Charge:</b>	110.00	

**Workorder:** 648685

**Problem:** P.M. SERVICE

<b>Meter Reading:</b> 167585		<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 11/14/2006	<b>Close Date:</b> 11/27/2006	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
-	Pm Service	<b>6.50</b>	P1108 FUEL FILTER WIX 33336	1.00
-	Road Test		10003 INJECTOR CLEANER DON'T REORDER	1.00
			31-16 WIPER BLADES 16" WIPER BLADE	1.00
			LH8504 IH.P/S FILTER FRAM C8246 WIX 57131	1.00
			61A P/STEERING FLUID	2.00
			1819452C1 OIL FILTER FRM PH7138 WIX 51799	1.00
			15/40 OIL	29.00
			CA1596 AIR FILTER LBF LAF9545 WIX 42253	1.00
	<b>Parts Charge:</b> 128.42	<b>Labor Charge:</b>	27.50	

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

<b>Workorder:</b> 650215		<b>Problem:</b> REPLACE PRODUCT GASOLINE PUMP ASSEMBLY			
<b>Meter Reading:</b> 167737		<b>Labor</b>	<b>Parts</b>		
<b>In Date:</b> 12/21/2006	<b>Close Date:</b> 01/29/2007	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
<hr/>					
-	Replace Gasoline Product Pump Assy W/Fittings	<b>16.50</b>	ATFD TRANS FLUID MERCON V		16.00
-	Pickup Parts		COUPLING AL-D200		1.00
-	Transmission Pm Service		COUPLING AL-F100		1.00
			ADAPTER 2X1 HEX		1.00
			FT1051A TRANS FILTER LBF T153 WIX 58892		1.00
			1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
	<b>Parts Charge:</b> 79.96	<b>Labor Charge:</b> 82.50			
<b>Workorder:</b> 732925		<b>Problem:</b> VENT HOSE-----GASOILINE			
<b>Meter Reading:</b> 167680		<b>Labor</b>	<b>Parts</b>		
<b>In Date:</b> 01/18/2007	<b>Close Date:</b> 01/29/2007	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
<hr/>					
-	R&R Pressure Relief Hose From Gasoline Meter	<b>1.50</b>	HOSE ASSY		1.00
-	Pickup Hose In Belle Glade				
	<b>Parts Charge:</b> 42.59	<b>Labor Charge:</b> 27.50			
<b>Workorder:</b> 734343		<b>Problem:</b> 2-2" HOSE PLUGS			
<b>Meter Reading:</b> 167972		<b>Labor</b>	<b>Parts</b>		
<b>In Date:</b> 02/15/2007	<b>Close Date:</b> 02/28/2007	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
<hr/>					
-	Install Hose Plugs	<b>2.00</b>	PLUG AL-DP200		2.00
-	Repair Auto Shutoff Air Line On Diesel Tank				
-	Pick Up Parts At Hydraulic Supply				
	<b>Parts Charge:</b> 6.60	<b>Labor Charge:</b> 55.00			
<b>Workorder:</b> 734612		<b>Problem:</b> FUEL HOSE			
<b>Meter Reading:</b> 167870		<b>Labor</b>	<b>Parts</b>		
<b>In Date:</b> 02/22/2007	<b>Close Date:</b> 03/22/2007	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
<hr/>					
-	Replace Extension Hose For Reels	<b>1.50</b>			
-	Pick Up Parts At Belle Glade Chevy				
	<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 55.00	<b>Commercial Charge:</b> 276.54		

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 741804                      **Problem:** AIR HORNS\ORDER

Meter Reading: 168719	Labor	Parts
In Date: 07/23/2007	Hours	Description
Close Date: 08/07/2007		Quantity
- Order Air Horns	<b>0.50</b>	AIR HORN ASSB 244283R91
<b>Parts Charge:</b> 185.06	<b>Labor Charge:</b> 27.50	1.00

**Workorder:** 742647                      **Problem:** P.M. SERVICE

Meter Reading: 168720	Labor	Parts
In Date: 08/07/2007	Hours	Description
Close Date: 08/13/2007		Quantity
- P/M Service	<b>12.00</b>	15/40 OIL
- Install Air Horns		1819452C1 OIL FILTER FRM PH7138 WIX 51799
- Evap Water Leaking In Cab Repair Evap Tray Remove Debris Clean Filter Check Charge Evac Test And Recharge		10003 INJECTOR CLEANER DON'T REORDER
- Road Test		
<b>Parts Charge:</b> 84.52	<b>Labor Charge:</b> 27.50	

**Workorder:** 747545                      **Problem:** R&R FADED PLACKARDS

Meter Reading: 169173	Labor	Parts
In Date: 11/19/2007	Hours	Description
Close Date: 11/27/2007		Quantity
- Remove Faded Plackards And Replace With New Ones	<b>2.50</b>	
- Wash Truck		
<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 60.00	

**Workorder:** 832990                      **Problem:** REPLACE L.R.O. TIRE

Meter Reading: 169257	Labor	Parts
In Date: 01/18/2008	Hours	Description
Close Date: 01/23/2008		Quantity
- Set Up Replacement Of Tire Transport Vehicle To Dealer For Replacement	<b>1.50</b>	TIRE 11R22.5 G149RSA
<b>Parts Charge:</b> 370.23	<b>Labor Charge:</b> 60.00	1.00



5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 833172

**Problem:** FUEL HOSE FITTINGS

<b>Meter Reading:</b> 169258		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 01/24/2008	<b>Close Date:</b> 02/28/2008	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Fuel Pick Up Hose And Fittings And Assemble	<b>2.00</b>	FITTING		1.00
			BUSHING		1.00
			ADAPTER		2.00
			FITTING		2.00
			PVC/PIPE		1.00
			GLUE		1.00
			FITTING		1.00
			COUPLER		1.00
			COUPLER		1.00
			NIPPLE		1.00
			FITTING		1.00
			NIPPLE		1.00
			BUSHING		1.00
	<b>Parts Charge:</b> 141.92	<b>Labor Charge:</b>	90.00		

**Workorder:** 833572

**Problem:** AKRON TIRE CO. INC.

<b>Meter Reading:</b> 0		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 02/01/2008	<b>Close Date:</b> 02/01/2008	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-					
	<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b> 24.00	

**Workorder:** 833757

**Problem:** P.M. SERVICE \*\*FIRE EXTINGUISHERS\*\*

<b>Meter Reading:</b> 169446		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 02/06/2008	<b>Close Date:</b> 02/11/2008	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
-	Safety Inspection,Low Mileage	<b>1.50</b>	FIRE EXTINGUISHER		2.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
	<b>Parts Charge:</b> 27.68	<b>Labor Charge:</b>	90.00		

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 834827                      **Problem:** THROTTLE CABLE

<b>Meter Reading:</b> 169517		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 02/29/2008	<b>Close Date:</b> 03/14/2008	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Replace Throttle Cable Assy And Adjust		4.50	THROTTLE CABLE		1.00
- R&R Swivels On Unleaded And Diesel Hoses					
- Fab And Install New Cone Holders					
	<b>Parts Charge:</b> 77.40		<b>Labor Charge:</b> 90.00		

**Workorder:** 836570                      **Problem:** REPLACE WIPER BLADES

<b>Meter Reading:</b> 169665		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 04/04/2008	<b>Close Date:</b> 04/17/2008	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- R&R Wiper Blades		0.30	31-16 WIPER BLADES 16" WIPER BLADE		2.00
	<b>Parts Charge:</b> 8.99		<b>Labor Charge:</b> 18.00		

**Workorder:** 840103                      **Problem:** FUEL NOZZEL

<b>Meter Reading:</b> 170099		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 06/17/2008	<b>Close Date:</b> 06/27/2008	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- R&R Unleaded Fuel Nozzle		1.00	7H-0100 FUEL TRUCK DON'T REORDER		1.00
			45-5075 HOSE SWIVEL 1" (OPW)		1.00
	<b>Parts Charge:</b> 178.37		<b>Labor Charge:</b> 60.00		

**Workorder:** 840324                      **Problem:** PUMP FUEL OFF TRUCK

<b>Meter Reading:</b> 170099		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 06/20/2008	<b>Close Date:</b> 06/27/2008	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Dump Fuel For Tank Inspection And Refill After Inspection		2.50			
	<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 150.00		

**Workorder:** 840399                      **Problem:** FUEL TANK INSPECTION

<b>Meter Reading:</b> 170147		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 06/23/2008	<b>Close Date:</b> 07/09/2008	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Fuel Tank Inspection		1.00	TP-1993A-D DECAL DIESEL 1993		2.00
			TP-1993A-D DECAL DIESEL 1993		2.00
	<b>Parts Charge:</b> 39.00		<b>Labor Charge:</b> 60.00	<b>Commercial Charge:</b> 693.48	

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 842142      **Problem:** AIR LEAK      P.M. SERVICE      D00R

<b>Meter Reading:</b> 170902		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 07/30/2008	<b>Close Date:</b> 09/23/2008	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Check For Air Leak In Delivery System	<b>8.50</b>	1819452C1 OIL FILTER FRM PH7138 WIX 51799		1.00
-	P/M Service		15/40 OIL		29.00
-	R&R R/F Door Latch		31-16 WIPER BLADES 16" WIPER BLADE		2.00
			R/F DOOR LATCH		1.00
			ATFD TRANS FLUID MERCON V		2.00
<b>Parts Charge:</b> 190.59		<b>Labor Charge:</b> 90.00			

**Workorder:** 933661      **Problem:** L/F HEADLIGHT INOP

<b>Meter Reading:</b> 171719		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 02/06/2009	<b>Close Date:</b> 02/18/2009	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	L/F Headlite Inop, Loose Pin In Plug, Repair Wiring At Back Of headlite, Check Ok	<b>1.00</b>			
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 60.00			

**Workorder:** 935346      **Problem:** P.M. SERVICE

<b>Meter Reading:</b> 171997		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 03/19/2009	<b>Close Date:</b> 03/23/2009	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	P/M Service/Safety Inspection Low Mileage	<b>6.00</b>	31-16 WIPER BLADES 16" WIPER BLADE		2.00
<b>Parts Charge:</b> 9.38		<b>Labor Charge:</b> 360.00			

**Workorder:** 935498      **Problem:** TIRES/INSTALL

<b>Meter Reading:</b> 171998		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 03/24/2009	<b>Close Date:</b> 03/31/2009	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Replace Two Tires	<b>1.00</b>	TIRE DISPOSAL FEE		6.00
-	Set Up For Tire Replacement		TIRE DISPOSAL FEE		6.00
			138802903 11R22.5 G159 11R22.5 G159		2.00
<b>Parts Charge:</b> 762.00		<b>Labor Charge:</b> 60.00		<b>Commercial Charge:</b> 192.00	

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 937634

**Problem:** STROBE LITE S

Meter Reading: 172206 In Date: 05/11/2009	Close Date: 05/20/2009	Labor Hours	Description	Parts	Quantity
- Remove Light Housing Filled W/Water; Clean & Reseal; Clean Contacts In Signal Light Pigtail; Replace 2 Strobe Lights		2.00	S30HACP STROBE BULB FOR KIT S660CCCC S30HACP STROBE BULB FOR KIT S660CCCC		1.00 1.00
- Pick Up Parts At Dealer					
<b>Parts Charge:</b>		80.86	<b>Labor Charge:</b>		120.00

**Workorder:** 939454

**Problem:** AIR LEAK

Meter Reading: 172386 In Date: 06/25/2009	Close Date: 06/29/2009	Labor Hours	Description	Parts	Quantity
- Air Leak On Pto Control System And Fuel Tank Vent.Replace Two Air Regulators		6.50	AIR REGULATOR		2.00
<b>Parts Charge:</b>		87.36	<b>Labor Charge:</b>		60.00

**Workorder:** 940218

**Problem:** vent valves in tank

Meter Reading: 172386 In Date: 07/02/2009	Close Date: 07/13/2009	Labor Hours	Description	Parts	Quantity
- Re Build Two Internal Tank Vents.Trace And Repair Air Leaks At Activation Vlv Assy Ref To W/O 0939454		3.50			
<b>Parts Charge:</b>		0.00	<b>Labor Charge:</b>		210.00

**Workorder:** 941564

**Problem:** Fire extinguisher decals

Meter Reading: 172528 In Date: 08/04/2009	Close Date: 08/31/2009	Labor Hours	Description	Parts	Quantity
- Install Fire Ext. & Pbc Emblems Decals		2.50	FIRE EXT DECAL		2.00
- Internal Tank Vent			RETAINER PLATE		2.00
			DIAPHRAM		3.00
			SCREW		6.00
			09997 BRAKE CLEAN		1.00
<b>Parts Charge:</b>		222.46	<b>Labor Charge:</b>		60.00

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 943812                      **Problem:** P.M. Service trans. P.M. service

Meter Reading: 172750	Labor	Parts	Quantity
In Date: 09/28/2009	Hours	Description	
- P.M. Service	<b>8.50</b>	15/40 OIL	29.00
- Trans P.M. Service		1819452C1 OIL FILTER FRM PH7138 WIX 51799	1.00
- Road Test		FT1051A TRANS FILTER LBF T153 WIX 58892	1.00
- Shop Supplies		1259 HYDR FILTER LBF FRM P1653A WIX 51259	1.00
		ATFD TRANS FLUID MERCON V	16.00
		SHOP SUPPLIES	1.00
		31-16 WIPER BLADES 16" WIPER BLADE	2.00
<b>Parts Charge:</b> 227.04		<b>Labor Charge:</b> 120.00	

**Workorder:** 944165                      **Problem:** Hose swivle leaking

Meter Reading: 172750	Labor	Parts	Quantity
In Date: 10/05/2009	Hours	Description	
- Install Leaking Fuel Hose Swivel	<b>1.00</b>	METER HOSE SWIVEL ASSEMBLY 2"	1.00
<b>Parts Charge:</b> 612.03		<b>Labor Charge:</b> 60.00	

**Workorder:** 946645                      **Problem:** Meter head repair/inspection

Meter Reading: 172793	Labor	Parts	Quantity
In Date: 12/03/2009	Hours	Description	
- Inspection & Meter Head Repair To By-Pass Linkage	<b>1.00</b>		
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 120.00	<b>Commercial Charge:</b> 1,075.73

**Workorder:** 1006409                      **Problem:** driver seat belt not working .

Meter Reading: 173709	Labor	Parts	Quantity
In Date: 06/17/2010	Hours	Description	
- Replace Driver Side Seat Belt .	<b>1.00</b>	SEAT BELT ASSY / 1684505C3	1.00
<b>Parts Charge:</b> 301.29		<b>Labor Charge:</b> 60.00	

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 1006751                      **Problem:** pm service .

Meter Reading: 173720	Labor	Parts		
In Date: 06/28/2010	Hours	Description	Quantity	
- Pm Service .	<b>6.50</b>	USED FIREX REFURBED FIRE EXTINGSHERS	2.00	
- Low Air Psi Switch.		15/40 OIL	29.00	
- Replace Left Turn Sig Bulb .		31-16 WIPER BLADES 16" WIPER BLADE	2.00	
- Test Drive .		P1108 FUEL FILTER WIX 33336	1.00	
		1259 HYDR FILTER LBF FRM P1653A WIX 51259	1.00	
		1658820C1 SWITCH LOW AIR PRESSURE	1.00	
		AIR FRESHENER	1.00	
		1819452C1 OIL FILTER FRM PH7138 WIX 51799	1.00	
<b>Parts Charge:</b>	183.32	<b>Labor Charge:</b>	390.00	

**Workorder:** 1007118                      **Problem:** new fuel hose assy & fittings .

Meter Reading: 173755	Labor	Parts		
In Date: 07/07/2010	Hours	Description	Quantity	
- R & R Fuel Hose .	<b>1.00</b>			
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	60.00	<b>Commercial Charge:</b> 493.21

**Workorder:** 1007468                      **Problem:** make up spare fuel hose

Meter Reading: 173778	Labor	Parts		
In Date: 07/15/2010	Hours	Description	Quantity	
- O/R Make Up New Hyd Hose .				
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b> 72.00

**Workorder:** 1011031                      **Problem:** Build new draft tube for Belle Glade fuel site.

Meter Reading: 173778	Labor	Parts		
In Date: 10/06/2010	Hours	Description	Quantity	
- Build New Draft Tube For Fuel Truck To Draft Fuel From Belle Glade Fuel Site.	<b>6.00</b>	2" X 90 CAM LOCK	2.00	
<b>Parts Charge:</b>	128.06	<b>Labor Charge:</b>	360.00	<b>Commercial Charge:</b> 253.20

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

<b>Workorder:</b> 1011604		<b>Problem:</b> Transport			
<b>Meter Reading:</b> 173778		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 10/14/2010		<b>Close Date:</b> 10/18/2010		<b>Hours</b>	
				<b>Quantity</b>	
- From: 580 State Market Rd		To: Vista He			
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 0.00		<b>Commercial Charge:</b> 174.00	

<b>Workorder:</b> 1100529		<b>Problem:</b> pm service			
<b>Meter Reading:</b> 174498		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 01/13/2011		<b>Close Date:</b> 02/01/2011		<b>Hours</b>	
				<b>Quantity</b>	
- Pm Service		<b>34.80</b>		SYN/ATF TRANS FLUID SYNTHETIC	
- Replace 2 Aps Fuel Pumps				7H-0400 FUEL TRUCK NOZZLE BLACK (OPW)	
- Replace Air Lines To Over Flow Valves				PRODUCT VENT VALVE	
- Repair Light Bar				PRODUCT FUEL PUMPS	
- Repair Left Windshield Washer				15/40 OIL	
- Replace Leaking Oil Drain Plug				1819452C1 OIL FILTER FRM PH7138 WIX 51799	
				P1108 FUEL FILTER WIX 33336	
				1259 HYDR FILTER LBF FRM P1653A WIX 51259	
				31-16 WIPER BLADES 16" WIPER BLADE	
				1/4" SYNIFLEX LINE	
				701-D/H1 BULB WAGNER 1255/H1	
				ENGINE OIL DRAIN PLUG	
<b>Parts Charge:</b> 4,580.39		<b>Labor Charge:</b> 2,088.00			

<b>Workorder:</b> 1101845		<b>Problem:</b> leak			
<b>Meter Reading:</b> 174606		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 02/16/2011		<b>Close Date:</b> 02/17/2011		<b>Hours</b>	
				<b>Quantity</b>	
- Replace Steering Box		<b>7.00</b>		STEERING BOX	
- Road Test				61A P/STEERING FLUID	
<b>Parts Charge:</b> 1,003.11		<b>Labor Charge:</b> 420.00			

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

Workorder: 1103751		Problem: fuel tank inspection			
Meter Reading: 175227	Labor			Parts	
In Date: 04/06/2011	Hours	Description	Quantity		
- Tank Inspection By S&B					
<b>Parts Charge:</b>	20.00	<b>Labor Charge:</b>	0.00	<b>Commercial Charge:</b>	519.60
Workorder: 1103984		Problem: will not build air			
Meter Reading: 175403	Labor			Parts	
In Date: 04/13/2011	Hours	Description	Quantity		
- Replace Govenor	2.00	275491X GOVENOR D2 (BENDIX)	1.00		
- Fm To 45 Street					
<b>Parts Charge:</b>	12.25	<b>Labor Charge:</b>	120.00		
Workorder: 1104186		Problem: Check for engine blow by			
Meter Reading: 175403	Labor			Parts	
In Date: 04/18/2011	Hours	Description	Quantity		
-					
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00		
Workorder: 1105196		Problem: air leak			
Meter Reading: 175574	Labor			Parts	
In Date: 05/16/2011	Hours	Description	Quantity		
- Replace Air Valve And Fab Mounting	7.00	AIR CONTROL VALVE	1.00		
- Replace Two Recaps Boulevard		11R225RC TIRE RECAPPED	2.00		
- To Glasgow ,Compressor Works And Delta Petro					
- Test Run					
<b>Parts Charge:</b>	416.96	<b>Labor Charge:</b>	420.00	<b>Commercial Charge:</b>	134.70



5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 1107878

**Problem:** pm service

<b>Meter Reading: 175574</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 07/27/2011</b>	<b>Close Date: 07/29/2011</b>	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Pm Service	<b>9.20</b>	15/40 OIL		30.00
-	Replace Valve Core And Fill Tire With Nitrogen		1819452C1 OIL FILTER FRM PH7138 WIX 51799		1.00
-	Steam Clean Under Side Of Truck To Find Leak		P1108 FUEL FILTER WIX 33336		1.00
-	Repair Leak At Power Steering Fitting		1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
-	Test Drive		31-16 WIPER BLADES 16" WIPER BLADE		2.00
<b>Parts Charge:</b>		120.60	<b>Labor Charge:</b>	552.00	

**Workorder:** 1201146

**Problem:** 9103 and air leak

<b>Meter Reading: 176333</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 02/02/2012</b>	<b>Close Date: 02/27/2012</b>	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Pm Service	<b>10.00</b>	1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
-	Replace Brake Chamber And Park Brake Valve		MODIFIED WATER PASTE FOR ETHANOL		1.00
-	Repair Air Leak At Shut Off Valve		3030SB BRAKE CHAMBER (BENDIX 800831)		1.00
-	Replace Right Mirror		PARKING BRAKE VALVE		1.00
-	Test Drive		1819452C1 OIL FILTER FRM PH7138 WIX 51799		1.00
			15/40 OIL		30.00
			P1108 FUEL FILTER WIX 33336		1.00
			97803 SPOT MIRROR 8.5" VELVAC 708501		1.00
			31-16 WIPER BLADES 16" WIPER BLADE		2.00
<b>Parts Charge:</b>		417.17	<b>Labor Charge:</b>	600.00	

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 1206293

**Problem:** air leak

<b>Meter Reading:</b> 177453		<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 07/05/2012	<b>Close Date:</b> 07/18/2012	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
-	Reseal Gas Tank Vent Valve	<b>9.00</b>	DIAPHRAM KIT	1.00
-	Replace Air Govenor Clean Unloader Valve And Air Tank		MOUNTING RING	1.00
	Check Valves		RETAINER PLATE AIR OPER VENT	1.00
			PIN	1.00
			SCREW	1.00
			FREIGHT	1.00
			PISTON AIR OPERATED	1.00
			WEAR RING AIR OPER	1.00
			275491X GOVENOR D2 (BENDIX)	1.00
	<b>Parts Charge:</b> 194.51	<b>Labor Charge:</b> 540.00		

**Workorder:** 1206944

**Problem:** air leak

<b>Meter Reading:</b> 177453		<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 07/25/2012	<b>Close Date:</b> 08/14/2012	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
-	Replace Shuttle And Check Valves For Gas Side	<b>2.00</b>	CHECK VALVE	1.00
			SHUTTLE VALVE	1.00
	<b>Parts Charge:</b> 62.63	<b>Labor Charge:</b> 120.00		

**Workorder:** 1207906

**Problem:** pm service

<b>Meter Reading:</b> 177502		<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 08/21/2012	<b>Close Date:</b> 08/30/2012	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
-	Pm Service	<b>7.00</b>	CA1596 AIR FILTER LBF LAF9545 WIX 42253	1.00
-	Repair Wiring For Strobe Lights		USED FIREX REFURBED FIRE EXTINGSHERS	3.00
			31-16 WIPER BLADES 16" WIPER BLADE	2.00
			P1108 FUEL FILTER WIX 33336	1.00
			06133 3M ELECTRIC TAPE STOCK #832260101	1.00
			15/40 OIL	30.00
			1819452C1 OIL FILTER FRM PH7138 WIX 51799	1.00
	<b>Parts Charge:</b> 188.49	<b>Labor Charge:</b> 420.00		

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 1209752

**Problem:** Leaks

<b>Meter Reading:</b> 177502		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 10/11/2012	<b>Close Date:</b> 11/26/2012	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Replace Fuel Ball Valves	<b>1.00</b>	100-6-NE 1"GASKET GASBOY NEOPRENE CAMLOCK 1" BALL VALVE (VARIOUS)	2.00	2.00
<b>Parts Charge:</b> 46.95		<b>Labor Charge:</b> 60.00			

**Workorder:** 1301510

**Problem:** pm service

<b>Meter Reading:</b> 177530		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 02/12/2013	<b>Close Date:</b> 03/04/2013	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Pm Service	<b>14.00</b>	31-16 WIPER BLADES 16	2.00	
-	Replace Placards And Seals For Fuel Lines		KAMLOCK HOSE FITTING	2.00	
-	Replace Rear Strobe Lights		USED FIREX REFURBED F	1.00	
-	Replace Fuel Screen , Throttle Cable And Flush Fuel Tank		KAMLOCK DUST CAP	2.00	
-	Replace Batteries		15-40 OIL	30.00	
-	Parts Only		CLAMP	4.00	
			TP-1203-D DECAL GASOL	2.00	
			STROBE SELF CONTAINED	2.00	
			TP-1993A-D DECAL DIES	2.00	
			Freight Charge	1.00	
			CAMLOCK GASKET	12.00	
			1817677C91 FUEL FILTE	2.00	
			THROTTLE CABLE	1.00	
			KAMLOCK GASKET	12.00	
			THROTTLE PEDAL BUSHING	2.00	
			FUEL SENDING UNIT	1.00	
			FUEL SENDER GASKET	1.00	
			GROUP 31 STUD	2.00	
			THROTTLE CABLE RETAINER	1.00	
			NAPAGOLD OIL FILTER	1.00	
			54 RED REFLECTOR OVAL	1.00	
			P1108 FUEL FILTER WIX	1.00	
			TANK FILLER HOSE	22.00	
			THROTTE CABLE BALL	1.00	
<b>Parts Charge:</b> 1,623.85		<b>Labor Charge:</b> 840.00			

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

<b>Workorder:</b> 1301912		<b>Problem:</b> tank inspection			
<b>Meter Reading:</b> 177502		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 02/25/2013	<b>Close Date:</b> 03/13/2013	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Tank Inspection					
	<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 0.00	<b>Commercial Charge:</b> 420.00		
<b>Workorder:</b> 1302552		<b>Problem:</b> Repair fuel leak			
<b>Meter Reading:</b> 177530		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 03/14/2013	<b>Close Date:</b> 03/22/2013	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Repair Meter					
	<b>Parts Charge:</b> 367.95	<b>Labor Charge:</b> 0.00	FUEL METER GLAND REPAIR		1.00
<b>Workorder:</b> 1303948		<b>Problem:</b> repair tank/ pump			
<b>Meter Reading:</b> 177767		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 04/22/2013	<b>Close Date:</b> 05/10/2013	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Repair Tank By Leader Dot					
	<b>Parts Charge:</b> 396.00	<b>Labor Charge:</b> 0.00	ON SITE REPAIR		1.00
<b>Workorder:</b> 1304723		<b>Problem:</b> ac			
<b>Meter Reading:</b> 178399		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 05/10/2013	<b>Close Date:</b> 06/05/2013	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- Replace O Rings At Condenser Evac And Recharge					
	<b>Parts Charge:</b> 14.76	<b>Labor Charge:</b> 300.00	R134A REFRIGERANT		3.00
<b>Workorder:</b> 1308538		<b>Problem:</b> pm service			
<b>Meter Reading:</b> 178509		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 08/23/2013	<b>Close Date:</b> 09/11/2013	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
- P.M.					
		<b>6.00</b>	15-40 OIL		30.00
			NAPAGOLD OIL FILTER		1.00
			P1108 FUEL FILTER WIX		1.00
			USED FIRE X REFURBISHED		2.00
	<b>Parts Charge:</b> 144.51	<b>Labor Charge:</b> 360.00			

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 1312192                      **Problem:** wipers

<b>Meter Reading:</b> 178518		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 12/05/2013	<b>Close Date:</b> 12/10/2013	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Replace Mud Flaps	<b>0.50</b>	WIPER BLADE	2.00	
<b>Parts Charge:</b> 8.13		<b>Labor Charge:</b> 30.00			

**Workorder:** 1401889                      **Problem:** P.M.

<b>Meter Reading:</b> 179480		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 02/26/2014	<b>Close Date:</b> 03/28/2014	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	P.M.	<b>7.50</b>	15-40 OIL	30.00	
-	Tested Left And Right Side Marker Lights		NAPAGOLD OIL FILTER	1.00	
-	Test Drive		NAPAGOLD FUEL FILTER	1.00	
			NAPAGOLD AIR FILTER	1.00	
			WIPER BLADE	2.00	
<b>Parts Charge:</b> 151.18		<b>Labor Charge:</b> 450.00			

**Workorder:** 1405249                      **Problem:** air leak

<b>Meter Reading:</b> 179987		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 05/29/2014	<b>Close Date:</b> 06/24/2014	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Order Parts. Replace Air Switch Pack For Overfill	<b>10.00</b>	CONTROL BLOCK CENTER	2.00	
	Protection. Repair Airlines. Draft Fuel To Test Operation		LEFT BLOCK	1.00	
-	To Belvedere		RIGHT BLOCK	1.00	
			INSERT	8.00	
			Freight Charge	1.00	
<b>Parts Charge:</b> 1,064.91		<b>Labor Charge:</b> 600.00			

**Workorder:** 1406274                      **Problem:** fuel hoses

<b>Meter Reading:</b> 180121		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 06/26/2014	<b>Close Date:</b> 06/27/2014	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Replace Fuel Hoses	<b>2.50</b>	HOSE MAKE UP	1.00	
-	To Mako				
<b>Parts Charge:</b> 1,404.20		<b>Labor Charge:</b> 150.00			

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

<b>Workorder:</b> 1408996		<b>Problem:</b> pm service			
<b>Meter Reading:</b> 180228		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 09/08/2014	<b>Close Date:</b> 09/16/2014	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
		<b>9.00</b>			
- Pm			1817677C91 FUEL FILTE		1.00
- R&R Fuel Primer Pump			Wiper Blade - AccuFit - Rear - OE Style		2.00
- Test Run			COPPER O-RING		2.00
			PRIMER PUMP		1.00
			NAPAGOLD FUEL FILTER		1.00
			NAPAGOLD OIL FILTER		1.00
			USED FIRE X REFURBISHED		1.00
			PTEX THRD SEAL HITEMP		1.00
			15-40 OIL		30.00
<b>Parts Charge:</b> 444.15		<b>Labor Charge:</b> 540.00			
<b>Workorder:</b> 1411641		<b>Problem:</b> No crank			
<b>Meter Reading:</b> 180364		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 11/18/2014	<b>Close Date:</b> 11/25/2014	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
		<b>2.00</b>			
- Jump Start. Replace 2 Batteries Failed Load Test			SUPPORT BATTERY		2.00
- Replace Gas Struts For Rear Door					2.00
<b>Parts Charge:</b> 346.41		<b>Labor Charge:</b> 120.00			
<b>Workorder:</b> 1500907		<b>Problem:</b> Truck Insp.			
<b>Meter Reading:</b> 180364		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 01/27/2015	<b>Close Date:</b> 02/12/2015	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
		<b>2.00</b>			
- Tank Insp.			BIGG DEGREASER		2.00
- Replace All Air Lines On Top Of Tank And Drill Out Drains			FUEL TESTING		1.00
			AIR TUBE		1.00
<b>Parts Charge:</b> 1,677.24		<b>Labor Charge:</b> 120.00			
<b>Workorder:</b> 1501630		<b>Problem:</b> Tires			
<b>Meter Reading:</b> 180577		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 02/13/2015	<b>Close Date:</b> 02/13/2015	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
- Rrio Tires					
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 0.00		<b>Commercial Charge:</b> 521.60	

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

**Workorder:** 1502022

**Problem:** PM

<b>Meter Reading:</b> 180821		<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 02/25/2015	<b>Close Date:</b> 03/12/2015	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Pm		<b>29.00</b>	A C DRIER	1.00
- Replace Alternator			RADIATOR STOP LEAK	2.00
- Replace Belts			TUBE CLAMP	1.00
- Replace Water Pump,Hoses, And Radiator Thermostate And Gasket			WATER PUMP	1.00
			TUBE CLAMP	1.00
- Remove Becon Light			RADIATOR HOSE	1.00
			RADIATOR HOSE	1.00
			H DUTY ANTI-FREEZE	8.00
			RADIATOR	1.00
			15-40 OIL	30.00
			NAPAGOLD OIL FILTER	1.00
			NAPAGOLD FUEL FILTER	1.00
			Wiper Blade - AccuFit - Rear - OE Style	2.00
			BELT	1.00
			HALOGEN LAMP	1.00
			THERMOSTAT	1.00
			ALTERNATOR	1.00
			SERPENTINE BELT	1.00
	<b>Parts Charge:</b> 4,787.46	<b>Labor Charge:</b> 1,740.00		

**Workorder:** 1502617

**Problem:** Head Light

<b>Meter Reading:</b> 180930		<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 03/12/2015	<b>Close Date:</b> 03/17/2015	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Headlight		<b>0.50</b>	HALOGEN LAMP	1.00
	<b>Parts Charge:</b> 12.41	<b>Labor Charge:</b> 30.00		

**Workorder:** 1502844

**Problem:** fire ext

<b>Meter Reading:</b> 181050		<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 03/19/2015	<b>Close Date:</b> 04/20/2015	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Fire Ext		<b>1.00</b>	BRAKE CLEANER	2.00
			USED FIRE X REFURBISHED	2.00
	<b>Parts Charge:</b> 41.10	<b>Labor Charge:</b> 60.00		

5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

<b>Workorder:</b> 1508461		<b>Problem:</b> pm			
<b>Meter Reading:</b> 181715		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 08/24/2015	<b>Close Date:</b>	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-					
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 0.00			

<b>Workorder:</b> 1508794		<b>Problem:</b> Fuel leak			
<b>Meter Reading:</b> 182141		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 09/01/2015	<b>Close Date:</b> 09/09/2015	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-					
Replace Leaking Shut Off Valves And Gaskets. Replace Unleaded Side 1"Ball Valve.		<b>5.50</b>	CORK BUNA GASKET	4.00	
Test Run To Check For Fuel Leaks.			WET/DRY VALVE	2.00	
			CAMLOCK GASKET	6.00	
			BALL VALVE 1"	1.00	
			Freight Charge	1.00	
<b>Parts Charge:</b> 502.41		<b>Labor Charge:</b> 330.00			

<b>Workorder:</b> 1602693		<b>Problem:</b> Pm service. Valve leaking			
<b>Meter Reading:</b> 182385		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 03/14/2016	<b>Close Date:</b> 03/30/2016	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-					
Pm Service.		<b>9.50</b>	BRAKE CLEANER	1.00	
Replace Leaking Ds Ball Valve. Replace 1993 Decals.			BALL VALVE 2" FXF	1.00	
Test Drive.			15W40 BULK TANK PAHOKEE	30.00	
			NAPAGOLD OIL FILTER	1.00	
			NAPAGOLD FUEL FILTER	1.00	
			WASHER FLUID CONCENTR	1.00	
			USED FIRE X REFURBISHED	1.00	
			WIPER BLADE	2.00	
<b>Parts Charge:</b> 245.29		<b>Labor Charge:</b> 570.00			

<b>Workorder:</b> 1705144		<b>Problem:</b> Transition Prep Charge			
<b>Meter Reading:</b> 183534		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 05/24/2017	<b>Close Date:</b> 05/24/2017	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-					
Transition Prep Charge		<b>2.00</b>			
<b>Parts Charge:</b> 0.00		<b>Labor Charge:</b> 0.00			



5/31/2017  
10:36:26AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: M1088 1995 INTERNATIONAL 4700 Fuel Truck, 3000 Gal.

Total Parts Charges: **65,102.27**

Total Labor Charges: **38,209.00**

Total Comm. Charges: **13,327.11**