

10/17/2017
9:26:48AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166682 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 736093 **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts
In Date: 03/22/2007	Hours	Description
Close Date: 03/22/2007		Quantity
- Pre-Delivery Inspection	2.00	
Parts Charge:	0.00	Labor Charge: 110.00

Workorder: 736260 **Problem:** 001 WASH TICKET ISSUED OUT 03/22/07

Meter Reading: 0	Labor	Parts
In Date: 03/22/2007	Hours	Description
Close Date: 03/27/2007		Quantity
- 001 Wash Ticket Issued Out 03/22/07		
Parts Charge:	0.00	Labor Charge: 0.00 Commercial Charge: 7.14

Workorder: 746466 **Problem:** P.M. SERVICE.

Meter Reading: 794	Labor	Parts
In Date: 10/30/2007	Hours	Description
Close Date: 10/31/2007		Quantity
- Pm Service	4.00	5W30 OIL 4.00
- Nitro Service All 5 Tires And Replace With Green Caps.		PH4967 OIL FILTER LBF PH2840 WIX 51394 1.00
Resetlpms		10020 INJECTOR CLEANER DON'T REORDER 1.00
- Service And Inspect Rear Brakes And Adjust.		SHOP SUPPLIES 1.00
- Shop Supplies		
Parts Charge:	20.58	Labor Charge: 60.00

Workorder: 839081 **Problem:** P.M SERVICE

Meter Reading: 1275	Labor	Parts
In Date: 05/28/2008	Hours	Description
Close Date: 05/30/2008		Quantity
- Pm Service Complete	3.00	5W30 OIL 4.00
- Service And Adjust Rear Drum Brakes.		SHOP SUPPLIES 1.00
- Shop Supplies		PH4967 OIL FILTER LBF PH2840 WIX 51394 1.00
Parts Charge:	16.35	Labor Charge: 60.00

10/17/2017
9:26:48AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166682 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 934064

Problem: P.M SERVICE

Meter Reading: 3155	Labor	Parts	
In Date: 02/17/2009	Hours	Description	Quantity
- Pm Service	3.00	5W30 OIL	4.00
- Service Rear Brakes.Inspect, Clean And Adjust.		SHOP SUPPLIES	1.00
- Shop Supplies		PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
Parts Charge:	16.28	Labor Charge:	180.00

Workorder: 934350

Problem: 001 WASH TICKET ISSUED OUT 02/23/09

Meter Reading: 0	Labor	Parts	
In Date: 02/23/2009	Hours	Description	Quantity
- 001 Wash Ticket Issued Out 02/23/09			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	7.14

Workorder: 941556

Problem: P.M service

Meter Reading: 3895	Labor	Parts	
In Date: 08/03/2009	Hours	Description	Quantity
- P.M Service.	4.00	5W30 OIL	4.00
- Rotate & Balance All Four Tires.		PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
- Service Rear Drum Brakes.		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	16.38	Labor Charge:	240.00

10/17/2017
9:26:48AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166682 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1001541

Problem: P.M service, remove D/S floor mat.

Meter Reading: 4468	Labor	Parts	
In Date: 02/11/2010	Hours	Description	Quantity
- P.M Service.	4.00	NB-18 WIPER BLADES 18" ANCO 31-18	1.00
- Rotate & Balance All Four Tires.		31-24 WIPER BLADES 24" BLADE	1.00
- Service Rear Drum Brakes.		SHOP SUPPLIES	1.00
- Shop Supplies		8524247010 BLADE REAR WIPER (TOYOTA)	1.00
		5W30 OIL	4.00
		PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
		AIR FRESHENER	1.00
		WD40 SPRAY LUBE STOCK# 405540002	1.00
		CA10159 AIR FILTER WIX 49116 PRIUS 04-UP	1.00
Parts Charge:	53.42	Labor Charge:	240.00

Workorder: 1004009

Problem: no start at vista

Meter Reading: 4468	Labor	Parts	
In Date: 04/19/2010	Hours	Description	Quantity
- Tr To Vista And Back To Shop	2.50	SHOP SUPPLIES	1.00
- Replace Battery R&R Back Truck Safety Shields Order		BATTERY	1.00
- Shop Supplies			
Parts Charge:	184.04	Labor Charge:	120.00

Workorder: 1004365

Problem: Transition Prep Charge

Meter Reading: 4468	Labor	Parts	
In Date: 04/28/2010	Hours	Description	Quantity
- Transition Prep Charge	2.00		
Parts Charge:	0.00	Labor Charge:	120.00

10/17/2017
9:26:48AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166682 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1004558

Problem: install canceiver

Meter Reading: 4486		Labor		Parts	
In Date: 05/03/2010	Close Date: 05/05/2010	Hours	Description	Quantity	
-	Install Canceiver, Program And Test Ok	3.00	CBL-CVR-XTS CABLE CONNECTOR (EJ WARD)		1.00
			ANT-200 ANTENNA (EJ WARD)		1.00
			J2284LD CANCEIVER		1.00
			CBL-J1962-D CABLE (EJ WARD)		1.00
	Parts Charge: 396.85	Labor Charge:	180.00		

Workorder: 1004771

Problem: 1 - Wash ticket(s) issued

Meter Reading: 4486		Labor		Parts	
In Date: 05/07/2010	Close Date: 05/07/2010	Hours	Description	Quantity	
-	1 - Wash Ticket(S) Issued				
	Parts Charge: 0.00	Labor Charge:	0.00	Commercial Charge:	9.54

Workorder: 1008111

Problem: pm/ flash canceiver/ millage error

Meter Reading: 6178		Labor		Parts	
In Date: 07/30/2010	Close Date: 08/11/2010	Hours	Description	Quantity	
-	Pm	4.00	PH4967 OIL FILTER LBF PH2840 WIX 51394		1.00
-	Flash Canceiver W/A Calibration Of		31-24 WIPER BLADES 24" BLADE		1.00
-	Install Shorter Screw In Power Plug And Reconnect Antenna Wire		8524247010 BLADE REAR WIPER (TOYOTA)		1.00
			5W30 OIL		4.00
			NB-18 WIPER BLADES 18" ANCO 31-18		1.00
	Parts Charge: 40.74	Labor Charge:	240.00		

Workorder: 1008535

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 6178		Labor		Parts	
In Date: 08/09/2010	Close Date: 08/09/2010	Hours	Description	Quantity	
-	1 - Detail Vehicle Wash Ticket(S) Issued				
	Parts Charge: 0.00	Labor Charge:	0.00	Commercial Charge:	90.00

10/17/2017
9:26:48AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166682 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1010610 **Problem:** get ready for reassignment

Meter Reading: 6810	Labor	Parts	
In Date: 09/27/2010	Hours	Description	Quantity
- Get Ready For Reassignment To Health Dept	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 1010649 **Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 6810	Labor	Parts			
In Date: 09/28/2010	Hours	Description	Quantity		
- 1 - Detail Vehicle Wash Ticket(S) Issued					
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	90.00

Workorder: 1011428 **Problem:** Request for one extra key to operate vehicle.

Meter Reading: 7516	Labor	Parts	
In Date: 10/15/2010	Hours	Description	Quantity
- Add One Extra Transmitter To Vehicle.Erase And Reprogram All.Erase And Reprogram New Id For Vehicle Immobilizer To Start Vehicle And Cut Emergency Key For New Fob.	2.50	SHOP SUPPLIES KEY FOB	1.00 1.00
- Shop Supplies			
Parts Charge:	199.68	Labor Charge:	150.00

Workorder: 1012747 **Problem:** 1 - Wash ticket(s) issued

Meter Reading: 8806	Labor	Parts			
In Date: 11/16/2010	Hours	Description	Quantity		
- 1 - Wash Ticket(S) Issued					
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	8.51

10/17/2017
9:26:48AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166682 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1013829 **Problem:** 5 - Wash ticket(s) issued

Meter Reading: 10611	Labor	Parts		
In Date: 12/16/2010	Hours	Description	Quantity	
- 5 - Wash Ticket(S) Issued				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 42.54

Workorder: 1100762 **Problem:** Pm service

Meter Reading: 12012	Labor	Parts		
In Date: 01/19/2011	Hours	Description	Quantity	
- P.M. Service.	6.00	SHOP SUPPLIES		1.00
- Rotate And Balance All Tires.		5W30 OIL		4.00
- Service And Adjust Rear Brakes.		PH4967 OIL FILTER LBF PH2840 WIX 51394		1.00
- Shop Supplies		CF9846A CAB FILTER WIX 24875		1.00
- Transport Vehicle To Dealer For Recall, Water Pump		NB-18 WIPER BLADES 18" ANCO 31-18		1.00
		31-24 WIPER BLADES 24" BLADE		1.00
		WD40 SPRAY LUBE STOCK# 405540002		1.00
Parts Charge:	42.39	Labor Charge:	360.00	

Workorder: 1103636 **Problem:** 0 - Wash ticket(s) issued

Meter Reading: 14353	Labor	Parts		
In Date: 04/04/2011	Hours	Description	Quantity	
- 0 - Wash Ticket(S) Issued				
Parts Charge:	0.00	Labor Charge:	0.00	

Workorder: 1103649 **Problem:** 3 - Wash ticket(s) issued

Meter Reading: 14353	Labor	Parts		
In Date: 04/04/2011	Hours	Description	Quantity	
- 3 - Wash Ticket(S) Issued				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 25.52

10/17/2017
9:26:48AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166682 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1104537	Problem: 3 - Wash ticket(s) issued				
Meter Reading: 15970		Labor	Parts		
In Date: 04/27/2011	Close Date: 04/27/2011	Hours	Description		Quantity
<hr/>					
- 3 - Wash Ticket(S) Issued					
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 25.52		

Workorder: 1105362	Problem: Pm service				
Meter Reading: 17479		Labor	Parts		
In Date: 05/20/2011	Close Date: 05/26/2011	Hours	Description		Quantity
<hr/>					
- Perform Pm Service.		4.00	SHOP SUPPLIES		1.00
- Perform Rear Drum Brakes Service And Adjust Brake Shoes.			CA10159 AIR FILTER WIX 49116 PRIUS 04-UP		1.00
			PH4967 OIL FILTER LBF PH2840 WIX 51394		1.00
- Rotate And Balance All Four Tires.			5W30 OIL		4.00
- Shop Supplies					
	Parts Charge: 20.98	Labor Charge: 240.00			

Workorder: 1110029	Problem: 1 - Wash ticket(s) issued				
Meter Reading: 20165		Labor	Parts		
In Date: 09/20/2011	Close Date: 09/20/2011	Hours	Description		Quantity
<hr/>					
- 1 - Wash Ticket(S) Issued					
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 8.51		

Workorder: 1111969	Problem: P.M. service.				
Meter Reading: 23257		Labor	Parts		
In Date: 11/08/2011	Close Date: 11/14/2011	Hours	Description		Quantity
<hr/>					
- P.M. Service.		4.00	SHOP SUPPLIES		1.00
- Service And Adjust Rear Brakes			31-24 WIPER BLADES 24" BLADE		1.00
- Rotate And Balance All Tires.			8524247010 BLADE REAR WIPER (TOYOTA)		1.00
- Shop Supplies			PH4967 OIL FILTER LBF PH2840 WIX 51394		1.00
			5W30 OIL		4.00
			NB-18 WIPER BLADES 18" ANCO 31-18		1.00
	Parts Charge: 43.77	Labor Charge: 240.00			

10/17/2017
9:26:48AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166682 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1201870

Problem: 6 - Wash ticket(s) issued

Meter Reading: 25920	Labor	Parts	
In Date: 02/24/2012	Hours	Description	Quantity
<hr/>			
- 6 - Wash Ticket(S) Issued			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	51.05

Workorder: 1204379

Problem: Pm service

Meter Reading: 27894	Labor	Parts	
In Date: 05/08/2012	Hours	Description	Quantity
<hr/>			
- Perform Pm Service.	7.50	TIRE DISPOSAL FEE	4.00
- Install Four Tires.Nitrogen Fill And Balance All Four.		738523571 P185/65R15 ASSURANCE FUEL MAX 88H	4.00
- Perform Wheel Alignment Complete.		SHOP SUPPLIES	1.00
- Perform Rear Drum Brake Service And Adjust Brake Shoes.		31-24 WIPER BLADES 24" BLADE	1.00
- Shop Supplies		PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
		NB-18 WIPER BLADES 18" ANCO 31-18	1.00
		5W30 OIL	4.00
Parts Charge:	393.04	Labor Charge:	450.00

Workorder: 1207808

Problem: 5 - Wash ticket(s) issued

Meter Reading: 29565	Labor	Parts	
In Date: 08/16/2012	Hours	Description	Quantity
<hr/>			
- 5 - Wash Ticket(S) Issued			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	42.54

10/17/2017
9:26:48AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166682 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1211121

Problem: Pm service.

Meter Reading: 33721	Labor	Parts	
In Date: 11/15/2012	Hours	Description	Quantity
- Perform Pm Service.	6.75	SHOP SUPPLIES	1.00
- Remove Hatch Trim To Access And Replace Failed		5W30 OIL	4.00
- Tailgate Latch Release Switch And Harness With New.		31-18 WIPER BLADES 18	1.00
- Perform Both Headlamp Restoration With Kit.Clean And		31-24 WIPER BLADES 2	1.00
- Polish Both Headlamp Lens And Reseal.		cabin air filter cf9846a	1.00
- Perform Rear Drum Brake Service And Adjust Brake		REAR COMPOSITE BLADE	1.00
- Shoes.		SUB SWITCH	1.00
- Rotate And Balance All Four Tires.		NAPA QUART 5W30	4.00
- Shop Supplies		NAPAGOLD OIL FILTER	1.00
Parts Charge: 180.60		Labor Charge: 405.00	

Workorder: 1300843

Problem: 3 - Wash ticket(s) issued

Meter Reading: 33945	Labor	Parts	
In Date: 01/24/2013	Hours	Description	Quantity
- 3 - Wash Ticket(S) Issued			
Parts Charge: 0.00		Labor Charge: 0.00	Commercial Charge: 25.52

Workorder: 1303875

Problem: Pm service and steering shaft recall.

Meter Reading: 38835	Labor	Parts	
In Date: 04/19/2013	Hours	Description	Quantity
- Perform Pm Service.	7.00	NAPA QUART 5W30	4.00
- Perform Rear Drum Brake Service And Adjust Brake		SHOP SUPPLIES	1.00
- Shoes.		NAPAGOLD OIL FILTER	1.00
- Repair Flat Left Rear Tire.Nitrogen Fill And Balance All			
- Four.			
- Transport Vehicle To And From Dealer For Performing			
- Steering Shaft Recall Complete.			
- Shop Supplies			
Parts Charge: 20.21		Labor Charge: 420.00	

10/17/2017
9:26:48AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166682 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1305559		Problem: 2 - Wash ticket(s) issued			
Meter Reading: 38835		Labor		Parts	
In Date: 06/05/2013	Close Date: 06/05/2013	Hours	Description	Quantity	
- 2 - Wash Ticket(S) Issued					
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 17.02	

Workorder: 1306971		Problem: 8 - Wash ticket(s) issued			
Meter Reading: 40132		Labor		Parts	
In Date: 07/12/2013	Close Date: 07/12/2013	Hours	Description	Quantity	
- 8 - Wash Ticket(S) Issued					
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 68.06	

Workorder: 1309529		Problem: Check engine light on.			
Meter Reading: 43333		Labor		Parts	
In Date: 09/20/2013	Close Date: 09/25/2013	Hours	Description	Quantity	
- Computer Diagnose For Check Engine Light On.Test And Repair Evapt.System.Replace Failed Gas Cap With New.Clear Codes With Scan Tool And Road Test Vehicle.					
		2.25	FUEL CAP	1.00	
			SHOP SUPPLIES	1.00	
- Shop Supplies					
Parts Charge: 30.77		Labor Charge: 135.00			

10/17/2017
9:26:48AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166682 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1310866

Problem: Pm service.

Meter Reading: 44027		Labor		Parts	
In Date: 10/30/2013	Close Date: 11/15/2013	Hours	Description		Quantity
-	P.M. Service.	6.00	NAPA QUART 5W30		4.00
-	Rear Brakes Dragging.Check And Replace Defective Rear		WIPER BLADE		1.00
	Wheel Cylinder.Flush And Bleed System.		REAR BLADE TOYOTA		1.00
-	Rotate And Balance All Tires.		Wiper Blade - AccuFit - Rear - OE Style		1.00
-	Repair And Secure Air Deflector Below Front Bumper.		NAPAGOLD OIL FILTER		1.00
-	Shop Supplies		31-24 WIPER BLADES 2		1.00
			NAPAGOLD AIR FILTER		1.00
			wheel cylinder		1.00
			wheel cylinder		1.00
			WASHER FL		1.00
			SHOP SUPPLIES		1.00
			WD40 16OZ		1.00
Parts Charge: 198.38		Labor Charge: 360.00			

Workorder: 1400768

Problem: Won't start.

Meter Reading: 45916		Labor		Parts	
In Date: 01/23/2014	Close Date: 01/27/2014	Hours	Description		Quantity
-	Replace Battery.	2.00	AGM BATTERY		1.00
-	Fm To Health Dept. Belle Glade.		SHOP SUPPLIES		1.00
-	Shop Supplies				
Parts Charge: 221.00		Labor Charge: 120.00			

Workorder: 1403063

Problem: Flap under car hamging down and Left outside mirror inop.

Meter Reading: 47094		Labor		Parts	
In Date: 03/28/2014	Close Date: 04/03/2014	Hours	Description		Quantity
-	Diagnose And Test Driver Side Mirror Operation.Test And	1.50	OUTER SWITCH		1.00
	Replace Failed Left Side Mirror Switch With New And		SHOP SUPPLIES		1.00
	Retest.Also Replace Damage Front Splash Shield With		COVER ASY		1.00
	New.				
-	Shop Supplies				
Parts Charge: 199.33		Labor Charge: 90.00			

10/17/2017
9:26:48AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166682 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1403726 **Problem:** Pm service.Fuel gauge inop and driver door locks by it self.

Meter Reading: 47438	Labor	Parts		
In Date: 04/16/2014	Hours	Description	Quantity	
- P.M. Service.	9.50	NAPA QUART 5W30	4.00	
- Replace Driver Door Check Strap.		CHECK ASSY FR	1.00	
- Diagnose Inop Fuel Gauge.Perform Pin Point		WIPER BLADE	1.00	
Test.Replace Fuel Tak/Sender Assemble.Refill Fuel Fuel Tank.		TANK SUB ASSY	1.00	
		31-24 WIPER BLADES 2	1.00	
- Rotate And Balance All Tires.		NAPAGOLD OIL FILTER	1.00	
- Service And And Adjust Rear Brakes.		SHOP SUPPLIES	1.00	
- Shop Supplies		WASHER FLUID CONCENTR	1.00	
Parts Charge: 743.66		Labor Charge: 570.00		

Workorder: 1404437 **Problem:** Fuel gauge only shows half tank.just try to full up.took less than two gallons.

Meter Reading: 47543	Labor	Parts		
In Date: 05/06/2014	Hours	Description	Quantity	
- Diagnose For Fuel Gauge Fault.Power Down Instrument Cluster Memory To Recalculate Confused Gauges.Also Performtsb#Sb016308R1 To Calibrate And Reset Fuel Level And Gauge.	1.50	SHOP SUPPLIES	1.00	
- Shop Supplies				
Parts Charge: 2.00		Labor Charge: 90.00		

Workorder: 1406527 **Problem:** undr car shield loose

Meter Reading: 47543	Labor	Parts		
In Date: 07/02/2014	Hours	Description	Quantity	
- Repair Under Car Plastic Shield	0.50			
Parts Charge: 0.00		Labor Charge: 30.00		

Workorder: 1406552 **Problem:** 4 - Wash ticket(s) issued

Meter Reading: 47543	Labor	Parts		
In Date: 07/02/2014	Hours	Description	Quantity	
- 4 - Wash Ticket(S) Issued				
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 34.03

10/17/2017
9:26:48AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166682 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1407103 **Problem:** odometer error

Meter Reading: 49103		Labor		Parts	
In Date: 07/18/2014	Close Date: 07/24/2014	Hours	Description		Quantity
- Test And Remove Canceiver Issue Fuel Card		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
	Parts Charge: 2.00	Labor Charge:	60.00		

Workorder: 1407663 **Problem:** Shield under engine damage.

Meter Reading: 49430		Labor		Parts	
In Date: 08/04/2014	Close Date: 08/11/2014	Hours	Description		Quantity
- Inspect And Replace Damage Front Under Engine Splash Shield .		0.50	COVER ASY SHOP SUPPLIES		1.00 1.00
- Shop Supplies					
	Parts Charge: 83.61	Labor Charge:	30.00		

Workorder: 1408613 **Problem:** 6 - Wash ticket(s) issued

Meter Reading: 49660		Labor		Parts	
In Date: 08/27/2014	Close Date: 08/27/2014	Hours	Description		Quantity
- 6 - Wash Ticket(S) Issued					
	Parts Charge: 0.00	Labor Charge:	0.00	Commercial Charge:	51.05

Workorder: 1410775 **Problem:** No start/PM

Meter Reading: 50659		Labor		Parts	
In Date: 10/24/2014	Close Date: 10/28/2014	Hours	Description		Quantity
- Tow From: 7289 Gardens Rd (Health Dept)					
	Parts Charge: 0.00	Labor Charge:	0.00	Commercial Charge:	104.15

10/17/2017
9:26:48AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166682 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1410814

Problem: Pm service and towed in for no start.

Meter Reading: 50739		Labor		Parts	
In Date: 10/29/2014	Close Date: 11/06/2014	Hours	Description	Quantity	
-	P.M. Service.	5.00	NAPA QUART 5W30		4.00
-	Test Battery And Charging System.Replace Bad Battery.		NAPAGOLD OIL FILTER		1.00
-	Service And Adjust Rear Brakes.		NAPA CABIN AIR FILTER		1.00
-	Rotate And Balance All Tires.		31-24 WIPER BLADES 2		1.00
-	Shop Supplies		WIPER BLADE		1.00
			AGM BATTERY		1.00
			SHOP SUPPLIES		1.00
Parts Charge:		38.54	Labor Charge:	300.00	

Workorder: 1412069

Problem: 5 - Wash ticket(s) issued

Meter Reading: 51042		Labor		Parts	
In Date: 12/02/2014	Close Date: 12/02/2014	Hours	Description	Quantity	
-	5 - Wash Ticket(S) Issued				
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 42.54

Workorder: 1503755

Problem: 5 - Wash ticket(s) issued

Meter Reading: 53101		Labor		Parts	
In Date: 04/13/2015	Close Date: 04/13/2015	Hours	Description	Quantity	
-	5 - Wash Ticket(S) Issued				
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 47.70

10/17/2017
9:26:48AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166682 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1504829

Problem: Pm service.

Meter Reading: 58637 In Date: 05/12/2015	Close Date: 05/20/2015	Labor Hours	Description	Parts	Quantity
- Pm Service.		13.00	NAPA QUART 5W30		4.00
- Pressure Test And Inspect Cooling System.Replace Defective Water Pump,Thermostat And Drive Belt.Flush And Replace Engine Coolant.			31-24 WIPER BLADES 2		1.00
			NAPAGOLD OIL FILTER		1.00
			ACCUFIT REAR		1.00
- Replace Two Tires.Rotate And Balance All Four.			V-RIBBED BELT		1.00
- Inspect And Service Rear Drum Brakes.			WIPER BLADE		1.00
- Complete Front End Alignment And Road Test.			738523571 P185-65R15		2.00
- Shop Supplies			THERMOSTAT		1.00
			TOYOTA COOLANT		1.00
			GASKET		1.00
			TIRE DISPOSAL FEE		2.00
			WATER PUMP		1.00
			SHOP SUPPLIES		1.00
	Parts Charge: 466.30	Labor Charge: 780.00			

Workorder: 1506371

Problem: Right rear tire flat.

Meter Reading: 58637 In Date: 06/25/2015	Close Date: 06/29/2015	Labor Hours	Description	Parts	Quantity
- Repair And Balance Right Rear Tire.		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
	Parts Charge: 2.00	Labor Charge: 60.00			

Workorder: 1506445

Problem: Flat tire on P/R

Meter Reading: 58637 In Date: 06/25/2015	Close Date: 06/26/2015	Labor Hours	Description	Parts	Quantity
- Tire Service 1050 15Th Street-Riviera Beach - Flat Tire On P/R					
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 66.34		

10/17/2017
9:26:48AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166682 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1511334

Problem: Pm service.Low tire pressure light on.Detail.

Meter Reading: 58637		Labor		Parts	
In Date: 11/04/2015	Close Date: 11/23/2015	Hours	Description	Quantity	
- Pm Service.		4.00	NAPA QUART 5W30		4.00
- Inspect And Service Rear Brakes.			NAPAGOLD OIL FILTER		1.00
- Rotate And Balance All Four Wheels			WIPER BLADE		1.00
- Shop Supplies			WIPER BLADE		1.00
			Wiper Blade - AccuFit - Rear - OE Style		1.00
			SHOP SUPPLIES		1.00
			WASHER FLUID CONCENTR		1.00
			NAPAGOLD AIR FILTER		1.00
Parts Charge:		49.10	Labor Charge:	240.00	

Workorder: 1511757

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 58637		Labor		Parts	
In Date: 11/17/2015	Close Date: 11/17/2015	Hours	Description	Quantity	
- 1 - Detail Vehicle Wash Ticket(S) Issued					
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 90.00

Workorder: 1601427

Problem: Low tire pressure warning light on.

Meter Reading: 58834		Labor		Parts	
In Date: 02/10/2016	Close Date: 02/18/2016	Hours	Description	Quantity	
- Test And Replace Two Faulty Tire Pressure Sensors.Left Front And Right Rear.Register Two Sensor Id To Ip And Balance Both Tires.		2.00	SHOP SUPPLIES		1.00
- Shop Supplies			TPMS SENSOR		2.00
Parts Charge:		201.65	Labor Charge:	120.00	

10/17/2017
9:26:48AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166682 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1605136

Problem: P.M. Service.

Meter Reading: 60729	Labor	Parts	
In Date: 05/17/2016	Hours	Description	
Close Date: 05/27/2016	Quantity		
- P.M. Service.	6.00	NAPAGOLD OIL FILTER	1.00
- Cleaned And Reseal Headlamp Lenses.		WASHER FLUID CONCENTR	1.00
- Rotate And Balance All Tires.		18" wiper blades	1.00
- Fabricate And Replace Front And Rear Asset #'S		NAPA QUART 5W30	4.00
- Service And Adjust Rear Brakes.		ACCUFIT REAR	1.00
- Shop Supplies		3M TM HEADLIGHT LENS	1.00
		WIPER BLADES 24"	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	61.67	Labor Charge:	360.00

Workorder: 1608950

Problem: Right front tire flat spare on car.

Meter Reading: 62294	Labor	Parts	
In Date: 08/26/2016	Hours	Description	
Close Date: 08/31/2016	Quantity		
- Replace And Balance Both Front Tire.	1.00	738523571 P185-65R15	2.00
- Shop Supplies		TIRE DISPOSAL FEE	2.00
		SHOP SUPPLIES	1.00
Parts Charge:	223.24	Labor Charge:	60.00

Workorder: 1612176

Problem: P.M. service.

Meter Reading: 63839	Labor	Parts	
In Date: 11/29/2016	Hours	Description	
Close Date: 12/14/2016	Quantity		
- P.M. Service.	3.00	NAPA QUART 5W30	4.00
- Rotate And Balance Tires.		18" wiper blades	1.00
- Shop Supplies		WIPER BLADES 24"	1.00
		NAPAGOLD OIL FILTER	1.00
		ACCUFIT REAR	1.00
		SHOP SUPPLIES	1.00
		WASHER FLUID CONCENTR	1.00
Parts Charge:	37.33	Labor Charge:	180.00

10/17/2017
9:26:48AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166682 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1612863

Problem: 6 - Wash ticket(s) issued

Meter Reading: 63839	Labor	Parts			
In Date: 12/15/2016	Hours	Description	Quantity		
- 6 - Wash Ticket(S) Issued					
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	50.04

Workorder: 1705762

Problem: P.M. service and tire pressure light on.

Meter Reading: 65656	Labor	Parts			
In Date: 06/09/2017	Hours	Description	Quantity		
- P.M. Service.					
	3.30	SHOP SUPPLIES	1.00		
- Replace Broken Antenna Mast On Roof.					
		NAPA QUART 5W30	4.00		
- Rotate And Balance Four Tires.Adjust Pressures .All Tires					
		ANT POLE SUB ASSY	1.00		
Were Low.					
		NAPAGOLD OIL FILTER	1.00		
- Shop Supplies					
Parts Charge:	98.96	Labor Charge:	198.00		

Workorder: 1707165

Problem: Transition Prep Charge

Meter Reading: 66694	Labor	Parts			
In Date: 07/21/2017	Hours	Description	Quantity		
- Transition Prep Charge					
	2.00				
Parts Charge:	0.00	Labor Charge:	0.00		

Total Parts Charges:	4,306.85	Total Labor Charges:	7,658.00	Total Comm. Charges:	1,004.46
----------------------	-----------------	----------------------	-----------------	----------------------	-----------------