

10/17/2017
9:28:46AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166686 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 737468

Problem: PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts	
In Date: 04/23/2007	Hours	Description	Quantity
- Pre-Delivery Inspection	2.00		
Parts Charge: 0.00	Labor Charge: 110.00		

Workorder: 746694

Problem: P.M SERVICE

Meter Reading: 3563	Labor	Parts	
In Date: 11/02/2007	Hours	Description	Quantity
- Pm Service Complete	5.00	SHOP SUPPLIES	1.00
- Nitrogen Fill Tires Inflation Conversion Service On All Tires Complete.		PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
		5W30 OIL	4.00
- Highspeed Balance All 4 Tires To Correct Vibration In Body Of Vehicle When Driving Over 50 Mph			
- Clean And Adjust Rear Brake Shoes And Drums Also Lube All Adjusters.			
- Shop Supplies			
Parts Charge: 17.29	Labor Charge: 60.00		

Workorder: 838851

Problem: P.M SERVICE

Meter Reading: 7381	Labor	Parts	
In Date: 05/21/2008	Hours	Description	Quantity
- Pm Service	3.00	PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
- Service Rear Brakes Clean And Adjust.		SHOP SUPPLIES	1.00
- Shop Supplies		5W30 OIL	4.00
		CA10159 AIR FILTER WIX 49116 PRIUS 04-UP	1.00
		31-24 WIPER BLADES 24" BLADE	1.00
		NB-18 WIPER BLADES 18" ANCO 31-18	1.00
Parts Charge: 31.47	Labor Charge: 60.00		

10/17/2017
9:28:46AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166686 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 840803

Problem: ROAD CALL AT VISTA GARAGE,DEAD BATTERY.

Meter Reading: 8137	Labor	Parts	
In Date: 07/01/2008	Hours	Description	Quantity
- Jump Start & Transport Veh Fr Garage-Recharge & Test.Batts Ok Test Charging Sys.Ok Interior Light Was Left On.	2.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	120.00

Workorder: 847689

Problem: P.M SERVICE,TIRE LIGHT ON

Meter Reading: 10829	Labor	Parts	
In Date: 12/03/2008	Hours	Description	Quantity
- Pm Service	4.75	31-24 WIPER BLADES 24" BLADE	1.00
- Service Rear Brakes.		5W30 OIL	4.00
- Repair R/R Tire Hi Speed Balance And Nitrofill Tires.		PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
- Rotate & Hi Speed Balance 3 Tires,Nitrofill Tires.		NB-18 WIPER BLADES 18" ANCO 31-18	1.00
- Shop Supplies		CA10159 AIR FILTER WIX 49116 PRIUS 04-UP	1.00
		SHOP SUPPLIES	1.00
		8524247010 BLADE REAR WIPER (TOYOTA)	1.00
Parts Charge:	46.87	Labor Charge:	45.00

Workorder: 848680

Problem: JUMP START AT VISTA/CHECK CHARG SYSTEM & BATTERY

Meter Reading: 10829	Labor	Parts	
In Date: 12/31/2008	Hours	Description	Quantity
- Jump Start At Vista Drive Back To Fleet	3.00	SHOP SUPPLIES	1.00
- Ck Charge Battery Ck Charging Sys & For Draw			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	120.00

10/17/2017
9:28:46AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166686 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 932856

Problem: BATTERY KEEPS GOING DEAD

Meter Reading: 11029		Labor		Parts	
In Date: 01/15/2009	Close Date: 01/17/2009	Hours	Description		Quantity
-	To/Fr Dealer For Warranty Battery.	2.00	SHOP SUPPLIES		1.00
-	Shop Supplies				
Parts Charge:		2.00	Labor Charge:		60.00

Workorder: 939097

Problem: PM SERVICE.

Meter Reading: 14941		Labor		Parts	
In Date: 06/17/2009	Close Date: 06/26/2009	Hours	Description		Quantity
-	Pm Service	3.00	5W30 OIL		4.00
-	Service Rear Brakes.Clean, Inspect And Adjust Rear		NB-18 WIPER BLADES 18" ANCO 31-18		1.00
-	Brakes.		SHOP SUPPLIES		1.00
-	Shop Supplies		PH4967 OIL FILTER LBF PH2840 WIX 51394		1.00
			31-24 WIPER BLADES 24" BLADE		1.00
Parts Charge:		26.32	Labor Charge:		180.00

Workorder: 1000866

Problem: P.M service.

Meter Reading: 20065		Labor		Parts	
In Date: 01/22/2010	Close Date: 02/02/2010	Hours	Description		Quantity
-	P.M Service.	7.50	CA10159 AIR FILTER WIX 49116 PRIUS 04-UP		1.00
-	Mount, Balance & Nitro Fill Four New Tires.		TIRE DISPOSAL FEE		4.00
-	Alignment.		5W30 OIL		4.00
-	Service Rear Drum Brakes.		SHOP SUPPLIES		1.00
-	Shop Supplies		PH4967 OIL FILTER LBF PH2840 WIX 51394		1.00
			738001571 185/65R15 ASSURANCE(DISCONTINUED)		4.00
Parts Charge:		349.47	Labor Charge:		450.00

Workorder: 1004063

Problem: R/F tire flat.

Meter Reading: 21749		Labor		Parts	
In Date: 04/20/2010	Close Date: 04/21/2010	Hours	Description		Quantity
-	Repair R/F Tire.	1.00	SHOP SUPPLIES		1.00
-	Shop Supplies				
Parts Charge:		2.00	Labor Charge:		60.00

10/17/2017
9:28:46AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166686 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1004206 **Problem:** 20 - Wash ticket(s) issued

Meter Reading: 21749	Labor	Parts
In Date: 04/23/2010	Hours	Description
Close Date: 04/23/2010	Quantity	Quantity
- 20 - Wash Ticket(S) Issued		
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 166.80

Workorder: 1007862 **Problem:** Pm service.

Meter Reading: 23383	Labor	Parts
In Date: 07/23/2010	Hours	Description
Close Date: 08/04/2010	Quantity	Quantity
- Perform Pm Service.	5.50	SHOP SUPPLIES
- Perform Drum Brakes Service And Adjust Brake Shoes.		PH4967 OIL FILTER LBF PH2840 WIX 51394
- Fabricate And Secure Falling Splash Shield Under Radiator.		CF9846A CAB FILTER WIX 24875
- Repair Left Rear Tire Flat.Rotate And Balance All Four.		31-24 WIPER BLADES 24" BLADE
- Shop Supplies		5W30 OIL
		NB-18 WIPER BLADES 18" ANCO 31-18
		8524247010 BLADE REAR WIPER (TOYOTA)
Parts Charge: 52.79	Labor Charge: 330.00	

Workorder: 1101229 **Problem:** jump start at vista

Meter Reading: 26960	Labor	Parts
In Date: 02/01/2011	Hours	Description
Close Date: 02/07/2011	Quantity	Quantity
- Jump Start At Vista Garage. Take To Lv Shop	1.00	SHOP SUPPLIES
- Shop Supplies		
Parts Charge: 2.00	Labor Charge: 60.00	

10/17/2017
9:28:46AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166686 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1101243

Problem: Pm service also battery goes dead.Need jump start.

Meter Reading: 27176	Labor	Parts	
In Date: 02/01/2011	Hours	Description	Quantity
- P.M. Service.	7.50	00544-21171-325 BATTERY (TOYOTA)	1.00
- Test Battery And Charging System.Replace Bad Battery.		CA10159 AIR FILTER WIX 49116 PRIUS 04-UP	1.00
- Tail Gate Will Not Open.Test And Replace Defective Tailgate Release Switch.		TAILGATE LIFT HANDLE ASSY	1.00
- Service And Adjust Rear Brakes.		SHOP SUPPLIES	1.00
- Rotate And Balance All Tires.		31-24 WIPER BLADES 24" BLADE	1.00
- Transport Vehicle To Dealer For Water Pump And Gas Pedal Modification Recall.		5W30 OIL	4.00
- Shop Supplies		8524247010 BLADE REAR WIPER (TOYOTA)	1.00
		NB-18 WIPER BLADES 18" ANCO 31-18	1.00
		PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
Parts Charge: 220.56		Labor Charge: 450.00	

Workorder: 1107302

Problem: jump start at vista garage

Meter Reading: 31319	Labor	Parts	
In Date: 07/12/2011	Hours	Description	Quantity
- Tr To Vista For Jump Start And Drop Off To Lv	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00		Labor Charge: 60.00	

Workorder: 1107316

Problem: Had to jump start at vista garage.Interior light was left on.

Meter Reading: 31319	Labor	Parts	
In Date: 07/12/2011	Hours	Description	Quantity
- Interior Lights Was Left On.Fully Recharge Battery Then Test Starting And Charging System.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00		Labor Charge: 60.00	

10/17/2017
9:28:46AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166686 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1108139

Problem: Pm service

Meter Reading: 31794	Labor	Parts	
In Date: 08/03/2011	Hours	Description	Quantity
- P.M. Service.	4.00	SHOP SUPPLIES	1.00
- Service And Adjust Rear Brakes.		PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
- Rotate And Balance All Tires.		5W30 OIL	4.00
- Shop Supplies			
Parts Charge:	16.51	Labor Charge:	240.00

Workorder: 1110988

Problem: A/c has odor .

Meter Reading: 33686	Labor	Parts	
In Date: 10/14/2011	Hours	Description	Quantity
- Deodrizer A/C Evaporator.	1.00	6984 EVAPOR CLEANER EVAPORATOR CLEANER	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	11.00	Labor Charge:	60.00

Workorder: 1111820

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 33642	Labor	Parts	
In Date: 11/02/2011	Hours	Description	Quantity
- 1 - Detail Vehicle Wash Ticket(S) Issued			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	91.80

Workorder: 1200793

Problem: Pm service.

Meter Reading: 35862	Labor	Parts	
In Date: 01/25/2012	Hours	Description	Quantity
- P.M. Service.	4.00	PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
- Service And Adjust Rear Brakes.		31-24 WIPER BLADES 24" BLADE	1.00
- Rotate And Balance All Tires.		NB-18 WIPER BLADES 18" ANCO 31-18	1.00
- Shop Supplies		CF9846A CAB FILTER WIX 24875	1.00
		SHOP SUPPLIES	1.00
		5W30 OIL	4.00
Parts Charge:	37.45	Labor Charge:	240.00

10/17/2017
9:28:46AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166686 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1204650

Problem: Request fire extinguisher to be mounted and detail.

Meter Reading: 38896		Labor		Parts	
In Date: 05/16/2012	Close Date: 06/11/2012	Hours	Description		Quantity
-	Install New Extinguisher With Bracket.	1.50	BATTERY		1.00
-	Recharge Battery And Test.Replace Bad Battery.		SHOP SUPPLIES		1.00
-	Shop Supplies		USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			CUSTOM5LB BRACKET FIREX STOCK #340060300		1.00
Parts Charge: 312.47		Labor Charge: 90.00			

Workorder: 1204945

Problem: 0 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 38810		Labor		Parts	
In Date: 05/29/2012	Close Date: 05/29/2012	Hours	Description		Quantity
-	0 - Detail Vehicle Wash Ticket(S) Issued				
Parts Charge: 0.00		Labor Charge: 0.00			

Workorder: 1204947

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 38810		Labor		Parts	
In Date: 05/29/2012	Close Date: 05/29/2012	Hours	Description		Quantity
-	1 - Detail Vehicle Wash Ticket(S) Issued				
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 97.92	

Workorder: 1204997

Problem: Jump Start at Vista

Meter Reading: 38896		Labor		Parts	
In Date: 05/30/2012	Close Date: 06/06/2012	Hours	Description		Quantity
-	Travel To Vista Center	1.00	SHOP SUPPLIES		1.00
-	Jump Start Vehicle				
-	Shop Supplies				
Parts Charge: 2.00		Labor Charge: 60.00			

10/17/2017
9:28:46AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166686 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1206940

Problem: Pm service.

Meter Reading: 40282	Labor	Parts	
In Date: 07/25/2012	Hours	Description	Quantity
- Perform Pm Service.	4.00	PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
- Perform Rear Drum Brake Service And Adjust Brake Shoes.		5W30 OIL	4.00
		SHOP SUPPLIES	1.00
- Rotate And Balance All Four Tires.			
- Shop Supplies			
Parts Charge:	17.14	Labor Charge:	240.00

Workorder: 1301198

Problem: Pm service.

Meter Reading: 45176	Labor	Parts	
In Date: 02/01/2013	Hours	Description	Quantity
- P.M. Service.	5.00	COVER ASY	1.00
- Rotate And Balance All Tires.		COVER ASY	1.00
- Service And Adjust Rear Brakes.		NAPA QUART 5W30	4.00
- Replace Damaged Splash Shields.		CLIP	3.00
- Shop Supplies		NAPAGOLD OIL FILTER	1.00
		GROMMET	1.00
		cabin air filter cf9846a	1.00
		SHOP SUPPLIES	1.00
		WIPER BLADE	1.00
		31-24 WIPER BLADES 2	1.00
		8524247010 BLADE REAR	1.00
Parts Charge:	264.73	Labor Charge:	300.00

Workorder: 1304876

Problem: Left rear tire flat.

Meter Reading: 47591	Labor	Parts	
In Date: 05/15/2013	Hours	Description	Quantity
- Repair Flat Left Rear Tire.Nitrogen Fill And Balance Same.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

10/17/2017
9:28:46AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166686 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1308261

Problem: Pm service and recalls.

Meter Reading: 49868	Labor	Parts	
In Date: 08/16/2013	Hours	Description	Quantity
- Perform Pm Service.	4.00	NAPA QUART 5W30	4.00
- Rotate And Balance All Four Tires.		USED FIRE X REFURBISHED	1.00
- Perform Rear Drum Brake Service And Adjust Brake Shoes.		NAPAGOLD OIL FILTER	1.00
- Shop Supplies		CA10159 AIR FILTER WI	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	40.43	Labor Charge:	240.00

Workorder: 1310344

Problem: Engine stalls while driving.Will restart after pull over to side of road.

Meter Reading: 50872	Labor	Parts	
In Date: 10/15/2013	Hours	Description	Quantity
- Computer Diagnose For Stalling.Perform Trottle Body Service.Also Install One New Right Side Wiper Blade.	2.75	WIPER BLADE	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		THRTL PLT INTAKE CLNR	1.00
Parts Charge:	13.13	Labor Charge:	165.00

Workorder: 1402346

Problem: Pm service

Meter Reading: 52227	Labor	Parts	
In Date: 03/10/2014	Hours	Description	Quantity
- P.M. Service.	7.50	TIRE DISPOSAL FEE	4.00
- Replace And Balance Four New Tires.		SHOP SUPPLIES	1.00
- Service And Adjust Rear Brakes.		WIPER BLADE	1.00
- Complete Wheel Alignment.Test Drive.		31-24 WIPER BLADES 2	1.00
- Shop Supplies		REAR COMPOSITE BLADE	1.00
		738523571 P185-65R15	4.00
		NAPA QUART 5W30	4.00
		NAPAGOLD OIL FILTER	1.00
Parts Charge:	545.88	Labor Charge:	450.00

10/17/2017
9:28:46AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166686 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1410024

Problem: Pm service

Meter Reading: 57602	Labor	Parts	
In Date: 10/06/2014	Hours	Description	
Close Date: 10/17/2014		Quantity	
- Pm Service.	4.00	WIPER BLADE	1.00
- Rotate And Balance All Four Tires.		31-24 WIPER BLADES 2	1.00
- Inspect And Service Rear Drum Brakes.		SHOP SUPPLIES	1.00
- Shop Supplies		NAPA QUART 5W30	4.00
		REAR COMPOSITE BLADE	1.00
		USED FIRE X REFURBISHED	1.00
		WASHER FLUID CONCENTR	1.00
		NAPAGOLD OIL FILTER	1.00
Parts Charge:	57.65	Labor Charge:	240.00

Workorder: 1503478

Problem: Pm service

Meter Reading: 62261	Labor	Parts	
In Date: 04/03/2015	Hours	Description	
Close Date: 04/14/2015		Quantity	
- Pm Service.	4.00	NAPA QUART 5W30	4.00
- Inspect And Service Rear Drum Brakes.		NAPAGOLD OIL FILTER	1.00
- Rotate And Balance All Four Tires.		SHOP SUPPLIES	1.00
- Shop Supplies		31-24 WIPER BLADES 2	1.00
		WIPER BLADE	1.00
		NAPAGOLD AIR FILTER	1.00
		ACCUFIT REAR	1.00
Parts Charge:	45.90	Labor Charge:	240.00

10/17/2017
9:28:46AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166686 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1510116

Problem: Pm service.

Meter Reading: 66450	Labor	Parts	
In Date: 10/06/2015	Hours	Description	
Close Date: 10/20/2015		Quantity	
- Pm Service.	9.50	WATER PUMP	1.00
- Pressure Test And Inspect Cooling System.Replace		THERMOSTAT	1.00
Defective Leaking Water Pump And Thermostat.Replace		TOYOTA COOLANT	1.00
Worn Belt.Flush And Refill Cooling System.		DRIVE BELT	1.00
- Inspect And Service Rear Brakes.		GASKET	1.00
- Rotate And Balance All Four Tires.		WIPER BLADE	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		WATER PUMP GASKET	1.00
		NAPA CABIN AIR FILTER	1.00
		WIPER BLADE	1.00
		USED FIRE X REFURBISHED	1.00
		NAPA QUART 5W30	4.00
		NAPAGOLD OIL FILTER	1.00
		WIPER BLADE	1.00
Parts Charge:	258.20	Labor Charge:	570.00

Workorder: 1511391

Problem: Instrument cluster display inop and ignition will not turn off.

Meter Reading: 66877	Labor	Parts	
In Date: 11/05/2015	Hours	Description	
Close Date: 12/16/2015		Quantity	
- Replace Both Defective Center Ac Vent Bezels.	3.00	LEFT CENTER A /C VENT	1.00
- Transport Vehicle To And From Dealer For Replacing		SHOP SUPPLIES	1.00
Defective Combination Meter.		REGISTER ASSEMBLY	1.00
- Shop Supplies			
Parts Charge:	459.71	Labor Charge:	180.00

10/17/2017
9:28:46AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166686 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1603923

Problem: P.M. Service.

Meter Reading: 70586	Labor	Parts	
In Date: 04/14/2016	Hours	Description	
Close Date: 04/22/2016		Quantity	
- P.M. Service.	3.00	ACCUFIT REAR	1.00
- Rotate And Balance All Tires.		CAP SUB ASSY	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		18" wiper blades	1.00
		WIPER BLADES 24"	1.00
		NAPAGOLD OIL FILTER	1.00
		WASHER FLUID CONCENTR	1.00
		NAPA QUART 5W30	4.00
Parts Charge:	110.27	Labor Charge:	180.00

Workorder: 1611169

Problem: P.M. service.

Meter Reading: 73370	Labor	Parts	
In Date: 10/28/2016	Hours	Description	
Close Date: 11/14/2016		Quantity	
- P.M. Service.	6.00	WIPER	1.00
- Test Battery And Charging System.Replace Bad Battery.		USED FIRE X REFURBISHED	1.00
- Replace Two Tires,Rotate And Balance All Four.		18" wiper blades	1.00
- Service And Adjust Rear Brakes.		AGM BATTERY	1.00
- Shop Supplies		738523571 P185-65R15	2.00
		NAPA QUART 5W30	4.00
		SHOP SUPPLIES	1.00
		WIPER BLADES 24"	1.00
		NAPAGOLD OIL FILTER	1.00
		TIRE DISPOSAL FEE	2.00
Parts Charge:	484.20	Labor Charge:	360.00

10/17/2017
9:28:46AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166686 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1705532

Problem: P.M. Seervice.

Meter Reading: 77170	Labor	Parts	Quantity
In Date: 06/02/2017	Hours	Description	
- P.M. Service.	5.00	NAPA QUART 5W30	4.00
- Replace Two Tire,Rotate And Balance All Four.		WIPER BLADES 24"	1.00
- Service And Adjust Rear Brakes.		WIPER	1.00
- Shop Supplies		NAPAGOLD OIL FILTER	1.00
		738523571 P185-65R15	2.00
		18" wiper blades	1.00
		USED FIRE X REFURBISHED	1.00
		TIRE DISPOSAL FEE	2.00
		SHOP SUPPLIES	1.00
		Wiper Blade - AccuFit - Rear - OE Style	1.00
		NAPA CABIN AIR FILTER	1.00
Parts Charge:	280.09	Labor Charge:	300.00

Workorder: 1707820

Problem: Transition Prep Charge

Meter Reading: 77882	Labor	Parts	Quantity
In Date: 08/09/2017	Hours	Description	
- Transition Prep Charge	2.00		
Parts Charge:	0.00	Labor Charge:	0.00

Total Parts Charges:	3,717.53	Total Labor Charges:	6,440.00	Total Comm. Charges:	356.52
----------------------	-----------------	----------------------	-----------------	----------------------	---------------