

10/17/2017
9:29:43AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166691 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 737521 **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts
In Date: 04/23/2007	Hours	Description
Close Date: 04/23/2007		Quantity
- Pre-Delivery Inspection	2.00	
Parts Charge: 0.00	Labor Charge: 110.00	

Workorder: 744403 **Problem:** PLASTIC GUARD HANGING DOWN

Meter Reading: 2439	Labor	Parts
In Date: 09/19/2007	Hours	Description
Close Date: 09/20/2007		Quantity
- Repair Lower Mud Guard On Left Front Bumper.	1.30	SHOP SUPPLIES 1.00
- Nitrogen Fill Tires And Reset Low Tire Light		
- Shop Supplies		
Parts Charge: 2.00	Labor Charge: 55.00	

Workorder: 746454 **Problem:** P.M. SERVICE.

Meter Reading: 2892	Labor	Parts
In Date: 10/30/2007	Hours	Description
Close Date: 10/31/2007		Quantity
- Pm Service	4.00	5W30 OIL 4.00
- High Speed Balance All 4 Tires Nitro Fill		SHOP SUPPLIES 1.00
- Clean And Readjust Rear Shoes And Drums.		PH4967 OIL FILTER LBF PH2840 WIX 51394 1.00
- Shop Supplies		
Parts Charge: 16.36	Labor Charge: 60.00	

Workorder: 748800 **Problem:** REPAIR FRT VALANCE

Meter Reading: 3033	Labor	Parts
In Date: 12/18/2007	Hours	Description
Close Date: 12/19/2007		Quantity
- Repair Front Valance, Drill & Replace Bolts & Washers	2.00	SHOP SUPPLIES 1.00
- Touch Up Scratches On Rear Bumper		
- Shop Supplies		
Parts Charge: 2.00	Labor Charge: 60.00	

10/17/2017
9:29:43AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166691 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 833978

Problem: 005 WASH TICKETS ISSUED OUT 02/07/08

Meter Reading: 0	Labor	Parts		
In Date: 02/07/2008	Hours	Description	Quantity	
- 005 Wash Tickets Issued Out 02/07/08				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 41.70

Workorder: 837626

Problem: FRONT VALANCE WAS HIT

Meter Reading: 4251	Labor	Parts		
In Date: 04/28/2008	Hours	Description	Quantity	
- Resecure Frt Body Valance Was Pulled Loose, Drilled & Fastnd W/New Srews. Test Drive=Ok	1.00	SHOP SUPPLIES	1.00	
- Shop Supplies				
Parts Charge:	2.00	Labor Charge:	60.00	

Workorder: 838888

Problem: P.M. SERVICE.

Meter Reading: 4583	Labor	Parts		
In Date: 05/22/2008	Hours	Description	Quantity	
- Pm Service	3.00	5W30 OIL	4.00	
- Service Rear Brakes Clean And Adjust.		PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00	
- Shop Supplies		NB-18 WIPER BLADES 18" ANCO 31-18	1.00	
		31-24 WIPER BLADES 24" BLADE	1.00	
		CA10170 AIR FILTER LBF AF3601 WIX 49187	-1.00	
		CA10159 AIR FILTER WIX 49116 PRIUS 04-UP	1.00	
		SHOP SUPPLIES	1.00	
		CA10170 AIR FILTER LBF AF3601 WIX 49187	1.00	
Parts Charge:	31.47	Labor Charge:	60.00	

Workorder: 845696

Problem: 003 WASH TICKETS ISSUED OUT 10/03/08

Meter Reading: 0	Labor	Parts		
In Date: 10/03/2008	Hours	Description	Quantity	
- 003 Wash Tickets Issued Out 10/03/08				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 21.42

10/17/2017
9:29:43AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166691 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 847583

Problem: P.M SERVICE

Meter Reading: 7521		Labor		Parts	
In Date: 12/02/2008	Close Date: 12/09/2008	Hours	Description	Quantity	
-	Pm Service	4.00	5W30 OIL	4.00	
-	Service Rear Brakes.Clean,Inspect And Adjust Rear Brakes.		1066 WHITE LITHIUM (CRC 05037)	1.00	
-	Rotate And Hi Speed Balance All 4 Tires.Nitro Fill Tires.		NB-18 WIPER BLADES 18" ANCO 31-18	1.00	
-	Shop Supplies		SHOP SUPPLIES	1.00	
			8524247010 BLADE REAR WIPER (TOYOTA)	1.00	
			31-24 WIPER BLADES 24" BLADE	1.00	
			PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00	
Parts Charge: 45.51		Labor Charge: 60.00			

Workorder: 932665

Problem: 005 WASH TICKETS ISSUED OUT 01/06/09

Meter Reading: 0		Labor		Parts	
In Date: 01/06/2009	Close Date: 01/12/2009	Hours	Description	Quantity	
-	005 Wash Tickets Issued Out 01/06/09				
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 35.70	

Workorder: 935845

Problem: 004 WASH TICKETS ISSUED OUT 03/25/09

Meter Reading: 0		Labor		Parts	
In Date: 03/25/2009	Close Date: 03/30/2009	Hours	Description	Quantity	
-	004 Wash Tickets Issued Out 03/25/09				
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 28.56	

Workorder: 939180

Problem: P.M. SERVICE.

Meter Reading: 10515		Labor		Parts	
In Date: 06/18/2009	Close Date: 06/26/2009	Hours	Description	Quantity	
-	Pm Service	4.00	5W30 OIL	4.00	
-	Service Rear Brakes.		PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00	
-	Rotate And Hi Speed Balance 4 Tires.Fill W/Nitrogen.		SHOP SUPPLIES	1.00	
-	Shop Supplies				
Parts Charge: 16.28		Labor Charge: 240.00			

10/17/2017
9:29:43AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166691 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 941055 **Problem:** 5 - Wash ticket(s) issued

Meter Reading: 10539 **Labor**

In Date: 07/21/2009 **Hours** **Description** **Parts** **Quantity**

- 5 - Wash Ticket(S) Issued

Parts Charge: 0.00 **Labor Charge:** 0.00 **Commercial Charge:** 35.70

Workorder: 946121 **Problem:** 5 - Wash ticket(s) issued

Meter Reading: 11989 **Labor**

In Date: 11/17/2009 **Hours** **Description** **Parts** **Quantity**

- 5 - Wash Ticket(S) Issued

Parts Charge: 0.00 **Labor Charge:** 0.00 **Commercial Charge:** 41.70

Workorder: 947008 **Problem:** P.M. Service.

Meter Reading: 12488 **Labor**

In Date: 12/14/2009 **Hours** **Description** **Parts** **Quantity**

- P.Mn. Service. **4.00** SHOP SUPPLIES 1.00

- Service Rear Brakes. 5W30 OIL 4.00

- Rotate And Balance All Tires. 31-24 WIPER BLADES 24" BLADE 1.00

- Shop Supplies CA10159 AIR FILTER WIX 49116 PRIUS 04-UP 1.00

Parts Charge: 46.82 **Labor Charge:** 480.00

8524247010 BLADE REAR WIPER (TOYOTA) 1.00

NB-18 WIPER BLADES 18" ANCO 31-18 1.00

PH4967 OIL FILTER LBF PH2840 WIX 51394 1.00

Workorder: 1006573 **Problem:** Pm service.

Meter Reading: 14834 **Labor**

In Date: 06/22/2010 **Hours** **Description** **Parts** **Quantity**

- P.M. Service. **3.00** 5W30 OIL 4.00

- Service And Adjust Rear Brakes. SHOP SUPPLIES 1.00

- Shop Supplies PH4967 OIL FILTER LBF PH2840 WIX 51394 1.00

Parts Charge: 16.26 **Labor Charge:** 180.00

10/17/2017
9:29:43AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166691 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1008915 **Problem:** 4 - Wash ticket(s) issued

Meter Reading: 15721 **Labor**

In Date: 08/18/2010 **Hours** **Parts**

	Close Date:	Description		Quantity
- 4 - Wash Ticket(S) Issued	08/18/2010			
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 33.36

Workorder: 1012756 **Problem:** 4 - Wash ticket(s) issued

Meter Reading: 17336 **Labor**

In Date: 11/16/2010 **Hours** **Parts**

	Close Date:	Description		Quantity
- 4 - Wash Ticket(S) Issued	11/16/2010			
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 34.03

Workorder: 1013197 **Problem:** Pm service.

Meter Reading: 17489 **Labor**

In Date: 11/30/2010 **Hours** **Parts**

	Close Date:	Description		Quantity
- P.M. Service.			4.00	
- Service And Adjust Rear Brakes.		5W30 OIL		4.00
- Rotate And Balance All Tires.		PH4967 OIL FILTER LBF PH2840 WIX 51394		1.00
- Shop Supplies		31-24 WIPER BLADES 24" BLADE		1.00
		NB-18 WIPER BLADES 18" ANCO 31-18		1.00
		SHOP SUPPLIES		1.00
Parts Charge:	26.43	Labor Charge:	240.00	

Workorder: 1104538 **Problem:** 3 - Wash ticket(s) issued

Meter Reading: 18871 **Labor**

In Date: 04/27/2011 **Hours** **Parts**

	Close Date:	Description		Quantity
- 3 - Wash Ticket(S) Issued	04/27/2011			
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 25.52

10/17/2017
9:29:43AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166691 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1105532

Problem: Pm service and hybrid water pump recall.

Meter Reading: 19452 In Date: 05/25/2011	Close Date: 06/09/2011	Labor Hours	Description	Parts	Quantity
- Perform Pm Service.		10.50	SHOP SUPPLIES		1.00
- Install Two New Tires To The Front Wheels.Nitrogen Fill And Balance All Four.			PH4967 OIL FILTER LBF PH2840 WIX 51394		1.00
			5W30 OIL		4.00
- Remove Lift Gate Trim To Access And Replace Failed Handle/Release Button With New.			CF9846A CAB FILTER WIX 24875		1.00
			NB-18 WIPER BLADES 18" ANCO 31-18		1.00
- Perform Rear Drum Brakes Service And Adjust Brake Shoes.			31-24 WIPER BLADES 24" BLADE		1.00
			TIRE DISPOSAL FEE		2.00
- Perform Wheel Alignment Complete.			738523571 P185/65R15 ASSURANCE FUEL MAX 88H		2.00
- Transport Vehicle To And From Dealer For Hybrid Electric Water Pump And Accelerator Pedal Recalls.Replacing Hybrid Water Pump With New And Modify Accelerator Pedal To Floor Surface.			REAR LIFT GATE SWITCH		1.00
- Shop Supplies					
Parts Charge:		285.91	Labor Charge:		630.00

Workorder: 1111231

Problem: 3 - Wash ticket(s) issued

Meter Reading: 21164 In Date: 10/24/2011	Close Date: 10/24/2011	Labor Hours	Description	Parts	Quantity
- 3 - Wash Ticket(S) Issued					
Parts Charge:		0.00	Labor Charge:		0.00
			Commercial Charge:		25.52

Workorder: 1113029

Problem: Pm service

Meter Reading: 21754 In Date: 12/09/2011	Close Date: 12/27/2011	Labor Hours	Description	Parts	Quantity
- Perform Pm Service.		4.00	NB-18 WIPER BLADES 18" ANCO 31-18		1.00
- Perform Rear Drum Brakes Service And Adjust Brake Shoes.			31-24 WIPER BLADES 24" BLADE		1.00
			5W30 OIL		4.00
- Rotate And Balance All Four Tires.			PH4967 OIL FILTER LBF PH2840 WIX 51394		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
Parts Charge:		27.21	Labor Charge:		240.00

10/17/2017
9:29:43AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166691 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1201868 **Problem:** 4 - Wash ticket(s) issued

Meter Reading: 22611 **Labor**

In Date: 02/24/2012 **Hours** **Parts**

Description	Quantity	Parts Charge:	Labor Charge:	Commercial Charge:
- 4 - Wash Ticket(S) Issued		0.00	0.00	34.03

Workorder: 1205033 **Problem:** 5 - Wash ticket(s) issued

Meter Reading: 24146 **Labor**

In Date: 05/30/2012 **Hours** **Parts**

Description	Quantity	Parts Charge:	Labor Charge:	Commercial Charge:
- 5 - Wash Ticket(S) Issued		0.00	0.00	42.54

Workorder: 1205100 **Problem:** Pm service.

Meter Reading: 24146 **Labor**

In Date: 05/31/2012 **Hours** **Parts**

Description	Quantity	Parts Charge:	Labor Charge:	Commercial Charge:
- P.M. Service.			4.00	
- Rotate And Balance All Tires.				4.00
- Service And Adjust Rear Brakes.				1.00
- Shop Supplies				1.00
		26.60	240.00	

Workorder: 1210162 **Problem:** Tire pressure light on .

Meter Reading: 26182 **Labor**

In Date: 10/23/2012 **Hours** **Parts**

Description	Quantity	Parts Charge:	Labor Charge:	Commercial Charge:
- Check And Adjust All Tire Pressures.Reset Monitoring System.		0.00	0.50	30.00

10/17/2017
9:29:43AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166691 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1211710

Problem: Pm service

Meter Reading: 26501	Labor	Parts	
In Date: 12/04/2012	Hours	Description	Quantity
- P.M. Service.	5.00	SHOP SUPPLIES	1.00
- Replace Two Tires,Rotate And Balance All Four.		TIRE DISPOSAL FEE	2.00
- Service And Adjust Rear Brakes.		NAPAGOLD OIL FILTER	1.00
- Shop Supplies		31-24 WIPER BLADES 2	1.00
		5W30 OIL	2.00
		738523571 P185-65R15	2.00
		31-18 WIPER BLADES 18	1.00
		REAR COMPOSITE BLADE	1.00
		CA10159 AIR FILTER WI	1.00
Parts Charge:	275.46	Labor Charge:	300.00

Workorder: 1306322

Problem: P.M. Service.Recall.

Meter Reading: 27660	Labor	Parts	
In Date: 06/24/2013	Hours	Description	Quantity
- P.M. Service.	5.00	NAPA QUART 5W30	4.00
- Test Battery And Charging System.Replace Bad Battery.		NAPAGOLD OIL FILTER	1.00
- Service And Adjust Rear Brakes.		31-24 WIPER BLADES 2	1.00
- Rotate And Balance All Tires.		WIPER BLADE	1.00
- Shop Supplies		TOYOTA HYBRID BATTERY	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	178.35	Labor Charge:	300.00

Workorder: 1311153

Problem: Towed in for no start.

Meter Reading: 29342	Labor	Parts	
In Date: 11/04/2013	Hours	Description	Quantity
- Recharge And Test Battery,Good.Check For System Draw,Good.	0.50		
Parts Charge:	0.00	Labor Charge:	30.00

10/17/2017
9:29:43AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166691 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1311198

Problem: wont start

Meter Reading: 28927	Labor	Parts			
In Date: 11/01/2013	Hours	Description	Quantity		
- Tow From: 600 Clematis Parking Garage 3Rd Floor To: Vista					
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	104.15

Workorder: 1400081

Problem: Pm service

Meter Reading: 30075	Labor	Parts	
In Date: 01/03/2014	Hours	Description	Quantity
- P.M. Service.	4.00	NAPA QUART 5W30	4.00
- Service And Adjust Rear Brakes.		NAPAGOLD OIL FILTER	1.00
- Rotate And Balance All Tires.		WIPER BLADE	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		31-24 WIPER BLADES 2	1.00
Parts Charge:	30.41	Labor Charge:	240.00

Workorder: 1405137

Problem: Remote will not fit in igation.

Meter Reading: 34674	Labor	Parts	
In Date: 05/28/2014	Hours	Description	Quantity
- Transport Vehicle To Dealer To Program New Key And Transmitter.	2.00	SHOP SUPPLIES	1.00
		REMOTE FOB KEY	1.00
- Shop Supplies		TRANSMITTER AS	1.00
Parts Charge:	329.71	Labor Charge:	120.00

10/17/2017
9:29:43AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166691 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1407086

Problem: Pm service

Meter Reading: 34700		Labor		Parts	
In Date: 07/17/2014	Close Date: 07/29/2014	Hours	Description		Quantity
- P.M. Service.		4.00	SHOP SUPPLIES		1.00
- Service And Adjust Rear Brakes.			NAPA CABIN AIR FILTER		1.00
- Rotate And Balance All Tires.			NAPAGOLD OIL FILTER		1.00
- Shop Supplies			WASHER FL		1.00
			NAPA QUART 5W30		4.00
			REAR COMPOSITE BLADE		1.00
			WIPER BLADE		1.00
			31-24 WIPER BLADES 2		1.00
Parts Charge:		49.17	Labor Charge:	240.00	

Workorder: 1500668

Problem: Pm service.

Meter Reading: 39311		Labor		Parts	
In Date: 01/20/2015	Close Date: 01/30/2015	Hours	Description		Quantity
- P.M. Service.		4.00	NAPA QUART 5W30		4.00
- Service And Adjust Rear Brakes.			NAPAGOLD OIL FILTER		1.00
- Rotate And Balance Tires.			31-24 WIPER BLADES 2		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
			WIPER BLADE		1.00
Parts Charge:		30.18	Labor Charge:	240.00	

Workorder: 1507605

Problem: P.M. service and red brake light on at times and pulls left.

Meter Reading: 41910		Labor		Parts	
In Date: 07/30/2015	Close Date: 08/19/2015	Hours	Description		Quantity
- Pm Service.		10.00	NAPA QUART 5W30		4.00
- Computer Diagnose Brake Warning Light On Dash			WIPER BLADE		1.00
- Intermittently.Code P1249.Pinpoint Test And Replace			NAPAGOLD OIL FILTER		1.00
- Defective Stoplight Switch Assembly.Clear Code With			31-24 WIPER BLADES 2		1.00
- Scan Tool And Test Drive.			brake switch assy		1.00
- Replace Two Tires.Rotate And Balance All Four.			ACCUFIT REAR		1.00
- Inspect And Service Rear Brakes.			SHOP SUPPLIES		1.00
- Complete Front End Alignment And Test Drive.			TIRE DISPOSAL FEE		2.00
- Shop Supplies			738523571 P185-65R15		2.00
Parts Charge:		367.96	Labor Charge:	600.00	

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166691 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1512555

Problem: Pm service.Low tire pressure warning light.

Meter Reading: 46979	Labor	Parts		
In Date: 12/11/2015	Hours	Description	Quantity	
- Pm Service.	5.00	NAPA CABIN AIR FILTER	1.00	
- Replace Cracked Serpentine Belt.		V-RIBBED BELT	1.00	
- Inspect And Service Rear Brakes.		NAPA QUART 5W30	4.00	
- Rotate And Balance All Four Tires.		SHOP SUPPLIES	1.00	
- Shop Supplies		NAPAGOLD OIL FILTER	1.00	
		NAPAGOLD AIR FILTER	1.00	
Parts Charge:			51.80	
		Labor Charge:	300.00	

Workorder: 1600100

Problem: Ants in vehicle.

Meter Reading: 47264	Labor	Parts		
In Date: 01/05/2016	Hours	Description	Quantity	
- Fumigate For Ants And Send For Detail.	0.50			
Parts Charge:			0.00	
		Labor Charge:	30.00	

Workorder: 1600221

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 46979	Labor	Parts		
In Date: 01/07/2016	Hours	Description	Quantity	
- 1 - Detail Vehicle Wash Ticket(S) Issued				
Parts Charge:			0.00	
		Labor Charge:	0.00	
		Commercial Charge:	90.00	

10/17/2017
9:29:43AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166691 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1606002

Problem: P.M. service and damage to right bumper.

Meter Reading: 52051 In Date: 06/10/2016	Close Date: 06/22/2016	Labor Hours	Description	Parts	Quantity
- P.M. Service.		8.00	NAPA QUART 5W30		4.00
- Pressure Test And Inspect Cooling System.Flush And Refill System.			WIPER BLADES 24"		1.00
- Replace Two Tires,Rotate And Balance All Four.			TOYOTA COOLANT		1.00
- Test Battery And Charging System.Replace Bad Battery.			18" wiper blades		1.00
- Service And Adjust Rear Brakes.			738523571 P185-65R15		2.00
- Shop Supplies			SHOP SUPPLIES		1.00
			NAPAGOLD OIL FILTER		1.00
			Wiper Blade - AccuFit - Rear - OE Style		1.00
			TIRE DISPOSAL FEE		2.00
			BATTERY TOYOTA OEM		1.00
Parts Charge: 547.21		Labor Charge: 480.00			

Workorder: 1606824

Problem: damage to frt bumper

Meter Reading: 52051 In Date: 06/17/2016	Close Date: 07/06/2016	Labor Hours	Description	Parts	Quantity
- Damage To Frt Bumper					
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 438.60	

Workorder: 1612750

Problem: P.M. service and check engine light and tire light.

Meter Reading: 55142 In Date: 12/13/2016	Close Date: 01/03/2017	Labor Hours	Description	Parts	Quantity
- P.M. Service.		5.50	18" wiper blades		1.00
- Diagnose Check Engine Light.P0455.Perform Pin Point Test.Replace Defective Fuel Cap.Clear Code And Retest.			NAPA QUART 5W30		4.00
- Service And Adjust Rear Brakes.			SHOP SUPPLIES		1.00
- Rotate And Balance Tires.			WIPER BLADES 24"		1.00
- Shop Supplies			FUEL CAP		1.00
			NAPAGOLD OIL FILTER		1.00
			ACCUFIT REAR		1.00
			SILICONE SPRAY 10OZ		1.00
Parts Charge: 70.31		Labor Charge: 330.00			

10/17/2017
9:29:43AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166691 2007 TOYOTA PRIUS Car, Mid-Size, Hybrid

Workorder: 1701264

Problem: Remote inop.

Meter Reading: 55622		Labor		Parts	
In Date: 02/07/2017	Close Date: 02/22/2017	Hours	Description	Quantity	
-	Replace Keyfob Battery.Reprogram Keyfob.	1.00	SHOP SUPPLIES		1.00
-	Shop Supplies		ENR ELECT BATTERY		1.00
Parts Charge: 9.07		Labor Charge: 60.00			

Workorder: 1705707

Problem: P.M. service.

Meter Reading: 58326		Labor		Parts	
In Date: 06/08/2017	Close Date: 06/15/2017	Hours	Description	Quantity	
-	P.M. Service.	4.00	WD40 SPR		1.00
-	Rotate And High Speed Balance All Four Tires.Replace		SHOP SUPPLIES		1.00
-	Tpms Sensor In Right Rear And Program.		MAC WITE LITHIUM GRES		1.00
-	Shop Supplies		NAPAGOLD OIL FILTER		1.00
			NAPA QUART 5W30		4.00
			WIPER BLADES 24"		1.00
			TPMS SENSOR		1.00
			ACCUFIT REAR		1.00
			18" wiper blades		1.00
Parts Charge: 154.11		Labor Charge: 240.00			

Workorder: 1707345

Problem: Transition Prep Charge

Meter Reading: 59027		Labor		Parts	
In Date: 07/26/2017	Close Date: 07/26/2017	Hours	Description	Quantity	
-	Transition Prep Charge	2.00			
Parts Charge: 0.00		Labor Charge: 0.00			

Total Parts Charges:	2,638.59	Total Labor Charges:	6,255.00	Total Comm. Charges:	1,032.53
----------------------	-----------------	----------------------	-----------------	----------------------	-----------------