

10/6/2017
10:20:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11240 2003 CHEVROLET 2500 HD Utility Body, 3/4 Ton, Ext Cab, Liftgate

Workorder: 339510 **Problem:** WASH VEHICLE

Meter Reading: 0	Labor	Parts	Quantity
In Date: 04/30/2003	Hours	Description	
- Wash Vehicle	4.10		
- Pre-Delivery Inspection			
- Make Duplicate Keys For New Vehicle			
Parts Charge:	0.00	Labor Charge:	205.00

Workorder: 339928 **Problem:** RELOCATE LIGHT BAR

Meter Reading: 0	Labor	Parts	Quantity
In Date: 05/05/2003	Hours	Description	
- Relocate Light Bar	6.00	T-1 BLACK PAINT GLOSS	1.00
- Welding Supplies		1/4X4X20 STEEL FLAT BAR	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	15.56	Labor Charge:	300.00

Workorder: 339989 **Problem:** INSTALL STROBE LIGHT SYSTEM

Meter Reading: 22	Labor	Parts	Quantity
In Date: 05/06/2003	Hours	Description	
- Fabricate And Instsall Strobe Light Assy.	3.50	7044D 3-3/4" SPOT MIRROR	2.00
- Shop Supplies		DS-167 TOGGLE SWITCH (STANDARD)	1.00
		SHOP SUPPLIES	1.00
		S-12-30 30 AMP BREAKER	1.00
Parts Charge:	15.86	Labor Charge:	175.00

Workorder: 342421 **Problem:** VEHICLE TAGS

Meter Reading: 529	Labor	Parts	Quantity
In Date: 06/14/2003	Hours	Description	
- Vehicle Tags		VEHICLE TAGS	1.00
Parts Charge:	34.35	Labor Charge:	0.00

10/6/2017
10:20:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11240 2003 CHEVROLET 2500 HD Utility Body, 3/4 Ton, Ext Cab, Liftgate

Workorder: 352455

Problem: P.M.SERVICE

Meter Reading: 4120	Labor	Parts	
In Date: 12/01/2003	Hours	Description	Quantity
- Pm Service	2.75	10W30 MOTOR OIL	7.00
- Install How'S My Driving Sticker.		51522 WIX / PH59 L/F OIL FILTER	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	10.91	Labor Charge:	137.50

Workorder: 432417

Problem: CHECK ENGINE LIGHT STAYS ON

Meter Reading: 4625	Labor	Parts	
In Date: 01/06/2004	Hours	Description	Quantity
- Transport & Pickup Vehicle At Dealer.(Engine Light Stays On)	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	50.00

Workorder: 434766

Problem: ENGINE LIGHT STAYS ON

Meter Reading: 5413	Labor	Parts	
In Date: 02/10/2004	Hours	Description	Quantity
- Transport & Pickup Vehicle At Dealer.(Mass Airflow Problem)	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	50.00

Workorder: 443288

Problem: CHECK ENGINE SOON LIGHT ON

Meter Reading: 7324	Labor	Parts	
In Date: 05/03/2004	Hours	Description	Quantity
- Transport & Pickup Vehicle At Gmc Dealer.(Code P0101,Mass Airflow Sensor)	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	50.00

10/6/2017
10:20:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11240 2003 CHEVROLET 2500 HD Utility Body, 3/4 Ton, Ext Cab, Liftgate

Workorder: 449235

Problem: P.M.SERVICE

Meter Reading: 8639	Labor	Parts	
In Date: 06/28/2004	Hours	Description	Quantity
- Pm Service	4.50	10W30 MOTOR OIL	7.00
- Repair Wiring To R/Rear Body Light		AF1519 AIR FILTER USE LAF1520 FRM CA8755A	1.00
- Transport & Pickup Vehicle At Dealer (Defective Am/Fm Radio)		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		3481 FUEL FILTER FRM G3727 WIX 33481	1.00
Parts Charge:	24.86	Labor Charge:	225.00

Workorder: 449921

Problem: SCREW IN R/F TIRE

Meter Reading: 8740	Labor	Parts	
In Date: 07/06/2004	Hours	Description	Quantity
- Tire Repair	3.00	80865 FUSEHOLDER IMPERIAL 80865	1.00
- Repair Strobe Light-Open In Harness/Repair & Install Inline Holder		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	4.29	Labor Charge:	150.00

Workorder: 533571

Problem: P.M.SERVICE

Meter Reading: 11291	Labor	Parts	
In Date: 01/15/2005	Hours	Description	Quantity
- Pm Service	3.75	10W30 MOTOR OIL	6.00
- Transport & Pickup Vehicle At Dealer.(Clunk In Steering Sys)		3481 FUEL FILTER FRM G3727 WIX 33481	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
Parts Charge:	35.52	Labor Charge:	187.50

10/6/2017
10:20:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11240 2003 CHEVROLET 2500 HD Utility Body, 3/4 Ton, Ext Cab, Liftgate

Workorder: 537831 **Problem:** LEFT REAR TIRE FLAT

Meter Reading: 11798	Labor	Parts	
In Date: 03/02/2005	Hours	Description	Quantity
- Tire Repair	1.50	SHOP SUPPLIES	1.00
- Mount Tire Under Vehicle			
- Shop Supplies			
Parts Charge:		2.00	
		Labor Charge:	75.00

Workorder: 553085 **Problem:** P.M. SERVICE.

Meter Reading: 15455	Labor	Parts	
In Date: 08/15/2005	Hours	Description	Quantity
- Pm Service	5.75	1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
- Replace And Balance All Tires		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Transport Vehicle To Dealer For Driver Door Stop And Defectivew Battery		TR416 VALVE STEM	1.00
		TR416 VALVE STEM	3.00
- Shop Supplies		SHOP SUPPLIES	1.00
		749353434 245/75R16 WRANGLER RT/S E	4.00
		10W30 MOTOR OIL	6.00
Parts Charge:		575.75	
		Labor Charge:	287.50

Workorder: 632217 **Problem:** WINDOW CRANK ON PASSENGER DOOR INOP.

Meter Reading: 17600	Labor	Parts	
In Date: 01/03/2006	Hours	Description	Quantity
- Transport & Pickup Vehicle At Dealer.(Passenger Window Problem)	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:		2.00	
		Labor Charge:	50.00

Workorder: 635290 **Problem:** MINOR WELD REPAIR OR MACHINING.

Meter Reading: 0	Labor	Parts	
In Date: 03/06/2006	Hours	Description	Quantity
- Minor Weld Repair Or Machining.	1.00		
Parts Charge:		0.00	
		Labor Charge:	25.00

10/6/2017
10:20:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11240 2003 CHEVROLET 2500 HD Utility Body, 3/4 Ton, Ext Cab, Liftgate

Workorder: 635726

Problem: P.M.SERVICE

Meter Reading: 18879		Labor		Parts	
In Date: 03/14/2006	Close Date: 03/17/2006	Hours	Description	Quantity	
- Pm Service		5.75	3481 FUEL FILTER FRM G3727 WIX 33481		1.00
- Repair Backup Lights & Tag Lights.			SHOP SUPPLIES		1.00
- R&R Leaf Spring Insulators			31-22 WIPER BLADES 22" WIPER BLADE		2.00
- Service Lift Gate Sys.			15604067 LEAF SPRING INSULATOR INSERT		4.00
- Shop Supplies			10W30 MOTOR OIL		7.00
			1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
Parts Charge: 56.96		Labor Charge: 50.00			

Workorder: 640787

Problem: R/FRONT MARKER LIGHT INOP.

Meter Reading: 20331		Labor		Parts	
In Date: 06/13/2006	Close Date: 06/14/2006	Hours	Description	Quantity	
- Repair R/Front Running Light.		0.50	4114K BULB (ACD)		1.00
Parts Charge: 0.94		Labor Charge: 25.00			

Workorder: 644006

Problem: R/REAR SIGNAL LIGHT INOP.

Meter Reading: 21261		Labor		Parts	
In Date: 08/14/2006	Close Date: 08/17/2006	Hours	Description	Quantity	
- Remove Clean & Lubricate Steering Shaft.Test Drive.		2.00	26098419 STEERING LUBRICANT		2.00
- Repair R/Rear Signal Light Wiring & Replace Fuse.			SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 30.56		Labor Charge: 50.00			

Workorder: 645214

Problem: GUARANTEED BUMPER & SUPPLIERS

Meter Reading: 0		Labor		Parts	
In Date: 08/21/2006	Close Date: 09/08/2006	Hours	Description	Quantity	
- Guaranteed Bumper & Suppliers					
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 568.68	

10/6/2017
10:20:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11240 2003 CHEVROLET 2500 HD Utility Body, 3/4 Ton, Ext Cab, Liftgate

Workorder: 646151

Problem: P.M.SERVICE/DASH LIGHTS INOP.

Meter Reading: 21647	Labor	Parts	
In Date: 09/26/2006	Hours	Description	Quantity
- Pm Service	8.00	1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
- Balance All Tires		A1518C AIR FILTER	1.00
- Convert To Nitrogen System		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Complete Alignment		10W30 MOTOR OIL	7.00
- C/S Dash Light Inop. Could Not Verify Driver'S Concern At This Time. Repair Drivers Side Mirror Bracket		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	60.07	Labor Charge:	75.00

Workorder: 736348

Problem: P.M SERVICE

Meter Reading: 24134	Labor	Parts	
In Date: 03/29/2007	Hours	Description	Quantity
- Pm Service	5.25	10W30 MOTOR OIL	6.00
- Transmission Flush		6678 AIR FILTER FRM CA8755A WIX 46678	1.00
- Rear Differential Service.		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
- Shop Supplies		3481 FUEL FILTER FRM G3727 WIX 33481	1.00
		10020 INJECTOR CLEANER DON'T REORDER	1.00
		31-22 WIPER BLADES 22" WIPER BLADE	2.00
		12345841 GEAR OIL SYNTHETIC 75W-90	3.00
		85/140 GEAR OIL GEAR LUBE	3.00
		SYN/ATF TRANS FLUID SYNTHETIC	16.00
		SHOP SUPPLIES	1.00
Parts Charge:	207.68	Labor Charge:	55.00

10/6/2017
10:20:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11240 2003 CHEVROLET 2500 HD Utility Body, 3/4 Ton, Ext Cab, Liftgate

Workorder: 745481

Problem: P.M SERVICE

Meter Reading: 26413		Labor		Parts	
In Date: 10/11/2007	Close Date: 10/17/2007	Hours	Description	Quantity	
-	Pm Service	4.75	10W30 MOTOR OIL	6.00	
-	Liftgate Service,Lube And Test Operation Of Liftgate.		10020 INJECTOR CLEANER DON'T REORDER	1.00	
-	Electrical Test.Starter Test.Defective Battery,Replace		31-22 WIPER BLADES 22" WIPER BLADE	2.00	
-	Battery And Retest Charging Sys.		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00	
-	Shop Supplies		SHOP SUPPLIES	1.00	
			GROUP 78 BATTERY (ACD 78PS)	1.00	
Parts Charge: 97.10		Labor Charge: 60.00			

Workorder: 833286

Problem: CHECK STARTER.

Meter Reading: 27853		Labor		Parts	
In Date: 01/28/2008	Close Date: 01/30/2008	Hours	Description	Quantity	
-	Diag & Trace Prob To Failed Starter Motor Solnoid Drive	1.50	SHOP SUPPLIES	1.00	
-	Replstarter Motor W/New To Correct Prob.		STARTER	1.00	
-	Shop Supplies				
Parts Charge: 176.05		Labor Charge: 90.00			

Workorder: 836018

Problem: P.M SERVICE,SEE NOTE

Meter Reading: 28946		Labor		Parts	
In Date: 03/25/2008	Close Date: 03/28/2008	Hours	Description	Quantity	
-	Pm Service	10.75	10W30 MOTOR OIL	6.00	
-	Remove Dash Panels To Access Strobe Light Switch.		6678 AIR FILTER FRM CA8755A WIX 46678	1.00	
-	Replaced Strobe Light Switch And Rewired.		L0135-063 LUBRIPLATE CHAIN&CABLE LUBE,03050CRC	1.00	
-	Pressure Test & Inspect Cooling System.Flush & Refill		31-22 WIPER BLADES 22" WIPER BLADE	2.00	
-	System		3481 FUEL FILTER FRM G3727 WIX 33481	1.00	
-	Induction System Cleaning Flush Injectors.		DS-167 TOGGLE SWITCH (STANDARD)	1.00	
-	Inspect & Test Liftgate Assy. Had To Refabricate Power		L17301A ENGINE FOG KIT HARD CARBON (SMART BLEND)	1.00	
-	Lift Gate Latching Brackets.Lube All Liftgate Fittings &		L17040 INJECT CLEANER ONE PART (SMART BLEND)	1.00	
-	Service Liftgate.		SHOP SUPPLIES	1.00	
-	Rotate & High Speed Balance All 4 Tires. Nitro Fill All		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00	
-	Tires.		ANTIFREEZE EXT/LIFE ALL MAKES (PEAK 407)	2.00	
-	Shop Supplies				
Parts Charge: 178.59		Labor Charge: 60.00			

10/6/2017
10:20:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11240 2003 CHEVROLET 2500 HD Utility Body, 3/4 Ton, Ext Cab, Liftgate

Workorder: 841011

Problem: CHECK TIRES, TAIL GATE & A/C

Meter Reading: 31186		Labor		Parts	
In Date: 07/08/2008	Close Date: 07/11/2008	Hours	Description		Quantity
-	Mount And Balance 4 New Tires	6.50	SHOP SUPPLIES		1.00
-	Diag Ac-Repl Defective Blower Resister & Burnt Wiring		A/C BLOWER RESISTOR PIGTAIL		1.00
-	Harnesck For Latest Computer Undates For Blend Door Function.		TIRE DISPOSAL FEE		4.00
-	Service Liftgate And Adjust Hydraulic Mechanism For Correct Tilgate Operation		749353434 245/75R16 WRANGLER RT/S E		4.00
-	Shop Supplies		TR416 VALVE STEM		4.00
			A/C BLOWER RESISTOR		1.00
Parts Charge:		715.66	Labor Charge:	120.00	

Workorder: 845039

Problem: P.M SERVICE

Meter Reading: 32469		Labor		Parts	
In Date: 10/02/2008	Close Date: 10/09/2008	Hours	Description		Quantity
-	Pm Service	9.25	10W30 MOTOR OIL		6.00
-	Perform Minor Tuneup And Throttle Plate Service To Correct Enine Miss.		41-110 SPARK PLUG (ACD)		8.00
-	R&R Worn Engine And A/C Drive Belts.		31-22 WIPER BLADES 22" WIPER BLADE		2.00
-	Service Rear Power Liftgate		1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
-	Rotate & High Speed Balance All 4 Tires.Nitrofill All Tires To Spec.		748HH PLUG WIRES (ACD)		1.00
-	Shop Supplies		3481 FUEL FILTER FRM G3727 WIX 33481		1.00
			K040378HD A/C BELT		1.00
			SHOP SUPPLIES		1.00
			K060923HD SERP BELT		1.00
Parts Charge:		246.83	Labor Charge:	60.00	

Workorder: 933946

Problem: DRIVER SIDEVIEW MIRROR BROKEN.

Meter Reading: 34369		Labor		Parts	
In Date: 02/12/2009	Close Date: 02/17/2009	Hours	Description		Quantity
-	Repl Mirror Assy W/Good Salvage Mirror Also Install New Spotmirror.	1.00	SHOP SUPPLIES		1.00
-	Shop Supplies		7044D 3-3/4" SPOT MIRROR		1.00
Parts Charge:		3.32	Labor Charge:	60.00	

10/6/2017
10:20:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11240 2003 CHEVROLET 2500 HD Utility Body, 3/4 Ton, Ext Cab, Liftgate

Workorder: 937393

Problem: P.M SERVICE

Meter Reading: 35607	Labor	Parts	
In Date: 05/04/2009	Hours	Description	Quantity
- Pm Service	8.25	1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
- Test Charging System. Replace Failed Battery.		GROUP 78 BATTERY (ACD 78PS)	1.00
- Replace Front Left Marker Light, Replace Right Rear Marker Assy. Repair Open In Circuit To Park Lights.		19721 BASE MOUNT 19 SERIES 4" MARKER LIGHT	1.00
- Service Lift Gate.		19200R RED MARK/LIGHT 4" MARKER LIGHT	1.00
- Repair Nail Hole Right Front Tire. Balance All 4, Nitro Fill.		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Shop Supplies		SHOP SUPPLIES	1.00
		10W30 MOTOR OIL	6.00
Parts Charge: 143.67		Labor Charge: 495.00	

Workorder: 944353

Problem: Left t/s inop.

Meter Reading: 37182	Labor	Parts	
In Date: 10/08/2009	Hours	Description	Quantity
- Diagnose Electrical Concern, R&R Failed Fuse Block & Flasher Unit.	3.00	450060020 BATTERY (CR2032)	1.00
- Install Spot Mirror On Driver Side.		SHOP SUPPLIES	1.00
- Shop Supplies		FLASHER MODULE	1.00
		7044D 3-3/4" SPOT MIRROR	1.00
		FUSE BLOCK	1.00
Parts Charge: 299.69		Labor Charge: 180.00	

Workorder: 945969

Problem: pm service

Meter Reading: 37459	Labor	Parts	
In Date: 11/13/2009	Hours	Description	Quantity
- P.M Service.	6.75	10W30 MOTOR OIL	6.00
- Replace Both Control Arm Bumper Stops.		SHOP SUPPLIES	1.00
- Trace & Repair Open Circuit In L/R Tail Lamp, Replace & Rewire L/R Marker Lamp Assembly.		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
- Service Power Lift Gate.		15835666 BUMPER CONTROL ARM (GMC)	2.00
- Rotate & Balance All Four Tires.		USED FIREX REFURBED FIRE EXTINGuishERS	1.00
- Shop Supplies		3481 FUEL FILTER FRM G3727 WIX 33481	1.00
		31-22 WIPER BLADES 22" WIPER BLADE	2.00
		19006R MARKER LIGHT 4" RECTANGULAR RED LED	1.00
Parts Charge: 122.44		Labor Charge: 810.00	

10/6/2017
10:20:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11240 2003 CHEVROLET 2500 HD Utility Body, 3/4 Ton, Ext Cab, Liftgate

Workorder: 1005139

Problem: P.M service.

Meter Reading: 40383		Labor		Parts	
In Date: 05/18/2010	Close Date: 05/24/2010	Hours	Description	Quantity	
- P.M Service.		5.75	10W30 MOTOR OIL		6.00
- Inspect & Service Power Lift Gate.			31-22 WIPER BLADES 22" WIPER BLADE		2.00
- Day Time Running Light Sensor Fell Down Behind Dash, Remove Dash Panels & Reinstall Sensor.			1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
Parts Charge:		31.79	Labor Charge:		345.00

Workorder: 1006826

Problem: Abs.and brake warning light on. Strobe light switch broken,see notes.

Meter Reading: 40930		Labor		Parts	
In Date: 06/29/2010	Close Date: 07/13/2010	Hours	Description	Quantity	
- Test And Replace Failed Strobe Lamp Switch With New.Diagnose Short Circuit.Fabricate And Install New Becon Lamp Assembly With New.Had To Rewire Power Circuit.		6.00	SHOP SUPPLIES		1.00
			BRAKE CONTROL MODULE		1.00
			250ADH12A STROBE STROBE LIGHT 12/24VT		1.00
			DS-167 TOGGLE SWITCH (STANDARD)		1.00
- Computer Diagnose Abs Concern.Test And Replace Failed Electronic Brake Control Module With New.Perform Automated Bleed Abs. System And Road Test.					
- Shop Supplies					
Parts Charge:		673.68	Labor Charge:		360.00

Workorder: 1012662

Problem: Pm service.

Meter Reading: 43081		Labor		Parts	
In Date: 11/12/2010	Close Date: 11/19/2010	Hours	Description	Quantity	
- Perform Pm Service.		4.75	10W30 MOTOR OIL		6.00
- Inspect And Service Power Lift Gate.			22514722 O-RING SEAL FUEL FILTER (ACD 217-452)		2.00
- Rotate And Balance All Four Tires.			6678 AIR FILTER FRM CA8755A WIX 46678		1.00
- Shop Supplies			31-22 WIPER BLADES 22" WIPER BLADE		2.00
			SHOP SUPPLIES		1.00
			1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			3481 FUEL FILTER FRM G3727 WIX 33481		1.00
Parts Charge:		62.21	Labor Charge:		285.00

10/6/2017
10:20:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11240 2003 CHEVROLET 2500 HD Utility Body, 3/4 Ton, Ext Cab, Liftgate

Workorder: 1101480

Problem: Both rear tires flat.

Meter Reading: 44407	Labor	Parts	
In Date: 02/08/2011	Hours	Description	Quantity
- Repair Two Flat Tires Left And Right Rear Wheels.Nitrogen Fill And Balance Both.	2.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	120.00

Workorder: 1106360

Problem: Pm service and tag lamp inop.

Meter Reading: 46466	Labor	Parts	
In Date: 06/16/2011	Hours	Description	Quantity
- P.M. Service.	16.50	1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
- Replace And Rewire Both Tag Lightsand Replace Right Rear Marker Light.		BOLT	1.00
- Replace And Balance All Four Tires.		ANTIFREEZE EXT/LIFE ALL MAKES (PEAK 407)	2.00
- Test And Replace Defective Left Front Speaker.		LT245/75R16 TIRE	2.00
- Pressure Test And Inspect Cooling System.Replace Leaking Water Pump And Thermostat.Flush And Refill System.		SHOP SUPPLIES	1.00
- Complete Wheel Alignment.		19006R MARKER LIGHT 4" RECTANGULAR RED LED	1.00
- Inspect And Service Liftgate.		31-22 WIPER BLADES 22" WIPER BLADE	2.00
- Shop Supplies		179747492 LT245/75R16 WRANGLER SR-A E	2.00
		THERMOSTAT	1.00
		10W30 MOTOR OIL	6.00
		DOOR SPEAKER	1.00
		TIRE DISPOSAL FEE	4.00
		WATER PUMP	1.00
		26331 TAG LIGHT	2.00
Parts Charge:	877.20	Labor Charge:	990.00

10/6/2017
10:20:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11240 2003 CHEVROLET 2500 HD Utility Body, 3/4 Ton, Ext Cab, Liftgate

Workorder: 1200043

Problem: Pm service

Meter Reading: 50154		Labor		Parts	
In Date: 01/03/2012	Close Date: 01/19/2012	Hours	Description	Quantity	
-	Perform Pm Service.	10.25	1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00	
-	Test And Replace Failed Drl Bulb And Socket With New.Secure And Insulate Wiring.		3481 FUEL FILTER FRM G3727 WIX 33481	1.00	
-	Computer Diagnose Instrument Cluster For Prndl Indicator		10W30 MOTOR OIL	6.00	
-	Inop.Test And Replace Failed Instrument Cluster With New And Reprogram With Tech 2.		SHOP SUPPLIES	1.00	
-	Test Starting And Charging System.Battery Failed		GROUP 78 BATTERY (ACD 78PS)	1.00	
-	Loadtest After Recharge.Replace Failed Battery With New.		4114K BULB (ACD)	1.00	
-	Inspect And Service Liftgate.		31-22 WIPER BLADES 22" WIPER BLADE	2.00	
-	Rotate And Balance All Four Tires.		INSTRUMENT CLUSTER	1.00	
-	Shop Supplies		USED FIREX REFURBED FIRE EXTINGSHERS	1.00	
			LS94 BULB SOCKET DRIVE LIGHT (ACD)	1.00	
Parts Charge: 460.81		Labor Charge: 615.00			

Workorder: 1201422

Problem: Check battery and charging systems and turn signals fflash fast at times.

Meter Reading: 50812		Labor		Parts	
In Date: 02/13/2012	Close Date: 02/16/2012	Hours	Description	Quantity	
-	Fully Recharge Battery.Test Starting And Charging System.Test And Replace Failed Alternator Assembly With New.	1.75	SHOP SUPPLIES	1.00	
-	Clean Left Side Mirror And Replace Missing Spot Mirror With New.		7039D SPOT MIRROR VELVAC 723060	1.00	
-	Shop Supplies		ALTERNATOR	1.00	
Parts Charge: 149.03		Labor Charge: 105.00			

Workorder: 1202370

Problem: Left rear tire going flat.

Meter Reading: 51232		Labor		Parts	
In Date: 03/08/2012	Close Date: 03/12/2012	Hours	Description	Quantity	
-	Repair And Balance Left Rear Tire.	1.00	SHOP SUPPLIES	1.00	
-	Shop Supplies				
Parts Charge: 2.00		Labor Charge: 60.00			

10/6/2017
10:20:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11240 2003 CHEVROLET 2500 HD Utility Body, 3/4 Ton, Ext Cab, Liftgate

Workorder: 1208112

Problem: P.M. service and left rear door inop.

Meter Reading: 54619		Labor		Parts	
In Date: 08/27/2012	Close Date: 09/17/2012	Hours	Description	Quantity	
-	P.M. Service.	5.50	1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00	
-	Replace Broken Rear Door Outside Handle.		10W30 MOTOR OIL	6.00	
-	Rotate And Balance All Tires.		SHOP SUPPLIES	1.00	
-	Inspect And Service Liftgate.		89025539 DOOR HINGE BUSHING KIT (GMC)	1.00	
-	Shop Supplies		LEFTREAR SIDE DOOR HANDLE	1.00	
			89025539 DOOR HINGE BUSHING KIT (GMC)	1.00	
			31-22 WIPER BLADES 22" WIPER BLADE	2.00	
Parts Charge:		226.43	Labor Charge:	330.00	

Workorder: 1304423

Problem: Pm servicecheck for noise when starting and switch by shifter handle

Meter Reading: 57568		Labor		Parts	
In Date: 05/03/2013	Close Date: 05/10/2013	Hours	Description	Quantity	
-	Perform Pm Service.	10.75	31-22 WIPER BLADES 22	2.00	
-	Test Starting And Charging System.Replace Failed		SHOP SUPPLIES	1.00	
	Starter Motor Assembly With New.		STEERING WHEEL COVER	1.00	
-	Install Four New Tires.Nitrogen Fill And Balance All Four.		10W30 MOTOR OIL	6.00	
-	Perform Wheel Alignment Complete.		22514722 O-RING SEAL	2.00	
-	Inspect And Service Power Winch.		NAPAGOLD OIL FILTER	1.00	
-	Shop Supplies		NEW STARTER	1.00	
			USED FIRE X REFURBISHED	1.00	
			TIRE DISPOSAL FEE	4.00	
			179747492 LT245-75R16	4.00	
			NAPAGOLD FUEL FILTER	1.00	
Parts Charge:		1,106.81	Labor Charge:	645.00	

Workorder: 1308387

Problem: Check for coolant leak.

Meter Reading: 59143		Labor		Parts	
In Date: 08/20/2013	Close Date: 09/05/2013	Hours	Description	Quantity	
-	Pressure Test And Inspect Cooling System.Replace	3.00	NAPA RADIATOR	1.00	
	Failed Radiator With New.Flush And Renew Engine		STEERING WHEEL COVER	1.00	
	Coolant.Install New Steering Wheel Cover.		SHOP SUPPLIES	1.00	
-	Shop Supplies		PEAK GLOBAL	1.00	
Parts Charge:		286.24	Labor Charge:	180.00	

10/6/2017
10:20:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11240 2003 CHEVROLET 2500 HD Utility Body, 3/4 Ton, Ext Cab, Liftgate

Workorder: 1311408

Problem: Pm service.

Meter Reading: 59697		Labor		Parts	
In Date: 11/12/2013	Close Date: 11/25/2013	Hours	Description	Quantity	
-	P.M. Service.	7.25	SHOP SUPPLIES	1.00	
-	Service Transmission.Flush And Refill System.		FILTER KIT	1.00	
-	Inspect And Service Lift Gate.		NAPAGOLD OIL FILTER	1.00	
-	Rotate And Balance All Tires.		FILTER	1.00	
-	Shop Supplies		SYN-ATF TRANS FLUID S	16.00	
			10W30 MOTOR OIL	6.00	
Parts Charge: 111.78		Labor Charge: 435.00			

Workorder: 1401353

Problem: Right rear tire going flat.

Meter Reading: 60971		Labor		Parts	
In Date: 02/10/2014	Close Date: 02/19/2014	Hours	Description	Quantity	
-	Repair And Balance Right Rear Tire.	1.00	SHOP SUPPLIES	1.00	
-	Shop Supplies				
Parts Charge: 2.00		Labor Charge: 60.00			

Workorder: 1405918

Problem: Pm service .Lift gate cable and speakers.

Meter Reading: 62096		Labor		Parts	
In Date: 06/17/2014	Close Date: 07/10/2014	Hours	Description	Quantity	
-	Perform Pm Service.	7.30	USED FIRE X REFURBISHED	1.00	
-	Test Starting And Charging System.Battery Failed		WIPER BLADE	2.00	
-	Loadtest After Recharge.Replace Failed Battery With New		Freight Charge	1.00	
-	Warranty Part.		CABLE RELEASE KIT	1.00	
-	Inspect And Service Lift Gate.Replace Failed Latch And		10W30 MOTOR OIL	6.00	
-	Cable With New.		NAPAGOLD OIL FILTER	1.00	
-	Rotate And Balance All Four Tires.		NAPAGOLD FUEL FILTER	1.00	
-	Remove Driver Door Trim.Test And Replace Failed		GROUP 78 BATTERY	1.00	
-	Speaker With New.		SPEAKER	1.00	
-	Shop Supplies		SHOP SUPPLIES	1.00	
Parts Charge: 178.35		Labor Charge: 438.00			

10/6/2017
10:20:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11240 2003 CHEVROLET 2500 HD Utility Body, 3/4 Ton, Ext Cab, Liftgate

Workorder: 1508577

Problem: Pm service.

Meter Reading: 67187	Labor	Parts	Quantity
In Date: 08/26/2015	Hours	Description	Quantity
- Pm Service.	14.75	PREMIUM PLUG WIRE SET	1.00
- Check Battery And Charging System.Battery Failed Load		10W30 MOTOR OIL	6.00
Test.Replace Defective Battery.Replace Battery Terminals		NAPAGOLD OIL FILTER	1.00
And On Back Up Lamp Bulb.		NAPAGOLD FUEL FILTER	1.00
- Replace Two Defective Front Bounce Stops.		GROUP 78 BATTERY	1.00
- Replace All Eight Spark Plugs And Ignition Wires.		WIPER BLADE	2.00
- Replace Two Tires.Rotate And Balance All Four.		LT245/75R16 MIC TIRE	2.00
- Replace One Defective White Heater Hose Quick Coupler		TIRE DISPOSAL FEE	2.00
And Other Complete Heater Hose Assemblyflush And		PEAK GLOBAL	1.00
Replace Engine Coolant		SHOP SUPPLIES	1.00
- Inspect And Service Power Liftgate.		BRAKE CLEANER	1.00
- Shop Supplies		15835666 BUMPER CONTR	2.00
		QUIK CONNECTOR	1.00
		BATTERY CABLE BOLT	1.00
		hose	2.00
		SPARK PLUG	8.00
		LAMP	1.00
		PREMIUM PLUG WIRE SET	1.00
Parts Charge:	963.00	Labor Charge:	885.00

10/6/2017
10:20:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11240 2003 CHEVROLET 2500 HD Utility Body, 3/4 Ton, Ext Cab, Liftgate

Workorder: 1602989

Problem: Pm service.

Meter Reading: 71467	Labor	Parts	
In Date: 03/22/2016	Hours	Description	Quantity
- P.M. Service.	14.00	TIRE DISPOSAL FEE	2.00
- Replace Two Tires,Rotate And Balance All Four.		FLEETRANNER BELT	1.00
- R&R Damaged Transmission Crossmember.		SHOP SUPPLIES	1.00
- Replace Pittman Arm And Idler Arm.		TRAMSMISSION CROSSMEMB	1.00
- Replace Both Serpentine Belts.		22" WIPER BLADE	2.00
- Complete Wheel Alignment.Test Drive.		LONG LIFE SMALL BULB	1.00
- Inspect And Service Liftgate.		WASHER FLUID CONCENTR	1.00
- Shop Supplies		FLEETRANNER BELT	1.00
		LT245 75R16 MICH LTX MS2	2.00
		10W30 MOTOR OIL	6.00
		IDLER ARM BRACKET	1.00
		TR416 VALVE STEM	2.00
		NAPAGOLD OIL FILTER	1.00
		PITMAN ARM ASSEMBLY	1.00
		USED FIRE X REFURBISHED	1.00
		IDLER ARM ASSEMBLY	1.00
Parts Charge:	931.54	Labor Charge:	840.00

Workorder: 1610964

Problem: No start

Meter Reading: 76109	Labor	Parts	
In Date: 10/24/2016	Hours	Description	Quantity
- Tow From: Cell Phone Lot Of Airport To: Lv Shop			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	96.00

10/6/2017
10:20:23AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11240 2003 CHEVROLET 2500 HD Utility Body, 3/4 Ton, Ext Cab, Liftgate

Workorder: 1706226

Problem: P.M. Service.Replace beacon light switch.Steering wheel worn out.

Meter Reading: 79124		Labor		Parts	
In Date: 06/23/2017	Close Date: 07/10/2017	Hours	Description		Quantity
-	P.M. Service.	7.35	ROCKER LED BLK AMBE		1.00
-	Replace Beacon Lamp Switch With Rocker Type.Rewire As Needed.		10W30 MOTOR OIL		6.00
-	Replace Worn Steering Wheel.Install Cover.		22" WIPER BLADE		2.00
-	Replace Missing Safety Chains On Right Center Utility Box Door.		NAPAGOLD OIL FILTER		1.00
-	Replace Failed Left Running Lamp Bulb And Socket.		PIGTAILS SOCKETS		1.00
-	Rotate And Balancce Four Tires.Nitrofill.		USED FIRE X REFURBISHED		1.00
-	Inspect And Service Power Liftgate.		STG WHEEL COV - CHEVY		1.00
-	Shop Supplies		LONG LIFE SMALL BULB		1.00
			DOOR CHAIN		2.00
			SHOP SUPPLIES		1.00
			WASHER FLUID CONCENTR		1.00
			STEERING WHEEL		1.00
Parts Charge: 445.95		Labor Charge: 441.00			

Workorder: 1706619

Problem: 1 - Key(s) issued

Meter Reading: 78957		Labor		Parts	
In Date: 07/06/2017	Close Date: 07/06/2017	Hours	Description		Quantity
-	1 - Key(S) Issued	0.30	DUPLICATE VEHICLE KEYS		1.00
Parts Charge: 3.00		Labor Charge: 18.00			

Workorder: 1708735

Problem: No reverse gear.

Meter Reading: 80215		Labor		Parts	
In Date: 09/05/2017	Close Date:	Hours	Description		Quantity
-					
Parts Charge: 0.00		Labor Charge: 0.00			

Total Parts Charges:	12,987.29	Total Labor Charges:	14,114.50	Total Comm. Charges:	664.68
----------------------	------------------	----------------------	------------------	----------------------	---------------