



10/17/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V248

In Date: 10/17/2005
Close Date: 10/18/2005

Meter Reading:

Problem?

PASS, SIDE MIRROR BOLT BROKEN R-55B

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V546

In Date: 11/14/2005
Close Date: 11/18/2005

Meter Reading:

Problem?

A/C KNOBS BROKE, DOOR ADJAR LIGHT ON R55

Task performed:

Parts

Quantity

2000071102000072100 SOLENOID HALE PRIMER

1

87141USE LED MAP LIGHT 24"

1

ABPN8332229011-3050 SWITCH BLOWER

1

EL41023AUTO THROTTLE

1

I03100PT-2XE-IO3100PT3-S0B 600 TRANSDUCER INT

1

MG-C23SPMGC23 GAUGE

1



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V783

In Date: 12/02/2005
Close Date: 12/27/2005

Meter Reading: 51,934.00

Problem?

B INSPECTION R55

Task performed:

See B Inspection pre-printed form

Parts	Quantity
020383470CROLENS RED/C USE 4 SCREW LENS NOW	2
1895BULB	2
284142VALVE SAFETY ST-3	1
3937072PAN GASKET B ENG USE 3959052	1
52-24WIPER BLADES ANCO 24	2
6806970098SEAL DOOR	1
9451BELT	1
9485BELT	1
CA8193AIR FILTER 46744 WIX	1
HLD374211 IN HOLD-OPEN 30LB	1
HLD39916USE EAA-8200-60 STRUT 60#	2
HND5941USE HAN-1L METAL LATCH INTERIOR LOCKING	2
K080733BELT	1
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
RN60JDRYER KIT	1
S3225PFUEL FILTER 33630 LFF5849	1
SPR-W58-1TEE PLASTIC	1
VML-S1414FILTER P/S	1
VML-T1264GASKET P/S COVER	1
VML-T1279WASHER P/S	1

Workorder: V999

In Date: 12/22/2005
Close Date: 12/27/2005

Meter Reading:

Problem?

THE REAR AIRBAG ON THE DRIVER SIDE NOT FILLING UP, R-55B

Task performed:

Parts	Quantity
284358GOVERNOR D-2	1
VHD18537USE 284358 AIR GOVERNOR D-2 KN18537	1



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V695

In Date: 11/28/2005

Meter Reading:

Close Date: 12/29/2005

Problem?

NEED ENGINE OIL, R-55

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1100

In Date: 01/03/2006

Meter Reading:

Close Date: 01/06/2006

Problem?

A/C IN PAT, COMPT, INOP, R-55B

Task performed:

Parts

Quantity

UNT7744USE PINK A/C FILTER MEDIC MASTER

3

Workorder: V1187

In Date: 01/17/2006

Meter Reading:

Close Date: 01/24/2006

Problem?

SIDE ENTRY DOOR LATCH INOP, OVERHEAD GAUGES SCREWS FALLING OUT, R-55B

Task performed:

Parts

Quantity

HND5948TM22676-02 HANDLE DOOR ENTRY

2

LTC5993SSM1-63-8 LATCH STAINLESS

1

Workorder: V1270

In Date: 01/24/2006

Meter Reading:

Close Date: 02/01/2006

Problem?

R/SIDE TURN SIGNAL INOP, REAR AND RIGHT SIDE SCENE LITE INOP, R-55B

Task performed:

Parts

Quantity

PSP5911CIRCUIT BOARD 21

1



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V1548

In Date: 02/17/2006

Meter Reading:

Close Date: 03/03/2006

Problem?

FRONT A/C INOP, R-55B

Task performed:

Parts	Quantity
ABPN83321070RESISTOR BLOWER	1
ABPN8332229011-3050 SWITCH BLOWER	2

Workorder: V1654

In Date: 02/28/2006

Meter Reading:

Close Date: 03/15/2006

Problem?

REAR STROBE ON PASS/SIDE INOP, D/SIDE TURN SIGNAL INOP, ROOF SPOT LIGHT WILL NOT ROTATE, R-55B

Task performed:

Parts	Quantity
SPT6008146SL LIGHT-REMOTE SPOT	1
TURBO5TUBE - STROBE	2

Workorder: V1590

In Date: 02/22/2006

Meter Reading:

Close Date: 03/20/2006

Problem?

HOOD LATCH BROKEN, R-55B

Task performed:

Parts	Quantity
17-14781-000PLASTIC HOOD LATCH	1
HA238CHA238C STROBE BULB	1

Workorder: V2092

In Date: 04/04/2006

Meter Reading:

Close Date: 04/05/2006

Problem?

OVER HEAD PANEL LOOSE, R-55B

Task performed:

Parts	Quantity
NO PARTS USED	



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V2549

In Date: 05/10/2006

Meter Reading:

Close Date: 05/24/2006

Problem?

CHECK FOR AIR LEAK, R-55B

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3009

In Date: 06/15/2006

Meter Reading:

Close Date: 06/19/2006

Problem?

door open light continuously blinks when placed in drive. light causing hazard to driver.

Task performed:

Parts

Quantity

NO PARTS USED



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V3386

In Date: 07/10/2006

Meter Reading: 59,759.00

Close Date: 07/24/2006

Problem?

BINSPECTION AND REPAIRS AS NEEDED

Task performed:

<u>Parts</u>	<u>Quantity</u>
071601A07-0602A DRIER A/C 7118	1
19282TAPE ANTI-SLIP PER FT 60FT ON ROLL	4
22-49905-000CABLE HEATER	1
22512960001498 SWITCH BINA	1
23-12080-150BOLT BUMPER	2
322502BULB PATIENT GH22	1
381 838 02 19DASH VENT	1
3911638PLUG OIL DRAIN C	1
3920773WASHER DRAIN PLUG	1
3944427INTAKE HOSE NEW #3949710	1
52-24WIPER BLADES ANCO 24	2
6805450828PLUG A/C BLR	1
6806890001LOCK DASH	3
6808300174VENT A/C RH	2
716907-0610A DRYER	1
9451BELT	1
9485BELT	1
A1834388002MOLD L/H	1
A1834388003MOLD R/H	1
A22451940011499 SWITCH A/C HIGH PRESSURE NC	1
ABPN8332229011-3050 SWITCH BLOWER	1
CA46362CA46362 RUBBER D-GRABBER	1
CA8193AIR FILTER 46744 WIX	1
K080733BELT	1
L1261F33585XE FUEL FILTER WIX	1
MK184HDBRAKE PADS	2
PH8942FILTER OIL 57182 LFP3729	1
RN60JDRYER KIT	1
S3225PFUEL FILTER 33630 LFF5849	1
SWT5924DOOR OPEN MAP DISPLAY	1
TRW-L24VC0109DRAG LINK BOOT	2
TURBO5TUBE - STROBE	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1
VML-T1264GASKET P/S COVER	1



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V3427

In Date: 07/12/2006
Close Date: 07/24/2006

Meter Reading:

Problem?

tires at callaghan

Task performed:

Parts

Quantity

NO PARTS USED

Vendor? VC-15214

Workorder: V3667

In Date: 07/27/2006
Close Date: 07/31/2006

Meter Reading:

Problem?

rear A/c blowing hot air not cooling R55A

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V4222

In Date: 09/03/2006
Close Date: 09/13/2006

Meter Reading:

Problem?

reverse lights out R55A

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V5818

In Date: 12/14/2006
Close Date: 12/19/2006

Meter Reading: 62,026.00

Problem?

INSTALL FISH PLATE ON FRAME RAIL

Task performed:

Parts

Quantity

1. CRACKEDE FRAME RAIL- REMOVE STABILISER BAR FROM REAR & FRAME TO INSTALL FISH PLATE
2. PERFORM PM "A" INSPECTION.

15-21698-001REINFORCEMENT

1

161657700065489 SHOCK REAR NEW RESCUE

2



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V5934

In Date: 12/23/2006
Close Date: 01/03/2007

Meter Reading: 5,617.70

Problem?

2 clearance lights out, 1- driver side upper rear of box, 1- on top of rear light bar driver side R47

Task performed:

1. Replaced ground on marker light

Parts

NO PARTS USED

Quantity

Workorder: V6047

In Date: 01/02/2007
Close Date: 01/04/2007

Meter Reading: 62,952.00

Problem?

REPLACE BAD TURBO A INSPECTION SR5 BACK FROM 47

Task performed:

1. R&R bad turbo. Removed charge air cooler and sent out for cleaning
2. Performed A Inspection
3. Repaired marker lights

Parts

1445BULB
3802778RXTURBO
3883284O-RING AIR INTAKE
DR4-RADDR4-RADIATOR

Quantity

2
1
1
6

Workorder: V6538

In Date: 01/30/2007
Close Date: 02/01/2007

Meter Reading: 63,456.00

Problem?

a inspection and repairs as needed sr5

Task performed:

1. A Inspection
2. Fuel leak R&R transfer pump
3. Replace engine oil and filter
4. Hand light charger inop R&R charger

Parts

39663983USE 3963983 WASHER-FUEL SYS.
39901054943048 FUEL PUMP ISB
PH8942FILTER OIL 57182 LFP3729

Quantity

1
1
1

Workorder: V6761

In Date: 02/14/2007
Close Date: 02/21/2007

Meter Reading: 63,993.00

Problem?

A Inspection and related repairs

Task performed:

1. PERFORMED PM A INSPECTION.

Parts

435 VALVE CAP
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF
HP-31DBATTERY 950CCA HP-31D

Quantity

2
4
4



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V8018

In Date: 04/30/2007

Meter Reading: 67,369.00

Close Date: 05/07/2007

Problem?

B inspection and related repairs (back from 31)

Task performed:

- B-Inspection
- 1. Rebuild air brake dryer; rem air dryer twice; (pinched o-ring during 1st overhaul)
- 2. Rep trans harness that had melted on exh pipe
- 3. Replc wiper blades & unclogged squirters
- 4. Replc (2) cab roof mrkr light bulbs.
- 5. Replce (2) A/C dash vent defuser
- 6. Replc driver's side door weatherstrip
- 7. Replc compartment light high beam.
- 8. install new velcro to anchor 02 wrench

Parts	Quantity
194BULB	2
322502BULB PATIENT GH22	1
52-24WIPER BLADES ANCO 24	2
6808300074VENT A/C LH	1
6808300174VENT A/C RH	1
CA8193AIR FILTER 46744 WIX	1
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
RN60JDRYER KIT	2
S3225PFUEL FILTER 33630 LFF5849	1

Workorder: V7756

In Date: 04/16/2007

Meter Reading: 5,990.00

Close Date: 05/08/2007

Problem?

Spotlight on roof of rescue is not moving. R31

Task performed:

- Repaired connection on light.
- Adjusted rear entrance door linkage

Parts	Quantity
CB-50TRUCK NUMBER BRACKET	1

Workorder: V8401

In Date: 05/23/2007

Meter Reading: 65,102.00

Close Date: 05/31/2007

Problem?

A inspection and related repairs (back from 21)

Task performed:

- 1. A-Inspection & Road test
- 2. L-3 & L-4 Panel & Door hold open screws missing or loose - retap and secure

Parts	Quantity
NO PARTS USED	



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V9046

In Date: 06/27/2007

Meter Reading: 67,823.00

Close Date: 07/02/2007

Problem?

A inspection (back from 27) and related repairs

Task performed:

A-Inspection
Adjust A/C controls to get A/C out of defrost mode(stuck)

Parts

NO PARTS USED

Quantity

Workorder: V9261

In Date: 07/11/2007

Meter Reading: 67,823.00

Close Date: 07/16/2007

Problem?

Flat tire (in yard)

Task performed:

1. THIS WORK ORDER HANDLED BY CALLAGHAN.

Parts

NO PARTS USED

Quantity

Workorder: V9265

In Date: 07/11/2007

Meter Reading: 67,823.00

Close Date: 07/30/2007

Problem?

replace tire (outside agency-callaghan tire)

Task performed:

Replace tire - Callaghan

Parts

NO PARTS USED

Quantity

Vendor? CALLAGHAN

Workorder: V9466

In Date: 07/23/2007

Meter Reading: 68,083.00

Close Date: 07/31/2007

Problem?

A INSPECTION AND REPAIRS

Task performed:

1. MEETING WITH LEHAN.
2. A INSPECTION.
3. L-2 COMPT DOOR HOLDOPENS- REMOUNT TO COMP WALL- BOTH SIDES
4. REAR DOOR HARD TO OPEN- REMOVE PANELS TO READJUST LATCH LINKAGE- REPAIR STRIPPED HOLES.

Parts

HLD3999GSS1715UV 30LB STRUT GAS
HND5941USE HAN-1L METAL LATCH INTERIOR LOCKING

Quantity

8
1



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V9818

In Date: 08/10/2007

Meter Reading: 68,220.00

Close Date: 08/16/2007

Problem?

A inspection and related repairs (back from 47)

Task performed:

- A-Inspection & road test
- 1. Patient comp A/C filter - rem/in stall new filter
- 2. Compt door panels loose; sec all loose screws

Parts

Quantity

UNT7744USE PINK A/C FILTER MEDIC MASTER

1

Workorder: V10403

In Date: 09/12/2007

Meter Reading: 6,289.00

Close Date: 09/24/2007

Problem?

patient compartment not cooling R23

Task performed:

- 1. A/C INOP, COMPRESSOR BAD AND CONDENSOR DIRTY, REPLACED COMPRESSOR AND CLEANED CONDENSOR.
- 2. A/C INOP REPLACED COMPRESSOR AND CLEANED CONDENSOR.
- 3. ALTERNATOR NOT CHARGING, REPLACED ALTERNATOR

Parts

Quantity

4867JB320 UPGRADE ALTERNATOR

1

532703-0602 COMPRESSOR U4735 4471

1



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V4321

In Date: 09/07/2006

Meter Reading:

Close Date: 10/15/2007

Problem?

Noticed at morning checkout that the drivers side rear emergency light is missing the red lens cover. R55

Task performed:

B INSPECTION MINUS FILTERS AND FLUID FOR EVALUATION
REPLACE DRIVERS DOOR TRIM,PASSENGER DOOR SEAL, MAP LIGHT,BATTERY SWITCH
REPLACE STROBE LIGHT TOP LEFT REAR, PATIENT COMP. DOOR LATCH BEZELS,PATIENT COMP. A/C FILTER
INSTALL WEATHERSTRIP 3 COMP. DOORS,REPLACE NON-SKID SIDE ENTRY DOOR,REPLACE 2 HIGH BEAM BULBS PATIENT COMP.
TROUBLE SHOOT BACK-UP ALARM/LIGHTS INOP AND REPAIR WIRING AT CIRCUIT BOARD
SWAP INTO ON-CALL TRUCK
GO TO RED WING
CLEAN SHOP

Parts

Quantity

02038068900CSTROBE LT.	1
19282TAPE ANTI-SLIP PER FT 60FT ON ROLL	3
322502BULB PATIENT GH22	2
51-30219-1045 MASTER SWITCH 175 AMP	1
6806970098SEAL DOOR	1
6811802645S68-1180264-5S LENS RED	1
87141USE LED MAP LIGHT 24"	1
A1834388002MOLD L/H	1
HND5941USE HAN-1L METAL LATCH INTERIOR LOCKING	2
UNT7744USE PINK A/C FILTER MEDIC MASTER	1

Workorder: V6045

In Date: 01/02/2007

Meter Reading: 62,952.00

Close Date: 10/15/2007

Problem?

TOW UNIT FROM BOYNTON AND MILITARY TO SHOP SISTERS TOWING SR5 AT 47

Task performed:

1. Tow unit from Boyton and Military to shop Sisters Towing SR5 at 47

Vendor? SISTERS TOWING

Parts

Quantity

NO PARTS USED

Workorder: V10785

In Date: 10/02/2007

Meter Reading: 70,711.00

Close Date: 10/26/2007

Problem?

TOW UNIT FROM STA 23 TO SHOP SR5

Task performed:

tow unit from Stn23 to shop - Sister's Towing

Vendor? SISTER'S TOWING

Parts

Quantity

NO PARTS USED



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V9732

In Date: 08/06/2007 Meter Reading: 68,219.00
Close Date: 01/14/2008

Problem?

A INSPECTION AND REPAIRS SR5 BACK FROM 47

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V12265

In Date: 12/28/2007 Meter Reading: 70,711.00
Close Date: 01/16/2008

Problem?

C INSPECTION AND REPAIRS AS NEEDED SR5 BACK FROM 23

Task performed:

Parts

Quantity

C-Inspection	15W40BSYN OIL BULK QTS	33
2. Eng oil leak-push rod cover gasket; replc push rod cover gasket	23-09446-600SPRING BOLT	2
1/4/08 5.0 hrs	23-09901-110HEX NUT 5/8	8
1/10/08 5.0 hrs	23-13175-112NUT HEX C07G33	2
1/14/08 3.0 hrs Total 13.0 hrs	2332920005SMASK LENS W/RST BUTTON VDO	1
3. Rotate tires-uneven wear	3928759GROMMET SEAL ISB	6
4. Pat comp door-screws msng; stripped threads; replc panels	39288323928832 GASKET	1
5. Search lite inop; wires pulled out at control; rep wiring	3931604USE 3969988 GASKET ISB	2
6. 02 door holdpn worn out; installed new holder	3935032O-RING ISB	1
7. Fan clutch damaged; replc fan clutch	39663983USE 3963983 WASHER-FUEL SYS.	1
8. A/C inop; blowing out defrost; cables stuck; rep flaps; lube.	4ZM08MINITURE REGULATOR	1
1/3/08 1.0 hrs	996019FAN CLUTCH 680-200-06-26	1
1/4/08 1.0 hrs total 2.0 hrs	A16-14307-000BRACKET FRAME SPRING	2
9. Frnt spring hangers heated w/torch; replc spring hangers	CA46362CA46362 RUBBER D-GRABBER	1
10. Pat compt trim fell off; reinstalled trim	DOOR2LEXAN 14.5 X 8.5	1
11. installed clamps for A/C & header hoses on top of motor	L1261F33585XE FUEL FILTER WIX	1
12. Replc air fitting on gov on air compressor	PH8942FILTER OIL 57182 LFP3729	1
13. reposition steering whl on center j	S3225PFUEL FILTER 33630 LFF5849	1
	S777COUPLING NIPPLE	2
	S778COUPLING	1



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V13253

In Date: 02/14/2008

Meter Reading:

Close Date: 02/15/2008

Problem?

rotator light out on rear light bar. r72

Task performed:

- | Task performed: | Parts | Quantity |
|-------------------------|-------------|----------|
| 1. R & R light H 27-55W | H27SN12BULB | 1 |

Workorder: V13665

In Date: 03/04/2008

Meter Reading: 6,422.60

Close Date: 03/13/2008

Problem?

electric shore line not working on rescue 72. rescue located at sta 72

Task performed:

- | Task performed: | Parts | Quantity |
|---|---------------|----------|
| 1. installed auto eject plug that was not working | NO PARTS USED | |

Workorder: V13833

In Date: 03/12/2008

Meter Reading: 6,497.00

Close Date: 03/17/2008

Problem?

Fix air leak some where in the back of the rescue air bleeds out quickly when truck is not running and takes a long lime to build up
Also the the air suspension has intermittent problems. R-72

Task performed:

- | Task performed: | Parts | Quantity |
|---|---------------|----------|
| 1. check out. found air dump switch on in dash. | NO PARTS USED | |
| 2. repair wires on left rear strobe light. | | |

Workorder: V14029

In Date: 03/20/2008

Meter Reading: 6,497.00

Close Date: 03/24/2008

Problem?

front cab a/c does not work. Fan belt screeches. R-72

Task performed:

- | Task performed: | Parts | Quantity |
|---|-----------------------------------|----------|
| 1. foubd fan switch inop, remove dash panels to r/r switch. | 6805450828PLUG A/C BLR | 1 |
| 2. air leak- found air hourn valve leaking, r/r valve. | ABPN8332229011-3050 SWITCH BLOWER | 1 |
| | BRK591254-720 CIRCUIT BREAKER 20A | 1 |
| | EL360081760611 SOLENOID AIR HORN | 1 |



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V14346

In Date: 04/07/2008
Close Date: 04/10/2008

Meter Reading: 6,600.00

Problem?

check engine light is staying on R72

Task performed:

1. check engine lite on. inactive code (434) cleared code advised crew of proper shutdown.

Parts

NO PARTS USED

Quantity

Workorder: V14292

In Date: 04/04/2008
Close Date: 04/14/2008

Meter Reading: 75,898.00

Problem?

repair a/c and air leak r72

Task performed:

1. evacuate/charge A/C system.
2. repair air leaks at governor, airhorn valve and air tank drains

Parts

EL360081760611 SOLENOID AIR HORN

Quantity

2

Workorder: V14514

In Date: 04/16/2008
Close Date: 05/02/2008

Meter Reading: 6,640.00

Problem?

left side rear marker light is out. interior patient compartment dome light is out.R72

Task performed:

1. Repaired lights

Parts

322502BULB PATIENT GH22

921LIGHT BULB

Quantity

1

1

Workorder: V14878

In Date: 05/05/2008
Close Date: 05/12/2008

Meter Reading: 77,983.00

Problem?

shore line a/c 10-7 r72

Task performed:

Drive to Stn72; check out & charged up shore line A/C;
drive back to shop. j

Parts

NO PARTS USED

Quantity



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V14957

In Date: 05/08/2008
Close Date: 05/30/2008

Meter Reading: 78,651.00

Problem?

B inspection and repairs as needed r72 air leak at p brke valve paitent a/c 10-7 shore line a/c 10-7

Task performed:

- B-Inspection
- 2. Svc batrys; repl all (4) btrys; replc pos/neg btry jumpers; rep term ends & sec btry holddown anchor pins.
- 3. Replc rear ale air bags(dried, cracked, separating)
- 4. Replc all brakes
 - 5/12/08 2.0 hrs
 - 5/13/08 3.0 hrs
- 5. Rep dash A/C vent control; diss dash; adj all cables; straighten cable ends; rerouted cables for easy cable movement; reassembled dash.
- 6. Replc wiper blades.
- 7. Clnd debris from windshld squirters
- 8. trbleshoot 110V A/C inop; raced probl to faulty compressor causing brkr to trip; replc compressor, vac & recharged.
 - 5/13/08 1.5 hrs
 - 5/14/08 2.0 hrs
- 9. Replc inner door latch bezel on pat compt side entry door(broken).
- 10. Replc parking brake valve in dash(leaking)
- 11. Clnd work area after PM j

Parts

Quantity

103899KNOB PARKING BRAKE	1
15W40BSYN OIL BULK QTS	24
16-15762-00016-19471-000 AIR BAG	2
276567XVALVE DASH PP1	1
52-24WIPER BLADES ANCO 24	2
A0631087000CABLE BATT. POS.	1
A0631088000CABLE BATT. NEG.	1
ACX-84534LUG NUT COVER PK10	2
AEVDOOR LOCK BEZEL	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER	4
E-600013-3052 NUT	3
HP-31DBATTERY 950CCA HP-31D	4
L1261F33585XE FUEL FILTER WIX	1
MK184HDBRAKE PADS	2
PH8942FILTER OIL 57182 LFP3729	1
RKB5513COMPRESSOR A/C 115V R22	1
S3225PFUEL FILTER 33630 LFF5849	1
S775COUPLER	1
S778COUPLING	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1

Workorder: V14935

In Date: 05/07/2008
Close Date: 06/02/2008

Meter Reading: 6,740.00

Problem?

Rear A/C in cab blows hot. r72

Task performed:

- Drive to Stn; chk pressure; need valve bad; over charged; stall only blows out 60 at evaporator; 11o trip breaker; sent to shop. j

Parts

Quantity

14-7014HGR-1 HELMET HOOK	6
--------------------------	---



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V15033

In Date: 05/12/2008
Close Date: 06/11/2008

Meter Reading: 78,651.00

Problem?

replace tires at shop callaghan ent r72

Task performed:

replace tires at shop R72 - Callaghan j

Parts

NO PARTS USED

Quantity

Vendor? CALLAGHAN

Workorder: V15814

In Date: 06/18/2008
Close Date: 06/25/2008

Meter Reading: 81,062.00

Problem?

Check eng lt on eng protect lt on r72

Task performed:

1. Get laptop, all phone cable parts & work orders for Western County; fuel up svc truck.
 2. Travel to St72 from CS.
 3. Hookup laptop; get eng codes; drain both fuel filters; chk all ECM fuses/connections; erase eng codes.
- j

Parts

NO PARTS USED

Quantity

Workorder: V16292

In Date: 07/10/2008
Close Date: 08/01/2008

Meter Reading: 6,962.70

Problem?

The high beam switch is not working. R72

Task performed:

1. R/R swch cover; chk wiring/connector; high beams & high beacm indiator on dash work now; tightened switch mtng screws.
2. Travel to St72 from St73. j

Parts

NO PARTS USED

Quantity

Workorder: V16574

In Date: 07/24/2008
Close Date: 08/11/2008

Meter Reading: 7,047.30

Problem?

Open door alarm sounds off. All doors were verified to be closed. Possible broken sensor. r72

Task performed:

1. checked all doors all work no problem

Parts

NO PARTS USED

Quantity



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V16791

In Date: 08/03/2008

Meter Reading: 4,291.10

Close Date: 08/12/2008

Problem?

windshield washer fluid/intermiten switch not working. R-72

Task performed:

1 diagnose w/washer r&r wiper switch

Parts

064615900006-46159-001 SWITCH WIPER

Quantity

1

Workorder: V17598

In Date: 09/09/2008

Meter Reading: 85,518.80

Close Date: 09/30/2008

Problem?

A INSPECTION AND REPAIRS AS NEEDED SR 5

Task performed:

- A-Inspection
- R/R L/R marker light lens; rep bulb contacts.
- R/R lens; rep one low beam & two igh beam pat ceiling lights.
- Blow out washer nozzles & hoses; aim nozzles; fill washer reservoir; put R/S washer hose back into retainers on wiper arm.
- Test map light for power ground-ok; rep reflectors & bulb socket.
- Rep siren & siren head; had to do (3) times; units from parts dept were defective.
- Get on-call veh ready; fuel up; get all on-call equipt & put on veh. j

Parts

01-0862064-00SIREN FRONT SIDE
 02036320700LINEAR STROBE MOD.6E EXTR. MOUNT
 322502BULB PATIENT GH22
 921LIGHT BULB

Quantity

1
1
2
2

Workorder: V15745

In Date: 06/14/2008

Meter Reading: 81,062.00

Close Date: 10/21/2008

Problem?

Right side turn signals do not work. Although they do work when hazerd lights are turned on. R72

Task performed:

- travel to 72
- check truck for check engine light. didnt have lap top needed to swap out.

Parts

NO PARTS USED

Quantity



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V18802

In Date: 11/03/2008
Close Date: 11/18/2008

Meter Reading: 7,197.50

Problem?

Front Right headlight is out S R AT 54

Task performed:

In stalled new headlight that was out. j

Parts

NO PARTS USED

Quantity

Workorder: V19224

In Date: 11/20/2008
Close Date: 11/26/2008

Meter Reading: 86,635.00

Problem?

REAR BRAKES HANGING UP

Task performed:

1. Fnd L-rear brake hanging up; test drive; ck for caliper press; ck ok; out of service truck followed to shop.
2. Replc R- brake pads & calipers; rem tires, calipers & pads; replcd calipers & pads; bled brakes; test drove; ck ok.
3. Replcd R-brake calipers & brake pads. j

Parts

ASL4152092CALIPER F/R RESCUE 55314 NEW 1
 ASL4152737141-70003 BRAKE CALIPER REAR ONLY MAC 1
 E-600013-3052 NUT 3
 MK184HDBRAKE PADS 1

Quantity

Workorder: V19235

In Date: 11/20/2008
Close Date: 11/26/2008

Meter Reading: 86,635.00

Problem?

A INSPECTION AND REPAIRS AS NEEDED SR 5

Task performed:

A-Inspection & Road test. j

Parts

NO PARTS USED

Quantity



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V19850

In Date: 12/18/2008

Meter Reading: 87,833.30

Close Date: 01/07/2009

Problem?

C INSPECTION AND REPAIRS AS NEEDED SR 5

Task performed:

- 1. C-Inspection
- 2. Replc btry minder/tender.
- 3. Replc (1) btry.
- 4. Svc trans; replc filters.
- 5. Torque front/rear suspension u-bolts as per mfr recommendation.
- 6. Svc power steering sys.
- 7. Pressurize cooling sys; rep lense at air compressor.
- 8. Map light brkn; rem/install new map light.
- 9. Svc rear diff.
- 10. Drain/refill cooling sys.
- 11. Blowout both condensers for A/C & cab A/C.
- 12. Svc air dryer sys; cln canister of excessive dir/grease.
- 13. Replc fan belts; had to rem compressor to access adjustor.
- 14. Replc marker lamp lens; rep light.
- 15. Replc msng passenger window crank handle.
- 16. Replc rear door weatherstrip; adj rear door strikers.
- 17. Rem jump seat; rem/trace & send out for match; reinstall seat.
- 18. Rem/replc large plexiglass door.
- 19. Replc crew bench plexi door.
- 20. Rep shorted wiring to air gauge; chk air guage opn.
- 21. Replc all frnt A/C diverters.
- 22. Replc wiper blades.
- 23. Cln pat A/C intake filter.
- 24. Paint fuel cap.
- 25. Safety meeting.
- 26. Rep cables to A/C controller; replc controller head.
- 27. Reset fast adaptive throttle calibrations; road test & chk shifting opn.
- 28. Rem/replc flag decals.
- 29. Replc msng electrical box cover under pat compt; rep chaffed covers.
- 30. Rep connection to R/headlamp.
- 31. Rem drivers seat; send out for rep & reinstall; reassemble; trace asy. j

Parts

Quantity

032-0116549297 BATTERY INDICATOR	1
15W40BSYN OIL BULK QTS	16
194BULB	11
29526898 29548988 TRANS FILTER ALLISON	1
52-24WIPER BLADES ANCO 24	2
680-10LAMERICAN FLAG W UV CLEAR LEFT	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
6806970098SEAL DOOR	1
6808300074VENT A/C LH	2
6808300174VENT A/C RH	2
8714287142 LIGHT MAP 12"	1
92183LENS AMBER	1
9451BELT	1
9485BELT	1
A1818557002HANDLE-WINDOW	1
ABPN83322930CONTROL HEAD AC/HEAT	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	1
CA8193AIR FILTER 46744 WIX	1
DOOR2LEXAN 14.5 X 8.5	1
DOOR5LEXAN 9 X 38 1/2 IN	1
HA24027HINGE EA	4
HP-31DBATTERY 950CCA HP-31D	1
K080733BELT	1
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
RN60JDRYER KIT	1
S3225PFUEL FILTER 33630 LFF5849	1
SWT54924ACTUATOR-RED	1
VML-S1414FILTER P/S	1
VML-T1264GASKET P/S COVER	1
VML-T1279WASHER P/S	1



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V20108

In Date: 01/05/2009

Meter Reading: 87,979.50

Close Date: 01/30/2009

Problem?

on call siren 10-7 sr at 28

Task performed:

Rem siren head asy & wires to both spkrs; rem center console covers; ck all fuses; went to Stn 25 to get control head; replcd head; ck ok; reinstalled (1) spkr; went to E-22 to winch out; return to Stn28; rem spkr to install wires; ck ok. j

Parts

Quantity

01-0862064-00SIREN FRONT SIDE

1

Workorder: V20119

In Date: 01/05/2009

Meter Reading: 87,979.50

Close Date: 02/04/2009

Problem?

cab A/C innop R28

Task performed:

Drive to Stn; chk freon, relays, ele; replcd swtch in dash; chk load manager & fnd relay 9 going to compressor; know power; talk with Ed Erhke; will repair at shop. j

1. T-Shoot A/C electrical pro blem
2. Replc primary fuel filter hs ng (leaking). j

Parts

Quantity

1219360123-11276-041 RELAY VF28-35F14-Z05

1

361000005RELAY FERRARA/EONE

1

361000014RELAY

1

6805450005RELAY NEW # POT-BFMA-15F41

2

87499RY48 RELAY

1

ABPN8332229011-3050 SWITCH BLOWER

1

EL36074RELAY VF4-15F11S05

2

FS1269FUEL FILTER COMPLETE

1

PSP5911CIRCUIT BOARD 21

1

Workorder: V20329

In Date: 01/13/2009

Meter Reading: 88,202.00

Close Date: 02/18/2009

Problem?

a inspection and related repairs, check cab A/C (back from 28)

Task performed:

1. Perm A-Inspection
2. T-shoot & rep cab A/C; fnd bad load manager poor connections at dryer & freeze swtch; chk performance. j

Parts

Quantity

091-32R-12LOAD MANAGER

1

6808300174VENT A/C RH

1



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V20003

In Date: 12/29/2008

Meter Reading: 87,833.30

Close Date: 02/19/2009

Problem?

REPAIR TWO SEATS SR

Task performed:

Parts

Quantity

Repair (2) seats SR - Central Auto Trim j

NO PARTS USED

Vendor? CENTRAL AUTO

Workorder: V20716

In Date: 01/30/2009

Meter Reading: 88,825.00

Close Date: 02/23/2009

Problem?

A inspection and related repairs (back from 36)

Task performed:

Parts

Quantity

Perform A-Inspection. j

NO PARTS USED

Workorder: V21103

In Date: 02/13/2009

Meter Reading: 89,270.00

Close Date: 02/28/2009

Problem?

A inspection and related repairs (back from 52)

Task performed:

Parts

Quantity

- A-Inspection; add P/S fluid.
- 2. Sec fender skirt; secure upper rad hose to saddle.
- 3. replcd L-windshield squirter & adj.
- 4. Dia no maplight; replcd bulb.
- 5. Dia city horn problem; fnd low horn bad; replcd horn.
- 6. Dia air leak LF tire; fnd loose schreader core; tightened core; aired tire.
- 7. Dia no defrost mode; R/R dash; rem obstruction interferring w/linkage.
- 8. Adj air horns. j

1202364111-0 MAP LIGHT BULB	1
13-7108GASKET AXLE	1
370047ASEAL 34387	1
A0631117003HORN LOW NEW #06-52125-041	1
SPRGW2612WASHER NOZZLE W/RELIEF	1



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V21652

In Date: 03/09/2009

Meter Reading: 89,623.00

Close Date: 03/12/2009

Problem?

A inspection and related repairs (from 44)

Task performed:

A-Inspection j

Parts

NO PARTS USED

Quantity

Workorder: V22000

In Date: 03/23/2009

Meter Reading: 89,751.60

Close Date: 03/25/2009

Problem?

ON CALL SR AT 33 BATT SWITCH / LOW POWER

Task performed:

Replcd btry switch & fuel filters. j

Parts

L1261F33585XE FUEL FILTER WIX

S3225PFUEL FILTER 33630 LFF5849

Quantity

1

1

Workorder: V22183

In Date: 03/30/2009

Meter Reading: 90,267.10

Close Date: 03/30/2009

Problem?

ON CALL SR AT33 RUNS POORLY

Task performed:

Fnd eng light on - T-shoot; rep electrical connections; test drove w/driver; ck ok; returned home. j

Parts

NO PARTS USED

Quantity

Workorder: V22228

In Date: 03/31/2009

Meter Reading: 90,267.10

Close Date: 04/03/2009

Problem?

raplace manifold gasket

Task performed:

Ck for low power; test drove; ck for eng codes; ck voltages at ECM connector & pump; fnd air manifold gskt leaking; ck trans codes; rem air tubes, brkts, fuel lines, etc; R/R gaskts; reassembled; test drove; no change. j

Parts

3938152INTAKE GASKET B

3969988GASKET CONNECTION ISB

Quantity

1

2



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V22546

In Date: 04/14/2009
Close Date: 05/08/2009

Meter Reading: 90,267.10

Problem?

A inspection and related repairs (from 33) back from cummins repair, test drive for low power to verify repair

Task performed:

1. A-Inspection
2. Loosen up hood mount pivots; adj hood to close; readj mounts.
3. R/R outer door handler & adj.
4. R/R brake booster; reseal unit pump & bloc,.
5. Replc vent & exh in pat compt blower.
6. Replc bulbs in pat compt lights.
7. Replcd lens on frnt grill light.
8. Reseal P/S sys; leaking all over; refill unit.
9. R.R pass side cab seat belt. j

Parts	Quantity
322502BULB PATIENT GH22	2
6807600070HANDLE DOOR EXT L/H	1
6807600170HANDLE DOOR EXT. R/H	1
68318336550 508 4 HOLE LENS 68-3183365-50	1
ASL-2770932O-RING POWER BOOSTER	4
ELB56711446175 BLOWER 4 IN	1
IMMF13225BELT SEAT PASS. IMMF11852 OLD #	1
VML-T1264GASKET P/S COVER	1
VML-T1279WASHER P/S	1

Workorder: V22389

In Date: 04/08/2009
Close Date: 05/11/2009

Meter Reading: 90,267.10

Problem?

replace bad turbo cummins power south sr 5

Task performed:

Replace bad turbo SR5 - Cummins j

Parts	Quantity
NO PARTS USED	

Vendor? CUMMINS POWER

Workorder: V22862

In Date: 04/28/2009
Close Date: 05/11/2009

Meter Reading: 90,605.00

Problem?

repair spare stretcher R41 (outside agency-medco eqmpt. repair)

Task performed:

Repair spare stretcher R41 - Medco eqmpt j

Parts	Quantity
NO PARTS USED	

Vendor? MEDCO



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V23344

In Date: 05/18/2009

Meter Reading: 91,306.60

Close Date: 06/01/2009

Problem?

A inspection and repairs (from 51)

Task performed:

- A-Inspection
- 2. Center strobe on frnt light bar out; rem lenses; mod light to frt bar; replcd bulb.
- 3. Ck for emergency lights oing out; ck alt & btry ck; ok; T-shoot & trace wires; fnd bad connection at load manager; rep; adj AMP gauge; ck ok.
- 4. R/R L/F strobe light asy.

Parts

Quantity

02036320700LINEAR STROBE MOD.6E EXTR. MOUNT

1

Workorder: V24513

In Date: 07/01/2009

Meter Reading: 92,159.10

Close Date: 07/13/2009

Problem?

A inspection and repairs (from 32)

Task performed:

- A-Inspection
- 2. Reduced oil level in P/S reservoir to cold fill mark; cln external area of P/S reservoir & P/S box below.
- 3. Cln out R/S washer nozzle & T-fitting on windshield washers.
- 4. R/R L/F fender turn signal/marker light asy. bulb sockets burned; NG.
- 5. R/R end cap & lens; rep L/S rotator. j

Parts

Quantity

194BULB

1

6808200020LIGHT ASSY. TURN SIGNAL

1

Workorder: V24719

In Date: 07/13/2009

Meter Reading: 92,528.30

Close Date: 07/15/2009

Problem?

ON CALL NO POWER TO PAITIENT COMP SR 5 AT 31

Task performed:

- Pat compt light inop; dia fault; fnd load mgr outputs working intermittently; rem load mgr & install new unit; fault corrected; sys working normal. j

Parts

Quantity

EL30213091-32 LOAD MANAGER

1



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V25645

In Date: 08/19/2009

Meter Reading: 94,500.00

Close Date: 08/27/2009

Problem?

A inspection and repairs (from 31)

Task performed:

- Perform A-Inspection
- 2. Replc burnt out bulbs in pat compt.
- 3. Replc all (4) A/C diverters.
- 4. Start T-shooting 110 A/C inop. j

Parts

Quantity

322502BULB PATIENT GH22	1
6808300074VENT A/C LH	2
6808300174VENT A/C RH	2
921LIGHT BULB	1

Workorder: V25820

In Date: 08/27/2009

Meter Reading: 94,433.70

Close Date: 09/02/2009

Problem?

A inspection and repairs (from 37)

Task performed:

- A-Inspection.
- 2. R/R L/F headlight.
- 3. Cut, reposition, tighten power steering hose.
- 4. Start T-shoot 110V A/C.
- 5. Continue T-shoot 110V A/C wire in new ckt board.
- 6. Chk & recharge frnt/rear A/C sys.
- 7. R/R pat comp side door; inner door handle asy & adj latches.
- 8. Tighten/adj pat compt doors & latches.
- 9. Install new R/F pillar trim.
- 10. Tighten A/C belts.
- 11. Recharge 110 A/C. j

Parts

Quantity

1829601001RHINGE PILLAR RESCUE	1
CM110VCONTROL BOARD OLD REV-3	1
H6054USE CV TYPE SEALED BEAM	1
HAN-1LBEZEL AND HANDLE	1

Workorder: V26866

In Date: 10/14/2009

Meter Reading: 96,424.10

Close Date: 10/22/2009

Problem?

check and repair charging system sr7

Task performed:

- 1. Replcd alt.
- 2. Tried to adj fast idle but program will not allow.
- 3. Hooked up Mike's computer; still cannot chargecharge parameters for hi-idle. j

Parts

Quantity

4867JB320 UPGRADE ALTERNATOR	1
------------------------------	---



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V26671

In Date: 10/05/2009

Meter Reading: 96,424.10

Close Date: 10/26/2009

Problem?

B INSPECTION AND REPAIRS AS NEEDED SR5

Task performed:

Parts

Quantity



10/17/2017

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

B-Inspection	01-0416333-00LIGHT ROTATOR	2
2. Replc both burnt out rear box turn/marker light asys.	02028345000REFLECTOR	1
3. Replc msgng A/C filter in pat area; use mod filter asy.	02036320700LINEAR STROBE MOD.6E EXTR. MOUNT	2
4. Adj all tire pressures.	071601A07-0602A DRIER A/C 7118	2
5. Rem bat-com wiring & shunts frm btrys & install batry	12-0612AUSE 1600 VALVE EXPANSION RED DOT HOSELI	1
4 post cable directly to btrys.	1501450007750USE 0775145	1
6. Spray/wash out btry tray slide; traces frm sand dirt &	15W40BSYN OIL BULK QTS	24
debris; blow out/lube traces; work	18-29935-001RH DOOR LATCH NEW	1
7. Replc bent up lid cvr & dipstick onleaking P/S	18-45484-000LATCH L/H	1
reservoir; fill to proper level.	1895BULB	1
8. Rep accessory btry term end at btry connections.	194BULB	10
9. Rem instrument cluster from dash; diss back cvr to	2073411640 VALVE EXPANSION	1
gain access to alum bulbs & replc all (10) bulbs; rem	23-11865-000SPRING NUT	4
side panel & replc bad dimmer swtch.	322502BULB PATIENT GH22	2
10. R/side wiper arm twisted/bent; rem arm & install	359-5915359-5915 OIL PLUG	2
new; also install new wiperblade refills.	38026169400BGASKET ENDCAP SUPER EDGE PLUS	2
11. Rep windshield washer; C/O problem; fnd very little	381 838 02 19DASH VENT	1
press at nozzles; start at reservoir & blow out all hoses;	40202RT/L#40202R RED TAIL LIGHT	2
blowout all nozzles; reattach hose & retest; now ok; adj	4923090025DASH BULB VDO	10
spray nozzle.	6805420125SWITCH DIMM	1
12. Adj air press gov at air compressor for proper cut	6805450828PLUG A/C BLR	1
in/out press.	6808310398SEAL AIR DUCT	1
13. Replc bulb burnt out in pat area ovrhd lighting.	6809881078DZ STUD	1
14. Replc burnt out bulbs in action area counter.	68118206050BEND CAP RED SUPER ADV.PLUS LT.BAR	1
15. C/O problem with AC frosting up windshld; adj	7821-3440TERM END A/C BLOCK	5
cable-NG; fnd control panel brkn; rem all dash cvrs &	A1834388002MOLD L/H	1
install new cntrl head; adj cables so all A/C doors	A1834388003MOLD R/H	1
operate correctly.	A2241332084A2241332084 HOSE A/C LOW	1
16. Defroster duct R/side inop; reinstall tube & msgng air	ABPN83322930CONTROL HEAD AC/HEAT	1
deflector.	H35SN12BULB	1
17. L/S box frnt clearance light inop; C/O bulb; entire	IMMF13224BELT SEAT DRIVER SIDE IMMF11851 OLD #	1
fixture rusted/corroded inside; replc.	KN20901KN20901 KNOB PARKING BRAK	1
18. Rem dash panel & tighten parking brake air valve -	L1261F33585XE FUEL FILTER WIX	1
loose in dash.	MK184HDBRAKE PADS	4
19. Rem all lense rear light bar completely; diss entire	PH8942FILTER OIL 57182 LFP3729	1
bar; sev pieces/screws msgng; replc (3) rotaters using	S3225PFUEL FILTER 33630 LFF5849	1
newer style; mod inside holding brkts; search thru shop	SPR-60191-2600BQWIPER ARM ASSBLY	1
to dig up msgng brkts; install/reassemble entire bar.	U-24RWIPER REFILL	1
20. Replc drivers side seat belt asy.	V122XARESCUES MARKER LIGHT	1
21. C/O problem w/leaking shrader valve in cab A/C sys;	VML-T1264GASKET P/S COVER	1
Shader was rusted in hose connection; evac sys; replc	VML-T1279WASHER P/S	1
entire Lo-side hose; vac/recharge sys; retest/leaks; now	VML-T1311COVER PWR STEER RES	1
ok.	VMLT1411CAP ASSY. P/S	1
22. Fuse/ckt brkr cvr falling off; attaching hardware msgng		
23. C/O problem w/pat area veh A/C sys; sys had only		
half charge; charge sys; retest & fnd hi-side press going		
over 300PSI & lo-dropping to 10PSI; change out		
expansion valve/dryer; blowout all lines, cond & evap;		
vac/recharge; now ok.		
24. Complete brake job frnt/rear; includes svc all caliper		
slides/fluid.		
25. C/O 110 A/C sys; fnd freon low; recharge/rechk; sys		
blows cold for short & then stops; diss rear A/C cabinet;		
chk opn of dryer/expansion valve; replc valve/dryer asy;		



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

vac/recharge again; rechk; system cools ok.
26. C/O problem w/master swtch getting hot; rem top cvr of center console & fnd wiring loose on term studs.
27. Veh has slight pull to right; swtch tires frm side-to-side in frnt only; reroad test; seems to be ok now.
j

Workorder: V27284

In Date: 10/29/2009 Meter Reading: 97,099.60
Close Date: 11/05/2009

Problem?
repair air leak sr 5 at 21

Task performed:	Parts	Quantity
1. Drive to Stn; protection valve bad; installed valve; test ok. j	284142VALVE SAFETY ST-3	1

Workorder: V26224

In Date: 09/14/2009 Meter Reading: 94,988.10
Close Date: 11/06/2009

Problem?
BURNING SMELL IN CAB SR AT 46

Task performed:	Parts	Quantity
1. Burning smell; replc blower switch. 2. A/C inop; cln condensor fans. j	NO PARTS USED	

Workorder: V26752

In Date: 10/08/2009 Meter Reading: 96,424.10
Close Date: 11/16/2009

Problem?
OIL PRESSURE UPDATE CUMMINS SR5

Task performed:	Parts	Quantity
Oil pressure update SR5 - Cummins j	NO PARTS USED	

Vendor? CUMMINS



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V27388

In Date: 11/03/2009
Close Date: 11/17/2009

Meter Reading: 8,159.70

Problem?

right rear emergency light cover found broken during truck check r21

Task performed:

Drive to Stn; installed light/lens; test ok. j

Parts

TURBO5TUBE - STROBE

Quantity

2

Workorder: V27808

In Date: 11/19/2009
Close Date: 11/30/2009

Meter Reading: 97,688.50

Problem?

A inspection and repairs (from 21)

Task performed:

A-Inspection j

Parts

NO PARTS USED

Quantity

Workorder: V28122

In Date: 12/04/2009
Close Date: 12/21/2009

Meter Reading: 97,840.00

Problem?

A inspection and repairs (from 37)

Task performed:

1. Replc (2) compt door shocks.
2. C/O lights; rep by crew.
3. Blowout A/C drain hoses; rem filter & cln pan; blow out drain hoses from inside.
4. PA/siren needs whole unit order parts
5. Velco mic to compt console. j
6. A-Inspection
7. Adj tire press to 105 all j

Parts

NO PARTS USED

Quantity

Workorder: V27955

In Date: 11/26/2009
Close Date: 01/13/2010

Meter Reading: 8,101.20

Problem?

Rear driver side strobe cover is missing. R37

Task performed:

Replcd strobe cover. j

Parts

NO PARTS USED

Quantity



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V27823

In Date: 11/20/2009
Close Date: 01/15/2010

Meter Reading: 97,688.50

Problem?

replace 2 front tires (outside agency-callaghan tire)

Task performed:

Replc (2) front tires - Callaghan j

Parts

NO PARTS USED

Quantity

Vendor? CALLAGHAN

Workorder: V28864

In Date: 01/06/2010
Close Date: 01/26/2010

Meter Reading: 8,101.20

Problem?

massive airleak unable to move truck out of bay sr at28

Task performed:

Replc air gov on air compress at station. j

Parts

284358GOVERNOR D-2

Quantity

1

Workorder: V28937

In Date: 01/08/2010
Close Date: 01/27/2010

Meter Reading: 97,840.00

Problem?

A inspection and repairs (from 28)

Task performed:

1. A-Inspection
2. Replcd gas spring; assist on inner compt door.
3. Install grip tape on steps.
4. Tightened door stay on L3 compt door.
5. Installed latch on compt above stairs in back & R/R.
6. Replc air pack brkts to fit new tanks. j

Parts

HLD3999GSS1715UV 30LB STRUT GAS

Quantity

3

Workorder: V29287

In Date: 01/20/2010
Close Date: 02/08/2010

Meter Reading: 98,827.20

Problem?

A inspection and repairs (from 23)

Task performed:

Performed "A" svc j

Parts

NO PARTS USED

Quantity



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V31029

In Date: 04/05/2010
Close Date: 04/05/2010

Meter Reading: 99,999.00

Problem?

On call batt stw inop R21

Task performed:

went to Strn21; fnd btry swtch hot; R/R btry sw; ck opn; ck ok; return home. j

Parts

M-284-01SWITCH BATTERY MASTER

Quantity

1

Workorder: V31744

In Date: 04/23/2010
Close Date: 04/27/2010

Meter Reading: 98,827.20

Problem?

A inspection and repairs (from 23)

Task performed:

A-Inspection j

Parts

NO PARTS USED

Quantity

Workorder: V32335

In Date: 05/20/2010
Close Date: 05/25/2010

Meter Reading: 100,138.80

Problem?

A inspection and repairs

Task performed:

A-Inspection
2. Rep drivers air seat control switch; disconnect hoses & route correctly so as to be able to mnt swtch asy to seat frame; also had to heat & bewnd mtng clips.
2. Cln & aim R/S w/washer nozzles on R/S blade asy; also chk blade & wiper shaft - ok. j

Parts

NO PARTS USED

Quantity

Workorder: V32211

In Date: 05/14/2010
Close Date: 06/03/2010

Meter Reading: 100,138.80

Problem?

door alarm staying on R47

Task performed:

Btry box switch out of adjustment & dirty; cln/adj; working ok at this time. j

Parts

NO PARTS USED

Quantity



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V32093

In Date: 05/10/2010 Meter Reading: 100,138.80
Close Date: 06/21/2010

Problem?

Check out door alarm going off. R47

Task performed:

Door alarm going off; chk all door switches; fnd drivers door switch w/corrosion replcd. j

Parts

91823SWITCH SWT5499 MED MASTER

Quantity

1

Workorder: V33040

In Date: 06/21/2010 Meter Reading: 101,081.00
Close Date: 06/25/2010

Problem?

A inspection and repairs needed

Task performed:

A-Inspection
2. Replc btrys.
3. Replc wiper blades. j

Parts

52-24WIPER BLADES ANCO 24
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF
HP-31DBATTERY 950CCA HP-31D

Quantity

2

4

4

Workorder: V33090

In Date: 06/23/2010 Meter Reading: 101,560.00
Close Date: 08/09/2010

Problem?

C INSPECTION AND REPAIRS AS NEEDED SR5

Task performed:

C-inspection
2. R/R A/C vent.
3. R/R light biox holder & rewire.
4. Tighten & lube door latch on L2 compt.
5. Tighten up rear l3 door hinge & seal plate.
6. Replcd body pads in pat compt - falling off.
7. Reinstall fire ext; rep brkt.
8. Replcd msng door screws in panels on pat compt & tighten the rest.
9. R/R door gskts on cab doors.
10. Tighten up frnt bumper bolts falling off.
11. R/R volt gauge not the same as the old one; had to rewire to get to work.
12. R/R AMP gauge, not the same, had to rewire to get to work.
13. R/R dryer; rebuild. ja

Parts

15W40BSYN OIL BULK QTS
6806970098SEAL DOOR
6808300174VENT A/C RH
CA8193AIR FILTER 46744 WIX
L1261F33585XE FUEL FILTER WIX
MTR3030VM-100 VOLT METER
MTR3040VM-200 GUAGE DIGITAL AMP
PH8942FILTER OIL 57182 LFP3729
RKB5513COMPRESSOR A/C 115V R22
RN60JDRYER KIT
S3225PFUEL FILTER 33630 LFF5849

Quantity

16

2

1

1

1

1

1

1

1

1

1



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V34168

In Date: 08/10/2010
Close Date: 08/26/2010

Meter Reading: 101,742.00

Problem?

A inpection and repair

Task performed:

- A-Inspection
- 2. Replc spotlight central head
- 3. Replc rear scene light in light bar. ja

Parts

21481SEARCHLIGHT CONTROL
H50SN12BULB

Quantity

1
1

Workorder: V35108

In Date: 09/22/2010
Close Date: 10/07/2010

Meter Reading: 101,436.00

Problem?

bolts missing for stretcher braket SR5 at 18

Task performed:

- 1. travel to station 18 from station 28 ; installed missing bolt ; check operation , checks ok. jab

Parts

NO PARTS USED

Quantity

Workorder: V35487

In Date: 10/07/2010
Close Date: 10/28/2010

Meter Reading: 102,116.00

Problem?

A INSPECTION BACK FROM 18

Task performed:

- A-Inspection
- 2. 4 of 5 rear clearance lights out; replce bulbs, still out; diss light bar & fnd brkn wire; rep - ok. j

Parts

1895BULB

Quantity

4

Workorder: V36466

In Date: 11/15/2010
Close Date: 11/30/2010

Meter Reading: 101,436.00

Problem?

A INSPECTION AND REPAIRS SR5

Task performed:

- (1) ROAD TEST AND "A" INSPECTION OF SR5. OK. J.W.

Parts

NO PARTS USED

Quantity



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V38287

In Date: 02/04/2011
Close Date: 02/16/2011

Meter Reading: 101,436.00

Problem?

A INSPECTION AND REPAIRS SR5

Task performed:

- Perform A-Svc
- 2. Replc left back-up light asy - brkn.
- 3. Rep leaking air line for air horns; also adj horns - leaking. j

Parts	Quantity
02028345000REFLECTOR	1
H50SN12BULB	1

Workorder: V38606

In Date: 02/18/2011
Close Date: 03/07/2011

Meter Reading: 103,750.00

Problem?

A INSPECTION SR5

Task performed:

- Perform A-Inspection
- 2. Replcd wiper blades.
- 3. Cnd debris frm windshield washer squirters. j

Parts	Quantity
52-24WIPER BLADES ANCO 24	2
91513AMBER LENS	2

Workorder: V38191

In Date: 02/01/2011
Close Date: 03/08/2011

Meter Reading: 103,626.00

Problem?

Air horn works intermittently, with officer side not sounding at all. R36

Task performed:

- rep bad connection on horn bottiom & tested. j

Parts	Quantity
NO PARTS USED	

Workorder: V39328

In Date: 03/21/2011
Close Date: 03/24/2011

Meter Reading: 103,626.00

Problem?

ON CALL R22 SEAT BELT 10-7

Task performed:

- C/O officers seat belt - ok; lubed; capt. advisd ok; officer to go to shop for new latch if he felt unsafe. j

Parts	Quantity
NO PARTS USED	



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V39372

In Date: 03/22/2011

Meter Reading: 103,626.00

Close Date: 03/28/2011

Problem?

door damaged by tree B17

Task performed:

1. R/R pass side door.
2. Assist w/door replacement. j

Parts

68072003K368072009K3 DOOR R/H

A1834388003MOLD R/H

Quantity

1

1

Workorder: V39515

In Date: 03/29/2011

Meter Reading: 104,010.00

Close Date: 03/31/2011

Problem?

A inspection (from 22)

Task performed:

- A-Inspection
2. R/R L/F headlight. j

Parts

H6054USE CV TYPE SEALED BEAM

Quantity

1

Workorder: V38944

In Date: 03/03/2011

Meter Reading: 103,758.00

Close Date: 04/01/2011

Problem?

B inspection and repairs as needed sr5

Task performed:

- B-Service.
2. Fnd truck won't start - btry dear; btry charger inop; jump started truck.
3. Fnd btry charger inop; ck connections; rem cage, R/R fuse; ck opn ck ok.
4. Fnd compt doors loose; tighten/adj all latches & nader pins; fnd latches brkn on L-2; rem panel & latch; R/R latch; lube & chk ok.
5. Fnd R/upper king pin won't grease; rem cap/grease zerk; cldn grease; R/R Zert; reassem & greased.
6. Ck for coolant leaks; R/R clamp; tighten all clamps; filled/press test; ck ok.
7. Ck for P/S leak; cldn fittings; drained & R/R o-ring; filled & chk for leaks; ck ok.
8. R/R pat lt & pat A/C filter; flushed/filled washer fluid; ck ok.
9. Fnd pat compt oxygen gauge inop; fnd bad connection; rep - ck ok.
10. Tigthen A/C belts - ck ok.
11. Quality inspection - Hines. j

Parts

05-17223-000CAP RADIATOR 10 LB

1501450007750USE 0775145

15W40BSYN OIL BULK QTS

18-29935-001RH DOOR LATCH NEW

18-45484-000LATCH L/H

322502BULB PATIENT GH22

L1261F33585XE FUEL FILTER WIX

LTC594211657-16 LATCH L/H MEDIC MASTER

PH8942FILTER OIL 57182 LFP3729

S3225PFUEL FILTER 33630 LFF5849

Quantity

1

1

24

1

1

1

1

1

1

1



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V40087

In Date: 04/22/2011
Close Date: 04/27/2011

Meter Reading: 104,102.00

Problem?

A Inspection from 81

Task performed:

- A-Inspection
- 2. Door sticks on drivers side; replc latch & adj linkage.
- j

Parts

18-45484-000LATCH L/H

Quantity

1

Workorder: V40075

In Date: 04/22/2011
Close Date: 05/02/2011

Meter Reading: 104,067.00

Problem?

TRUCK DOOR ALARM REMAINS ON (SOUNDS AND FLASHES) EVENTHOUGH ALL DOORS ARE CLOSE AND WHILE TRUCK IS MOVING. Sta 81.

Task performed:

- Clid not verify complaint; chkd opn of door alarm & all sensors.
- j

Parts

NO PARTS USED

Quantity

Workorder: V41587

In Date: 06/24/2011
Close Date: 07/08/2011

Meter Reading: 104,964.60

Problem?

A inspection.

Task performed:

- A-Service
- 2. Chk/repl both air horns; installed new diaphragm in both 0 ok.
- 3. Replc light in right frnt marker.
- 4. C/replc overhead light in rear.
- 5. Cln/paint fuse cap.
- 6. Rep wires on shoreline blower speed.
- 7. Chk/adj all tire press.
- 8. Chk & top off rear shoreline A/C.
- 9. Top off all fluids. j

Parts

1094KIT-AIR HORN-GROVER

322502BULB PATIENT GH22

Quantity

2

1



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V40345

In Date: 05/02/2011
Close Date: 08/03/2011

Meter Reading: 104,067.00

Problem?

REPLACE TIRES SR5

Task performed:

Parts

Quantity

Replc tires SR5 - Boulevard j

NO PARTS USED

Vendor? BOULEVARD

Workorder: V42064

In Date: 07/16/2011
Close Date: 08/08/2011

Meter Reading: 104,964.60

Problem?

R400 has a soft beeping sound on the ECCO under R bumper undercarriage while in park and W/battery on.

Task performed:

Parts

Quantity

repaired connection on backup alarm

NO PARTS USED

Workorder: V42079

In Date: 07/18/2011
Close Date: 08/08/2011

Meter Reading: 105,540.80

Problem?

Right break light not working. Sta 44.

Task performed:

Parts

Quantity

replaced bulb and repaired wires

NO PARTS USED

Workorder: V42596

In Date: 08/05/2011
Close Date: 09/02/2011

Meter Reading: 106,555.00

Problem?

A inspection.

Task performed:

Parts

Quantity

A INSPECTION AIR UP TIRES

NO PARTS USED



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V43522

In Date: 09/08/2011
Close Date: 09/14/2011

Meter Reading: 107,119.00

Problem?

A inspection.

Task performed:

A INSPECTION

Parts

Quantity

02036320700LINEAR STROBE MOD.6E EXTR. MOUNT

1

BATTERY SWITCH HANDLE SCREW STRIPPED
DRILL OUT SWITCH AND TAP NEW THREADS IN
SWITCH CLEAN THREADS CUT # 8-32 CREW TO
LENGTH AND SECURE HANDLE WITH SCREW AND
THREAD LOCKER

DIAGNOSE L REAR STROBE INOP FOUND STROBE
BULB BAD REPALCED STROBE

ADD PX FLUID AND COOLANT

Workorder: V43869

In Date: 09/23/2011
Close Date: 10/14/2011

Meter Reading: 106,931.80

Problem?

brake lights out, door alarm going off.

Task performed:

REPLACED BULB IN REAR

Parts

Quantity

STOPSN12BULB STOP/TAIL LIGHT

2

REPAIRED GROUND WIRE IN REAR DOOR

Workorder: V44442

In Date: 10/17/2011
Close Date: 10/31/2011

Meter Reading:

Problem?

door open buzzard does not turn off. Sta 91.

Task performed:

Rep main door open board. j

Parts

Quantity

SWT5924DOOR OPEN MAP DISPLAY

1



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V44907

In Date: 11/02/2011

Meter Reading: 109,220.00

Close Date: 11/14/2011

Problem?

C INSPECTION SR5

Task performed:

1. C-Inspection
2. Svc batteries.
3. Tighten all door panel screws & install screws where msgng; lube all latches/door hold opens; tighten all brkts & loose latches; replc worn pins in holdopens.
4. Tighten loose nader pins & install sheet metal screw to secure reflector.
5. Adj tire press to proper press.
6. Replc R-1 holdopen brkt, link & pin.
7. Install new wiper blades.
8. Cln R/window squirter.
9. replc drivers door light.
10. Replc actionary light bulbs.
11. Replc belts/tensioner; R/R air clnr & itnake indution pipes; install new air filter.
12. p/S svc.
13. trans svc.
14. Rear axle svc.
15. Replc hydro boost.
16. Replc L/rear pat compt door reflector.
17. Replcd rear A/C door shocks & squad bench shocks
18. Replc rear A/C filter.
19. Svc air dryer.
20. Cooling sys leaks; tighten line at compressor; rem filter hsnng & tighten line beh hsnng; rem compressor air intake hose & tighten fitting; reinstall hose; press chk w/eng running.
21. Coolant svc.
22. Chk eng codes; fnd one code twice for intermittant power data; erased code & test drive - ok.
23. 110V inop; fnd brkr tripped; reset brkr; run 110V A/C & accessories & chk AMP draw ok.
24. Chk 110V A/C - not blowing cold; connect guages & chkd press(fnd low charge); tried to add freon to obtain correct guage press - NG; recvr, evac & recharge w/correct amnt; A/C ok.
25. Reinstall bottom pat compt drawer track; install w/larger screws; rem/adj drawer face to fit properly.
26. Chk O2 sys for leaks.
27. Replc R/side rear SCBA compt tube; drill/tap thrds for label; cut liner to size & glue on floor; file sharp edge on fret SCBA tube. j

Parts

Quantity

1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	17
1619296P/S RESERVOIR SEAL	1
29526898 29548988 TRANS FILTER ALLISON	1
39768315259022 GROOVED TENSIONER OLD#3936213	1
4020362171 GRO LAMP DOME 4 IN	1
52-24WIPER BLADES ANCO 24	2
75W90GEAR OIL SYN QT	6
9451BELT	1
9485BELT	1
98003RREFLECTOR RED 40132 GROTE	1
ANTICOOLANT ANTIFREEZE GAL	8
ASL2772866ASL2772866 BOOSTER BRAKE	1
CA8193AIR FILTER 46744 WIX	1
DOOR 7BIO HAZARD DOOR SLIDDING RED	1
DOR4011AD0010-0 DOOR SCBA COMPT.	1
FGQ59267COVER GASKET STEERING	1
GSS1717UL1717UL0270N 343/09 GAS SHOCK 60 LB	2
HLD3999GSS1715UV 30LB STRUT GAS	2
K080733BELT	1
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
RN60JDRYER KIT	1
S3225PFUEL FILTER 33630 LFF5849	1
TRANSYNDALLISON TRANS FLUID GAL	6
VML-S1414FILTER P/S	1
VML-T1264GASKET P/S COVER	1
VML-T1279WASHER P/S	1



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V44179

In Date: 10/05/2011

Meter Reading: 107,822.00

Close Date: 11/17/2011

Problem?

check engine light stays on, Sta 91.

Task performed:

INSTALLED NEW SPEED SENSOR AND ROAD TESTED

Parts

40020664921601 SENSOR CRANK POSITION

Quantity

1

Workorder: V45861

In Date: 12/14/2011

Meter Reading: 109,859.60

Close Date: 12/15/2011

Problem?

A Inspection SR5

Task performed:

A-SERVICE

Parts

39901054943048 FUEL PUMP ISB

Quantity

1

REPAIR WASHER ON RIGHT SIDE.
TIGHTEN A/C BELTS BOLTS.
ADJUST ALL TIRE PRESSURE.

REPLACE LEFT PUMP ON ENGINE FUEL.

COMPLETE PUMP REPAIR AND REPLACE
REPAIR AND ADJUST BOTH AIR HORM, REMOVE
BRAKET TO ADJ.
REPAIR BROKEN WIRE AT BATTERY.

Workorder: V46673

In Date: 01/18/2012

Meter Reading: 110,414.00

Close Date: 01/19/2012

Problem?

A inspection.

Task performed:

A-INSPECTION

Parts

NO PARTS USED

Quantity



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V46496

In Date: 01/11/2012
Close Date: 01/23/2012

Meter Reading: 110,414.00

Problem?

Box lights (sn 08655, 12109) not charging and do not work. JM 18520, Sta 31

Task performed:

REPAIRED CHARGER LIGHTS ON REAR OF CAB AND
REPLACED FUSE.

Parts

NO PARTS USED

Quantity

Workorder: V47297

In Date: 02/14/2012
Close Date: 02/14/2012

Meter Reading: 111,688.60

Problem?

RELACE LENS

Task performed:

TRAVEL TO ST 73 R&R LENS ON BOX.

Parts

NO PARTS USED

Quantity

Workorder: V48126

In Date: 03/22/2012
Close Date: 04/03/2012

Meter Reading: 112,549.70

Problem?

A inspection.

Task performed:

1. A-INSPECTION.
2. REPAIR MARKER LIGHT.

Parts

NO PARTS USED

Quantity

Workorder: V48264

In Date: 03/28/2012
Close Date: 04/06/2012

Meter Reading: 112,549.70

Problem?

spare rescue 21; front driver high beam is out. rear left scene light is out

Task performed:

TRAVEL TO ST 21 R&R HEAD LIGHT.

Parts

3542606C12611234C1 VENT ACTUATOR
H6054USE CV TYPE SEALED BEAM

Quantity

1
1



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V48474

In Date: 04/05/2012

Meter Reading: 112,698.20

Close Date: 04/09/2012

Problem?

flat tire on southern blvd r 21

Task performed:

Parts

Quantity

FLAT TIRE ON SOUTHERN BLVD. R 21

NO PARTS USED

Vendor? ELPEX

Workorder: V48475

In Date: 04/05/2012

Meter Reading: 112,698.20

Close Date: 04/09/2012

Problem?

replace rear tires

Task performed:

Parts

Quantity

REPLACE REAR TIRES.

NO PARTS USED

Vendor? ELPEX

Workorder: V47400

In Date: 02/17/2012

Meter Reading: 111,841.70

Close Date: 04/11/2012

Problem?

A inspection.

Task performed:

Parts

Quantity

1. A INSPECTION.
2. CHECK AND RECHARGE CAB A/C
3. ADJUST AIR HORNS
4. R&R REAR BRAKE PADS, PULL FRONT WHEELS OFF CHECK BRAKES OK.

H5010BOLT

2

MK184HDBRAKE PADS

1



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V48749

In Date: 04/18/2012
Close Date: 04/25/2012

Meter Reading: 112,698.20

Problem?

A inspection

Task performed:

1. A-INSPECTION.
2. INSTALL WIPER BLADES.
3. ASSIST JOHN WITH REAR COMPARTMENT.
4. STRAIGHTEN OUT BENT COMPARTMENT FROM TIRE BLOW OUT.

Parts

Quantity

52-24WIPER BLADES ANCO 24

2

Workorder: V49178

In Date: 05/08/2012
Close Date: 05/08/2012

Meter Reading: 11,372.70

Problem?

stretcher hook loose

Task performed:

STRETCHER HOOK LOOSE/BOLTS STRIPPED OUT/HAD TO DISASSEMBLE COMPARTMENT BELOW STRETCHER TO ACCESS NUTS REINSTALLED TEST OK.

Parts

Quantity

NO PARTS USED

Workorder: V48819

In Date: 04/23/2012
Close Date: 05/30/2012

Meter Reading: 113,101.00

Problem?

left rear bar (white bar) seam light out on Rescue 93

Task performed:

1. REAR LIGHT BAR INOP- FOUND BAD CONNECTION IN LIGHT BAR.
2. RECHARGE REAR A/C INOP.

Parts

Quantity

NO PARTS USED



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V49503

In Date: 05/21/2012
Close Date: 06/13/2012

Meter Reading: 114,049.00

Problem?

A inspection

Task performed:

1. A-SERVICE.
2. REPAIR DRIVER SEAT LEAKING AIR CUT LINE REINSTALLED LEAK STOP.
3. REPLACE A/C VENT IN DASH, 2 BROKEN, INSTALLED NEW ONE.
4. CHECK AND REPLACE O/2 GAUGES ON BOTTLE, RECHECK FOR LEAKS AND CHECK INSIDE READING GOOD.
5. REMOVE LENSE COVER FOR REAR LIGHT BAR TO REPLACE CENTER SENCE LIGHT, REINSTALL ALL LIGHT COVER CHECK.
6. REMOVE ALL NECESSARY PARTS TO INSTALL NEW LIFT PUMP ON SIDE OF MOTOR, REINSTALL ALL EQUIPMENT RECHECK FOR LEAKS, OK.

Parts	Quantity
15W40BSYN OIL BULK QTS	2
39901054943048 FUEL PUMP ISB	1
6808300174VENT A/C RH	2
H50SN12BULB	1
LB-D30BULB QUARTZ HAL. 12V 150W	1
MG-C23SPMGC23 GAUGE	1

Workorder: V50470

In Date: 06/29/2012
Close Date: 06/29/2012

Meter Reading: 114,756.00

Problem?

A INSPECTION SR5

Task performed:

1. PERFORM A SERVICE.
2. REPLACED WIPER BLADES.
3. TIGHTENED AND ADJUSTED PASSENGER SIDE MIRRORS.
4. CHECKED AND TIGHTENED A/C BELTS. (LOOSE/NOISE)

Parts	Quantity
52-24WIPER BLADES ANCO 24	2

Workorder: V51060

In Date: 07/23/2012
Close Date: 07/30/2012

Meter Reading: 114,756.00

Problem?

B INSPECTION OIL CHANGE SERVICES

Task performed:

B INSPECTION OIL CHANGE SERVICES

Parts	Quantity
NO PARTS USED	

Vendor? OIL CHANGE SERVICES



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V51229

In Date: 07/30/2012

Meter Reading: 114,756.00

Close Date: 09/17/2012

Problem?

REPAIRS FROM B INSPECTION SR 5

Task performed:

1. DEAD BATT MOVE ROBS TRUCK TO GET MULE OUT. CONNECT JUMPERS FRM MULE VLAVE. WOULD NOT START. CONNECT CHARGER AND RUN EXT CORD TO PLAY.
2. CHK LISTED PROB WENT OVER OIL LEAKS W/ EDE OREDER PARTS AND RECIEVE PARTS.
3. JUMP START VEHICLE AND CHARGE BATT.
4. DEGREASE ENGINE AND TIGHTEN OIL PAN BOLTS PER EDE.
5. CLEANED OFF REAR DIFF BY GASKET AND PIN IN SEAL PERED NOT S CLASS TWO LEAK CHK FLUID LEVEL OK.
6. REPLACED STERING ARM RUBBER BOOTS TORN. GREASE FITTINGS.
7. RGTH FRT TIRE CUT REPLACED TIRE AND WHEEL AIR TIRE TO 110 PSI INSTALL MISSING VALVE STEM. CAP ON WHEELS MARK.
8. REPLACE DRIVERS SEAT SWITCH APLIE IN AIR LINES AND CHK FOR LEAKS OK.
9. ROAD TEST VEHICLE AFTER STEERING ARM REPLACEMENT AND RF WHEEL.

Parts

Quantity

435 VALVE CAP	4
A1414374000DRAG LINK RESCUE	1
BOS62221360026222207-001 W AIR SEAT	1

Workorder: V51916

In Date: 08/27/2012

Meter Reading: 114,879.00

Close Date: 09/17/2012

Problem?

COOLANT LEAK AND NO A/C

Task performed:

1. RADIATOR LEAKING-REMOVE RADIATOR ASSEMBLE NEW RADIATOR INSTALLED RADIATOR REPLACE CUT RADIATOR HOSE SECURE TO ALL RADIATOR W/ COOLANT.
2. A/C COMPRESSOR BELT AND COMPRESSOR REMOVE FREON AND COMPRESSOR CHK COMPRESSOR OIL VOLUME INSTALL COMPRESSOR.

Parts

Quantity

05-17544-002HOSE LOWER RADIATOR	1
071601A07-0602A DRIER A/C 7118	1
160012-2012A EXPANSION VALVE 71R8301	1
532703-0602 COMPRESSOR U4735 4471	1
9485BELT	1
A0516058001F10 RESCUE C RADIATOR	1



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V52549

In Date: 09/21/2012

Meter Reading: 116,177.60

Close Date: 10/01/2012

Problem?

A INSPECTION AND NEEDED REPAIRS

Task performed:

1. A INSP
2. REMOVED WHEELS INSPECTED BRAKES NO NEED FOR REPLACEMENT AT THIS TIME.
3. L/2 LIGHT OUT CHK FOR POWER HAD 12.41 VOLTS CHK CONTINUELY IN BULB WAS OK. REPLACED BULB.
4. BLOWER NUT OPERATING CHK BLOWER CIRCUIT FOUND WIRING WRONG ON RESISTER. REWIRED FOUND NO ISSUES AFTER REPAIR.
5. DEFROSTER BLOWS ON WINDSHIELD ON VENT SETTING ADJUSTED LINKAGE BLOWS OUT VENTS ONLY.

Parts

Quantity

621714 IN LIGHT

1

Workorder: V52700

In Date: 09/28/2012

Meter Reading: 116,177.60

Close Date: 10/02/2012

Problem?

replace flat tire

Task performed:

REPLACE FLAT TIRE.

Parts

Quantity

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V53249

In Date: 10/22/2012

Meter Reading: 116,511.80

Close Date: 10/23/2012

Problem?

A Inspection

Task performed:

1. A INSP AIR R/F TIRE AND TIGHTEN LEAKING VALVE STEM CORE.
2. RR O TIRE LEAK REMOVED HUB CAP AND WHEEL. FOUND LOOSE VALVE STEM. TIGHTEND VALVE STEM AND AIR TIRE, INSTALL WHEELS AND HUB CAPS.
3. REPLACED PATIENT COMPT SIDE DOOR REFLECTOR AND BOLTS CLEAN OFF CORROSION FROM PANEL AND LUBRICATE BOLT THREADS.
4. REPLACED RIGHT WINDOW SQUIRTER.
5. DEFROST INOP. REMOVED DASH BOARD INSTRUMENT CLUSTER, PARK BRAKE. VALVE AIR DUCTS AND FRT CONTROL HEAD, FOUND BROKEN CABLE AND CUT OFF ADJ LEVER. REPLACED CABLE AND ADJ REPLACE L-SIDE DASH VENT.
6. REPLACED RADS MIC AND STRAIGHTENED CLIP.

Parts

Quantity

6806870307A/C VENT DASH COVER 18-35571-000	1
6808330631CABLE ASSY HEATER	1
98003RREFLECTOR RED 40132 GROTE	1
SPRGW2612WASHER NOZZLE W/RELIEF	1

Workorder: V53475

In Date: 11/01/2012

Meter Reading: 116,648.00

Close Date: 11/01/2012

Problem?

strecther bar inop, SR-5 back from sta-57

Task performed:

1. check strecther bar, found to be worn out, replace with new bar

Parts

Quantity

090-0278STRECHER BAR NEW	1
--------------------------	---

Workorder: V54166

In Date: 12/03/2012

Meter Reading: 116,927.00

Close Date: 12/04/2012

Problem?

A INSPECTION SR 5

Task performed:

1. A INSPECTION.
2. SET ALL TIRE PRESSURE TO PROPER LEVEL, REPLACE TWO LEAKING VALVE CORES.
3. REPLACE BULB R/ FENDER MARKER LT.

Parts

Quantity

NO PARTS USED



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V54240

In Date: 12/06/2012

Meter Reading:

Close Date: 12/11/2012

Problem?

Drivers side front head light has come loose and the spot light is very dim. R18

Task performed:

1. TRAVEL TO ST 18 CHECK OUT HEAD LIGHT REINSTALL SPRING ON BUCKET AND ADJUST.
2. CHECK OUT SPOT LIGHT WILL NOT MOVE, REPLACE CONTROL POD AND TEST OK.

Parts

Quantity

H6054USE CV TYPE SEALED BEAM

1

Workorder: V54771

In Date: 01/03/2013

Meter Reading:

Close Date: 01/04/2013

Problem?

door open sensor/alarm is going off while driving. the sensor shows the hood is open. we checked the hood by opening and closing it with no success R-18's crew ran into a pool of water and that may have been the cause. R18

Task performed:

- TRAVEL TO 18 REPAIRED DOOR AJAR SWITCH.

Parts

Quantity

NO PARTS USED

Workorder: V55387

In Date: 01/29/2013

Meter Reading: 119,173.20

Close Date: 01/30/2013

Problem?

A inspection

Task performed:

1. A INSPECTION.
2. HIGH SIDE TRAFFIC ADVISOR INOP, R/R SIDE LIGHT BAR CLEARANCE LIGHT INOP, REMOVE BLOWN BULBS AND DAMAGED ASSEMBLY, INSTALLED NEW BULBS AND REPLACE DAMAGE ASSEMBLY.
3. BACK UP LIGHT INOP- REPLACE BLOWN BULB AND LEAKING BULB ASSEMBLY HOUSING.
4. DIFFERENTIAL OIL LEAK CLASS #1. (NO LABOR)
5. FRONT BRAKER 10% REMOVE FRONT WHEEL AND BRAKE PADS INSTALL NEW BRAKE PADS.
6. OIL LEAK ENGINE- CLEAN GREASE AND GRIME OFF ENGINE OPERATE ENGINE TO LOCATE OIL LEAK FRONT LOVE BOLTS LOOSE REMOVE BELTS TO TORQUE LOOSE BOLTS.
7. SECURE LOOSE HANGING ELECTRICAL WIRES ALONG UNDER CARRAGE.

Parts

Quantity

01068234000CTACTLD1 CONTROL PANEL TRAFFIC

1

02028345000REFLECTOR

1

1195LAMP BULB

1

ACX-84534LUG NUT COVER PK10

2

H27SN12BULB

1

MK184HDBRAKE PADS

1



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V56060

In Date: 02/28/2013
Close Date: 02/28/2013

Meter Reading: 119,720.40

Problem?

alternator inop

Task performed:

INSTALLED NEW ALTERNATOR AND 2 BATTERIES
TESTED AND RETURNED TO SERVICE.

Parts

Quantity

4867JB320 UPGRADE ALTERNATOR	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER	2
HP-31DBATTERY 950CCA HP-31D	2

Workorder: V56430

In Date: 03/15/2013
Close Date: 03/18/2013

Meter Reading: 121,148.00

Problem?

Truck broken down at wellington hospital R-30

Task performed:

TRUCK QUIT RUNNING/ALTERNATOR
FAILED/CHARGED AND TESTED BATTERIES
REPLACED ALTERNATOR.

Parts

Quantity

4867JB320 UPGRADE ALTERNATOR	1
------------------------------	---

Workorder: V52107

In Date: 09/03/2012
Close Date: 04/08/2013

Meter Reading:

Problem?

Top right clearance lamp inop (box) R 400

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V52751

In Date: 10/01/2012
Close Date: 04/09/2013

Meter Reading: 116,177.60

Problem?

REPLACE TIRE

Task performed:

Parts

Quantity

NO PARTS USED



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V56120

In Date: 03/03/2013

Meter Reading: 120,219.70

Close Date: 04/09/2013

Problem?

R300 - 10136358 - Brakes squealing.

Task performed:

INSPECTED BRAKE LININGS OK.

Parts

NO PARTS USED

Quantity

Workorder: V56763

In Date: 04/01/2013

Meter Reading: 122,605.50

Close Date: 04/09/2013

Problem?

When battery is turned on a faint alarm is heard under pt compartment at rear of vehicle. SR-5 @ ST-30

Task performed:

TRAVEL TO 30 NO PROBLEM FOUND

Parts

NO PARTS USED

Quantity

Workorder: V55138

In Date: 01/18/2013

Meter Reading:

Close Date: 04/22/2013

Problem?

MDT Handle bracket is broken on the L-side. Strap is still in place, but bracket is completely broken. SR-5 ST 18

Task performed:

REPAIRS WERE COMPLETED.

Parts

NO PARTS USED

Quantity



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V56983

In Date: 04/12/2013

Meter Reading: 123,290.30

Close Date: 04/25/2013

Problem?

C inspection R300 (spare)

Task performed:

1. C-INSPECTION.
2. TESTED BATTERIES FOUND 2 BAD AND 2 GOOD. CHECKED WITH PARTS ON REPLACEMENT ON GOOD BATTERIES, 3/28/13. REPLACED 2 BAD BATTERIES AND MARKED ALL 4 BATTERIES 4/13.
3. DIAGNOSE LEFT LIGHT BAR STROBE IN/OP- FOUND STROBE BAD. REMOVED LENSES AND REPLACED STROBE. TEST OK.
4. ACTIONARY LIGHTS DIM, REPLACED BULBS, TEST OK.
5. REPLACED SHOCKS ON 3 PATIENT COMPTS.
6. REMOVE OLD NON SKID STRIPS, CLEAN STEP OF GLUE AND DIRT. CUT TO SIZE AND INSTALL NEW NON SKID.
7. REMOVE HUB CAPS, TOP OFF WHEEL HUB LUBE AND INSTALL NEW RESERVOIR PLUGS.
8. COOLANT LEAKS AT SIGHT GLASS AND UPPER RAD. HOSE CLAMP. TIGHTENED SIGHT GLASS AND TIGHTENED HOSE CLAMP. PRESSURE TEST (OK).
9. BATTERY CHARGER IN/OP - REMOVE PROTECTIVE CAGE AND COAT HOOK TO ACCESS CHARGER. CHECKED ELECTRICAL CONNECTIONS AND FOUND ONE LOOSE AT TERMINAL. TIGHTEN TERMINAL AND TEST OK.
10. TIE STRAP UPPER RADIATOR HOSE TO SADDLE. REPOSITION PROTECTIVE COVER.
11. REMOVE ACCREDITATION DECALS AND CLEAN GLUE FROM BODY.
12. REBUILD DRYER AND PURGE VALVE.
13. TAIL PIPE HANGER BROKEN. CUT, BEND AND FABRICATE UNIVERSAL HANGER TO FIT FRAME MOUNTING.
14. DIAGNOSE AIR LEAKS - SEAL LEAKS AT FITTINGS. REPLACED LEAKING TANK SAFETY VALVE. AIR SYSTEM AND CHECK REPAIRS (OK).
15. SPLICE IN DRIVERS DOOR WEATHERSTRIP.

Parts

Quantity

02036320700LINEAR STROBE MOD.6E EXTR. MOUNT	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	17
35103HANGAR EXHAUST	1
359-5915359-5915 OIL PLUG	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	2
HLD3999GSS1715UV 30LB STRUT GAS	6
HP-31DBATTERY 950CCA HP-31D	2
KN31400VALVE	1
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
RN60JDRYER KIT	1
S3225PFUEL FILTER 33630 LFF5849	1



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V57806

In Date: 05/17/2013

Meter Reading: 123,423.90

Close Date: 05/21/2013

Problem?

quality check

Task performed:

QUALITY CHECK.

Parts

Quantity

103899KNOB PARKING BRAKE

1

Workorder: V57886

In Date: 05/21/2013

Meter Reading: 123,423.90

Close Date: 05/29/2013

Problem?

Rear patient compt door inop

Task performed:

TRAVEL TO ST 15 GET DOOR OPEN AND R&R HANDLE PANELS AND WINDOWS ADJUST DOOR AND PUT BACK TOGETHER.

Parts

Quantity

HND5948TM22676-02 HANDLE DOOR ENTRY

1

Workorder: V58976

In Date: 07/09/2013

Meter Reading: 123,423.90

Close Date: 07/15/2013

Problem?

shore charger inop

Task performed:

1. HAD TO CHARGE BATTERIES IN LOT TO GET TRUCK STARTED AND BRING INTO SHOP. BEGAN TROUBLESHOOTING CHARGER INOP.
2. CONTINUED/COMPLETED, CHARGER CONCERN. FINALLY TRACED PROBLEM TO MELTED CONNECTION DEEP IN HARNESS IN L-2 COMPARTMENT NEAR BATTERY CHARGER THAT WAS KICKING CIRCUIT BREAKER.
3. REPAIRED CONNECTION AND MELTED WIRE, REASSEMBLED HARNESS. TESTED CHARGER. ALL NOW FUNCTIONING NORMALLY.

Parts

Quantity

NO PARTS USED



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V59237

In Date: 07/22/2013
Close Date: 07/22/2013

Meter Reading: 123,423.90

Problem?

low power R22

Task performed:

WENT TO 22 - FOUND ENGINE SPEED SENSOR BAD
- R&R SENSOR - RAN AND CHECK OK. RETURN HOME.

Parts

Quantity

40020664921601 SENSOR CRANK POSITION

1

Workorder: V59192

In Date: 07/18/2013
Close Date: 07/25/2013

Meter Reading: 123,423.90

Problem?

wig wags on front of r22 are not working.

Task performed:

TRAVEL TO STATION 22 WIG WAGS WORKING FINE
PARKING BRAKE MUST BE RELEASED.

Parts

Quantity

NO PARTS USED

Workorder: V60168

In Date: 08/29/2013
Close Date: 08/30/2013

Meter Reading: 123,945.00

Problem?

A-inspection

Task performed:

PERFORMED "A" INSPECTION.

Parts

Quantity

NO PARTS USED

Workorder: V57233

In Date: 04/23/2013
Close Date: 09/10/2013

Meter Reading: 123,423.90

Problem?

Repair oil and fuel leaks [Cummins]

Task performed:

REPAIRED ON DO-440-042413-16214

Parts

Quantity

NO PARTS USED



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V59573

In Date: 08/05/2013
Close Date: 09/10/2013

Meter Reading: 123,945.00

Problem?

A inspection SR5 from 22

Task performed:

REPAIRED ON W.O. #V60168

Parts

NO PARTS USED

Quantity

Workorder: V60602

In Date: 09/18/2013
Close Date: 09/23/2013

Meter Reading: 125,083.10

Problem?

R35 pat a/c inop

Task performed:

CHECKED OUT A/C TRACED PROBLEM TO FAULTY CONDENSER FANS REPLACED BOTH FANS, CHECKED A/C OPERATION. A/C IN PATIENT COMPARTMENT IS NOW COOLING NORMALLY.

Parts

60027FAN A/C COND 12IN 860026-2-W

2

Quantity

Workorder: V60361

In Date: 09/07/2013
Close Date: 09/30/2013

Meter Reading: 124,450.00

Problem?

1.spot light bulb blown. 2.rescue dumps air when parked in bay 3.rescue takes greater than one minute for air pressure to build up while responding to emergency call. R35 4.right side front light blown.

Task performed:

AIR LEAK FOUND AIR PUMP SWITCH WAS LEFT ON TESTED SYSTEM AND TESTED OK NO AIR LEAKS.

Parts

NO PARTS USED

Quantity

Workorder: V61014

In Date: 10/04/2013
Close Date: 10/15/2013

Meter Reading: 125,849.00

Problem?

Patient compartment a/c inop. shoreline a/c inop SR@35

Task performed:

TRACED OUT PROBLEM WITH A/C FOUND CONDENSER FANS NOT WORKING TRACED OUT WIRING AND FOUND SHORT REPAIRED SHORT AND TESTED. FUEL LEAK FOUND LEAK AT FUEL LINE, REPAIRED AND RECHECKED.

Parts

NO PARTS USED

Quantity



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

* **ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V61661

In Date: 10/30/2013
Close Date: 11/04/2013

Meter Reading: 126,278.70

Problem?

Check for vibration

Task performed:

- CHECK FRONT END FOR VIBRATION. ALL COMPONENTS ARE OK. FOUND DRIVER SIDE FRONT TIRE WHEEL IS A BIT OFF SIDE TO SIDE.
- REPLACED FRONT TIRES TEST FOR VIBRATION. FOUND NEEDS REAR TIRES REPLACE REAR TIRES TEST FOR VIBRATION NEEDS U-JOINT ON DRIVE LINE #1 YOKE.
- REMOVE DRIVE LINE REPLACE U-JOIN REINSTALL DRIVE LINE GREASE U-JOINT. TEST FOR VIBRATION IS GOOD NOW.

Parts	Quantity
5-675XU JOINT	1
E-600013-3052 NUT	4

Workorder: V62618

In Date: 12/10/2013
Close Date: 12/13/2013

Meter Reading: 126,278.70

Problem?

Check out no start condition.

Task performed:

- GET TRUCK STARTED BRING IN SHOP, REPLACED BATTERIES.
- ASSIST IN STARTING TRUCK- R&R L/SCENE LT AND REAR LT BAR STROBE- ASSIST IN R&R BATT.
- CHK FOR LOW POWER- COULD NOT CONNECT TO ECM NO BOOST- R&R MAP SENSOR- TEST DROVE- CHK OK.

Parts	Quantity
02036320700LINEAR STROBE MOD.6E EXTR. MOUNT	1
3348747NX4921497 SENSOR PRESS.	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER	4
H50SN12BULB	1
HP-31DBATTERY 950CCA HP-31D	4

Workorder: V63340

In Date: 01/13/2014
Close Date: 01/14/2014

Meter Reading:

Problem?

B shift noticed large amounts of various fluids under the motor compartment. Water levels appear to be low as well. R300

Task performed:

- TRAVEL TO 30 DRIVER COMPLAINT COOLANT LEAK, FOUND WATER PUMP LEAK R&R WATER PUMP AND COOLANT.

Parts	Quantity
3286278WATER PUMP ISB	1
ALA00350-50 EXTENDED LIFE COOLANT GAL	4



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V63959

In Date: 02/04/2014
Close Date: 02/07/2014

Meter Reading: 129,083.60

Problem?

hardstarting

Task performed:

CHECK BATTES OK, CHECK CHARGING SYST OK
110V CHARGER OK STARTER SYST OK 300 AMPS
OK.

Parts

Quantity

11132766583 STARTER 28MT 5.9 10 TOOTH 10465043

1

Workorder: V63547

In Date: 01/20/2014
Close Date: 02/20/2014

Meter Reading:

Problem?

strong smell of diesel fumes in the cab, side door stop broken. R300

Task performed:

FUEL LEAK NUMBER INJECTOR NOZZLE LINE
LOOSE TIGHTENED NOZZLE AND CLEANED MESS.

Parts

Quantity

NO PARTS USED

Workorder: V64125

In Date: 02/10/2014
Close Date: 03/05/2014

Meter Reading:

Problem?

R300 Left front and Left rear scene light are out... Also inside patient compartment-Right rear lamp is out...

Task performed:

PATIENT COMPT LIGHT INOP, LOOSE CONNECT AT
LIGHT REPAIRED CONNECT.

Parts

Quantity

NO PARTS USED

Workorder: V63680

In Date: 01/24/2014
Close Date: 03/18/2014

Meter Reading: 128,040.20

Problem?

starter inop

Task performed:

WILL BE REPAIRED AT SHOP.

Parts

Quantity

NO PARTS USED



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V64806

In Date: 03/09/2014
Close Date: 03/18/2014

Meter Reading: 131,086.00

Problem?

leaking coolant

Task performed:

1. REMOVE AND REPLACED ENGINE FRONT MAIN SEALY REPLACE SERPENTINE BELT AND TEST FOR LEAKS IS GOOD NOW.
2. REMOVE AND REPLACE PATIENT COMPARTMENT. DOOR STOPPER AND SLIDE TEST FOR OPERATION IS GOOD NOW.
3. REPLACE BROKEN A/C BENT ROAD TEST FOR OPERATION CHECK ONE MORE TIME FOR LEAKS IS OK NOW.

Parts

Quantity

DC23-3008-18 IN HOLD OPEN 30 LB

1

K080733BELT

1

Workorder: V64514

In Date: 02/25/2014
Close Date: 03/19/2014

Meter Reading:

Problem?

Weld broken on stretcher bracket where stretcher wheel locks in.

Task performed:

REPLACED BRACKET FOR STRETCHER.

Parts

Quantity

NO PARTS USED

Workorder: V64540

In Date: 02/26/2014
Close Date: 03/19/2014

Meter Reading: 130,946.70

Problem?

REPAIR STRETCHER BRACKET R300

Task performed:

REPAIRED STRETCHER LATCH AND YELLOW HOOP

Parts

Quantity

NO PARTS USED



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V65095

In Date: 03/21/2014

Meter Reading: 131,086.00

Close Date: 03/26/2014

Problem?

Repair lights Check vehicle condition

Task performed:

- CHECK UNIT FOR DELIVERY, REPAIR ELECTRIC WIRES ON CONTROL PANEL TO LIGHTS. REPLACE SCENE LIGHT BULBS FL RED STROBE.
- CLEANED OUT UNIT AND ASSISTED LUIS WITH ABOVE REPAIRS.

Parts

Quantity

02038332800REFLECTOR

1

H50SN12BULB

1

TURBO5TUBE - STROBE

2

Workorder: V64663

In Date: 03/03/2014

Meter Reading: 131,158.00

Close Date: 04/15/2014

Problem?

B inspection OCS SR5

Task performed:

B inspection filter change

Parts

Quantity

L1261F33585XE FUEL FILTER WIX

1

PH8942FILTER OIL 57182 LFP3729

1

S3225PFUEL FILTER 33630 LFF5849

1

Vendor? OCS

Workorder: V65210

In Date: 03/25/2014

Meter Reading:

Close Date: 06/11/2014

Problem?

REPLACE FRONT HEADLAMP.

Task performed:

Wont start. Batteries dead. Charge batteries. Cehck shore line charger (no good) diagnose charger- found blown fuse. Replaced fuse.

Replaced Rfrt headlight. Install missing screw in bezel

Parts

Quantity

H4656USE CV TYPE HEAD LIGHT

1



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V67536

In Date: 06/28/2014

Meter Reading:

Close Date: 07/09/2014

Problem?

Rescue is leaking oil and air pressure. R56

Task performed:

Parts

Quantity

1. Oil leak. Checked for leaks and cleaned. Will monitor.
2. Airl leak. Repaired air leak and checked.

NO PARTS USED

Workorder: V65340

In Date: 03/31/2014

Meter Reading:

Close Date: 07/17/2014

Problem?

officer side head light out. r45

Task performed:

Parts

Quantity

repaired done on ticket v65210

NO PARTS USED

Workorder: V68492

In Date: 08/07/2014

Meter Reading: 133,205.40

Close Date: 08/14/2014

Problem?

Check lights

Task performed:

Parts

Quantity

1. ck uint for swap out found several problem.
2. right front box marker left rear box marker right front strobe light diaanoise fault ck wires and connection found strobe power box intterment power lose at output removed box and installed new strobe box rewired new replacement strobe pack to unit.
3. alt, not charging batt,removed alt, and installed new alt,ck, charging system full load 13.8 v ok.

01-0285809-00C REFURB ONLY POWER SUPPLY KKKEPS

1

46892-546892-5 MARKER LAMP

1

4867JB320 UPGRADE ALTERNATOR

1

508RED58EC20RU STROBE-RED SURFACE MOUNT

1

ISP94POWER SUPPLY

1



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V68776

In Date: 08/19/2014
Close Date: 10/16/2014

Meter Reading: 133,205.40

Problem?

A inspection SR5

Task performed:

1. A Inspection.
2. Performed brake inspection. Found rear pads worn below minimum specification and sticking rear calipers. Replaced rear calipers and pads. Flushed and bled complete brake system. Test driven.
3. Replaced failed interior dome lamp bulb, failed L-1 (Oxygen) compartment lamp, and replaced worn wiper blades.

Parts	Quantity
1156BULB	1
52-24WIPER BLADES ANCO 24	2
621714 IN LIGHT	1

Workorder: V70719

In Date: 11/05/2014
Close Date: 11/06/2014

Meter Reading: 133,815.00

Problem?

A-inspection No start

Task performed:

1. Dead in yard. Put on charger and started unit.
2. A inspection.
3. Front brakes: Remove worn brake pads to install new pads.
4. Left head light loose: Remove assembly. Disassemble, drill support hole, tap hole, reassemble to secure.
5. Fuel Leak: Primary fill drain valve leaking. Remove filter assembly. Remove drain valve assembly. Assemble new drain valve and filter assembly. Re-install to operate
6. Diagnose low voltage on cranking: Clean battery terminals overnight charge. Check battery. Load test and operate battery. Good condition.
7. Patient compartment, 2 dome lights inoperable. Found one blown bulb and one loose electrical connection. Replace bad bulb and correct loose connection fault.

Parts	Quantity
322502BULB PATIENT GH22	1
3926759-SDRAIN KIT	1
68054400K0BEZEL HEADLIGHT	1
MK184HDBRAKE PADS	1



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V71035

In Date: 11/18/2014

Meter Reading: 133,815.00

Close Date: 12/01/2014

Problem?

C inspection SR5

Task performed:

1. Perform "C" service
2. continued/completed "c" service
3. removed both front seats(torn) to be sent out for repair
4. Replaced pt compt AC filter
5. Replaced wiperblades
6. replaced turn signal side marker light lenses (broken)
7. replaced O2 tank pressure gauge
8. Unjammed passenger seat adjuster cleaned and lubed.
9. Paint fuel cap
10. replaced o2 compt. door hold open (broken)
11. Installed placard frame on rear of rescue(missing)
12. Made and installed overhead height sticker
13. replaced hold open shocks on squad bench and pt compartment AC access door.
14. serviced p/s
15. Replaced cap door weatherstripping (both sides)(torn)
16. Replaced air tank pull cord drain with petcock style drain.
17. replaced rear suspension air bags (cracked/dried)
18. Cut to fit new mud flaps and installed (ripped/torn) also straighten left mud flap bracket and flange(smashed)
19. continued/completed mud flap/bracket install and repair.
20. replaced 2nd air tank pull cord-drain with petcock style drain.
21. rebuilt air brake dryer
22. Replaced belts
23. Replaced action area flourescents in pt comp
24. Troubleshoot 110v AC fan motor only has one speed-traced problem to faulty fan resistor. Replaced resistor and rewired melted terminal ends.
25. Troubleshoot 110v AC not cooling well; Found system low on chagre. Recovered system vaccumed (held vac)
26. Continued/completed 110v AC repair system-held vaccum overnight recharged system and tested. System is cooling normally
27. Received seats back from upholstery shop and installed

Parts

Quantity

Parts	Quantity
0775145PANEL FILTER	1
103385NDRAIN COCK	2
123411-0806 RESISTOR BLOWER MTR A/C	1
16-15762-00016-19471-000 AIR BAG	2
52-24WIPER BLADES ANCO 24	2
6806970098SEAL DOOR	1
91513AMBER LENS	1
9451BELT	1
9485BELT	1
B2420LP-SMUD FLAP 24 X 24	2
DRC401202840048 DOOR GRABBER	1
GSS1717UL1717UL0270N 343/09 GAS SHOCK 60 LB	2
HLD3999GSS1715UV 30LB STRUT GAS	2
K080733BELT	1
L1261F33585XE FUEL FILTER WIX	1
MG-C23SPMGC23 GAUGE	1
PH8942FILTER OIL 57182 LFP3729	1
RN60JDRYER KIT	1
S PLACARDFRONT AND BACK PLACARD	1
S3225PFUEL FILTER 33630 LFF5849	2
S448GAUGE TIRE TREAD DEPTH	1
VML-S1414FILTER P/S	1
VML-T1264GASKET P/S COVER	1
VML-T1279WASHER P/S	1



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V72132

In Date: 01/08/2015
Close Date: 01/13/2015

Meter Reading: 133,815.00

Problem?

Cummins power south

Task performed:

REPAIR OIL LEAK.

Parts

NO PARTS USED

Quantity

Vendor? CUMMINS POWER

Workorder: V72176

In Date: 01/09/2015
Close Date: 01/20/2015

Meter Reading: 133,893.00

Problem?

SR5 A - Inspect

Task performed:

1. A Inspection.

Parts

NO PARTS USED

Quantity

Workorder: V73070

In Date: 02/11/2015
Close Date: 02/13/2015

Meter Reading: 133,815.00

Problem?

batteries dead need replaced

Task performed:

1. Dead battery. Will not jump start or slow charge. Install 4 new batteries. Load test battery weak.
2. Check charging system 12.6V to starter. Starter solenoid energized. Starter relay 12.6V is bad. Remove starter and install new one.
3. Auto eject working intermittently. Found super auto-eject malfunction. Remove and rewire new unit in place.

Parts

0915520120AUTO EJECT 20 AERO OTL3925
 11132766583 STARTER 28MT 5.9 10 TOOTH 10465043
 BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF
 ESX120105112STARTER RELAY ESX-120-105112
 HP-31DBATTERY 950CCA HP-31D

Quantity

1
1
4
1
4



10/17/2017

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136358

*** ADVANCED LIFE SUPPORT VEHICLE**

Workorder: V73922

In Date: 03/16/2015

Meter Reading: 134,816.00

Close Date: 04/27/2015

Problem?

PAT A/C INOP

Task performed:

REPAIR PAT A/C

1. Check patient A/C, found condenser fans inop. Found bad circuit board, replaced. Check ok.
2. Checked out patient A/C inop. Recovered system and found low. Recharged system cutting off due to high pressure. Further trouble shoot showed condenser fans inop. Replaced fans.
3. Continued A/C trouble shoot after approximately 20 min. of running A/C condenser fans would shut off. Traced problem to faulty breaker and relay in drop down panel in patient compartment. Replaced breaker and relay. A/C now operates normally.

Parts

Quantity

22230-000-30BREAKER CIRCUIT 30A

1

5269LPVM-5 SM MOUNT

1

60027FAN A/C COND 12IN 860026-2-W

2

PSP5911CIRCUIT BOARD 21

1

VF445F11FSO140A RELAY A/C DIODE SUP

1



Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (10136358) 2001 - AMERICAN LAFRAN FL60 Advanced Life Support Vehicle

10136358

CSHOP-2015-2181

Date Opened 8-6-2015 Date Finished 8-6-2015 Meter 1 Reading: 135,036

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

CSHOP-2015-2582

Comments: SR5 CHECK PAT A/C

Date Opened 8-27-2015 Date Finished 8-28-2015 Meter 1 Reading: 135,350

TASKS PERFORMED

Q PARTS

AIR CONDITIONING

- 1 DRYER; 07-0602A DRIER A/C 7118
- 1 PORT; 08-6932BS 90 DEGREE FEMALE W/SERVICE PORT
- 1 HOSE AND FITTING
- 1 FITTING; 08-6933BS A/C FITTING STEEL
- 2 A/C; FREON LB
- 1 HOSE AND FITTING

CSHOP-2015-2943

Comments: WONT START

Date Opened 9-16-2015 Date Finished 9-18-2015 Meter 1 Reading: 135,356

TASKS PERFORMED

Q PARTS

CRANKING SYSTEM

- 1 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
- 4 BATTERY; BATTERY 950CCA HP-31D
- 1 CABLE; CABLE BATT. NEG.

CSHOP-2015-4073

Comments: SR5 DEAD BATTERY

Date Opened 11-20-2015 Date Finished 11-25-2015 Meter 1 Reading: 135,357

TASKS PERFORMED

NO PARTS USED

BATTERY

Asset Work Order History 10136358

CSHOP-2015-4547

Comments: **A-INSPECTION SR5**

Date Opened 12-18-2015 Date Finished 12-23-2015 Meter 1 Reading: 135,431

TASKS PERFORMED

Q PARTS

A INSPECTION	1	FERRARA; TEE PLASTIC
WIPERS-WASHER	2	WIPER; WIPER BLADES
LIGHTING SYSTEM	1	BULB; BULB PATIENT GH22
TIRE	1	DRYER; 07-0610A DRYER
AIR SYSTEM	1	NONSTOCK; CONDENSOR FL70
AIR HORN		
BUMPER FRONT		
DOOR HANDLES INSIDE-OUTSIDE		
AIR CONDITIONING		

CSHOP-2016-1019

Comments: **ON-CALL R244 DOOR ALARM**

Date Opened 3-3-2016 Date Finished 3-3-2016 Meter 1 Reading: 140,459

TASKS PERFORMED

NO PARTS USED

ALARM-BUZZER-WARNING LIGHT

CSHOP-2016-1151

Date Opened 3-10-2016 Date Finished 3-20-2016 Meter 1 Reading: 141,685

TASKS PERFORMED

Q PARTS

COOLING SYSTEM	1	FREIGHTLINER; T3248 SIGHT GLASS
	1	SWITCH; 64-0023 SWITCH FOOT SIREN

CSHOP-2016-136

Comments: **R241 COMP DOOR ISSUE**

Date Opened 1-11-2016 Date Finished 1-26-2016 Meter 1 Reading: 137,847

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER BODY EXTERIOR	4	CAP; LED PRESSURE CAP
---	---	-----------------------

Service Requests:

01/11/2016	DOOR / 16: GLAZED / REPAIR SECOND COMPARTMENT DOOR DRIVER SIDE; DOOR IS PULLED FROM THE HINGE SIDE PREVENTING TOP LOCKING MECHANISM TO WORK. DOORS CAN STILL BE SECURED BUT ONLY THE BOTTOM NADER PIN IS BEING UTILIZED.
------------	--

Asset Work Order History 10136358

CSHOP-2016-2958

Comments: **SR5 C INSPECTION**

Date Opened 6-20-2016

Date Finished

8-2-2016

Meter 1 Reading:

141,685

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

1 FILTER; FILTER OIL 57182 LFP3729
1 FILTER; FUEL FILTER 33630 LFF5849
1 FILTER; 33585XE FUEL FILTER WIX

CSHOP-2016-2984

Comments: **REPAIRS FROM PM**

Date Opened 6-21-2016

Date Finished

8-16-2016

Meter 1 Reading:

141,759

TASKS PERFORMED

Q PARTS

DOOR PROP CYLINDER
WIPERS-WASHER
FUEL TANK
COOLING SYSTEM
LIGHTING SYSTEM
AUTO-EJECT
TRANSMISSION
AIR SYSTEM
DOOR STRIKER PLATE
AIR CONDITIONING

1 STRUT; GSS1715UV 30LB STRUT GAS
2 WIPER; WIPER BLADES ANCO 24
1 BULB; BULB
1 LIGHT; HEADLIGHT EXTRA BRIGHT
1 CHARGER; CHARGER 2000
1 CHARGER; CHARGER 2000
1 FILTER; 29548988 TRANS FILTER ALLISON
1 DRYER; DRYER KIT
1 MEDIC MASTER; 15449 STRIKER PIN
1 MEDIC MASTER; STRIKER PIN
2 VENT; VENT A/C RH
2 VENT; VENT A/C RH
1 FILTER; PANEL FILTER
1 FILTER; PANEL FILTER

CSHOP-2016-4564

Comments: **A INSPECTION**

Date Opened 9-19-2016

Date Finished

9-27-2016

Meter 1 Reading:

141,946

TASKS PERFORMED

NO PARTS USED

A INSPECTION

CSHOP-2016-4665

Date Opened 9-27-2016

Date Finished

9-27-2016

Meter 1 Reading:

141,946

TASKS PERFORMED

NO PARTS USED

STROBE LIGHTS
GRILLE

Asset Work Order History 10136358

CSHOP-2017-1707

Date Opened 3-20-2017 Date Finished 3-23-2017 Meter 1 Reading: 146,592

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FIL; NAPAGOLD OIL FILTER
23 9OC; SYN 15W40
1 FILTER; FUEL FILTER 33630 LFF5849
1 FILTER; 33585XE FUEL FILTER WIX

CSHOP-2017-1708

Comments: **REPAIRS FROM PM**

Date Opened 3-20-2017 Date Finished 4-21-2017 Meter 1 Reading: 146,593

TASKS PERFORMED

Q PARTS

REPAIR FROM PM - PATIENT COMPT
REPAIR FROM PM - ENGINE
REPAIR FROM PM - TRANSMISSION
STROBE LIGHTS
REPAIR FROM PM - AIR COMPRESSOR

1 1ED; BREATHER
24 9OC; 9OC
1 NCB; PURPLE POWER 40 OZ
5 9OC; BULK TRANS SYN
5 2CU; SEAL
-1 2IH; BREATHER
1 2IH; BREATHER
4 MAC; NON-CHLOR BRAKE CLNR
1 9HY; HOSE
1 1WL; 508 STROBE
1 NONSTOCK; FREIGHT CHARGE

CSHOP-2017-2476

Date Opened 4-27-2017 Date Finished 4-27-2017 Meter 1 Reading: 146,593

TASKS PERFORMED

NO PARTS USED

BATTERY

CSHOP-2017-2900

Comments: **SPARE RESCUE AT 23 RESCUE 223**

Date Opened 5-16-2017 Date Finished 5-16-2017 Meter 1 Reading: 148,479

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
OIL

Service Requests:

05/16/2017 FUEL / 18: LEAKING / INSPECT
LOW FUEL/OUT OF FUEL- SERIOUS OIL LEAK

Asset Work Order History 10136358

CSHOP-2017-3356

Comments: **QC GET READY TO SEND TO ST30**

Date Opened 6-7-2017 Date Finished 6-8-2017 Meter 1 Reading: 150,204

TASKS PERFORMED

NO PARTS USED

QUALITY CHECK-REPAIRS

CSHOP-2017-3357

Date Opened 6-7-2017 Date Finished 6-7-2017 Meter 1 Reading: 150,204

TASKS PERFORMED

NO PARTS USED

QUALITY CHECK-REPAIRS

CSHOP-2017-3422

Comments: **CHECK UNIT FOR OIL LEAK**

Date Opened 6-9-2017 Date Finished 8-14-2017 Meter 1 Reading: 150,250

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES

3 90C; SYN 15W40
3 FLUID; SYN OIL BULK QTS

CSHOP-2017-416

Comments: **QUALITY CHECK**

Date Opened 1-19-2017 Date Finished 2-17-2017 Meter 1 Reading: 146,431

TASKS PERFORMED

Q PARTS

A INSPECTION

2 9IP; BULB
4 1AD; BATTERY 31 SERIES

RADIO-2016-707

Comments: **CALLED STATION TOLD LT TO DISCONNECT MIC AND CYCLE POWER. FIXED PROBLEM.**

Date Opened 11-10-2016 Date Finished 11-10-2016 Meter 1 Reading: 143,653

TASKS PERFORMED

NO PARTS USED

RADIO

Service Requests:

11/10/2016 RADIO / /
SR5 RUNNING AS R256: RADIO ISSUES. MAIN MOUNTED RADIO ON BOTH FRONT AND BACK. RADIO INDICATES "FAIL 01/90".

Asset Work Order History 10136358

RADIO-2016-72

Comments: **PERFORMED POWER RESET.**

Date Opened 2-11-2016 Date Finished 7-6-2016 Meter 1 Reading: 141,685

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
RADIO

Service Requests:

01/06/2016 HAZARD / /
THE MEDCOM RADIO STOPPED WORKING LAST NIGHT. IT DOESN'T DO ANYTHING. THE CREW TRIED MULTIPLE THINGS TO TRY TO TURN IT ON AND NOTHING WORKED. THIS SPARE RESCUE IS HOUSED AT STATION 41 AT THE MOMENT.

RADIO-2016-9

Date Opened 1-7-2016 Date Finished 2-11-2016 Meter 1 Reading: 138,632

TASKS PERFORMED

NO PARTS USED

QUALITY CHECK-REPAIRS

RADIO-2017-66

Comments: **T/S PROBLEM TO CORROSION IN THE MIC CONNECTOR ON THE FRONT CH. REPLACED THE CH AND MIC. TESTED ON-AIR WITH DISPATCH.**

Date Opened 2-6-2017 Date Finished 2-6-2017 Meter 1 Reading: 145,921

TASKS PERFORMED

NO PARTS USED

RADIO

Service Requests:

02/04/2017 RADIO / /
VEHICLE RADIO TURNS OFF WHEN THE VOLUME IS ADJUSTED OR CHANNEL IS CHANGED-RADIO ISSUES
