

10/11/2016
4:22:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11488 2004 GMC 3500 Pickup, 1 Ton

| | | | | | |
|----------------------------|-------------------------------|---------------------------|--------------------|--------------|-----------------|
| Workorder: 443121 | Problem: TAG CHARGE | | | | |
| Meter Reading: 0 | | Labor | | Parts | |
| In Date: 04/30/2004 | Close Date: 04/30/2004 | Hours | Description | | Quantity |
| - Tag Charge | | | TAG CHARGE | | 1.00 |
| | Parts Charge: 34.35 | Labor Charge: 0.00 | | | |

| | | | | | |
|----------------------------|---|-----------------------------|--------------------|--------------|-----------------|
| Workorder: 443617 | Problem: PRE-DELIVERY INSPECTION | | | | |
| Meter Reading: 0 | | Labor | | Parts | |
| In Date: 05/05/2004 | Close Date: 05/05/2004 | Hours | Description | | Quantity |
| - Pre-Delivery Inspection | | 2.00 | | | |
| | Parts Charge: 0.00 | Labor Charge: 100.00 | | | |

| | | | | | |
|----------------------------|-----------------------------------|-----------------------------|---|--------------|-----------------|
| Workorder: 443785 | Problem: FAB LIGHT BRACKET | | | | |
| Meter Reading: 0 | | Labor | | Parts | |
| In Date: 05/06/2004 | Close Date: 05/24/2004 | Hours | Description | | Quantity |
| - Fab Light Bracket | | 3.50 | SHOP SUPPLIES | | 1.00 |
| - Welding Supplies | | | 3/16X4X10 DIA PLATE ALUMINUM NON BRIGHT | | 1.00 |
| | | | 3/16X4X12 ALUM PLATE 5052 | | 2.00 |
| | | | 1/4X2X24 SQ. ALUM TUBE | | 1.00 |
| | Parts Charge: 25.77 | Labor Charge: 175.00 | | | |

| | | | | | |
|---|--------------------------------------|-----------------------------|---------------------------------|--------------|-----------------|
| Workorder: 443854 | Problem: INSTALL STROBE LIGHT | | | | |
| Meter Reading: 24 | | Labor | | Parts | |
| In Date: 05/07/2004 | Close Date: 05/14/2004 | Hours | Description | | Quantity |
| - Fabricate & Install Strobe Light Sys.Relocate | | 3.50 | DS367 YELLOW PILOT LIGHT | | 1.00 |
| F/Extinguisherand Bracket. | | | 30055-30 30AMP CIRCUIT BREAKER | | 1.00 |
| - Shop Supplies | | | DS-167 TOGGLE SWITCH (STANDARD) | | 1.00 |
| | | | SHOP SUPPLIES | | 1.00 |
| | Parts Charge: 16.23 | Labor Charge: 175.00 | | | |

10/11/2016
4:22:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11488 2004 GMC 3500 Pickup, 1 Ton

Workorder: 463424

Problem: P.M.SERVICE

| Meter Reading: 2671 | Labor | Parts | |
|----------------------------|--------------|-----------------------------|-----------------|
| In Date: 12/03/2004 | Hours | Description | Quantity |
| - Pm Service. | 4.00 | PH3506 OIL FILTER WIX 51042 | 1.00 |
| - Shop Supplies | | SHOP SUPPLIES | 1.00 |
| | | 10W30 MOTOR OIL | 7.00 |
| Parts Charge: | 12.57 | Labor Charge: | 200.00 |

Workorder: 550567

Problem: P.M.SERVICE

| Meter Reading: 5019 | Labor | Parts | |
|-----------------------------------|--------------|-----------------------------|-----------------|
| In Date: 07/18/2005 | Hours | Description | Quantity |
| - Pm Service | 6.00 | 10W30 MOTOR OIL | 7.00 |
| - Complete Allignment.Test Drive. | | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | PH3506 OIL FILTER WIX 51042 | 1.00 |
| Parts Charge: | 13.04 | Labor Charge: | 300.00 |

Workorder: 635565

Problem: P.M.SERVICE

| Meter Reading: 7164 | Labor | Parts | |
|----------------------------|--------------|-----------------------------|-----------------|
| In Date: 03/10/2006 | Hours | Description | Quantity |
| - Pm Service | 4.00 | PH3506 OIL FILTER WIX 51042 | 1.00 |
| - Shop Supplies | | 10W30 MOTOR OIL | 7.00 |
| | | SHOP SUPPLIES | 1.00 |
| Parts Charge: | 20.77 | Labor Charge: | 200.00 |

10/11/2016
4:22:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11488 2004 GMC 3500 Pickup, 1 Ton

Workorder: 645390

Problem: P.M.SERVICE/SEE NOTE

| Meter Reading: 10313 | Labor | Parts | |
|---|--------|---------------------------------------|----------|
| In Date: 09/11/2006 | Hours | Description | Quantity |
| - Pm Service | 9.50 | 10W30 MOTOR OIL | 7.00 |
| - R&R Tail Gate Cables | | 6678 AIR FILTER FRM CA8755A WIX 46678 | 1.00 |
| - R&R 6 Tires & Fill With Nitrogen. | | PH3506 OIL FILTER WIX 51042 | 1.00 |
| - Repair Marker Lights. | | TIRE DISPOSAL FEE | 6.00 |
| - Transport & Pickup Vehicle At Dealer.(Speedometer Inop) | | TR416 VALVE STEM | 6.00 |
| - Shop Supplies | | SHOP SUPPLIES | 1.00 |
| | | 31-22 WIPER BLADES 22" WIPER BLADE | 2.00 |
| | | 744821900 215/85R16 WRANGLER HT E | 6.00 |
| Parts Charge: | 950.35 | Labor Charge: | 50.00 |

Workorder: 736352

Problem: P.M SERVICE,TROUBLE FUELING

| Meter Reading: 13845 | Labor | Parts | |
|---|--------|--------------------------------------|----------|
| In Date: 03/29/2007 | Hours | Description | Quantity |
| - Perform Pm Service | 8.50 | PH3506 OIL FILTER WIX 51042 | 1.00 |
| - Transmission Flush | | SYN/ATF TRANS FLUID SYNTHETIC | 14.00 |
| - Inspect Fuel Sys.Repl Filler Hose To Frt Tank.Repl Vent | | 15078048 FUEL VENT HOSE | 1.00 |
| Hoseto Rear Tank.Realign Fill Tubes. | | 10020 INJECTOR CLEANER DON'T REORDER | 1.00 |
| - Replace Trailer Plug.Straighten Bracket. | | 15085432 FUEL FILLER HOSE | 1.00 |
| - Shop Supplies | | 10W30 MOTOR OIL | 6.00 |
| | | 5404 FEMALE CONNECTOR | 1.00 |
| | | SHOP SUPPLIES | 1.00 |
| | | 31-22 WIPER BLADES 22" WIPER BLADE | 2.00 |
| Parts Charge: | 200.08 | Labor Charge: | 55.00 |

Workorder: 746602

Problem: P.M SERVICE.

| Meter Reading: 15425 | Labor | Parts | |
|----------------------|-------|------------------------------------|----------|
| In Date: 11/01/2007 | Hours | Description | Quantity |
| - Pm Service | 5.00 | 31-22 WIPER BLADES 22" WIPER BLADE | 2.00 |
| - Shop Supplies | | SHOP SUPPLIES | 1.00 |
| | | PH3506 OIL FILTER WIX 51042 | 1.00 |
| | | 10W30 MOTOR OIL | 6.00 |
| | | L0152-063 GEAR SHIELD | 1.00 |
| Parts Charge: | 44.72 | Labor Charge: | 60.00 |

10/11/2016
4:22:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11488 2004 GMC 3500 Pickup, 1 Ton

Workorder: 838640

Problem: P.M SERVICE

| Meter Reading: 16825 | | Labor | | Parts | |
|-----------------------------|---|----------------------------|---------------------------------------|-----------------|--|
| In Date: 05/16/2008 | Close Date: 05/21/2008 | Hours | Description | Quantity | |
| - | Pm Service | 8.00 | 10W30 MOTOR OIL | 6.00 | |
| - | R&R Faulty Tail/Brake Lamp.Tag Lamp Inoperative,Trace | | 6678 AIR FILTER FRM CA8755A WIX 46678 | 1.00 | |
| | Wiringto Faulty Ground,R&R Tag Lamp Housing,Clean | | PH3506 OIL FILTER WIX 51042 | 1.00 | |
| | Contact Arm Reinstall Ok | | 44202R TAIL LIGHT 4" RED 42 LED | 1.00 | |
| - | Nail In Right Front Tire Side Wall.Unrepairable Replace | | 31-22 WIPER BLADES 22" WIPER BLADE | 2.00 | |
| | Tire,High Speed Balance 6 Tires.Nitro Filled | | SHOP SUPPLIES | 1.00 | |
| - | R&R Intermediate Steering Shaft To Excessive And | | USED FIREX REFURBED FIRE EXTINGSHERS | 1.00 | |
| | Lubricate To Correct Steering Clunk. | | 744821900 215/85R16 WRANGLER HT E | 1.00 | |
| - | Shop Supplies | | TIRE DISPOSAL FEE | 1.00 | |
| Parts Charge: 249.09 | | Labor Charge: 18.00 | | | |

Workorder: 844238

Problem: ALVIN MATTHEWS PAINT & BODY

| Meter Reading: 0 | | Labor | | Parts | |
|----------------------------|-------------------------------|---------------------------|----------------------------------|-----------------|--|
| In Date: 08/26/2008 | Close Date: 09/16/2008 | Hours | Description | Quantity | |
| - | Alvin Matthews Paint & Body | | | | |
| Parts Charge: 0.00 | | Labor Charge: 0.00 | Commercial Charge: 240.00 | | |

Workorder: 847314

Problem: P.M SERVICE,SEE NOTE

| Meter Reading: 18272 | | Labor | | Parts | |
|-----------------------------|--|-----------------------------|--|-----------------|--|
| In Date: 11/20/2008 | Close Date: 11/26/2008 | Hours | Description | Quantity | |
| - | Pm Service | 10.50 | 10W30 MOTOR OIL | 6.00 | |
| - | Ck Battery & Charging Sys Battery Failed.Replace | | PH3506 OIL FILTER WIX 51042 | 1.00 | |
| | W/New | | USED FIREX REFURBED FIRE EXTINGSHERS | 1.00 | |
| - | Cooling Sys Service | | 5404 FEMALE CONNECTOR | 1.00 | |
| - | Trailer Plug Defective R&R W/New And Fabricate Wiring. | | 6678 AIR FILTER FRM CA8755A WIX 46678 | 1.00 | |
| | Rotate Tires High Speed Balance All 6.Repair R Rear | | SHOP SUPPLIES | 1.00 | |
| | Outer. | | 31-22 WIPER BLADES 22" WIPER BLADE | 2.00 | |
| - | Shop Supplies | | GROUP 78 BATTERY (ACD 78PS) | 1.00 | |
| | | | ANTIFREEZE EXT/LIFE ALL MAKES (PEAK 407) | 2.00 | |
| Parts Charge: 211.70 | | Labor Charge: 150.00 | | | |

10/11/2016
4:22:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11488 2004 GMC 3500 Pickup, 1 Ton

Workorder: 934461

Problem: SERVICE BRAKE/ABS LIGHT ON

| Meter Reading: 19769 | Labor | Parts | |
|--|-------|-----------------------------|----------|
| In Date: 02/26/2009 | Hours | Description | Quantity |
| - Scan Abs Sys For Codes No Power To Ald,Trace Short | 2.00 | CIGARETE LIGHTER | 1.00 |
| To Cig Lighter-Replaced Fuse.Scan Sys. No Codes.Test | | SHOP SUPPLIES | 1.00 |
| Drive. | | CIGARETE LIGHTER RECEPTACLE | 1.00 |
| - Shop Supplies | | | |
| Parts Charge: | 20.89 | Labor Charge: | 120.00 |

Workorder: 937880

Problem: P.M SERVICE

| Meter Reading: 21104 | Labor | Parts | |
|--|--------|--------------------------------------|----------|
| In Date: 05/18/2009 | Hours | Description | Quantity |
| - Pm Service | 7.30 | USED FIREX REFURBED FIRE EXTINGSHERS | 1.00 |
| - Replace 2 Tires.Put On Front. High Speed Balance 6 | | PH3506 OIL FILTER WIX 51042 | 1.00 |
| Tires. Fill W/Nitrogen | | SHOP SUPPLIES | 1.00 |
| - Replace Trailer Plug Socket.Broken.Straighten Mounting | | 5404 FEMALE CONNECTOR | 1.00 |
| Bracket. | | TIRE DISPOSAL FEE | 2.00 |
| - Shop Supplies | | 10W30 MOTOR OIL | 6.00 |
| | | 744821900 215/85R16 WRANGLER HT E | 2.00 |
| Parts Charge: | 357.56 | Labor Charge: | 438.00 |

10/11/2016
4:22:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11488 2004 GMC 3500 Pickup, 1 Ton

Workorder: 1001197

Problem: P.M service, see note.

| Meter Reading: 24930 In Date: 02/02/2010 | Close Date: 02/11/2010 | Labor Hours | Description | Parts | Quantity |
|--|------------------------|----------------------|--|-------|----------|
| - P.M Service. | | 12.60 | W/WASHER PUMP | | 1.00 |
| - Test & Repair Ground Circuit To Tag Lights, Test & Replace R/F Utility Bed Marker Lamp. | | | EVAP PURGE SOLENOID | | 1.00 |
| - Perform Computer Diagnostics, Run Evap Bay Test, Replace Purge Solinoid, Rerun Test & Clear Codes. | | | SHOP SUPPLIES | | 1.00 |
| - Mount Three New Tires, Repair One Tire, Rotate & Balance All Six Tires. | | | GROUP 78 BATTERY (ACD 78PS) | | 1.00 |
| - Replace Leaking Winshield Washer Fluid Bottle & Pump. | | | 744821900 215/85R16 WRANGLER HT E | | 3.00 |
| - Test Starting & Charging System, Charge & Test Battery, Replace Battery. | | | TIRE DISPOSAL FEE | | 3.00 |
| - Shop Supplies | | | 19006Y MARKER LIGHT 4" RECT YELLOW LED | | 1.00 |
| | | | PH3506 OIL FILTER WIX 51042 | | 1.00 |
| | | | 10W30 MOTOR OIL | | 6.00 |
| | | | 31-22 WIPER BLADES 22" WIPER BLADE | | 2.00 |
| | | | TR416 VALVE STEM | | 3.00 |
| | | | W/WASHER BOTTLE | | 1.00 |
| Parts Charge: | 780.00 | Labor Charge: | 756.00 | | |

Workorder: 1011672

Problem: Pm service.

| Meter Reading: 30329 In Date: 10/19/2010 | Close Date: 10/28/2010 | Labor Hours | Description | Parts | Quantity |
|--|------------------------|----------------------|--|-------|----------|
| - Perform Pm Service. | | 7.50 | TIRE DISPOSAL FEE | | 2.00 |
| - Install Two New Tires To The Front Wheels.Rotate And Balance All Six. | | | 19006R MARKER LIGHT 4" RECTANGULAR RED LED | | 1.00 |
| - Replace Failed Right Rear Marker Lamp With New.Fabricate And Rewire Power And Ground Circuits. | | | TR416 VALVE STEM | | 2.00 |
| - Shop Supplies | | | SHOP SUPPLIES | | 1.00 |
| | | | PH3506 OIL FILTER WIX 51042 | | 1.00 |
| | | | 6678 AIR FILTER FRM CA8755A WIX 46678 | | 1.00 |
| | | | 744821900 215/85R16 WRANGLER HT E | | 2.00 |
| | | | 10W30 MOTOR OIL | | 6.00 |
| | | | USED FIREX REFURBED FIRE EXTINGSHERS | | 1.00 |
| | | | 31-22 WIPER BLADES 22" WIPER BLADE | | 2.00 |
| Parts Charge: | 418.08 | Labor Charge: | 450.00 | | |

10/11/2016
4:22:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11488 2004 GMC 3500 Pickup, 1 Ton

Workorder: 1105410

Problem: P.M. service.

| Meter Reading: 33063 In Date: 05/23/2011 | Close Date: 05/31/2011 | Labor Hours | Description | Parts | Quantity |
|---|------------------------|----------------------|--------------------------------------|-------|----------|
| - Perform Pm Service. | | 13.25 | PH3506 OIL FILTER WIX 51042 | | 1.00 |
| - Computer Diagnose For Check Engine Light On.Test And | | | 10W30 MOTOR OIL | | 6.00 |
| Replace Failed Left Side Upstream Oxygen Sensor With | | | 744821900 215/85R16 WRANGLER HT E | | 4.00 |
| New.Clear Codes With Scan Tool And Road Test. | | | 31-22 WIPER BLADES 22" WIPER BLADE | | 2.00 |
| - Inspect Front Suspension For Noise And Replace Failed | | | OXYGEN SENSOR | | 1.00 |
| Steering Intermediate Sector Shaft With New. | | | USED FIREX REFURBED FIRE EXTINGSHERS | | 1.00 |
| - Inspect And Replace Failed Right Brake Lamp Bulb With | | | INTERMEDIATE STEERING SHAFT | | 1.00 |
| New. | | | SHOP SUPPLIES | | 1.00 |
| - Install Four New Tires.Nitrogen Fill And Balance All Six. | | | TIRE DISPOSAL FEE | | 4.00 |
| - Inspect And Repair Open Back Up Alarm Power Circuit To | | | 44202R TAIL LIGHT 4" RED 42 LED | | 1.00 |
| Make Backup Alarm Opperable. | | | | | |
| - Perform Wheel Alignment Complete. | | | | | |
| - Shop Supplies | | | | | |
| Parts Charge: 1,029.68 | | Labor Charge: | 795.00 | | |

Workorder: 1112661

Problem: P.M. service.

| Meter Reading: 34749 In Date: 11/30/2011 | Close Date: 12/12/2011 | Labor Hours | Description | Parts | Quantity |
|---|------------------------|----------------------|-----------------------------------|-------|----------|
| - Perform Pm Service. | | 7.25 | 10W30 MOTOR OIL | | 6.00 |
| - Fabricate And Replace Failed Rear Clearance Light Bar | | | PH3506 OIL FILTER WIX 51042 | | 1.00 |
| With New And Repair Wiring Harness. | | | 15835666 BUMPER CONTROL ARM (GMC) | | 2.00 |
| - Inspect And Replace Both Failed Front Lower Control Arm | | | SHOP SUPPLIES | | 1.00 |
| Bump Stops With New. | | | 15050R ID BAR RED MODEL 15 LED | | 1.00 |
| - Rotate And Balance All Six Tires. | | | | | |
| - Shop Supplies | | | | | |
| Parts Charge: 116.48 | | Labor Charge: | 435.00 | | |

10/11/2016
4:22:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11488 2004 GMC 3500 Pickup, 1 Ton

Workorder: 1206733 **Problem:** Pm service and ac blows warm air.

| Meter Reading: 35992 | Labor | Parts | | |
|---|-------|--------------------------------------|----------|--|
| In Date: 07/19/2012 | Hours | Description | Quantity | |
| - Perform Pm Service. | 11.00 | ORIFICE TUBE | 1.00 | |
| - Test Starting And Charging System.Battery Failed Load | | 31-22 WIPER BLADES 22" WIPER BLADE | 1.00 | |
| Test After Recharge.Replace Failed Battery With New. | | USED FIREX REFURBED FIRE EXTINGSHERS | 1.00 | |
| - Ac Performance And Leak Test System.Recover | | SHOP SUPPLIES | 1.00 | |
| Freon.Test And Replace Failed Expansion Valve,Low | | HIGH SIDE SERVICE PORT | 1.00 | |
| Cycle Switch And High Side Service Port With | | 10W30 MOTOR OIL | 6.00 | |
| New.Vacume And Recharge System To Specs.With | | 31-22 WIPER BLADES 22" WIPER BLADE | 1.00 | |
| Freon And Oil. | | A/C CYCLE SWITCH | 1.00 | |
| - Repair Right Rear Outer Tire Flat.Nitrogen Fill And | | PH3506 OIL FILTER WIX 51042 | 1.00 | |
| Balance All Six. | | GROUP 78 BATTERY (ACD 78PS) | 1.00 | |
| - Shop Supplies | | R134A REFRIGERANT | 2.00 | |
| Parts Charge: | | 213.83 | | |
| | | Labor Charge: | 660.00 | |

Workorder: 1301402 **Problem:** Pm service.Towed in for no start.

| Meter Reading: 37106 | Labor | Parts | | |
|--|-------|-----------------------|----------|--|
| In Date: 02/07/2013 | Hours | Description | Quantity | |
| - Perform Pm Service. | 12.00 | 10W30 MOTOR OIL | 6.00 | |
| - Computer Diagnose For No Start.Test And Replace Failed | | 31-22 WIPER BLADES 22 | 2.00 | |
| Fuel Pump Assembly With New.Had To Drain And Clean | | NAPAGOLD OIL FILTER | 1.00 | |
| Fuel Tank. | | SHOP SUPPLIES | 1.00 | |
| - Inspect And Replace Both Failed Serpentine Belts With | | K060923HD SERP BELT | 1.00 | |
| New. | | FUEL PUMP | 1.00 | |
| - Rotate And Balance All Six Tires. | | K040378HD A-C BELT | 1.00 | |
| - Fabricate And Secure Falling Headliner. | | | | |
| - Shop Supplies | | | | |
| Parts Charge: | | 479.67 | | |
| | | Labor Charge: | 720.00 | |

Workorder: 1301405 **Problem:** Stalled Out

| Meter Reading: 36782 | Labor | Parts | | |
|---|-------|---------------------------|----------|--|
| In Date: 02/07/2013 | Hours | Description | Quantity | |
| - Tow From: Congress Ave And Belvedere Rd To: Lv Shop | | | | |
| Parts Charge: | | 0.00 | | |
| | | Labor Charge: | 0.00 | |
| | | Commercial Charge: | 134.77 | |

10/11/2016
4:22:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11488 2004 GMC 3500 Pickup, 1 Ton

Workorder: 1310643

Problem: Trailer plug inop

| Meter Reading: 38545 | Labor | Parts | |
|--|-----------------------------|-----------------------|-----------------|
| In Date: 10/23/2013 | Hours | Description | Quantity |
| - Check Trailer Plug.Replace Trailer Plug And | 2.50 | 5404 FEMALE CONNECTOR | 1.00 |
| Rewire.Replace And Rewire Inop Trailer Brake Controller. | | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | 4047 BRAKE CONTROLLER | 1.00 |
| Parts Charge: 103.52 | Labor Charge: 150.00 | | |

Workorder: 1311415

Problem: P.M. service.

| Meter Reading: 38610 | Labor | Parts | |
|---|-----------------------------|-------------------------|-----------------|
| In Date: 11/12/2013 | Hours | Description | Quantity |
| - P.M. Service. | 12.00 | USED FIRE X REFURBISHED | 1.00 |
| - Replace And Balance Six New Tires. | | BRAKE CLEANER | 1.00 |
| - Blower High Speed Inop.Replace Blower Motor And | | 744821900 215-85R16 | 6.00 |
| Resistor.Replace Melted Resistor Connector. | | NAPAGOLD OIL FILTER | 1.00 |
| - Replace Right Brake Lamp Assemble And Left Rear | | RESISTOR | 1.00 |
| Marker Light.Repair Wiring. | | PT2195 PIGTAIL BLOWER | 1.00 |
| - Complete Wheel Alignment. | | 10W30 MOTOR OIL | 6.00 |
| - Shop Supplies | | WIPER BLADE | 2.00 |
| | | LED SUP MDL 44 42 DIO | 1.00 |
| | | TIRE DISPOSAL FEE | 6.00 |
| | | 15-81683 BLOWER MOTOR | 1.00 |
| | | M C LAMP | 1.00 |
| | | SHOP SUPPLIES | 1.00 |
| | | TR416 VALVE STEM | 6.00 |
| Parts Charge: 1,747.74 | Labor Charge: 720.00 | | |

10/11/2016
4:22:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11488 2004 GMC 3500 Pickup, 1 Ton

Workorder: 1406640

Problem: Pm service.

| Meter Reading: 41100 | Labor | Parts |
|---|--------------------|------------------------------|
| In Date: 07/07/2014 | Hours | Quantity |
| Close Date: 07/22/2014 | Description | |
| - Perform Pm Service. | 8.25 | 10W30 MOTOR OIL 6.00 |
| - Check Charging And Starting System.Battery Failed | | NAPAGOLD OIL FILTER 1.00 |
| Loadtest After Recharge.Replace Failed Battery With | | GROUP 78 BATTERY 1.00 |
| New. | | WIPER BLADE 2.00 |
| - Test And Replace Failed Left Drl Lamp Bulb With | | LONG LIFE SMALL BULB 1.00 |
| New.Also Replace Right Brake Lamp Seal/Grummet With | | door ckeck 1.00 |
| New.With New. | | SHOP SUPPLIES 1.00 |
| - Inspect Driver Door For Noise And Replace Failed Door | | GROMMET 1.00 |
| Stop With New.Adjust Door Hinges To Open And Close | | NAPAGOLD AIR FILTER 1.00 |
| Properly. | | USED FIRE X REFURBISHED 1.00 |
| - Rotate And Balance All Six Tires. | | |
| - Shop Supplies | | |
| Parts Charge: | 227.83 | Labor Charge: 495.00 |

10/11/2016
4:22:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11488 2004 GMC 3500 Pickup, 1 Ton

Workorder: 1502848

Problem: P.M. Service.

| Meter Reading: 44030 | Labor | Parts | Quantity |
|--|--------------|----------------------------|----------|
| In Date: 03/19/2015 | Hours | Description | Quantity |
| - Pm Service. | 25.50 | 10W30 MOTOR OIL | 6.00 |
| - Replace Failed Tag Lamp,Left Brake Lamp,Roof Clearance Lamps And Strobe Lamp Indicator.Fabricate Wiring As Needed. | | LED SUP MDL 44 42 DIO BULB | 1.00 |
| - Replace Rear Brake Pads And Both Rear Brake Calipers. Resurface Both Rear Brake Rotors.Flush And Bleed Brake System.Test Drive. | | DISC BRAKE PADS | 3.00 |
| - Replace Leaking Brake Hydro Booster Unit.Refill Fluid. | | LICENSE LAMP | 1.00 |
| - Inspect And Replace Both Failed Engine Mounts. | | USED FIRE X REFURBISHED | 1.00 |
| - Replace Two Tires.Rotate And Balance All Six. | | 1401 BRAKE FLUID BRA | 3.00 |
| - Test And Replace Both Failed Door Speakers.Diagnose Ticking Noise In Dash.Replace Failed Left And Right Temperature Blend Door Actuators.Had To Remove Instrument Panel To Access Right Side Actuator.Re | | BRAKE CLEANER | 1.00 |
| - Remove And Install Damage Driver Seat For Repair. | | SPEAKER | 2.00 |
| - Shop Supplies | | 744821900 215-85R16 | 2.00 |
| | | SEAT R AND R | 1.00 |
| | | TR416 VALVE STEM | 2.00 |
| | | TIRE DISPOSAL FEE | 2.00 |
| | | ENGINE MOUNT | 2.00 |
| | | GROMMET MOUNT KIT | 1.00 |
| | | NAPAGOLD OIL FILTER | 1.00 |
| | | DS367 YELLOW PILOT LI | 1.00 |
| | | REMAN BRAKE CALIPER | 1.00 |
| | | SHOP SUPPLIES | 1.00 |
| | | REMAN BRAKE CALIPER | 1.00 |
| | | WIPER BLADE | 2.00 |
| | | REMAN BRAKE BOOSTER | 1.00 |
| | | ACTUATOR | 2.00 |
| Parts Charge: | 2,033.65 | Labor Charge: | 1,530.00 |

Workorder: 1504752

Problem: Right rear outer tire flat

| Meter Reading: 44144 | Labor | Parts | Quantity |
|---|-------------|----------------------|----------|
| In Date: 05/11/2015 | Hours | Description | Quantity |
| - Repair And Balance Right Rear Outer Tire. | 1.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | |
| Parts Charge: | 2.00 | Labor Charge: | 60.00 |

10/11/2016
4:22:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11488 2004 GMC 3500 Pickup, 1 Ton

Workorder: 1510081

Problem: Pm service.

| Meter Reading: 45023 In Date: 10/05/2015 | Close Date: 10/27/2015 | Labor Hours | Description | Parts | Quantity |
|--|-------------------------------|-----------------------------|-----------------------|-------|----------|
| - Pm Service. | | 14.50 | REMAN PS PUMP | | 1.00 |
| - Replace Four Tires.Rotate And Balance All Six. | | | TIRE DISPOSAL FEE | | 4.00 |
| - Service Transmission.Replace Filter And Pan | | | SHOP SUPPLIES | | 1.00 |
| Gasket.Flush And Refill System. | | | PAN GASKET TRAMICION | | 1.00 |
| - Diagnose And Replace Defective Steering Gear Box.Flush | | | 10W30 MOTOR OIL | | 6.00 |
| Power Steeering Fluid. | | | NAPAGOLD OIL FILTER | | 1.00 |
| - Complete Front End Alignment. | | | WIPER BLADE | | 2.00 |
| - Shop Supplies | | | SYN-ATF TRANS FLUID S | | 16.00 |
| | | | TR416 VALVE STEM | | 4.00 |
| | | | TRANS FILTER | | 1.00 |
| | | | 744821900 215-85R16 | | 4.00 |
| | | | PSF QT | | 1.00 |
| | Parts Charge: 1,523.03 | Labor Charge: 870.00 | | | |

Workorder: 1602388

Problem: damage to left rear fender

| Meter Reading: 45545 In Date: 01/29/2016 | Close Date: 03/07/2016 | Labor Hours | Description | Parts | Quantity |
|---|---------------------------|---------------------------|-------------|----------------------------------|----------|
| - Damage To Left Rear Fender | | | | | |
| | Parts Charge: 0.00 | Labor Charge: 0.00 | | Commercial Charge: 660.00 | |

Workorder: 1605837

Problem: P.M. service.

| Meter Reading: 46976 In Date: 06/07/2016 | Close Date: 06/21/2016 | Labor Hours | Description | Parts | Quantity |
|---|-----------------------------|-----------------------------|-------------------------|-------|----------|
| - P.M. Service. | | 5.50 | 10W30 MOTOR OIL | | 6.00 |
| - Rotate And Balance All Six Wheels. | | | NAPAGOLD OIL FILTER | | 1.00 |
| - Shop Supplies | | | 22" WIPER BLADE | | 2.00 |
| | | | USED FIRE X REFURBISHED | | 1.00 |
| | | | GROUP 78 BATTERY | | 1.00 |
| | | | BATTERY CABLE BOLT | | 1.00 |
| | | | SHOP SUPPLIES | | 1.00 |
| | | | WASHER FLUID CONCENTR | | 1.00 |
| | Parts Charge: 150.11 | Labor Charge: 330.00 | | | |

10/11/2016
4:22:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11488 2004 GMC 3500 Pickup, 1 Ton

Total Parts Charges: **10,982.74**

Total Labor Charges: **10,012.00**

Total Comm. Charges: **1,034.77**