

10/17/2017
12:15:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139983 2003 ROCKET 17 Trailer For 17' Boat

Workorder: 343172	Problem: REPLACE LITE PLUG				
Meter Reading: 0		Labor	Parts		
In Date: 06/27/2003	Close Date: 06/30/2003	Hours	Description		Quantity
-	Replace Trailor Male Plug	1.50	755-5046 MALE CONNECTOR		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
	Parts Charge: 6.63	Labor Charge:	75.00		

Workorder: 344374	Problem: PRE-DELIVERY INSPECTION				
Meter Reading: 0		Labor	Parts		
In Date: 07/18/2003	Close Date: 07/18/2003	Hours	Description		Quantity
-	Pre-Delivery Inspection	2.00			
	Parts Charge: 0.00	Labor Charge:	100.00		

Workorder: 443899	Problem: NO LIGHTS				
Meter Reading: 0		Labor	Parts		
In Date: 05/07/2004	Close Date: 05/14/2004	Hours	Description		Quantity
-	Repair Trailer Lite Harness	1.50	SHOP SUPPLIES		1.00
-	Shop Supplies				
	Parts Charge: 2.00	Labor Charge:	75.00		

Workorder: 450259	Problem: TRAILER LIGHT				
Meter Reading: 0		Labor	Parts		
In Date: 07/08/2004	Close Date: 07/26/2004	Hours	Description		Quantity
-	Replace Light	1.50	2628 RH TAIL LIGHT		1.00
-	Shop Supplies		L/R LITE 2679		1.00
			SHOP SUPPLIES		1.00
	Parts Charge: 17.11	Labor Charge:	75.00		

10/17/2017
12:15:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139983 2003 ROCKET 17 Trailer For 17' Boat

Workorder: 451778

Problem: REPLACE R/R TAIL LIGHT

Meter Reading: 0	Labor	Parts	
In Date: 07/23/2004	Hours	Description	Quantity
- Replace Tail Light And Repair Wiring	1.50	SHOP SUPPLIES	1.00
- Shop Supplies		R/RLITE 2682	1.00
Parts Charge:	14.57	Labor Charge:	75.00

Workorder: 741029

Problem: PM SERVICE

Meter Reading: 0	Labor	Parts	
In Date: 07/05/2007	Hours	Description	Quantity
- Pm Single Axle Trailer	7.60	SHOP SUPPLIES	1.00
- Replace Both Tail Lights & Clearance Light		46760 SEAL	2.00
- Replace Both Lead Springs And U Bolts On Axle		18906 JACK WHEEL	1.00
- Nitro Tires		81733 GREASE CAP	2.00
- Replae Tongue Jack Wheel		SET4 BEARING	5.00
- Shop Supplies		14059 NUTS	2.00
		97073 U BOLT	2.00
		038 LEAF SPRING	2.00
		2699 BAR LITE RED	1.00
		2908 LIGHT KIT SUBM	1.00
		SET 4 BEARING	-1.00
Parts Charge:	171.63	Labor Charge:	27.50

Workorder: 839626

Problem: PM TRAILER, REPAIR TIRES AS NEEDED

Meter Reading: 0	Labor	Parts	
In Date: 06/06/2008	Hours	Description	Quantity
- Pm Service	3.50	SHOP SUPPLIES	1.00
- Replace One Valve Stem Nitro Both 2 Tiers To 50 Psi		46760 SEAL	2.00
- Shop Supplies			
Parts Charge:	4.40	Labor Charge:	30.00

10/17/2017
12:15:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139983 2003 ROCKET 17 Trailer For 17' Boat

Workorder: 938806 **Problem:** P.M. -SOUTH DISTRIC

Meter Reading: 0	Labor	Parts	
In Date: 06/09/2009	Hours	Description	
Close Date: 06/16/2009		Quantity	
- Pm Single Axle Trailer	4.00	SHOP SUPPLIES	1.00
- Repair Tongue Jack		46760 SEAL	2.00
- Shop Supplies			
Parts Charge: 5.36		Labor Charge: 240.00	

Workorder: 1007871 **Problem:** pm

Meter Reading: 0	Labor	Parts	
In Date: 07/23/2010	Hours	Description	
Close Date: 08/17/2010		Quantity	
- Pm Single Axle Trailer	5.00	46760 SEAL	2.00
- Replace Corroded And Damaged Male Plug		WINCH STRAP	1.00
- Replace Damged Winch Straps		755-5046 MALE CONNECTOR	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge: 20.90		Labor Charge: 300.00	

Workorder: 1108639 **Problem:** PM

Meter Reading: 0	Labor	Parts	
In Date: 08/16/2011	Hours	Description	
Close Date: 08/19/2011		Quantity	
- Pm Serviec	4.00	46760 SEAL	2.00
- Replace Asset#'S		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 6.20		Labor Charge: 240.00	

Workorder: 1208788 **Problem:** PM

Meter Reading: 0	Labor	Parts	
In Date: 09/14/2012	Hours	Description	
Close Date: 10/25/2012		Quantity	
- Pm Trailer	7.00	RATCHET REPAIR KIT	1.00
- Repair Winch		SHOP SUPPLIES	1.00
- Rewire Entire Trailer, Replace Both Tail And Side Marker		46760 SEAL	2.00
Left		5404 FEMALE CONNECTOR	1.00
- Shop Supplies		LED TRAILER LMP KIT	1.00
Parts Charge: 112.67		Labor Charge: 420.00	

10/17/2017
12:15:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139983 2003 ROCKET 17 Trailer For 17' Boat

Workorder: 1311462

Problem: pm service

Meter Reading: 0	Labor	Parts	
In Date: 11/13/2013	Hours	Description	Quantity
- Pm Service	5.00	TRAILER CONN PLUG	1.00
- Replace Trailer Plug		SHOP SUPPLIES	1.00
- Service Winch		46760 SEAL	2.00
- Shop Supplies			
Parts Charge:	12.51	Labor Charge:	300.00

Workorder: 1406431

Problem: lights/ check bearings and tires

Meter Reading: 0	Labor	Parts	
In Date: 07/01/2014	Hours	Description	Quantity
- Replace Plug And Repair Ground Thermosta Trailer	6.00	TIRE DISPOSAL FEE	2.00
- Replace 2 Tires		MALE TRAILER CONNECTOR	1.00
- Spring Crack Replace Spring Unit Repack Bearings And		SEAL 1.250 1.979 .250	2.00
Seals		U-BOLT SET	2.00
- Shop Supplies		762174406 175-80R13	2.00
		SPRING	2.00
		SHOP SUPPLIES	1.00
Parts Charge:	259.82	Labor Charge:	360.00

Workorder: 1411798

Problem: pm service/ replace trailer plug

Meter Reading: 0	Labor	Parts	
In Date: 11/20/2014	Hours	Description	Quantity
- Pm	5.50	SEAL 1.250 1.979 .250	2.00
- Replace Trailer Plug		TRAILER CONN PLUG	1.00
- Service Winch Strap		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	12.51	Labor Charge:	330.00

10/17/2017
12:15:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139983 2003 ROCKET 17 Trailer For 17' Boat

Workorder: 1511838

Problem: pm/ light broken

Meter Reading: 0	Labor	Parts	
In Date: 11/19/2015	Hours	Description	Quantity
- Pm	6.00	TRAILER CONN PLUG	1.00
- Replace Rear Tail Lights Along With Right Side Marker Light And Rewire		LGT/KIT	1.00
		SEAL 1.250 1.979 .250	2.00
- Replaced Trailer Plug And Wire Up		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	53.65	Labor Charge:	360.00

Workorder: 1603341

Problem: left tail light not working

Meter Reading: 0	Labor	Parts	
In Date: 03/30/2016	Hours	Description	Quantity
- Test Lights Rewire New Male Trailer Plug Replace Loft Of Cable For Trailer Plug Replae Blown Lights	2.50	MALE TRAILER CONNECTOR	1.00
		SUB LIGHT KIT	1.00
- Shop Supplies		BULK TRAILER WIRE	10.00
		SHOP SUPPLIES	1.00
		VINYL ELECTRICAL TAPE	1.00
Parts Charge:	96.60	Labor Charge:	150.00

Workorder: 1611823

Problem: pm service

Meter Reading: 0	Labor	Parts	
In Date: 11/16/2016	Hours	Description	Quantity
- Pm	6.50	SEAL 1.250 1.979 .250	2.00
- Replace Trailer Plug.- Repair Ground To Side Marker		SHOP SUPPLIES	1.00
- Replace Hub Assembly With Inner Outerr Bearings		TAPPERED BEARING SET	4.00
- Service Winch		HUB ASSY BT 16 W/BRG PAK 1	2.00
- Shop Supplies		NON-CHLOR BRAKE CLNR	1.00
		MALE TRAILER CONNECTOR	1.00
Parts Charge:	67.57	Labor Charge:	390.00

10/17/2017
12:15:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139983 2003 ROCKET 17 Trailer For 17' Boat

Workorder: 1707172

Problem: pm service, check trailer & left lgt broken

Meter Reading: 0	Labor	Parts
In Date: 07/21/2017	Hours	Description
Close Date: 07/27/2017		Quantity
- Pm Service	7.50	SUB LIGHT KIT
- Replace Trailer Plug And Tail Lights		SHOP SUPPLIES
- Replace Rusted Trailer Jack		CLEVIS SLIP HK W LTCH
- Replace Trailer Latch Coupler And Safety Chain And Hooks		SEAL 1.250 1.979 .250
- Service Winch		JACK ASSY
- Shop Supplies		NON-CHLOR BRAKE CLNR
		COUPLER REPAIR KIT
		MALE TRAILER CONNECTOR
Parts Charge:	182.12	Labor Charge: 450.00

Workorder: 1707847

Problem: hitch wont lock

Meter Reading: 0	Labor	Parts
In Date: 08/10/2017	Hours	Description
Close Date: 08/29/2017		Quantity
- Hitch Lock Not Working. New Trailer On Order. Customer Declines Repairs	0.50	
Parts Charge:	0.00	Labor Charge: 30.00

Workorder: 1709898

Problem: Transition Prep Charge

Meter Reading: 0	Labor	Parts
In Date: 10/11/2017	Hours	Description
Close Date: 10/11/2017		Quantity
- Transition Prep Charge	2.00	
Parts Charge:	0.00	Labor Charge: 120.00

Total Parts Charges:	1,046.25	Total Labor Charges:	4,147.50	Total Comm. Charges:	0.00
----------------------	-----------------	----------------------	-----------------	----------------------	-------------