

10/6/2017  
10:22:27AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K10984 2001 SPRAYING DEVICES INC. 30020KE12 Trailer, W/300 Gallon Sprayer

**Workorder:** 132889

**Problem:** SET UP AS REQUESTED

| Meter Reading: 0    |                                 | Labor                       |  | Parts |          |
|---------------------|---------------------------------|-----------------------------|--|-------|----------|
| In Date: 01/17/2001 | Close Date: 02/22/2001          | Hours                       | Description                                  |       | Quantity |
| -                   | Install Lights And Wiring       | 10.00                       | D-075-P KAMLOCK POLLY                        |       | 2.00     |
| -                   | Install Flood Valve And Plubing |                             | D-075-P KAMLOCK                              |       | 1.00     |
| -                   | Parts                           |                             | 755-5046 MALE CONNECTOR                      |       | 1.00     |
| -                   | Shop Supplies                   |                             | 82-5602 TRAILER WIRE 4 WIRE 14 GAUGE (GROTE) |       | 15.00    |
|                     |                                 |                             | 2628 RH TAIL LIGHT                           |       | 2.00     |
|                     |                                 |                             | A-075-P KAMLOCK                              |       | 3.00     |
|                     |                                 |                             | 307A STROBE LIGHT                            |       | 1.00     |
|                     |                                 |                             | 250ADH12A STROBE STROBE LIGHT 12/24VT        |       | 1.00     |
|                     |                                 |                             | SHOP SUPPLIES                                |       | 1.00     |
|                     |                                 |                             | 78006 TERMINAL BLOCK                         |       | 1.00     |
|                     |                                 |                             | 1321 RH LIGHT BOX                            |       | 1.00     |
|                     |                                 |                             | 1320 LH LIGHT BOX                            |       | 1.00     |
|                     | <b>Parts Charge:</b> 409.15     | <b>Labor Charge:</b> 450.00 |  |       |          |

**Workorder:** 133602

**Problem:** PRE-DELIVERY INSPECTION

| Meter Reading: 0    |                           | Labor                      |             | Parts |          |
|---------------------|---------------------------|----------------------------|-------------|-------|----------|
| In Date: 01/30/2001 | Close Date: 01/30/2001    | Hours                      | Description |       | Quantity |
| -                   | Pre-Delivery Inspection   | 2.00                       |             |       |          |
|                     | <b>Parts Charge:</b> 0.00 | <b>Labor Charge:</b> 90.00 |             |       |          |

**Workorder:** 133858

**Problem:** PRE-DELIVERY INSPECTION

| Meter Reading: 0    |                           | Labor                      |             | Parts |          |
|---------------------|---------------------------|----------------------------|-------------|-------|----------|
| In Date: 02/01/2001 | Close Date: 02/01/2001    | Hours                      | Description |       | Quantity |
| -                   | Pre-Delivery Inspection   | 2.00                       |             |       |          |
|                     | <b>Parts Charge:</b> 0.00 | <b>Labor Charge:</b> 90.00 |             |       |          |

10/6/2017  
10:22:27AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K10984 2001 SPRAYING DEVICES INC. 30020KE12 Trailer, W/300 Gallon Sprayer

**Workorder:** 134243

**Problem:** FAB STEPS WITH HAND RAIL

| Meter Reading: 0                             | Labor | Parts                                 |          |
|--|-------|---------------------------------------|----------|
| In Date: 02/09/2001                          | Hours | Description                           | Quantity |
| - Fab Steps W/Hand Rail Install Saftey Chain | 7.50  | T-235 GRAY PRIMER                     | 1.00     |
| - Fab Light Bracket                          |       | SHOP SUPPLIES                         | 1.00     |
| - Welding Supplies                           |       | 3/8X3X20 STEEL ANGLE                  | 4.00     |
|  |       | 1/8X1-1/4X24 SQ. TUBING STEEL         | 16.00    |
|  |       | 3/16X1-1/2X20 ALUM ANGLE ARCHITECTUAL | 3.00     |
|  |       | 3/16X4X12 ALUM PLATE 5052             | 1.00     |
|  |       | T-1 BLACK PAINT GLOSS                 | 2.00     |
|  |       | 2848 S HOOK                           | 2.00     |
| <b>Parts Charge:</b>                         | 99.02 | <b>Labor Charge:</b>                  | 337.50   |

**Workorder:** 138190

**Problem:** LIGHT OUT

| Meter Reading: 0     | Labor | Parts                |          |
|----------------------|-------|----------------------|----------|
| In Date: 04/19/2001  | Hours | Description          | Quantity |
| - Repair Wiring      | 1.00  |                      |          |
| <b>Parts Charge:</b> | 0.00  | <b>Labor Charge:</b> | 45.00    |

**Workorder:** 138386

**Problem:** VALVE INOPERABLE

| Meter Reading: 0     | Labor | Parts                |          |
|----------------------|-------|----------------------|----------|
| In Date: 04/23/2001  | Hours | Description          | Quantity |
| - Adjust Valve       | 1.00  |                      |          |
| <b>Parts Charge:</b> | 0.00  | <b>Labor Charge:</b> | 45.00    |

**Workorder:** 139802

**Problem:** NO TAIL LIGHTS/BATTERY DEAD

| Meter Reading: 0           | Labor | Parts                |          |
|----------------------------|-------|----------------------|----------|
| In Date: 05/16/2001        | Hours | Description          | Quantity |
| - Rewire Trailer Plug      | 3.00  | SHOP SUPPLIES        | 1.00     |
| - Clean And Charge Battery |       |                      |          |
| - Repair Valve             |       |                      |          |
| - Shop Supplies            |       |                      |          |
| <b>Parts Charge:</b>       | 2.00  | <b>Labor Charge:</b> | 135.00   |

10/6/2017  
10:22:27AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K10984 2001 SPRAYING DEVICES INC. 30020KE12 Trailer, W/300 Gallon Sprayer

**Workorder:** 140173                      **Problem:** ORDER SPRING LOCKING LATCH FOR HOSEREEL (2)

| Meter Reading: 0     | Labor | Parts                |          |
|----------------------|-------|----------------------|----------|
| In Date: 05/22/2001  | Hours | Description          | Quantity |
| - Install Hose Locks | 0.50  | LATCH                | 2.00     |
| - Shop Supplies      |       | SHOP SUPPLIES        | 1.00     |
| <b>Parts Charge:</b> | 77.90 | <b>Labor Charge:</b> | 22.50    |

**Workorder:** 145651                      **Problem:** REPLACE BATTERY

| Meter Reading: 0            | Labor | Parts                        |          |
|-----------------------------|-------|------------------------------|----------|
| In Date: 08/24/2001         | Hours | Description                  | Quantity |
| - Diagnose                  | 2.60  | SHOP SUPPLIES                | 1.00     |
| - Replace Battery           |       | GROUP 22NF BATTERY (ACD 351) | 1.00     |
| - Ck Charging System        |       |                              |          |
| - Test Run                  |       |                              |          |
| - Replaced Battery Terminal |       |                              |          |
| - Shop Supplies             |       |                              |          |
| <b>Parts Charge:</b>        | 50.37 | <b>Labor Charge:</b>         | 117.00   |

**Workorder:** 148418                      **Problem:** WON'T START

| Meter Reading: 0           | Labor | Parts                |          |
|----------------------------|-------|----------------------|----------|
| In Date: 10/15/2001        | Hours | Description          | Quantity |
| - Diagnose                 | 2.00  | SHOP SUPPLIES        | 1.00     |
| - Jump Start               |       |                      |          |
| - Replace Battery Terminal |       |                      |          |
| - Check Charging System    |       |                      |          |
| - Shop Supplies            |       |                      |          |
| <b>Parts Charge:</b>       | 2.00  | <b>Labor Charge:</b> | 100.00   |

**Workorder:** 148608                      **Problem:** WARRANTY REPAIR/REPLACE STARTER-KILPATRICK

| Meter Reading: 0                  | Labor | Parts                |          |
|-----------------------------------|-------|----------------------|----------|
| In Date: 10/16/2001               | Hours | Description          | Quantity |
| - 10/30 Starter Still Not Working | 1.00  | SHOP SUPPLIES        | 1.00     |
| - Shop Supplies                   |       |                      |          |
| <b>Parts Charge:</b>              | 2.00  | <b>Labor Charge:</b> | 50.00    |

10/6/2017  
10:22:27AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K10984 2001 SPRAYING DEVICES INC. 30020KE12 Trailer, W/300 Gallon Sprayer

| Workorder: 150476                                      |                     | Problem: WARRENTY/STARTER PROBLEMS           |             |                              |       |          |
|--|---------------------|--|-------------|------------------------------|-------|----------|
| Meter Reading: 0                                       | In Date: 11/20/2001 | Close Date: 12/04/2001                       | Labor Hours | Description                  | Parts | Quantity |
| - Warranty From Kilpatrick 11/29/01                    |                     |  |             |                              |       |          |
| Parts Charge: 0.00                                     |                     | Labor Charge: 0.00                           |             |                              |       |          |
| Workorder: 151721                                      |                     | Problem: NO START                            |             |                              |       |          |
| Meter Reading: 0                                       | In Date: 12/13/2001 | Close Date: 12/19/2001                       | Labor Hours | Description                  | Parts | Quantity |
| - Diagnose   |                     |  |             |                              |       |          |
|  |                     |  | 2.00        | GROUP 22NF BATTERY (ACD 351) |       | 1.00     |
| - R/Battery  |                     |  |             |                              |       |          |
|  |                     |  |             | SHOP SUPPLIES                |       | 1.00     |
| - Shop Supplies  |                     |  |             |                              |       |          |
| Parts Charge: 51.38                                    |                     | Labor Charge: 100.00                         |             |                              |       |          |
| Workorder: 239184                                      |                     | Problem: W                                   |             |                              |       |          |
| Meter Reading: 0                                       | In Date: 04/25/2002 | Close Date: 04/25/2002                       | Labor Hours | Description                  | Parts | Quantity |
| - Won'T Start Diagnosed Cranking And Charging System   |                     |  |             |                              |       |          |
|  |                     |  | 1.00        | SHOP SUPPLIES                |       | 1.00     |
| - Shop Supplies  |                     |  |             |                              |       |          |
| Parts Charge: 2.00                                     |                     | Labor Charge: 50.00                          |             |                              |       |          |
| Workorder: 240045                                      |                     | Problem: STARTER PROBLEMS/WARRENTY-KILPATRIC |             |                              |       |          |
| Meter Reading: 0                                       | In Date: 05/08/2002 | Close Date: 05/17/2002                       | Labor Hours | Description                  | Parts | Quantity |
| - Set Up Warranty Work With Kilpatrick                 |                     |  |             |                              |       |          |
|  |                     |  | 1.50        | SHOP SUPPLIES                |       | 1.00     |
| - Check Over. Warranty Repairs Completed By Kilpatrick |                     |  |             |                              |       |          |
| - Shop Supplies  |                     |  |             |                              |       |          |
| Parts Charge: 2.00                                     |                     | Labor Charge: 75.00                          |             |                              |       |          |

10/6/2017  
10:22:27AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K10984 2001 SPRAYING DEVICES INC. 30020KE12 Trailer, W/300 Gallon Sprayer

**Workorder:** 240594

**Problem:** RUNS POORLY

| Meter Reading: 0   | Labor | Parts                | Quantity |
|--|-------|----------------------|----------|
| In Date: 05/17/2002  | Hours | Description          |          |
| - Check Run & Poorly Problem, Engine Has Problem/Under Warrant | 1.00  | SHOP SUPPLIES        | 1.00     |
| - Shop Supplies  |       |                      |          |
| <b>Parts Charge:</b>   | 2.00  | <b>Labor Charge:</b> | 50.00    |

**Workorder:** 240596

**Problem:** SET UP FOR WARRENTY ENGINE REPAIRS

| Meter Reading: 0                                  | Labor | Parts                | Quantity |
|---|-------|----------------------|----------|
| In Date: 05/17/2002                               | Hours | Description          |          |
| - Set Up Warranty Work/Check Over Upon Completion | 1.50  | SHOP SUPPLIES        | 1.00     |
| - Shop Supplies                                   |       |                      |          |
| <b>Parts Charge:</b>                              | 2.00  | <b>Labor Charge:</b> | 75.00    |

**Workorder:** 244461

**Problem:** PUMP LEAKING

| Meter Reading: 0                    | Labor  | Parts                | Quantity |
|-------------------------------------|--------|----------------------|----------|
| In Date: 07/22/2002                 | Hours  | Description          |          |
| - Sprayer Front Housing Cracked R/R | 3.00   | OIL SEAL 78-029      | 1.00     |
| - Shop Supplies                     |        | O'RING 78-032        | 1.00     |
|                                     |        | O'RING 78-030        | 1.00     |
|                                     |        | SHOP SUPPLIES        | 1.00     |
|                                     |        | O'RING 78-031        | 1.00     |
|                                     |        | FLANGE 78-033        | 1.00     |
|                                     |        | SCREW 78-034         | 6.00     |
| <b>Parts Charge:</b>                | 198.12 | <b>Labor Charge:</b> | 150.00   |

10/6/2017  
10:22:27AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K10984 2001 SPRAYING DEVICES INC. 30020KE12 Trailer, W/300 Gallon Sprayer

**Workorder:** 246728

**Problem:** REPAIR CHOKE

| Meter Reading: 0       | Labor | Parts                  |          |
|------------------------|-------|------------------------|----------|
| In Date: 08/26/2002    | Hours | Description            | Quantity |
| - Replace Spark Plug   | 2.00  | BPR4HS SPARK PLUG 7823 | 1.00     |
| - Repair Choke Linkage |       | SHOP SUPPLIES          | 1.00     |
| - Test Run             |       |                        |          |
| - Shop Supplies        |       |                        |          |
| <b>Parts Charge:</b>   | 6.44  | <b>Labor Charge:</b>   | 100.00   |

**Workorder:** 251942

**Problem:** WON'T START

| Meter Reading: 0                              | Labor | Parts                |          |
|---|-------|----------------------|----------|
| In Date: 11/19/2002                           | Hours | Description          | Quantity |
| - Starter Draw Excessive, Found Engine Seized | 7.80  | SHOP SUPPLIES        | 1.00     |
| - Remove Head Free Engine Reinstall Head      |       | 10W30 MOTOR OIL      | 1.00     |
| - Carb,Clean, Drain Tank, Repair Fuel Cut Off |       |                      |          |
| - Service Engine Fuel Contaminated            |       |                      |          |
| - Test Run                                    |       |                      |          |
| - Shop Supplies                               |       |                      |          |
| <b>Parts Charge:</b>                          | 3.67  | <b>Labor Charge:</b> | 390.00   |

**Workorder:** 333286

**Problem:** P.M.

| Meter Reading: 0                             | Labor | Parts                   |          |
|--|-------|-------------------------|----------|
| In Date: 01/23/2003                          | Hours | Description             | Quantity |
| - Pm Spray Unit-Engine Pump, Service Battery | 8.50  | 30WT ND OIL             | 1.00     |
| - Service Trailer                            |       | 63-083-01 FILTER        | 1.00     |
| - Replace Trailer Plug, Repair Wiring        |       | RC12YC SPARK PLUG       | 1.00     |
| - Test Run                                   |       | 63-083-09 PRECLEANER    | 1.00     |
| - Repair Tire                                |       | SHOP SUPPLIES           | 1.00     |
| - Shop Supplies                              |       | 755-5046 MALE CONNECTOR | 1.00     |
|  |       | 10W30 MOTOR OIL         | 2.00     |
| <b>Parts Charge:</b>                         | 61.30 | <b>Labor Charge:</b>    | 425.00   |

10/6/2017  
10:22:27AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K10984 2001 SPRAYING DEVICES INC. 30020KE12 Trailer, W/300 Gallon Sprayer

**Workorder:** 346027

**Problem:** REPAIR ELECTRIC HOSE REEL

| Meter Reading: 0                                     | Labor | Parts                | Quantity |
|--|-------|----------------------|----------|
| In Date: 08/14/2003                                  | Hours | Description          | Quantity |
| - Trace And Repair Open Circuit In Electric Reel Sys | 2.50  | SHOP SUPPLIES        | 1.00     |
| - Test Run   |       |                      |          |
| - Shop Supplies                                      |       |                      |          |
| <b>Parts Charge:</b>                                 | 2.00  | <b>Labor Charge:</b> | 125.00   |

**Workorder:** 351046

**Problem:** PACKING LEAKING

| Meter Reading: 0   | Labor  | Parts                   | Quantity |
|--|--------|-------------------------|----------|
| In Date: 11/03/2003                                      | Hours  | Description             | Quantity |
| - Replace Shaft Packing                                  | 6.50   | 16-817 TEFLON PACKING   | 36.00    |
| - Replace Pump Flang E And O'Rings                       |        | SHOP SUPPLIES           | 1.00     |
| - Install New Battery Tray And Battery After Tray Primed |        | 78-029 OIL SEAL         | 1.00     |
| And Painted  |        | 78-030 O-RING           | 1.00     |
| - Test Run To Confirm Repair                             |        | 78-031 O-RING           | 1.00     |
| - Shop Supplies  |        | 78-032 O-RING           | 1.00     |
|  |        | 78-033 DISCHARGE FLANGE | 1.00     |
| <b>Parts Charge:</b>                                     | 223.04 | <b>Labor Charge:</b>    | 325.00   |

**Workorder:** 435362

**Problem:** WONT START

| Meter Reading: 0                            | Labor | Parts                 | Quantity |
|---|-------|-----------------------|----------|
| In Date: 02/18/2004                         | Hours | Description           | Quantity |
| - Check Compression                         | 3.50  | BKR5E SPARK PLUG 7938 | 1.00     |
| - Remove And Drain Carb And Clean Reinstall |       | SHOP SUPPLIES         | 1.00     |
| - Check Spark And Replace Plug              |       |                       |          |
| - Test Run                                  |       |                       |          |
| - Shop Supplies                             |       |                       |          |
| <b>Parts Charge:</b>                        | 4.02  | <b>Labor Charge:</b>  | 175.00   |

10/6/2017  
10:22:27AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K10984 2001 SPRAYING DEVICES INC. 30020KE12 Trailer, W/300 Gallon Sprayer

**Workorder:** 441638

**Problem:** NO START

| Meter Reading: 0           |   | Labor                       |                              | Parts    |  |
|----------------------------|---|-----------------------------|------------------------------|----------|--|
| In Date: 04/16/2004        | Close Date: 04/21/2004  | Hours                       | Description                  | Quantity |  |
| -                          | Tested Old Battery  | 2.00                        | SHOP SUPPLIES                | 1.00     |  |
| -                          | Checked For Voltage Draw And Checked Charging Sys.<br>Repaired Wire |                             | GROUP 22NF BATTERY (ACD 351) | 1.00     |  |
| -                          | Test Ran  |                             |                              |          |  |
| -                          | Shop Supplies   |                             |                              |          |  |
| <b>Parts Charge:</b> 48.39 |   | <b>Labor Charge:</b> 100.00 |                              |          |  |

**Workorder:** 449584

**Problem:** P.M./PACKING LEAKING ON TANK

| Meter Reading: 0            |  | Labor                       |                      | Parts    |  |
|-----------------------------|--|-----------------------------|----------------------|----------|--|
| In Date: 07/01/2004         | Close Date: 07/23/2004                 | Hours                       | Description          | Quantity |  |
| -                           | Pm Unit                                | 8.50                        | 8752 SEALS           | 2.00     |  |
| -                           | Replace Agitate Packing Seal On Tank   |                             | SHOP SUPPLIES        | 1.00     |  |
| -                           | Pm Trailer Sing Axle                   |                             | 10W30 MOTOR OIL      | 2.00     |  |
| -                           | Test Run Fill W/Water And Ck For Leaks |                             | RC12YC SPARK PLUG 71 | 1.00     |  |
| -                           | Repair Leaking Hose Connector          |                             | 78068 OIL FILL CAP   | 1.00     |  |
| -                           | Shop Supplies                          |                             | 16950 TEFLON PACKING | 36.00    |  |
|                             |  |                             | O-RING 78071         | 1.00     |  |
|                             |  |                             | O-RING 78069         | 1.00     |  |
|                             |  |                             | FILLER/NECK 78070    | 1.00     |  |
|                             |  |                             | A/FILTER 16308301    | 1.00     |  |
|                             |  |                             | AGGATATOR 16272      | 1.00     |  |
|                             |  |                             | A/FILTER 16308308    | 1.00     |  |
| <b>Parts Charge:</b> 192.22 |  | <b>Labor Charge:</b> 425.00 |                      |          |  |

**Workorder:** 534571

**Problem:** DEAD BATTERY

| Meter Reading: 0           |                        | Labor                      |                              | Parts    |  |
|----------------------------|------------------------|----------------------------|------------------------------|----------|--|
| In Date: 01/27/2005        | Close Date: 01/31/2005 | Hours                      | Description                  | Quantity |  |
| -                          | Repalce Battery        | 1.50                       | BUNGIE CORD STOCK# 450240010 | 1.00     |  |
| -                          | Test Run               |                            | GROUP 22NF BATTERY (ACD 351) | 1.00     |  |
| -                          | Shop Supplies          |                            | SHOP SUPPLIES                | 1.00     |  |
| <b>Parts Charge:</b> 46.27 |                        | <b>Labor Charge:</b> 75.00 |                              |          |  |



10/6/2017  
10:22:27AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K10984 2001 SPRAYING DEVICES INC. 30020KE12 Trailer, W/300 Gallon Sprayer

**Workorder:** 552789

**Problem:** REPLACE BROKEN NIPPLE

| Meter Reading: 0                             | Labor | Parts                |          |
|--|-------|----------------------|----------|
| In Date: 08/11/2005                          | Hours | Description          | Quantity |
| - Replace Broken Fitting Supplied By Airport | 3.00  | SHOP SUPPLIES        | 1.00     |
| - Test Run                                   |       |                      |          |
| - Shop Supplies                              |       |                      |          |
| <b>Parts Charge:</b>                         | 2.00  | <b>Labor Charge:</b> | 150.00   |

**Workorder:** 554900

**Problem:** CARB LINKAGE

| Meter Reading: 0                                     | Labor | Parts                              |          |
|--|-------|------------------------------------|----------|
| In Date: 09/13/2005                                  | Hours | Description                        | Quantity |
| - Bent And Frozen Linkage Repair As Needed           | 4.00  | 15/40 OIL                          | 1.00     |
| - Wont Start Water In Fuel R&R Fuel Tank Drain Carb. |       | 15/40 OIL                          | -1.00    |
| - Test Run   |       | SHOP SUPPLIES                      | 1.00     |
| - Shop Supplies                                      |       | SF16 MOTOR TREATMENT DON'T REORDER | 1.00     |
| <b>Parts Charge:</b>                                 | 11.89 | <b>Labor Charge:</b>               | 200.00   |

**Workorder:** 555925

**Problem:** TRAILER PLUG

| Meter Reading: 0       | Labor | Parts                   |          |
|------------------------|-------|-------------------------|----------|
| In Date: 09/28/2005    | Hours | Description             | Quantity |
| - Replace Trailer Plug | 1.50  | 755-5046 MALE CONNECTOR | 1.00     |
| - Shop Supplies        |       | SHOP SUPPLIES           | 1.00     |
| <b>Parts Charge:</b>   | 8.20  | <b>Labor Charge:</b>    | 75.00    |

**Workorder:** 556663

**Problem:** WON'T START

| Meter Reading: 0                       | Labor  | Parts                |          |
|--|--------|----------------------|----------|
| In Date: 10/12/2005                    | Hours  | Description          | Quantity |
| - No Start-Starter Bad.R/R Bad Starter | 4.50   | SHOP SUPPLIES        | 1.00     |
| - R/R Engine Shrouding To Excess Start |        | STARTER 6309801-S    | 1.00     |
| - R/R Battery                          |        |                      |          |
| - Test Run                             |        |                      |          |
| - Shop Supplies                        |        |                      |          |
| - R&R Fuel Tank To Remove Shrouding    |        |                      |          |
| <b>Parts Charge:</b>                   | 286.67 | <b>Labor Charge:</b> | 225.00   |

10/6/2017  
10:22:27AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K10984 2001 SPRAYING DEVICES INC. 30020KE12 Trailer, W/300 Gallon Sprayer

**Workorder:** 633156

**Problem:** FUEL CAP

| <b>Meter Reading:</b> 0              | <b>Labor</b>               | <b>Parts</b>               |                 |
|--------------------------------------|----------------------------|----------------------------|-----------------|
| <b>In Date:</b> 01/23/2006           | <b>Hours</b>               | <b>Description</b>         | <b>Quantity</b> |
| - Replace Fuel Cap-Tighten Fuel Tank | <b>0.50</b>                | 17620ZH7023 FUEL CAP HONDA | 1.00            |
| <b>Parts Charge:</b> 14.36           | <b>Labor Charge:</b> 25.00 |                            |                 |

**Workorder:** 636128

**Problem:** PM SERVICE/REPLACE LOST COVER ON TANK

| <b>Meter Reading:</b> 0   | <b>Labor</b>               | <b>Parts</b>                         |                 |
|---|----------------------------|--------------------------------------|-----------------|
| <b>In Date:</b> 03/22/2006  | <b>Hours</b>               | <b>Description</b>                   | <b>Quantity</b> |
| - Service Engine Only   | <b>3.00</b>                | SAE 30W OIL                          | 1.00            |
| - Replace Lost Cover Dull Rivets Out Reseal Lid Mount Mounting Assembly And Lid Cover |                            | SCREW ON LID 15-040<br>SHOP SUPPLIES | 1.00<br>1.00    |
| - Shop Supplies   |                            |                                      |                 |
| <b>Parts Charge:</b> 135.06   | <b>Labor Charge:</b> 75.00 |                                      |                 |

**Workorder:** 641438

**Problem:** WON'T START

| <b>Meter Reading:</b> 0     | <b>Labor</b>               | <b>Parts</b>       |                 |
|-----------------------------|----------------------------|--------------------|-----------------|
| <b>In Date:</b> 06/26/2006  | <b>Hours</b>               | <b>Description</b> | <b>Quantity</b> |
| - R&R Starter               | <b>6.50</b>                | STARTER 6309801-S  | 1.00            |
| - R&R Gas Tank              |                            | SHOP SUPPLIES      | 1.00            |
| - Service Engine            |                            | 10W30 MOTOR OIL    | 2.00            |
| - Test Run                  |                            |                    |                 |
| - Shop Supplies             |                            |                    |                 |
| <b>Parts Charge:</b> 308.85 | <b>Labor Charge:</b> 25.00 |                    |                 |

10/6/2017  
10:22:27AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K10984 2001 SPRAYING DEVICES INC. 30020KE12 Trailer, W/300 Gallon Sprayer

**Workorder:** 735811

**Problem:** P.M./REPLACE HOSE ON HOSE REEL/

| Meter Reading: 0                     |                        | Labor  |                                | Parts |          |
|--------------------------------------|------------------------|--------|--------------------------------|-------|----------|
| In Date: 03/19/2007                  | Close Date: 04/23/2007 | Hours  | Description                    |       | Quantity |
| - Pm Sprayer                         |                        | 7.00   | 10W30 MOTOR OIL                |       | 2.00     |
| - Hose To Be Installed At Later Date |                        |        | BKR5E SPARK PLUG 7938          |       | 1.00     |
| - Service Trailer Single Axle        |                        |        | 8752 SEALS                     |       | 2.00     |
| - Replace Nitro Tires X2             |                        |        | PRE/FLTR 6308302S              |       | 1.00     |
| - Shop Supplies                      |                        |        | 150601-300 HOSE                |       | 1.00     |
|                                      |                        |        | 160540116 11L-15 LABORER 10PLY |       | 2.00     |
|                                      |                        |        | A/FLTR 6308301S                |       | 1.00     |
|                                      |                        |        | SHOP SUPPLIES                  |       | 1.00     |
| <b>Parts Charge:</b>                 |                        | 941.25 | <b>Labor Charge:</b>           | 55.00 |          |

**Workorder:** 741575

**Problem:** REPAIR LEAK

| Meter Reading: 0                    |                        | Labor |                      | Parts |          |
|-------------------------------------|------------------------|-------|----------------------|-------|----------|
| In Date: 07/17/2007                 | Close Date: 07/18/2007 | Hours | Description          |       | Quantity |
| - Repair Plumbing                   |                        | 2.00  | SHOP SUPPLIES        |       | 1.00     |
| - Fabricate Nozzel Holddown Bracket |                        |       |                      |       |          |
| - Shop Supplies                     |                        |       |                      |       |          |
| <b>Parts Charge:</b>                |                        | 2.00  | <b>Labor Charge:</b> | 55.00 |          |

**Workorder:** 742354

**Problem:** RIGHT TAIL LAMP INOP.

| Meter Reading: 0            |                        | Labor |                       | Parts |          |
|-----------------------------|------------------------|-------|-----------------------|-------|----------|
| In Date: 07/31/2007         | Close Date: 08/02/2007 | Hours | Description           |       | Quantity |
| - Replace Female Light Plug |                        | 1.50  | 5404 FEMALE CONNECTOR |       | 1.00     |
| - Shop Supplies             |                        |       | SHOP SUPPLIES         |       | 1.00     |
| <b>Parts Charge:</b>        |                        | 11.57 | <b>Labor Charge:</b>  | 82.50 |          |

**Workorder:** 743273

**Problem:** PARTS/ BATTERY BILL DWYER

| Meter Reading: 0                |                        | Labor |                              | Parts |          |
|---------------------------------|------------------------|-------|------------------------------|-------|----------|
| In Date: 08/28/2007             | Close Date: 08/29/2007 | Hours | Description                  |       | Quantity |
| - Parts Only/Battery-Bill Dwyer |                        |       | GROUP 22NF BATTERY (ACD 351) |       | 1.00     |
| <b>Parts Charge:</b>            |                        | 42.75 | <b>Labor Charge:</b>         | 0.00  |          |

10/6/2017  
10:22:27AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K10984 2001 SPRAYING DEVICES INC. 30020KE12 Trailer, W/300 Gallon Sprayer

**Workorder:** 839617

**Problem:** PM SERVICE,SUPPLY 3 NEW FILTER COVERS

| Meter Reading: 0   |                        | Labor                       |                           | Parts |          |
|--|------------------------|-----------------------------|---------------------------|-------|----------|
| In Date: 06/06/2008  | Close Date: 07/01/2008 | Hours                       | Description               |       | Quantity |
| - Pm Engine  |                        | 8.00                        | PRE CLEANER               |       | 1.00     |
| - Service Trailer  |                        |                             | 10W30 MOTOR OIL           |       | 2.00     |
| - Replace Damaged Filter Cover And Supply With 2 Extras                |                        |                             | FILTER                    |       | 1.00     |
| - Clean And Coat Rusted Battery Tray, Repalce Cracked Battery Terminal |                        |                             | BKR5E SPARK PLUG 7938     |       | 1.00     |
| - Shop Supplies  |                        |                             | CLEAR BOWL FOR STRAINER   |       | 3.00     |
|  |                        |                             | 42703 GASKET TORO         |       | 3.00     |
|  |                        |                             | BP90 TERMINAL #4 STANDARD |       | 2.00     |
|  |                        |                             | SHOP SUPPLIES             |       | 1.00     |
|  |                        |                             | 8752 SEALS                |       | 2.00     |
| <b>Parts Charge:</b> 313.29  |                        | <b>Labor Charge:</b> 120.00 |                           |       |          |

**Workorder:** 842100

**Problem:** WILL NOT START

| Meter Reading: 0          |                        | Labor                      |               | Parts |          |
|---------------------------|------------------------|----------------------------|---------------|-------|----------|
| In Date: 07/29/2008       | Close Date: 08/12/2008 | Hours                      | Description   |       | Quantity |
| - Charge And Ck Battery   |                        | 1.00                       | SHOP SUPPLIES |       | 1.00     |
| - Shop Supplies           |                        |                            |               |       |          |
| <b>Parts Charge:</b> 2.00 |                        | <b>Labor Charge:</b> 60.00 |               |       |          |

**Workorder:** 939140

**Problem:** PM SERVICE,REPLACE JACK HANDLE

| Meter Reading: 0           |                        | Labor                       |                       | Parts |          |
|----------------------------|------------------------|-----------------------------|-----------------------|-------|----------|
| In Date: 06/17/2009        | Close Date: 06/24/2009 | Hours                       | Description           |       | Quantity |
| - Pm Service               |                        | 6.00                        | BKR5E SPARK PLUG 7938 |       | 1.00     |
| - Trailer Service          |                        |                             | 8752 SEALS            |       | 2.00     |
| - Repalce Jack Stand       |                        |                             | JACK ASSY             |       | 1.00     |
| - Shop Supplies            |                        |                             | 10W30 MOTOR OIL       |       | 2.00     |
|                            |                        |                             | SHOP SUPPLIES         |       | 1.00     |
| <b>Parts Charge:</b> 85.12 |                        | <b>Labor Charge:</b> 360.00 |                       |       |          |

10/6/2017  
10:22:27AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K10984 2001 SPRAYING DEVICES INC. 30020KE12 Trailer, W/300 Gallon Sprayer

**Workorder:** 946580

**Problem:** Repair Electric Reel

| Meter Reading: 0  | Labor                       | Parts         | Quantity |
|---|-----------------------------|---------------|----------|
| In Date: 12/02/2009   | Hours                       | Description   |          |
| - Reel Motor Not Engaging Reel R&R Motor To Sit Closer To Reel. Reposition Reel Bushings To Reduce End Play In Reel | 3.00                        | SHOP SUPPLIES | 1.00     |
| - Shop Supplies   |                             |               |          |
| <b>Parts Charge:</b> 2.00   | <b>Labor Charge:</b> 360.00 |               |          |

**Workorder:** 1000627

**Problem:** REPAIR ELECTRIC REEL

| Meter Reading: 0          | Labor                     | Parts       | Quantity |
|---------------------------|---------------------------|-------------|----------|
| In Date: 01/15/2010       | Hours                     | Description |          |
| -                         |                           |             |          |
| <b>Parts Charge:</b> 0.00 | <b>Labor Charge:</b> 0.00 |             |          |

**Workorder:** 1005119

**Problem:** blown hose

| Meter Reading: 0                                    | Labor                      | Parts         | Quantity |
|---|----------------------------|---------------|----------|
| In Date: 05/17/2010                                 | Hours                      | Description   |          |
| - Cut Hose At Damage Area And Reattach Spray Nozzle | 1.00                       | SHOP SUPPLIES | 1.00     |
| - Shop Supplies                                     |                            |               |          |
| <b>Parts Charge:</b> 2.00                           | <b>Labor Charge:</b> 60.00 |               |          |

10/6/2017  
10:22:27AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K10984 2001 SPRAYING DEVICES INC. 30020KE12 Trailer, W/300 Gallon Sprayer

**Workorder:** 1007283

**Problem:** won't start / pm

| Meter Reading: 0                  |                        | Labor                       |  | Parts |          |
|-----------------------------------|------------------------|-----------------------------|--|-------|----------|
| In Date: 07/12/2010               | Close Date: 07/29/2010 | Hours                       | Description                              |       | Quantity |
| - Pm Spraying Rig                 |                        | 7.50                        | BKR5E SPARK PLUG 7938                    |       | 1.00     |
| - Service Trailer                 |                        |                             | 8752 SEALS                               |       | 2.00     |
| - Replace Faulty Starty           |                        |                             | AIR FILTER                               |       | 1.00     |
| - Replace Both Hub Wheel Bearings |                        |                             | PRE FILTER                               |       | 1.00     |
| - Shop Supplies                   |                        |                             | SET 2 BEARING SET TIMKEN LM11949/LM11910 |       | 2.00     |
|                                   |                        |                             | SHOP SUPPLIES                            |       | 1.00     |
|                                   |                        |                             | SET 6 BEARING SET 67010 67048 (TIMKEN)   |       | 2.00     |
|                                   |                        |                             | STARTER ASSY                             |       | 1.00     |
|                                   |                        |                             | 10W30 MOTOR OIL                          |       | 2.00     |
| <b>Parts Charge:</b> 553.40       |                        | <b>Labor Charge:</b> 450.00 |  |       |          |

**Workorder:** 1108168

**Problem:** PM

| Meter Reading: 0                         |                        | Labor                       |                              | Parts |          |
|--|------------------------|-----------------------------|------------------------------|-------|----------|
| In Date: 08/04/2011                      | Close Date: 08/05/2011 | Hours                       | Description                  |       | Quantity |
| - Pm Service                             |                        | 8.50                        | 10W30 MOTOR OIL              |       | 2.00     |
| - Pm Trailer                             |                        |                             | BKR5E SPARK PLUG 7938        |       | 1.00     |
| - Check Charging Sys And Replace Battery |                        |                             | 8752 SEALS                   |       | 2.00     |
| - Replace Trailer Plug                   |                        |                             | GROUP 22NF BATTERY (ACD 351) |       | 1.00     |
| - Shop Supplies                          |                        |                             | 755-5046 MALE CONNECTOR      |       | 1.00     |
|  |                        |                             | SHOP SUPPLIES                |       | 1.00     |
| <b>Parts Charge:</b> 99.28               |                        | <b>Labor Charge:</b> 510.00 |                              |       |          |

**Workorder:** 1112650

**Problem:** trailer plug

| Meter Reading: 0                 |                        | Labor                      |             | Parts |          |
|----------------------------------|------------------------|----------------------------|-------------|-------|----------|
| In Date: 11/30/2011              | Close Date: 11/30/2011 | Hours                      | Description |       | Quantity |
| - Repair Trailer Plug Connection |                        | 0.50                       |             |       |          |
| <b>Parts Charge:</b> 0.00        |                        | <b>Labor Charge:</b> 30.00 |             |       |          |

10/6/2017  
10:22:27AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K10984 2001 SPRAYING DEVICES INC. 30020KE12 Trailer, W/300 Gallon Sprayer

**Workorder:** 1113258

**Problem:** reel problem

| Meter Reading: 0                      | Labor                      | Parts                            | Quantity |
|---------------------------------------|----------------------------|----------------------------------|----------|
| In Date: 12/16/2011                   | Hours                      | Description                      |          |
| - R&R Reel Motor, Send Out For Repair | 1.50                       | SHOP SUPPLIES                    | 1.00     |
| - Travel To P/U Parts                 |                            |                                  |          |
| - Shop Supplies                       |                            |                                  |          |
| <b>Parts Charge:</b> 2.00             | <b>Labor Charge:</b> 90.00 | <b>Commercial Charge:</b> 150.00 |          |

**Workorder:** 1203716

**Problem:** needs fuel cap

| Meter Reading: 0           | Labor                      | Parts       | Quantity |
|----------------------------|----------------------------|-------------|----------|
| In Date: 04/19/2012        | Hours                      | Description |          |
| - Replace Fuel Cap         | 0.50                       | FUEL CAP    | 1.00     |
| <b>Parts Charge:</b> 12.75 | <b>Labor Charge:</b> 30.00 |             |          |

**Workorder:** 1302330

**Problem:** pm/ lights/ gauge/ hose/ see notes

| Meter Reading: 0                                    | Labor                       | Parts                 | Quantity |
|---|-----------------------------|-----------------------|----------|
| In Date: 03/07/2013                                 | Hours                       | Description           |          |
| - Pm Service  | 8.50                        | SHOP SUPPLIES         | 1.00     |
| - Trailer Service                                   |                             | NAPA 10W30 QT         | 2.00     |
| - Replace Trailer Plug                              |                             | SPARK PLUG            | 1.00     |
| - Replace Strobe Light And Rewire                   |                             | SEAL                  | 2.00     |
| - Cut Off Damaged Length Of Spray Hose And Reattach |                             | TRAILER CONN PLUG     | 1.00     |
| - Spray Nozzle Repalce Pressure Gauge               |                             | 0-200 PSI GAUGE       | 1.00     |
| - Shop Supplies                                     |                             | 250ADH12A STROBE STRO | 1.00     |
| <b>Parts Charge:</b> 275.33                         | <b>Labor Charge:</b> 510.00 |                       |          |

10/6/2017  
10:22:27AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K10984 2001 SPRAYING DEVICES INC. 30020KE12 Trailer, W/300 Gallon Sprayer

**Workorder:** 1306074

**Problem:** pump leaking oil into tank

| Meter Reading: 0   |                               | Labor                       | Parts                |          |
|--|-------------------------------|-----------------------------|----------------------|----------|
| In Date: 06/18/2013  | Close Date: 07/24/2013        | Hours                       | Description          | Quantity |
| - R/R Pump To Repair Diaphragms Valves, R/R Head And Valve Covers Corrosion Test Run |                               | 6.00                        | DIAPHRAGM REPAIR KIT | 3.00     |
|  |                               |                             | Freight Charge       | 1.00     |
| - Remove Rottenh Bolts From Trailer Tongue Frame Connection. Install New Bolts       |                               |                             | MANIFOLD VALVE       | 3.00     |
|  |                               |                             | O-RING               | 6.00     |
| - Shop Supplies  |                               |                             | Freight Charge       | 1.00     |
|  |                               |                             | SHOP SUPPLIES        | 1.00     |
|  |                               |                             | O-RING               | 6.00     |
|  |                               |                             | O-RING               | 6.00     |
|  |                               |                             | VALVE COVER          | 3.00     |
|  |                               |                             | VALVE & SEAL KIT     | 6.00     |
|  |                               |                             | NAPA NON-DETER 30 QT | 2.00     |
|  | <b>Parts Charge:</b> 1,453.85 | <b>Labor Charge:</b> 360.00 |                      |          |

**Workorder:** 1307681

**Problem:** mount spray apparatus

| Meter Reading: 0   |                             | Labor                       | Parts                        |          |
|--|-----------------------------|-----------------------------|------------------------------|----------|
| In Date: 08/01/2013  | Close Date: 09/10/2013      | Hours                       | Description                  | Quantity |
| - Mount And Adjust Customers Spray Rig. Plumb In And Wire In. Replace Ball Valve |                             | 11.00                       | SHOP SUPPLIES                | 1.00     |
|  |                             |                             | 3/4 SPRING LOADED BALL VALVE | 1.00     |
| - Shop Supplies  |                             |                             | Freight Charge               | 1.00     |
|  |                             |                             | KAMLOCK POLLY .75            | 1.00     |
|  | <b>Parts Charge:</b> 235.27 | <b>Labor Charge:</b> 660.00 |                              |          |



10/6/2017  
10:22:27AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K10984 2001 SPRAYING DEVICES INC. 30020KE12 Trailer, W/300 Gallon Sprayer

**Workorder:** 1401677

**Problem:** pm/ check beacon and trailer lights

| Meter Reading: 0     |   | Labor |                      | Parts  |          |
|----------------------|---|-------|----------------------|--------|----------|
| In Date: 02/20/2014  | Close Date: 02/26/2014                              | Hours | Description          |        | Quantity |
| -                    | Pm Spraying Rig                                     | 9.50  | 10W30 MOTOR OIL      |        | 2.00     |
| -                    | Service Trailer                                     |       | SPARK PLUG           |        | 1.00     |
| -                    | Both Hub Wheel Bearings Repacked And Repacked       |       | TAPPERED BEARING SET |        | 2.00     |
| -                    | Replace Trailer Plug                                |       | TRAILER CONN PLUG    |        | 1.00     |
| -                    | Check Beacon Light And Trailer Lights Working Order |       | AIR FILTER           |        | 1.00     |
| -                    | Shop Supplies                                       |       | SEAL                 |        | 2.00     |
|                      |   |       | PRE-FILTER           |        | 1.00     |
|                      |   |       | TAPPERED BEARING SET |        | 2.00     |
|                      |   |       | SHOP SUPPLIES        |        | 1.00     |
| <b>Parts Charge:</b> |   | 77.76 | <b>Labor Charge:</b> | 570.00 |          |

**Workorder:** 1404253

**Problem:** beacon/ clamp/ valve

| Meter Reading: 0     |   | Labor |                      | Parts  |          |
|----------------------|---|-------|----------------------|--------|----------|
| In Date: 05/01/2014  | Close Date: 06/26/2014                              | Hours | Description          |        | Quantity |
| -                    | Ck Strobe Repair Questionable Connection            | 4.50  | 1-1/4X3/4 BUSHING    |        | 2.00     |
| -                    | Install Customer Supplied Ratchet Valve. Replumb To |       | 3/4 COUPLING         |        | 3.00     |
|                      | Accept Larger Valve. Fabricate Support Bracket Test |       | 3/4 CLOSE NIPPLE     |        | 2.00     |
| -                    | Shop Supplies                                       |       | SHOP SUPPLIES        |        | 1.00     |
|                      |   |       | 1-1/2X1-1/4 BUSHING  |        | 2.00     |
| <b>Parts Charge:</b> |   | 17.27 | <b>Labor Charge:</b> | 270.00 |          |

**Workorder:** 1411420

**Problem:** water leak/ see notes

| Meter Reading: 0     |   | Labor  |                      | Parts  |          |
|----------------------|---|--------|----------------------|--------|----------|
| In Date: 11/17/2014  | Close Date: 12/09/2014                              | Hours  | Description          |        | Quantity |
| -                    | Diagnose Shaft Leakage                              | 6.00   | Freight Charge       |        | 1.00     |
| -                    | R&R Blower Housing 2(X)                             |        | O-RING               |        | 1.00     |
| -                    | R&R Starter And Flywheel And Cleaning Repair Damage |        | O-RING               |        | 1.00     |
|                      | Wire Harness  |        | GROUP 22NF DELCO     |        | 1.00     |
| -                    | Replace Battery                                     |        | SHOP SUPPLIES        |        | 1.00     |
| -                    | Shop Supplies                                       |        | TEFLON PACKING       |        | 1.00     |
| <b>Parts Charge:</b> |   | 375.26 | <b>Labor Charge:</b> | 360.00 |          |

10/6/2017  
10:22:27AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K10984 2001 SPRAYING DEVICES INC. 30020KE12 Trailer, W/300 Gallon Sprayer

**Workorder:** 1503339                      **Problem:** pm service/ replace tank fluid sight hose/ hard to start some times/ under press dist. valve leaks

| <b>Meter Reading: 0</b>                                 |                               | <b>Labor</b>                |                       | <b>Parts</b>    |      |
|---|-------------------------------|-----------------------------|-----------------------|-----------------|------|
| <b>In Date:</b> 03/31/2015                              | <b>Close Date:</b> 04/15/2015 | <b>Hours</b>                | <b>Description</b>    | <b>Quantity</b> |      |
| - Pm  |                               | <b>9.50</b>                 | SHOP SUPPLIES         |                 | 1.00 |
| - Service Trailer                                       |                               |                             | TRAILER CONN PLUG     |                 | 1.00 |
| - Replace Trailer Plug And Ground                       |                               |                             | PRE-FILTER            |                 | 1.00 |
| - Replace Side Hose Fluid Sight Fabricate Ratchet Valve |                               |                             | SPARK PLUG            |                 | 1.00 |
| Support Bracket   |                               |                             | 10W30 MOTOR OIL       |                 | 2.00 |
| - Ck And Replace Fluid Supply Elbow Connector           |                               |                             | HOSE 3/8 CL BRAIDED W |                 | 1.00 |
| - Shop Supplies   |                               |                             |                       |                 |      |
| <b>Parts Charge:</b> 34.50                              |                               | <b>Labor Charge:</b> 570.00 |                       |                 |      |

**Workorder:** 1507093                      **Problem:** battery issues

| <b>Meter Reading: 0</b>  |                               | <b>Labor</b>                |                     | <b>Parts</b>    |      |
|--|-------------------------------|-----------------------------|---------------------|-----------------|------|
| <b>In Date:</b> 07/16/2015   | <b>Close Date:</b> 08/04/2015 | <b>Hours</b>                | <b>Description</b>  | <b>Quantity</b> |      |
| - Replace Both Battery Cables And Ends                                 |                               | <b>6.00</b>                 | TRAILER JACK        |                 | 1.00 |
| - Disassemble Engine And Remove Fuel Tank To Replace Defective Starter |                               |                             | BULK BATTERY CABLE  |                 | 5.00 |
|  |                               |                             | ELECTRIC STARTER    |                 | 1.00 |
| - Replace Trailer Jack   |                               |                             | SHOP SUPPLIES       |                 | 1.00 |
| - Shop Supplies  |                               |                             | IND JACK            |                 | 1.00 |
|  |                               |                             | JACK ASSY           |                 | 1.00 |
|  |                               |                             | BATT CABLE TERMINAL |                 | 2.00 |
| <b>Parts Charge:</b> 541.19  |                               | <b>Labor Charge:</b> 360.00 |                     |                 |      |

**Workorder:** 1600839                      **Problem:** dead battery

| <b>Meter Reading: 0</b>                          |                               | <b>Labor</b>                |                     | <b>Parts</b>    |      |
|--|-------------------------------|-----------------------------|---------------------|-----------------|------|
| <b>In Date:</b> 01/26/2016                       | <b>Close Date:</b> 01/29/2016 | <b>Hours</b>                | <b>Description</b>  | <b>Quantity</b> |      |
| - Diag No Start Change Oil, Fuel Contaminated    |                               | <b>2.50</b>                 | GROUP 22NF DELCO    |                 | 1.00 |
| - R/R Plugs (Plugs Fouled )                      |                               |                             | BATT CABLE TERMINAL |                 | 2.00 |
| - Test Charging Sys And Battery. Replace Battery |                               |                             | SPARK PLUG          |                 | 2.00 |
| - Shop Supplies                                  |                               |                             | SHOP SUPPLIES       |                 | 1.00 |
|  |                               |                             | NAPA 10W30 QT       |                 | 2.00 |
| <b>Parts Charge:</b> 103.01                      |                               | <b>Labor Charge:</b> 150.00 |                     |                 |      |

10/6/2017  
10:22:27AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K10984 2001 SPRAYING DEVICES INC. 30020KE12 Trailer, W/300 Gallon Sprayer

**Workorder:** 1603221

**Problem:** pm service

| Meter Reading: 0                   | Labor       | Parts                |          |
|------------------------------------|-------------|----------------------|----------|
| In Date: 03/28/2016                | Hours       | Description          | Quantity |
| - Pm                               | <b>8.50</b> | 10W30 MOTOR OIL      | 2.00     |
| - Service Trailer                  |             | GLOS BLK             | 1.00     |
| - R/R 2 Tires                      |             | SPARK PLUG           | 1.00     |
| - R/R Fuel Shut Off Valve          |             | TR416 VALVE STEM     | 2.00     |
| - Fab Battery Tie Down And Install |             | 31x10.5R15           | 2.00     |
| - Shop Supplies                    |             | TIRE DISPOSAL FEE    | 2.00     |
|                                    |             | VALVE COTTER         | 1.00     |
|                                    |             | VALVE COCK           | 1.00     |
|                                    |             | SHOP SUPPLIES        | 1.00     |
|                                    |             | SEAL                 | 2.00     |
|                                    |             | precleaner           | 1.00     |
|                                    |             | air filter           | 1.00     |
| <b>Parts Charge:</b>               | 521.53      | <b>Labor Charge:</b> | 510.00   |

**Workorder:** 1608969

**Problem:** boom/ reel/ belt cover/ see notes

| Meter Reading: 0  | Labor       | Parts                |          |
|---|-------------|----------------------|----------|
| In Date: 08/29/2016   | Hours       | Description          | Quantity |
| - Repair Boom, Adjust Belt Cover Resecured Forward Hose<br>Reg. Fab Sleeve For Reel | <b>2.50</b> | SHOP SUPPLIES        | 1.00     |
| - Shop Supplies   |             |                      |          |
| <b>Parts Charge:</b>  | 2.00        | <b>Labor Charge:</b> | 150.00   |

**Workorder:** 1610057

**Problem:** extend trailer plug 12 inches, motor is smoking-possible wrong fuel, sprayer bowl has a crack

| Meter Reading: 0                                   | Labor       | Parts                  |          |
|--|-------------|------------------------|----------|
| In Date: 09/26/2016                                | Hours       | Description            | Quantity |
| - Extend Wire Harness And Install New Trailer Plug | <b>4.00</b> | SHOP SUPPLIES          | 1.00     |
| - R/R Fouling Spark Plug And Rear Compression Test |             | MALE TRAILER CONNECTOR | 1.00     |
| - Drain And Flush Contaminated Oil In Motor (Fuel) |             | 10W30 MOTOR OIL        | 2.00     |
| - Assemble And Install New Strainer                |             | STRAINER FOR SPRAYER   | 1.00     |
| - Shop Supplies                                    |             | BULK TRAILER WIRE      | 9.00     |
|  |             | SPARK PLUG             | 1.00     |
| <b>Parts Charge:</b>                               | 83.62       | <b>Labor Charge:</b>   | 240.00   |

10/6/2017  
10:22:27AM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: K10984 2001 SPRAYING DEVICES INC. 30020KE12 Trailer, W/300 Gallon Sprayer

**Workorder:** 1612631

**Problem:** no pressure/ gauges/ check nozzles/ see notes

| Meter Reading: 0  | Labor | Parts   |
|---|-------|---|
| In Date: 12/09/2016   | Hours | Description   |
| Close Date: 12/20/2016  |       | Quantity  |
| - Replace Pcv Fittings And Couplers, Reseal And Adjust Nozzles. (Control Valves Leaking)                  | 4.50  | 1 1/2 ADAPTER<br>PVC CLEANER                                    |
| - Engine Was Hydrlocked Due To Gas In Crankcase-Drain And Add New Oil Clean Spark Plug And Charge Battery |       | 3/4 PVC CPLG<br>SHOP SUPPLIES                                   |
| - Shop Supplies   |       | PVC CEMENT<br>HOSE COUPLER<br>PVC BUSHING<br>PVC FEMALE ADAPTER |
| <b>Parts Charge:</b>  | 46.76 | <b>Labor Charge:</b> 270.00                                     |

**Workorder:** 1704240

**Problem:** pm service/ engine smoke

| Meter Reading: 0       | Labor | Parts                       |
|------------------------|-------|-----------------------------|
| In Date: 04/27/2017    | Hours | Description                 |
| Close Date: 05/03/2017 |       | Quantity                    |
| - Pm                   | 5.00  | SPARK PLUG                  |
| - Trailer Service      |       | NAPA 10W30 QT               |
| - Shop Supplies        |       | SHOP SUPPLIES               |
| <b>Parts Charge:</b>   | 11.93 | <b>Labor Charge:</b> 300.00 |

|                      |                 |                      |                  |                      |               |
|----------------------|-----------------|----------------------|------------------|----------------------|---------------|
| Total Parts Charges: | <b>8,103.01</b> | Total Labor Charges: | <b>12,439.50</b> | Total Comm. Charges: | <b>150.00</b> |
|----------------------|-----------------|----------------------|------------------|----------------------|---------------|