

10/17/2017
12:21:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175059 2009 JOHN DEERE 673 Roto-Tiller, 74" Width

Workorder: 846652 **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts
In Date: 11/03/2008	Hours	Description
Close Date: 11/03/2008		Quantity
- Pre-Delivery Inspection	2.00	
Parts Charge: 0.00	Labor Charge: 120.00	

Workorder: 846925 **Problem:** WELD ASSET NUMBERS ON EQUIPMENT

Meter Reading: 0	Labor	Parts
In Date: 11/10/2008	Hours	Description
Close Date: 11/14/2008		Quantity
- Prep And Weld Asset#S	1.50	1355 NEW CAT YELLOW PLASTI-KOTE 1.00
- Paint Welded Area		SHOP SUPPLIES 1.00
- Shop Supplies		
Parts Charge: 6.48	Labor Charge: 30.00	

Workorder: 932722 **Problem:** SHORTEN PTO SHAFT

Meter Reading: 0	Labor	Parts
In Date: 01/13/2009	Hours	Description
Close Date: 01/13/2009		Quantity
- Shorten Pto Shaft To Proper	1.50	SHOP SUPPLIES 1.00
- Test Run		
- Shop Supplies		
Parts Charge: 2.00	Labor Charge: 90.00	

Workorder: 937227 **Problem:** DRIVESHAFT COUPLER WILL NOT GO ON TRACTOR 10151794

Meter Reading: 0	Labor	Parts
In Date: 04/30/2009	Hours	Description
Close Date: 05/05/2009		Quantity
- Debris And Clean Spines On Quick Coupler Lubricate And Test	2.00	SHOP SUPPLIES 1.00
- Shop Supplies		
Parts Charge: 2.00	Labor Charge: 120.00	

10/17/2017
12:21:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175059 2009 JOHN DEERE 673 Roto-Tiller, 74" Width

Workorder: 937803

Problem: SHAFT BROKEN,BOLTS BROKEN OFF

Meter Reading: 0	Labor	Parts	
In Date: 05/14/2009	Hours	Description	
Close Date: 05/26/2009		Quantity	
- R&R Tiller Shaft, Drill & Tap Breaker Botls Out & Replace W/New Bolts	1.50	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	90.00

Workorder: 940765

Problem: PTO SHAFT

Meter Reading: 0	Labor	Parts	
In Date: 07/15/2009	Hours	Description	
Close Date: 09/16/2009		Quantity	
- R&R Pto Shaft / Cut Old One Off	3.80	PTO SHAFT	1.00
- Travel To Jpp		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	475.10	Labor Charge:	228.00

Workorder: 943608

Problem: cut pto shaft to size

Meter Reading: 0	Labor	Parts	
In Date: 09/23/2009	Hours	Description	
Close Date: 09/25/2009		Quantity	
- Shorten Pto Shaft And Install On Tractor To Tiller	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 1211924

Problem: 9950

Meter Reading: 0	Labor	Parts	
In Date: 12/10/2012	Hours	Description	
Close Date: 12/11/2012		Quantity	
- On Site Lube	1.00	12345841 GEAR OIL SYN	2.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	46.70	Labor Charge:	60.00

10/17/2017
12:21:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10175059 2009 JOHN DEERE 673 Roto-Tiller, 74" Width

Workorder: 1308355

Problem: 9950

Meter Reading: 0	Labor	Parts	
In Date: 08/19/2013	Hours	Description	Quantity
- Onsite Lube	2.00	SHOP SUPPLIES	1.00
- To Jp Park			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	120.00

Workorder: 1709765

Problem: Transition Prep Charge

Meter Reading: 0	Labor	Parts	
In Date: 10/05/2017	Hours	Description	Quantity
- Transition Prep Charge	2.00		
Parts Charge:	0.00	Labor Charge:	0.00

Total Parts Charges: **538.28** Total Labor Charges: **918.00** Total Comm. Charges: **0.00**