

10/6/2017
10:17:07AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11606 2005 TORO 3300D Utility Cart, Heavy Duty

Workorder: 533353 **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts
In Date: 01/13/2005	Hours	Description
Close Date: 01/13/2005	Quantity	
- Pre-Delivery Inspection	2.00	
Parts Charge: 0.00	Labor Charge: 100.00	

Workorder: 541796 **Problem:** INSTALL MIRROR/PARTS ON FLOOR OF SPRAYER

Meter Reading: 94	Labor	Parts
In Date: 04/13/2005	Hours	Description
Close Date: 04/19/2005	Quantity	
- Install Right Mirror. Install Scow Vehicle Triangle	1.00	SHOP SUPPLIES
- Shop Supplies		1.00
Parts Charge: 2.00	Labor Charge: 50.00	

Workorder: 543423 **Problem:** P.M.

Meter Reading: 143	Labor	Parts
In Date: 04/29/2005	Hours	Description
Close Date: 05/24/2005	Quantity	
- Pm Service	9.00	PH4967 OIL FILTER LBF PH2840 WIX 51394
- Service Trans. Axle		1259 HYDR FILTER LBF FRM P1653A WIX 51259
- Repack Frt Brgs		ATFD TRANS FLUID MERCON V
- Rf Tire Rotate Side To Side Reverse Tires On Wheels		SHOP SUPPLIES
- Frt End Out Of Alignment Reset Toe-In		33392 FUEL FILTER FRM NONE
- Shop Supplies		FRT/SEAL 87-3590
		05046 BATTERY PROTECTOR (CRC)
		15/40 OIL
		6449 AIR FILTERFRM CA9248 WIX 46449
Parts Charge: 61.25	Labor Charge: 450.00	

Workorder: 548384 **Problem:** REPLACE FRONT LEFT TIRE

Meter Reading: 176	Labor	Parts
In Date: 06/22/2005	Hours	Description
Close Date: 06/29/2005	Quantity	
- Repalce L/F Tire	1.00	SHOP SUPPLIES
- Shop Supplies		209467146 20-1000-10 POWER RIB 4PLY
Parts Charge: 64.94	Labor Charge: 50.00	

10/6/2017
10:17:07AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11606 2005 TORO 3300D Utility Cart, Heavy Duty

Workorder: 555293

Problem: REPLACE FRONT TIRES

Meter Reading: 0	Close Date: 09/22/2005	Labor Hours	Description	Parts	Quantity
In Date: 09/19/2005					
- Replace 2 Frt Tires		1.00	SHOP SUPPLIES		1.00
- Shop Supplies			209467146 20-1000-10 POWER RIB 4PLY		2.00
Parts Charge: 127.88		Labor Charge: 50.00			

Workorder: 559834

Problem: WON'T TURN? & DUMP BED NOT WORKING

Meter Reading: 287	Close Date: 01/06/2006	Labor Hours	Description	Parts	Quantity
In Date: 12/19/2005					
- P/S Pump Belt Off, Replaced		1.50	SHOP SUPPLIES		1.00
- Test Run			P/S BELT 1350		1.00
- Shop Supplies					
Parts Charge: 8.17		Labor Charge: 75.00			

Workorder: 733213

Problem: PM SERVICE

Meter Reading: 571	Close Date: 01/26/2007	Labor Hours	Description	Parts	Quantity
In Date: 01/24/2007					
- Pm Service		7.50	6449 AIR FILTERFRM CA9248 WIX 46449		1.00
- Battery R/R			PH4967 OIL FILTER LBF PH2840 WIX 51394		1.00
- Lights Inop-Repair Wiring, Replace Fuse			33392 FUEL FILTER FRM NONE		1.00
- Horn Inop Repair Wiring			GROUP 24 BATTERY (ACD 24PS)		1.00
- Test Run			15/40 OIL		4.00
- Shop Supplies			SHOP SUPPLIES		1.00
Parts Charge: 129.63		Labor Charge: 27.50			

Workorder: 733373

Problem: ORDER CLUTCH CABLE

Meter Reading: 574	Close Date: 02/26/2007	Labor Hours	Description	Parts	Quantity
In Date: 01/26/2007					
- Parts-Dwyer			CLUTCH/CBLE 106-2450 OR 112-3181		1.00
Parts Charge: 70.02		Labor Charge: 0.00			

10/6/2017
10:17:07AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11606 2005 TORO 3300D Utility Cart, Heavy Duty

Workorder: 740126

Problem: CLUTCH CABLE

Meter Reading: 670	Labor	Parts	
In Date: 06/15/2007	Hours	Description	Quantity
- Replaced Clutch Cable And Throttle Cable And Adjust/Parts Supplied By Manufacturer	4.50	209467146 20-1000-10 POWER RIB 4PLY SHOP SUPPLIES	1.00 1.00
- Replaced 2 Frt Tires			
- Road Test			
- Shop Supplies			
Parts Charge:	101.41	Labor Charge:	27.50

Workorder: 833067

Problem: P.M.

Meter Reading: 869	Labor	Parts	
In Date: 01/22/2008	Hours	Description	Quantity
- Pm Service	8.50	33392 FUEL FILTER FRM NONE	1.00
- Service Transaxle		SYN/ATF TRANS FLUID SYNTHETIC	1.00
- R/R R/F Tire		63-8140 IDLER PULLEY TORO	-1.00
- R/R Cooling Fan Belt Tensioner		SHOP SUPPLIES	1.00
- Test Run		IDLER PULLEY	1.00
- Shop Supplies		SYN/ATF TRANS FLUID SYNTHETIC	7.00
		V-BELT	1.00
		15/40 OIL	4.00
		1259 HYDR FILTER LBF FRM P1653A WIX 51259	1.00
		PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
		63-8140 IDLER PULLEY TORO	1.00
		6449 AIR FILTERFRM CA9248 WIX 46449	1.00
		209467146 20-1000-10 POWER RIB 4PLY	1.00
Parts Charge:	203.93	Labor Charge:	30.00

Workorder: 840691

Problem: LEFT FRONT TIRE WORN/ FRONT END ALIGNMENT

Meter Reading: 941	Labor	Parts	
In Date: 06/30/2008	Hours	Description	Quantity
- R/R L/F Tire	2.00	SHOP SUPPLIES	1.00
- Alignment		TIRE DISPOSAL FEE	1.00
- Test Run		209467146 20-1000-10 POWER RIB 4PLY	1.00
- Shop Supplies			
Parts Charge:	97.78	Labor Charge:	30.00

10/6/2017
10:17:07AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11606 2005 TORO 3300D Utility Cart, Heavy Duty

Workorder: 844695

Problem: QUIT RUNNING AFTER FUELING

Meter Reading: 1007	Labor	Parts	
In Date: 09/24/2008	Hours	Description	Quantity
- Ck For No Start-No Fuel To Injectors Due To No Power At Fuel Shut Off Solenoid Repaired Wire Terminal At Connector For Solenoid	2.00	SHOP SUPPLIES	1.00
- Road Test			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	30.00

Workorder: 848329

Problem: REPLACE FRT TIRES, SUPPLY SPARE TIRE AND WHEEL

Meter Reading: 1062	Labor	Parts	
In Date: 12/17/2008	Hours	Description	Quantity
- Replace 2 Frt Tires	3.00	FRONT RIM	1.00
- Build-Up Tire & Wheel For Spare		TIRE DISPOSAL FEE	3.00
- Adjust Frt Toe In & Ck For Worn Or Loose Parts		209467146 20-1000-10 POWER RIB 4PLY	3.00
- Test Run		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	502.75	Labor Charge:	30.00

10/6/2017
10:17:07AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11606 2005 TORO 3300D Utility Cart, Heavy Duty

Workorder: 934062

Problem: PM SERVICE

Meter Reading: 0		Labor	Parts	
In Date: 02/17/2009	Close Date: 03/03/2009	Hours	Description	Quantity
- Pm Cart		12.50	ALTERNATOR BELT	1.00
- Clean Cart			SHOP SUPPLIES	1.00
- Radiator Replace Bad Frame And Core			6449 AIR FILTERFRM CA9248 WIX 46449	1.00
- Hydraulic Sys Service			33392 FUEL FILTER FRM NONE	1.00
- Replace Frt Wheel Cyl			RADIATOR ASSY	1.00
- Replace Frt Seals And Repack Wheel Bearings			12345841 GEAR OIL SYNTHETIC 75W-90	1.00
- Replace Alt Belt			1259 HYDR FILTER LBF FRM P1653A WIX 51259	1.00
- Shop Supplies			LH WHEEL CYLINDER	1.00
			15/40 OIL	4.00
			PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
			RH WHEEL CYLINDER	1.00
			SEAL	2.00
			THERMOSTAT	1.00
Parts Charge: 1,039.52		Labor Charge: 750.00		

Workorder: 942087

Problem: need tire

Meter Reading: 1222		Labor	Parts	
In Date: 08/13/2009	Close Date: 08/17/2009	Hours	Description	Quantity
- Replace One Tire		0.50	TIRE DISPOSAL FEE	1.00
- Shop Supplies			209467146 20-1000-10 POWER RIB 4PLY	1.00
			SHOP SUPPLIES	1.00
Parts Charge: 115.40		Labor Charge: 30.00		

Workorder: 942987

Problem: Clutch Problem

Meter Reading: 1246		Labor	Parts	
In Date: 09/08/2009	Close Date: 09/14/2009	Hours	Description	Quantity
- Won'T Crank-Traced To Clutch Safety Switch Out Of Adjustment. Adjust Switch & Road Test.		1.00	SHOP SUPPLIES	1.00
- Shop Supplies				
Parts Charge: 2.00		Labor Charge: 60.00		

10/6/2017
10:17:07AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11606 2005 TORO 3300D Utility Cart, Heavy Duty

Workorder: 1001672

Problem: PM / WON'T START

Meter Reading: 1345	Labor	Parts	
In Date: 02/17/2010	Hours	Description	Quantity
- Pm Service	12.50	GROUP 24 BATTERY (ACD 24PS)	1.00
- Hyd Sys Service		1259 HYDR FILTER LBF FRM P1653A WIX 51259	1.00
- Wash		15/40 OIL	4.00
- Readjust Clutch Cable-Diagnose No Start-Readjust Clutch Switch		209467146 20-1000-10 POWER RIB 4PLY	1.00
- Replace Front Tire		TIRE DISPOSAL FEE	1.00
- Replace Air Sys		09997 BRAKE CLEAN	1.00
- Replace Battery		PH4967 OIL FILTER LBF PH2840 WIX 51394	1.00
- Tire Repair Left Rear Tire Repaired		AW68 HYDRO FLUID HYDRAULIC OIL 68	1.00
- Shop Supplies		AIR CLEANER ASSY	1.00
		33392 FUEL FILTER FRM NONE	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	349.03	Labor Charge:	750.00

Workorder: 1004619

Problem: clutch

Meter Reading: 1393	Labor	Parts	
In Date: 05/04/2010	Hours	Description	Quantity
- Readjust All Cables Ck Clutch Pedal Play	2.00	CLUTCH CABLE	1.00
- New Clutch Cable Test Run		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	102.29	Labor Charge:	120.00

Workorder: 1013698

Problem: repair seats / check power source (for flashing lights)

Meter Reading: 1511	Labor	Parts	
In Date: 12/14/2010	Hours	Description	Quantity
- Replace Two Sents Order Remove Safety Shields And Sent Rails Reuse Clean Sent Rails Two.	4.50	209467146 20-1000-10 POWER RIB 4PLY	1.00
- New Front Left Tire Mount A& Nitro Fill All 4 Tires		SHOP SUPPLIES	1.00
- Check All Fuses Checked Lighter Outlet		TIRE DISPOSAL FEE	1.00
- Tire Repair-Repair Left Rear Tire Nitro		SEATS LH AND RH	2.00
- Shop Supplies			
Parts Charge:	611.38	Labor Charge:	270.00

10/6/2017
10:17:07AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11606 2005 TORO 3300D Utility Cart, Heavy Duty

Workorder: 1102440

Problem: pm service

Meter Reading: 1592	Close Date: 03/14/2011	Labor Hours	Description	Parts	Quantity
- Pm Cart		8.50	PH4967 OIL FILTER LBF PH2840 WIX 51394		1.00
- Cooling Sys Service			15/40 OIL		4.00
- Hydraulic Sys Service			THERMOSTAT ASSY		1.00
- Replace Rear Tires			33392 FUEL FILTER FRM NONE		1.00
- Shop Supplies			SEALS		2.00
			6449 AIR FILTERFRM CA9248 WIX 46449		1.00
			1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
			TIRE DISPOSAL FEE		2.00
			GREEN ANTIFREEZE STOCK #060030002		1.00
			511409 24-1200-12 TURFMASTER 4PLY		2.00
			SHOP SUPPLIES		1.00
	Parts Charge: 423.46	Labor Charge: 510.00			

Workorder: 1202578

Problem: pm service

Meter Reading: 1849	Close Date: 03/23/2012	Labor Hours	Description	Parts	Quantity
- Pm		6.50	209467146 20-1000-10 POWER RIB 4PLY		2.00
- Mount Two New Front Tires Nitro Fill All Four Tires			AW68 HYDRO FLUID HYDRAULIC OIL 68		4.00
- Hydro Service			SHOP SUPPLIES		1.00
- Shop Supplies			6449 AIR FILTERFRM CA9248 WIX 46449		1.00
			15/40 OIL		4.00
			33392 FUEL FILTER FRM NONE		1.00
			TIRE DISPOSAL FEE		2.00
			09997 BRAKE CLEAN		1.00
			PH4967 OIL FILTER LBF PH2840 WIX 51394		1.00
			1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
	Parts Charge: 308.84	Labor Charge: 390.00			

10/6/2017
10:17:07AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11606 2005 TORO 3300D Utility Cart, Heavy Duty

Workorder: 1209170

Problem: fan belt/ bed does not go up

Meter Reading: 1986	Labor	Parts	Quantity
In Date: 09/25/2012	Hours	Description	Quantity
- Reinstall Fan Belt On Hyd Pump And Ck Power Bed Operation -Ok	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 1304403

Problem: PM / Broken tail light lens

Meter Reading: 2114	Labor	Parts	Quantity
In Date: 05/03/2013	Hours	Description	Quantity
- Pm Service	7.00	TIRE DISPOSAL FEE	2.00
- R/R 4 Tires		fuel filter	1.00
- R/R Tail Lamp And Bracket		SHOP SUPPLIES	1.00
- Shop Supplies		NAPAGOLD AIR FILTER	1.00
		20X10.00-10 RIBBED TIRE	2.00
		Freight Charge	1.00
		Freight Charge	1.00
		NAPAGOLD OIL FILTER	1.00
		15-40 OIL	4.00
		LH TAIL LIGHT BRACKET ASSY	1.00
		24-1200-12B TURF M CARL	2.00
		TAIL LIGHT	1.00
		Freight Charge	1.00
Parts Charge:	849.14	Labor Charge:	420.00

Workorder: 1305150

Problem: overheating

Meter Reading: 2114	Labor	Parts	Quantity
In Date: 05/24/2013	Hours	Description	Quantity
- R/R Therm. As Per Customer	1.00	SHOP SUPPLIES	1.00
- Shop Supplies		THERMOSTAT ASSY	1.00
		Freight Charge	1.00
Parts Charge:	82.74	Labor Charge:	60.00

10/6/2017
10:17:07AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11606 2005 TORO 3300D Utility Cart, Heavy Duty

Workorder: 1311591

Problem: battery issues

Meter Reading: 2214		Labor		Parts	
In Date: 11/18/2013	Close Date: 11/25/2013	Hours	Description	Quantity	
-	Check Battery Condition (Load Test) Failed, Replaced Battery	1.00	SHOP SUPPLIES GROUP 24 DELCO	1.00	
-	Shop Supplies			1.00	
Parts Charge:		80.30	Labor Charge:		60.00

Workorder: 1401333

Problem: starting/ seat/ shifter boot/ see notes

Meter Reading: 2221		Labor		Parts	
In Date: 02/10/2014	Close Date: 02/24/2014	Hours	Description	Quantity	
-	R/R Clutch Pedal Switch And Acuvator	3.50	SHOP SUPPLIES	1.00	
-	R/R Shfter Boot		BLASTER PENETRANT	1.00	
-	Free Up Seat Sliders And Remvoe Stripped Bolt And Resecure Seat		SHIFT BOOT	1.00	
-	Shop Supplies		CLUTCH SWITCH PADDLE	1.00	
			Freight Charge	1.00	
			CLUTCH SWITCH	1.00	
Parts Charge:		278.26	Labor Charge:		210.00

Workorder: 1401915

Problem: replace tire (tire only)

Meter Reading: 2221		Labor		Parts	
In Date: 02/27/2014	Close Date: 03/06/2014	Hours	Description	Quantity	
-	Replace Tire	1.00	SHOP SUPPLIES	1.00	
-	Shop Supplies		20X10X10 TURF GLIDE TIRE	1.00	
			TIRE DISPOSAL FEE	1.00	
Parts Charge:		124.80	Labor Charge:		60.00

10/6/2017
10:17:07AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11606 2005 TORO 3300D Utility Cart, Heavy Duty

Workorder: 1405794

Problem: pm service

Meter Reading: 2292		Labor	Parts	
In Date: 06/12/2014	Close Date: 06/19/2014	Hours	Description	Quantity
- Pm		5.00	NAPAGOLD OIL FILTER	1.00
- Hyd Service			NAPAGOLD AIR FILTER	1.00
- Shop Supplies			15-40 OIL	4.00
			NAPA HYDRAULIC FILTR	1.00
			SHOP SUPPLIES	1.00
			NAPAGOLD FUEL FILTER	1.00
	Parts Charge: 46.77	Labor Charge: 300.00		

Workorder: 1505880

Problem: pm service

Meter Reading: 2436		Labor	Parts	
In Date: 06/12/2015	Close Date: 06/19/2015	Hours	Description	Quantity
- Pm		8.00	NAPAGOLD OIL FILTER	1.00
- Replace Rear 1 Tires			24-1200-12B TURF M CARL	1.00
- Hydraulic Service			NAPAGOLD FUEL FILTER	1.00
- Adjust And Clean All Brakes. Adj Parking Brake			NAPAGOLD AIR FILTER	1.00
- Engine Noise. Replace Idler Pulley			TIRE DISPOSAL FEE	1.00
- Shop Supplies			IDLER PULLEY	1.00
			NAPA HYDRAULIC FILTR	1.00
			15-40 OIL	4.00
			1CART PALLADIUM 2 GRS	2.00
			SHOP SUPPLIES	1.00
	Parts Charge: 260.61	Labor Charge: 480.00		

Workorder: 1508408

Problem: replace tire (tire only)

Meter Reading: 2454		Labor	Parts	
In Date: 08/21/2015	Close Date: 08/28/2015	Hours	Description	Quantity
- Replace Tire		1.00	20X10X10 TURF GLIDE TIRE	1.00
- Shop Supplies			TIRE DISPOSAL FEE	1.00
			SHOP SUPPLIES	1.00
	Parts Charge: 128.10	Labor Charge: 60.00		

10/6/2017
10:17:07AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11606 2005 TORO 3300D Utility Cart, Heavy Duty

Workorder: 1511450

Problem: replace tire / match tire (tire only)

Meter Reading: 2498		Labor		Parts	
In Date: 11/06/2015	Close Date: 11/18/2015	Hours	Description		Quantity
-	Replace Tire	1.00	TIRE DISPOSAL FEE		1.00
-	Shop Supplies		24-1200-12B TURF M CARL		1.00
			SHOP SUPPLIES		1.00
Parts Charge: 129.21		Labor Charge: 60.00			

Workorder: 1603736

Problem: replace tire, tire only

Meter Reading: 2552		Labor		Parts	
In Date: 04/08/2016	Close Date: 04/20/2016	Hours	Description		Quantity
-	Replace Tire	1.00	20X10X10 TURF GLIDE TIRE		1.00
-	Shop Supplies		TIRE DISPOSAL FEE		1.00
			SHOP SUPPLIES		1.00
Parts Charge: 133.05		Labor Charge: 60.00			

Workorder: 1606269

Problem: pm service

Meter Reading: 2595		Labor		Parts	
In Date: 06/20/2016	Close Date: 06/24/2016	Hours	Description		Quantity
-	Pm	9.00	15-40 OIL		4.00
-	Hyd Service Transaxle		GROUP 24 DELCO		1.00
-	Replace One Tire		TIRE DISPOSAL FEE		1.00
-	Service Brakes Adj Pk Brk		SHOP SUPPLIES		1.00
-	Front Alignment		NAPA HYDRAULIC FILTR		1.00
-	Check Charging Sys. Battery Fail Load Test. Replace Battery		SYN-ATF TRANS FLUID S		7.00
			NAPAGOLD FUEL FILTER		1.00
			NAPAGOLD AIR FILTER		1.00
-	Shop Supplies		NAPAGOLD OIL FILTER		1.00
			AW68 HYDRO FLUID HYDR		4.00
			24-1200-12B TURF M CARL		1.00
Parts Charge: 340.53		Labor Charge: 540.00			

10/6/2017
10:17:07AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11606 2005 TORO 3300D Utility Cart, Heavy Duty

Workorder: 1607316

Problem: oil drain plug leaking

Meter Reading: 2597		Labor		Parts	
In Date: 07/18/2016	Close Date: 07/27/2016	Hours	Description	Quantity	
-	Replace Drain Plug And Leak Check	1.00	OIL DRAIN PLUG		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
Parts Charge:		19.72	Labor Charge:	60.00	

Workorder: 1610924

Problem: check front end for tire wear/ replace front tire/ right rear/ see notes

Meter Reading: 2625		Labor		Parts	
In Date: 10/24/2016	Close Date: 11/29/2016	Hours	Description	Quantity	
-	Rebuild Front Steering, Suspension And Align	11.50	FLANGE BUSHING		8.00
-	R/R 3 Tires		BALL JOINT		4.00
-	Shop Supplies		SNAP RING		4.00
			RH BALL JOINT		2.00
			CAPSCREW		8.00
			24-1200-12B TURF M CARL		1.00
			JAM NUT		1.00
			20X10.00X10 MULTI-TRAC		2.00
			NUT		1.00
			BALL JOINT		4.00
			TIRE DISPOSAL FEE		3.00
			BUSHING		8.00
			SHOCK ADSORBER		2.00
			SHOP SUPPLIES		1.00
			PIVOT SHAFT		1.00
			BUSHING		2.00
			TIE ROD		1.00
			LH BALL JOINT		2.00
Parts Charge:		1,908.70	Labor Charge:	690.00	

10/6/2017
10:17:07AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: K11606 2005 TORO 3300D Utility Cart, Heavy Duty

Workorder: 1705771

Problem: pm service

Meter Reading: 2678

In Date: 06/09/2017

Close Date: 06/21/2017

Labor

Hours

Description

Parts

Quantity

	Labor Hours	Description	Parts	Quantity
- Pm	9.50	NAPA HYDRAULIC FILTR		1.00
- Hyd Service		AW68 HYDRO FLUID HYDR		2.00
- R/R Hyd Belt		20X10.00X10 MULTI-TRAC		2.00
- R/R Frt Tires		NON-CHLOR BRAKE CLNR		1.00
- Cooling Sys Service		NAPAGOLD FUEL FILTER		1.00
- Shop Supplies		NAPAGOLD OIL FILTER		1.00
		SHOP SUPPLIES		1.00
		TIRE DISPOSAL FEE		2.00
		THERMOSTAT ASSY		1.00
		NAPAGOLD AIR FILTER		1.00
		15-40 OIL		4.00
		PUMP BELT		1.00

Parts Charge: 416.74

Labor Charge: 570.00

Total Parts Charges: **9,124.35**

Total Labor Charges: **7,520.00**

Total Comm. Charges: **0.00**