

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 557565

Problem: CHECK IN

Meter Reading: 63 In Date: 11/02/2005	Close Date: 11/23/2005	Labor Hours	Description	Parts	Quantity
- Adjusted Oil Level		0.50	ATFD TRANS FLUID MERCON V		3.00
	Parts Charge: 4.84		Labor Charge: 25.00		

Workorder: 559116

Problem: RECHECK

Meter Reading: 63 In Date: 12/06/2005	Close Date: 12/09/2005	Labor Hours	Description	Parts	Quantity
- Verify Check-In Problems Have Been Corrected		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
	Parts Charge: 2.00		Labor Charge: 50.00		

Workorder: 559223

Problem: MAKE & APPLY DECALS. CHECK FLUIDS, BELTS, AND OPER

Meter Reading: 0 In Date: 12/07/2005	Close Date: 12/07/2005	Labor Hours	Description	Parts	Quantity
- Make & Apply Decals. Check Fluids, Belts, And Operation As Applicable.		1.00			
	Parts Charge: 0.00		Labor Charge: 50.00		

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 559367

Problem: AUX. LITES/FENDERS/BUG SCREEN

Meter Reading: 248 In Date: 12/09/2005	Close Date: 01/18/2006	Labor Hours	Description	Parts	Quantity
- Install Reflector Kit & Fire Extinguisher		24.80	798 FLARE KITS TRIANGLE REFLECTOR KITS		1.00
- P/U Parts In Wp Shop			HINGES BB1199		2.00
- Install Aux Battery Cable For Aux Engine On Tractor			ROCKER SWITCH RS2002		1.00
M1283			CONNECTOR 9185		1.00
- Order Fenders & Hardware			FENDER FLE03401494		1.00
- Mount Work Lights, Fab Brackets, Add Decking, Weld			RELAY 192D		1.00
Goose Neck Support, Relocate Glad Hand Holder			5LB FIREX ABC STOCK# 340280001		1.00
- Shop Supplies			6-1643 FUSEHOLDER 20 AMP ATO		1.00
			71/2" MIRROR 97815		2.00
			CLEAR HALOGAN LITES 80493		2.00
			SHOP SUPPLIES		1.00
			KIT FLE03100063		1.00
			KIT FLE03100786		2.00
Parts Charge:		1,514.42	Labor Charge:		1,240.00

Workorder: 560055

Problem: CUT MATERIAL

Meter Reading: 63 In Date: 12/28/2005	Close Date: 12/29/2005	Labor Hours	Description	Parts	Quantity
- Cut Material		0.50	1/2X5X20 STEEL FLAT BAR		3.00
Parts Charge:		17.18	Labor Charge:		25.00

Workorder: 632406

Problem: INSTALL FENDERS

Meter Reading: 1165 In Date: 01/06/2006	Close Date: 02/13/2006	Labor Hours	Description	Parts	Quantity
- Installed Fenders		4.00	SHOP SUPPLIES		1.00
- Set Up Repairs For Body Shop					
- Transport To Body Shop For Repairs					
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:		50.00
			Commercial Charge:		624.00

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 639809 **Problem:** AIR PRESSURE LITE COMES ON(R/R) CHECK VALVE

Meter Reading: 3510	Labor	Parts
In Date: 05/24/2006	Hours	Description
Close Date: 06/08/2006	Quantity	
- Diagnostic/Replace Chk Vlve On Parking Air Tank	1.50	SHOP SUPPLIES
- Shop Supplies		800376 CHECK VALVE
Parts Charge: 34.18	Labor Charge: 75.00	

Workorder: 640485 **Problem:** CHECK ENGINE LITE ON

Meter Reading: 3675	Labor	Parts
In Date: 06/07/2006	Hours	Description
Close Date: 06/08/2006	Quantity	
- Check Intermittent Check Engine Light	0.50	
Parts Charge: 0.00	Labor Charge: 25.00	

Workorder: 641076 **Problem:** P.M. SERVICE

Meter Reading: 3754	Labor	Parts
In Date: 06/19/2006	Hours	Description
Close Date: 06/27/2006	Quantity	
- P M Service	9.20	12105 AIR TANK DRAINS
- Install Pull Valve Air Drain		12345841 GEAR OIL SYNTHETIC 75W-90
- Pick Up Parts In Wpb		5410900151 FUEL FILTER WIX 33628 FRAM C9559
- Performance Test		S3226FL02 FUEL FILTER USE FRAM PS9794
- Shop Supplies		10003 INJECTOR CLEANER DON'T REORDER
		SHOP SUPPLIES
		15/40 OIL
		P527682 AIR FILTER USE FRAM CA7140
		0001802109 OIL FILTER WIX 57213 FRAM CH9558
Parts Charge: 261.07	Labor Charge: 25.00	

Workorder: 642158 **Problem:** ADD OIL

Meter Reading: 3805	Labor	Parts
In Date: 07/11/2006	Hours	Description
Close Date: 07/11/2006	Quantity	
- Add Oil	0.30	15/40 OIL
Parts Charge: 19.15	Labor Charge: 15.00	

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 643055 **Problem:** WILL NOT HOLD AIR PRESSURE

Meter Reading: 3949		Labor		Parts	
In Date: 07/27/2006	Close Date: 08/04/2006	Hours	Description		Quantity
- Locate Source Of Air Leak, Reseal Purge Valve		1.50	SHOP SUPPLIES		1.00
- Shop Supplies					
	Parts Charge: 2.00	Labor Charge:	75.00		

Workorder: 648182 **Problem:** GOOSE NECK STOP

Meter Reading: 5518		Labor		Parts	
In Date: 11/03/2006	Close Date: 11/27/2006	Hours	Description		Quantity
- Attach Plate To Frame For Gooseneck Stop		1.50	SHOP SUPPLIES		1.00
- Shop Supplies					
	Parts Charge: 2.00	Labor Charge:	82.50		

Workorder: 648190 **Problem:** CUT MATERIAL

Meter Reading: 5518		Labor		Parts	
In Date: 11/03/2006	Close Date: 12/13/2006	Hours	Description		Quantity
- Cut Material		0.50	1/2X5X20 STEEL FLAT BAR		3.00
	Parts Charge: 17.18	Labor Charge:	27.50		

Workorder: 648261 **Problem:** CHECK ENGINE LITE ON

Meter Reading: 5785		Labor		Parts	
In Date: 11/06/2006	Close Date: 11/29/2006	Hours	Description		Quantity
-					
	Parts Charge: 0.00	Labor Charge:	0.00		

Workorder: 649813 **Problem:** MOVE STEP

Meter Reading: 6120		Labor		Parts	
In Date: 12/12/2006	Close Date: 12/27/2006	Hours	Description		Quantity
- Move Access Step From L/S To R/S		3.50	SHOP SUPPLIES		1.00
- Shop Supplies					
	Parts Charge: 2.00	Labor Charge:	192.50		

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 733406

Problem: P.M. SERVICE

Meter Reading: 7203		Labor		Parts	
In Date: 01/29/2007	Close Date: 02/12/2007	Hours	Description	Quantity	
- Pm Service		9.50	SHOP SUPPLIES		1.00
- Pickup Parts In Belle Glade			15/40 OIL		22.00
- Repair Rain Cap On Top Of Exhaust Pipe			15/40 OIL		22.00
- Performance Test			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
- Shop Supplies			C9559 FUEL FILTER LBF L8994F WIX 33628		1.00
			10003 INJECTOR CLEANER DON'T REORDER		1.00
			7213 OIL FILTER FRM CH9558 WIX 57213		1.00
			S3226FL02 FUEL FILTER USE FRAM PS9794		1.00
Parts Charge: 230.66		Labor Charge: 27.50			

Workorder: 735334

Problem: CHECK ENGINE LITE ON ALL THE TIME (EGR SYS.)

Meter Reading: 7638		Labor		Parts	
In Date: 03/08/2007	Close Date: 03/22/2007	Hours	Description	Quantity	
- Set Up For Replacement Of Egr Valve & Harness And To Reprogram Plo - Atlantic Truck Center		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 55.00			

Workorder: 735882

Problem: DONAL MOSS CORPORATION TOW FROM PA FLEET - TOW TO

Meter Reading: 0		Labor		Parts	
In Date: 03/09/2007	Close Date: 03/20/2007	Hours	Description	Quantity	
- Donal Moss Corporation Tow From Pa Fleet - Tow To Atlantic Truck Center					
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 630.00	

Workorder: 736983

Problem: DONAL MOSS CORPORATION TOW FROM ATLANTIC TRUCK - T

Meter Reading: 0		Labor		Parts	
In Date: 03/15/2007	Close Date: 04/10/2007	Hours	Description	Quantity	
- Donal Moss Corporation Tow From Atlantic Truck - Tow To Pa Fleet					
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 630.00	

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 737137		Problem: FRONT AXLE HUB CAPS (SEALS)			
Meter Reading: 8464		Labor	Parts		
In Date: 04/13/2007	Close Date: 05/03/2007	Hours	Description		Quantity
-	Replace 2 Front Hub Cap Seals	2.50	HUB CAP 21024		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
			HUB CAP 21024		1.00
	Parts Charge: 77.18	Labor Charge:	110.00		
Workorder: 738025		Problem: PERFORM TEMP TIRE REPAIR, ARANGE FOR TIRE SERVICEON THE ROAD			
Meter Reading: 8721		Labor	Parts		
In Date: 05/02/2007	Close Date: 05/25/2007	Hours	Description		Quantity
-	Plug Tire; Set Up Akron Tire Road Call	1.00	SHOP SUPPLIES		1.00
-	Shop Supplies				
	Parts Charge: 2.00	Labor Charge:	55.00		
Workorder: 739316		Problem: AKRON TIRE CO. INC.			
Meter Reading: 0		Labor	Parts		
In Date: 05/02/2007	Close Date: 05/31/2007	Hours	Description		Quantity
-	Akron Tire Co. Inc.				
	Parts Charge: 0.00	Labor Charge:	0.00	Commercial Charge: 30.00	
Workorder: 740027		Problem: AIRLEAK			
Meter Reading: 9465		Labor	Parts		
In Date: 06/14/2007	Close Date: 06/25/2007	Hours	Description		Quantity
-	Check For Air Leak At Knob	0.50			
	Parts Charge: 0.00	Labor Charge:	27.50		
Workorder: 741988		Problem: NO HEADLIGHTS			
Meter Reading: 9566		Labor	Parts		
In Date: 07/25/2007	Close Date: 07/26/2007	Hours	Description		Quantity
-	Void				
	Parts Charge: 0.00	Labor Charge:	0.00		

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 742745

Problem: PM SERVICE

Meter Reading: 10095		Labor		Parts	
In Date: 08/13/2007	Close Date: 08/17/2007	Hours	Description	Quantity	
- P/M Service		8.00	C9559 FUEL FILTER LBF L8994F WIX 33628		1.00
- R&R Right Reverse Light			SHOP SUPPLIES		1.00
- Road Test			10003 INJECTOR CLEANER DON'T REORDER		1.00
- Shop Supplies			15/40 OIL		26.00
			15/40 OIL		18.00
			7213 OIL FILTER FRM CH9558 WIX 57213		1.00
			S3226FL02 FUEL FILTER USE FRAM PS9794		1.00
Parts Charge: 225.45		Labor Charge: 27.50			

Workorder: 747705

Problem: ROAD CALL R&R TIRE

Meter Reading: 12135		Labor		Parts	
In Date: 11/26/2007	Close Date: 11/27/2007	Hours	Description	Quantity	
- Replace Tire		1.00	TIRE 295/75R225 7568174530		1.00
- Set Up For Road Service			SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 371.95		Labor Charge: 30.00			

Workorder: 747715

Problem: AKRON TIRE CO. INC.

Meter Reading: 0		Labor		Parts	
In Date: 11/26/2007	Close Date: 11/26/2007	Hours	Description	Quantity	
- Akron Tire Co. Inc.					
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 60.00	

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 833944

Problem: P.M. SERVICE

Meter Reading: 13622		Labor		Parts	
In Date: 02/11/2008	Close Date: 02/21/2008	Hours	Description		Quantity
-	P/M Service	8.50	15/40 OIL		44.00
-	5Th Wheel Lock Would Not Release Lube And Inspect		7213 OIL FILTER FRM CH9558 WIX 57213		1.00
-	Repair Bracket And Ground For Light Relay		USED FIREX REFURBED FIRE EXTINGSHERS		1.00
-	Road Test		10003 INJECTOR CLEANER DON'T REORDER		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
			S3226FL02 FUEL FILTER USE FRAM PS9794		1.00
			C9559 FUEL FILTER LBF L8994F WIX 33628		1.00
			31-20 WIPER BLADES 20" BLADE		2.00
Parts Charge:		233.18	Labor Charge:	30.00	

Workorder: 835375

Problem: WORK LIGHTS WILL NOT TURN ON

Meter Reading: 14117		Labor		Parts	
In Date: 03/12/2008	Close Date: 03/14/2008	Hours	Description		Quantity
-	Trouble Shoot Lights,One Light Had Bad Ground, Second Light Had Burned Out Bulb Replace Bulb	1.50	SHOP SUPPLIES		1.00
-	Shop Supplies		BP1255/H3 H/LIGHT BULB		1.00
Parts Charge:		9.56	Labor Charge:	90.00	

Workorder: 836209

Problem: WRITTEN IN ERROR

Meter Reading: 3070		Labor		Parts	
In Date: 03/28/2008	Close Date: 09/27/2008	Hours	Description		Quantity
-					
Parts Charge:		0.00	Labor Charge:	0.00	

Workorder: 836640

Problem: REPAIR FLAT

Meter Reading: 14411		Labor		Parts	
In Date: 04/07/2008	Close Date: 04/14/2008	Hours	Description		Quantity
-	Set Up With Vendor For Tire Repair	0.50			
Parts Charge:		0.00	Labor Charge:	30.00	

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 837585 **Problem:** AKRON TIRE CO. INC.

Meter Reading: 0	Labor	Parts	Quantity
In Date: 04/28/2008	Hours	Description	Quantity
- Akron Tire Co. Inc.			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	48.00

Workorder: 842128 **Problem:** TRAILER BRAKE

Meter Reading: 2478	Labor	Parts	Quantity
In Date: 07/30/2008	Hours	Description	Quantity
- Problem With Parking/Trailer Brake,Locate Leaking Line Under Dash And Repair			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	90.00
			1.00

Workorder: 842758 **Problem:** ORDER COMBONATION VALVE

Meter Reading: 16317	Labor	Parts	Quantity
In Date: 08/13/2008	Hours	Description	Quantity
- Order Combination Air Valve Assy			
- Shop Supplies			
Parts Charge:	278.14	Labor Charge:	30.00
			1.00
			1.00
			1.00

Workorder: 842896 **Problem:** P.M.SERVICE AIR VALVE

Meter Reading: 16557	Labor	Parts	Quantity
In Date: 08/15/2008	Hours	Description	Quantity
- P/M Service			
- R&R Combination Valve For Parking/Trailer Brake			
- Performance Test			
- Shop Supplies			
Parts Charge:	203.97	Labor Charge:	30.00
			44.00
			1.00
			1.00
			1.00
			2.00
			1.00

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 843837 **Problem:** FUEL FILTER

Meter Reading: 16716 **Labor**

In Date: 09/05/2008 **Hours** **Parts**

In Date: 09/05/2008	Close Date: 09/08/2008	Labor Hours	Description	Quantity
- R&R Fuel Filter		0.50	5410900151 FUEL FILTER WIX 33628 FRAM C9559	1.00
	Parts Charge: 16.56	Labor Charge: 30.00		

Workorder: 845807 **Problem:** HI BEAMS COME ON/OFF

Meter Reading: 17528 **Labor**

In Date: 10/17/2008 **Hours** **Parts**

In Date: 10/17/2008	Close Date: 10/29/2008	Labor Hours	Description	Quantity
- Hi Beams Go On And Off When Hitting Bumps,Intermittent Shortin Switch,R&R Muilt Function Switch,Check Op/Ok		2.50	MULTI/FUNCTION SW SHOP SUPPLIES	1.00 1.00
- Shop Supplies				
	Parts Charge: 79.76	Labor Charge: 150.00		

Workorder: 847622 **Problem:** DASH PANEL/BRACKET

Meter Reading: 18400 **Labor**

In Date: 12/02/2008 **Hours** **Parts**

In Date: 12/02/2008	Close Date: 12/08/2008	Labor Hours	Description	Quantity
- Replace Dash Panel For Ac Controls,Trailer Brake Control Andparking Valve,Plastic Panel Cracked		3.50	TIRE 295/75RX22.5 SHOP SUPPLIES	2.00 1.00
- Replace Two Front Tires			DASH PANEL SUPPORT	1.00
- Set Up For Tire Service				
- Shop Supplies				
	Parts Charge: 872.27	Labor Charge: 30.00		

Workorder: 848457 **Problem:** AKRON TIRE CO. INC.

Meter Reading: 0 **Labor**

In Date: 12/19/2008 **Hours** **Parts**

In Date: 12/19/2008	Close Date: 12/19/2008	Labor Hours	Description	Quantity
- Akron Tire Co. Inc.				
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 96.00	

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 932195

Problem: FUEL LINE RECALL\FREEZE & OIL GALLY PLUGS

Meter Reading: 18918	Labor	Parts			
In Date: 01/02/2009	Hours	Description	Quantity		
- Set Up With Dealer For Recall #08C-1 On Fuel Lines	2.00	SHOP SUPPLIES	1.00		
- Set Up Repairs At Atlantic Truck To Perform Campaign #06-M5 On Oil Galley Plugs					
- Shop Supplies					
Parts Charge:	2.00	Labor Charge:	120.00	Commercial Charge:	588.73

Workorder: 932355

Problem: RECALL

Meter Reading: 18724	Labor	Parts			
In Date: 01/06/2009	Hours	Description	Quantity		
- To Atlantic Truck And Back.	6.00	SHOP SUPPLIES	1.00		
- Pickup Vehicle Fr Atlantic.					
- Shop Supplies					
Parts Charge:	2.00	Labor Charge:	180.00		

Workorder: 932926

Problem: ADD OIL

Meter Reading: 19243	Labor	Parts			
In Date: 01/20/2009	Hours	Description	Quantity		
- Add Oil	0.30	15/40 OIL	3.00		
Parts Charge:	7.95	Labor Charge:	18.00		

Workorder: 933705

Problem: AKRON TIRE CO. INC.

Meter Reading: 0	Labor	Parts			
In Date: 02/06/2009	Hours	Description	Quantity		
- Akron Tire Co. Inc.					
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	78.00

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 934317

Problem: FLOOD LITES NOT WORKING

Meter Reading: 19682		Labor		Parts	
In Date: 02/23/2009	Close Date: 02/23/2009	Hours	Description	Quantity	
-	Light Bar Loose,Tighten All Mounting Bolts For Light Bar	1.30	P527682 AIR FILTER USE FRAM CA7140		1.00
	Andreplace Defective Bulb		SHOP SUPPLIES		1.00
-	Replace Dirty Air Filter		BP1255/H3 H/LIGHT BULB		1.00
-	Shop Supplies				
Parts Charge:		82.94	Labor Charge:		78.00

Workorder: 934582

Problem: P.M. SERVICE 2 BATT

Meter Reading: 19947		Labor		Parts	
In Date: 03/02/2009	Close Date: 03/09/2009	Hours	Description	Quantity	
-	P/M Service	8.00	SHOP SUPPLIES		1.00
-	Check Batteries,Defective,Cell Bad,Replace Batteries		GROUP 31 STUD BATTERY (ACD 31-900CT)		2.00
-	Shop Supplies		15/40 OIL		44.00
			31-20 WIPER BLADES 20" BLADE		2.00
			7213 OIL FILTER FRM CH9558 WIX 57213		1.00
Parts Charge:		444.25	Labor Charge:		480.00

Workorder: 935274

Problem: ABS LIGHT IS ON

Meter Reading: 20142		Labor		Parts	
In Date: 03/17/2009	Close Date: 03/26/2009	Hours	Description	Quantity	
-	Fm Atlantic Truck	4.00	SHOP SUPPLIES		1.00
-	Repair Abs By Atlantic Trucks.				
-	Shop Supplies				
Parts Charge:		2.00	Labor Charge:		120.00
			Commercial Charge:		765.60

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 938958

Problem: WATER IN FUELITE ON

Meter Reading: 22075	Labor	Parts	
In Date: 06/15/2009	Hours	Description	Quantity
- R&R Fuel Filter,Drain Both Tanks.No New Sensor	2.00	SHOP SUPPLIES FUEL/WATER SENSOR	1.00 1.00
- Water In Fuel Sensor Assy And Install Shop Supplies		S3226FL02 FUEL FILTER USE FRAM PS9794	1.00
Parts Charge: 135.15		Labor Charge: 120.00	

Workorder: 942393

Problem: P.M. Service trans service

Meter Reading: 23296	Labor	Parts	
In Date: 08/21/2009	Hours	Description	Quantity
- Pm Service	9.50	15/40 OIL	44.00
- Trans Pm Service W/Internal Filter Change		7213 OIL FILTER FRM CH9558 WIX 57213	1.00
- R&R Reverse Light Bulbs		S3226FL02 FUEL FILTER USE FRAM PS9794	1.00
- Performance Test		31-20 WIPER BLADES 20" BLADE	2.00
- Shop Supplies		ATFD TRANS FLUID MERCON V	27.00
		29526898 TRANS FILTER FRM C9031 WIX 57740XE	1.00
		C9559 FUEL FILTER LBF L8994F WIX 33628	1.00
		SHOP SUPPLIES	1.00
Parts Charge: 421.99		Labor Charge: 570.00	

Workorder: 943157

Problem: Lite on chain rack out

Meter Reading: 23766	Labor	Parts	
In Date: 09/11/2009	Hours	Description	Quantity
- Replace Bulb In Lamp On Chain Race	2.00	SHOP SUPPLIES	1.00
- Repair Tire		BP1255/H3 H/LIGHT BULB	1.00
- Shop Supplies		TIRE REPAIR 148186	1.00
Parts Charge: 44.27		Labor Charge: 120.00	

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 944732 **Problem:** Check for nail in R.R. tire

Meter Reading: 24418	Labor	Parts
In Date: 10/19/2009	Hours	Description
Close Date: 10/19/2009	Quantity	
- Ck. Tire For Nail/Screw In R.R. Tire	0.50	
Parts Charge: 0.00	Labor Charge: 30.00	

Workorder: 945596 **Problem:** LEFT REAR INSIDE TIRE FLAT

Meter Reading: 24727	Labor	Parts
In Date: 11/03/2009	Hours	Description
Close Date: 11/16/2009	Quantity	
- Temp.Repairs To L.R.R.I Tire/Order New Tire	3.00	TIRE DISPOSAL FEE
- Install Tire		295/75R22.5 G169 TIRE
- Shop Supplies		SHOP SUPPLIES
		INSTALL NEW TIRE @ PAHOKEE SHOP
Parts Charge: 655.64	Labor Charge: 120.00	
		3.00
		1.00
		1.00
		1.00

Workorder: 945865 **Problem:** trailer coard

Meter Reading: 24600	Labor	Parts
In Date: 11/09/2009	Hours	Description
Close Date: 11/18/2009	Quantity	
- R&R Damaged Trailer Lit Coard Assembly	1.50	A.B.S. GREEN TRAILER PIG TAIL
- Shop Supplies		SHOP SUPPLIES
Parts Charge: 96.77	Labor Charge: 180.00	
		1.00
		1.00

Workorder: 1001856 **Problem:** Replace All Tires

Meter Reading: 26279	Labor	Parts
In Date: 02/22/2010	Hours	Description
Close Date: 03/29/2010	Quantity	
- Replace All Tires	1.00	50308PW, 22.5 X 8.25 HP 3HH 10 HOLE WHEEL
- Shop Supplies		275/80R22.5(G) MICHELIN XZE2
		SHOP SUPPLIES
		27580R22.5 PXDEMS
Parts Charge: 3,206.12	Labor Charge: 60.00	
		2.00
		2.00
		1.00
		8.00

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 1003169

Problem: install 10 tires

Meter Reading: 26747	Labor	Parts	Quantity
In Date: 02/22/2010	Hours	Description	Quantity
- Pa			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	414.00

Workorder: 1006022

Problem: pm service / air leak on dash .

Meter Reading: 28096	Labor	Parts	Quantity
In Date: 06/08/2010	Hours	Description	Quantity
- Pm Service .	9.00	S3226FL02 FUEL FILTER USE FRAM PS9794	1.00
- Check For Air Leakes On Trailer . No Leaks Found .		31-20 WIPER BLADES 20" BLADE	2.00
- Test Drive.		SHOP SUPPLIES	1.00
- Shop Supplies		C9559 FUEL FILTER LBF L8994F WIX 33628	1.00
		15/40 OIL	44.00
		7213 OIL FILTER FRM CH9558 WIX 57213	1.00
Parts Charge:	218.64	Labor Charge:	540.00

Workorder: 1007500

Problem: repair tail light

Meter Reading: 28457	Labor	Parts	Quantity
In Date: 07/15/2010	Hours	Description	Quantity
- Replace Tail Light	1.50	SHOP SUPPLIES	1.00
- Move Tag To Rear		LH TAIL LIGHT ASSY	1.00
- Shop Supplies			
Parts Charge:	27.53	Labor Charge:	90.00

Workorder: 1008666

Problem: REPAIR AIR LEAK AT DRAIN

Meter Reading: 28609	Labor	Parts	Quantity
In Date: 08/11/2010	Hours	Description	Quantity
- R&R Leaking Air Drains .	1.00	AIR TANK DRAIN / 1421	2.00
- Shop Supplies		AIR TANK DRAIN / 1421	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	85.07	Labor Charge:	60.00

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 1012077

Problem: trailer air supply vale not working .

Meter Reading: 30186		Labor		Parts	
In Date: 10/28/2010	Close Date: 11/16/2010	Hours	Description		Quantity
- R&R Combo Air Valve.		7.50	COBINATION AIR VALVE / BW/800622		1.00
- Road Call To Hatton Hwy			S3226FL02 FUEL FILTER USE FRAM PS9794		1.00
- R&R Fuel Filters			09997 BRAKE CLEAN		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
			C9559 FUEL FILTER LBF L8994F WIX 33628		1.00
Parts Charge: 330.35		Labor Charge: 300.00			

Workorder: 1101695

Problem: pm service / leaking air valve dash / install cone rack on frame .

Meter Reading: 32413		Labor		Parts	
In Date: 02/14/2011	Close Date: 03/08/2011	Hours	Description		Quantity
- Pm Service		8.00	7213 OIL FILTER FRM CH9558 WIX 57213		1.00
- Un Hook From Trailer			SHOP SUPPLIES		1.00
- Test Drive			SYN/ATF TRANS FLUID SYNTHETIC		2.00
- Shop Supplies			C9559 FUEL FILTER LBF L8994F WIX 33628		1.00
			15/40 OIL		44.00
			31-20 WIPER BLADES 20" BLADE		2.00
			AIR FILTER / 6556		1.00
			S3226FL02 FUEL FILTER USE FRAM PS9794		1.00
Parts Charge: 319.14		Labor Charge: 480.00			

Workorder: 1104832

Problem: Leaking Oil

Meter Reading: 33780		Labor		Parts	
In Date: 05/05/2011	Close Date: 05/10/2011	Hours	Description		Quantity
- Check Rear End Top Off Oil		0.50	12345841 GEAR OIL SYNTHETIC 75W-90		8.00
- Shop Supplies			SHOP SUPPLIES		1.00
Parts Charge: 68.48		Labor Charge: 30.00			

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 1105165 **Problem:** check rear end for oil leak

Meter Reading: 34010	Labor	Parts
In Date: 05/16/2011	Hours	Description
Close Date: 05/17/2011		Quantity
- Check Rears No Problem Found	0.50	
Parts Charge:	0.00	Labor Charge: 30.00

Workorder: 1105447 **Problem:** check rear out side tire needs air

Meter Reading: 34158	Labor	Parts
In Date: 05/24/2011	Hours	Description
Close Date: 06/15/2011		Quantity
- Commercial Repair	3.30	AIR GAUGE / NTH90-3006
- Install Fittings & Air Hose For Tires		50FT / HD AIR HOSE / ATD8212
- Drain And Clean Fuel / Water Seperator		AIR CHUCK / NTH90-465
- Check Tire Air Psi		SHOP SUPPLIES
- Shop Supplies		
Parts Charge:	219.39	Labor Charge: 198.00 Commercial Charge: 72.00

Workorder: 1106138 **Problem:** water in fuel light on

Meter Reading: 34357	Labor	Parts
In Date: 06/09/2011	Hours	Description
Close Date: 06/28/2011		Quantity
- R&R Fuel Filter Water Seperator, Inspected And Cleaned Bowl, Bleed System	1.50	S3226FL02 FUEL FILTER USE FRAM PS9794
- Shop Supplies		SHOP SUPPLIES
Parts Charge:	38.02	Labor Charge: 90.00

Workorder: 1107782 **Problem:** WATER IN FUEL LIGHT ON

Meter Reading: 34898	Labor	Parts
In Date: 07/25/2011	Hours	Description
Close Date: 07/27/2011		Quantity
- Removed And Replaced Fuel/Water Separator Filter, Bleed System & Checked Fuel Quality In Tank	1.00	SHOP SUPPLIES
- Shop Supplies		S3226FL02 FUEL FILTER USE FRAM PS9794
Parts Charge:	38.02	Labor Charge: 60.00

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 1108631

Problem: Will not hold air,auto release not working,tractor abs stays on

Meter Reading: 35444		Labor		Parts	
In Date: 08/16/2011	Close Date: 09/08/2011	Hours	Description		Quantity
-	Auto Drain Not Closing, Disabled Auto Drain	17.50	5LB FIREX ABC STOCK# 340280001		1.00
-	Replaced Broken Bulbs In Worklights		15/40 OIL		44.00
-	Seatbelt Found In Locked Position,Released From Air Line And Adjusted		7213 OIL FILTER FRM CH9558 WIX 57213		1.00
-	Replaced Water In Fuel Sensor		31-20 WIPER BLADES 20" BLADE		2.00
-	Pm Service		C9559 FUEL FILTER LBF L8994F WIX 33628		1.00
-	Transmission Service		SYN/ATF TRANS FLUID SYNTHETIC		2.00
-	Serviced Last Axle, Checked For Debris In Fluid		S3226FL02 FUEL FILTER USE FRAM PS9794		1.00
-	Removed Gear Oil From Back Of Truck And Front Of Trailer		BP1255/H3 H/LIGHT BULB		2.00
-	Performance Test		SYN/ATF TRANS FLUID SYNTHETIC		2.00
-	Dissassembled Dash To Check Air Box Doors, Located Source Of Lossed Air Flow, Repaired Accordingly		29526898 TRANS FILTER FRM C9031 WIX 57740XE		1.00
-	Shop Supplies		AIR FILTER / 6556		1.00
			SYN/ATF TRANS FLUID SYNTHETIC		27.00
			SHOP SUPPLIES		1.00
			FUEL WATER SENSOR / N122-WSKL4000		1.00
			12345841 GEAR OIL SYNTHETIC 75W-90		13.00
Parts Charge:		977.70	Labor Charge:	1,050.00	

Workorder: 1109857

Problem: REBUILD AUTO AIR DRAIN VALVE

Meter Reading: 36270		Labor		Parts	
In Date: 09/15/2011	Close Date: 09/23/2011	Hours	Description		Quantity
-	Rebuild Auto Drain Valve	2.50	SHOP SUPPLIES		1.00
-	Replaced Water In Fuel Sensor & Tested System				
-	Shop Supplies				
Parts Charge:		2.00	Labor Charge:	150.00	

Workorder: 1112289

Problem: LEFT HEADLIGHT OUT

Meter Reading: 37153		Labor		Parts	
In Date: 11/17/2011	Close Date: 12/06/2011	Hours	Description		Quantity
-	Replaced Front Head Light	1.00	H6054 SEALED BEAM		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
Parts Charge:		19.99	Labor Charge:	60.00	

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 1112654

Problem: Tractor loses all air when not running

Meter Reading: 37268		Labor		Parts	
In Date: 11/30/2011	Close Date: 12/15/2011	Hours	Description		Quantity
-	Repair Air Leak At Secondary Air Tank, Replaced Valve With Manual Bleed Valve	5.00	SHOP SUPPLIES		1.00
-	Road Call				
-	Shop Supplies				
Parts Charge: 2.00		Labor Charge: 300.00			

Workorder: 1113299

Problem: ABS light On

Meter Reading: 37834		Labor		Parts	
In Date: 12/19/2011	Close Date: 12/20/2011	Hours	Description		Quantity
-	Inspect Wheels For Broken Wires, No Abs Light At The Moment, Road Tested No Problem Found.	1.00	SHOP SUPPLIES		1.00
Note: Abs Light Will Light In When Brake Is Applied And Abs Is Engaged					
-	Shop Supplies				
Parts Charge: 2.00		Labor Charge: 60.00			

Workorder: 1200489

Problem: WORK LIGHT OUT, CHECK OIL IN FRONT HUBS

Meter Reading: 38394		Labor		Parts	
In Date: 01/17/2012	Close Date: 01/23/2012	Hours	Description		Quantity
-	R&R Work Light Bulb	0.80	SHOP SUPPLIES		1.00
-	Top Off Hubs		BP1255/H3 H/LIGHT BULB		1.00
-	Shop Supplies		85/140 GEAR OIL GEAR LUBE		1.00
Parts Charge: 9.19		Labor Charge: 48.00			

Workorder: 1201694

Problem: ADD OIL

Meter Reading: 39491		Labor		Parts	
In Date: 02/22/2012	Close Date: 02/27/2012	Hours	Description		Quantity
-	Add Oil	0.30	15/40 OIL		3.00
Parts Charge: 8.47		Labor Charge: 18.00			

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 1202032 **Problem:** pm service / dash board loose

Meter Reading: 40878	Labor	Parts	
In Date: 02/29/2012	Hours	Description	
Close Date: 05/25/2012		Quantity	
- Pm Service	7.50	S3226FL02 FUEL FILTER USE FRAM PS9794	1.00
- Serviced Ac Cab Filters, Cleaned & Inspected		31-20 WIPER BLADES 20" BLADE	2.00
- Shop Supplies		C9559 FUEL FILTER LBF L8994F WIX 33628	1.00
		AIR FILTER / 6556	1.00
		7213 OIL FILTER FRM CH9558 WIX 57213	1.00
		15/40 OIL	44.00
		SHOP SUPPLIES	1.00
Parts Charge:	322.49	Labor Charge:	450.00

Workorder: 1206459 **Problem:** ADD OIL

Meter Reading: 42230	Labor	Parts	
In Date: 07/10/2012	Hours	Description	
Close Date: 07/19/2012		Quantity	
- Add Oil	0.30	15/40 OIL	3.00
Parts Charge:	8.47	Labor Charge:	18.00

Workorder: 1207876 **Problem:** No trailer air suply

Meter Reading: 43101	Labor	Parts	
In Date: 08/20/2012	Hours	Description	
Close Date: 08/24/2012		Quantity	
- Replace Protection Air Valve	4.00	VALVE	1.00
- To Total Truck		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	67.61	Labor Charge:	240.00

Workorder: 1207890 **Problem:** TRANSPORT TO VISTA

Meter Reading: 43302	Labor	Parts	
In Date: 08/20/2012	Hours	Description	
Close Date: 08/29/2012		Quantity	
- Drive To Vista For Repairs	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 1209417

Problem: 9103

Meter Reading: 43915		Labor	Parts	
In Date: 10/02/2012	Close Date: 10/16/2012	Hours	Description	Quantity
-	P.M. Tandom	10.50	CH9558 OIL FILTER LBF	1.00
-	Couple And Uncouple Trailer		31-20 WIPER BLADES 20	2.00
-	Used High Presure Pump To Blead System		SHOP SUPPLIES	1.00
-	Test Run		C9559 FUEL FILTER LBF	1.00
-	Shop Supplies		USED FIREX REFURBED F	1.00
			05088 BRAKE CLEAN	1.00
			15-40 OIL	6.00
			15-40 OIL	44.00
			PS9794 FUEL FILTER LB	1.00
Parts Charge: 311.21		Labor Charge: 630.00		

Workorder: 1210284

Problem: Trailer brake not releasing

Meter Reading: 44199		Labor	Parts	
In Date: 10/25/2012	Close Date: 11/21/2012	Hours	Description	Quantity
-	Trailer Brake Not Releasing. Brake Valve Leaking.	2.00	VALVE MANIF DASH	1.00
	Replace Brake Valve		SHOP SUPPLIES	1.00
-	Shop Supplies		DASH VALVE	1.00
Parts Charge: 360.49		Labor Charge: 120.00		

Workorder: 1212339

Problem: ac on high blows out dash not vents

Meter Reading: 45102		Labor	Parts	
In Date: 12/27/2012	Close Date: 01/11/2013	Hours	Description	Quantity
-	Test Ac Operation Npf	1.00	SHOP SUPPLIES	1.00
-	Shop Supplies			
Parts Charge: 2.00		Labor Charge: 60.00		

Workorder: 1301362

Problem: DS headlight not working.

Meter Reading: 45728		Labor	Parts	
In Date: 02/07/2013	Close Date: 02/11/2013	Hours	Description	Quantity
-	Replace Shorted Ds Headlight.	0.50	HALOGEN LAMP	1.00
Parts Charge: 9.87		Labor Charge: 30.00		

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 1303202

Problem: Pm service

Meter Reading: 46991		Labor		Parts	
In Date: 04/02/2013	Close Date: 04/10/2013	Hours	Description	Quantity	
- Pm Service.		9.00	NAPAGOLD OIL FILTER	1.00	
- Trans. Service.			NAPAGOLD FUEL FILTER	1.00	
- Shop Supplies			29526898 TRANS FILTER	1.00	
			31-20 WIPER BLADES 20	2.00	
			SYN ATF BULK PAHOKEE	27.00	
			NAPAGOLD FUEL FILTER	1.00	
			SHOP SUPPLIES	1.00	
			NAPAGOLD AIR FILTER	1.00	
			15W40 BULK TANK PAHOKEE	44.00	
Parts Charge: 551.31		Labor Charge: 540.00			

Workorder: 1307760

Problem: Replace tires by Boulevard.

Meter Reading: 48993		Labor		Parts	
In Date: 08/05/2013	Close Date: 09/04/2013	Hours	Description	Quantity	
- Replace Tires By Boulevard Tire.		3.00	DASH PANEL	1.00	
- Rear Diff. Vent Clogged. Removed And Cleaned Vent.			Freight Charge	1.00	
- Checked Fluid Level. Pressure Wash Rear Diff.			SHOP SUPPLIES	1.00	
- Replace Broken Dash Panel.					
- Shop Supplies					
Parts Charge: 95.35		Labor Charge: 180.00		Commercial Charge: 2,562.58	

Workorder: 1309072

Problem: Exhaust leak. Tires

Meter Reading: 49669		Labor		Parts	
In Date: 09/09/2013	Close Date: 09/26/2013	Hours	Description	Quantity	
- Replace Rusted Exhaust Pipe.		5.00	SHOP SUPPLIES	1.00	
- Shop Supplies			PIPE-MUF IN 10SOB LC	1.00	
			HOSE FLEX EXH 5 IN	1.00	
			Freight Charge	1.00	
			EXHAUST CLAMP 5 IN	3.00	
Parts Charge: 470.64		Labor Charge: 300.00			

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 1311150

Problem: Pm service.

Meter Reading: 50564		Labor		Parts	
In Date: 11/04/2013	Close Date: 11/15/2013	Hours	Description	Quantity	
- Pm Service.		9.50	WIPER BLADE		2.00
- Clean Fifth Wheel And Rear Axle Area.			SHOP SUPPLIES		1.00
- Repair Running Lights And Wiring.			NAPAGOLD OIL FILTER		1.00
- Test Drive.			NAPAGOLD FUEL FILTER		1.00
- Shop Supplies			USED FIRE X REFURBISHED		1.00
			15W40 BULK TANK PAHOKEE		44.00
			NAPAGOLD FUEL FILTER		1.00
Parts Charge: 218.30		Labor Charge: 570.00			

Workorder: 1400993

Problem: Replace wiper blades

Meter Reading: 52723		Labor		Parts	
In Date: 01/30/2014	Close Date: 02/10/2014	Hours	Description	Quantity	
- Replace Wiper Blades.		0.50	WIPER BLADE		2.00
Parts Charge: 8.49		Labor Charge: 30.00			

Workorder: 1402071

Problem: Replace front tires.

Meter Reading: 53740		Labor		Parts	
In Date: 03/04/2014	Close Date: 03/12/2014	Hours	Description	Quantity	
- Replace Tires By Boulevard Tire.		2.00	GROUP 31 STUD DELCO		2.00
- Won'T Start Replace. Load Test Batteries. Batteries			SHOP SUPPLIES		1.00
- Failed Laod Test. Replace Both Batteries.					
- Test Drive.					
- Shop Supplies					
Parts Charge: 268.37		Labor Charge: 120.00		Commercial Charge: 898.22	

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 1402801

Problem: Washer fluid hose. Tires shake.

Meter Reading: 54250	Labor	Parts	
In Date: 03/24/2014	Hours	Description	Quantity
<hr/>			
- Replace Broken Fitting For Windshield Washer Hose.	4.00	SHOP SUPPLIES	1.00
- Front End Inspection.			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	240.00

Workorder: 1403082

Problem: Air leak.

Meter Reading: 54301	Labor	Parts	
In Date: 03/31/2014	Hours	Description	Quantity
<hr/>			
- Replace Leaking Air Valve.	2.00	SHOP SUPPLIES	1.00
- Hook Up To Low Boy Trailer.			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	120.00

Workorder: 1403130

Problem: Won't build air pressure.

Meter Reading: 54250	Labor	Parts	
In Date: 03/31/2014	Hours	Description	Quantity
<hr/>			
- Tow From: Us27 To: Pa Shop			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	300.00

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 1404753

Problem: MUFFLER BROKEN AT EXHAUST STACK

Meter Reading: 55507		Labor		Parts	
In Date: 05/15/2014	Close Date: 07/02/2014	Hours	Description		Quantity
- Pm Service.		12.00	Freight Charge		1.00
- Muffler Broken. Replace Muffler,Clamps And Pipe.			SYN ATF BULK PAHOKEE		4.00
- Check A/C Operation. Low Airflow From Vents. Clean Clogged Intake Vent.			NAPAGOLD OIL FILTER		1.00
			NAPAGOLD FUEL FILTER		1.00
- Lr Signal Light Dim. Check Circuit And Clean Corroded Ground.			NAPAGOLD FUEL FILTER		1.00
			WIPER BLADE		2.00
- Shop Supplies			15W40 BULK TANK PAHOKEE		44.00
			CLAMP		2.00
			PWR STEERING FL-QUART		1.00
			MUFFLER OE STERLING		1.00
			WASHER FLUID CONCENTR		1.00
			SHOP SUPPLIES		1.00
			NAPAGOLD AIR FILTER		1.00
Parts Charge: 640.39		Labor Charge: 720.00			

Workorder: 1408578

Problem: Park brake won't release.

Meter Reading: 57588		Labor		Parts	
In Date: 08/27/2014	Close Date: 09/08/2014	Hours	Description		Quantity
- Replace Leaking Dash Valve.		1.50	SHOP SUPPLIES		1.00
- Shop Supplies			Freight Charge		1.00
			DASH VALVE		1.00
			VALVE		1.00
Parts Charge: 334.42		Labor Charge: 90.00			

Workorder: 1410813

Problem: Replace tires.

Meter Reading: 58191		Labor		Parts	
In Date: 10/29/2014	Close Date: 11/05/2014	Hours	Description		Quantity
- Replace All Tires On Rear Drive Axle.					
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 1,782.72	

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 1411850

Problem: Air leak under dash. Dash trim

Meter Reading: 59259		Labor		Parts	
In Date: 11/24/2014	Close Date: 12/09/2014	Hours	Description		Quantity
-	Secure Loose Dash Panels. Replace Missing Mounting Screws As Needed.	4.50	SHOP SUPPLIES		1.00
-	Replace Leaking Trailer Brake Valve In Dash.		Freight Charge		1.00
-	Shop Supplies		VALVE		1.00
Parts Charge: 108.13		Labor Charge: 270.00			

Workorder: 1500379

Problem: Pm service.

Meter Reading: 59919		Labor		Parts	
In Date: 01/12/2015	Close Date: 01/13/2015	Hours	Description		Quantity
-	Pm Service.	7.50	15W40 BULK TANK PAHOKEE		44.00
-	Test Drive.		NAPAGOLD FUEL FILTER		1.00
-	Shop Supplies		NAPAGOLD OIL FILTER		1.00
			WIPER BLADE		2.00
			WASHER FLUID CONCENTR		1.00
			NAPAGOLD FUEL FILTER		1.00
			SHOP SUPPLIES		1.00
			USED FIRE X REFURBISHED		1.00
			SYN ATF BULK PAHOKEE		3.00
Parts Charge: 237.82		Labor Charge: 450.00			

Workorder: 1503872

Problem: Won't move.

Meter Reading: 61860		Labor		Parts	
In Date: 04/15/2015	Close Date: 05/14/2015	Hours	Description		Quantity
-	Fm To Sr715	6.50	15W40 BULK TANK PAHOKEE		6.00
-	Check Tramsmission Per Complaint. Check Trans Dtc'S.		GEAR OIL DRUM PAHOKEE		2.00
	No Problem Found.		FENDER KIT		1.00
-	Replace Rear Fenders.		Freight Charge		1.00
-	Add Oil.		SHOP SUPPLIES		1.00
-	Shop Supplies				
Parts Charge: 637.10		Labor Charge: 390.00			

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 1507449

Problem: Pm service.

Meter Reading: 63000	Labor	Parts	
In Date: 07/27/2015	Hours	Description	Quantity
- Pm Service.	9.50	SHOP SUPPLIES	1.00
- Complaint Fuel Tanks Not Pulling Equal. Check Fuel Tank		15W40 BULK TANK PAHOKEE	44.00
Vent Hoses And Pickup Hoses. No Problem Found.		NAPAGOLD OIL FILTER	1.00
- Test Drive.		NAPAGOLD FUEL FILTER	1.00
- Replace Leaking Tractor To Trailer Airlines.		NAPAGOLD AIR FILTER	1.00
- Shop Supplies		WIPER BLADE	2.00
		SEAL	4.00
		WASHER FLUID CONCENTR	1.00
		1SET,2 AIR HOSES	1.00
		NAPAGOLD FUEL FILTER	1.00
Parts Charge:	305.45	Labor Charge:	570.00

Workorder: 1508598

Problem: A/c not working. Seat leaking down

Meter Reading: 63581	Labor	Parts	
In Date: 08/27/2015	Hours	Description	Quantity
- Check A/C System Pressures. System Pressures Low.	3.50	TX VALVE SWITCH	1.00
Evacuate And Recharge A/C System. Replace Leaking		AIR VALVE KIT	1.00
Low Pressure Switch.		PAHOKEE SHOP FREON	1.00
- Replace Leaking Seat Switch For Air Suspension.		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	109.97	Labor Charge:	210.00

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 1602054

Problem: Pm service.

Meter Reading: 67119		Labor	Parts	
In Date: 02/29/2016	Close Date: 03/09/2016	Hours	Description	Quantity
- Pm Service.		8.00	SEALED BEAM FLOOD PAT	2.00
- Rear Cab Lights Not Working. Replace Broken Lights And Shorted Relay.			SHOP SUPPLIES	1.00
- Shop Supplies			RELAY	1.00
			15W40 BULK TANK PAHOKEE	3.00
			NAPAGOLD OIL FILTER	1.00
			15W40 BULK TANK PAHOKEE	44.00
			NAPAGOLD FUEL FILTER	1.00
			WASHER FLUID CONCENTR	1.00
			20" WIPER BLADE	2.00
			NAPAGOLD FUEL FILTER	1.00
Parts Charge: 319.25		Labor Charge: 480.00		

Workorder: 1603492

Problem: Flat tire.

Meter Reading: 67887		Labor	Parts	
In Date: 04/04/2016	Close Date: 04/06/2016	Hours	Description	Quantity
- Replace Rfi Tire.		1.00	TIRE DISPOSAL FEE	1.00
- Shop Supplies			11R22.5 G661 TIRE	1.00
			SHOP SUPPLIES	1.00
Parts Charge: 505.08		Labor Charge: 60.00		

Workorder: 1603748

Problem: Secure dash,a/c shutting off.

Meter Reading: 67981		Labor	Parts	
In Date: 04/11/2016	Close Date: 04/11/2016	Hours	Description	Quantity
- Replace Broken Dash Mounting Hardware.		2.50	SHOP SUPPLIES	1.00
- Repair Wires That Were Rubbing On Dash Brackets For A/C Control.				
- Shop Supplies				
Parts Charge: 2.00		Labor Charge: 150.00		

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 1604609

Problem: REPLACE REAR TIRES

Meter Reading: 68555	Labor	Parts	Quantity
In Date: 05/02/2016	Hours	Description	Quantity
- Replace Four Rear Tires			
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 2,036.69	

Workorder: 1605044

Problem: A/c not cooling. Check fuel tank vents.

Meter Reading: 68555	Labor	Parts	Quantity
In Date: 05/16/2016	Hours	Description	Quantity
- A/C Cycling. Evap Freezing Up/Clogged. Cleaned Evap. Test Ran And Checked System Pressures.	3.00	SHOP SUPPLIES	1.00
- Checked Fuel Tank Vents And Check Valves Per Complaint. No Problem Found.			
- Shop Supplies			
Parts Charge: 2.00	Labor Charge: 180.00		

Workorder: 1605243

Problem: AC / Glad Hands

Meter Reading: 68976	Labor	Parts	Quantity
In Date: 05/20/2016	Hours	Description	Quantity
- Replace Gladhand Rubbers	3.00	SHOP SUPPLIES	1.00
- Check Ac System		SEAL	2.00
- Long Test Drives		BRAKE CLEANER	2.00
- Shop Supplies			
Parts Charge: 9.38	Labor Charge: 180.00		

10/17/2016
11:19:42AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10156546 2006 STERLING LT9500 Truck Tractor, Tandem Axle

Workorder: 1606545

Problem: Fuel Leak

Meter Reading: 69295	Labor	Parts		
In Date: 06/28/2016	Hours	Description	Quantity	
- Replace Fuel Supply Line And Remove Accessories To Access To Mako Wash Engine Bay Test Run Couple Low Boy For Road Test Shop Supplies	9.00	SHOP SUPPLIES	1.00	
Parts Charge:	2.00	Labor Charge:	540.00	

Workorder: 1607178

Problem: Fuel Line Broken

Meter Reading: 69615	Labor	Parts		
In Date: 06/24/2016	Hours	Description	Quantity	
- Tow From: Seminole Pratt Whitney Rd North Of Southern Blvd To: He Shop				
Parts Charge:	0.00	Labor Charge:	0.00	

Workorder: 1608726

Problem: Transition Prep Charge

Meter Reading: 70118	Labor	Parts		
In Date: 08/23/2016	Hours	Description	Quantity	
- Transition Prep Charge	2.00			
Parts Charge:	0.00	Labor Charge:	0.00	

Total Parts Charges:	17,863.36	Total Labor Charges:	16,558.00	Total Comm. Charges:	11,616.54
----------------------	------------------	----------------------	------------------	----------------------	------------------