

12/28/2017
3:55:28PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179133 2009 FORD F150 Pickup, 1/2 Ton, 4X4

Workorder: 941858

Problem: weld winch bolts

Meter Reading: 334	Labor	Parts	
In Date: 08/07/2009	Hours	Description	Quantity
<hr/>			
- Weld Bolts On Winch	1.50	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	90.00

Workorder: 941875

Problem: Pre Delivery Inspection

Meter Reading: 334	Labor	Parts	
In Date: 08/10/2009	Hours	Description	Quantity
<hr/>			
- Pre Delivery Inspection	2.00		
Parts Charge:	0.00	Labor Charge:	120.00

Workorder: 1000791

Problem: P.M service, winch planetary drive won't disengage.

Meter Reading: 5493	Labor	Parts	
In Date: 01/21/2010	Hours	Description	Quantity
<hr/>			
- P.M Service.	5.25	SHOP SUPPLIES	1.00
- Rotate & Balance All Four Tires.		1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Disassemble Planetary Gear Drive On Winch & O/H.		5W20 ENGINE OIL	7.00
- Shop Supplies		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
Parts Charge:	31.08	Labor Charge:	315.00

Workorder: 1006303

Problem: Pm service.

Meter Reading: 10589	Labor	Parts	
In Date: 06/15/2010	Hours	Description	Quantity
<hr/>			
- Perform Pm Service.	3.75	5W20 ENGINE OIL	7.00
- Inspect And Service Power Winch.		7090BLK FRT FLOOR MATS (RUBBER QUEEN)	1.00
- Shop Supplies		CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
		31-20 WIPER BLADES 20" BLADE	2.00
		SHOP SUPPLIES	1.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
Parts Charge:	92.07	Labor Charge:	225.00

12/28/2017
3:55:28PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179133 2009 FORD F150 Pickup, 1/2 Ton, 4X4

Workorder: 1014107

Problem: P.M. service and canceiver.

Meter Reading: 16072	Labor	Parts	
In Date: 12/28/2010	Hours	Description	Quantity
- Perform Pm Service.	5.75	TIRE PRESSURE SENSOR	1.00
- Remove Left Front Tire And Replace Failed Tire Pressure Sensor With New.Rotate And Balance All Four Tires.		SHOP SUPPLIES	1.00
- Inspect And Service Power Winch.		5W20 ENGINE OIL	7.00
- Shop Supplies		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		31-20 WIPER BLADES 20" BLADE	2.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
Parts Charge:	100.59	Labor Charge:	345.00

Workorder: 1100148

Problem: flash canceiver spot # 217

Meter Reading: 16075	Labor	Parts	
In Date: 01/04/2011	Hours	Description	Quantity
- Reflash Canceiver And Reprogram	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 1103921

Problem: Request for installing new trailer hitch assembly and wiring harness.

Meter Reading: 18861	Labor	Parts	
In Date: 04/12/2011	Hours	Description	Quantity
- Fabricate And And Install Trailer Hitch.Install Trailer Plug	2.00	5404 FEMALE CONNECTOR	1.00
- And Install Wiring.		5402 SOCKET BRACKET	1.00
- Shop Supplies		6033 MOUNTED PINTLES BALL/PINTLE HITCH	1.00
		2535 D.P. HITCH MOUNT	1.00
		8616-100 TRAILER WIRE 6 WIRE 14 GAUGE	3.00
		SHOP SUPPLIES	1.00
		2571 RECEIVER LOCK 5/8"	1.00
		HITCH/RECEIVER	1.00
Parts Charge:	274.94	Labor Charge:	120.00

12/28/2017
3:55:28PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179133 2009 FORD F150 Pickup, 1/2 Ton, 4X4

Workorder: 1107032

Problem: Pm service

Meter Reading: 21387	Labor	Parts	
In Date: 07/01/2011	Hours	Description	Quantity
- Perform Pm Service.	5.75	5W20 ENGINE OIL	7.00
- Repair Flat Right Front Tire.Nitrogen Fill And Balance All Four.		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		31-20 WIPER BLADES 20" BLADE	2.00
- Inspect And Service Power Winch.		SHOP SUPPLIES	1.00
- Shop Supplies		CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
Parts Charge:	35.84	Labor Charge:	345.00

Workorder: 1112138

Problem: Ir flat put on spare

Meter Reading: 24753	Labor	Parts	
In Date: 11/10/2011	Hours	Description	Quantity
- Boynton Inlet			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	62.70

Workorder: 1113192

Problem: P.M. service and repair flat tire left rear.

Meter Reading: 25681	Labor	Parts	
In Date: 12/15/2011	Hours	Description	Quantity
- P.M. Service.	7.75	LEFT FRONT DOOR CHECK STRAP	1.00
- Test Battery And Charging System.Charge And Retest Battery,Fail Load Test.Replace Defective Battery.		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		TIRE DISPOSAL FEE	2.00
- Replace Two Tires,Rotate And Balance All Four.		758537188 235/75R17 WRGLR SILENT ARMOR 108T	2.00
- R&R Left Front Door Panel And Replace Broken Door Stop Strap.		GROUP 59 BATTERY (MTC BXT 59)	1.00
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Inspect And Service Winch.		SHOP SUPPLIES	1.00
- Shop Supplies		5W20 ENGINE OIL	7.00
Parts Charge:	503.44	Labor Charge:	465.00

12/28/2017
3:55:28PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179133 2009 FORD F150 Pickup, 1/2 Ton, 4X4

Workorder: 1205183

Problem: P.M. service.

Meter Reading: 30845	Labor	Parts	
In Date: 06/04/2012	Hours	Description	Quantity
- P.M. Service.	4.75	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Inspect And Service Winch.		SHOP SUPPLIES	1.00
- Rotate And Balance All Tires.		31-20 WIPER BLADES 20" BLADE	2.00
- Shop Supplies		5W20 ENGINE OIL	7.00
Parts Charge:	32.05	Labor Charge:	285.00

Workorder: 1212022

Problem: Pm service.Turnsignal and winch pendant,See notes.

Meter Reading: 37212	Labor	Parts	
In Date: 12/13/2012	Hours	Description	Quantity
- Perform Pm Service.	8.75	SHOP SUPPLIES	1.00
- Test And Replace Failed Right Rear Signal Lamp Bulb With New.		TIRE DISPOSAL FEE	2.00
		PH2 OIL FILTER LBF PH	1.00
- Inspect And Service Power Winch.Test And Replace Failed ,Broken Pendant Controller With New.		5W20 ENGINE OIL	7.00
		CA10262 AIR FILTER MT	1.00
- Install Two New Tires To The Front Wheels.Nitrogen Fill And Balance All Four.		31-20 WIPER BLADES 20	2.00
		BIG G DEGREASER STOCK	1.00
- Perform Wheel Alignment Complete.		4057 BULB	2.00
- Shop Supplies		758537188 235-75R17	2.00
		USED FIREX REFURBED F	1.00
		WINCH REMOTE CONTROL	1.00
		Freight Charge	1.00
Parts Charge:	629.52	Labor Charge:	525.00

Workorder: 1306725

Problem: P.M. Service.

Meter Reading: 41930	Labor	Parts	
In Date: 07/05/2013	Hours	Description	Quantity
- P.M. Service.	6.25	5W20 ENGINE OIL	7.00
- Flush And Refil Transmission System.		31-20 WIPER BLADES 20	2.00
- Inspect And Service Winch.		NAPAGOLD OIL FILTER	1.00
- Rotate And Balance All Tires.		SYN-ATF TRANS FLUID S	16.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	111.97	Labor Charge:	375.00

12/28/2017
3:55:28PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179133 2009 FORD F150 Pickup, 1/2 Ton, 4X4

Workorder: 1308015

Problem: damage to rgt side of bed

Meter Reading: 41930	Labor	Parts	
In Date: 07/18/2013	Hours	Description	Quantity
<hr/>			
- Damage To Rgt Side Of Bed			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	294.00

Workorder: 1312671

Problem: Pm service and decal fell off tail gate.

Meter Reading: 47021	Labor	Parts	
In Date: 12/19/2013	Hours	Description	Quantity
<hr/>			
- Perform Pm Service.	6.25	5W20 ENGINE OIL	7.00
- Clean Off Old Adhesive And Install New Emblem On To Tail Gate.Also Replace Failed Driver Visor Clip With New.		NAPAGOLD OIL FILTER	1.00
		WIPER BLADE	2.00
- Replace Missing Hitch Pintle Pin With New.		USED FIRE X REFURBISHED	1.00
- Inspect And Service Power Winch		PINTLE PIN W/CHAIN	1.00
- Rotate And Balance All Four Tires.		visor clip retainer	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		emblem name plate	1.00
Parts Charge:	104.53	Labor Charge:	375.00

Workorder: 1405266

Problem: P.M. service.

Meter Reading: 52075	Labor	Parts	
In Date: 05/30/2014	Hours	Description	Quantity
<hr/>			
- P.M. Service.	10.15	5W20 ENGINE OIL	7.00
- A/C Not Cold.Check A/C System.Replace Leaking Condensor.Vacuum And Recharge System To Specs.		NAPAGOLD OIL FILTER	1.00
		USED FIRE X REFURBISHED	1.00
- Check Fluid Leak.Replace Leaking Power Steering Pressure Hose.Flush And Bleed System.		WIPER BLADE	2.00
		R134A LV SHOP 1	2.00
- Rotate And Balance All Tires.		RAPID SEAL KIT	1.00
- Inspect And Service Winch.		PS HOSE	1.00
- Shop Supplies		SYN-ATF TRANS FLUID S	2.00
		STG WHEEL COV - FORD	1.00
		CONDENSER	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	547.63	Labor Charge:	609.00

12/28/2017
3:55:28PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179133 2009 FORD F150 Pickup, 1/2 Ton, 4X4

Workorder: 1408196

Problem: Towed in for wont go into gear.

Meter Reading: 54312	Labor	Parts	
In Date: 08/19/2014	Hours	Description	Quantity
- Diagnose Transfer Case.Replace Defective Transfer Case	1.50	LEVER	1.00
Shifter Cable Assembly.Retest.		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	103.26	Labor Charge:	90.00

Workorder: 1408389

Problem: Wont go in gear

Meter Reading: 54074	Labor	Parts	
In Date: 08/18/2014	Hours	Description	Quantity
- Tow From: Coral Cove Park, Jupiter			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	104.15

Workorder: 1411248

Problem: Pm service

Meter Reading: 57252	Labor	Parts	
In Date: 11/10/2014	Hours	Description	Quantity
- Pm Service.	5.75	5W20 ENGINE OIL	7.00
- Inspect,,Check Electrical And Charging System.Battery		WIPER BLADE	2.00
Failed Loadtest.Replace Defective Battery.		WASHER FLUID CONCENTR	1.00
- Inspect And Service Winch.		BATTERY	1.00
- Rotate And Balance All Four Tires.		MACS CHAIN CABLE LUBE	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		NAPAGOLD OIL FILTER	1.00
Parts Charge:	160.93	Labor Charge:	345.00

12/28/2017
3:55:28PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179133 2009 FORD F150 Pickup, 1/2 Ton, 4X4

Workorder: 1506050

Problem: Pm service.

Meter Reading: 63065	Labor	Parts	
In Date: 06/17/2015	Hours	Description	Quantity
- Pm Service.	10.75	USED FIRE X REFURBISHED	1.00
- Perform Engine Coolant Flush And Refill System.		WIPER BLADE	2.00
- Replace Front Brake Pads And Two Front Brake Calipers.Resurface Both Front Brake Rotors.Bleed Brake System And Roadtest.		REMAN BRAKE CALIPER	1.00
		REMAN BRAKE CALIPER	1.00
		BRAKE CLEANER	1.00
- Rotate And Balance All Four Tires.		DISC BRAKE PADS	1.00
- Inspect And Service Winch.		SHOP SUPPLIES	1.00
- Shop Supplies		B FLUID DOT 3-32OZ	1.00
		PEAK GLOBAL	2.00
		5W20 ENGINE OIL	7.00
		NAPAGOLD OIL FILTER	1.00
Parts Charge:	271.76	Labor Charge:	645.00

Workorder: 1512641

Problem: P.M. service and tire pressure light on.

Meter Reading: 69125	Labor	Parts	
In Date: 12/15/2015	Hours	Description	Quantity
- Pm Service.	10.00	TPMS12 SENSOR TIRE PR	1.00
- Replace Defective Right Front Tire Pressure Sensor.Replace And Balance All Four Tires.		NAPAGOLD OIL FILTER	1.00
		235 75R17 ADVENTURE	4.00
- Disassemble Power Winch.Clean And Lube Binding Planetary Gears Due To Water.Service Winch.		TPM SENSOR	1.00
		5W20 ENGINE OIL	7.00
- Complete Front End Alignment And Roadtest.		DRAIN PLUG	1.00
- Shop Supplies		22" WIPER BLADE	2.00
		TIRE DISPOSAL FEE	4.00
		SHOP SUPPLIES	1.00
		WASHER FLUID CONCENTR	1.00
Parts Charge:	978.85	Labor Charge:	600.00

12/28/2017
3:55:28PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179133 2009 FORD F150 Pickup, 1/2 Ton, 4X4

Workorder: 1602489

Problem: Left rear tire flat.

Meter Reading: 71035	Labor	Parts
In Date: 03/09/2016	Hours	Description
Close Date: 03/14/2016	Quantity	
- Repair And Balabce Left Rear Tire.	1.00	SHOP SUPPLIES
- Shop Supplies		
Parts Charge:	2.00	Labor Charge: 60.00

Workorder: 1602504

Problem: Driver Rear Flat, tire change, put spare on

Meter Reading: 71035	Labor	Parts
In Date: 03/07/2016	Hours	Description
Close Date: 03/09/2016	Quantity	
- Tow From: Jpp Maint Compound		
Parts Charge:	0.00	Labor Charge: 0.00

Workorder: 1606186

Problem: P.M. service.

Meter Reading: 74476	Labor	Parts
In Date: 06/16/2016	Hours	Description
Close Date: 07/01/2016	Quantity	
- P.M. Service.	15.75	SHOP SUPPLIES
- Reploace Spark Plug And One Coil.		FORD IGNITION COIL
- Service And Clean Throttle Body.Clean Induction System.Flush Injectors.		NAPAGOLD OIL FILTER
		5W20 ENGINE OIL
- Diagnose Check Engine Light.Perform Pin Point Test.Replace Both Upstream Oxygen Sensors.Clear Codes.		22" WIPER BLADE
		WASHER FLUID CONCENTR
		NAPAGOLD AIR FILTER
- Replace Leaking Power Steering Pressure Hose.Flush And Refill System.		USED FIRE X REFURBISHED
		spark plug
- Inspect And Service Winch.		INTAKE CLEANER KIT
- Rotate And Balance All Tires.		SENSOR
- Shop Supplies		PS HOSE
		oil auto
		BRAKE CLEANER
		INJECTOR CLEANER
Parts Charge:	664.86	Labor Charge: 945.00

12/28/2017
3:55:28PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179133 2009 FORD F150 Pickup, 1/2 Ton, 4X4

Workorder: 1612327

Problem: P.M. service.

Meter Reading: 79568	Labor	Parts	
In Date: 12/01/2016	Hours	Description	Quantity
- P.M. Service.	7.25	CLEVIS SLIP HOOK-BULK	1.00
- Test Battery And Charging System.Replace Bad Battery.		BATTERY	1.00
- Replace Right Signal Light Bulb And Marker Lamp Bulb.		5W20 ENGINE OIL	7.00
- Inspect And Service Winch.Replace And Respool Cable.		CRANE CABLE FABRICATION	1.00
- Rotate And Balance Tires.		20" WIPER BLADE	2.00
- Shop Supplies		USED FIRE X REFURBISHED	1.00
		NAPAGOLD OIL FILTER	1.00
		BULB	1.00
		SHOP SUPPLIES	1.00
		BULB	1.00
Parts Charge:	392.11	Labor Charge:	435.00

Workorder: 1704912

Problem: P.M. service and tire pressure sensor fault warning on.

Meter Reading: 84423	Labor	Parts	
In Date: 05/17/2017	Hours	Description	Quantity
- P.M. Service.	5.75	5W20 ENGINE OIL	7.00
- Tire Pressure Light On ,Sensor Fault.Replace Right Rear Tire Pressure Sensor With New Due To No Communication.Rotate Four Tires And Balance And Reset Tire Sensors.		NAPAGOLD OIL FILTER	1.00
		WASHER FLUID CONCENTR	1.00
		20" WIPER BLADE	2.00
		TPMS12 SENSOR TIRE PR	1.00
- Inspect And Service Power Winch.		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	110.97	Labor Charge:	345.00

12/28/2017
3:55:28PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10179133 2009 FORD F150 Pickup, 1/2 Ton, 4X4

Workorder: 1709451

Problem: A/C inop and noise from belt area.

Meter Reading: 88234	Labor	Parts	
In Date: 09/28/2017	Hours	Description	Quantity
- Check And Replace Noisy A/C Compressor And Accumulator.Flush System.Vacuum And Recharge System To Specs.	5.50	SHOP SUPPLIES	1.00
		accumulator	1.00
		SERPENTINE BELT	1.00
		A/C COMPRESSOR	1.00
		A/C ORING KIT	1.00
		RAPID SEAL KIT	1.00
		PAG OIL	1.00
			1.00
Parts Charge:	625.37	Labor Charge:	330.00

Workorder: 1711874

Problem: Transition Prep Charge

Meter Reading: 88842	Labor	Parts	
In Date: 12/04/2017	Hours	Description	Quantity
- Transition Prep Charge	2.00		
Parts Charge:	0.00	Labor Charge:	0.00

Total Parts Charges:	5,777.77	Total Labor Charges:	8,049.00	Total Comm. Charges:	460.85
----------------------	-----------------	----------------------	-----------------	----------------------	---------------