



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V16342

In Date: 07/14/2008
Close Date: 07/16/2008

Meter Reading: 1,763.00

Problem?

ON CALL AIR PESS SENSOR LEAKING R41

Parts	Quantity
-------	----------

Task performed:

Remove tire air sensor; air up tire; fnd sensor leaking; remove. j

NO PARTS USED

Workorder: V16293

In Date: 07/11/2008
Close Date: 07/23/2008

Meter Reading: 1,623.00

Problem?

repair a/c and turn signal r41

Parts	Quantity
-------	----------

Task performed:

Recharged rear 110 A/C. j

NO PARTS USED

Workorder: V16624

In Date: 07/28/2008
Close Date: 07/30/2008

Meter Reading: 2,662.00

Problem?

TIRES LOW ON AIR R-41

Parts	Quantity
-------	----------

Task performed:

REFILLED TIRES. J

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V16797

In Date: 08/04/2008
Close Date: 08/11/2008

Meter Reading: 2,976.00

Problem?

LOW COOLANT ALARM GOING OFF, CAB A/C INOP,

Parts	Quantity
-------	----------

Task performed:

1. A/C not cooling well in cab; poss refrigerant leak; chkd for leaks; needs additional work. 2. Low coolant alarm goes on sometimes; works ok now; poss defect in senser. j

NO PARTS USED

Workorder: V16914

In Date: 08/08/2008
Close Date: 08/14/2008

Meter Reading:

Problem?

both left rear tires leaking air R-41

Parts	Quantity
-------	----------

Task performed:

Rem air monitor sys from tires & refilled tires. j

NO PARTS USED

Workorder: V16925

In Date: 08/08/2008
Close Date: 08/14/2008

Meter Reading:

Problem?

Rubber seal detached in back window that seperates cab from passanger compartment. R-41

Parts	Quantity
-------	----------

Task performed:

Rep rubber seal around rear cab window. j

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V17196

In Date: 08/21/2008 **Meter Reading:** 275.00
Close Date: 08/22/2008

Problem?

R41 Quick release on SCBA brackets malfunctioning(all seats).

<u>Parts</u>	<u>Quantity</u>
--------------	-----------------

Task performed:

1. Adjust air pack bracket on seats. 2. Installed the boot betwn cap & back compartment. j

NO PARTS USED

Workorder: V17779

In Date: 09/17/2008 **Meter Reading:** 408.00
Close Date: 09/29/2008

Problem?

R41 has fluids leaking from the engine. A/C in R41 not working properly

<u>Parts</u>	<u>Quantity</u>
--------------	-----------------

Task performed:

check leak -fuel leak- E-1 repaired

NO PARTS USED

Workorder: V17659

In Date: 09/12/2008 **Meter Reading:** 5,352.00
Close Date: 09/30/2008

Problem?

TIRE MONITOR READS LOW PRESSURE R41

<u>Parts</u>	<u>Quantity</u>
--------------	-----------------

Task performed:

Refilled all tires and tested. Repaired seal for cab and body.

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V18615

In Date: 10/27/2008
Close Date: 11/18/2008

Meter Reading:

Problem?

L. front air grill on R41 located on hood is missing two screws. (loose with rattaling noise)

Parts	Quantity
-------	----------

5-20PH1PGK4 CONNECTOR 120V 20A FEMALE	4
---------------------------------------	---

Task performed:

1. Grill falling out; replc grill. 2. 110 A/C inop; replc 110 outlet plug. j

Workorder: V18881

In Date: 11/06/2008
Close Date: 11/18/2008

Meter Reading: 8,004.00

Problem?

repair brake lt e41

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

Reprogrammed left rear brake light. j

Workorder: V19068

In Date: 11/14/2008
Close Date: 12/01/2008

Meter Reading: 8,501.00

Problem?

repair rear step r41

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

Rep rear step that was falling off. j



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V19418

In Date: 12/01/2008
Close Date: 12/02/2008

Meter Reading: 9,660.00

Problem?

SIREN AND HORN INOP, R-41

Task performed:

Siren/horn button flex plate not returning to neutral position; rem & temporarily rep; parts need to be replaced. j

Parts

Quantity

NO PARTS USED

Workorder: V19761

In Date: 12/15/2008
Close Date: 12/24/2008

Meter Reading: 10,443.00

Problem?

c inspection and repairs as needed r41

Task performed:

C-Inspection. 2. Reinstall diesel tank emblem; rem old glue. 3. Rem waste/sharps draw lid; diss frame asy; rem brkn pieces of old lid; mod new lid & reassemble. 4. Replc wiper refills. 5. Rep cab; rear A/C register (vent) holding clip & reinstall on A/C hsng. 6. Cln tar type substance frm btry cables (btry term, btry post, etc.). 7. Rear under truck light frame bent up & light brkn; rem frame & straighten out to except new light fixture. 8. Change out Zerk fittings on several suspension components; (cld not attach grease gun w/straight type Zerks). 9. Redesign mntng brkts on crew seats w/air bottle brkts holders; install new pull cables & make all adjustments. 10. Stretcher bar holding brkt still loose after warrantee people made repair; rem brkt & mk adjustments in floor plate; reinstall & tighten. 11. Chk out frnt cab dash A/C sys; send to International for repairs. j

Parts

Quantity

1045-257-101SEAT CONTROL CABLE RIGHT 51 IN	2
1500900017000USE 9 X 14 FILTER	3
15W40BSYN OIL BULK QTS	28
1873910C91FUEL STRAINER HORTON	1
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
2FC00ZCR4 IN ROUND LED	1
46870AIR FILTER	1
5774457744XD OIL FILTER	1
78R539018-2699 A/C FILTER	1
91-22WIPER BLADE	2
DOOR6RED HAZ DOOR	2



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V19472

In Date: 12/03/2008
Close Date: 01/05/2009

Meter Reading: 9,660.00

Problem?

auto eject 10-7 r41

Parts	Quantity
-------	----------

Task performed:

1. Auto-eject inop; fnd wire off on unit; rep/tested. 2. Rear step falling off; rep rear step; redrilled/installed new screws. 3. Rear right side backup ligh inop; rep bad connection. j

NO PARTS USED

Workorder: V19652

In Date: 12/10/2008
Close Date: 01/05/2009

Meter Reading: 10,068.00

Problem?

rear led lights 10-7 r41

Parts	Quantity
-------	----------

Task performed:

No rear emergency light; fnd bad connection on rear panel. j

NO PARTS USED

Workorder: V19911

In Date: 12/22/2008
Close Date: 01/15/2009

Meter Reading: 10,443.00

Problem?

REPLACE ALL 6 TIRES, R-41

Parts	Quantity
-------	----------

Task performed:

Replace all (6) tires R41 - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V20585

In Date: 01/26/2009 Meter Reading: 263.40
Close Date: 01/27/2009

Problem?

NO POWER TO REAR OF VEHICLE, R-41

Parts	Quantity
-------	----------

Task performed:

No power to rear; fnd bad connection on rear relay. j

NO PARTS USED

Workorder: V20421

In Date: 01/17/2009 Meter Reading: 854.00
Close Date: 01/28/2009

Problem?

horn sticking on again...took it apart and its stopped for now R-41

Parts	Quantity
-------	----------

Task performed:

1- horn button assy damage, field repaired horn to keep from sticking.
need no parts.

NO PARTS USED

Workorder: V20423

In Date: 01/17/2009 Meter Reading: 854.00
Close Date: 01/28/2009

Problem?

LEFT REAR TURNING SIGNALS (YELLOW TURNING ARROW AND RED LIGHT ON LEFT BACK SIDE OF VEHICLE) ARE NOT WORKING. R-41

Parts	Quantity
-------	----------

Task performed:

1- turn signals inop, found fuse missing from fuse plnel. 2- rear privated glass inop, found no problem whit glass.

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V20361

In Date: 01/14/2009
Close Date: 01/29/2009

Meter Reading: 854.00

Problem?

Fuse came out of passenger dash, unknown which socket is goes in. R41

Parts	Quantity
-------	----------

Task performed:

1- Air bottle holders are loose, readjusted all air bottle holders. 2- Rear load lights out, repaired relay.

NO PARTS USED

Workorder: V20697

In Date: 01/29/2009
Close Date: 02/12/2009

Meter Reading: 13,059.00

Problem?

rear folding step fasteners coming off R41

Parts	Quantity
-------	----------

Task performed:

1- installed new bolts in rear step, that was falling out.

NO PARTS USED

Workorder: V16953

In Date: 08/10/2008
Close Date: 03/06/2009

Meter Reading:

Problem?

The connecting window in between front and back cabs on rescue truck is broken and leaking water. R41

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V17850

In Date: 09/22/2008
Close Date: 03/09/2009

Meter Reading: 5,905.00

Problem?

FUEL LEAK, BELLOW HAS HOLES, A/C IN CAB INOP, PAT. A/C BLOWS HOT, RADIO MIC KEYS UP ON ITS OWN, PRIVACY WINDOWS COME ON & OFF GOING OVER BUMPS, AUTOMATIC DOOR LOCKS INOP, FUEL FILL TAG FELL OFF,

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED

Workorder: V20444

In Date: 01/18/2009
Close Date: 03/10/2009

Meter Reading: 854.00

Problem?

Rubber cover for horn on steering wheel has come off, horn and siren activates on its own, with out any pressure. metal switch plate is exposed.
R-41

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED

Workorder: V21510

In Date: 03/03/2009
Close Date: 03/23/2009

Meter Reading: 15,310.00

Problem?

Install long stretcher release rod R41

Parts	Quantity
-------	----------

Task performed:

Drive to Stn; install long rod end on base end. j

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V21863

In Date: 03/17/2009
Close Date: 03/23/2009

Meter Reading: 16,691.00

Problem?

repair cb a/c r41

Parts	Quantity
-------	----------

Task performed:

1. Cab A/C inop; recharged A/C & tested. 2. Rep cab hand rails that were loose on cab. j

NO PARTS USED

Workorder: V21630

In Date: 03/08/2009
Close Date: 03/26/2009

Meter Reading: 1,122.00

Problem?

pin fail alarm R-41

Parts	Quantity
-------	----------

Task performed:

Chkd for pin fail & alarm; all rtested ok. j

NO PARTS USED

Workorder: V22923

In Date: 04/29/2009
Close Date: 05/04/2009

Meter Reading: 18,769.00

Problem?

A inspection R-41

Parts	Quantity
-------	----------

Task performed:

A-Inspection j

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V22175

In Date: 03/30/2009
Close Date: 05/05/2009

Meter Reading: 1,273.00

Problem?

alarm going off after truck sits for aprox 2 hrs then goes off once truck warms(about 2 mins run time)unable to talk well with crew during response due to alarm going off R41

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

1. Road tested truck & fnd no alarms going off. 2. Air leak; rep air leak at air seat. 3. A/C inop; recharged rear A/C. j

Workorder: V22680

In Date: 04/20/2009
Close Date: 05/07/2009

Meter Reading: 18,190.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED R41

Parts	Quantity
-------	----------

1094KIT-AIR HORN-GROVER	1
15W40BSYN OIL BULK QTS	24
1873910C91FUEL STRAINER HORTON	1
1878042C91FUEL FILTER 2008 HORTON	1
5774457744XD OIL FILTER	1

Task performed:

1. Cln shop floor walkway per Tim Calhoun. 2. Svc btrys. 3. B-Inspection 4. Comp Time 5. B-Inspection 6. Ck frt A/C for proper charge & pressures. 7. Rem rear brkts from u-bolts & torque to specs; reinstall brkts torque frt u-bolts. 8. Press ck cooling sys & dia leak; fnd leak at clamp behind turbo to be rep by International. 9. Air tires & tighten loose R-rear inside valve stem. 10. Ck problem with L-rear turn signal/flasher; fnd bad connection at fuse box. 11. Install air horn kit left side & adj air horns. 12. Assist Jeff w/retorquing u-bolts. j



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V22913

In Date: 04/29/2009 Meter Reading: 18,769.00
Close Date: 05/13/2009

Problem?

Adjust fast Idle on R41 (outside agency-Reichtien International)

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED

Vendor? RECHTIEN

Workorder: V24799

In Date: 07/15/2009 Meter Reading: 22,961.00
Close Date: 07/30/2009

Problem?

REPLACE TIRES AT 41 CALLAGHAN

Parts	Quantity
-------	----------

Task performed:

replace tires at Stn41 - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V24792

In Date: 07/15/2009 Meter Reading: 22,961.00
Close Date: 08/19/2009

Problem?

replace stretcher lock r41

Parts	Quantity
-------	----------

Task performed:

R/R adj stretcher lock. REPLACED LOCK WITH A "DNI" LOCK... j

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V25646

In Date: 08/19/2009

Meter Reading: 25,347.00

Close Date: 09/30/2009

Problem?

REPLACE LONG STRECHER RELEASE, R-41

Parts

Quantity

Task performed:

1. installed new stretcher latch in rear. 2. A/C inop; recharged unit. 3. AM/FM radio inop; replcd fuses. j

0567042LONG STRECHER BAR

1



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V26276

In Date: 09/15/2009

Meter Reading: 26,282.00

Close Date: 10/02/2009

Problem?

C INSPECTION AND REPAIRS AS NEEDED R41

Task performed:

C-Inspection 2. Svc trans. 3. Svc diff 4. Pulls to the right; rotate frnt tires. 5. Svc pat compt A/C filters-dirty. 6. wipers worn; replc wipers & installed washer fluid. 7. Diff torque arm loose; tightened torque arm. 8. L/S step loose; bolt msng; installed new bolt & tightened others. 9. Svc P/S. 10. Svc air dryer/purge valve. 11. R/R/I flat; valve stem loose; rem tire; fnd leak; tightened valve stem. 12. Rear brakes worn; replcd rear brakes/drums. 13. Door open warning inop; braker tripped; reset brkr & chkd wiring; working ok. 14. Replc belts. 15. Cab A/C poor cooling; A/C sys wired in series w/ rear evap; chk for leaks & A/C cycling off of rear evap; sent to dealer. 16. Rear door panels loose; svc all doors & panels. j

Parts

Quantity

065624AD-IP DRIER	1
1501450007750USE 0775145	3
15W40QSYN OIL QT	28
1847727C1BELT	1
1873910C91FUEL STRAINER HORTON	1
1878042C91FUEL FILTER 2008 HORTON	1
29526898 29548988 TRANS FILTER ALLISON	2
3757REAR DRUMS 3757X 3647X	2
46870AIR FILTER	1
5011387O RING KIT AD-IP	1
5774457744XD OIL FILTER	1
75W90GEAR OIL SYN QT	12
91-22WIPER BLADE	2
K022105PURGE VALVE AD-IP-IS	1
K060695BELT	1
TRANSYNDALLISON TRANS FLUID GAL	5
VML/T1808D2503221C1 FILTER POWER STEERING	1
XX4034707QPMHD SHOE KIT 3/8 BEAM	2



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V25683

In Date: 08/21/2009
Close Date: 10/08/2009

Meter Reading:

Problem?

Driver side step rail has a screw missing. R41

Parts	Quantity
-------	----------

Task performed:
rep all missing screws. j

NO PARTS USED

Workorder: V26537

In Date: 09/29/2009
Close Date: 10/15/2009

Meter Reading: 26,282.00

Problem?

replace 1 tire R41 (outside agency-callaghan tire)

Parts	Quantity
-------	----------

Task performed:
Replace (1) tire R41 - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V27062

In Date: 10/21/2009
Close Date: 11/05/2009

Meter Reading: 26,282.00

Problem?

NO START - ENGINE MAKES LOUD NOISE

Parts	Quantity
-------	----------

Task performed:
travel to stn - not; lost fuel primer; started eng; did not find a problem w/fuel sys. j

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V26625

In Date: 10/01/2009
Close Date: 11/16/2009

Meter Reading: 78,280.00

Problem?

repair a/c rechtein r41

Parts	Quantity
-------	----------

Task performed:

Repair A/C R41 - Rechtein j

NO PARTS USED

Vendor? RECHTIEN

Workorder: V28066

In Date: 12/02/2009
Close Date: 01/14/2010

Meter Reading: 2,151.00

Problem?

Door hinge shock absorber in driver compartment is broken on one of the ends. r41

Parts	Quantity
-------	----------

Task performed:

Rep door hinge on L-1 compt. j

101281021GSS1917UY 90# STRUT-LIFT	1
EAA-8350-30UGSS1783UQ STRUT-LIFT	1
GSS1729UWHOLD OPEN STRUT 60LB	1
HLD39914GSS7139UK STRUT 90#	1

Workorder: V29354

In Date: 01/22/2010
Close Date: 02/10/2010

Meter Reading: 33,290.00

Problem?

stuck in grass R41A (on-call)

Parts	Quantity
-------	----------

Task performed:

Stuck in grass; Pulled R41 out of grass. j

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V29429

In Date: 01/25/2010
Close Date: 02/12/2010

Meter Reading: 33,290.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED R41

Task performed:

B-Service. 2. Pump down & charge A/C to right press in sys. 3. Install new cap & top off coolant; press chk sys. 4. Torque all lugs & set air press to right press. 5. R/R frnt brakes/drums/hardware; reinstalled; ajd brakes; road test. 6. Installed new screw in light side, step msgng. 7. C/O code in display in center console; fnd window ____ out; Hallmark will be here to repair on 1/29/10. 8. Complete all work & test drive for brakes. j

Parts	Quantity
12105QUICK DRAIN	1
15W40BSYN OIL BULK QTS	30
1873910C91FUEL STRAINER HORTON	1
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
3753BRAKE DRUM RUMPER FRONT	2
5774457744XD OIL FILTER	1
F6DZ-8100-A9C3Z8101B RADIATOR CAP 10238 STAI	1
KSMA2124703QFRONTBRAKE KIT RUMPER AND 4D	2

Workorder: V28582

In Date: 12/26/2009
Close Date: 02/17/2010

Meter Reading:

Problem?

Right scene light is out (light nearest patient compartment side door R41

Task performed:

Rep right side scene light. j

Parts	Quantity
NO PARTS USED	



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V28278

In Date: 12/11/2009 Meter Reading: 2,151.00
 Close Date: 02/22/2010

Problem?

We need replacement for the center console partitions because they are damage beyond repair. R41

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

Air leaks; fnd fitting on tank leaking. j

Workorder: V28584

In Date: 12/26/2009 Meter Reading:
 Close Date: 02/22/2010

Problem?

The rt scene light near the side entrance door is out. R41

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

Rep connection in rear scene light. j

Workorder: V28907

In Date: 01/07/2010 Meter Reading: 2,382.00
 Close Date: 02/22/2010

Problem?

Rear drop down step came loose on one side. Missing screws. Sirens go off on their own. have a weird sound to them. Horn honks on its own when master is off.

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

rep rear step that was falling out. j



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V29062

In Date: 01/13/2010 Meter Reading: 32,650.00
Close Date: 03/19/2010

Problem?

REPLACE HORN BUTTON R41A

Task performed:
Replcd horn bottom & tested. j

Parts	Quantity
3616382C1HORN PAD NAVISTAR	1
FREIGHTSHIPPING CHARGES	7

Workorder: V29701

In Date: 02/04/2010 Meter Reading: 33,683.00
Close Date: 03/19/2010

Problem?

Front driver headlight out R41

Task performed:
1. Replc headlight. 2. Rep stretcher latch j

Parts	Quantity
NO PARTS USED	

Workorder: V31648

In Date: 04/20/2010 Meter Reading: 33,290.00
Close Date: 04/27/2010

Problem?

no emergency lights/ no radio R41A (on-call)

Task performed:
Rep PC board for emergency lites. j

Parts	Quantity
NO PARTS USED	



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V31290

In Date: 04/06/2010
Close Date: 05/01/2010

Meter Reading: 37,618.00

Problem?

unit hard starting r41

Parts	Quantity
-------	----------

Task performed:

Chkd starting & chkd ok; will monitor problem. j

NO PARTS USED

Workorder: V31521

In Date: 04/14/2010
Close Date: 05/01/2010

Meter Reading: 37,618.00

Problem?

Install moulding around screen r41

Parts	Quantity
-------	----------

Task performed:

install molding. j

NO PARTS USED

Workorder: V30508

In Date: 03/06/2010
Close Date: 05/05/2010

Meter Reading: 35,155.00

Problem?

air horn support broken off on driver side of R41

Parts	Quantity
-------	----------

Task performed:

1. O2 alarm going off; rep connection on tank. 2. Air horn brkt brkn; replcd brkt. j

GRV1720244770R1 HORN SUPPORT BRKT	1
MNT587148Z671 ALARM CARBON MONOXIDE	1



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V31567

In Date: 04/15/2010
Close Date: 05/12/2010

Meter Reading: 38,092.00

Problem?

replace tires boulevard tire

Parts	Quantity
-------	----------

Task performed:

Replace tires - Boulevard j

NO PARTS USED

Vendor? BOULEVARD TIRE

Workorder: V31961

In Date: 05/04/2010
Close Date: 05/17/2010

Meter Reading: 39,611.00

Problem?

a/c inop R41

Parts	Quantity
-------	----------

Task performed:

A/C inop; comp lockat TX valve; located parts; sent to dealer for warranty repair. j 2. Traced out problem with A/C; will send to International. j

NO PARTS USED

Workorder: V32161

In Date: 05/12/2010
Close Date: 05/19/2010

Meter Reading: 39,907.00

Problem?

Map light in front cab is damaged R41

Parts	Quantity
-------	----------

Task performed:

Replace brkn map lite. j

LF18TS-LEDMAP LIGHT LED 18 IN	2
-------------------------------	---



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V31763

In Date: 04/24/2010 Meter Reading: 38,544.00
 Close Date: 06/04/2010

Problem?

small compartment on the bumper of r41 will not open

Parts	Quantity
-------	----------

Task performed:

Rep rear door latch on rear of rescue that was hard to open. j

NO PARTS USED

Workorder: V31948

In Date: 05/03/2010 Meter Reading: 39,427.00
 Close Date: 06/04/2010

Problem?

air in front part of rescue not blowing cold. R41

Parts	Quantity
-------	----------

Task performed:

Chkd A/C; fnd A/C compressor bad; sent to shop. j

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V32433

In Date: 05/25/2010
Close Date: 06/10/2010

Meter Reading: 40,826.00

Problem?

C INSPECTION AND REPAIRS AS NEEDED R41

Task performed:

Perform C-Service 2. Replcd cab fresh air filter. 3. Rem flipup step on rear bumper; redrilled/tapped hinge mntng hole one size bigger-stripped/cut; reinstalled w/new hardware & lock tite-red. 4. Replc al (3) rear A/C filters-pat compt. 5. R/R squad bench seat to be sent out for rep-ripped. 6. Secured all door hinge screws in L-2 compt-lose. 7. Reinstalled light rail in R-2 compt. 8. Replcd wiper blades. 9. Drilled out/installed new O2 wrench mntng bolts; drilled out new hoes in O2 wrench & attached new safety cable to wrench. 10. Replcd stretcher lock bar-brkn handle. 11. Replcd dump switch button on rear entry door of pat compt. 12. Svc air brake dryer. 13. Replcd rear axle brake shoes & hardware-worn. 14. T-shoot cab A/C blow war air; recvrd, vac/recharged A/C sys; diss evap case to chk blend door opn; all seems normal. j

Parts	Quantity
03910007SW CAP BLANK	1
0567042LONG STRECHER BAR	1
065624AD-IP DRIER	1
15W40BSYN OIL BULK QTS	30
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
3757REAR DRUMS 3757X 3647X	2
5774457744XD OIL FILTER	1
91-22WIPER BLADE	2
K022105PURGE VALVE AD-IP-IS	1
PH8942FILTER OIL 57182 LFP3729	1
XK4034707QPMHD SHOE KIT 3/8 BEAM	2

Workorder: V32940

In Date: 06/16/2010
Close Date: 06/22/2010

Meter Reading: 40,826.00

Problem?

install seat and qa unit

Task performed:

1. R/R rear ___ seat. 2. Quality check truck. 3. 110V A/C not working; C/O DanHart unit compressor not running; chk voltage to compressor-ok; evac unit & refill sys; retest compressor - Bad. j

Parts	Quantity
10006527WINDOW INVERTOR	1



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V32947

In Date: 06/16/2010 Meter Reading: 40,826.00
Close Date: 06/25/2010

Problem?

window inverter 10-7 R41

Parts	Quantity
-------	----------

Task performed:

Windows dont work; C/O windows for voltage side door window didn't; rea is over 40V; needs window replcd; R/R inverter; rear windows ok; send inverter for warranty; also window inside door. j

NO PARTS USED

Workorder: V33111

In Date: 06/24/2010 Meter Reading: 40,826.00
Close Date: 06/29/2010

Problem?

REPAIR SHORELINE A/C R41

Parts	Quantity
-------	----------

Task performed:

Install 100V A/C compressor; vac sys & charge; test for leaks; ok. j

NO PARTS USED

Workorder: V32750

In Date: 06/08/2010 Meter Reading: 38,092.00
Close Date: 06/30/2010

Problem?

repair seat R41 (central auto trim)

Parts	Quantity
-------	----------

Task performed:

Repair seat R41 - Central Auto j

NO PARTS USED

Vendor? CENTRAL AUTO



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V29240

In Date: 01/19/2010 Meter Reading: 2,434.00
 Close Date: 07/13/2010

Problem?

right front lamp is out, scene light r41

Parts	Quantity
-------	----------

Task performed:

Verified job. j

NO PARTS USED

Workorder: V33185

In Date: 06/28/2010 Meter Reading: 40,826.00
 Close Date: 07/21/2010

Problem?

ON CALL R41 DOOR OPEN LT ON

Parts	Quantity
-------	----------

Task performed:

1. Rear door switch brkn; rep/teted. 2. Coolant light on; fnd low on coolant j

NO PARTS USED

Workorder: V33531

In Date: 07/13/2010 Meter Reading: 41,400.00
 Close Date: 07/22/2010

Problem?

right front amber marker lite broken (near pass door) R41

Parts	Quantity
-------	----------

Task performed:

Replc light on R/frnt fender - brkn off at screw; had one on truck from headliught asy. j

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V33810

In Date: 07/26/2010
Close Date: 07/27/2010

Meter Reading: 42,451.00

Problem?

WONT START R41

Task performed:

1.UNIT CRANKS WILL NOT START HOOK UP LAP TOP CODE FOR LOW VOLTAGE TO ECM. TROUBLESHOOT ELECTRICAL SYSTEM TRACED PROBLEM TO RELAY FOR ECM POWER REPLACE RELAY RUN AND ROAD TEST NPF

Parts	Quantity
3505300C1RELAY	1

Workorder: V34866

In Date: 09/10/2010
Close Date: 10/06/2010

Meter Reading: 44,696.00

Problem?

The vehicle takes an unusually long time getting out of dump mode.. In addition, the seats also take a little time to adjust. R41

Task performed:

Went to 41; Waited for truck; fnd susp dump slow engaged; ran/ck opn; ck ok. j

Parts	Quantity
NO PARTS USED	

Workorder: V31418

In Date: 04/09/2010
Close Date: 10/19/2010

Meter Reading: 38,092.00

Problem?

a/c in front portion of r41 not blowing cold air

Task performed:

Completed j

Parts	Quantity
NO PARTS USED	



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V34517

In Date: 08/25/2010 **Meter Reading:** 43,718.00
Close Date: 10/20/2010

Problem?

the truck is leaning in the back, possible air shocks. rubber boat that is inbetween the drivers cab and passengers cab r41

Parts	Quantity
-------	----------

90054007VALVE AIR SUSP HEIGHT CONTROL	2
FREIGHTSHIPPING CHARGES	9
LML-1102-0023CAB AIR BAG IS4007	2

Task performed:

Tried adjusting ride height; wont stay adjusted; replc one leveling valve; w have to order second one; adj a little better but still second valve replcd. j
Readj air bags & road tested. j 1020/10

Workorder: V35085

In Date: 09/21/2010 **Meter Reading:** 44,696.00
Close Date: 10/20/2010

Problem?

air horn not working, sounds like a donkey r41

Parts	Quantity
-------	----------

1094KIT-AIR HORN-GROVER	2
-------------------------	---

Task performed:

1. Air horn inop; rebuilt air horn & tested. 2. Rep cab boot that was falling off. j

Workorder: V35752

In Date: 10/19/2010 **Meter Reading:** 47,314.00
Close Date: 11/09/2010

Problem?

rescue leaning to one side. R41

Parts	Quantity
-------	----------

NO PARTS USED	
---------------	--

Task performed:

1. Readj air bags & road tested. 2. Rep med compt that was loose. j



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V35500

In Date: 10/08/2010
Close Date: 11/17/2010

Meter Reading: 45,884.00

Problem?

R41 would not start

Task performed:

1. after hours road call, slow starting, load test batterys, found battery weak, r&r batterys. test ok. jab

Parts	Quantity
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	3
HP-31DBATTERY 950CCA HP-31D	3

Workorder: V36196

In Date: 11/04/2010
Close Date: 11/30/2010

Meter Reading: 47,314.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED R41

Task performed:

(1) "B" INSPECTION ON R-41 (2) ADJUST STRETCHER LOCK. (3) CHECK POWER STEERING LEAK. REMOVED AND REPOSITIONED ,TIGHTENED FOUR HOSE CLAMP ON HOSE CONNECTIONS. (5) CHECKED COOLANT LEAK. TIGHTENED ALL HOSE CLAMPS ON COOLANT HOSES. (6) TIGHTENED ALL COMPARTMENT DOOR STRL MOUNTING BOLTS. (7) CLEANED AND LUBE REAR STORAGE DOOR LATCHES. (8) TROUBLE SHOOT REAR FLUORESCENT LIGHT TIMER SWITCH. HALLMARK WILL COME AND SOLVE PROBLEM / ED EHRKE (9) ASSISTED IN TROUBLESHOOTING LIGHT PROBLEM WITH HALLMARK.

Parts	Quantity
15W40BSYN OIL BULK QTS	30
1878042C91FUEL FILTER 2008 HORTON	1
5774457744XD OIL FILTER	1
91-22WIPER BLADE	2



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V33387

In Date: 07/07/2010 Meter Reading: 41,400.00
Close Date: 12/22/2010

Problem?

rattle noise from left rear when driving...poss air bag issue r41

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED

Workorder: V36892

In Date: 12/05/2010 Meter Reading: 50,356.00
Close Date: 01/11/2011

Problem?

Coolant levels and power steering levels are at the minimum. No coolant or power steering fluid available at the station. R41

Parts	Quantity
-------	----------

Task performed:

Dropped off supplies to strn. j

NO PARTS USED

Workorder: V37544

In Date: 01/02/2011 Meter Reading: 52,291.00
Close Date: 02/07/2011

Problem?

right side mirror taped onto truck, top mirror shattered. needs to be fixed, looks like will fall off r41

Parts	Quantity
-------	----------

Task performed:

Replcd mirror w/new one & adjusted. j

3561634C923561634C99 MIRROR ASSY R/H	1
FREIGHTSHIPPING CHARGES	119



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V38262

In Date: 02/03/2011
Close Date: 02/16/2011

Meter Reading: 55,113.00

Problem?

REPLACE ALL TIRES R41

Parts	Quantity
-------	----------

Task performed:

Replace all tires R41 - TCI j

NO PARTS USED

Vendor? TCI



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V38100

In Date: 01/27/2011

Meter Reading: 55,313.00

Close Date: 04/04/2011

Problem?

C INSPECTION AND REPAIRS AS NEEDED R41

Parts

Quantity



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Task performed:

C-Inspection 2. L-2 door striker loose; sec striker & lube door locks. 3. Chk veh codes; cld not chk eng codes; no program in laptop; hunt down laptop & connections. 4. Replc all A/C filter; no filter for cab rear unit; rem/cln filter w/coil clnr & reinstall. 5. R/rear cab door padding fell off; cln area, apply adhesive on padding & sec to door. 6. Drug cabinet latch inop rem, reposition & securely mnt; adj locking mechanism. 7. Comp door panels loose & have msng screws; sec loose screw & install msng screws 8. Maplight 10-7. fnd loose grd wire; cln/sec grd wire. 9. Replc air filter. 10. Add coolant. 11. Rep L/air horn brkt; cut gskt frm inner tube; sec brkt w/lock nut & fender washer. 12. Rear A/C cab register msng; fnd register behind seat; reinstall. 13. Rear brakes - jackup & rem wheels, diss rear brakes; install new brake shoe, hardware & drum. 14. Side privacy window inop; dia window fault. 15. Rear brakes. 16. Replc belts, move A/C idler to new lcn & install larger belt in order for belt to ride on idler pulley correctly. 17. Degrease motor & chk for leaks. 18. Dia P/S leak; fnd leak at splice clamp connection; tightened clamps. 19. tighten door panel screws, rear door handles, tool brkts, SCBA brkt; adj rear door latch. 20. Adj rear brakes. 21. Mk tool for brake adj parking pawl. 22. Dia air leak; fnd leak at rear parking brake valve fitting; rem fitting, cln, apply thread sealer & reinstall; chk/leaks - NG; replc valve. 23. Replc wiper blades, cln/adj washer nozzles. 24. Add P/S fluid. 25. Svc/test btrys - ok; switch btrys enc to end; lengthened neg cable. 26. Add washer fluid. 27. Rep numerous coolant leaks; replc some clamps & cut off banded clamps; tightened othe clamps. 28. Dia veh low on R/rear side; fnd bad level valve & where left lir was replcd w/all thread & cut too long; replc valve & cut rod to proper length; adj height on valves. 29. Rep more air leaks at air bag mini-tank fittings. 30. Brkn strap on one mini-tank for air bag sys; lower plate for access; order part. 31. Dia problem w/pat compt siude window privacy opn; R/R door panel; chkd inverter - ok; jumpered side window to inverter window - works; problem in wiring frm window to inverter. 32. Dia/rep mor air leaks; rep leak a fitting R-frame rail; replc fitting at gov & add splice to lengthen tube; rem dash, chk beh dash & park brake valve. 33. Chk svc max codes - ok. 34. Reattach tire monitor to dash. 35. Fab (2) brkts for rear air bag tank & secure tank; mnt tank to plate & install plate to frame. 36. Readj L/air bag height. 37. Test run veh to get warm; perform inj balance- test ok; perform relative cyl compression; test cyl 1 & 4 21; cyl

1501450007750USE 0775145	2
15W40BSYN OIL BULK QTS	30
1847727C1BELT	1
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
33180021INVERTOR	1
3757REAR DRUMS 3757X 3647X	2
46870AIR FILTER	1
473794C91KN32005/800064 QUICK RELEASE VALVE	1
5774457744XD OIL FILTER	1
72R311018-2640 VENT A/C NEW # 1719	1
90054007VALVE AIR SUSP HEIGHT CONTROL	1
91-22WIPER BLADE	2
ANN-125FUSE LINK	1
FREIGHTSHIPPING CHARGES	50
HAN-1LBEZEL AND HANDLE	1
K060705BELT HORTON	1
XK4034707QPMHD SHOE KIT 3/8 BEAM	2



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

2,3,5 & 6 13. 38. Dia side privacy window inop; fnd msng wire to window disconnected beh ceiling channel; connect/splice wire - tested ok; reinstall all trim works. 39. Install new inverter - charge still not working; start t-shoot elect sys. 40. Continue t-shoot inverter/charger; fnd 125 AMP fuse blown; mntd in center console; replc fuse - C/O ok. j

Workorder: V38914

In Date: 03/02/2011 **Meter Reading:** 55,865.00
Close Date: 04/06/2011

Problem?

Light bar not working properly.Warning system states Mod8 pin2/pin4 fail.
R41

Parts ----- Quantity -----

Task performed:

Rep connection on relay for light bar. j

NO PARTS USED

Workorder: V39889

In Date: 04/13/2011 **Meter Reading:** 58,937.00
Close Date: 04/27/2011

Problem?

REPAIR COOLING SYSTEM RECHTIEN

Parts ----- Quantity -----

Task performed:

Rep cooling system - Rechten j also see wo 39775

NO PARTS USED

Vendor? RECHTIEN



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V40223

In Date: 04/28/2011 **Meter Reading:** 60,205.00
Close Date: 04/28/2011

Problem?

put unit on scales, R-411

Task performed:

1. fill unit up with fuel, put unit on scales with crew (2), l/f 4,410 lbs r/f 4,430 lbs l/r 5,560 lbs r/r 5,100 lbs

Parts	Quantity
4867JB320 UPGRADE ALTERNATOR	1

Workorder: V40312

In Date: 05/02/2011 **Meter Reading:** 60,351.00
Close Date: 05/02/2011

Problem?

front right siren speaker not working on R41 4dr rescue, Sta 41.

Task performed:

SIREN SPEAKER AND LABOR ON W/O#40317

Parts	Quantity
NO PARTS USED	

Workorder: V40317

In Date: 05/02/2011 **Meter Reading:** 60,351.00
Close Date: 05/02/2011

Problem?

r/side siren speaker inop, R-41

Task performed:

1. siren speaker inop, r/side, repalce speaker

Parts	Quantity
NO PARTS USED	



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V39543

In Date: 03/30/2011
Close Date: 05/05/2011

Meter Reading: 58,335.00

Problem?

R41 overheating. sta.41.

Parts	Quantity
-------	----------

Task performed:
Sent to shop. j

NO PARTS USED

Workorder: V39835

In Date: 04/11/2011
Close Date: 05/13/2011

Meter Reading: 58,808.00

Problem?

DRIVER'S SIDE AIRHORN NOT WORKING. ALSO, AN AMBER/YELLOW UPSIDE-DOWN TRIANGLE APPEARED IN THE INSTRUMENT CLUSTER ON DASH. IT WAS ONLY THERE FOR A LITTLE WHILE. IT IS NO LONGER SHOWING UP UPON STARTING THE VEHICLE. Sta.41.

Parts	Quantity
-------	----------

Task performed:
1. Rep air horn valve that was leaking. 2. Chkd for amber light on dash - no codes. j

NO PARTS USED

Workorder: V40415

In Date: 05/04/2011
Close Date: 06/03/2011

Meter Reading: 60,500.00

Problem?

the center boot that connects the cab to the patients compartment is leaking because of a cut on the boot. R41

Parts	Quantity
-------	----------

Task performed:
1. Rep boot for cab & body. 2. Readj rear air bags. j

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V40755

In Date: 05/20/2011 Meter Reading: 61,651.00
 Close Date: 06/09/2011

Problem?

SCBA bracket in L1 are too long which causes improper placement (loose) and damage to the air pack. Sta 41.

Parts	Quantity
-------	----------

Task performed:

Rem air pack & installed smaller bottle holder. j

NO PARTS USED

Workorder: V41001

In Date: 05/31/2011 Meter Reading: 62,722.00
 Close Date: 06/09/2011

Problem?

B INSPECTION AND REPAIRS AS NEEDED R 41

Parts	Quantity
-------	----------

Task performed:

1. B inspection 2. travel to c/shop for parts,, travel back to s/shop 3. r/side middle led light inop, replace lite 4.privacy windows inop, replace all 4 windows 5. service air drier 6. vehicle has an air leak, use soap and water to locate leak, found leaks at the foot valve for the air horns, and also on the wet tank valve, replace fittings and recheck for leaks.

065624AD-IP DRIER	1
10007599WINDOW HORTON	3
15W40QSYN OIL QT	5
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
4DA2545W LAMP	2
50R03ZCRLIGHT LED RED TIR 6	1
5774457744XD OIL FILTER	1
K022105PURGE VALVE AD-IP-IS	1



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V41960

In Date: 07/12/2011 **Meter Reading:** 64,703.00
Close Date: 07/12/2011

Problem?

driver states that vehicle cranks to long before starting, R-41

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

1. let truck cool down and try to start, npf, run truck to normal temp. and try to restart npf, did notice that the driver was not waiting for the glow plug light on dash to go out before cranking engine, told driver to wait for light to go out then start. he will keep a eye out on it and will report any problems.

Workorder: V41542

In Date: 06/22/2011 **Meter Reading:** 63,266.00
Close Date: 07/14/2011

Problem?

Air bags leaking. Warrenty.

Parts	Quantity
-------	----------

GUI1R11216GY1R11216 AIR BAG INT.	2
----------------------------------	---

Task performed:

1. Fnd air bags leaking; R/R both rear air bags; ran/ck opn; ck ok. 2. Assist w/air bags. j

Workorder: V41431

In Date: 06/18/2011 **Meter Reading:** 63,266.00
Close Date: 07/19/2011

Problem?

Possible leak in the truck dump/ airbag R41

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

DROVE TO STATION CHECKED FOR AIR LEAKS FOUND AIR BAGS HAS HOLE SENT TO SHOP AK



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V39775

In Date: 04/07/2011 Meter Reading: 58,335.00
 Close Date: 08/02/2011

Problem?

A INSPECTION BACK FROM RECHTIEN

Parts	Quantity
-------	----------

Task performed:

Inv. cooling system wo 39889

NO PARTS USED

Workorder: V41946

In Date: 07/12/2011 Meter Reading: 64,703.00
 Close Date: 08/08/2011

Problem?

Truck hesitates on start up,Sta 41.

Parts	Quantity
-------	----------

Task performed:

road tested all tested good

NO PARTS USED

Workorder: V42063

In Date: 07/16/2011 Meter Reading: 64,703.00
 Close Date: 08/08/2011

Problem?

Battery seems to be very low on charge making it difficult for truck to crank R41

Parts	Quantity
-------	----------

Task performed:

checked and tested batteries and all tested good air leak found no air leak will monitor

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V42831

In Date: 08/16/2011 Meter Reading: 66,600.00
 Close Date: 08/16/2011

Problem?

Rear a/c inop.

Parts	Quantity
-------	----------

Task performed:
 CLEANED CONDENCER FANS AND ALL TESTED OK

NO PARTS USED

Workorder: V42307

In Date: 07/26/2011 Meter Reading: 65,245.00
 Close Date: 09/06/2011

Problem?

UNIT HAS HARD START NO START R 41

Parts	Quantity
-------	----------

Task performed:
 WARRANTY 1. Truck cranking for 10 sec before firing; perform hard start & no start dia; fnd hi-press oil pump bad. 2. Start rem hi-press oil pump. 3. Finish install of hi-press oil pump; hookup laptop; chk press; all good; clea old codes; test drive truck. j

15W40BSYN OIL BULK QTS	30
1812348C1FUEL LINE SLEEVE INT	2
1882259C931882259C94 HIGH PRESSURE OIL PUMI	1
1893940C911893940C93 OIL LINE HIGH PRESS PUM	1
5774457744XD OIL FILTER	1
CORECORE CHARGE	1



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V42853

In Date: 08/16/2011 **Meter Reading:** 66,600.00
Close Date: 09/12/2011

Problem?

An upside down yellow triangle light in the dash came on, "warn engine" in the read out window. Light went ou and message disappeared t after turning the truck off and restarting later. R41

Parts ----- Quantity -----

Task performed:

found truck low on coolant remounted tools in l1

NO PARTS USED

Workorder: V43113

In Date: 08/29/2011 **Meter Reading:** 67,527.00
Close Date: 09/19/2011

Problem?

The "brake air" alarm (audible and the light on the dash) came on today while leaving the station but went off after approximately 10 seconds. R 41

Parts ----- Quantity -----

Task performed:

checked for air leaks found none at this time

NO PARTS USED

Workorder: V43368

In Date: 09/01/2011 **Meter Reading:** 67,747.00
Close Date: 09/19/2011

Problem?

upside down triangle lit up on dashboard with warn engine display, Sta 41.

Parts ----- Quantity -----

Task performed:

found low on coolant pressure tested

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V43387

In Date: 09/02/2011 Meter Reading: 67,875.00
Close Date: 09/21/2011

Problem?

The right scene light cover is cracked, the front light on the right side of the box. Sta 41.

Parts	Quantity
-------	----------

Task performed:

R/R light cvr on side of rescue with new one; ok at this time. j

NO PARTS USED

Workorder: V42942

In Date: 08/20/2011 Meter Reading: 62,126.00
Close Date: 10/07/2011

Problem?

asset #10175531. left passenger side door has minor white scratch. and right rear backboard door has two black streaks with minor scratch towards the right rear corner on r41

Parts	Quantity
-------	----------

Task performed:

air horn inop adjusted air horns checked rear door waxed out

HDY-H005700SOLENOID HORN AIR	1
------------------------------	---

Workorder: V44069

In Date: 10/01/2011 Meter Reading: 69,784.00
Close Date: 10/07/2011

Problem?

engine warning light is on. E41

Parts	Quantity
-------	----------

Task performed:

traced out problem truck sent to shop no start

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V44575

In Date: 10/20/2011
Close Date: 10/27/2011

Meter Reading: 71,192.00

Problem?

replace body mounts

<u>Parts</u>	<u>Quantity</u>
--------------	-----------------

Task performed:

WARRANTY Body mnt replace; rem 110 A/C condensor & stair chair cabinet; replc worn mnts; reinstall stair chair cabinet & A/C condensor. j

NO PARTS USED

Workorder: V44715

In Date: 10/27/2011
Close Date: 10/28/2011

Meter Reading: 71,420.00

Problem?

ON CALL COOLANT LEAK R 41

<u>Parts</u>	<u>Quantity</u>
--------------	-----------------

Task performed:

Rep leak & road tested j

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V44462

In Date: 10/18/2011

Meter Reading: 71,302.00

Close Date: 11/14/2011

Problem?

C INSPECTION AND REPAIRS AS NEEDED R 41

Parts

Quantity



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Task performed:

C-Inspection 2. Cln btry term & grnd(chassis); rechk volt on full load; volt 13.9V. 3. Btry tray hard to open; cln sliders & lube. 4. L/side outside time valve stem leaking; secure loose valve stem core & air tire to 110 PSI. 5. Diff fluid low - no leaks visable; top off fluid level; diff breather tube loose; secure breather tube to chk valve breathing asy. 6. Coolant leak at oil cooler; rem factory clamp & install new clamp. 7. Oil leak at turbo supply line; cln area, secure line. 8. Drvr /pass side t-signal asy brkn; rem asy & install new T-signal asy. 9. Cab 4-door switch cvr bolt msgng or damaged; rem switch & install new switch & bolt. 10. Pass side air horn holder falling off; rem horn & resecure horn support brkt; remnt horn. 11. Install heater coolant shutoff valve; coolant level low; add coolant. 12. Dashboard custe molding loose; fnd holddown clips bent; rem/straighten out clips & reassem. 13. Fuse box cvr officers side unsecure; rem/relocate holddown spring clip & reassem. 14. Eng compt insulation falling off; cln area & use dble-sided tape to secure foam molding. 15. Dia 110 A/C failure; fnd dble "A" btry for cntrl panel dead/corroding; rem btry, cln holder, install new btry; sys operating normal. 16. Side ____ lights 10-7; fnd light asy burnt out; rem asy & install new lighting asy. 17. Cab rear A/C vent louvre msg; install replacement part. 18. Cab rear A/C filter svc. 19. Coolant leak at reservoir tank loose; replc weak hose clamp. 20. Top rad hose collapsng weak hose coil spring; rem hose & install new hose w/coil spring. 21. Secure loose door panels. 22. L-1 cvr plate loose; secure cvr plate. 23. SCBA in L-2 loose secure unit. 24. L/rear SCBA door damage has sharp edges; grind down & smooth polish sharp edge away. 25. Officers door panel loose; secure door panel. 26. Cab fire extinguisher low on charge; replc extinguisher & mnt. 27. R-2 compt rope light hanging; sec mntng brk & secureloose rope light into holder. 28. Module box r/rear molding falling off; rem, cln mntng surface & rubber; apply silicone adhesive & install rubber. 29. P/S filter & fluid svc. 30. Laptop stn loose; secure loose holddown/swivel points. 31. Pat compt side door step needs non-skid strip cln/install non-skid strip to steps. 32. Electronic cabinet lights out; replc blown bulb. 33. Pat compt A/C filter - cut/install filter material. 34. Frnt A/C oil stain at dryer fitting; chk press, chk/leaks; press normal-no leak fnd; cln off fitting/area; chk discharge temp 6 degrees. 35. Quality check - J. George. j

10007150CURB LIGHT HORTON	1
1003INTERIOR DOME BULB	1
15W40BSYN OIL BULK QTS	30
1878042C91FUEL FILTER 2008 HORTON	2
19282TAPE ANTI-SLIP PER FT 60FT ON ROLL	4
2506656C124316 WIX CAB A/C FILTER	1
2507061C1PS RESV GASKET	1
330-3024HUB COVER GASKET	1
3561965C1LIGHT	1
3561966C1LAMP	1
3579984C1DOOR SWITCH	4
3610318C2RADIATOR HOSE	1
388863HOSE KIT	2
5774457744XD OIL FILTER	1
72R311018-2640 VENT A/C NEW # 1719	1
75W90GEAR OIL SYN QT	2
78R539018-2699 A/C FILTER	1
VML/T1808D2503221C1 FILTER POWER STEERING	1



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V44892

In Date: 11/02/2011 Meter Reading:
Close Date: 11/14/2011

Problem?

The unit is leaking coolant. After being filled yesterday, the fluid level is below the "ADD" mark. Sta 41

Parts ----- Quantity -----

Task performed:

1. Fnd hose leaking - rep. 2. Rep stretcher latch & tested. j

NO PARTS USED

Workorder: V45117

In Date: 11/12/2011 Meter Reading:
Close Date: 12/02/2011

Problem?

driver side rear scba door hard to open and close. some damage noted to door rim R 41

Parts ----- Quantity -----

Task performed:

repaired door on side

NO PARTS USED

Workorder: V45204

In Date: 11/15/2011 Meter Reading:
Close Date: 12/02/2011

Problem?

The power door lock/ unlock button located in the cab of the truck is working intermitently. R41

Parts ----- Quantity -----

Task performed:

repaired door locks and tested

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V45284

In Date: 11/18/2011
Close Date: 12/02/2011

Meter Reading:

Problem?

locking mechanism for stretcher is extrememly difficult to lock.stretcher Has to be forcefully slammed in to lock

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

replaced latch on strecher

Workorder: V45384

In Date: 11/23/2011
Close Date: 12/02/2011

Meter Reading: 73,831.00

Problem?

No start, sta 41

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

recharged battery

Workorder: V45588

In Date: 12/02/2011
Close Date: 12/02/2011

Meter Reading:

Problem?

locking mechanism for stretcher is extrememly difficult to lock.stretcher Has to be forcefully slammed in to lock

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

duplicate for 45284 disregard



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V45443

In Date: 11/27/2011
Close Date: 12/12/2011

Meter Reading:

Problem?

Truck has an engine warn light that comes on intermittently. Truck also has a wierd shake that feels like it is coming possibly from the drivetrain as it accelerates above 40 mph R41

Parts	Quantity
-------	----------

Task performed:

road tested and found no problem with shake in front end engine light on found lo coolant

NO PARTS USED

Workorder: V45768

In Date: 12/09/2011
Close Date: 12/12/2011

Meter Reading: 75,284.00

Problem?

MDT stand broken

Parts	Quantity
-------	----------

Task performed:

REPLACED BROKEN STAND.

NO PARTS USED

Workorder: V45579

In Date: 12/02/2011
Close Date: 12/16/2011

Meter Reading:

Problem?

Adding water to the coolant resevoir per the shop today. Sta41

Parts	Quantity
-------	----------

Task performed:

PRESSURE TESTED UNIT FOUND NO LEAKS AT THIS TIME.

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V46357

In Date: 01/05/2012
Close Date: 01/09/2012

Meter Reading: 77,974.00

Problem?

REPLACE TIRES R 41

Parts	Quantity
-------	----------

Task performed:

REPLACE TIRES R41

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE

Workorder: V46403

In Date: 01/08/2012
Close Date: 01/10/2012

Meter Reading: 77,911.00

Problem?

Low coolant level, Sta 41

Parts	Quantity
-------	----------

Task performed:

PRESSURE TEST COOLING SYSTEM NO LEAK AT THIS TIME.
TIGHTEN EGR COOLER CLAMP. GAVE THEN 2 GALLONS COLLANT.
CHECK AIR HORNS R/SIDE NEED SOLENOID.

NO PARTS USED

Workorder: V45917

In Date: 12/17/2011
Close Date: 01/13/2012

Meter Reading: 75,923.00

Problem?

back up camera not engaging. Black screen. Sta 41

Parts	Quantity
-------	----------

Task performed:

REPAIRED BAD CONNECTION ON BACK-UP CAMERA.

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V46535

In Date: 01/12/2012

Meter Reading: 78,280.00

Close Date: 01/27/2012

Problem?

I PUT APPROX A 1/2 GALLON OF COOLANT INTO THE RESERVOIR. IT SEEMS TO BE A CONSTANT PROBLEM/ISSUE. NO CHECK ENGINE LIGHTS ARE GOING OFF. Sta 41

Parts

Quantity

Task performed:

REPLACE WATER PUMP/LEAKING/REPLACED/WATER PUMP.

1842665C93WATER PUMP DT570

1



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V46551

In Date: 01/12/2012

Meter Reading: 78,280.00

Close Date: 01/31/2012

Problem?

B INSPECTION AND REPAIRS R 41

Task performed:

1. B-INSPECTION. 2. L/F AND R/R/I VALUE CORES/LEAKING/AIRED ALL TIRES. COULD NOT GET R/R/I TO STOP LEAKING. WILL CALL TIRE SERVICE. 3. COOLANT LEAKS/BAD HOSES AND DEFECTIVE CRIMPON CLAMPS/REPLACED DEFECTIVE CLAMPS AND HOSES REPAIRED ALL LEAKS. 4. OIL LEAK R/S ENG/BREATHER O-RINGS/REPLACED BREATHER O-RINGS. 5. AIR LEAKS/MULTIPLE LEAKS/REPLACED SUSPENSION AND CAB LEVELING VALVES ALSO RE-CONNECTED SEVERAL FILLINGS IN DASH. ROAD TEST AND ADJUSTED SUSPENSION. 6. REPLACE REAR BRAKES/WORKS/REPLACED REAR BRAKES. 7. LEATHER STRIP/LOOSE/SECURED LEATHER STRIP. 8. FRESH AIR DOOR INOP/MOTOR DAMAGED/REPLACED FRESH AIR MOTOR. 9. TIRE PRESSURE MONITOR/INACCURATE/INSTALLED LED TYPE ON EACH TIRE. ALSO INSTALLED BRAIDED STEEL EXTENDERS. ALSO REPAIRED LEAKS AND VALVE CORES. 10. SERVICE BATTERY TRAY/WON'T PULL OUT/ SERVICED BATTERY TRAY. 11. DOOR LOCKS INOP/BAD CONNECTION AT SWITCH/UNPLUGGED HARNES AT DRIVERS CONTROL REINSTALL DOOR LOCKS. ARE WORKING PROPERLY. 12. REPLACE STEERING WHEEL/WORN/REPLACED STEERING WHEEL. 13. SWAP OUT SCBA BRACKETS.

Parts

Quantity

1875880C2SEAL	1
1876922C91SEAL KIT	1
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
3542606C12611234C1 VENT ACTUATOR	1
3546230C93STEERING WHEEL INT.	1
3616382C1HORN PAD NAVISTAR	1
3757REAR DRUMS 3757X 3647X	2
440-1440-1 VALVE EXTENTION	2
440-33-11/16 VALVE EXT	2
5774457744XD OIL FILTER	1
90054007VALVE AIR SUSP HEIGHT CONTROL	2
AMH-1AMH-1 VALVE EXTENSION	2
FHLP-6TANK CLIP	2
RWTG1234LED PRESSURE CAP	6
S775COUPLER	1
XK4034707QPMHD SHOE KIT 3/8 BEAM	2



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V47590

In Date: 02/27/2012 Meter Reading: 80,225.00
 Close Date: 03/02/2012

Problem?

ON CALL WONT START R 41

Parts	Quantity
-------	----------

Task performed:

TRAVEL TO BETHESDA HOSPITAL DIAGNOSE NO START. WAIT ON TOW TRUCK. TRAVEL TO SHOP TO SWAP OUT.

NO PARTS USED

Workorder: V47715

In Date: 03/02/2012 Meter Reading: 80,401.00
 Close Date: 03/07/2012

Problem?

R41 not running right. R41 has spuddering movement from the engine compartment but no codes showing. Sta 41

Parts	Quantity
-------	----------

Task performed:

SENT UNIT TO SHOP/

NO PARTS USED

Workorder: V48148

In Date: 03/23/2012 Meter Reading: 80,146.00
 Close Date: 03/26/2012

Problem?

Check repairs from International

Parts	Quantity
-------	----------

Task performed:

TEST DROVE CHECK FOR LEAKS - CHECK OK. CHECK LEVELS - CHECK OK.

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V47597

In Date: 02/27/2012
Close Date: 03/28/2012

Meter Reading: 80,225.00

Problem?

UNIT HAS HARD START NO START R 41

Task performed:

1. AIR UP TANKS TOW IN FROM LOT. 2. PERFORM PIN POINT TESTING OF HIGH PRESSURE OIL SYSTEM H/P PUMP HAS NO PRESSURE. 3. PULLED TRUCK IN FROM LOT. 4. INSTALL H/P OIL PUMP AND REMOVE VALVE COVER TO INSPECT FOR O-RING LEAKING AND REINSTALL TAKE ON LONG TEST DRIVE.

Parts	Quantity
091-3YWCOVER KUSSMAUL AUTO EJECT	1
1812348C1FUEL LINE SLEEVE INT	3
1882259C931882259C94 HIGH PRESSURE OIL PUMI	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	3
CORECORE CHARGE	1
HP-31DBATTERY 950CCA HP-31D	3

Workorder: V48332

In Date: 04/01/2012
Close Date: 04/16/2012

Meter Reading: 81,358.00

Problem?

ONE OF THE COOLERS IS DRIPPING OIL A LITTLE BIT. FLUID IS YELLOW. POSSIBLY POWER STEERING COOLER? NOT A LOT, BUT IT IS. R 41

Task performed:

REPAIRED COOLING LINES THAT WERE LEAKING.

Parts	Quantity
NO PARTS USED	



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V48512

In Date: 04/07/2012 Meter Reading: 81,918.00
Close Date: 04/20/2012

Problem?

Truck is leaking fluid possibly oil and transmission fluid.

Parts	Quantity
-------	----------

Task performed:
REPAIRED FITTING ON TRANS COOLER.

NO PARTS USED

Workorder: V48513

In Date: 04/07/2012 Meter Reading: 81,918.00
Close Date: 04/20/2012

Problem?

Driver side passenger step is loose, the latches are not closing all the way leaving the step loose and shaky.

Parts	Quantity
-------	----------

Task performed:
REPAIRED STEP THAT WAS BROKEN.

NO PARTS USED

Workorder: V48673

In Date: 04/14/2012 Meter Reading: 82,372.00
Close Date: 04/20/2012

Problem?

battery compartment doesnt lock

Parts	Quantity
-------	----------

Task performed:
REPAIRED COMPARTMENT.

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V48693

In Date: 04/16/2012
Close Date: 04/20/2012

Meter Reading: 82,372.00

Problem?

no battery power

Parts	Quantity
-------	----------

Task performed:
REPLACED BATTERY SWITCH.

51-30219-1045 MASTER SWITCH 175 AMP	1
-------------------------------------	---

Workorder: V49091

In Date: 05/03/2012
Close Date: 05/11/2012

Meter Reading: 4,321.00

Problem?

Check engine light is frequently turning on, and off. Therefore an inspection is being requested for the vehicle.

Parts	Quantity
-------	----------

Task performed:
FOUND LOW ON COOLANT, CHECKED FOR LEAKS.

NO PARTS USED

Workorder: V48672

In Date: 04/14/2012
Close Date: 05/14/2012

Meter Reading: 82,372.00

Problem?

left front scene light is out.

Parts	Quantity
-------	----------

Task performed:
REPLACED BULB AND REPAIRED SHORT.

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V49261

In Date: 05/11/2012
Close Date: 05/18/2012

Meter Reading: 84,261.00

Problem?

DRIVER'S SIDE, STEP-SIDE PANEL IS LOOSE. A SCREW IS MISSING FROM THE ALUMINUM CASE THAT SURROUNDS THE BATTERIES AN IT IS LOOSE/RATTLES.

Parts	Quantity
-------	----------

Task performed:

REPAIRED SIDE STEP AND REPAIRED SLIDE OUT TRAY.

NO PARTS USED

Workorder: V49542

In Date: 05/22/2012
Close Date: 06/14/2012

Meter Reading:

Problem?

Battery steps on driver side broken , 2 latches on top are broken and battery tray no locking in place. R41

Parts	Quantity
-------	----------

Task performed:

1. check battery tray, found broken drill and install bolts to hold tray in the closed position untill new tray is ordered. replace 1 broken battery tray door latch. (2 were broken only had 1 in stock) * repairs were made on w/o#49931

02841108BATTERY TRAY KWIKEE	1
252189LATCH TRIGGER W/LOCK	2



9/26/2016

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V50263

In Date: 06/20/2012

Close Date: 06/21/2012

Meter Reading: 86,322.00

Problem?

FAN CLUTCH LEAKING

Task performed:

FOUND FAN CLUTCH LEAKING - REMOVED FAN AND CLUTCH ASSEMBLY REPLACED CLUTCH - REASSEMBLED AND CHECK FOR LEAKS CHECK OK.

Parts

Quantity

HOR994972FAN CLUTCH INT. 3611885C93

1



9/26/2016

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V49931

In Date: 06/06/2012

Close Date: 06/26/2012

Meter Reading: 86,322.00

Problem?

C INSPECTION R41

Parts

Quantity



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Task performed:

1. C service and inspection. 2. "C" continue. 3. Found battery tray broken - removed cables, batteries, air tanks and tray assembly. 4. Battery tray continue, replaced tray - reinstalled battery cables, and air tanks - rerouted battery cables - lubed slides. 5. Service air dryer - removed purge valve and filter. 6. Service air dryer continue - replaced purge valve and filter. 7. Found battery cover latches broken - R&R 2 latches - adjusted all latches - found left step assembly loose and missing bolt - removed fender - replaced bolt - tighten step. 8. Repair step continue - installed fender. 9. Found oil b reather leaking - found tube clamps loose - tightened clamps - cleaned area - checked ok. 10. Found EGR hose leaking - drained radiator - cut and removed EGR tube hoses to remove - disassembled tube assembly - replaced hoses and o-ring - reassembled - filled rod - check for leaks - check ok. R&R rad. cap. 11. Found flow - lts switch assembly broken on rear door. - removed switch assembly - removed sw panel tags and installed - set switches - found flo-timer inop. 12. Replace side door grip tape - removed old tape and cleaned - replace tape and check ok. 13. Found flow timer inop - check wiring from sw to timer. 14. Found pat lights won't adjust - check modules and wiring - R&R bulb. 15. Found a/c leaking around exp. valve - recover freon - leak - test system - found exp. valve leaking - had to remove tubing and cut exp. val out - R&R exp. valve and drier reassembled leak test - vac and charge system. 16. Check flourescent light timer cont. - trouble shoot wiring - found time juper out - reinstalled jumper - found timer bad - ordered timer assembly. 17. Found pat. door panels and hindges loose - tightened pane screws and replaced missing screws - tightened door hinge mount screws - check ok. 18. Check for air leaks - sprayed fittings - found leaks at air gov - removed lines and reinstalled - check ok. 19. Found rear folding step loose - could not loosen bolts - removed cover and plates - adjusted hinges. 20. Repair rear step cont. - lubed hinges - reassembled - check ok. fount right side step loose - removed right fender - reinstalled brakes and replaced missing mount bolt - reassembled. 21. Pat. lights won't adjust cont. - troubleshoot wiring at modules - repair connection at module - check ok. 22. Check air leaks cont. - found park valve leaking - removed dash panels and air lines - R&R valve assembly - ran and check for leaks check ok - reassembled - adjusted brake pedal travel. 23. Found compartment door won't stay shut - found screws missing - replaced

03210072SWITCH DUMP/FLOR LT	1
03910007SW CAP BLANK	2
065624AD-IP DRIER	1
15-40B15W40 MOTOR OIL NON SYN	30
1501450007750USE 0775145	3
1844447C1ORING	1
1873940C3RAD HOSE	2
1878042C91FUEL FILTER 2008 HORTON	1
2505876C91DASH VALVE	1
2506656C124316 WIX CAB A/C FILTER	1
322502BULB PATIENT GH22	1
3660853C22512331C1 EXP VALVE NAV	1
3666273C1A/C DRIER NAV	1
5774457744XD OIL FILTER	1
684-4 VALVE - FILL AIR TANK	1
78R539018-2699 A/C FILTER	1
91-22WIPER BLADE	2
F6DZ-8100-A9C3Z8101B RADIATOR CAP 10238 STAI	1
HA49102C2-32-15 LATCH NON LOCKING	2
K022105PURGE VALVE AD-IP-IS	1
RWTG1234LED PRESSURE CAP	2
S777COUPLING NIPPLE	1



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

screws - adjusted latch - check ok. 24. Q & A inspection. 25. Test drove truck - found air pressure drops from 120 psi - 100 and goes back to 120 psi - found fan clutch fitting leaking replaced fitting behind pulley - check ok.

Workorder: V50527

In Date: 07/02/2012 **Meter Reading:** 87,233.00
Close Date: 07/02/2012

Problem?

REPLACE BATTERY DISCONNECT SWITCH R41

Parts	Quantity
-------	----------

Task performed:

TRAVEL TO ST 41 DIAGNOSE TRAVEL TO CENTRAL SHOP AND REPLACE BATTERY DISCONNECT SWITCH.

51-30219-1045 MASTER SWITCH 175 AMP	1
-------------------------------------	---

Workorder: V50833

In Date: 07/13/2012 **Meter Reading:** 87,819.00
Close Date: 07/13/2012

Problem?

No start R41

Parts	Quantity
-------	----------

Task performed:

NO START/FOUND ACTIVE CODE 1113 BT VOLTAGE LOW/TIGHTENE AND CLEANED CONNECTIONS CHECKED FUSES AND CONNECTION CLEARED CODE TESTED OK WITH MONITOR.

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V51207

In Date: 07/30/2012
Close Date: 07/30/2012

Meter Reading:

Problem?

R41 not starting/turning on

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

1. travel to sta-41, 2. check R-41 for no start, hook up laptop check for codes, had numurous codes, went to check for pressure for oil pump and truck started, shut unit and it restarted, called Ed E crew needs to swap out and truck was going to c/shop for repair 3. travel back to s/shop

Workorder: V51104

In Date: 07/24/2012
Close Date: 08/06/2012

Meter Reading: 89,242.00

Problem?

BASE OF SCBA MOUNT BROKEN. AIPACK WILL NOT STAY IN HOLDE
R41

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

REPAIRED AIR BOTTLE HOLDER THAT HAD BROKEN OFF.



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V51332

In Date: 08/02/2012
Close Date: 08/06/2012

Meter Reading: 89,768.00

Problem?

Hard start/no start

Task performed:

1. STARTED TRUCK - TEST DROVE - CHECK D.T.C. LOW VOLTAGE CODES - CHECK ECM FUSES, GROUNDS, POWER CABLES - RAN KEY OFF AND KEY ON TESTS - CHECK OK, CHECK PUMP SOL. CHECK OK. - STARTED MULTIPLE TIMES HOT AND COLD NO PROBLEMS FOUND. 2. CHECK BATTER BOX COVERS - ADJUSTED LATCHES. 3. CHECK FOR COOLANT LEAK - FOUND TANK DOWN A LITTLE - PRESSURE TEST - CHECK FOR LEAKS NO LEAKS FOUND - FOUND RAD. CAP VERY LOOSE - TOPPED OFF COOLANT TANK - CHECK OK.

Parts	Quantity
-------	----------

NO PARTS USED

Workorder: V51575

In Date: 08/13/2012
Close Date: 09/17/2012

Meter Reading:

Problem?

R41's annunciator panel keeps going off, and stating that their was a malfunction on MOD8 Pin1.

Task performed:

1. FOUND SHORT ON P.C BOARD REPAIRED AND TESTED.

Parts	Quantity
-------	----------

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V51712

In Date: 08/20/2012
Close Date: 09/17/2012

Meter Reading: 91,048.00

Problem?

ON CALL NO POWER TO REAR OF UNIT R 41

Parts	Quantity
-------	----------

Task performed:

FOUND BATTERY SWITCH WAS NO GOOD CUT OUT ACCESS HOLE AND REMOVED BATTERY SWITCH AND INSTALLED NEW ONE.

51-30219-1045 MASTER SWITCH 175 AMP	1
-------------------------------------	---

Workorder: V51668

In Date: 08/17/2012
Close Date: 09/21/2012

Meter Reading: 90,824.00

Problem?

NO EMERGENCY LIGHTS

Parts	Quantity
-------	----------

Task performed:

TRACED OUT PROBLEM BAD CONNECTION ON SOLENOID REPAIR AND TESTED.

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V51512

In Date: 08/10/2012
Close Date: 10/01/2012

Meter Reading: 90,112.00

Problem?

WONT START R41

Task performed:

FOUND TRUCK CRANKS BUT DOES NOT START WHEN ENGINE COL
- FOUND 1113,4516-16 AND VGTPOW VOLT CODES - CK AND TRACE
CONNECTIONS TO ECM AND ECM RELAY - CHECK VOLTS AT RELAY
CHECK OK - CHECK VOLTS AT RELAY DURING CRANKING - 10.78
CHECK - LOAD TEST BATTERY - CHECK OK- PREVIOUSLY CHECK
ALL GROUNDHDS - CK - OK - CK VOLTAGE DROP AND RELAY AND
ECM AND CK - OK AND R&R ECM RELAY - CLEARED CODES - CK
OK.

Parts	Quantity
-------	----------

1219360123-11276-041 RELAY VF28-35F14-Z05	1
---	---

Workorder: V52444

In Date: 09/17/2012
Close Date: 10/01/2012

Meter Reading:

Problem?

Rear drivers side scene light is out. R 41

Task performed:

REMOVED LIGHT AND INSTALLED NEW BULB.

Parts	Quantity
-------	----------

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V53077

In Date: 10/15/2012
Close Date: 10/17/2012

Meter Reading: 95,326.00

Problem?

ON CALL A/C 10-7 EGR LEAKING R 41

Parts	Quantity
-------	----------

Task performed:

1. PATIENT COMP A/C CLUTCH LOCK UP - UNIT TO SHOP. UNIT OUT OF SERVICE. SWAP INTO SR-12 1015665613564.8 MILES HRS. 6880.
 2. FOUND WATER AND GRAY OIL IN AFTER COOLER TUBE AND IN AFTER COOLER. 3. COOLANT LEVEL BELOW LOW MARK NO WARNING LIGHT ON. 4. SR NEED COMPUTER LOCK INSTALL.

NO PARTS USED

Workorder: V53319

In Date: 10/26/2012
Close Date: 10/29/2012

Meter Reading: 95,326.00

Problem?

Replace Tires R41

Parts	Quantity
-------	----------

Task performed:

REPLACE TIRES R41

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V53080

In Date: 10/15/2012

Meter Reading: 95,326.00

Close Date: 11/01/2012

Problem?

B INSPECTION R41 A/C 10-7 POSS EGR LEAK

Task performed:

1. B-INSPECTION. 2. REASSEMBLE - INTAKE PIPING AND P/STEERING RES. REMOVED FOR DIAGNOSIS OF ENG. PROBLEM AND A/C. 3. INSTALL PATIENT A/C COMPRESSOR AND DRYER. TEST FOR LEAKS EVALUATE AND RECHARGE A/C SYSTEM. 4. TEST FOR COOLANT LEAKS. REMOVE EGR CROSSOVER TUBE TO RULE OUT BAD COOLERS. 5. TEST EGR COOLANT HOSE FOR LEAK DRAIN COOLANT AND INSTALL COOLANT TUBE ON BACK SIDE OF TUBO REFILL AND TEST. 6. INSTALL EGR CROSSOVER TUBE AND CHANGE AIR TUBES AIR FILTER. 7. REPLACE FRONT AND REAR BRAKE SHOES, SPRING KITS AND DRUMS ADJUST ALL BRAKES CLEAN SPINDLES AND, S-CAMS, ABS SENSORS. 8. ADJUST ALL SCBA DOOR LATCHES. 9. SCAN COMPUTER AND CLEAR ALL CODES. 10. REPLACE SIDE REVERSE LIGHTS. 11. REPLACE R/F MARKER LIGHT 12. TRACE WIRES FOR STEP LIGHTS AND REPAIR WIRING.

Parts

Quantity

071601A07-0602A DRIER A/C 7118	1
1839415C91OIL PRESSURE SENSOR	1
1873940C3RAD HOSE	1
1878042C91FUEL FILTER 2008 HORTON	2
2506656C124316 WIX CAB A/C FILTER	1
3753BRAKE DRUM RUMPER FRONT	2
3757REAR DRUMS 3757X 3647X	2
4DA2545W LAMP	2
559103-6537 MANIFOLD COMP 5779	1
5774457744XD OIL FILTER	1
577903-3673 COMP USE 5591 MANIFOLD	1
8201L17-3428 ESTER OIL E7	1
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
K060705BELT HORTON	1
KSMA2124703QFRONTBRAKE KIT RUMPER AND 4D	2
S775COUPLER	1
XK4034707QPMHD SHOE KIT 3/8 BEAM	2



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V53983

In Date: 11/26/2012 Meter Reading: 97,593.00
Close Date: 11/28/2012

Problem?

ON CALL COOLANT LEAK R41

Parts	Quantity
-------	----------

Task performed:

COOLANT LEAK TOP OFF RESEVOIR PRESSURES TEST NO LEAK
UNIT IN ENGINE SERVICE TO REPORT TO SHOP ON NEXT WORKING
DAY.

NO PARTS USED

Workorder: V53519

In Date: 11/03/2012 Meter Reading:
Close Date: 12/07/2012

Problem?

front grille on the rescue is cracked R 41

Parts	Quantity
-------	----------

Task performed:

INSTALL STRAPS IN REAR COMPARTMENT.

14-7014HGR-1 HELMET HOOK	11
CYBS27299011 STRAP 36IN	5
UMVS111611STRAP	5
UMVS162511STRAP	7

Workorder: V53627

In Date: 11/08/2012 Meter Reading:
Close Date: 12/07/2012

Problem?

air leak fuse box cover in cab falls off. R41

Parts	Quantity
-------	----------

Task performed:

TRACED OUT AIR LEAK LEAK AND REPAIRED.

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V53813

In Date: 11/16/2012 Meter Reading:
Close Date: 12/14/2012

Problem?

shoreline auto eject recepticle on R41 has a broken cover. It is exposed to the elements. R41

Parts	Quantity
-------	----------

Task performed:
TRACED OUT AIR LEAK AND REPAIRED.

NO PARTS USED

Workorder: V53853

In Date: 11/18/2012 Meter Reading:
Close Date: 12/14/2012

Problem?

WHOITE COVER FOR SHORELINE PLUG IS BROKEN/MISSING. R41

Parts	Quantity
-------	----------

Task performed:
REPLACED COVER ON SIDE OF TRUCK FOR 110 PLUG.

NO PARTS USED

Workorder: V54575

In Date: 12/23/2012 Meter Reading:
Close Date: 01/14/2013

Problem?

BACK UP CAMERA NOT WORKING ON R41

Parts	Quantity
-------	----------

Task performed:
COOLANT LEAK AT CAP REPAIRED. REPAIRED BAD CONNECTION ON BACKUP CAM.

F6DZ-8100-A9C3Z8101B RADIATOR CAP 10238 STAI	1
--	---



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V54692

In Date: 12/29/2012
Close Date: 01/14/2013

Meter Reading:

Problem?

FRONT A/C NOT WORKING PROPERLY. ON/OFF

Parts	Quantity
-------	----------

Task performed:

CHECKED A/C AND TESTED OK. REPAIRED REAR STEP THAT WAS FALLING OFF.

NO PARTS USED

Workorder: V55199

In Date: 01/22/2013
Close Date: 02/07/2013

Meter Reading: 102,627.00

Problem?

loss of coolant again !!! Added water to antifreeze overflow container. Has been 6 days since last repair for same issue. Rbailey at 305-815-4678 for explanation of continuous problem

Parts	Quantity
-------	----------

Task performed:

1. CHECKED FOR LEAKS NO LEKAS AT THIS TIME. 2. REPAIRED SIDE ENTRE DOOR THAT WOULD NOT OPEN.

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V55575

In Date: 02/07/2013
Close Date: 02/14/2013

Meter Reading: 104,338.00

Problem?

C INSPECTION R 41

Task performed:

1. C insp. 2. pat. compt. lite inop over squad bench, replace bulb 3. replace pat. a/c filters 4. 110v outlets inop, found plug for outlets loose in inverter, repair plug 5. replace non skid tape on rear entry door 6. replace wiper blades 7. front grill cracked, remove grill, remove LED lites from grill and mount on new grill, install new grill 8. coolant leak, pressure leak foun hose clamps under turbo loose, clamps under cooler and upper radiator hose all loose, tighten clamps and pressure check with engine on high idle found another hose clamp loose on cross over coolant hose under air filter leaking remove air filter assy. and tighten clamp, reinstall filter housing, and retest system, no more leaks found 9. air system drops down overnight, found air leaks at tank fittings, replace fittings, recheck for leaks, found fitting leaking at foot valve replace fitting and recheck, no more leaks 10. service transmission 11. service air drier 12. service rear axel 13. replace cab red dot a/c filter 14. replace front shocks 15. replace rear shocks 16. road test vehicle

Parts	Quantity
065624AD-IP DRIER	1
15-40B15W40 MOTOR OIL NON SYN	30
1501450007750USE 0775145	3
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
29526898 29548988 TRANS FILTER ALLISON	1
322502BULB PATIENT GH22	1
3553628C3SHOCK REAR WPB	2
3578105C2FRONT SHOCKS	2
3610519C1GRILLE ASSY FIXED	1
5774457744XD OIL FILTER	1
78R539018-2699 A/C FILTER	1
91-22WIPER BLADE	2
K022105PURGE VALVE AD-IP-IS	1
TRANSYNDALLISON TRANS FLUID GAL	5

Workorder: V56454

In Date: 03/17/2013
Close Date: 03/19/2013

Meter Reading: 105,421.00

Problem?

DRIVER-SIDE STEP IS COMING UNBOLTED/IS LOOSE. A FEW BOLTS ARE MISSING. STEP IS BECOMING UNSTABLE. R41

Task performed:

ADJUSTED ALL LATCHES FOR STEP DRILLED AND INSTALLED NEW HARDWARE TO HOLD STEP SECURE.

Parts	Quantity
NO PARTS USED	



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V56067

In Date: 02/28/2013 Meter Reading: 105,277.00
 Close Date: 04/05/2013

Problem?

SCENE LIGHT ON OFFICER SIDE IS OUT.

Parts	Quantity
-------	----------

Task performed:
 REPAIRED BAD GROUND.

NO PARTS USED

Workorder: V48890

In Date: 04/25/2012 Meter Reading:
 Close Date: 04/08/2013

Problem?

Driverside front tire is low on air.

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED

Workorder: V49594

In Date: 05/23/2012 Meter Reading:
 Close Date: 04/08/2013

Problem?

Step is lose. Broken latch for battery cover. R 41

Parts	Quantity
-------	----------

Task performed:

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V56373

In Date: 03/13/2013
Close Date: 04/10/2013

Meter Reading: 105,421.00

Problem?

Rear a/c inop R-41

Parts	Quantity
-------	----------

Task performed:

CLEANED CODENCER FANS AND TESTED.

NO PARTS USED

Workorder: V56845

In Date: 04/02/2013
Close Date: 04/10/2013

Meter Reading: 108,055.00

Problem?

Tow to shop R-41

Parts	Quantity
-------	----------

Task performed:

TOW TO SHOP R-41

NO PARTS USED

Vendor? WESTWAY TOWING, INC.



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V56797

In Date: 04/03/2013

Meter Reading: 108,055.00

Close Date: 04/17/2013

Problem?

Engine not running properly Check air brake system for possible compressor problem R-41

Parts

Quantity



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Task performed:

1. FOUND BATTERY DEAD - TRIED TO JUMP COULD NOT JUMP - CHANGED BATTERY WITH CHARGER - FOUND COOLANT TANK EMPTY ADDED COOLANT STARTED, RAN AND BROUGHT INTO SHOP
 2. CHARGED BATTERY - MOVED TRUCK - CHECK CODES - ECL CRITICAL/LOW - FOUND COOLANT IN EXHAUST SYSTEM - TURBO BLOWING OIL INTO ENGINE - DRAINED RADIATOR. 3. REPAIR ENGINE REMOVED AIR CLEANER, AIR TUBES, AIR CLEANER BRACKET. 4. REPAIR ENGINE REMOVED EXHAUST. CROSSOVER EXHAUST EGR COOLER, TURBO CLAMP, TURBO DRAIN CLAMP CRANK VENT TUBE. 5. REPAIR ENGINE CONT. REMOVED BUMPER, HOOD ASSEMBLY, TRANS LINES, RADIATOR HOSES AND RADIATOR ASSEMBLY - DISASSEMBLED RADIATOR ASSEMBLY REMOVED AFTER COOLER. 6. REPAIR ENGINE: REMOVED D.P.F., DISASSEMBLED EXHAUST AND DRAIN REMAINING COOLANT. 7. REPAIR ENGINE REMOVED OIL LINES AND CLAMPS - REMOVED ALTERNATOR HOSE BRACKET. 8. REPAIR ENGINE - REMOVED TURBO DRAIN TUBE - REPLACE D.P.F. WITH CLEANED UNIT - REMOVED TURBO ASSEMBLY - REMOVED OIL SUPPLY LINE AND FITTING - CLEANED SCREEN REPLACED "O"RING. 9. REPAIR ENGINE: REPLACED TURBO AND INSTALLED - REPLACED SEALS - REPLACED EXHAUST EGR COOLER, IN- 10. REPAIR ENGINE: INSTALLED ALTERNATOR, BRACKETS, WATER PIPE - REMOVED INTAKE EGR COOLER - INSTALLED INTER COOLER, ASSEMBLED RADIATOR BRACKETS CLEANED RADIATOR. FINISHED - REMOVED A/C CONDENSER. 11. REPAIR ENGINE: REMOVED A/C CONDENSER INSTALLED RADIATOR ASSEMBLY - INSTALLED A/C CONDENSER, A/C LINES, TRANS LINES, RADIATOR HOSES, SHROUD, GRILLE. 12. REPAIR ENGINE: REMOVED ENGINE HARNESS, VALVE COVER, INJECTOR HARNESS, OIL RAIL, INJECTORS - REPLACED INJECTOR AND OIL RAIL SEALS. 13. REPAIR ENGINE: REPLACED INTAKE EGR COOLER, INSTALLED INJECTOR HARNESS, VALVE COVER GASKET VALVE COVER, - REPLACED EGR VALVE - REPLACED ALL COOLANT JUMPER HOSES AND CLAMPS - CLEANED AIR TUBES. 14. REPAIR ENGINE: R&R BOOST AND AIR MANIFOLD SENSORS - INSTALLED A TUBES. 15. REPAIR ENGINE: R&R ENGINE OIL AND FILTER - FILLED COOLING SYSTEM - R&R HOSE CLAMPS AT HEATER HOSE

15-40B15W40 MOTOR OIL NON SYN	30
1822018C1IDLER PULLEY BOLT	1
1832771C1PULLEY BUSHING	1
1832784C1IDLER DUST COVER	1
1841930C1IDLER PULLEY	1
1842626C951842626C96 OIL RAIL MANIFOLD SEALS	1
1846481C92SENSOR MAP	1
1875784C921875784C93 ICP SENSOR	1
1875838C91SENSOR MANIFOLD AIR TEMP MAT	1
1876118C95TURBOCHARGER	1
1878918C2EGR VALVE	1
2593986C1DPF GASKET	1
2593998C1DPF GASKET	1
4307362R91KIT EGR COOLER COLD SIDE OLD 1876	1
5010561R925010561R93 INJECTOR	6
5774457744XD OIL FILTER	1
7090595C91COOLER EGR KIT 330MM EXH SIDE OLI	1
ALA00350-50 EXTENDED LIFE COOLANT GAL	1
CLEAN AND TESTCOOLER/RADIATOR	4
DPFCLEANED UNIT	1
F6DZ-8100-A9C3Z8101B RADIATOR CAP 10238 STAI	1



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

CONNECTIONS AT "T" FITTINGS - FILLED COOLING SYSTEM. 16. ASSIST WITH HOOD INSTALL. 17. REPAIR ENGINE: INSTALLED HOOD ASSEMBLY, BUMPER, ALL WIRES - ERASE ENGINE CODES - TEST DROVE - CHECK CODES AND SENSOR OPERATIONS - CHECK OK - CHECK FOR LEAKS AND LEVELS - CHECK OK BOX ALL COVERS. 18 CHECK AIR COMPRESSOR FOR PUMPING OIL INTO AIR SYSTEM - DRAINED AIR TANK - REMOVED DISCHARGE LINER - RAN ENGINE - NO OIL COMING FROM LINE - CHECK DRYER OPERATION - CHECK OK.

Workorder: V48132

In Date: 03/22/2012 Meter Reading: 80,146.00
Close Date: 04/23/2013

Problem?

repair cooling system

Parts ----- Quantity

Task performed:
REPAIED UNDER WARRANTY.

NO PARTS USED

Workorder: V57222

In Date: 04/23/2013 Meter Reading: 108,055.00
Close Date: 04/23/2013

Problem?

stretcher leaning to side

Parts ----- Quantity

Task performed:
FOUND A USE STRETCHER IN BLDG. 3.

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V57753

In Date: 05/15/2013 Meter Reading: 110,949.00
 Close Date: 05/24/2013

Problem?

Coolant leak R41

Parts	Quantity
-------	----------

Task performed:
 REPAIRED COOLANT LEAK AT LOWER HOSE.

NO PARTS USED

Workorder: V56605

In Date: 03/24/2013 Meter Reading:
 Close Date: 05/29/2013

Problem?

coolant seems to be leaking. R-41

Parts	Quantity
-------	----------

Task performed:
 PRESSURE TESTED SYSTEM AND FOUND SMALL LEAK AND REPAIRED.

NO PARTS USED

Workorder: V57821

In Date: 05/18/2013 Meter Reading:
 Close Date: 05/31/2013

Problem?

On R41 the officer side door sags, and does not close properly unless forced.

Parts	Quantity
-------	----------

Task performed:
 1. REMOVED AND REPLACED CAB DOOR HINGES.

3549259C1DOOR HINGES R F	2
--------------------------	---



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V58307

In Date: 06/10/2013
Close Date: 06/21/2013

Meter Reading: 113,184.00

Problem?

DRIVER'S SIDE FRONT TIRE IS LOW ON TREAD. RUBBER IS PAST THE MARKERS R41

Parts	Quantity
-------	----------

216568BRIDGESTONE 255/70R22.5	2
-------------------------------	---

Task performed:

1. DRIVER'S SIDE FRONT TIRE IS LOW ON TREAD. RUBBER IS PAST THE MARKERS R41. 2. ORDERED TWO FRONT TIRES AND CHECKED AND ROAD TESTED ALIGNMENT. 3. AIR LEAK - CHECKED FOR AIR LEAKS.

Vendor? BOULEVARD TIRE CENTE

Workorder: V58377

In Date: 06/13/2013
Close Date: 06/21/2013

Meter Reading: 112,921.00

Problem?

at 0238 this morning the check engine light came on. all gauges appear to be normal R41

Parts	Quantity
-------	----------

NO PARTS USED	
---------------	--

Task performed:

CHECKED FOR CODES FOUND LOW ON COOLANT.

Workorder: V58526

In Date: 06/18/2013
Close Date: 06/24/2013

Meter Reading: 113,184.00

Problem?

at 1155 this morning the check engine light came on. this happen after sitting idol for about 10 mins R41

Parts	Quantity
-------	----------

NO PARTS USED	
---------------	--

Task performed:

TRACED OUT PROBLEM WITH LIGHT COMING ON FOUND LOW ON COOLANT.



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V58682

In Date: 06/25/2013

Meter Reading: 113,645.00

Close Date: 07/18/2013

Problem?

B inspection R41

Task performed:

1. VEHICLE WON'T START IN PARKING LOT. HOOK UP CHARGER FC BATTERIES TO CHARGE A WHILE. 2. B-INSPECTION. 3. B-INSPECTION. 4. R&R CAB AUX A/C FILTER. 5. DIAGNOSE AND REPAIR WINDSHIELD WASHER. REPAIRED CONNECTOR AT MOTOF FILL WASHER RESERVOIR. 6. R&R WIPER BLADES. 7. FIGURE OUT WHY BATT. DOOR WON'T OPEN. AFTER GETTING DOOR OPEN ADJ STRIKERS AND LUBE LATCHES (FOUR) ON BATT DOOR. 8. R&R LENS R&R BULB ON PATIENT CEILING LIGHT ASSY. 9. TIGHTEN COMPT. L LOWER HOLD OPEN TIGHTEN COMPT. L-3 UPPER HOLD OPEN TIGHTEN COMPT. R-2 HOLD OPEN. 10. R&R INNER DOOR PANEL AC UPPER LATCH LINKAGE ROD IN COMPT. L-3 ALSO DRILL OUT AND INSTALL NEW 10-24 NUTSERT AND REPLACE BENT SCREW. 11. R&I LENS R&R BULB AND REFLECTOR ASSY CHANGE BULB. HAD TO WASH LENS AND REFLECTOR OF BULB RESIDUE. SAME ON BOTH SIDES. 12. SEARCH FOR AIR LEAKS. 13. SIGN BRKTS REMOVE 5 NUMBER AND CAMPAGN SIGN BRKETS. 14. REMOVE ALL OLD ADHESIVE FROM TRUCK BODY FROM 5 NUMBER AND CAMPAIGN SIGNS AND INSTALL 3 NEW NUMBER FRAMES. MAKE 2 NUMBER PLATES. 15. Q & A. 16. REMOVE OLD NON SKID FROM S/S PLATE AT PATIENT ENTRY-EXIT REAR FLOOR. REMOVE ALL OLD ADHESIVE APPLY NEW NON-SKID. 17. R&R LENS R&R BULB ON 3 COURTESY LIGHTS ON CAB DOOR PANELS. 18. INSTALL HOSE PROTECTOR ON P/S SUCTION HOSE. 19. R&R EDGE PROTECTOR TRIM IN COMPT. R-2. 20. R&R LIGHT ASSY R&R BACKING GASKET ON R/S EMERG. LIGHT.

Parts

Quantity

1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
2506988C91CHECK VALVE QUICK CONNECT AIR TA	1
322502BULB PATIENT GH22	1
3542606C12611234C1 VENT ACTUATOR	1
3757REAR DRUMS 3757X 3647X	2
5774457744XD OIL FILTER	1
5TSMACMOUNT 500 TIR SER CHROME	1
78R539018-2699 A/C FILTER	1
91-22WIPER BLADE	2
H50SN12BULB	2
L PLACARDLARGE SIDE PLACARD	2
L PLACARD INSERTLARGE PLACARD INSERT CARL	2
PM27JUGUREA ADDITIVE	2
S PLACARDFRONT AND BACK PLACARD	1
XK4034707QPMHD SHOE KIT 3/8 BEAM	2



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V58994

In Date: 07/10/2013
Close Date: 07/23/2013

Meter Reading: 113,645.00

Problem?

Replace rear tires R41

Parts	Quantity
-------	----------

Task performed:

REPLACE REAR TIRES R41

216568BRIDGESTONE 255/70R22.5	1
-------------------------------	---

Vendor? BOULEVARD TIRE CENTE

Workorder: V59463

In Date: 07/31/2013
Close Date: 08/01/2013

Meter Reading:

Problem?

TRUCK HAS A AIR LEAK IN THE ENGINE COMPARTMENT AND A SENSOR CABLE HANGING UNDER THE FRONT BUMPER R41

Parts	Quantity
-------	----------

Task performed:

1. check cable hanging down, found it was a dead end wire capped off, wire tie back up 2. check for air leak, found push on fitting on frame rail leaking, replace fitting, recheck no leaks

NO PARTS USED	
---------------	--

Workorder: V59227

In Date: 07/21/2013
Close Date: 08/09/2013

Meter Reading: 114,310.00

Problem?

Squeaky engine belt and AC leaking into the patient compartment R41

Parts	Quantity
-------	----------

Task performed:

1. CHECKED BELTS AND CHECKED OK. 2. CLEAN A/C DRAIN, AND TESTED SYSTEM. 3. ADJUSTED AIR HORNS.

NO PARTS USED	
---------------	--



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V60579

In Date: 09/18/2013
Close Date: 09/23/2013

Meter Reading: 118,044.00

Problem?

no start

Parts	Quantity
-------	----------

Task performed:

RECHARGED BATTERIES AND ROAD TESTED AND ALL TESTED OK.

NO PARTS USED

Workorder: V61029

In Date: 10/05/2013
Close Date: 10/21/2013

Meter Reading: 120,072.00

Problem?

Metal strip at bottom of rear pt compartment door broke loose, and needs replacement. (function appears cosmetic)

Parts	Quantity
-------	----------

Task performed:

REMOVED MEDAL STRIP FROM BOTTOM OF DOOR AND REMOUNTED.

K022105PURGE VALVE AD-IP-IS	1
-----------------------------	---

Workorder: V61332

In Date: 10/17/2013
Close Date: 11/01/2013

Meter Reading: 120,894.00

Problem?

air leak

Parts	Quantity
-------	----------

Task performed:

TRACED OUT AIR LEAKS AND REPAIRED.

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V61505

In Date: 10/24/2013
Close Date: 11/08/2013

Meter Reading:

Problem?

The light in cab will not shut off and appears to be broken.

Parts	Quantity
-------	----------

Task performed:

1. REPAIRED LIGHT IN REAR BOX THAT SHORTED OUT REPAIRED WIRES AND TESTED. 2. REPAIRED LAPTOP MOUNT THAT HAD BROKEN BOLT.

NO PARTS USED

Workorder: V61506

In Date: 10/24/2013
Close Date: 11/08/2013

Meter Reading:

Problem?

The truck will not start if it is not on the charger over night. Batteries drain very rapidly.

Parts	Quantity
-------	----------

Task performed:

NO START-FOUND BATTERIES NO GOOD REMOVED AND REPLACE

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V61811

In Date: 11/05/2013

Meter Reading: 122,505.00

Close Date: 11/27/2013

Problem?

C inspection R41

Task performed:

1. C inspection 2. air leak overnight, check with soap and water, found multiple leaks at push on fittings and repair 3. back up alarm inop, replace alarm 4. install N.Y hook brackets 5. driver's window will not go up, remove door panel and wiring, remove and install new window motor, window goes up and down now, but needs a regulator, on order will install when comes in 6. weather strip on all 4 cab doors torn, replace all weather strip 7. red dot a/c vent missing, replace vent 8. replace red dot a/c filter 9. replace wiper blades 10. washer inop, clean washer lines 11. replace pat. a/c filters, replace missing cover screws on a 3 filters 12. sharps drawer cracked, remove slide assembly. screws were stripped, had to cut out frame and replace doors, drill and install new screws 13. replace bulb in pat. compartment. light above squad bench 14. light assembly in cab above center console missing, replace light 15. replace fan and a/c belts 16. service air dryer 17. adjust tire pressure and install LED air indicators 18. 110v a/c condenser fans inop, remove and install new style fans 19. remove, clean and replace non-skid tape on side entry and rear entry doors 20. 110v receptacle in pat. compartment. missing, replace receptacle 21. low on coolant, pressure test, found leaks at hose clamps that were loose under turbo, EGR valve, and behind water pump, replace 2 clamps and tighten the other clamps. recheck for leaks, none found

Parts	Quantity
065624AD-IP DRIER	1
15-40B15W40 MOTOR OIL NON SYN	30
1501450007750USE 0775145	3
1847727C1BELT	1
1878042C91FUEL FILTER 2008 HORTON	1
2505420C91L/H WINDOW MOTOR	1
2506656C124316 WIX CAB A/C FILTER	1
322502BULB PATIENT GH22	1
3508972C6DOOR SEAL F	2
3508974C4DOOR SEAL REAR	2
3626066C1DOME LIGHT ASSY	1
3986484C92DOOR BEAM WINDOW REGULATOR L/H	1
50-2204FAN KIT DANHARD CONDENSER	1
5269LPVM-5 SM MOUNT	2
575BACKUP ALARM ECCO 107 DEC	1
5774457744XD OIL FILTER	1
72R311018-2640 VENT A/C NEW # 1719	1
78R539018-2699 A/C FILTER	1
91-22WIPER BLADE	2
DOOR6RED HAZ DOOR	2
K022105PURGE VALVE AD-IP-IS	1
K060705BELT HORTON	1
RWTG1234LED PRESSURE CAP	1



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V62274

In Date: 11/25/2013 **Meter Reading:** 123,164.00
Close Date: 12/17/2013

Problem?

air leak

Parts	Quantity
-------	----------

Task performed:
 TRACED OUT AIR LEAKS AND REPAIRED.

NO PARTS USED

Workorder: V62368

In Date: 12/01/2013 **Meter Reading:**
Close Date: 12/17/2013

Problem?

front officer side headlight is out

Parts	Quantity
-------	----------

Task performed:
 1. REPLACED HEADLIGHT AND REPAIRED CONNECTION OF LIGHT.
 REPAIRED STRETCHER LATCH AND TESTED.

NO PARTS USED

Workorder: V61607

In Date: 10/29/2013 **Meter Reading:**
Close Date: 01/06/2014

Problem?

STRYKER STRETCHER(10175533) WILL NOT RISE WITH OUT ASSISTANCE. ON R41(ALPHA)

Parts	Quantity
-------	----------

Task performed:
 PERFORMED BY ENSAR.

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V63474

In Date: 01/17/2014 Meter Reading:
Close Date: 01/21/2014

Problem?

driver side mirror is broken and hanging off due to a gate coming down on it.

Parts	Quantity
-------	----------

Task performed:

DRIVER MIRROR BROKE OFF- REMOVE MIRROR- INSTALL AND REWIRE NEW MIRROR.

3735635C91LEFT MIRROR ASSBLY	1
------------------------------	---

Workorder: V61537

In Date: 10/25/2013 Meter Reading: 124,535.00
Close Date: 01/24/2014

Problem?

back up warning sound not working R41

Parts	Quantity
-------	----------

Task performed:

VERIFIED COMPLAINT. WORK COMPLETED ON ANOTHER WORK ORDER.

575BACKUP ALARM ECCO 107 DEC	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	3
HP-31DBATTERY 950CCA HP-31D	3

Workorder: V61860

In Date: 11/07/2013 Meter Reading: 124,535.00
Close Date: 01/24/2014

Problem?

reverse warning sound not working on R41

Parts	Quantity
-------	----------

Task performed:

VERIFIED COMPLAINT/ WORK COMPLETED ON ANOTHER WORK ORDER.

15-40B15W40 MOTOR OIL NON SYN	40
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	3
HP-31DBATTERY 950CCA HP-31D	3



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V63143

In Date: 01/05/2014 Meter Reading: 127,110.00
Close Date: 01/24/2014

Problem?

rescue will not shift out of 2nd gear R41

Parts	Quantity
-------	----------

Task performed:

ROAD TESTED AND CHECKED FOR CODES ALL TESTED OK.

NO PARTS USED

Workorder: V63650

In Date: 01/23/2014 Meter Reading: 128,249.00
Close Date: 01/24/2014

Problem?

replace front tires

Parts	Quantity
-------	----------

Task performed:

REPLACE FRONT TIRES.

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE

Workorder: V63596

In Date: 01/22/2014 Meter Reading:
Close Date: 02/06/2014

Problem?

Shore power plug does not eject when vehicle is started up. Damage to power cord resulted.

Parts	Quantity
-------	----------

Task performed:

TESTED PLUG AND FOUND UNIT WORKING.

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V64296

In Date: 02/18/2014
Close Date: 02/19/2014

Meter Reading: 130,670.00

Problem?

R41 was in an accident

Parts	Quantity
-------	----------

Task performed:

ACCIDENT- HIT IN R/F WHEEL TRAVEL TO SCENE BROUGHT TO ST 42 AND INSPECTED FRONT END OK BACK IN SENSOR.

NO PARTS USED

Workorder: V63812

In Date: 01/29/2014
Close Date: 02/25/2014

Meter Reading:

Problem?

rear passanger tire has a slash on the side wall. needs to be changed r41

Parts	Quantity
-------	----------

Task performed:

REAR PASSENGER TIRE HAS A SLASH ON THE SIDE WALL, NEEDS TO BE CHANGED R-41. 1. CHECKED TIRE NEED TO BE REPLACED. ; CHECKED FOR COOLANT LEAK, FOUND AND REPAIRED.

NO PARTS USED

Vendor? BOULEVARD TIRE



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V64659

In Date: 03/03/2014
Close Date: 03/04/2014

Meter Reading: 131,578.00

Problem?

cab a/c inop

Task performed:

1. FOUND HIGHT SIDE A/C LINE SPLIT AND LEAKING. RECOVERED SYSTEM REMOVED HOSE/LINE AND SENT TO MAKO TO HOSE NEW LINE MADE. 2. GOT REPAIRED A/C LINE BACK FROM MAKO INSTALLED LINE VACUUMED SYSTEM AND RECHARGED. SYSTEM NOW COOLING NORMALLY.

Parts	Quantity
462657HOSE & FITTINGS ASSY	1

Workorder: V64752

In Date: 03/06/2014
Close Date: 03/10/2014

Meter Reading:

Problem?

Oil on dipstick is showing about an 1" over high mark line.

Task performed:

vehicle bought in for B insp. on 3/10/14

Parts	Quantity
NO PARTS USED	

Workorder: V64274

In Date: 02/17/2014
Close Date: 03/12/2014

Meter Reading:

Problem?

rear floodlight is out on R41

Task performed:

REPAIRED SHORT IN LIGHT.

Parts	Quantity
NO PARTS USED	



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V64275

In Date: 02/17/2014
Close Date: 03/12/2014

Meter Reading:

Problem?

alignment is off on R41

Parts	Quantity
-------	----------

Task performed:

ROAD TESTED TRUCK AND TESTED OK.

NO PARTS USED

Workorder: V64373

In Date: 02/19/2014
Close Date: 03/12/2014

Meter Reading:

Problem?

Locking lever that locks the main O2 tank in place is broken off. R41

Parts	Quantity
-------	----------

Task performed:

REPAIRED O2 LATCH THAT WAS BROKEN.

NO PARTS USED

Workorder: V64753

In Date: 03/06/2014
Close Date: 03/27/2014

Meter Reading:

Problem?

All tires on driver's side of vehicle have low tread.

Parts	Quantity
-------	----------

Task performed:

ALL TIRES ON DRIVERS SIDE OF VEHICLE HAVE LOW TREAD.

NO PARTS USED

Vendor? BOULEVARD TIRE



9/26/2016

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V65349

In Date: 04/01/2014

Meter Reading:

Close Date: 04/02/2014

Problem?

all lights in the mod are out and we have a door open warning light R41

Task performed:

DOME LIGHTS INOP- INPUT MODULE DEFECTIVE- REPLACE #2
INPUT MODULE.

Parts

Quantity

10008500OUTPUT MODULE HORTON

1



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V64796

In Date: 03/09/2014

Meter Reading: 132,317.00

Close Date: 04/08/2014

Problem?

B inspection R41

Task performed:

1. went to move vehicle and would not start, hook up scanner, no codes, replace both start relays, vehicle started. 2. B insp 3. remove driver side door panel, window and window regulator, install new regulator, wire up to horton wiring, switch door lock cylinder, reinstall window, door panel, and accessory's. 4. remove air filter, clear out air intake hose to air compressor, install new filter 5. replace wiper blades 6. service p/s 7. remove o2 bottles and remove pull out tray in l/1 compt. drill new holes and mount new locking slide, reinstall pull out tray and o2 bottles 8. try to remove torsion bar, remove r/rear shock, remove both air leveling valves, use torches to heat up and remove bar to be sent out for bushings 9. during insp. noticed engine oil on bottom of oil pan, and transmission, degrease engine, tighten oil pan bolts, run engine check for oil leak 10. pat. compt. a/c filter housing falling off, replace screws 11. 110v outlets inop. in pat. compt. found circuit breaker tripped, reset, run inverter. did not trip 12. replace struts in cabinet over EMT work bench 13. remove rear wheels, drums and brake shoes, install new brake shoes, hardware and drums, adjust brakes 14. remove r/side front fender well, 15. install rear torsion bar, had a hell of a time installing it by myself.... 16. air for rear tank leaks down overnight, trace out air leak with soap and water, found rear suspension solenoid's on frame rail leaking, non in stock had to be ordered, will install when delivered 16. received air solenoids, remove module from frame rail, install 2 new solenoids, replace o rings, recheck for leaks, found more leaks, replace fittings on air lines on wet tank, recheck for leaks none found 17. received new painted r/side fender, drill holes for mud flap, install fender, adjust pass. side cab door so it will not hit fender, 18. road test vehicle, ca john murray, vehicle needs to go to c/shop weld cracked on r/side fuel tank cover, also needs front end alignment

Parts

Quantity

10006527WINDOW INVERTOR	1
1219360123-11276-041 RELAY VF28-35F14-Z05	2
15-40B15W40 MOTOR OIL NON SYN	30
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
2506712C91SOLENOID AIR DUMP INT	2
2507061C1PS RESV GASKET	1
283255 SLIDE 18IN 500 LBS	1
3757REAR DRUMS 3757X 3647X	2
46870AIR FILTER	1
5774457744XD OIL FILTER	1
91-22WIPER BLADE	2
VML/T1808D2503221C1 FILTER POWER STEERING	1
XK4034707QPMHD SHOE KIT 3/8 BEAM	2



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V65264

In Date: 03/27/2014 Meter Reading: 1,320,420.00
Close Date: 04/09/2014

Problem?

R-S diamond plate needs to be welded

Task performed:

1. STRAIGHTEN OUT AND GET READY TO WELD CRACK IN PLATE. 2. PULL TRUCK INTO WELD SHOP TO WELD UP STEP ON RIGHT SIDE, CLEAN AND WELD CRACK INSTALLED SIDE FENDER. 3. CRACK OUT COOLANT SYSTEM NOT HEATING UP 140 DEGREES ONLY DRAIN SYSTEM FOUND BAD THERMOSTAT REPLACE STRAIGHTEN STEERING WHEEL IN SIDE. 4. WORK ON ALL SYSTEM WILL NOT STOP PURGING AIR SYSTEM WORK OK AT THIS TIME.

Parts	Quantity
284358GOVERNOR D-2	1
K022105PURGE VALVE AD-IP-IS	1

Workorder: V65540

In Date: 04/07/2014 Meter Reading: 132,962.00
Close Date: 04/15/2014

Problem?

REPLACE FENDER DAMAGED DURING ACCIDENT R41

Task performed:

REPLACE FENDER DAMAGED IN ACCIDENT

Parts	Quantity
3566717C4EXTENSION FENDER R/H	1



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V65390

In Date: 04/02/2014 Meter Reading:
Close Date: 04/17/2014

Problem?

Electronic mirrors do not work and air compressor tanks are leaking. r41

Parts	Quantity
-------	----------

Task performed:

1. REMOVED DOOR PANEL AND RECONNECTED WIRE TO MIRROR SWITCH. 2. READJUSTED AIR BAGS THAT WERE LEAKING.

NO PARTS USED

Workorder: V65802

In Date: 04/18/2014 Meter Reading: 133,632.00
Close Date: 04/21/2014

Problem?

Oil level over full

Parts	Quantity
-------	----------

Task performed:

CHK FOR CODES- RAN ENG TESTS RAN REGEN, FAILED. CODE 128 IHV SELF TEST FAILED. DRAINED OIL REPLACED OIL. R&R D.P.F AND IHV VALVE- RAN AND CHECK OK.

1838248C1SEAL	1
1872145C1HOUSING ASSY INTAKE THROTTLE	1
2593986C1DPF GASKET	1
2593998C1DPF GASKET	1
DPFCLEANED UNIT	1

Workorder: V65502

In Date: 04/06/2014 Meter Reading:
Close Date: 04/25/2014

Problem?

Air dump on Rescue-41 is not working appropriately. When rescue is not running, even without opening back doors the rescue goes to "DUMP POSITION", especially on driver side.

Parts	Quantity
-------	----------

Task performed:

FOUND SWITCH WAS LEFT ON AT DASH.

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V66108

In Date: 04/30/2014
Close Date: 05/22/2014

Meter Reading: 134,648.00

Problem?

Smoking smell

Parts	Quantity
-------	----------

Task performed:

CHECKED FOR WIRES BURNING FOUND NONE AT THIS TIME.

NO PARTS USED

Workorder: V66207

In Date: 05/03/2014
Close Date: 05/23/2014

Meter Reading:

Problem?

Main O2 line is linking, can't keep O2 open because it bleeds the tank.
Dump air bags in the back (for taking out the patients) not working properly.
The truck viewed from the back it leans towards the driver side. R41

Parts	Quantity
-------	----------

Task performed:

1. REPAIRED O2 LEAK AT FITTING AT BOTTLE. 2. READJUSTED AIR BAGS ABD RAOD TESTED.

NO PARTS USED

Workorder: V66952

In Date: 06/03/2014
Close Date: 06/11/2014

Meter Reading:

Problem?

Very loud air leak on the airbag system. Once the truck is off it leaks all the air out of the system.

Parts	Quantity
-------	----------

Task performed:

1. check air leak, found r/side rear air bag had hole in it, replace both air bags

GUI1R11216GY1R11216 AIR BAG INT.	2
----------------------------------	---



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V67133

In Date: 06/11/2014
Close Date: 06/11/2014

Meter Reading: 138,049.00

Problem?

will not start, R-41

Task performed:

1. travel to sta-41, found vehicle running. crew plugged in charger, test battery's all failed, replace all 3 battery's check charging all ok. travel back to s/shop

Parts	Quantity
279LSS1250D-RING HANDLE W/LOCK 101280008	1
BATTERY EPA TAX BATTERY EPA TAX \$1.50 PER B/	3
HP-31D BATTERY 950CCA HP-31D	3

Workorder: V66993

In Date: 06/05/2014
Close Date: 07/03/2014

Meter Reading:

Problem?

The back up camera on Rescue 41 goes off at times when backing up, it flashes. Thank you !!

Task performed:

REPAIRED BAD CONNECTION ON BACK OF DISPLAY.

Parts	Quantity
NO PARTS USED	

Workorder: V67375

In Date: 06/22/2014
Close Date: 07/09/2014

Meter Reading:

Problem?

front cab ac not working. R41

Task performed:

Removed and replaced blower motor

Parts	Quantity
3674285C1 BLOWER MOTOR	1



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V67767

In Date: 07/08/2014
Close Date: 07/14/2014

Meter Reading: 139,975.00

Problem?

C inspection R41

Task performed:

1. C insp 2. check for air leak, found r/side brake hose had hole in it, replace both front brake hoses 3.replace pat. compt a/c filters 4. 110v a/c inop,low on freon, fill check for leaks, found at crimps, recrimp, refill recheck for leaks none found at this time

Parts	Quantity
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
474987HOSE AND FITTING	1
5774457744XD OIL FILTER	1

Workorder: V67567

In Date: 06/30/2014
Close Date: 07/16/2014

Meter Reading:

Problem?

leak in one side of air brakes

Task performed:

repaired on w/o#67767

Parts	Quantity
NO PARTS USED	

Workorder: V69036

In Date: 08/29/2014
Close Date: 09/19/2014

Meter Reading:

Problem?

top red emergency light bar is lose and hanging by conections.

Task performed:

TRIP TIX NOT CHARGING REPAIRED . REPAIRED RED LIGHT IN REA THAT WAS FALLING OFF.

Parts	Quantity
NO PARTS USED	



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V69151

In Date: 09/03/2014 Meter Reading:
Close Date: 09/19/2014

Problem?

screws missing for A/C filter grill under seat

Parts	Quantity
-------	----------

Task performed:

REPAIRED A/C GRILL ADJUSTED REAR AIR BAGS LEANING TO ONE SIDE.

NO PARTS USED

Workorder: V69931

In Date: 10/06/2014 Meter Reading: 146,971.00
Close Date: 10/28/2014

Problem?

low power

Parts	Quantity
-------	----------

Task performed:

1. Travel to station 42. Check engine code. VGT - change oil. No part at south shop. Bring unit to central shop. Change filter, road and performance tests. Passed, unit is in service.

5774457744XD OIL FILTER	1
-------------------------	---

Workorder: V70153

In Date: 10/09/2014 Meter Reading: 147,560.00
Close Date: 11/06/2014

Problem?

replace rear tires

Parts	Quantity
-------	----------

Task performed:

Replace rear tires

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V70695

In Date: 11/04/2014

Meter Reading: 149,211.00

Close Date: 11/13/2014

Problem?

B inspection R41

Task performed:

1. "B" inspection 2. Rear slack adjusters-replace 3. R/R rear brakes shoes and drums 4. Convert front hub from grease filled to oil bath hub and replace oil souls and inspect bearings. 5. R/R front brakes 6. Coolant leak at upper coolant hose-tighten clamps 7. R/R wipers 8. R/R fan clutch and air leaks at connectors at hub 9. Rear wheel seal leak-R/R wheel seal-remove hub. 10. Assist in brake replacement 11. Removed left rear wheels, drum axle, hub, seals and races and replaced paces, brqs and sea 12. Rear door latch inop-remove rear door panel, handel and latch. Replaced bottom door latch 13. R/R rear wheel bearings-removed both rear wheels drum, axle, hub seals and races-replaced seals, bearings and races-reassembled. 14. R/R F/right and R/ left window switches 15. R/R F left mirror holder 16. R/R Auto eject 17. R/R map light 18. Adjust air bags 19. Test drive R41 and clen up bay after repair.

Parts	Quantity
0915520120AUTO EJECT 20 AERO OTL3925	1
108653108563 COTTER PIN INT.	2
1878042C91FUEL FILTER 2008 HORTON	1
2505201C1CONTAINER	1
2506656C124316 WIX CAB A/C FILTER	1
3544936C6DOOR POD 2 DOOR OFFICER SIDE	2
370001ASEAL 35066	2
3753BRAKE DRUM RUMPER FRONT	2
3757REAR DRUMS 3757X 3647X	2
38780370023A SEAL	2
39520RACE	2
39590BEARING	2
47620RACE	2
47686BEARING	2
5774457744XD OIL FILTER	1
91-22WIPER BLADE	2
CHR1612340-4024 HUB COVER - FRONT AXLE 2004	2
E-2436R002436 GASKET-REAR AXLE	2
HOR994972FAN CLUTCH INT. 3611885C93	1
KSMA2124703QFRONTBRAKE KIT RUMPER AND 4D	2
LF18TS-LED MAP LIGHT LED 18 IN	1
LTC594111656-16 LATCH R/H MEDIC MASTER	1
R802446AUTO SLACK ADJ	1
R802447AUTO SLACK ADJ	1
XK3014707QPUSE XK4034707QPM QPLUS BRAKE S	2



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V70871

In Date: 11/12/2014 Meter Reading: 149,211.00
 Close Date: 11/13/2014

Problem?

R41 replace front tires

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:
 WORK REPAIR REQUESTED.

Vendor? BLVD TIRE CENTER

Workorder: V70571

In Date: 10/29/2014 Meter Reading:
 Close Date: 11/18/2014

Problem?

the driver side mirror folds in while driving. R41

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:
 Readjusted mirror and tested

Workorder: V70246

In Date: 10/18/2014 Meter Reading:
 Close Date: 11/20/2014

Problem?

Ferno stretcher needs to be fixed. Broken rear pneumatic patient positioning bracket broken.

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:
 Emsar called they will repair



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V70072

In Date: 10/11/2014 Meter Reading: 147,560.00
Close Date: 12/12/2014

Problem?

the rear wheel of the power stryker stretcher is broken (10175533)

Parts	Quantity
-------	----------

Task performed:
Stretcher repaired at Station 42.

NO PARTS USED

Workorder: V71805

In Date: 12/22/2014 Meter Reading: 152,803.00
Close Date: 12/29/2014

Problem?

no start

Parts	Quantity
-------	----------

Task performed:
1. No start-R/R batteries 2. Coolant leak, repaired coolant leak and road tested.

BATTERY EPA TAX	3
BATTERY EPA TAX \$1.50 PER B/	
HP-31DBATTERY 950CCA HP-31D	3

Workorder: V71891

In Date: 12/28/2014 Meter Reading: 153,421.00
Close Date: 01/09/2015

Problem?

please evaluate exterior safety reflective tape. it is peeling off and stripping due to weather. R41

Parts	Quantity
-------	----------

Task performed:
1. Checked strip and will monitor for replacement 2. Repaired stretcher latch

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V72281

In Date: 01/13/2015 Meter Reading:
Close Date: 01/13/2015

Problem?

Nail in front driver side tire.

Parts	Quantity
-------	----------

Task performed:

FF work pulled nail, tire ok at this time

NO PARTS USED

Workorder: V72033

In Date: 01/04/2015 Meter Reading:
Close Date: 01/20/2015

Problem?

Oil dipstick does not tighten down

Parts	Quantity
-------	----------

Task performed:

Repaired dip stick.

NO PARTS USED

Workorder: V72419

In Date: 01/18/2015 Meter Reading: 155,181.00
Close Date: 01/21/2015

Problem?

driver seat belt broken

Parts	Quantity
-------	----------

Task performed:

1. Driver seat belt lock broken. Travel to shop for part. Travel to station an remove broken seat belt receiver and install new part. Part hard to lock bu works temporarily. 2. Call back to station - lock jammed. Remove right rea receiver and temporarily install. Parts to be ordered.

NO PARTS USED



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V72423

In Date: 01/18/2015 Meter Reading:
Close Date: 02/05/2015

Problem?

the driver's seatbelt clip is broken. it fell apart when trying to buckle up. we tried to put it back together but can't.

Parts	Quantity
-------	----------

Task performed:

Removed and replaced driver's side front seat belt.

3711331C1SEAT BELT	1
3711355C91RECIEVER SEAT BELT BUCKLE WITH TI	1

Workorder: V73269

In Date: 02/19/2015 Meter Reading:
Close Date: 02/23/2015

Problem?

Driver's side rearview mirror is slipping from the frame and falling out of place. It can be returned to the proper position, but when under pressure it will slip again.

Parts	Quantity
-------	----------

Task performed:

Adjusted rubber isolator at joint support.

NO PARTS USED

Workorder: V73898

In Date: 03/16/2015 Meter Reading:
Close Date: 03/16/2015

Problem?

truck will not start R-41

Parts	Quantity
-------	----------

Task performed:

travel to sta-41, driver had truck running, stated truck would crank but not start, hook up laptop, found no codes replaced start relays, test battery's found 2 leaking acid, replace all 3 batterys, travel back to s/shop

1219360123-11276-041 RELAY VF28-35F14-Z05	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	3
HP-31DBATTERY 950CCA HP-31D	3



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V73375

In Date: 02/23/2015 Meter Reading:
Close Date: 03/31/2015

Problem?

Low air brakes, and possible air leak.

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

1. Traced out leaks and repaired.

Workorder: V74454

In Date: 04/06/2015 Meter Reading: 161,557.00
Close Date: 04/06/2015

Problem?

will not start, R-41

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

- travel to sta-41, cranks but will not start, hook up laptop no codes found, spray silicone to get started.travel back to s/shop

Workorder: V74169

In Date: 03/25/2015 Meter Reading:
Close Date: 04/22/2015

Problem?

The ABS warning light and Triangle symbole on the dash are constantly on

Parts	Quantity
-------	----------

NO PARTS USED

Task performed:

1. Traced out problem found front sencor needed to be adjusted.



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V73986

In Date: 03/18/2015
Close Date: 05/04/2015

Meter Reading:

Problem?

Leaking engine oil r41

Parts	Quantity
NO PARTS USED	

Task performed:

1. Repaired small oil leak at engine.

Workorder: V74113

In Date: 03/23/2015
Close Date: 05/04/2015

Meter Reading:

Problem?

back up sound indicator not working R41

Parts	Quantity
575BACKUP ALARM ECCO 107 DEC	1

Task performed:

1. Removed and replaced back-up alarm.

Workorder: V74114

In Date: 03/23/2015
Close Date: 05/04/2015

Meter Reading:

Problem?

ABS light indicator on R41

Parts	Quantity
NO PARTS USED	

Task performed:

1. Adjusted right front sencer for ABS light.



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V74470

In Date: 04/06/2015

Close Date: 05/14/2015

Meter Reading: 161,557.00

Problem?

C inspection R41

Parts

Quantity



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

Task performed:

1. Performed "C" inspection. 2. Continued/completed "C" Inspection. 3. Began removing oil pan to replace gasket (leaking). 4. Continued oil pan gasket replacement. Had to drop front axle to facilitate pan removal. Waiting on gasket from parts dept. 5. Removed oil cooler to reseal (leaking). Waiting on seal kit. 6. Began replacing air brake compressor (pumping oil). 7. Removed both front seats to be sent out for repair (ripped/torn). 8. Replaced break away arm on driver's mirror (broken). 9. Painted fuel caps (both). 10. Replaced brake pedal pad (worn/slick). 11. Replaced wiper blades. 12. Replaced cab fresh air filter and rear cab A/C filter. 13. Replaced all three patient compartment A/C filters. 14. Removed computer stand in cab. Repaired mounting tube, reinstalled stand. Adjusted all pivot points. Secured wiring pigtail going to laptop mount. 15. R&R driver's door panel, replace missing anchor clips that hold panel to door (falling off). While panel was off window mech. and door checked were lubed. 16. Replaced cab door hinges on both left side cab doors (worn/loose). 17. Began changing out door, check on left rear cab door (worn out/ had to R&R door panel). 18. Completed replacing door, check on left rear cab door (worn out). 19. Continued replacing air brake compressor. 20. Cleaned & flushed out oil coder. Received oil coder O-rings from parts and reinstalled cooler. Also cleaned and prepped block for reinstallation. 21. Began reinstalling oil pan with new gasket, cleaned c pan, bolts and engine block surface. Had to support truck with jack stands and lower front axle again to reinstall pan. 22. Began reinstalling air brake compressor, also replaced oil and coolant supply lines hoses. 23. Replaced belts. 24. Assist in installing new air compressor, help start bolts in sir pump. 25. Continued air brake compressor.

0775145PANEL FILTER	3
1830070C1GEAR AIR COMPRESSOR	1
1836197C1OIL PAN GASKET DT466	1
1836235C1COMP MOUNT GASKET	1
1839415C91OIL PRESSURE SENSOR	1
1841296C1GASKET	1
1841938C1REAR MAIN SEAL INT 466	1
1842124C94KIT OIL COOLER MTG	1
1842126C91SEAL KIT OIL COOLER	1
1845232C1HOSE	1
1847727C1BELT	1
1878042C91FUEL FILTER 2008 HORTON	1
2505695C1BRK PEDAL PAD	1
2506656C124316 WIX CAB A/C FILTER	1
2507061C1PS RESV GASKET	1
2507655C91MIRROR SUPPORT	1
3547564C2DOOR HINGE REAR	2
3549259C1DOOR HINGES R F	2
3551973C2REAR DOOR CHECK	1
3552184C3PIN	1
3555201C1PS HOSE NAVISTAR	1
3805943C1DOOR RETAINER	3
46870AIR FILTER	1
501542HOSE AND FITTING	62
5774457744XD OIL FILTER	1
78R539018-2699 A/C FILTER	1
91-22WIPER BLADE	2
A2254926000WASHER PUMP W/GROMMET	1
BX5014144XAIR COMPRESSOR 3596420C91 366359	1
K060705BELT HORTON	1
L2643655P/S HOSE 3/4	6



9/26/2016

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10175531

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT VEHICLE

VML/T1808D2503221C1 FILTER POWER STEERING

1

238