

Workorder: In Date: Close Date: Problem?	V184 10/12/2005 10/13/2005	Meter Reading:			
DOOR AJA	R LIGHT ON, A	AIR HORNS INOP, R-4	46	Parts	Quantity
	pection of equi	pment: Engine <i>P</i> o Drive Shaft	Air Compressor	NO PARTS USED	
Vorkorder:	V125				
n Date:	10/11/2005	Meter Reading:			
Close Date: Problem?	11/07/2005	• • • • • • • • • • • • • • • • • • •			
Problem?	11/07/2005 IDE NUMBERS	_		Parts	Quantity
Problem?	IDE NUMBER	_		Parts  NO PARTS USED	Quantity
Problem? MISSING S	IDE NUMBER:	_			Quantity
Problem?  MISSING S  Task perform  Vorkorder:	IDE NUMBER:	_	29,888.00		Quantity
Problem?  MISSING S  Task perform  Vorkorder: In Date: Close Date: Problem?	IDE NUMBERS med:  V487  11/05/2005 11/15/2005	S R-46	,		Quantity



Workorder: V1013

## **Palm Beach County Fire Rescue Fleet Maintenance Asset History** 10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Quantity

In Date: 12/27/2005 Meter Reading: Close Date: 12/28/2005 Problem?		
L/CORNER STROBE INOP, R-46	Parts	Quantity
Task performed:	NO PARTS USED	
Workorder: V1107 In Date: 01/02/2006 Mater Reading:		

FRONT AND	<b>REAR A/C</b>	<b>INOP</b>	. R-46

01/09/2006

Meter Reading:

Task performed: 11-26521487 SWITCH NC O 340 - C 210 HIGH PRES FTT5392USE 1432 SWITCH PRESSURE AC LO LIMIT

**Parts** 

Workorder: V1093

In Date: 01/03/2006 Meter Reading:

Close Date: 01/19/2006

**Problem?** 

Close Date:

**Problem?** 

REAR BACK UP CAMERA INOP, R-46 **Parts** Quantity

Task performed: **NO PARTS USED** 



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V1183

In Date: 01/13/2006 Close Date: 01/23/2006

Meter Reading:

Problem?

starter for service unit

Task performed:

Parts	Quantity	
190114036842 29MT 9 TOOTH STARTER	1	
38026169400BGASKET ENDCAP SUPER EDGE PLUS	1	
68118206050REND CAD RED SLIDER ADV DLUS LT F	1	



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V1243

01/20/2006 In Date: Close Date:

02/23/2006

Meter Reading:

34,752.00

Problem?

**B INSPECTION R46** 

**Parts** 

Quantity



\* ADVANCED LIFE SUPPORT VEHICLE

#### Task performed:

See B Inspection pre-printed form

1
1 1
1
1
1
·
1
8
8
1
1
4
2
2
2
1
4
1
1
1
1
2
1
1
2
2
1
1
2
2
1
1



Workorder:	V1440				
In Date: Close Date: Problem?	02/08/2006 02/24/2006	Meter Reading:			
NEED 4 Q1	TS MOTOR OIL	-, R-46		<u>Parts</u>	Quantity
Task perform	med:			NO PARTS USED	
Workorder:	V1618				
In Date: Close Date: Problem?	02/23/2006 03/20/2006	Meter Reading:	35,830.00		
A INSPECT	ΓΙΟΝ R46			Parts	Quantity
Task perfor	med:			203FFBEARING PULLEY 322502BULB PATIENT GH22	1 1
Workorder:	V1683				
In Date: Close Date: Problem?	03/01/2006 04/04/2006	Meter Reading:			
NEED LAR	GE NUMBER I	PLATE FOR SIDE OF	RESCUE R-46	<u>Parts</u>	Quantity
Task perfori	med:			NO PARTS USED	



Workorder: In Date: Close Date: Problem?	<b>V2324</b> 04/21/2006 04/24/2006	Meter Reading:		
BACK-UP (	CAMERA INOP	, R-46	Parts	Quantity
Task perforr	ned:		NO PARTS USED	
Workorder:	V2344			
In Date: Close Date: Problem?	04/24/2006 04/27/2006	Meter Reading:		
NEED HEA	DLIGHT R-46		Parts	Quantity
Task perforr	med:		NO PARTS USED	
Workorder:	V2351			
In Date: Close Date: Problem?	04/24/2006 04/28/2006	Meter Reading:		
A/C IN PAT	COMPT, INO	P, R-46	Parts	Quantity
Task perform	ned:		NO PARTS USED	



10156657

Vorkorder:	V2473			
n Date: Close Date: Problem?	05/03/2006 05/05/2006	Meter Reading:		
R/FRONT I	HEADLIGHT IN	IOP, R-46	Parts	Quantity
Task perfori	med:		H6054USE CV TYPE SEALED BEAM	1
Workorder:	V2584			
In Date: Close Date: Problem?	05/12/2006 05/23/2006	Meter Reading:		
PAT, A/C II	NOP, R-46		Parts	Quantity
Task perfori	med:		NO PARTS USED	
Vorkorder:	V2686			
n Date: Close Date: Problem?	05/20/2006 05/26/2006	Meter Reading:		
	ropping to grou	nd at exiting from rescue causing employee for safety	Parts	Quantity
Task perfori	med:		NO PARTS USED	



Workorder: In Date: Close Date: Problem?	<b>V2826</b> 06/06/2006 06/07/2006	Meter Reading:		
A/C INOP,	R-46		Parts	Quantity
Task perfori	med:		NO PARTS USED	
Workorder:	V2872			
In Date: Close Date: Problem?	06/05/2006 06/09/2006	Meter Reading:		
a/c out in fr	ont cab of resc	ue truck	Parts	Quantity
Task perform	med:		60027FAN A/C COND 12IN 860026-2-W	2
Workorder:	V2889			
In Date: Close Date: Problem?	06/06/2006 06/09/2006	Meter Reading:		
Camera no	t working while	backing up R46. Screen appears black again.	Parts	Quantity
Task perform	med:		NO PARTS USED	



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V2945

In Date: 06/12/2006 Close Date:

06/19/2006

Meter Reading:

42,952.00

**Problem?** 

B INSPECTION, R-46

Task performed:

Quantity **Parts** 

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0915520120AUTO EJECT 20 AERO OTL3925	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
322502BULB PATIENT GH22	1
40004-2A/C BRACKET	1
4867JB320 UPGRADE ALTERNATOR	1
52-24WIPER BLADES ANCO 24	2
6806970098SEAL DOOR	1
72R311018-2640 VENT A/C NEW # 1719	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
91513AMBER LENS	1
921LIGHT BULB	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	2
CA8193AIR FILTER 46744 WIX	1
DDE-5411870080GASKET OIL RETURN TUBE TURB(	1
DDE-9061801210FILTER HOUSING	1
FND3991FENDER FLAIR RUBBER PER FT	12
HOS40004BNNUT IDLER PULLY	1
R90PFILTER FUEL 33231	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1

Vendor? VC-15214



Vendor? TIRE0007

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10156657

Workorder:				
In Date: Close Date: Problem?	05/22/2006 06/29/2006	Meter Reading:		
	ropped during ronsar-medco)	emoval of patient-removed from truck (Outside	Parts	Quantity
Task perfor	med:		NO PARTS USED	
 Workorder:	V3088			
In Date: Close Date: Problem?	06/22/2006 06/29/2006	Meter Reading:		
replace ste	ering box (outsi	ide agency-freightliner)	Parts	Quantity
Task perfor	med:		NO PARTS USED	
Vendor?	FREI0006			
Workorder:	V3458			
In Date: Close Date: Problem?	07/13/2006 07/21/2006	Meter Reading:		
A INSPEC	TION AND REP	PAIRS AS NEEDED R46	Parts	Quantity
Task perfor	med:		CM3000DISPLAY BOARD HOSELINE	1



Vendor? AERO0002

# Palm Beach County Fire Rescue Fleet Maintenance Asset History 10156657

<b>V3575</b> 07/21/2006	Meter Reading:		
07/25/2006			
J BOLTS R46		Parts	Quantity
med:		NO PARTS USED	
V3596			
07/22/2006 07/31/2006	Meter Reading:		
		Parts	Quantity
med:		NO PARTS USED	
V3242			
06/30/2006 08/02/2006	Meter Reading:		
L/FRONT COM	IPT DOOR, R-46 (MEDIC MASTER)	Parts	Quantity
med:		NO PARTS USED	
	07/21/2006 07/25/2006 07/25/2006 J BOLTS R46 med: V3596 07/22/2006 07/31/2006 eed of a small # sk from the shop med: V3242 06/30/2006 08/02/2006	07/21/2006 Meter Reading:  UBOLTS R46  Meter Reading:  V3596  07/22/2006 Meter Reading: 07/31/2006  Deed of a small #46 plaque for the rear of the rescue. The rescue of the shop on 07/21/06 and didn't have one. R46  Meter Reading:  V3242  06/30/2006 Meter Reading:	07/21/2006 07/25/2006 Meter Reading:  D BOLTS R46  Parts  NO PARTS USED  V3596 07/22/2006 07/31/2006 Meter Reading:  Deed of a small #46 plaque for the rear of the rescue. The rescue of the shop on 07/21/06 and didn't have one. R46  med:  NO PARTS USED  Parts  NO PARTS USED  V3242 06/30/2006 08/02/2006 Meter Reading:



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder:	V3632
------------	-------

In Date: 07/25/2006

09/08/2006

**Close Date:** Problem?

repair or replace flat tire (outside agency-callaghan tire)

**Parts** 

Quantity

Task performed:

NO PARTS USED

Vendor? VC-15214

Workorder: V4224

In Date: 09/03/2006

Close Date: 09/11/2006

Meter Reading: 3,365.00

Problem?

The compartment on drivers side that the pro splints are in does not close right. It will not open by itself at this time. It looks like its not closed allI the way when you close it.R45

Meter Reading:

Task performed:

**Parts** 

Quantity

**NO PARTS USED** 

Workorder: V5252

In Date: 11/06/2006

Close Date: 11/07/2006 Meter Reading:

3,713.00

Problem?

Headlight out on R46

**Parts** 

Quantity

Task performed:

1. TRAVELED TO STN 46. INSTALLED ONE HEAD LIGHT.

H6054USE CV TYPE SEALED BEAM



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

**Parts** 

Workorder: V5349

In Date: 11/10/2006

3,730.00

Close Date: 11/27/2006

Problem?

B INSPECTION AND REPAIRS AS NEEDED R46

#### Task performed:

1. PERFORM PM "B". 2. MASTER POWER SWITCH HARD- NESS TO R/R SWITCH. 3. MARKER LIGHT INOP- NO POWER- WIRE FELL OFF NESS TO REMOVE INTERIOR & RECONNECT. 4. ROOF LIGHT AR LE INOP. R.R LED ASSEMBLY. 5. PT HIGH & FLOOR LIGHTS INOP. R/R BULBS. 6. COMP DOOR HOLD OPENS BROKEN R/R ASSEMBLY. 7. DOOR MOLDINGS LOOSE NESS TO REMOVE DOOR PANELS TO TIGHTEN SCREWS.

Meter Reading:

	<del>Quality</del>
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
05-17223-000CAP RADIATOR 10 LB	1
6809880678STUD DZ	2
6809940145CLIP	2
78R536078R5360M 2PK FILTER AIR COND	1
ACX-8453LUG CAPS WHEELED COACH # CH2732	40
R90PFILTER FUEL 33231	1

Workorder: V5401

In Date: 11/15/2006

--

12/08/2006

Meter Reading:

50.227.00

Close Date: Problem?

replace tires at callaghan r46

Parts

UNT7744USE PINK A/C FILTER MEDIC MASTER

Quantity

Quantity

#### Task performed:

1. SENT VEHICLE TO CALLGHAN TIRE FOR NEW TIRES.

Vendor?

CALLGHAN TIRE



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V5815

12/14/2006 In Date: Close Date:

12/15/2006

Meter Reading:

3,803.00

Problem?

door light/buzzer on all the time with doors closed

**Parts** 

Quantity

Task performed:

1. TRAVELED TO STN 46. FOUND SHORTED WIRE IN DOOR. R/R

WIRING.

NO PARTS USED

Workorder: V5948

In Date: 12/25/2006

Close Date: 01/03/2007 Meter Reading:

3,887.00

Problem?

pt compt A/C intermittently inoperative. begins working again if you slam the door on the evaporator cabinet in back. suspect a loose connection. R46

**Parts** Quantity

Task performed:

1. Checked connections and system tested ok

NO PARTS USED

Workorder: V6251

In Date: 01/12/2007 Close Date:

01/25/2007

Meter Reading:

3,990.00

Problem?

Drivers door does not open. Appears to need adjustment of latch. r46

Quantity **Parts** 

Task performed:

1. TRAVELED TO STN 46. ADJUSTED DRIVERS DOOR LATCH. TEST/

OK.



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V6252

In Date: 01/12/2007 Meter Reading: 3.990.00

Close Date: 01/25/2007

Problem?

Pt compartment A/C intermittently stops working. Starts working again if we slam the evaporator compt door. Suspect a loose connection, r46

slam the evaporator compt door. Suspect a loose connection. r46

Task performed:

1. TRAVELED TO STN 46. RAN REAR A/C FOR 15 MIN AND TESTED OK. CHECKED FOR LOSE WIRES AND FOUND NONE AT THIS TIME.

NO PARTS USED

**Parts** 

Workorder: V6293

In Date: 01/16/2007 Meter Reading: 4,051.00

Close Date: 01/25/2007

Problem?

rear ac intermittent R46 Parts

Task performed:

1. CHECKED PROBLEM WITH A/C FOUND H-BLOCK NEEDS TO BE REPLACED.

NO PARTS USED

Workorder: V6395

In Date: 01/22/2007 Meter Reading: 54,765.00

Close Date: 01/26/2007

Problem?

ON CALL A/C COMP 10-7 R46

Task performed:

071601A07-0602A DRIER A/C 7118 1 501-3090-00PRIMER PUMP MOTOR 1 532703-0602 COMPRESSOR U4735 4471 1

Quantity

Quantity

Quantity

**Parts** 



10156657

UNT1400BLOWER MTR. + SQU IRREL CAGE ASSY.

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V6448

In Date: 01/24/2007

02/02/2007

Meter Reading:

54,765.00

54,765.00

Close Date: Problem?

**REPAIR A/C HOSES R46** 

Task performed:

1. Removed hoses sent to Mako hose for rebuild. Installed and charged system. Fabricated support bracket for hose. 2. Installed new blower moto

Meter Reading:

Workorder: V6462

In Date: 01/25/2007

Close Date: 02/02/2007

Problem?

rear a/c 10-7

Task performed:

WORK PERFORMED ON TICKET V6448

**Parts** 

**Parts** 

Quantity

NO PARTS USED

Workorder: V6753

In Date: 02/14/2007

Close Date:

02/22/2007

Meter Reading:

56,050.00

Problem?

turn signals 10-7 (R46)

**Parts** 

Quantity

Quantity

Task performed:

1. TRAVELED TO STN 46. REPAIRED COVER FOR TURN SIGNALS.

TEST/ OK.



10156657 \* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V7255

In Date: 03/19/2007 Close Date: 03/19/2007

Meter Reading: 58,838.00

Meter Reading:

Meter Reading:

Problem?

ON CALL DOOR LATCH 10-7 R46

**Parts** Quantity

Task performed:

Replaced left rear compartment door latch

HND5948TM22676-02 HANDLE DOOR ENTRY

Quantity

Workorder: V7425

In Date: 03/29/2007

Close Date: 04/03/2007

Problem?

passenger seat does not go up and down. it is stuck in down position. R-46 **Parts** 

4,464.00

60,030.00

Task performed:

Repaired air line

NO PARTS USED

Workorder: V7509

In Date: 04/03/2007

Close Date:

04/12/2007

repair seat r46 central auto trim

**Parts** Quantity

Task performed:

Problem?

Repair seat R46 Central Auto Trim

NO PARTS USED

Vendor? CENTRAL AUTO TRIM



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V7471

In Date: 04/02/2007 Close Date: 04/13/2007

**Meter Reading:** 60,030.00

Problem?

B INSPECTION AND REPAIRS AS NEEDED R46

**Parts** 

Quantity



\* ADVANCED LIFE SUPPORT VEHICLE

#### Task performed:

1. B Inspection 2. Serviced air dryer 3. R&R water pump 4. Replaced belts, tensioner, and a/c pulley bearing 5. R&R If seat for repair 6. R&R batteries and jumper cables 7. R&R all door seals and moldings 8. Serviced a/c system. Replaced dryer and both a/c filters. Replaced broked diffusres 9. Repaired lights 10. Serviced front bearings 11. Replaced rear brakes and drums 12. Replaced all six tires 13. Torqued u-bolts 14. Replaced rf door entry light and wiring 15. Replaced exhaust fan in patient compt. 16. Replaced flouresents in patient compt. 17. Repaired air horns 18. Shop meeting

000090155133634 FUEL FILTER WIX MERCEDES	
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
0127110042BELT MERCEDES MOTORS	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
161657700065489 SHOCK REAR NEW RESCUE	2
1836267000VISOR RETRN	2
19282TAPE ANTI-SLIP PER FT 60FT ON ROLL	4
203FFBEARING PULLEY	1
2057LIGHT BULB	2
22512960001498 SWITCH BINA	1
29526898 29548988 TRANS FILTER ALLISON	1
2FC00ZCR4 IN ROUND LED	1
322502BULB PATIENT GH22	2
3744BRAKE DRUM REAR	2
52-24WIPER BLADES ANCO 24	2
6806970098SEAL DOOR	2
6808300074VENT A/C LH	2
6808300174VENT A/C RH	1
71R4040KNOB	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
91513AMBER LENS	2
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
A0631087000CABLE BATT. POS.	1
A0631088000CABLE BATT. NEG.	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	2
A22451940011499 SWITCH A/C HIGH PRESSURE NC	1
ACX-84534LUG NUT COVER PK10	2



\* ADVANCED LIFE SUPPORT VEHICLE

4
1
2
2
1
1
2
1
1
4
2
1
2
1

Workorder: V7662

In Date: 04/11/2007 Close Date:

04/18/2007

60,030.00 Meter Reading:

Problem?

install frame rail fishplate R46

Task performed:

Installed frame rail fishplate according to warranty recall notice.

Parts		Quantity

25-SF350-000L-SERT REINFORCEMENT



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V7725

In Date: 04/15/2007 Close Date: 04/30/2007

Meter Reading: 4,462.00

Problem?

back up cam does not work. R-46

Task performed:

Need new cables & screen. Replc cable & repaired power cable

Meter Reading:

Meter Reading:

60,030.00

61.850.00

Parts

Quantity

Workorder: V7516

In Date: 04/03/2007

Close Date: 05/04/2007

Problem?

replace tires at callaghan ent r46

Task performed:

Replace tires

Parts

Quantity

**NO PARTS USED** 

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V8181

In Date: 05/10/2007

Close Date: 06/01/2007

Problem?

NOISE IN ENGINE, R-46

**Parts** 

Quantity

Task performed:

Adjusted belts



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V9325

In Date: 07/16/2007 Meter Reading:

07/18/2007

827.00

665,795.00

5,013.50

Close Date: Problem?

> the back left door is getting stuck and it caused the inside door handle to break. The on call mechanic fix the handle, but it is still getting stuck on top may cause the handle to break again. R46

#### Task performed:

1. REMOVED REAR DOOR PANEL AND RESET ALL LINKAGE TO HANDLE.

NO PARTS USED

**Parts** 

Workorder: V9353

In Date: 07/16/2007

Close Date: 07/19/2007

**Problem?** 

on call r46 paitent door 10-7

#### Task performed:

1. R PT DOOR LOCK BROKEN. PART NOT ON TRUCK, GOT PART FROM SHOP, REPAIR WORK AT STATION, 2, OUT LATE ON CALL-0013 TO 0430. AUTHORIZED BY ED EHRKE TO COME IN AT 1200 HR

Meter Reading:

Meter Reading:

Par	rts									C	Quai	ntity	/
										_			_

Quantity

HND5948TM22676-02 HANDLE DOOR ENTRY SLD5366HT4932-16 DRAWER SLIDE 16

Workorder: V9462

In Date: 07/22/2007

Close Date: 07/24/2007

Rescue truck tries to start but will not turn over. Was fixed at the station by

the mechanic on-call, r46

#### Task performed:

Problem?

Fnd check eng light & no eng on dash called Mike; fnd grnds for ECM bad; repaired - ok

Quantity **Parts** 



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V9468

In Date: 07/23/2007

07/24/2007

.

Meter Reading:

67,032.00

Close Date: Problem?

ON CALL R46 WATER IN FUEL LT ON

Parts

Quantity

Task performed:

chkd for water in fuel; none found; faulty sensor; will repair Monday

Meter Reading:

R90PFILTER FUEL 33231

RAIRK30880N122WSKL4000 SENSOR WATER IN FU

1

Workorder: V9471

In Date: 07/23/2007

07/24/2007

67,032.00

Close Date: Problem?

ON CALL R46 COMP DOOR WONT OPEN

**Parts** 

Quantity

Task performed:

Rear door latch loose; adj door linkage & secured latch

NO PARTS USED

Workorder: V9511

In Date: 07/24/2007

Close Date: 07/30/2007

Meter Reading: 5,061.00

Problem?

R46 air dump is constantly leaking and dump alarm is going off.

Parts

Quantity

Task performed:

1. Fnd air leak at purge valve; rem purge valve & replaced 2. Rear door no opening; readj rear door linkage

800405PURGE VALVE KIT

.



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V9633

In Date: 07/30/2007 Close Date:

08/07/2007

Meter Reading: 67,592.00

**Problem?** 

r46 exhaust fan does not work in the back, r46

**Parts** 

Quantity

Task performed:

void duplicate order

NO PARTS USED

Workorder: V9736

In Date: 08/06/2007

Close Date: 08/09/2007

Problem?

5,095.40

right back passenger door is not closing and you have to slam it in order to close it. The timer light button in the back of the transport cab does not

Meter Reading:

work. R46

Task performed:

1. readjust door latch for right rear 2. replaced two bulbs in check out light

**Parts** 

Quantity



\* ADVANCED LIFE SUPPORT VEHICLE

**Parts** 

Workorder: V9754

In Date: 08/07/2007 Meter Reading:

68,068.00

Close Date: 08/21/2007

Problem?

B inspection and related repairs R46

#### Task performed:

B-Inspection 1. A/c UV bulb blown; rem/install new bulb 2. Power steering svc 3. Tailboard damage; diss, cut, pull to gather spread section of tailboard assy; reassemble 4. Weldup brackt tailboard 5. (1) hr VC; , tech meeting .75 6. Pat compt hi/lo, driver door light, mrkr light & L-2 door reflector blow bulb; bad ground; mk ness repaires 7. Door window molding, locks & hldopn damage; replc damage parts, sec loose locks 8. Pat compt jump seat belt sticking; adj seat belt position; not sticking low 9. pat compt exh vent louver msng; install new louver 10. Backup camer inor dia fault; fnd contrast & color knobs out of adj; adj/refocus Entry 11/9/07 11. B-Inspection & road test; Add (2) qt trans oil 8/7/07 3.5 hrs 8/8/07 2.5 hrs Total 6.0 12. Swap into o n-call svc truck 13. Cab AC Frt & rear blowing warm; chk/lk; none fnd; add freon; chk pressures & for leak; sys operating normal pressures & temperature 14. Pat comp AC not cooling down; cln evaporator coil; add 6 oz freon; sys operating normal

	Quality
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
921LIGHT BULB	2
98003RREFLECTOR RED 40132 GROTE	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	2
CA8193AIR FILTER 46744 WIX	1
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
H27W12VH27W12V BULB	2
HLD3999GSS1715UV 30LB STRUT GAS	2
HND5941USE HAN-1L METAL LATCH INTERIOR LOC	2
R90PFILTER FUEL 33231	1
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1

Quantity



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

NO PARTS USED

Workorder: V9772

In Date: 08/08/2007 Close Date: 09/07/2007

Meter Reading:

68,068.00

Problem?

REPLACE TIRES AT CALLAGHAN ENT R46

**Parts** Quantity

Task performed:

Replc tires - Callaghan

Vendor? CALLAGHN

Workorder: V10132

In Date: 08/27/2007

Close Date: 09/11/2007

Meter Reading:

69,133.00

Problem?

ON CALL R46 NO START

**Parts** Quantity

#### Task performed:

- 1. chk fnd btry low due to fuel leak(vapor leak); change btrys 2. Fuel filter had some water; chinge filter 3. start on fuel tank need to be chkd for wate
- 4. Start & run engine all is good at this time

4 BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/ HP-31DBATTERY 950CCA HP-31D

Workorder: V10387

09/11/2007 In Date: Close Date: 09/21/2007

Meter Reading:

70,009.60

Problem?

front a/c and patient compartment not blowing cold r46

**Parts** Quantity

#### Task performed:

Fnd cab A/C/ pressure low; added freon presure ok; coooling ok; (look like hose on compressor may be leaking but pat compt A/C compressor is going bad; Ed sent truck to shop



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V10323

In Date: 09/07/2007 Close Date: 09/26/2007

Meter Reading: 16.20

**Problem?** 

cardon monoxide alarm is beeping and the battery needs to be replace.

**Parts** Quantity

Task performed:

1. CHECK CARBON MONOXIDE ALARM, GREEN LIGHT O.K.

NO PARTS USED

Workorder: V10740

In Date: 09/28/2007

Close Date: 10/02/2007

**Problem?** 

R46 stretcher is not connecting to the locking mechanism in the back of the

Meter Reading:

unit when loading the pt into the unit. R46

Quantity **Parts** 

Task performed:

1. adjusted and lubed stretcher latch 2. FOLD DOWN STEP IN REAR NO

STAYING UP- REPAIRED HING

090-0278STRECHER BAR NEW

Workorder: V8639

In Date: 06/06/2007

Close Date: 10/15/2007 Meter Reading: 63,960.50

5,345.60

**Problem?** 

R46 exhaust fan for pt compartment not functioning and throwing node

malfuction notice to control screen in cab

Task performed:

1. installed new exhaust fan for rear compartment 2. readjusted rear box door

Quantity **Parts** 

ELB56711446175 BLOWER 4 IN



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V9535

In Date: 07/25/2007 Close Date: 10/15/2007

Meter Reading: 50,315.00

Problem?

right side, back passenger door is not closing properly, the door alarm is going off when the door is not closing properly, you have to close it several times in order for it to caught. R46

Task performed:

1. readjusted door linkage 2. installed new sender for wather and fule light

RAIRK30880N122WSKL4000 SENSOR WATER IN FU

Quantity

Workorder: V9572

In Date: 07/27/2007

10/15/2007

Meter Reading:

67,350.00

Close Date: Problem?

WATER IN FUEL LT ON R46

**Parts** Quantity

Task performed:

changed out sender unit

**NO PARTS USED** 

**Parts** 

Workorder: V10948

In Date: 10/10/2007

Meter Reading:

Close Date: 10/22/2007

Problem?

Onboard O2 leaking at valve where it screws into O2 tank. R-46

**Parts** Quantity

Task performed:

1. found no leaks 2. checked problem with backup camera and found bad connection on camera.



72,876.00

Palm Beach County Fire Rescue **Fleet Maintenance Asset History** 

10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V11253

In Date: 10/26/2007 Meter Reading:

11/06/2007

Close Date: Problem?

comp door 10-7 r46

Task performed:

1. Rep side door in rear of rescue 2. Air ride not level; readj air ride &

road test

Workorder: V11293

In Date: 10/29/2007 Meter Reading: 5,486.70

Close Date: 11/09/2007

**Problem?** 

r46 oxygen alarm is going off for no reason and the oxygen is reading @ a 1000. Also the front passenger is broken, the air pressure is not working.

Task performed:

1. Traced problem with O2 alarm going off; Fnd bottle empty - Replaced 2 Chkd R-side air ride seat; fnd air line kinked; rep & tested

**Parts** 

**Parts** 

NO PARTS USED

AS80697O2 REGULATOR-TRANSDUCER

Quantity

Quantity

Workorder: V10870

In Date: 10/05/2007 Meter Reading: 71,512.00

Close Date: 11/13/2007

repair stretcher R46 (outside agency-medco equipt repair)

Task performed:

**Problem?** 

Repair stretcher R46 - Medco Egpmt

Vendor? MEDCO

**Parts** 

NO PARTS USED

Quantity



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

NO PARTS USED

Workorder: V11516

In Date: 11/08/2007

Meter Reading: 5,585.70

Close Date: 11/14/2007

Problem?

Coolant reservoir appears low. No coolant visible in sight glass. r46

Parts Quantity

#### Task performed:

- 1. Pressure tested system and checked for leaks, found none at this time.
- 2. Adjusted air horns that were not working. 3. Repaired drivers side air ride seat that would not go up, found kinked line.

Workorder: V11781

In Date: 11/28/2007 Meter Reading: 75,174.00

Close Date: 11/30/2007

**Problem?** 

on call wont start r46

Parts Quantity

#### Task performed:

Intermittent no start; Air in fuel; replc pre filter cap & all fuel filters; brought to unit to shop to repair; ok j

0000900087DDE/A0000900087 FILTER HEAD SM ME	1
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
R90PFILTER FUEL 33231	1

Workorder: V11827

In Date: 11/30/2007 Meter Reading: 75,460.00

Close Date: 11/30/2007

Problem?

on call wont start r46

Parts Quantity

#### Task performed:

1. Traced problem with truck not starting; fnd problem w/auto eject 2. Replcd O2 gauge on bottle j

MG-C23SPMGC23 GAUGE 2



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V11865

In Date: 12/03/2007 Close Date:

12/03/2007

Meter Reading: 75,689.00

75,689.00

Problem?

ON CALL R46 WONT START

Traced prob lem w/no-start; fnd starter solenoid bad j

**Parts** Quantity

ESX120105112STARTER RELAY ESX-120-105112

Workorder: V11943

Task performed:

In Date: 12/06/2007

Close Date: 12/19/2007

Problem?

**Parts** Quantity replace bad starter r46

Task performed:

1. Replaced starter on rescue that would not start.

190114036842 29MT 9 TOOTH STARTER

Workorder: V12216

In Date: 12/24/2007 Meter Reading: 01/04/2008

77.275.00

Close Date: Problem?

Pt compartment check out light or switch is out E-46

**Parts** Quantity

Task performed:

1. Traced out problem with checkout lights, found bad connection. 2. Rear door hard to open, readjusted rear door linkage. 3. Checked for air leak found, leaks at rear tank.

Meter Reading:



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V11023

In Date: 10/15/2007 Close Date: 01/15/2008

Meter Reading:

72,371.00

Problem?

ON CALL REPAIR O2 LEAK R46

Parts Quantity

Task performed:

AS75600MONI-A01 O2 MINDER KIT

1

Workorder: V11119

In Date: 10/19/2007

Close Date: 01/15/2008

Meter Reading: 72,371.00

Problem?

install S.O.P. (middle section front bumper) R46

Parts Quantity

Task performed:

6808801370BUMPER CENTER 1
FREIGHTSHIPPING CHARGES 1

Workorder: V12331

In Date: 01/03/2008

01/16/2008

**Meter Reading:** 77,275.00

Close Date: Problem?

REPAIR O2 LEAK R46

Parts Quantity

Task performed:

1. Repaired regulator that was leaking. 2. Rear door hard to open adjusted rear door latch.



\* ADVANCED LIFE SUPPORT VEHICLE

**NO PARTS USED** 

Workorder: V12550

In Date: 01/13/2008 Meter Reading: 5,918.00

**Close Date:** 01/24/2008

Problem?

truck needs rear tires. wear bars showing on outside tires. R-46

Parts Quantity

Task performed:

1. Need rear tires.



\* ADVANCED LIFE SUPPORT VEHICLE

**Parts** 

Workorder: V12654

In Date: 01/17/2008 Meter Reading: 78,626.00

Close Date: 02/01/2008

Problem?

b inspection and repairs as needed r46

#### Task performed:

B-Inspection 2. Cln bay floor 3. Install glove butler on rear cab A/C 4. Replc wiper blades 5. Replc right/left frt T/S, side marker lens 6. Replc cal roof marker ight bulb 7. Replc L-Rear mud flap 8. Replc pat compt A/C filter 9. Replc both steer axle tires 10. Svc batrys 11. Secured frt cnter console 12. Assy, with Svc-B j

0000900087DDE/A0000900087 FILTER HEAD SM ME	1
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
15-22150-06OIL PLUG ADAPTER MBE900	2
15W40BSYN OIL BULK QTS	48
52-24WIPER BLADES ANCO 24	2
800405PURGE VALVE KIT	1
91513AMBER LENS	2
ACX-84534LUG NUT COVER PK10	4
B2420LP-SMUD FLAP 24 X 24	1
P1147GFUEL FILTER 33120 WIX DELCO TP916	1
PH3612WIX 51970 OIL FILTER L/F LFP911	1
R90PFILTER FUEL 33231	1
SPRGW2612WASHER NOZZLE W/RELIEF	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1

Quantity



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V12563

In Date: 01/14/2008 Close Date:

02/06/2008

Meter Reading: 89,069.00

Problem?

replace tires at sta 46

Task performed:

Replace tires at Stn46 - Callaghan j

Vendor? CALLAGHAN

Workorder: V12771

In Date: 01/23/2008

Close Date: 02/06/2008

79,211.00

on call door open light on r46

Task performed:

Problem?

1. Called out to station 46 to replace passanger front door alarm switch

Meter Reading:

Meter Reading:

**Parts** 

**Parts** 

NO PARTS USED

Quantity

Quantity

918220BSOLETE USE SERV TKS SWITCH - DOOR

Workorder: V3089

In Date: 06/22/2006

02/07/2008

Close Date: Problem?

REPLACE 6 TIRES, R-46 (CALLAGHAN)

**Parts** 

Quantity

Task performed:



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Worl	korder: \	/1	131	197	7
****	NOIGEI.		J	IJ	

In Date: 02/12/2008

02/13/2008

Meter Reading:

Close Date: Problem?

a/c unit in cab blowing hot air. r46

Parts Quantity

#### Task performed:

1. A/C inop in lab, ran A/C and found no problem with A/C 2. Rear door not opening in rear adjusted linkage

NO PARTS USED

Workorder: V12881

In Date: 01/28/2008

Close Date: 02/21/2008

**Meter Reading:** 79,631.00

Problem?

replace tires at callaghan r46

Parts Quantity

Task performed:

Replace tires R46 - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V13460

In Date: 02/25/2008

02/26/2008

Meter Reading: 81.532.00

Close Date: Problem?

PAT. A/C INOP, R-46

Parts Quantity

Task performed:

Recharged patient A/C & clnd condenser fans. j



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V13337

In Date: 02/19/2008 Close Date:

03/03/2008

Meter Reading: 81,159.00

The spring is broken that holds the compartment door on the driver side r46

**Parts** 

Quantity

Task performed:

Problem?

1. Replaced hold open spring that was broken

HLD374211 IN HOLD-OPEN 30LB

Workorder: V13723

In Date: 03/06/2008

Close Date: 03/20/2008 Meter Reading: 6,227.00

**Problem?** 

The brake line is still leaking. The Rescue doesn't want to go when you put

into drive.

**Parts** 

Quantity

Task performed:

1 REPLACED HEADLIGHT 2 CHECKED FOR AIR LEAKS, FOUND AIR

DRAIN, REPAIRED AND TESTED

9006XSLLHEADLAMP M2 HI

2

Workorder: V13835

In Date: 03/12/2008 Close Date:

03/20/2008

Meter Reading:

82,773.00

**Problem?** 

**PAITENT A/C 10-7 R46** 

**Parts** 

Quantity

Task performed:

1. Found broken belt for A/C, replaced belt and ran OK

9425BELT MERCEDES RESCUE 12.5X1075 OE



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V13928

In Date: 03/17/2008 Close Date: 03/24/2008

Meter Reading: 83,395.00

Problem?

brake It on dash staying on r46

Parts Quantity

Task performed:

1. traced out air leaks-found valve leaking, removed and replaced.

Meter Reading:

800034VALVE PARKING BRK. 2

Workorder: V14205

In Date: 04/01/2008

Close Date: 04/11/2008

Problem?

turn signal and hazard lights not working E46 Parts Quantity

Task performed:

turn signals plug was unplugged

NO PARTS USED

Workorder: V14409

In Date: 04/11/2008

04/22/2008

Meter Reading: 6.464.30

Close Date: Problem?

R46 Left turn and Right turn indicator lights is not working.

Parts Quantity

Task performed:

1. found unit unpluged from steering colum.



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V14518

In Date: 04/17/2008 Close Date:

04/23/2008

Meter Reading: 85,458.00

Problem?

REAR TAIL LIGHTS INOP, R-46

**Parts** Quantity

Task performed:

1. tail lights out traled out problem with tail lights found bad connection.

Meter Reading:

NO PARTS USED

Workorder: V14608

In Date: 04/22/2008

Close Date: 05/07/2008

Problem?

repair seat belt headlight out **Parts** Quantity

Task performed:

1. replaced headlight. 2. found no problem with seatbelt.

H4656USE CV TYPE HEAD LIGHT

Workorder: V14941

In Date: 05/08/2008

05/16/2008

86,961.00

85,678.00

Close Date: Problem?

r46 doom lights in the back of transport cab is not working properly R46

Meter Reading:

**Parts** Quantity

Task performed:

1. traced out problem with pt lights found bad connection



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V15062

In Date: 05/13/2008 Close Date:

06/09/2008

Meter Reading: 87,153.00

Problem?

get a bracket on drivers side compartment for air pack R46

**Parts** 

Quantity

Task performed:

Will have BC order pack. j

NO PARTS USED

Workorder: V14717

In Date: 04/28/2008

Close Date: 06/11/2008

Problem?

replace rear tires r46

**Parts** 

Quantity

Task performed:

Replace reat tires R46 - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

Workorder: V15694

In Date: 06/12/2008

Meter Reading: 6.736.00

86,259.00

Close Date: 06/27/2008

Problem?

Pt compartment lighting has 2 lights out on passenger side - these are the main ones, not the checkout lights. r46

Meter Reading:

**Parts** 

Quantity

Task performed:

1. Replc (2) pat light in rear of rescue. 2. Compt lights inop; trce out problem; fnd bad connection. j



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V15069

In Date: 05/14/2008 Meter Reading: 87,153.00

Close Date: 07/01/2008

Problem?

The a/c fan is not working under the back passenger door and it causing the pt compartment not to cool down so you have to hit the reset button R-4

Parts Quantity

Task performed:

replc condesnro fan motor & tested. j

RD571290 01-2616 MOTOR 12V 73R-0542 3512

Workorder: V16159

In Date: 07/04/2008 Meter Reading: 6,858.00

Close Date: 07/18/2008

**Problem?** 

THE WATER IN THE FUEL LIGHT KEEPS FLASHING ON R46. Parts Quantity

Task performed:

Installed new fuel sensor & tested. j

RAIRK30880N122WSKL4000 SENSOR WATER IN FU

Workorder: V16440

In Date: 07/18/2008 Meter Reading: 90,947.00

Close Date: 07/28/2008 **Problem?** 

replace front tires at shop r46

Parts Quantity

Task performed:

REPLACE FRONT TIRES AT SHOP r46 - cALLAGHAN J

NO PARTS USED

Vendor? CALLAGHAN



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V16486

In Date: 07/21/2008 Meter Reading: 6,906.00

Close Date: 07/29/2008

**Problem?** 

Camera wires are switch when you back up it shows the inside of the transport cab. The lights does not come up on with the check out light in the transport cab. r46

Task performed:

1. repaired back up camera that wires were backwards

NO PARTS USED

**Parts** 

Workorder: V16736

In Date: 07/31/2008 Meter Reading: 6,941.60

Close Date: 08/01/2008

**Problem?** 

fan belt squeeling, check out lights in patient compartment not working, ac in back compartment not working (on/off), o2 tank regulator is cracked, o2 alarm is going off with full tank. R46

Task performed:

1. Chk belts, tighten A/C belt. 2. Rep check out lights. 3. Rep pat compt A/C. j

Parts Quantity

Quantity

MG-C23SPMGC23 GAUGE



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V16279

In Date: 07/10/2008 Meter Reading: 90,816.00

Close Date: 08/04/2008

**Problem?** 

c inspection and repairs as needed r46

**Parts** 



\* ADVANCED LIFE SUPPORT VEHICLE

#### Task performed:

C-Inspection 2. Fuel Cap. 3. Replc eng air filter. 4. Sec access door latch inside of pass frt cab door. (loose, fall off). 5. Replc all (4) door weatherstrips (torn). 6. Svc cooling sys; (had to change out empty coolant barrel). 7. Repld btry switch. 8. Replc all (4) batteries. 9. Replc RT, upper, side body marker. 10. Replc both turn signal side marker lenses (cracked). 11. Replc rear cab A/C filter 12. Replc pat compt A/C filter. 13. Replc belts 14. Svc air dryer. 15. Replc rear brake shoes/drums. 16. installed/adjusted right side steering stop. 17. Replc flag stickers on rear o body (faded). 18. Replc driver's seat belt. 19. Replc both pat compt inner entry door latch bezels (cracked). 20. Replc wiper blades. 21. Install velcre in O2 compt for O2 wrench. 22. Replc left/right outer A/C vent defusers (broken). 23. Replc monitor for backup camerajk

0000900087DDE/A0000900087 FILTER HEAD SM ME	1
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
0127110042BELT MERCEDES MOTORS	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
15W40BSYN OIL BULK QTS	24
3744BRAKE DRUM REAR	2
52-24WIPER BLADES ANCO 24	2
680-10LAMERICAN FLAG W UV CLEAR LEFT	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
6806970098SEAL DOOR	1
6808300074VENT A/C LH	1
6808300174VENT A/C RH	1
75908SWITCH BATTERY MASTER 300A	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
91513AMBER LENS	2
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
ACX-84534LUG NUT COVER PK10	9
AEVDOOR LOCK BEZEL	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
CA8193AIR FILTER 46744 WIX	1
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
HP-31DBATTERY 950CCA HP-31D	4
IMMF11358SEAT BELTS	1
KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2
R90PFILTER FUEL 33231	1
TDA13X163NUT-LOCK	1
TDA26X1017BOLT STR STOP	1



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

					_
				UNT7744USE PINK A/C FILTER MEDIC MASTER	1
Vorkorder: n Date: Close Date: Problem?	V16698 07/30/2008 08/04/2008	Meter Reading:	91,616.00		
BELT NOIS	E, E-46			Parts	Quantity
Task perforn Readjusted				NO PARTS USED	
Vorkorder:	V17111				
n Date: Close Date: Problem?	08/18/2008 08/20/2008	Meter Reading:			
Blinkers/haz	zard lights not	working at all. R46		Parts	Quantity
Task perforn check and r		als. found wiring harn	ess plug loose at lever.	NO PARTS USED	
Vorkorder:	V17477				
n Date: Close Date: Problem?	09/03/2008 09/08/2008	Meter Reading:	93,206.80		
on call r46 t	urbo hose cam	ne off		Parts	Quantity
Task perforn r/r hose clar				01-20152-00501-20152-006 CLAMP	1



Workorder: V17357

### Palm Beach County Fire Rescue Fleet Maintenance Asset History 10156657

\* ADVANCED LIFE SUPPORT VEHICLE

NO PARTS USED

Close Date: Problem?	08/27/2008 09/22/2008	Meter Reading:	7,056.00		
Air horn no	t working. r46			<u>Parts</u>	 

Workorder: V17529

Adjusted air horns. j

Task performed:

In Date: 09/05/2008 Meter Reading:

Close Date: 09/30/2008

Problem?

Recue vehicle won't start,unit is out of service at the station. R46

Parts

Quantity

Task performed:

No start, found auto eject plug not popping out, repaired auto eject.

0915520120AUTO EJECT 20 AERO OTL3925

Quantity

Workorder: V16066

In Date: 06/30/2008 Meter Reading:

Close Date: 10/01/2008

r46 holto are equadin

r46 belts are squealing Parts Quantity

Task performed:

Problem?

1. Adj belts & road tested 2. Adj rear door latch that was not openig from inside. j



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

W	orko	rder:	V1	827	72
A A	UINU	nuci.	v		_

In Date: 10/10/2008 **Close Date:** 

10/28/2008

Meter Reading: 7,456.00

Problem?

left front headlight out. brights work R46

Task performed:

1. installed new headlight & dropped off spares. 2. 110 A/C inop; fnd short

in 110 plug; rep plug & tested. j

Workorder: V18273

In Date: 10/10/2008

10/31/2008

Meter Reading:

7,456.00

Close Date: **Problem?** 

Scba bracket for L1 compartment. Chief Wells and Chief Moser approved.

They told me to get it done. R46 Thanks Frank

Task performed:

Installed air b ottle in L-1 compartment. j

**Parts** 

**Parts** 

NO PARTS USED

Quantity

Quantity

**KD-UN-5-SFUSE 6-SF BRACKET** 

Workorder: V18905

In Date: 11/07/2008

Close Date: 11/17/2008 Meter Reading:

7,394.00

Problem?

r46 has been stalling out 3 times today on nov. 6, 2008. the engine just shuts off when you are at a stand still.

Task performed:

1. Chkd out stalling; problem fnd date link codes; chkd over all ECM connections from btrhys to ECM; road tested; cld not reproduce problem.

2. Chkd eng stumble problem; assisted chkng with connections & power &

**Parts** 

Quantity



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V18768

In Date: 11/01/2008

Close Date: 11/18/2008

**Problem?** 

While enroute to the hospital R46 stalled in the middle of the road. The EM had to shut the entire truck down including the ignition and battery inorder for the truck to turn back on.

7,394.00

97,405.40

Meter Reading:

Task performed:

Road tested; chkd all connectins & tested ok. j

NO PARTS USED

Workorder: V18888

In Date: 11/06/2008 Meter Reading:

Close Date: 12/01/2008

**Problem?** 

Main O2 leaking R46

Task performed:

Chkd for leaks; fnd no leaks at this time. j

**Parts** 

**Parts** 

Quantity

Quantity

**NO PARTS USED** 

Workorder: V19245

In Date: 11/21/2008

Close Date: 12/01/2008

Problem?

repair electrical problem r46

#### Task performed:

1. T-Shoot eng cut-out; bad eng harness; R/R harness; multiple test orifice to confirm complaint & repair. 2. Fnd faulty air discharge lines; R/R line. 3. Made up new hoses. j

Meter Reading:

**Parts** Quantity

29543432INPUT SENSOR ALLISON A06-31001-000HARNESS ENG. DDE/RA0004464335VCU FREIGHTSHIPPING CHARGES



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V19382

In Date: 11/28/2008

Meter Reading: 3.40

Close Date: 12/03/2008 Problem?

turn signals/emergency flashers not functioning. R-46

**Parts** Quantity

Task performed:

Turn signal warning light inop; fnd loose swtch connection; properly

secure switch & wire harness. j

12/11/2008

Workorder: V19659

In Date: 12/10/2008

Meter Reading: 98,523.00

Close Date: Problem?

> on call unit shut off r46 **Parts** Quantity

Task performed:

Chkd codes & T-shoot; possible bad PDL. j

NO PARTS USED

NO PARTS USED

Workorder: V19476

In Date: 12/03/2008

12/16/2008

Meter Reading: 98,173.00

Close Date: Problem?

> back up alarm 10-7 r46 **Parts** Quantity

Task performed:

1. Backup alarm inop; fnd bad connection. 2. 02 leak; fnd fitting in rear

leaking. j



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V19514

In Date: 12/04/2008 Meter Reading:

Close Date: 01/02/2009

**Problem?** 

repair rear eme light Parts

98,173.00

Task performed:

1. Coolant leak; fnd hose clamp leaking; rep clamp. 2. Chk tires; replcd all

(4) rear tires. j

Workorder: V19975

In Date: 12/26/2008 Meter Reading: 7,470.00

**Close Date:** 01/05/2009 **Problem?** 

Siren begins sounding all by itself while driving. Electrical problem in steering column?? Turned siren off at switch. Truck not in service yet. R46

Task performed:

Rep short in steering column that was shorting out siren. j

**Parts** 

Quantity

Quantity

**NO PARTS USED** 



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

**Parts** 

Workorder: V19848

In Date: 12/18/2008 Meter Reading: 98,523.00

**Close Date:** 01/07/2009

Problem?

#### B INSPECTION AND REPAIRS AS NEEDED R46

#### Task performed:

B-Inspection 2. Replcd faulty purge valve; now not purging at all; chk gov; replcd gov; purge valve wrkng properly. 3. Assist w/purge system opns. 4. Replcd faulty R-frnt siren speaker. 5. Repld faulty city horns. j

0000900087DDE/A0000900087 FILTER HEAD SM ME	1
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
15W40BSYN OIL BULK QTS	24
284358GOVERNOR D-2	1
800405PURGE VALVE KIT	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
A0631117000HORN HIGH NEW # 06-52125-039	1
A0631117003HORN LOW NEW #06-52125-041	1

Quantity

Workorder: V19688

In Date: 12/11/2008 Meter Reading: 98.523.00

Close Date: 01/08/2009 Problem?

repair electrical problem r46

#### Task performed:

1. T-shoot eng cut-out. 2. Inspected Tim 's car for poss recall. 3. Test drove to confirm repair. j

Quantity **Parts** 

**NO PARTS USED** 

R90PFILTER FUEL 33231

SD-210RXSIREN DRIVER SMALL



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V19765

In Date: 12/15/2008 M Close Date: 01/13/2009

**Meter Reading:** 98,523.00

Problem?

tow unit to ft pierce fla detroit sisters towing

Parts Quantity

Task performed:

NO PARTS USED

**Parts** 

Vendor? SISTERS TOWING

Workorder: V20065

In Date: 01/01/2009 Meter Reading: 7,470.00

Close Date: 01/27/2009

Problem?

When lights are on and siren is off is you turn the steering wheel the siren

will turn on automatically on its own

Task performed:

1- Found short in steering colom, ordered parts.

Workorder: V20066

In Date: 01/01/2009 Meter Reading: 7,470.00

Close Date: 01/27/2009

Problem?

Siren activates on its own, usually when turning a corner. Tommy repaired

once, but problem has recurred. R46

Task performed:

1- Ordered parts for siren.

Parts Quantity

Quantity

NO PARTS USED



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

SPT6008146SL LIGHT-REMOTE SPOT

Workorder: V20060

In Date: 12/31/2008 Close Date:

02/04/2009

Meter Reading: 7,470.00

Problem?

Spot light on R46 needs to be replaced after being ripped off.

**Parts** 

Quantity

Task performed:

Spotlight damaged-hit; replaced spotlight; went back to shop to get anothe

light. j

Workorder: V19610

In Date: 12/08/2008

02/19/2009

Meter Reading:

98,523.00

Close Date: Problem?

REPLACE REAR TIRES, R-46

**Parts** 

Quantity

Task performed:

Replace rear tires R46 - Callaghan j

Vendor?

CALLAGHAN

Workorder: V20854

In Date: 02/03/2009

02/19/2009

Meter Reading:

7.645.00

Close Date: Problem?

right turn signal not working R47

**Parts** 

Quantity

Task performed:

turn signals out; fnd unplugged. j

NO PARTS USED



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V20940

In Date: 02/07/2009 Meter Reading: 7,707.00

Close Date: 02/19/2009

Problem?

Belt is making noises when you accelerate. hands free needs to be fixed fo

siren noise, but the horn does work. R46

Task performed:

Belts making noise; fnd A/C condenser fans nop; rep fans & road rtested;

all tested ok. j

Workorder: V21019

In Date: 02/10/2009 Meter Reading:

Close Date: 02/19/2009

Problem?

a/c is not blowing cold air inside the quad cab and door handle is sticking

Meter Reading:

7.731.80

102,917.00

on the transport door in back of unit r46

Task performed:

rear door inop; readj rear door inkage. j

Workorder: V21222

In Date: 02/20/2009

Close Date: 02/24/2009

Problem?

ON CALL A/C 10-7 R46

Task performed:

Go to Stn; c hk A/C not cold; chk charger sys; look for leak. j

Parts

NO PARTS USED

**Parts** 

NO PARTS USED

Parts

R134AFREON LB

2

Quantity

Quantity



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V20118

In Date: 01/05/2009 Meter Reading: 7,527.40

Close Date: 02/25/2009

Problem?

The Oxygen gauge is not working properly in the side oxygen compartment and the timer button which turns on the light in the transport compartment is not working R-46

#### Task performed:

1. 02 leak. 2. Siren coming on; rem steering wheel & replcd horn & siren sleeve. 3. C/O light out inop. j

680-462-00-89HOUSING	1
680-464-00-27CAP HOUSING	1
MG-C23SPMGC23 GAUGE	2
PAC/12015987HOUSING	1
RGT/451656B7X1HORN CONNECTOR	1

Quantity

Workorder: V21090

In Date: 02/12/2009 Meter Reading: 7,731.80

Close Date: 02/25/2009

Problem?

The turbo or the fan is making a loud noise when you accerate and you smell something burning afterward as well R-46

#### Task performed:

1. Siren inop; replcd siren head. 2. Road tested for noise; fnd no noise. j

Parts	Quantity
295SLSA1SIREN	1

**Parts** 



Air condition in front cab is blowing hot air. r46

Recharged unit & chkd for leaks. j

Task performed:

## Palm Beach County Fire Rescue Fleet Maintenance Asset History 10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V19914 In Date: 12/22/2008 Meter Reading: 98,523.00 Close Date: 03/06/2009 Problem? reprogram vcu r46 **Parts** Quantity Task performed: NO PARTS USED Vendor? FL DETROIT Workorder: V21594 In Date: 03/06/2009 Meter Reading: 7,882.00 Close Date: 03/26/2009 Problem? Quantity r46 front a/c is not working **Parts** Task performed: NO PARTS USED Recharged A/C unit & clnd A/C condensor fans. j Workorder: V21724 In Date: 03/11/2009 Meter Reading: 104,583.00 Close Date: 03/26/2009 Problem?

**Parts** 

NO PARTS USED



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V21739

In Date: 03/12/2009 Meter Reading:

Close Date: 03/26/2009

Problem?

R46 front passenger seat needs to be fix, it wont's stay up. Also the front

cab a/c needs freon. A/C is not blowing cold air.

Task performed:

1. A/C inop; recharged cab A/C. 2. Rep air ride seat that was not working.

Meter Reading:

7.969.00

7,969.00

Workorder: V21918

In Date: 03/18/2009

Close Date: 03/26/2009

Problem?

Roof leak above front passenger. Getting wet when it rains!!!! r46

Task performed:

Resealed top marker ights. j

Workorder: V21932

In Date: 03/19/2009 Meter Reading:

Close Date: 03/27/2009

**Problem?** 

Water leaking inside of driver compartment, AC not cooling properly. R46

Task performed:

Sealed top cab roof for leakage of watr. j

**Parts** 

**NO PARTS USED** 

**Parts** 

NO PARTS USED

NO PARTS USED

**Parts** 

Quantity

Quantity



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V21946

In Date: 03/19/2009 Meter Reading: 105,361.00

Close Date: 04/13/2009

Problem?

#### C INSPECTION AND REPAIRS AS NEEDED R46

#### Task performed:

C-Inspection 2. Go to shop for parts/supplies. Shop meeting & PU parts. 3. Pulls to the right-tires; swapped tires & road tested - corrected pull. 4. Steering off center; rem steering wheel shaft & nut stripped; rep thrds & installed new wheel. 5. Cab A/C inop; multiple leaks; went to shop & replo hoses; rep air leaks. 6. Btry box hard to open; svcd track. 7. Several compt doors hard to open & panels loose; stripped/msng screws; svc/rep rear doors. 8. Water leak in cab; rem headliner to find leak; fnd/replc (2) leaks. 9. Side door grip tape worn; installed new grip tape. 10. Backup camera inop; connector loose in dog house; reconnected. 11. Needs wipers/washers-inop; installed new wiperblades & clnd out nozzle lines & tank. 12. Coolant low; loose hose clamps; adj coolant protection level & tightened clamps. 13. Several pat compt lights inop; installed bulbs as needed. 14. Pat compt A/C evap dirty; clnd evap/condensor. 15. Several medic drawers hard to operate; tracks loose & out of adj; tightened;adj tracks. 16. Several marker lights inop; installed bulbs as needed. 17. O2 sys leaks; nipple worn; installed new nipple. 18. Medic cab plate cracked; replc plexi glass. 19. Instrument cluster plastic cracked; replcd instrument plastic. i

Parts	Quantity
	1
0000900087DDE/A0000900087 FILTER HEAD SM MEI	1
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
2332920005SMASK LENS W/RST BUTTON VDO	1
52-24WIPER BLADES ANCO 24	2
6819634283068-1963428-30 LENS CLR	2
800405PURGE VALVE KIT	1
806050014900KNOB A/C FREIGHTLINER	1
906-181-00-86OIL FILTER M2 SPINNER 57140	1
CA8193AIR FILTER 46744 WIX	1
DOOR5-1USE WIDE SLOTE LEXAN 9X38 NARROW §	1
FND3991FENDER FLAIR RUBBER PER FT	6
GSS1717UL1717UL0270N 343/09 GAS SHOCK 60 LB	4
M54-13SPM5413 NIPPLE	1
R90PFILTER FUEL 33231	1
REG041462369 O2 REGULATOR	1



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: In Date: Close Date: Problem?	<b>V22326</b> 04/05/2009 04/17/2009	Meter Reading:	7,996.30		
front cab a/	c is not working	g R46		Parts	Quantity
Task perfori Truck sent	med: to south shop.	j		NO PARTS USED	
Workorder:	V22338				
In Date: Close Date: Problem?	04/06/2009 04/20/2009	Meter Reading:	7,996.30		
Air conditio	ner in driver's o	compartment not coolin	g properly r46	Parts	Quantity
	; compressor le from defective	eaking; located leak w/ı crimps. j 2. Discharge	nitrocer; also rep several sys; R/R compr asy;	533103-0607 A/C COMPRESSOR U4482 USE 7169 D	1
Workorder:	V21649				
In Date: Close Date: Problem?	03/09/2009 05/04/2009	Meter Reading:	104,398.80		
repair paitie	ent a/c r46			Parts	Quantity
Task perform		wire at hi-press swtch	; rep wiring. j	NO PARTS USED	



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V22828

In Date: 04/27/2009 Meter Reading: 8,107.00

Close Date: 05/05/2009

Problem?

Main O2 bottle in rescue not lasting after minimal calls run. Ex:bottle was refilled on 04/24/09, & used 3-4 times with NC @ 4-6 lpm during the last 3 days and is now reading low with the alarm. This morning it read 800 psi.

R-46

Task performed:

O2 leak chkd for leaks & fnd none at this time. j

NO PARTS USED

**Parts** 

Workorder: V22668

In Date: 04/20/2009 Meter Reading: 8,050.00

Close Date: 05/13/2009

Problem?

Officer's passenger seat will not stay in the up position. The air leaks out

somewhere. r46

Task performed:

1. Air leak; traced air leak & fnd air leaks & rep. 2. Coolant leak; press tested & rep leaks. 3. Wipers inop; fnd shorted fuse in fuse box. 4. Water leak in cab; resealed top of roof. j

Parts

Quantity

Quantity



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V23076

In Date: 05/05/2009 Meter Reading:

Close Date: 05/21/2009

Problem?

repair lightbar R-46

#### Task performed:

1. Trave to Stn & make rep to damaged light bar. 2. Rep ight bar. 3.

Installed new lens for light bar. j

**Parts** Quantity

2 9UCAPCC9UCAPCC END CAP CLEAR 2 9ULENSCCLEAR LENS FREEDOM BAR MAKJ29ADJ. LIGHT BAR MOUNT

PRMISCONLA PIERCER 2 DUAL STROBE

Workorder: V23313

05/16/2009 In Date:

Close Date: 05/26/2009

Meter Reading: 8.172.00

107,667.50

Problem?

BIG O2 tank attach connector on the side of the truck is leaking. The front

passenger seat is not staying up, it sits low. R46

#### Task performed:

1. C hkd for Os leaks & repaired. 2. Roof leaking water; resealed roof. j

NO PARTS USED

**Parts** 

Workorder: V23373

In Date: 05/19/2009

Close Date: 06/01/2009 Meter Reading: 8.220.60

Problem?

Replaced headlight. Need another spare bulb for high/low beam headlight.

**Parts** 

Quantity

Quantity

Task performed:

Spotlight inop; rep bad connection. j

H3-100WBP1210H3 BULB



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

W	ork	orde	r: V	<b>/241</b>	75
---	-----	------	------	-------------	----

In Date: 06/18/2009 Close Date:

07/06/2009

109,529.80

Problem?

rear back up Its 10-7 r46

**Parts** 

Quantity

Task performed:

Back-up lights inop; rep bad connection. j

Workorder: V24572

In Date: 07/05/2009

Close Date: 07/28/2009 8,974.00

Problem?

Front Cab a/c poor cooling. R-46

**Parts** Quantity

Task performed:

1. A/C warm; readj heater cable & tested. 2. O2 leak; traced out leak & fnc

Meter Reading:

Meter Reading:

leak bottle. j

NO PARTS USED

NO PARTS USED

Workorder: V25419

In Date: 08/10/2009

08/27/2009

Meter Reading:

114,430.20

Close Date: Problem?

REAR A/C INOP, R-46

**Parts** Quantity

Task performed:

1. Recharged rear A/C & tested. 2. Replcd rear stretcher latch. 3. Air leak;

fnd no air leak at this time. j



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V25748

In Date: 08/24/2009

Meter Reading: 1,239.00

1,239.00

Close Date: 09/21/2009 Problem?

front tires are low AIR PRESSURE

**Parts** Quantity

Task performed:

1. Chkd & refilled all tires w/air. 2. Rear A/C warm; recharged rear A/C. j

NO PARTS USED

Workorder: V25682

In Date: 08/21/2009 Meter Reading:

Close Date: 09/30/2009

Problem?

The floor mount stretcher lock that holds the stretcher in place in the back c

the unit is not holding the stretcher and it is loose.

**Parts** Quantity

Task performed:

1. Repld stretcher latch. 2. Rear A/C inop; cln condensor fans. j

090-0278STRECHER BAR NEW



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V26143

In Date: 09/09/2009 Meter Reading: 116,799.60

Close Date: 10/07/2009

**Problem?** 

C INSPECTION AND REPAIRS AS NEEDED R46

**Parts** 



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

#### Task performed:

C-Service 2. Replc all (4) btrys. 3. Replc rear axle air bags. 4. Cut/adj air bag leveling valve rods. 5. Replcd air tank pull cord drains w/petrock style drains. 6. Rebuilt air brake dryer. 7. Replcd rear brake shoes. 8. Replc exh manifold gskts, extract & replc brkn manifold mntng bolts; installed ne ech manifold. 9. Replcd fuel pump. 10. Replcd water pump & T-stats. 11. Replcd coolant line frm water pum to air brake compressor. 12. Replcd fuel return line & chk valve w/updated version. 13. Replc belts. 14. welded tog (2) brkn A/C mntng support brkts. 15. Replcd rear cab A/C filter. 16. Replcd wiper blades. 17. Replcd L/side T-signal side marker lite/lens. 18. Replcd R/side T-signal side marker lite/lens. 19. Replcd L/side cab roof mrkr lite bulb. 20. paint fuel cap. 21. Replcd non-skid tape on all cab steps 22. Replcd R/side mid cab strobe lite. 23. Tigthen hinge mnts on over the wheel compt. 24. Adj/lube/tightened all door latches, strikers & holdopens on body/cab. 25. Straightened/sec shelves in R1 compt. 26. Replcd inner door latch bezel asy w/up dated latch on pat compt side entry door. 27. Replcd inner door latch bezel asy w/updated latch on pat comp rear entry door. 28. R/R drivers seat to be sent out for rep 29. Sec SCBA brkt to R/rear seat back. 30. Replcd brkn tech panel cvr under R/side dash. 31. Reattach wshr fluid reservoir access door. 32. Sec pass frt door panl w/sheet metal screws. 33. Replcd (3) door weaterstipes. 34. Replcd drvr door outdoor hndle/ltch; sec inner door panel . 35. Replcd all (4) door trims. 36. Svc P/S. 37. Reinstalled new tires. 38. Replcd A/C compr pat compt; replcd shrader valve in hi-side svc port. 39. Replcd pat compt dome lite bulb. 40. Replcd flourescent wrk lite bulbs pat compt. 41. Adj stretcher lock. 42. Replc pat compt A/C filter. 43. Installed "out of svc" stickers. 44. Installed on/off vol knob AM/FM radio. 45. Recvr vac & recharge frt cab A/C to verify proper refrig charge. 46. Reattach window wthrstrip pass rear door. 47. installed msng lug nut cvrs. 48. Rem bungie cord frm trans cooler lines/fab clmp brkt to sec lines frm rubbing on fan belt. 49. Cln debris frm windshld wshr sgrtrs. 50. R/R steering wheel to straighten. 51. Rep faulty connection at monitor for backup camera. 52. Road test truck for all repairs. 53. Replcd turbo oil return tube gskt. 54. Replcd FR sticker on frt of hood. 55. Replcd L/R frt door (cab) jam latches 56. Replc both A/C condenser fans behind L/R cab step; also built new wiring harness for fans. 57. R/R dash to rep vent controls; replcd controler; replc temp cntrl cable; replcd blend door cable/adj linkage. 58.

0000900087DDE/A0000900087 FILTER HEAD SM ME	1
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	
0127110042BELT MERCEDES MOTORS	1
101-L-SS-RHD-RING	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	28
16-15762-00016-19471-000 AIR BAG	2
16-31438915 VALVE CORE A/C 3544706C1	1
18-29935-001RH DOOR LATCH NEW	1
18-45484-000LATCH L/H	1
22-49905-000CABLE HEATER	1
23-12337002RIVET PLASTIC	9
322502BULB PATIENT GH22	1
50R03ZCRLIGHT LED RED TIR 6	1
52-24WIPER BLADES ANCO 24	2
532703-0602 COMPRESSOR U4735 4471	1
5452AC FITTING	1
607141-05USE 61H01 COPMPARTMENT LIGHT	1
6806870807COVER FUSE PANEL	1
6806970098SEAL DOOR	1
6807600070HANDLE DOOR EXT L/H	1
6807600170HANDLE DOOR EXT. R/H	1
6808330631CABLE ASSY HEATER	1
78R536078R5360M 2PK FILTER AIR COND	1
800405PURGE VALVE KIT	1
9060910580FUEL PUMP GASKET M2	1
9060920510FUEL CHECK VALVE	1



\* ADVANCED LIFE SUPPORT VEHICLE

C/O R/frnt cab door lite inop; fnd brkn power wire at door jam; R/R door panel to replc wire. 59. C/O drivers door lite inop; fnd brkn power wire inside door; rewired. 60. Rep faulty cab door lite wiring L/rear door. 61. Replc pat compt L-1 dome lite asy. 62. Diss drvr door lock; adj/lube door lock. 63. R/R headliner to find wtr leak in roof; traced leaks to wiring harness for lite bar. 64. Rem lock/latch asy frm rear storage compt door; rebuild asy. 65. Replc heater control valve. 66. Road tested truck. j

9061420057SEAL RING EXHAUST MANIFOLD	2
9061421101EXHAUST MANIFOLD CENTER	1
9061421201EXHAUST MANIFOLD R/L	2
91513AMBER LENS	2
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	2
A1835899000HEADLINER	1
A9060901276A9060903376 FUEL LINE	1
A9062030102A9062037102 COOLANT LINE	1
ABPN83322930CONTROL HEAD AC/HEAT	1
ABPN83324191WATER VALVE OLD # KYS417266	1
ACX-84534LUG NUT COVER PK10	6
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
DDE-0052035975A0052032675 THERMOSTAT ELEMI	2
DDE-0076030102007603016102 WASHER OIL SEND	1
DDE-5411870080GASKET OIL RETURN TUBE TURB(	1
DDE-9062030180GASKET SOCKET TO HEAD M2	1
DDE-R0040910501FUEL PUMP M2	1
DDE/00009903150TURBO NUTS	4
DDE/9049900412EXHAUST BOLTS	12
DDE/9061420280USE A9261420080 EXHAUST MANIF	3
DDE/A0289976348TURBO ORINGS	1
DDE/R9062006201RA906200620 WATER PUMP REM	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
H50SN12BULB	1
HAN-1LBEZEL AND HANDLE	2
HP-31DBATTERY 950CCA HP-31D	4
HTS388SPRING HOSE CLAMP	1
KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2



Workorder: V26262

09/15/2009

10/14/2009

Replc all (6) tires - Callaghan j

CALLAGHAN

09/22/2009

10/15/2009

Repair seat R46 - Central Auto j

**CENTRAL AUTO** 

replace all 6 tires R46 (outside agency-tiresoles)

repair seat R46 (outside agency-central auto trim)

Meter Reading:

Meter Reading:

116,799.60

116,799.60

In Date:

Close Date:

Problem?

Vendor?

In Date:

Close Date:

Problem?

Vendor?

Task performed:

Task performed:

Workorder: V26407

## Palm Beach County Fire Rescue Fleet Maintenance Asset History 10156657

\* ADVANCED LIFE SUPPORT VEHICLE

R90PFILTER FUEL 33231	1
RD571290 01-2616 MOTOR 12V 73R-0542 3512	2
WKL0381DOME LIGHT WELDON 8046	1
Parts	Quantity
NO PARTS USED	
NOTALLO GOLD	
Parts	Quantity
NO PARTS USED	



\* ADVANCED LIFE SUPPORT VEHICLE

Quantity

Quantity

Workorder: V26950

In Date: 10/17/2009 Meter Reading: Close Date:

10/23/2009

**Problem?** 

r46 leaking oil, mechanic checked and didnt find anything

Task performed:

Ck oil; oil leve within specs; chk for codes; noned stored. j

NO PARTS USED

**Parts** 

**Parts** 

Workorder: V27013

In Date: 10/20/2009

Close Date: 10/27/2009

Problem?

on call check eng It on r46

Task performed:

Dia fault coolant code (42 count); press test sys; no leak fnd; ran unit fan; does engage; sys operating normal at this time. j

Meter Reading:

8,846.50

19,084.00



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

**Parts** 

Workorder: V27114

In Date: 10/22/2009 Meter Reading: Close Date:

10/27/2009

19,084.00

116,799.60

**Problem?** 

coolant leak r46

#### Task performed:

1. C/O for coolant leak. 2. Assist in cooling system repair - McIntosh. 3. R/side headlight out; rem blown bulb & install new headlight. 4. Replaced air brake compressor. 5. Rebuilt air dryer. 6. Clnd out air lines & air tanks (coolant residue). j

<del></del>	
05-17223-000CAP RADIATOR 10 LB	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
800405PURGE VALVE KIT	1
A0249972148SEAL	1
DDE-00000001069USE V007603014104 SEAL WASH	4
EXO3AH00015SPLUG RAD. DRAIN	1
H6054USE CV TYPE SEALED BEAM	1
RA9061301415AIR COMPRESSOR	1

Quantity

Workorder: V26773

In Date: 10/08/2009 Close Date:

11/23/2009

windshield wiper hose is disconnected and the belt is squealing e46

Meter Reading:

Quantity **Parts** 

#### Task performed:

Problem?

1. Rep wiper hose. 2. Chkd belts for making noise & chkd out ok. j



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V26817

In Date: 10/12/2009 Meter Reading: 8.812.00

Close Date: 12/04/2009

**Problem?** 

driver's side scba storage compartments need repairing due to an earlier accident against st#42 bay pole(YELLOW). Both compartments need bumpers and the front one of the two needs repair to open. R46

Parts Quantity

Task performed:

Rem damaged parts & will repair at B Inspection. j

NO PARTS USED

Workorder: V27225

In Date: 10/28/2009 Meter Reading: 8,888.00

Close Date: 12/04/2009

Problem?

R46 still leaking oil, about a cup over 24 hour shift. Also a belt has resumed squeeking. Anyone on R46 is familiar with the problems.

Parts Quantity

Task performed:

1. Oil leak; ran trk & fnd no leaks. 2. Rear backup lights inop; rep connection. j

NO PARTS USED

Workorder: V27578

In Date: 11/10/2009 Meter Reading: 8,949.90

Close Date: 12/08/2009 **Problem?** 

left headlight is out E46 Parts Quantity

Task performed:

Dropped off headlights. j

H4656USE CV TYPE HEAD LIGHT



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V26862

In Date: 10/14/2009 Meter Reading: 8,812.00

Close Date: 12/09/2009

Problem?

Windshield wiper hose that comes from the wiper blade is broken, where it

attaches to valve for pump. r46

Task performed:

1. Rep wiper hose. 2. Reseal top roof for leak. j

NO PARTS USED

Workorder: V28655

In Date: 12/29/2009 1.873.10 Meter Reading:

Close Date: 01/14/2010

Problem?

Oxygen is leaking from the middle of the guage that is connected to d tank.

**R46** 

Task performed:

Chkd for O2 leak; fnd no leaks. j

**Parts** 

**Parts** 

Quantity

Quantity

Workorder: V28076

In Date: 12/02/2009 Meter Reading: Close Date:

01/15/2010

9.041.00

driver rear inside tire will not hold pressure. fill it to 90psi, goes to 20psi in 2

shifts.R46

Problem?

Task performed:

Driver rear inside tire will nothold press; fill it to 90PSi; goes to 20PSI in

(2) shifts - Callaghan j Vendor? CALLAGHAN **Parts** 

Quantity

NO PARTS USED



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V29682

In Date: 02/03/2010 Meter Reading: 126,262.00

Close Date: 02/03/2010

Problem?

LEFT SIDE HEADLIGHT INOP, R-46

Task performed:

1. Replc L/side headlight. 2. Chk backup camera; driveer states works

Meter Reading:

120,677.70

1.873.10

intermittently; needs rear camera; will order. j

Workorder: V28087

In Date: 12/02/2009

02/22/2010

Close Date: Problem?

replace missing valve stem extension R46

Task performed:

1. Door open light on; fnd bad conection on btry & day door. 2. Rad

exhaust for heat protection. j

Workorder: V28732

In Date: 01/01/2010

02/22/2010

Close Date: Problem?

Rear door not closing right. Door is catching on floor/side? Door has to be

Meter Reading:

forced to close (Slamming shut). R46

Task performed:

1. Readj door linkage. 2. Rep stretcher latche. j

**Parts** 

H6054USE CV TYPE SEALED BEAM

Quantity

**Parts** 

010102WRAP 2 IN WIDE

Quantity

Quantity

**Parts** 



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

NO PARTS USED

Workorder: V29318

In Date: 01/21/2010 Meter Reading: 125,466.80

Close Date: 02/25/2010

Problem?

replace 4 tires R46 at sta 42 (outside agency-callaghan tire)

**Parts** Quantity

Task performed:

Replace (4) tires R46 at Stn42 - Callaghan i

Vendor? CALLAGHAN

Workorder: V29441

In Date: 01/26/2010 Meter Reading: 125,921.00

Close Date: 03/01/2010

Problem?

Quantity ON CALL DOOR ALRM GOING OFF R46 **Parts** 

Task performed:

Door alarm intermittent; fnd right rear door switch on cab sticking; replcd

switch. j

91823SWITCH SWT5499 MED MASTER BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BA HP-31DBATTERY 950CCA HP-31D

Workorder: V29745

02/05/2010 In Date: Meter Reading: 126.262.00

03/02/2010 Close Date:

**Problem?** 

a/c in not working going from cold to hot then cold then back to hot please

fix R46

Task performed:

Fnd A/C condensor fans inop; rep relay. j

Quantity **Parts** 



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

CVC460HXLCAMERA

Workorder: V29685

In Date: 02/03/2010 Close Date:

03/04/2010

Meter Reading:

126,262.00

Problem?

BACK UP CAMERA INOP. AFTER WASHING VEHICLE, R-46

**Parts** 

Quantity

Task performed:

Completed; rep test ok. j

Workorder: V29384

In Date: 01/24/2010

Close Date: 03/19/2010

Meter Reading:

9,373.00

Problem?

The front a/c is not working.it is not blowing any cool air. R46

**Parts** 

Quantity

Task performed:

Recharged A/C & tested. j

NO PARTS USED

NO PARTS USED

Workorder: V29676

In Date: 02/03/2010

03/19/2010

Meter Reading:

9.411.00

Close Date: Problem?

A/C in the front cab is not working it keeps turning from cool to hot then coo

then to hot R46

Task performed:

Rep condensor fans that had bad connection. j

**Parts** 

Quantity



\* ADVANCED LIFE SUPPORT VEHICLE

NO PARTS USED

Workorder: V30158

In Date: 02/23/2010

03/19/2010

**REPAIR AIR LEAK R46 Parts** Quantity

Task performed:

Close Date:

Problem?

Rep air leaks on rear of rescue. j

Workorder: V29006

In Date: 01/11/2010 Meter Reading:

Close Date: 03/30/2010

124,470.00

128,267.00

Problem?

### B INSPECTION AND REPAIRS AS NEEDED, R-46

### Task performed:

B-Inspection Svc. Trans. 3. Svc rear axle. 4. Replc windshield wiper blades. 5. Replc water in fuel sensor. 6. Replc (2) pat compt lens. 7. Program D/side rear door LED to stay on; install in door. 8. Install rear brakes/drums. 9. install SCBA brakets. 10. Veh wld not start after fuel filter replacement; fnd small cap for screen filter cracked; replc cap; still will not start; have Tommy assist w/bleeding fuel sys. j

Meter Reading:

Parts	Quantity
-------	----------

0000900087DDE/A0000900087 FILTER HEAD SM ME	1
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
15W40BSYN OIL BULK QTS	24
29526898 29548988 TRANS FILTER ALLISON	1
2FC00ZCR4 IN ROUND LED	1
3183-0313183-031 LENS CLEAR	2
3744BRAKE DRUM REAR	2
52-24WIPER BLADES ANCO 24	2
CA8193AIR FILTER 46744 WIX	1
KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2
R90PFILTER FUEL 33231	1
RAIRK30880N122WSKL4000 SENSOR WATER IN FU	1



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V31300

In Date: 04/06/2010 Meter Reading: 132,394.00

**Close Date:** 05/01/2010

Problem?

The connection to the right headlight keeps burning out the headlight this is

our fourth headlight that we changed when in two months please help R46

Task performed:

Chkd connection; C/O ok; fnd plug on headlight was not on all the way. j

**Parts** 

**NO PARTS USED** 

Workorder: V31484

In Date: 04/13/2010 Meter Reading: 132,574.00

Close Date: 05/01/2010

Problem?

The connection to the right headlight is not working and keeps blowing out

the headlight. This is our 4th time chaging the same right headlight r46

Task performed:

Rep connection at headlight. j

**Parts** 

Quantity

Quantity



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V31993

In Date: 05/04/2010

**Close Date:** 06/02/2010

Meter Reading:

135,035.00

Problem?

Perform "C" service. R46

Parts

Quantity



\* ADVANCED LIFE SUPPORT VEHICLE

#### Task performed:

C-Inspection 2. Replc wiper refills/repos R/side wiper arm. 3. Adj washer nozzles. 4. Rem (3) lite lenses in pat area & replc burnt bulbs 5. Rem lic plate/straighten out 6. Tighten JIG fittings P/S box-seeping fluid 7. Replc stripped screw on btry swtch knob 8. Replc lens on brake/tail; screws corroded/brkn 9. Replc R/side siren spkr 10. Rem lens on roof clearance lite; install new lite fixture. 11. Replc btry charge indicateor. 12. Rem lenses (3) pat area ovrhd lites, replc burnt bulbs. 13. C/O spotlight on roof only a spot-no flood element. 14. C/O cab door step lites flicker; order special wiring for joint flexing. 15. Replc all cab door window moldings. 16 R/side nbr plate falling off; install new decals. 17. Rem both R/rear compt doors; send for body repairs. 18. Cab fuse/power relay cvr falling off dash. 19. Rem instrument anel frm dahs; replc all bulbs inside. 20. Blow out road debris frm under veh A/C condensor. 21. Rem air dryer under veh; rebuild/reassem/reinstall. 22. Replc both Rear A/C cond fans. 23. Replc both frnt seat belts. 24. Chassis sets too low in rear; adj air bag. 25. Replc L/side cab hood fender skirt. 26. Btry slide draw slides bound up/frzn; pry open; style slides no longer avail; install new/mod. 27. Replc all eng belts/tensioner/eng iderl pulley/bearings. 28. Rem eng valve cvr; cln/rebuild press valve; reinstall. 29. Replc door hold open pistons rear A/C fan/evap cab door. 30. Rear door striker pin cvrs scraping door; grind edges to fit; readj. 31. Replc lite rear A/C unit. 32. Rechk opn of pat area A/C sys; evac/recharge; stil not down cold; replc expan block/dryer. 33. Replc dash A/C air duct vents both ends. 34. Replc door w/stripping both L/side cab doors. 35. Rem noisy fan center console. 36. C/O backup cam - picture in monitor starts folling; monitor bad, order. 37.C/O door ajar; replc lite fixture; retest-ok. 38. Locate new roof sys Bldg 3; install. 39. Vista screen showed fault node #3, pin N; after repairs completed, fault never showed on screen again. 40. Quality check truck w/Stan (Vasko). j

000090155133634 FUEL FILTER WIX       MERCEDES       1         0000902051FILTER FUEL 03 MERCEDES       1         00018017090IL FILTER 03 57215 WIX       MERCEDES       1         0127110042BELT MERCEDES MOTORS       1         032-0116549297 BATTERY INDICATOR       1         0634305000CAB LAMP       1         071601A07-0602A DRIER A/C 7118       1         107796DRYER KIT AD9 -NEW       1         107800VALVE CHECK AD9       1         1501450007750USE 0775145       1         15W40BSYN OIL BULK QTS       24         160012-2012A EXPANSION VALVE 71R8301       1         17-12645-000SHIELD SPLASH L/H       1         203FFBEARING PULLEY       1         283255 SLIDE 18IN 500 LBS       2         347347NUT       1         4923090025DASH BULB VDO       10         50000FRRFLASHER RED LED FLANGED       1         5FLANGEC5FLANGEC FLANGE CHROME       1         60027FAN A/C COND 12IN 860026-2-W       2         680-10RAMERICAN FLAG W UV CLEAR RIGHT       1         6808300074VENT A/C LH       1         6808300074VENT A/C RH       1         68083881078DZ STUD       1         68318358710600 SER NON OPTIC AMBER       2         6	0000900087DDE/A0000900087 FILTER HEAD SM ME	1
00018017090IL FILTER FOEL 03 MERCEDES 00018017090IL FILTER 03 57215 WIX MERCEDES 1 0127110042BELT MERCEDES MOTORS 1 032-0116549297 BATTERY INDICATOR 1 0634305000CAB LAMP 071601A07-0602A DRIER A/C 7118 1 107796DRYER KIT AD9 -NEW 1 107800VALVE CHECK AD9 1 1501450007750USE 0775145 1 15W40BSYN OIL BULK QTS 24 160012-2012A EXPANSION VALVE 71R8301 1 17-12645-000SHIELD SPLASH L/H 203FFBEARING PULLEY 1 283255 SLIDE 18IN 500 LBS 2 347347NUT 1 4923090025DASH BULB VDO 50R00FRRFLASHER RED LED FLANGED 5FLANGEC5FLANGEC FLANGE CHROME 10 5027FAN A/C COND 12IN 860026-2-W 2 680-10RAMERICAN FLAG W UV CLEAR RIGHT 6808300074VENT A/C LH 6808300074VENT A/C RH 6808300074VENT A/C RH 6809881078DZ STUD 68318358750600 NON OPTIC AMBER 2 68318358750600 NON OPTIC RED LENS 776477-774475USE 63152 800405PURGE VALVE KIT	000090155133634 FUEL FILTER WIX MERCEDES	1
0127110042BELT MERCEDES MOTORS 0127110042BELT MERCEDES MOTORS 1 032-0116549297 BATTERY INDICATOR 1 0634305000CAB LAMP 1 071601A07-0602A DRIER A/C 7118 1 107796DRYER KIT AD9 -NEW 1 107800VALVE CHECK AD9 1 1501450007750USE 0775145 1 15W40BSYN OIL BULK QTS 24 160012-2012A EXPANSION VALVE 71R8301 17-12645-000SHIELD SPLASH L/H 203FFBEARING PULLEY 283255 SLIDE 18IN 500 LBS 2 347347NUT 1 4923090025DASH BULB VDO 50R00FRRFLASHER RED LED FLANGED 5FLANGEC FLANGE CHROME 1 60027FAN A/C COND 12IN 860026-2-W 680-10RAMERICAN FLAG W UV CLEAR RIGHT 1 6808300074VENT A/C LH 6808300074VENT A/C RH 6808300074VENT A/C RH 6808381078DZ STUD 1 68318358750600 NON OPTIC AMBER 2 68318358750600 NON OPTIC AMBER 2 676477-774475USE 63152 1 800405PURGE VALVE KIT	0000902051FILTER FUEL 03 MERCEDES	1
032-0116549297 BATTERY INDICATOR       1         0634305000CAB LAMP       1         071601A07-0602A DRIER A/C 7118       1         107796DRYER KIT AD9 -NEW       1         107800VALVE CHECK AD9       1         1501450007750USE 0775145       1         15W40BSYN OIL BULK QTS       24         160012-2012A EXPANSION VALVE 71R8301       1         17-12645-000SHIELD SPLASH L/H       1         203FFBEARING PULLEY       1         283255 SLIDE 18IN 500 LBS       2         347347NUT       1         4923090025DASH BULB VDO       10         50R00FRRFLASHER RED LED FLANGED       1         5FLANGEC5FLANGEC FLANGE CHROME       1         60027FAN A/C COND 12IN 860026-2-W       2         680-10RAMERICAN FLAG W UV CLEAR RIGHT       1         6808300074VENT A/C LH       1         6808300074VENT A/C RH       1         6808380078DZ STUD       1         68318358710600 SER NON OPTIC AMBER       2         68318358750600 NON OPTIC RED LENS       2         776477-774475USE 63152       1         800405PURGE VALVE KIT       1	0001801709OIL FILTER 03 57215 WIX MERCEDES	1
0334305000CAB LAMP 071601A07-0602A DRIER A/C 7118 107796DRYER KIT AD9 -NEW 1107800VALVE CHECK AD9 1501450007750USE 0775145 15W40BSYN OIL BULK QTS 24 160012-2012A EXPANSION VALVE 71R8301 17-12645-000SHIELD SPLASH L/H 203FFBEARING PULLEY 283255 SLIDE 18IN 500 LBS 24 347347NUT 1923090025DASH BULB VDO 50R00FRRFLASHER RED LED FLANGED 5FLANGEC5FLANGEC FLANGE CHROME 105027FAN A/C COND 12IN 860026-2-W 2680-10RAMERICAN FLAG W UV CLEAR RIGHT 6806970098SEAL DOOR 6808300074VENT A/C LH 6808800074VENT A/C RH 6809881078DZ STUD 68318358710600 SER NON OPTIC AMBER 268318358750600 NON OPTIC RED LENS 2776477-774475USE 63152 800405PURGE VALVE KIT	0127110042BELT MERCEDES MOTORS	1
071601A07-0602A DRIER A/C 7118 1107796DRYER KIT AD9 -NEW 1107800VALVE CHECK AD9 11501450007750USE 0775145 15W40BSYN OIL BULK QTS 24 160012-2012A EXPANSION VALVE 71R8301 17-12645-000SHIELD SPLASH L/H 203FFBEARING PULLEY 283255 SLIDE 18IN 500 LBS 2447347NUT 1923090025DASH BULB VDO 50R00FRRFLASHER RED LED FLANGED 5FLANGEC5FLANGEC FLANGE CHROME 60027FAN A/C COND 12IN 860026-2-W 680-10RAMERICAN FLAG W UV CLEAR RIGHT 16808970098SEAL DOOR 6808300074VENT A/C RH 6809881078DZ STUD 68318358710600 SER NON OPTIC AMBER 268318358750600 NON OPTIC RED LENS 2776477-774475USE 63152 800405PURGE VALVE KIT	032-0116549297 BATTERY INDICATOR	1
107796DRYER KIT AD9 -NEW 1107800VALVE CHECK AD9 11501450007750USE 0775145 15W40BSYN OIL BULK QTS 160012-2012A EXPANSION VALVE 71R8301 17-12645-000SHIELD SPLASH L/H 103FFBEARING PULLEY 1283255 SLIDE 18IN 500 LBS 1247347NUT 15W40890025DASH BULB VDO 1050R00FRRFLASHER RED LED FLANGED 115FLANGEC5FLANGEC FLANGE CHROME 1160027FAN A/C COND 12IN 860026-2-W 1680-10RAMERICAN FLAG W UV CLEAR RIGHT 16806970098SEAL DOOR 176808300074VENT A/C RH 18809881078DZ STUD 188318358710600 SER NON OPTIC AMBER 188318358750600 NON OPTIC RED LENS 176477-774475USE 63152 1800405PURGE VALVE KIT	0634305000CAB LAMP	1
107790DRYER RIT AD9 -NEW 107800VALVE CHECK AD9 1 1501450007750USE 0775145 1 15W40BSYN OIL BULK QTS 24 160012-2012A EXPANSION VALVE 71R8301 1 17-12645-000SHIELD SPLASH L/H 203FFBEARING PULLEY 283255 SLIDE 18IN 500 LBS 2 347347NUT 4923090025DASH BULB VDO 50R00FRRFLASHER RED LED FLANGED 5FLANGEC5FLANGEC FLANGE CHROME 1 60027FAN A/C COND 12IN 860026-2-W 2 680-10RAMERICAN FLAG W UV CLEAR RIGHT 6806970098SEAL DOOR 6808300074VENT A/C LH 6808300174VENT A/C RH 6809881078DZ STUD 68318358710600 SER NON OPTIC AMBER 2 68318358750600 NON OPTIC RED LENS 776477-774475USE 63152 800405PURGE VALVE KIT	071601A07-0602A DRIER A/C 7118	•
1501450007750USE 0775145 1501450007750USE 0775145 15W40BSYN OIL BULK QTS 24 160012-2012A EXPANSION VALVE 71R8301 17-12645-000SHIELD SPLASH L/H 203FFBEARING PULLEY 283255 SLIDE 18IN 500 LBS 24 347347NUT 10 4923090025DASH BULB VDO 50R00FRRFLASHER RED LED FLANGED 5FLANGEC5FLANGEC FLANGE CHROME 10 60027FAN A/C COND 12IN 860026-2-W 2680-10RAMERICAN FLAG W UV CLEAR RIGHT 16806970098SEAL DOOR 17 6808300074VENT A/C LH 6808300174VENT A/C RH 6809881078DZ STUD 18 68318358750600 NON OPTIC AMBER 268318358750600 NON OPTIC RED LENS 776477-774475USE 63152 800405PURGE VALVE KIT	107796DRYER KIT AD9 -NEW	•
15W40BSYN OIL BULK QTS 15W40BSYN OIL BULK QTS 160012-2012A EXPANSION VALVE 71R8301 17-12645-000SHIELD SPLASH L/H 203FFBEARING PULLEY 1283255 SLIDE 18IN 500 LBS 2347347NUT 14923090025DASH BULB VDO 50R00FRRFLASHER RED LED FLANGED 15FLANGEC5FLANGEC FLANGE CHROME 160027FAN A/C COND 12IN 860026-2-W 2680-10RAMERICAN FLAG W UV CLEAR RIGHT 16806970098SEAL DOOR 176808300074VENT A/C LH 18088300174VENT A/C RH 1809881078DZ STUD 198318358750600 NON OPTIC AMBER 268318358750600 NON OPTIC RED LENS 2776477-774475USE 63152 800405PURGE VALVE KIT	107800VALVE CHECK AD9	•
160012-2012A EXPANSION VALVE 71R8301 17-12645-000SHIELD SPLASH L/H 203FFBEARING PULLEY 1283255 SLIDE 18IN 500 LBS 347347NUT 14923090025DASH BULB VDO 50R00FRRFLASHER RED LED FLANGED 5FLANGEC5FLANGEC FLANGE CHROME 60027FAN A/C COND 12IN 860026-2-W 2680-10RAMERICAN FLAG W UV CLEAR RIGHT 6806970098SEAL DOOR 6808300074VENT A/C LH 6808300174VENT A/C RH 6809881078DZ STUD 168318358710600 SER NON OPTIC AMBER 268318358750600 NON OPTIC RED LENS 776477-774475USE 63152 800405PURGE VALVE KIT	1501450007750USE 0775145	•
17-12645-000SHIELD SPLASH L/H 203FFBEARING PULLEY 283255 SLIDE 18IN 500 LBS 347347NUT 4923090025DASH BULB VDO 50R00FRRFLASHER RED LED FLANGED 5FLANGEC5FLANGEC FLANGE CHROME 60027FAN A/C COND 12IN 860026-2-W 680-10RAMERICAN FLAG W UV CLEAR RIGHT 1 6806970098SEAL DOOR 6808300074VENT A/C LH 6808300174VENT A/C RH 6809881078DZ STUD 1 68318358710600 SER NON OPTIC AMBER 68318358750600 NON OPTIC RED LENS 776477-774475USE 63152 800405PURGE VALVE KIT	15W40BSYN OIL BULK QTS	24
203FFBEARING PULLEY 203FFBEARING PULLEY 283255 SLIDE 18IN 500 LBS 347347NUT 4923090025DASH BULB VDO 50R00FRRFLASHER RED LED FLANGED 5FLANGEC5FLANGEC FLANGE CHROME 60027FAN A/C COND 12IN 860026-2-W 680-10RAMERICAN FLAG W UV CLEAR RIGHT 6806970098SEAL DOOR 6808300074VENT A/C LH 6808300174VENT A/C RH 6809881078DZ STUD 108318358710600 SER NON OPTIC AMBER 68318358750600 NON OPTIC RED LENS 776477-774475USE 63152 800405PURGE VALVE KIT	160012-2012A EXPANSION VALVE 71R8301	•
283255 SLIDE 18IN 500 LBS  347347NUT  4923090025DASH BULB VDO  50R00FRRFLASHER RED LED FLANGED  5FLANGEC5FLANGEC FLANGE CHROME  60027FAN A/C COND 12IN 860026-2-W  680-10RAMERICAN FLAG W UV CLEAR RIGHT  6806970098SEAL DOOR  1 6808300074VENT A/C LH  6808300174VENT A/C RH  6809881078DZ STUD  1 68318358710600 SER NON OPTIC AMBER  2 68318358750600 NON OPTIC RED LENS  776477-774475USE 63152  800405PURGE VALVE KIT	17-12645-000SHIELD SPLASH L/H	•
347347NUT 1 1 4923090025DASH BULB VDO 10 10 50R00FRRFLASHER RED LED FLANGED 1 1 5FLANGEC5FLANGEC FLANGE CHROME 1 60027FAN A/C COND 12IN 860026-2-W 2 680-10RAMERICAN FLAG W UV CLEAR RIGHT 1 6806970098SEAL DOOR 1 6808300074VENT A/C LH 1 6808300174VENT A/C RH 1 6809881078DZ STUD 1 1 68318358710600 SER NON OPTIC AMBER 2 68318358750600 NON OPTIC RED LENS 776477-774475USE 63152 1 800405PURGE VALVE KIT 1 1	203FFBEARING PULLEY	-
4923090025DASH BULB VDO 50R00FRRFLASHER RED LED FLANGED 5FLANGEC5FLANGEC FLANGE CHROME 60027FAN A/C COND 12IN 860026-2-W 680-10RAMERICAN FLAG W UV CLEAR RIGHT 1 6806970098SEAL DOOR 1 6808300074VENT A/C LH 6808300174VENT A/C RH 1 6809881078DZ STUD 1 68318358710600 SER NON OPTIC AMBER 2 68318358750600 NON OPTIC RED LENS 776477-774475USE 63152 1 800405PURGE VALVE KIT	283255 SLIDE 18IN 500 LBS	
50R00FRFLASHER RED LED FLANGED  5FLANGEC5FLANGEC FLANGE CHROME  60027FAN A/C COND 12IN 860026-2-W  680-10RAMERICAN FLAG W UV CLEAR RIGHT  6806970098SEAL DOOR  1 6808300074VENT A/C LH  6808300174VENT A/C RH  6809881078DZ STUD  1 68318358710600 SER NON OPTIC AMBER  68318358750600 NON OPTIC RED LENS  776477-774475USE 63152  800405PURGE VALVE KIT	347347NUT	•
5FLANGEC5FLANGEC FLANGE CHROME  60027FAN A/C COND 12IN 860026-2-W  680-10RAMERICAN FLAG W UV CLEAR RIGHT  6806970098SEAL DOOR  6808300074VENT A/C LH  6808300174VENT A/C RH  6809881078DZ STUD  1068318358710600 SER NON OPTIC AMBER  68318358750600 NON OPTIC RED LENS  776477-774475USE 63152  800405PURGE VALVE KIT	4923090025DASH BULB VDO	
60027FAN A/C COND 12IN 860026-2-W  680-10RAMERICAN FLAG W UV CLEAR RIGHT  6806970098SEAL DOOR  6808300074VENT A/C LH  6808300174VENT A/C RH  6809881078DZ STUD  108318358710600 SER NON OPTIC AMBER  68318358750600 NON OPTIC RED LENS  776477-774475USE 63152  800405PURGE VALVE KIT	50R00FRRFLASHER RED LED FLANGED	•
680-10RAMERICAN FLAG W UV CLEAR RIGHT  6806970098SEAL DOOR  6808300074VENT A/C LH  6808300174VENT A/C RH  6809881078DZ STUD  1068318358710600 SER NON OPTIC AMBER  68318358750600 NON OPTIC RED LENS  776477-774475USE 63152  800405PURGE VALVE KIT	5FLANGEC5FLANGEC FLANGE CHROME	•
6806970098SEAL DOOR 6808300074VENT A/C LH 6808300174VENT A/C RH 6809881078DZ STUD 1 68318358710600 SER NON OPTIC AMBER 2 68318358750600 NON OPTIC RED LENS 2 776477-774475USE 63152 1 800405PURGE VALVE KIT	60027FAN A/C COND 12IN 860026-2-W	_
6808300074VENT A/C LH 6808300174VENT A/C RH 6809881078DZ STUD 68318358710600 SER NON OPTIC AMBER 68318358750600 NON OPTIC RED LENS 776477-774475USE 63152 800405PURGE VALVE KIT	680-10RAMERICAN FLAG W UV CLEAR RIGHT	•
6808300074VENT A/C LH 6808300174VENT A/C RH 1 6809881078DZ STUD 1 68318358710600 SER NON OPTIC AMBER 2 68318358750600 NON OPTIC RED LENS 2 776477-774475USE 63152 1 800405PURGE VALVE KIT 1	6806970098SEAL DOOR	•
6809881078DZ STUD 1 68318358710600 SER NON OPTIC AMBER 2 68318358750600 NON OPTIC RED LENS 2 776477-774475USE 63152 1 800405PURGE VALVE KIT 1	6808300074VENT A/C LH	•
68318358710600 SER NON OPTIC AMBER  68318358750600 NON OPTIC RED LENS  776477-774475USE 63152  800405PURGE VALVE KIT  1	6808300174VENT A/C RH	•
68318358750600 NON OPTIC AMBER  68318358750600 NON OPTIC RED LENS  776477-774475USE 63152  800405PURGE VALVE KIT  1	6809881078DZ STUD	•
776477-774475USE 63152 1 800405PURGE VALVE KIT 1	68318358710600 SER NON OPTIC AMBER	
800405PURGE VALVE KIT 1	68318358750600 NON OPTIC RED LENS	_
600405PURGE VALVE KIT	776477-774475USE 63152	1
9062001170IDLER MERCEDES 1	800405PURGE VALVE KIT	•
	9062001170IDLER MERCEDES	1



\* ADVANCED LIFE SUPPORT VEHICLE

9425BELT MERCEDES RESCUE 12.5X1075 OE	1
A0000160521GASKET VALVE COVER	1
A0000180133DIAPHRAM SEAL	1
A0079932401SPRING DIAPHRAM	1
A1834388002MOLD L/H	2
A1834388003MOLD R/H	2
A9060160080GROMET VALVE COVER	7
A9060160721SIDE GASKET	1
CA8193AIR FILTER 46744 WIX	1
DDE/9062002470BELT TENSIONER MERCEDES	1
HLD3999GSS1715UV 30LB STRUT GAS	2
IMMF11358SEAT BELTS	2
R90PFILTER FUEL 33231	1
S4640024430VALVE LEVELIN	2
SD-210RXSIREN DRIVER SMALL	1
SPR596273CAVITY PLUG	1
U-24RWIPER REFILL	1
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1
-	

Workorder: V32024

In Date: 05/05/2010 Meter Reading: 134,370.00

Close Date: Problem?

Truck in for PM. Pt Compt A/C inop. R46

06/04/2010

Parts Quantity

Task performed:

Repairs done on C-Inspection W/O 31993. j



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V32025

In Date: 05/05/2010 Meter Reading: 134,370.00

Close Date: 06/04/2010

**Problem?** 

Truck in for PM. Shoreline A/C in pt compt inoperative. R46

Parts Quantity

Task performed:

Repairs done on C-Inspection W/O 31993. j

NO PARTS USED

NO PARTS USED

Workorder: V32023

In Date: 05/05/2010 Meter Reading: 134,370.00

Close Date: 06/11/2010

Problem?

replace all 6 tires. R46 (outside agency-boulevard tire)

Parts

Quantity

Task performed:

Truck in for PM, needs rear tires R46 - Boulevard j Rear tires R46 -

Boulevard j

Vendor? BOULEVARD TIRE

Workorder: V32361

In Date: 05/21/2010 Meter Reading: 134.370.00

Close Date: 06/14/2010

Problem?

refinish and paint 2 compt. doors (outside agency-national collision) R46 Parts Quantity

Task performed:

Refinish/paint (2) compt doors - National Collision R46 j

NO PARTS USED

Vendor? NATIONAL COLLISION



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

NO PARTS USED

NO PARTS USED

Workorder: V32866

In Date: 06/14/2010 Meter Reading: 136,101.00

Close Date: 06/21/2010

Problem?

ON CALL A/C 10-7 R46

Task performed:

Recharged rear A/C & clnd condensor fans. j

Workorder: V32942

In Date: 06/16/2010 Meter Reading: 136,101.00

**Close Date:** 06/25/2010 **Problem?** 

Task performed:

A/C is not working in the pt transport cab and the front cab as well r46

770 is not working in the pt transport cab and the nont cab as well 140

1. Chk rear A/C blowing 48 degrees; the t-stat on wall shows 81 degrees; control panel on order. 2. Chk frnt cab A/C; rem freon evac sys; recharge sys; fnd not a fulll charge; chk for leaks; fnd none; cln cond. fans. 3. Rem rear entry door panels; tighten handles, lube rods & latches;, \*striker plate

brkn;; Tommy said he will replace on 6/17/10. j

Workorder: V27235

In Date: 10/28/2009 Meter Reading: 8,888.00

Close Date: 07/13/2010

Problem?

"water in fuel" light just came on last shift. all r46 crews aware.

Task performed:

Verified job. j

Parts

**Parts** 

Quantity

Quantity

Quantity



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V32839

In Date: 06/11/2010 Meter Reading: 136,101.00

Close Date: 07/20/2010

Problem?

a/c is not working properly in the cab and patient compartment during

transport

Task performed:

Recharged sys & clnd A/C unit. j

NO PARTS USED

Workorder: V33310

In Date: 07/03/2010 Meter Reading: 137.768.90

Close Date: 07/22/2010

Problem?

left headlight is out we have changed it severeal times. Something is makin the headlights burn out fast. Need connections checked out and front a/c

needs freon.R46

Task performed:

Left headlight out; FF explained this has happened multiple times; chk volwiring & connectors for HL's; all chkd good; replc left HL & confirm opn. j

**Parts** 

**Parts** 

Quantity

Quantity

H6054USE CV TYPE SEALED BEAM

1

Workorder: V34369

In Date: 08/18/2010 Meter Reading: 140,421.50

Close Date: 09/07/2010

**Problem?** 

UNIT NOT CHARGING, R-46

Parts

Quantity

Task performed:

Unit not charging; chk charging sys; charge btrys, replc alt; sys ok. j

4867JB320 UPGRADE ALTERNATOR

- 1



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V34047

In Date: 08/05/2010 Meter Reading:

Close Date: 09/10/2010

Problem?

repair stretcher for R46 @ station 42 (outside agency-medco equipt. repair)

137,768.90

Parts Quantity

Task performed:

Repair stretcher for R46 @ stn42 - Medco j

Vendor? MEDCO

Workorder: V34363

In Date: 08/18/2010 Meter Reading: 140,421.50

Close Date: 09/17/2010

Problem?

UNIT BROKE DOWN AT STA 46 R46 Parts Quantity

Task performed:

Overheat; fnd low on wtr; top off & press tested. j

**NO PARTS USED** 

NO PARTS USED

Workorder: V34743

In Date: 09/03/2010 Meter Reading: 140,421.50

Close Date: 09/28/2010

**Problem?** 

the door light keep flashing while driving and making the beeping noise and saying the compartment door number 5 is open which is not. Needs to be fi asap thx u R46

Parts Quantity

Task performed:

Door ajar stuck on; fnd small comp on rear door to have faulty sensor; replcd sensor; door ajar sys working properly. j

SWT54912SWITCH DOOR LGHT 1
SWT54930SWITCH DOOR 1



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V34859

In Date: 09/10/2010 Meter Reading: 140,421.50

Close Date: 09/28/2010

Problem?

top stretcher wheels are breaking apart the rubber wheels are going off r46

Parts Quantity

Quantity

Task performed:

Top stretcher wheels are breaking apart R46 - Medco j

NO PARTS USED

Vendor? MEDCO

Workorder: V35215

In Date: 09/27/2010 Meter Reading: 144,482.80

Close Date: 10/18/2010

Problem?

R46 alignment is out of line and it is turning to the right Parts Quantity

Task performed:

1. inspect tires on truck, needs all six tires. jab

NO PARTS USED

Workorder: V33114

In Date: 06/24/2010 Meter Reading: 136.827.40

Close Date: 10/19/2010

Problem?

CHECK AND REMOVE HEAT STRIP FROM 110 A/C IF INSTALLED (COULD CAUSE FIRE IN UNIT) RETURN HEAT STRIP TO PARTS ROOM

R46

Task performed:

Completed j

NO PARTS USED

**Parts** 



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V34512

In Date: 08/25/2010 10/20/2010

Meter Reading: 140,421.50

Meter Reading:

**Close Date:** 

**Problem?** 

AC on R46 in driver compartment not working

Quantity **Parts** 

Task performed:

Air leak; replc purge valve. j

K022105PURGE VALVE AD-IP-IS

Workorder: V35332

In Date: 10/01/2010

Close Date: 10/25/2010 144,482.80

Problem?

Replace all tires Outside tire service

**Parts** Quantity

Task performed:

Replac all tires - Boulevard j

**NO PARTS USED** 

Vendor? **BOULEVARD TIRE** 



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

**Parts** 

Workorder: V35449

In Date: 10/06/2010 Meter Reading: 145,560.00

Close Date: 10/28/2010

Problem?

#### **B INSPECTION AND REPAIRS R46**

#### Task performed:

B-Inspection 2. Veh dln't run after B-Insp; had to prime fuel sys. 3. R/R R/R door light; new light diff than orgn; had to replc rubber holder; replc wire connector & also door switch intermittent; had to R/R door switch. 4. F/S fender marker It bulb clips NG; needs new It asy; R/R It /harness asy. 5. Retap, align & install msng screws on rear bumper diamond plate. 6. Replc rubber cushion bumper on rear bumper folding step. 7. Rem weatherstrip to gain access to door hinge screws on compt R-2; tighten all screws; reattach weatherstrip. 8. Adj all tire press to 100 PSi. 9. Dia "wtr ir fuel" It on; R/R wtr sensor in fuel filter bowl. 10. Dia why city horns dont work; R/R inner fender; R/R (2) horns. 11. Cab vista screen swtch ID label gone; parts has none; chkng to see if available. 12. Roof spotlight only works in (1) switch pos; chk wires; replc swtch w/new one & also known good one; all same results. 13. Mark/drill & center sink pin cvr to match existing holes in veh; trim alum door panel where latch is; rubs/sticks on Nader pin cvr. 14. R/R headlnr to chk wiring harness & connector for roof spotlight; fnd (1) wire cut & taped back & no other end; peel back ikt til finc end of wire; add wire to join ends; It now works. 15. Dia/rep cab A/C sys; R/R dash/center console; R/R blower speed swtch. 16. R/R R/R rear wheels; inspect/measure brake linings & drum; R/R L/F wheel; inspect/measure linings/drum. 17. Redrill/retap hole for bumper on L/R SCBA door. 18. Replc (2) tire inflator hose mntng brkts. 19. Replc (8) wheel nut cvrs. 20. Drill out holes oversize & install (4) nut zerts to rep threaded holes for compt L-3 hold opens. 21. Tried to install L/R wheel we opening molding; veh must have been in accident; no flange to install screws; bad body work. j

	_ <b></b>
0000900087DDE/A0000900087 FILTER HEAD SM ME	1
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
15W40BSYN OIL BULK QTS	26
52-24WIPER BLADES ANCO 24	2
607141-05USE 61H01 COPMPARTMENT LIGHT	1
6808200020LIGHT ASSY. TURN SIGNAL	1
918220BSOLETE USE SERV TKS SWITCH - DOOR	1
A0631117000HORN HIGH NEW # 06-52125-039	1
A0631117003HORN LOW NEW #06-52125-041	1
ABPN8332229011-3050 SWITCH BLOWER	1
ACX-84534LUG NUT COVER PK10	8
R90PFILTER FUEL 33231	1
RAIRK30880N122WSKL4000 SENSOR WATER IN FU	1
UMVS162511STRAP	1

Quantity



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V35328

In Date: 10/01/2010 Meter Reading: 144,482.80

Close Date: 11/01/2010

Problem?

R-46 needs an allignment. Front right tire is wearing unevenly, needs to be

replaced. Rear tires do not have a lot of tread remaining

Task performed:

Checked truck for tires. Need all six.

NO PARTS USED

**Parts** 

Workorder: V36844

In Date: 11/19/2010 Meter Reading: 147.105.70

Close Date: 12/07/2010

Problem?

R-46 A-inspection Parts Quantity

Task performed:

(1) "A" INSPECTION. (2) AIR LEAK UNDER HOOD. REPLACED 3/8" VALVE. RETESTED, FOUND AIR HORN RELAY FAULTY. REPLACED, RETESTED. ALL OK. J.W.

HDY-H005700SOLENOID HORN AIR

1

Quantity

Quantity

Workorder: V36084

In Date: 11/01/2010 Meter Reading: 145,206.00

Close Date: 12/10/2010

Problem?

Door check pulled loose, need re-attachment. r46

Task performed:

(1) TRAVELED TO STATION 46 TO REPAIR R46 DOOR. REMOVED BROKEN LATCH AND INSTALLED A NEW DOOR SPRING. OK. (2) REPAIRED RIGHT SIDE AIR SEAT THAT WOULD NOT COME UP. OK. J.W.



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V36131

In Date: 11/02/2010 Meter Reading: 146,293.50

Close Date: 12/22/2010

Problem?

the lock and release thing that holds the stretcher in place in the back of the unit is not working properly and it won't hold the stretcher in place r46

Task performed:

(1) TRAVELED TO ST 46 TO REPAIR BRACKET THAT HOLDS THE STRETCHER IN PLACE IN R46. REPAIRED,OK. REPAIRED THE A/C THAT WASN'T WORKING, OK, FIXED DOOR SPRING, OK, J.W.

Parts Quantity

NO PARTS USED

Workorder: V36490

In Date: 11/16/2010 Meter Reading: 147,105.70

Close Date: 12/22/2010

Problem?

puddle of coolant on floor under engine. unknown source. r46 Parts

Parts Quantity

Task performed:

(1) TRAVELED TO ST46 FOR COOLANT LEAK ON R46. REPAIRED LOWER HOSE CLAMP THAT WAS LOOSE. J.W.

NO PARTS USED

Workorder: V36570

In Date: 11/18/2010 Meter Reading: 147,105.70

Close Date: 01/13/2011

**Problem?** 

repair engine coolant leak fla detroit r46 Parts Quantity

Task performed:

Rep eng coolant leak - Florida Detroit j

Vendor? FLORIDA DETROIT



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

**Parts** 

Workorder: V38398

In Date: 02/09/2011 Meter Reading: 153,967.00

Close Date: 02/18/2011

Problem?

#### C INSPECTION AND REPAIRS AS NEEDED R46

### Task performed:

C-Inspection 2. Replc btrys. 3. Replc A/C air filters. 4. Replc burnt dome bulb in pat compt. 5. R/R t-signal switch & cvr. 6. Replc struts on inside compt of apt compt. 7. T-shoot O2 switch; fnd only works when bypass is off. 8. Rep latch on squad bench. 9. Topped off washer fluid & added solution. 10. Drawer in pat compt not closing; had to rem & realign slide. 11. Rem, cln & repaint fuel cap. 12. Replcd emergency master switch cvr on vista screen; had to \_\_\_\_\_ vista screen & take apart to install buttons. 13. Adj brake pedal free play. 14. Quality check inspection - Kevin 15. Rep marker light on pat compt. 16. Put shims on struts of L-2 compt so they wldn't rub anymore.

0000900087DDE/A0000900087 FILTER HEAD SM ME	1
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
0560-0987-00KEY CAPS VISTA 1	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	24
322502BULB PATIENT GH22	1
6805450124SWITCH TURN SIGNAL	1
6808220090HOUSING TURN SIGNAL SWITCH	1
78R536078R5360M 2PK FILTER AIR COND	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
HLD3999GSS1715UV 30LB STRUT GAS	2
HP-31DBATTERY 950CCA HP-31D	4
R90PFILTER FUEL 33231	1

Quantity



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V37830

In Date: 01/16/2011 Meter Reading:

Close Date: 02/25/2011

Problem?

The driver's door is getting stuck on the pin so u have to play with it to get it

151,369.50

un-stuck. R46

Task performed:

Readj door latch & tested. j

NO PARTS USED

**Parts** 

Workorder: V38347

In Date: 02/08/2011 Meter Reading: 153,681.20

Close Date: 03/09/2011

Problem?

DOOR NOT CLOSING R46 Parts Quantity

Task performed:

Readj door latch & rep spring. j

**NO PARTS USED** 

Workorder: V39411

In Date: 03/24/2011 Meter Reading: 157,300.30

Close Date: 04/06/2011

Problem?

O2 pressure gauge that is mounted on the wall of the rear compartment is

stuck at 600 psi causing the low O2 alarm to keep going off. R46

Task performed:

1. Chkd for O2 leak & rep. 2. Readj rear air bags. j

Parts Quantity

Quantity



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V39640

In Date: 04/04/2011 Meter Reading:

**Meter Reading:** 158,440.00

Close Date: Problem?

ON CALL R46 STRETCHER LOCK 10-7

04/14/2011

Parts Quantity

Task performed:

Stretcher problem - seapped stretcher; brought to Stn42 & swapped. j

NO PARTS USED

Workorder: V39645

In Date: 04/04/2011 Meter Reading: 158,440.00

**Close Date:** 04/14/2011 **Problem?** 

REPLACE REAR TIRES R 46 BOULEVARD

Parts Quantity

Task performed:

Replc rear tires R46 Boulevard j

NO PARTS USED

Vendor? BOULEVARD

Workorder: V39776

In Date: 04/07/2011 Meter Reading: 158.957.60

Close Date: 04/14/2011

Problem?

REPLACE FRONT TIRES R 46 Parts Quantity

Task performed:

Replc front tires R46 - Boulevard j

NO PARTS USED

Vendor? BOULEVARD



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V39767

In Date: 04/07/2011 Meter Reading: 158,957.60

Close Date: 04/19/2011

Problem?

PASS, LIGHT DOESNT WORK WHEN ON HIGH BEAM-R46

### **Parts** Quantity H6054USE CV TYPE SEALED BEAM 2

2

KSMA2124703QFRONTBRAKE KIT RUMPER AND 4D

KSMA3124710QKSMA3124710QP REAR BRAKE SHC

### Task performed:

1. Frnt brake about 30% to 40% done.; rear brake at about 20%; (2) frnt tires right toe in/left toe out; need tires; test drive - line problem. 2. Assist with R/R brakes, tire swap & fast adapt. 3. R/R brakes, new tires on frnt; adj all new brakes; R/R right frnt headlight, set ; drive for brakes & trans - ok. i

Workorder: V40247

In Date: 04/29/2011 Meter Reading: 161,315.70

Close Date: 05/02/2011

Problem?

brake pressure switch leaking, remove and install new switch.

**Parts** Quantity

Task performed:

Brake press switchleaking; rem/install new switch. j

Workorder: V40248

04/29/2011 In Date: Meter Reading: 161,315.70

Close Date: 05/02/2011

Problem?

stretcher collapsing.

**Parts** Quantity

Task performed:

Stretcher keeps collapsin; go to shop & bring spare stretcher to stn46. j

NO PARTS USED



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V39659

In Date: 04/04/2011 Meter Reading: 158,440.00

Close Date: 05/05/2011

Problem?

move hand light on rescue, sta46.

**Parts** Quantity

Task performed:

Relocated handlights on rescue. j

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BA

4

Workorder: V39935

In Date: 04/14/2011 Meter Reading: 158,957.60

Close Date: 05/11/2011

Problem?

air leak in hose line for air horn. Tommy was notified and replaced section

of bad air hose on 4-14-11, Sta.46.

Task performed:

Air line brkn; rem line & installed new one; replcd door piston. j

**Parts** Quantity

HLD3999GSS1715UV 30LB STRUT GAS



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

**Parts** 

Workorder: V40429

In Date: 05/05/2011 Meter Reading: 162,547.00

Close Date: 05/16/2011

**Problem?** 

#### B INSPECTION AND REPAIRS AS NEEDED R 46

### Task performed:

1. B inspection 2. replace wiper blades 3. refill winshield washer fluid 4. diamond plate comming off of driver's door, rerivet diamond plate back on door 5.SCBA bracket in L-2 compartment loose, screws stripped, install new screws 6. L/side rear entry door window seal falling off, remove seal clean window, silcone window and reinstall seal. 7.gas strut missing from blanket compt. in pat. compartment, install 2 new gas struts 8.repalce a/c filter in cab 9. replace a/c filter in pat. compt.

000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
04320004RUBBER EXTRUSION	5
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	4
52-24WIPER BLADES ANCO 24	2
78R536078R5360M 2PK FILTER AIR COND	1
ANTICOOLANT ANTIFREEZE GAL	1
HLD3999GSS1715UV 30LB STRUT GAS	2
R90PFILTER FUEL 33231	1

Quantity

Workorder: V40473

In Date: 05/08/2011 Meter Reading: 161,949.00

Close Date: 06/03/2011

**Problem?** 

outside rear tire on the drivers side has a slow leak. Was checked on Saturday and was 20 psi. Tire was filled to 100psi and is now down to unde 90 psi. R46

### Task performed:

1. Rep valve stem extensions. 2. Readj rear side door that was hard to open.

Parts Quantity

NO PARTS USED

S448GAUGE TIRE TREAD DEPTH



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V40884

In Date: 05/26/2011 Close Date:

06/28/2011

Meter Reading: 162,463.10

166,779.70

161,677.80

Problem?

rear door pin cover needs replaced. Sta 46.

Task performed:

replaed pin cover ak

Workorder: V42170

In Date: 07/20/2011

07/21/2011

Close Date: Problem?

front and rear a/c not cold R 46

Task performed:

Problem?

patient compt ac inop condensor dirty and low charge cleaned condensor

Meter Reading:

Meter Reading:

topped off refridgerant add I1lbya ac ok ak

Workorder: V40339

In Date: 05/02/2011 Close Date:

08/03/2011

**REPLACE TIRES R46** 

Task performed:

Replace tires R46 - Boulevard j

Vendor? **BOULEVARD**  **Parts** 

NO PARTS USED

**Parts** 

15W40QSYN OIL QT

NO PARTS USED

**Parts** 

6

Quantity

Quantity

Quantity

Page 96 of 138



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V40531

In Date: 05/10/2011

08/03/2011

Meter Reading: 162,463.10

Close Date: Problem?

> REPLACE REAR TIRE **Parts** Quantity

Task performed:

Replace rear tire - Boulevard j

Vendor? BOULEVARD

Workorder: V41963

In Date: 07/13/2011 Meter Reading: 166,779.70

Close Date: 08/08/2011

Problem?

The handlights on charger are not working. When lights are in charger the light is on for charging. When the lights are taken off charger they do not work. The charger is located on middle console in front cab of rescue. r46

Task performed:

swapped out lights and tested recharged cab a/c that was out and repaire

leak

NO PARTS USED

NO PARTS USED

Workorder: V42347

In Date: 07/27/2011 Meter Reading: 168,500.90

Close Date: 08/26/2011

Problem?

Rear a/c inop. Sta 46.

Task performed:

Ran A/C; cln condensor fans & tested. j

**Parts** 

**Parts** 

33418FUEL FILTER

Quantity

Quantity



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V42875

In Date: 08/17/2011 Meter Reading: 170,387.80

Close Date: 09/02/2011

**Problem?** 

C INSPECTION AND REPAIRS AS NEEDED R 46

**Parts** 

Quantity



\* ADVANCED LIFE SUPPORT VEHICLE

### Task performed:

C-Inspection 2. Replc belts; R/R air clnr & air charge hose. 3. Rebuild air dryer. 4. Rep air line at purge valve. 5. Secure rear door reflector w/truss head screw; drill/tap thrds. 6. Replc wiper blades. Rem seat for repair. 8. Air tires to proper PSI. 9. Replc msng lug nut cvrs. 10. Add (4) qts trans fluid. 11. Replc air filter. 12. P/S svc. 13. Clean, prime & paint fuel cap. 14. Replc frt flourescent light bulbs. 15. Adj stretcher lock. 16. Block up rear of veh for rear tire replacement. 17. Chk codes on eng, trans & ABS, LR sensor code & trans code 63-40. 18. Lube latches, door holdopens & hinges. 19. Tighten all door panel screws; drill out brkn bolt in rear door & rethrd; install new bolt. 20. Tighten loose nader pins & adj doors. 21. Tighten loose tool brkts. 22. Replc L-4 reflector; drill/tap stripped thrds. 23 Tighten loose door latches. 24. install L/rear seat. 25. Replc drivers weatherstrip; splice in lower part. 26. Replc frt pass weatherstrip; splice in lower area. 27. Install R/side rear mark/turn lamp asy. 28. Glue weather strip rear; pat compt door.R/R L/frt door panel & replc top trim piece. 29. R/R L/rear door panel & replc top trim piece. 30. Replc L/frt outer weatherstrip; Replc L/rear outer weatherstrip. 31. Replc msng fastener frm inner splash well. 32. Replc R/frt & R/rear outer weatherstrip. 33. ABS code for L/rear sensor open (inactive); chkd sensor resistance & compared w/spec (ok); chkd wire term pins in harness - ok; erased code & test drive. 34. Trans code 63-40 inactive; erase code; test drive & rechk for codes; code came back inactive; cld not erase code. 35. Veh pulls right; adj tire press, raise veh; chk wheel bearings, steering & suspension; chk for brake dray-ok; swap L/frt & R/wheels; road test. 36. Dia no park brake indicator; rem instrument cluster; took cluster apart & replc bulb; tes ok; reinstall cluster & install in veh. 37. Dia no fast idle in emerg mode; chkd for grnd output-ok; jumped output to grnd - NG; rem wires at ECM & rinm & chk for continuity. 38. Work w/vendor frometroit Diesel; rem dash & identify brake switch malfunction; fnd disconnected wire grndng out; install term & test ok; reinstall dash & center console; reconnect spotlight. 39. Quality check. j

000090155133634 FUEL FILTER WIX MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
0127110042BELT MERCEDES MOTORS	1
107796DRYER KIT AD9 -NEW	1
52-24WIPER BLADES ANCO 24	2
6737200054673-720-00-54 SEAL WINDOW	3
6806970098SEAL DOOR	1
800405PURGE VALVE KIT	1
9425BELT MERCEDES RESCUE 12.5X1075 OE	1
98003RREFLECTOR RED 40132 GROTE	1
A1834388002MOLD L/H	2
ACX-84534LUG NUT COVER PK10	4
CA8193AIR FILTER 46744 WIX	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
R90PFILTER FUEL 33231	1



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V43509

In Date: 09/08/2011 Meter Reading: 171,451.00

Close Date: 09/09/2011

Problem?

ON CALL DOOR ALARM 10-7

leave st 57 go to st 46 door alarm going off repaired switch alrm went off

drive home

Task performed:

Workorder: V42739

In Date: 08/11/2011 Meter Reading: 169,849.90 Close Date: 09/12/2011

Close Date: Problem?

Regulator on M tank on rescue is not reading correct. It read 500 when

there was over 1200. Sta 46.

Task performed:

raplaced o2 gauge and tested

Parts

**Parts** 

NO PARTS USED

Quantity

Quantity

MG-C23SPMGC23 GAUGE

2

**RWTG1234LED PRESSURE CAP** 

1

Workorder: V42423

In Date: 08/01/2011 Meter Reading: 169,101.10

**Close Date:** 09/13/2011 **Problem?** 

ON CALL A/C 10-7 R 46

Parts Quantity

Task performed:

repaired connection on ac condencer fans tested unit tested ok



9/22/2016

RESCURED HOSE, TEST FROVE ALL OK

## **Palm Beach County Fire Rescue Fleet Maintenance Asset History** 10156657

\* ADVANCED LIFE SUPPORT VEHICLE

	<b>42966</b> /22/2011	170,387.80		
replace rear tire	es		Parts	Quantity
Task performed	l: res - Boulevard j		NO PARTS USED	
Vendor? BOU	LEVARD			
	43059			
	/25/2011 Meter Reading: /16/2011	170,387.80		
repair ecm r 46			Parts	Quantity
Task performed Rep ECM R46			NO PARTS USED	
Vendor? FLA	DETROIT			
————Workorder: V	44284			
	/11/2011 Meter Reading: /12/2011	174,566.00		
booster hose p	opped off.		Parts	Quantity
Task performed	: /ERBACK TO STATION A	FTER BIG POP SOLIND	NO PARTS USED	
	T HOSE POPPED OFF, FOU	· · · · · · · · · · · · · · · · · · ·		



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder:	V44827				
In Date: Close Date: Problem?	10/31/2011 11/02/2011	Meter Reading:	176,237.90		
Cab a/c ino	р			Parts	Quantity
Task performed:  1. C/O no A/C; rep wires on; chk press - ok; just bad wires. 2. Assist in A/C repair - Powers. j		NO PARTS USED			
Workorder:	V44680				
In Date: Close Date: Problem?	10/25/2011 11/07/2011	Meter Reading:			
a/c is not working in front cab. No cool air coming out, sta 46.		Parts	Quantity		
Task perform Rep A/C &				NO PARTS USED	
Workorder:	V44763				
In Date: Close Date: Problem?	10/29/2011 11/07/2011	Meter Reading:			
AC in the fr R46	ont compartmer	t is not working again	. Does not blow cold air	Parts	Quantity
Task performed: Fan switch burnt up; rep switch & tested. j		1512BINARY SWITCH 22-36474	1		
		,			



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V44709

In Date: 10/26/2011

Meter Reading:

**Close Date:** 11/21/2011

Problem?

O2 alarm keeps going of even when bottle is full, gauge on tank reads full

Meter Reading:

computer reads 0. Sta 46.

Task performed:

Replaced sender. j

**Parts** Quantity

AS75600MONI-A01 O2 MINDER KIT

Workorder: V45365

In Date: 11/22/2011

Close Date: 11/29/2011

Problem?

Replace front tires. **Parts** Quantity

Task performed:

Replace front tires.bp

NO PARTS USED

Vendor? **BOULEVARD** 

Workorder: V45502

In Date: 11/29/2011

11/29/2011

Meter Reading: 178,718.70

178,041.80

Close Date: Problem?

B INSPECTION OIL CHANGE SERVICES R 46

**Parts** Quantity

Task performed:

B INSPECTION OIL CHANGE SERVICES

Vendor? OIL CHANGE SERVICES



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V45254

In Date: 11/17/2011

Meter Reading:

Close Date: Problem?

Cab air conditioning not working, Sta 46

12/02/2011

**Parts** Quantity

Task performed:

recharged a/c system

ABPN8330101701-0604 3924 BLOWER A/C BOA 852

Workorder: V45143

In Date: 11/14/2011

Close Date: 12/05/2011

Problem?

Meter Reading:

Stretcher latch inop

**Parts** Quantity

Task performed:

STRECHER LATCH INOP.

NO PARTS USED

Workorder: V45504

In Date: 11/30/2011

12/12/2011

Meter Reading: 178,718.70

177,254.00

Close Date: Problem?

Repair marker lights and jumpseat in pt. compartment seatbelt. Sta 46.

**Parts** Quantity

Task performed:

repaired seat belt and tested repaired marker lights that were shorted out



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V46009

In Date: 12/21/2011 **Close Date:** 

01/13/2012

Meter Reading:

1,810,296.00

Problem?

broken drawer in pt. compartment, Sta 46

**Parts** 

Quantity

Task performed:

REPAIRED DRAWER IN PT COMPARTMENT.

NO PARTS USED

Workorder: V45694

In Date: 12/07/2011

Close Date: 01/17/2012

Problem?

Map light is broken, Sta 46

**Parts** 

Quantity

Task performed:

REPAIRED MAP LIGHT AND TESTED.

LF18TS-LEDMAP LIGHT LED 18 IN

2

Workorder: V46711

In Date: 01/19/2012

01/27/2012

Meter Reading:

Meter Reading:

183,932.50

80,543.90

Close Date: Problem?

rear a/c not working, Sta 46

**Parts** 

Quantity

Task performed:

1. REPAIRED REAR CAB A/C THAT WAS NOT WORKING, 2. REAR DOOR NOT LOCKING - REMOVED DOOR LOCK AND REPAIRED LINKAGE.



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V46842

In Date: 01/25/2012 Meter Reading:

Close Date: 01/27/2012

Problem?

Need motor oil to put in truck. It's a little low and we're out at the station. Sta

Task performed:

DROPPED OFF OIL AT STATION.

NO PARTS USED

NO PARTS USED

**Parts** 

Quantity

Workorder: V46761

In Date: 01/23/2012

Close Date: 02/03/2012

Meter Reading:

184,361.00

184,543.40

Problem?

Rear a/c inop.

**Parts** 

Quantity

Task performed:

FOUND REAR CONDENCER FANS NOT WORKING - REPAIRED RELA THAT HAD BAD CONNECTION.

Workorder: V47161

In Date: 02/07/2012 Close Date:

02/10/2012

Meter Reading: 185,346.60

Problem?

replace flat tire

**Parts** 

Quantity

Task performed:

REPLACE FLAT TIRE.

NO PARTS USED

**Vendor?** BOULEVARD TIRE CENTE



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V47308

In Date: 02/14/2012 **Close Date:** 

C INSPECTION R 46

02/24/2012

Meter Reading:

186,169.80

Problem?

**Parts** Quantity



### 9/22/2016

### Palm Beach County Fire Rescue Fleet Maintenance Asset History 10156657

\* ADVANCED LIFE SUPPORT VEHICLE

### Task performed:

1. C inspection 2. degrease engine 3. map lite broken, replace map lite 4. cab a/c inop, charge system check for leaks, found hoses leaking in red dot system, replace hoses and bulk head connector, replace drier, replace low pressure switch, replace oem drier on fire wall, recheck for leaks found low and high pressure switchs for rear pat. a/c leaking replace both switchs. 5. replace front shocks 6. replace rear shocks 7. replace wiper blades 8. windshield waser inop, found lines clogged and plastic T broken clear lines and replace T 9. roof mounted spot lite inop will not turn, replace spot lite, then found lite turns in reverse of control. trace out wiring in center console all ok, drop headliner and found wires up in front of cab were spliced to wrong color, install wiring to correct color wires and recheck. ok 10. defroster inop, trace problem to a/c / heat control head remove dash and replace control head, also found heater control cable broken at heater control, replace cable, adj.all cables for blend doors 11. replace missing screws for fuse / relay panel 12. rear arrow lite stick inop, found blown fuse replace fuse. 13. check out lites in pat. compt inop, replace all 6 lite bulbs 14. replace cab a/c filter and a/c filter in pat. compt 15. top med. compt. door latch missing, replace latch 16. bottom med. draw inop, remove draw and repair tracks 17. pat. compt plexi glass slide door in backwards, remove frame and reinstall the sliding plexi glass the correct way. 18. 2 med. compt. door struts inop. replace struts 19. 2 pat. compt. lites inop, replace bulbs 20. paint fuel cap. 21. I/side and r/side dash a/c vents broken, replace both vents 22. remove dash gauges and replace bulbs for gauges 23. cab lite bar intersector strobes inop, check fuses and wiring found internal strobe control n/g, replace intersector strobe assy. 24. back up camera very loose, remove and tighten all screws, reinstall.

0000900087DDE/A0000900087 FILTER HEAD SM ME	I
000090155133634 FUEL FILTER WIX MERCEDES	1
0000902051FILTER FUEL 03 MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
091-84-022DIODE 6 AMP	1
11-26521487 SWITCH NC O 340 - C 210 HIGH PRES	1
1432A/C PRESSURE SWITCH NO OPENS 25 CLOSE:	1
1501450007750USE 0775145	1
1512BINARY SWITCH 22-36474	1
15W40BSYN OIL BULK QTS	26
161657700065489 SHOCK REAR NEW RESCUE	2
22-49905-000CABLE HEATER	1
22512960001498 SWITCH BINA	1
252189LATCH TRIGGER W/LOCK	1
322502BULB PATIENT GH22	3
402386HOSE AND FITTING ASSY	1
6808300074VENT A/C LH	1
6808300174VENT A/C RH	1
716907-0610A DRYER	1
78R536078R5360M 2PK FILTER AIR COND	1
A22451940011499 SWITCH A/C HIGH PRESSURE NC	1
ABPN83322930CONTROL HEAD AC/HEAT	1
GSS1717UL1717UL0270N 343/09 GAS SHOCK 60 LB	3
LF18TS-LEDMAP LIGHT LED 18 IN	1
PRMISCCNLA PIERCER 2 DUAL STROBE	1
R90PFILTER FUEL 33231	1
RD-4-3804-0BRACKET ASSY RED DOT	1
RD-5-7063-OP07-2618A A/C DRIER 7155	1
SA66613SHOCK FRONT RESC	2
SPT6008146SL LIGHT-REMOTE SPOT	1
U-24RWIPER REFILL	1



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V47542 In Date: 02/24/2012 Meter Reading: 186,448.70 Close Date: 02/27/2012 Problem? replace three rear tires **Parts** Quantity Task performed: NO PARTS USED REPLACE THREE REAR TIRES Vendor? **BOULEVARD TIRE CENTE** Workorder: V47705 In Date: 03/02/2012 Meter Reading: 187,039.10 Close Date: 03/16/2012 Problem? right headlight out need spares for station, sta 46 **Parts** Quantity Task performed: **NO PARTS USED** REPLACED HEADLIGHT AND DROPPED OF SPARES. Workorder: V47928 03/13/2012 In Date: Meter Reading: 188.417.30

Task performed:

Close Date: Problem?

04/02/2012

right side headlight out R46

1. REPLACED HEADLIGHT. 2. REPLACED SLIDES IN MED DRAW.

H6054USE CV TYPE SEALED BEAM 2
SLD5366HT4932-16 DRAWER SLIDE 16 2

Quantity

**Parts** 



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V48886

In Date: 04/25/2012 Me

05/09/2012

Meter Reading: 192,024.00

Close Date: Problem?

**B INSPECTION** 

#### Task performed:

1. B-INSPECTION. 2. LOAD TEST BATTERIES (BAD). REPLACED BATTERIES. 3. REPLACE REAR BRAKES. 4. REPLACE REAR BRAKES, ADJUST, ROAD TEST. 5. DIAGNOSE OIL LEAK. DEGREASE MOTOR. ROAD TEST AND CHECK FOR LEAKS. FOUND LEAK AROUN OIL FILTER HOUSING TIGHTEN 2 BOLTS, REGREASE AND RE-CHEC STILL SEEPING. 6. DISASSEMBLE MOTOR TO REPLACE OIL COOLEI GASKETS. 7. FINISH DISASSEMBLING MOTOR FOR OIL LEAK AT COOLER CLEAN AND INSPECT PARTS. REINSTALL COOLER AND FRONT PLATE; INSTALL ALT, A/C COMPRESSOR, BRACKETS, BELTS CHARGE A/C, INSTALL WATER HOSES, FILL RESERVOIR, CONNECT AIR INDUCTION HOSES. CONNECT INTAKE HEATER, BATTERY CABLES, AIR CLEANER FENDER SPLASH WELL. TURBO OIL LINE AND AIR INTAKE AND OUT PUT, ETC. 8. REPLACE WIPER BLADES. § REPLACE L&R FENDER MARKER LIGHTS. 10. REPLACE ACTIONARY BULBS. 11. REPAIR LEAK AT R REAR OUTSIDE VALVE CORE AND AIRED ALL TIRES. 12. DIAGNOSE AIR LEAKS. REMOVE DASH FOUNI PARK BRAKE VALVE BAD. 13. REPLACED PARKING BRAKE VALVE. SWITCH FITTINGS TO NEW VALVE. R&R DASH PANEL AND INSTRUMENT CLUSTER. 14. REAR BACK-UP CAMERA IN/OP. DIAGNOSE PROBLEM - FOUND BAD CONNECTION AT MONITOR REPAIR CONNECTION. TEST OK.

Parts	Quantity
000090155133634 FUEL FILTER WIX MERCEDES	2
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
3744BRAKE DRUM REAR	2
52-24WIPER BLADES ANCO 24	2
800034VALVE PARKING BRK.	1
ANTICOOLANT ANTIFREEZE GAL	8
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4
DDE-0001883380GASKET COOLER COVER	1
DDE-9061880280GASKET	1
HP-31DBATTERY 950CCA HP-31D	4
KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2
R90PFILTER FUEL 33231	1
TRANSYNDALLISON TRANS FLUID GAL	12



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V48737

In Date: 04/18/2012

05/11/2012

Meter Reading: 191,932.40

Close Date: Problem?

Siren not working R 46

Task performed:

1. SIREN INOP - REPLACED SIREN AND TESTED. 2. STRETCHER

LATCH BROKEN - REPLACED LATCH.

**Parts** Quantity

090-0278STRECHER BAR NEW

295SLSA1SIREN

NO PARTS USED

Workorder: V49397

In Date: 05/16/2012

Close Date: 05/31/2012

Problem?

Meter Reading: 192,157.70

Spare at station 53. Back up camera screen is black.

Task performed:

FOUND UNIT WORKING - CHECKED ALL CONNECTIONS.

**Parts** 

Quantity

Workorder: V49576

In Date: 05/23/2012

05/31/2012

Meter Reading:

192,355.10

Close Date: Problem?

A INSPECTION

**Parts** 

Quantity

### Task performed:

1. A- INSPECTION, 2. DIAGNOSE SPOT LIGHT IN/OP - REMOVED CONTROL HEAD AND FOUND BAD GROUND CONNECTION. TIGHTEI CONNECTOR AND INSTALL ON TERMINAL. INSTALL CONTROL HEAL TEST (OK) 3. REPLACED R HEADLIGHT.

H6054USE CV TYPE SEALED BEAM



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder:	V50162
------------	--------

In Date: 06/15/2012

06/25/2012

Meter Reading: 192,355.10

Close Date: Problem?

A INSPECTION

**Parts** 

Quantity

Task performed:

A INSPECTION.

NO PARTS USED

NO PARTS USED

Workorder: V50651

07/06/2012 In Date:

Close Date: 07/06/2012

Problem?

front lite bar falling off, R-42

**Parts** 

Quantity

### Task performed:

1. driver stated that front lite bar was banging on roof, check lite bar found 2 bolts missing on hold downs, replace bolts and tighten both sides of lite bar.

Meter Reading:

Workorder: V50515

In Date: 07/01/2012 Close Date:

07/18/2012

Meter Reading:

193,835.80

193,077.00

Problem?

A/C in rear of passenger compartment not turning on. R 53

**Parts** 

Quantity

#### Task performed:

PLUG IN 120V A/C AND TEST PERFORMANCE OF A/C UNIT - NOTICE THAT SWITCHES ON UNIT WERE NOT SET PROPERLY - RESET -AFTER .5 HOURS WAS COLD IN BACK - PERFORMANCE OK -CHECKED OUT BY SHOP FOREMAN - ALSO, SAYS - OK.



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V52056

In Date: 08/31/2012 Meter Reading:

Close Date: 09/12/2012

Problem?

A inspection

#### Task performed:

1. A INSP 2. R/R TIRE LEAKING. R&R SCHRADER VALVE INSTALL TIRE FILL HOSE AND MOUNTING BRACKET TO WHEEL NUT. 3. R&R LIGHT ASSY ON INNER DRIVERS DOOR REPAIR WIRING CONNECTOR. 4. CHK OUT W/ WIPER SYST- SHAFTS MOVE MOUNT ALL PARTS LOOK OK CHK ANOTHER SAME PLAY- OK AT THIS TIME 5.LOOSEN COOLING PIPE MTNG BRKT MOVE PIPE-TRIED TO TURN SMALLER HOSE FITTING WONT MOVE. ADDED HOSE CHAFE PROTECTOR. 6. LOOK FOR A USED GOOD TIRE IN BLDNG 7 NONE FOUND. PICK RCKAT 2 NEW TIRE/ WHEELS R&R 4S INROTATOR R& AIR HOSES ON WHEELS IN PLATE TO PRESSURE.

194,411.40

Parts Quantity

404-100 VALVE CORE

Workorder: V51161

In Date: 07/27/2012 Meter Reading: 194,131.40

Close Date: 09/14/2012

Problem?

SMOKE COMING FROM UNDER DASH AT STATION 51. SR13

Task performed:

FOUND RELAY MELTED REPLACED RELAY AND REPLACED WIRING

1830606C94WATER PUMP	1				
K080726BELT	1				

Quantity

**Parts** 



9/22/2016

## Palm Beach County Fire Rescue **Fleet Maintenance Asset History**

10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V51395

In Date: 08/06/2012 Meter Reading: 194,411.40

Close Date: 09/17/2012

Problem?

A INSPECTION AND NEEDED REPAIRS, ROOF WATER LEAK IN FRON CAB, SR13

### Task performed:

1. PERFORMED A SERVICE. 2. REPLACED WIPER BLADES. 3. CHKD ROOF SPOTLIGHT INOP: TRACED PROB TO FAULTY CONNECTION / CONTROLLER IN CENTER CONSOLE SECURED AND WIRED SPOT LIGHT NOW WORKING NORMALLY. 4. BEGAN PULLING HEAD LINER DOWN TO CHK FOR WATER LEAK. 5. WATER CHK CAB ROOF W/ WATER HOSE TO FIND LEAK TRACED LEAK TO SPOT LIGHT MOUNTING BRACKET BOLT HOLES LEAKING. REMOVED SPOT LIGH AND BRACKET SCAPED OFF ALL OLD SILICONE AND RESEALED. 6. ASSIST IN ROOF LEAK, 7, REMOVED TWO LFT HAND SIDE CAB ROOF MARKER LIGHT ASSEMBLY SCRAPED OFF ALL EXCESS SILICONE INSTALLED AND SEALED NEW MARKERS (LEAKING). 8. HOSED DOWN TRUCK CAB ROOF TO CHK LEAK REPAIR NO LEAKS FOUND REINSTALLED BOTH SECTIONS OF HEADLINER.

Parts	Quantity
22-51950-000HEADLINER RETAINER PLUG	12
52-24WIPER BLADES ANCO 24	2
A06-40578-000TOP CLEARANCE LIGHT M2	2

Workorder: V53599

11/07/2012 In Date: 197,471.80 Meter Reading:

Close Date: 11/08/2012

Problem?

install hook for stryker

### Task performed:

INSTALLED STRYKER HOOK HAD TO REMOVE STAIR CHAIR BOX TO PUT NUTS AND WASHERS UNDER.

**Parts** Quantity 6092036018J HOOK STRYKER



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V53329

In Date: 10/26/2012 Mete

11/15/2012

Meter Reading:

Close Date: Problem?

A inspectionion - cab roof mounted spot light not working.

Parts Quantity

### Task performed:

1. REPALCED CAB ROOF MARKER. (LEFT) 2. CHK ROOF SPOT INOP TRACED PROB TO CONTROL IN CENTER CONSOLE ORDERED NEW CONTROLLER. 3. CHK OUT AIR LEAKS. REPAIRED NUMEROUS AIR LEAKS UNDER TRUCK. (RESEALED LEAKING FITTINGS). 4. TIRES ARE GOOD AS PER EDDIE ERHKE. 5. A INSPECTION.



9/22/2016

## Palm Beach County Fire Rescue Fleet Maintenance Asset History

10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V54511

In Date: 12/19/2012 Meter Reading: 199,296.10

Close Date: 12/21/2012

**Problem?** 

A inspection

#### Task performed:

1. A INSP 2. REPLACE BENT BOLT ON COMPT LATCH AND ADJ BOTI LATCHES FOR CLOSING PROPERLY. 3. L-3 DOOR HITTING STRIKEF GRIND DOOR OPENING TO CLEAR STRIKER. 4. TIGHTEN SCREWS ( L-2 DOOR PANEL RE-THREAD STRIPPED ADJ SCREW. 5. LF TIRE WORN AND R&R RR I TIRE LEAK. WORKOUT TO BUILDING 3 MOVE TIRES AND WHEELS TO PROCESS WHEELS ON SHELF. REMOVE WHEELS ON SHELF. SCRATCH CORRECT ALUMINUM WHEELS. PUT BACK WHEELS THAT WERE MOVED AIR UP WHEELS TO PROPER PSI. INSTALL WHEELS ON FRT.L REMOVE R REAR WHEELS. DIAGNOSE TIRE LEAK FOUND BAD CORE AND EXT REPAIR LEAK AND AIR TIRE TO PROPER PSI. INSTALL R/F TIRE ON RRO. PUT BAC 2 WHEELS AND NET USED IN BUILDING 3 AFTER MOVING TRAILER. 6. REPLACE R SIDE PATIENT COMPT HOLD OPEN. DISASSEMBLE NEW AND USED HOLD OPENS AND SWITCH BRACKETS. INSTALL ACORN NUTS TO PROTECT WIRING IN COMPT. 7. ROAD TEST. VEHICLE AND CLEAN PRO TIRE. 8. DIAGNOSE AIR LEAKS FOUND BOTH LEVEL VALVES LEAKING REAR DRAIN VALVE AND VARIOUS PLUGS. ADJ LEVEL VALVES. REMOVE FRT SEAT. 9. REMOVE R FRT SEAT. REPLACE AIR LINES AND FITTINGS. 10. RE-INSTALL SEAT. TEST FOR LEAKS OK. 11. REPLACED R REAR PATIENT COMPT BULI

Parts	Quantity			
103385NDRAIN COCK	1			
297518265/70R19.5 BRIDGESTONE R250	2			
322502BULB PATIENT GH22	1			
HLD39917DC23-5011 50 # HOLD-OPEN RESCUE	1			
S4640024430VALVE LEVELIN	2			



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V54560

In Date: 12/21/2012 Close Date:

12/27/2012

Meter Reading: 199,296.10

Problem?

repalce front tires

Task performed:

REPLACE FRONT TIRES.

Vendor? **BOULEVARD TIRE CENTE** 

Workorder: V55370

In Date: 01/29/2013

Close Date: 01/30/2013

Problem?

A inspection

Task performed:

1. A INSP. 2. REMOVE 110V A/C UNIT RESEAL AND MOUNT UNIT WA MISSING MOUNTING BOLTS, CHECK FOR LEAKS OK. 3. ADJUST AIR HORNS. 4. REPLACE BENCH SEAT HOLD OPENS, ADJUST LATCH.

Meter Reading:

**Parts** 

**Parts** 

NO PARTS USED

78R536078R5360M 2PK FILTER AIR COND HLD3999GSS1715UV 30LB STRUT GAS

2

Quantity

Quantity

Workorder: V55117

In Date: 01/17/2013 Close Date:

02/12/2013

Meter Reading:

201,469.00

202,170.00

R 46 is leaning to the drivers side in the back. it is a steep lean. R46

Task performed:

Problem?

READJUSTED REAR AIR BAGS.

**Parts** 

Quantity



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V55357

In Date: 01/28/2013 Close Date:

02/12/2013

Meter Reading:

202,170.00

Problem?

I/side headlight inop, R-45

**Parts** Quantity

Task performed:

1. replace l/side headlight

H6054USE CV TYPE SEALED BEAM



Palm Beach County Fire Rescue

**Fleet Maintenance Asset History** 

10156657

\* ADVANCED LIFE SUPPORT VEHICLE

**Parts** 

Workorder: V55444

In Date: 01/31/2013 Meter Reading:

02/25/2013

202,170.00

Close Date: Problem?

C inspection

#### Task performed:

1. C INSP. 2. REPLACE RAD CAP. 3. ADJUST RIGHT REAR AIR BAG ARM. 4. SERVICED AIR BRAKE DRYER. 5. CHECKED TRUCK FOR AIF LEAKS FOUND 4 DRAIN VALVES AT AIR TANKS LEAKING. REPLACEI ALL FOUR WITH PROPER VALVE. ALSO FOUND 3/8 AIR LINE FOR AI HORN SOLENOID LEAKING AT UNION. REPLACED UNION AIRED TRUCK BACK UP AND CHECKED REPAIRS NO FURTHER LEAKS. 6. REPLACED WIPER BLADES. 7. REMOVE ACCEDIDATION STICKERS. 8. REPLACED PATIENT COMPARTMENT A/C FILTER. 9. REPLACED ALL FOUR REAR TIRES WITH TIRES FROM BUILDING 3. ALSO REPAIRED VALVE STEM EXTENSIONS AND REPLACED VALVE CORI IN ONE OF THE NEW TIRES. 10. REMOVED TRANS COOLER LINE/HOSE AT RADIATOR, REMOVED FITTINGS, REPLACED O-RING ON FITTNGS AND REINSTALLED. RECONNECTED COOLER LINE, TOPPED OFF TRANS AND ROAD TESTED. LEAK IS NO LONGER DETECTABLE. 11. REPLACED KUSSMAIL COVER FOR 110V A/C (BROKEN). 12. REPLACED TWO DOOR (CAB) TRIMS (BROKEN). 13. REPLACED 3 CAB DOOR WEATHRSTRIPS (TORN). 14. R&R LEFT CA DOOR PANEL TO ACCESS DOOR HANDLE AND TIGHTEN (OUTTER/LOOSE). 15. REPLACED ULTRA VIOLET LIGHT I PATIENT COMPARTMENT A/C (BURNT OUT). 16. REPROGRAMMED BRAKE LIGHTS. 17. CHECKED OUT B/UP CAMERA INOP. TRACED PROBLEM TO FAULTY CAMERA ON BACK OF BODY REMOVED INTERIOR PANELS IN PATIENT COMP. TO ACCESS WIRING, CHANGED OVER AND TEST CAMERA IS NOT OPERATING NORMALLY.

000090155133634 FUEL FILTER WIX MERCEDES	1
0001801709OIL FILTER 03 57215 WIX MERCEDES	1
05-17223-000CAP RADIATOR 10 LB	1
091-3YWCOVER KUSSMAUL AUTO EJECT	1
103385NDRAIN COCK	4
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1501450007750USE 0775145	1
52-24WIPER BLADES ANCO 24	2
6806970098SEAL DOOR	1
800405PURGE VALVE KIT	1
A1834388002MOLD L/H	1
A1834388003MOLD R/H	1
CA8193AIR FILTER 46744 WIX	1
CVC460CAMERA	1
R90PFILTER FUEL 33231	1
UVBULBAPS253PLS11W/TUV BULB A/C RESCUES	1

Quantity



10156657 \* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V56616

In Date: 03/25/2013 Close Date:

03/25/2013

Meter Reading: 204,029.70

195,844.70

198,352.00

Problem?

on call stretecher braket r 47

MOVE STRETCHER HOOK.

Workorder: V52707

Task performed:

In Date: 09/28/2012

Close Date: 04/04/2013

Problem?

Bracket holding Oxygen bottle to stretcher is broken. R 53

Meter Reading:

Task performed:

CONTACTED EMSAR FOR REPAIR.

Workorder: V53966

In Date: 11/24/2012

04/04/2013

a inspection

Close Date:

Problem?

Task performed:

1. A INSPECTION, 2. CHECK AIR LEAKS REPLACE 2 FITTINGS ON PRIMARY TANK, 3, INSTALL WIPER BLADES AND TIGHTEN LEFT DOOR STOP. 4. REPAIR CONNECTOR ON REAR LOADING LIGHT.

Meter Reading:

**Parts** 

NO PARTS USED

**Parts** 

NO PARTS USED

52-24WIPER BLADES ANCO 24

**Parts** 

Quantity

Quantity

Quantity

2



9/22/2016

## Palm Beach County Fire Rescue **Fleet Maintenance Asset History**

10156657

\* ADVANCED LIFE SUPPORT VEHICLE

S693AIR CHUCK

Workorder: V56854

In Date: 04/05/2013 Meter Reading: Close Date:

04/10/2013

Problem?

A inspection

#### Task performed:

1. START SER A. 2. DRILL AND REMOUNT GROUND STRAP UNDER REAR OF TRUCK REPAIR WIRES HANGING DOWN AND WIRE BACK UP REPAIR LATCH IN COMPARTMENT, ADJUST TO LOCK. 3. TROUBLESHOOT NO 12V PLUG IN REAR COMPARTMENTS FRONT CAPTAIN SIDE. FOUND WIRES OFF ON BATTERY TO POWER UP PLUGS. 4. CHECK OUT 110 PLUG NOT WORKING, TROUBLESHOOT PLUG FOUND TWO PLUG ON PLUG IN A/C CABINET TO POWER UP OTHER PLUG, REPLACE. 5. REPAIR PLUG TO BATTERY CHARGER NOT WORK, AFTER REPAIR BATTERY CHARGER WORKS AND LIGHTS ON SIDE WORKING CHARGING 13.95 OK. 6. REPAIRS STRAPS, INSTALLED SCREW IN STRAPS HOLE DOWN, REPAIR RELEASE HANDLE.

204,680.00

**Parts** Quantity 2

Workorder: V57220

In Date: 04/23/2013 Meter Reading: 205,161.90 Close Date: 04/23/2013

Problem?

roof spot light damaged

Task performed:

ROOF TOP SPOT LIGHT RIPED OFF - REMOVE PIECES STRAIGHTEN MOUNT, REWIRE NEW SPOT LIGHT IN - RUN NEW WIRE HARNESS, CUT NEW ACCESS MOUNT FOR CONTROLE SWITCH AND REWIRE.

**Parts** Quantity

LGHGO-2020GOLIGHT MODEL 2020 SEARCH LIGHT



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V57384

In Date: 05/01/2013 Meter Reading:

Close Date: 05/06/2013

Problem?

Rescue fuel gauge inaccurate. Reads 1/4 lower than actual level. Head

lights misaligned. Very difficult to see at night. R16

Task performed:

1. TRAVEL TO 16 CHECKED GUAGE, FOUND NO PROBLEM. 2. ADJUSTED HEADLIGHT ADJUSTED SCREW CAME OFF LIGHT BUCKET.

NO PARTS USED

**Parts** 

Workorder: V56997

04/12/2013 In Date:

Close Date: 05/16/2013

Problem?

While leaving to respond to a call the front bay door began to close, knocking off the spot light, leaving wires exposed. SR@ ST-43

Meter Reading:

Task performed:

REPLACE RADIATOR CAP- AND PRESSURE TESTED SYSTEM.

**Parts** Quantity

05-17223-000CAP RADIATOR 10 LB LGHGO-2020GOLIGHT MODEL 2020 SEARCH LIGHT SPT6008146SL LIGHT-REMOTE SPOT

Workorder: V59641

In Date: 08/06/2013

Close Date: 08/12/2013 Meter Reading: 208.096.80

stretcher locking mechanism not working properly SR@32

Task performed:

Problem?

REPAIRED STRETCHER LATCH.

**Parts** 

090-0278STRECHER BAR NEW

Quantity

Quantity



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V59718

In Date: 08/10/2013 Meter Reading: 109.482.90

Close Date: 08/12/2013

Problem?

Both AC units in front cab are not blowing cold. Freon was filled yesterday

and no improvement. R32

Task performed:

TRAVEL TO STA 32. ADDED FREON TO FRONT A/C. REMOVED FREOUND REAR A/C. CLEAN CONDENSERS. RESET 110V BREAKER FOI 110V A/C. PLUG IN 110V A/C AND CHECK OK. TRAVEL HOME.

NO PARTS USED

Workorder: V59138

In Date: 07/16/2013 Meter Reading: 207.376.00

Close Date: 08/15/2013

Problem?

Air leak SR

Task performed:

WENT TO 17810 61AR PLACE - FOUND PURGE VALVE LEAKING - R& VALVE - FOUND RAD. TOP TANK CRACKED - TEMP. PATCHED - FILLED RADIATOR - WENT TO ST 22 WENT TO SHOP FOR SPARE - RETURN HOME.

**Parts** 

**Parts** 

Quantity

Quantity

800405PURGE VALVE KIT

1

Quantity

Workorder: V60303

In Date: 09/05/2013 Meter Reading: 209,233.40

Close Date: 09/06/2013

Problem?

front ac is not working R29

Task performed:

TRAVEL TO 29 DRIVER COMPLAINT NO A/C. HOOK UP GAUGES PRESSURES REAL HIGH CLEANED OUT CONDENSER AND TESTED OK.

**Parts** 



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

NO PARTS USED

NO PARTS USED

Workorder: V59200

In Date: 07/19/2013 Meter Reading:

**Close Date:** 09/13/2013

Problem?

radiator cracked **Parts** Quantity

207,376.00

Task performed:

REPAIRS MADE ON SEPERATE TICKET.

10/01/2013

Workorder: V60372

In Date: 09/08/2013 Meter Reading: 209,276.10

Close Date: Problem?

> front cab AC is out E43 **Parts** Quantity

Task performed:

Task performed:

A/C INOP - FOUND BOLTS FALLING OUT OF A/C COMPRESSURE

INSTALLED NEW BOLTS AND TESTED A/C.

Workorder: V60513

In Date: 09/15/2013 Meter Reading: 209,511.60

Close Date: 10/10/2013 Problem?

warning light, water in fuel light is on. R43

1. WATER IN FUEL LIGHT ON - REMOVED FILTER AND CLEANED SENSOR AND ALL TESTED OK. 2. READJUSTED ALL SLIDE OUT DRAWS IN REAR OF RESCUE.

NO PARTS USED

Quantity

**Parts** 



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V61167

In Date: 10/10/2013

10/31/2013

Meter Reading:

209,511.60

Close Date: Problem?

replace cracked radiator

Task performed:

1. WORK ON RADIATOR HENCH. 2. WORK ON REMOVING RADIATOF

3. REMOVE AND REPLACE RADIATOR. INSTALL BRACKETS AND MOUNTING. 4. INSTALL FITTINGS FOR TRANY COOLER TOP OFF FLUIDS TEST FOR OPERATION IS GOOD AND READY NOW.

Workorder: V61662

In Date: 10/30/2013 Meter Reading:

Close Date: 11/04/2013

Problem?

front A/C not workingproperly, not blowing cold, station 74

Task performed:

TRAVEL TO 74 DRIVER COMPLAINT A/C INOP CHECKED SYSTEM PRESSURES ALL GOOD AND AIM IS COLD NO PROBLEM.

**Parts** 

**Parts** 

Quantity

A0516058001F10 RESCUE C RADIATOR

- 1

Quantity



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V61770

In Date: 11/04/2013 Me

11/06/2013

**Meter Reading:** 209,511.60

Close Date: Problem?

cab a/c warm

#### Task performed:

VACUUMED SYSTEM- REMOVED SEAT BY REAR UNIT CUT ACCESS HOLE TO GET TO EXPANSION VALVE CHANGED BOTH EXPANSION VALVES AND DRYERS CLEANED CONDENSER FINS CHARGED A/C TESTED GOOD-INSTALLED PLATES FOR ACCESS DOOR REASSEMBLED CONDENSER FANS.

Parts	Quantity
12-2612A1602 EXPANSION VALVE	1
16-3007TAPE 8990	1
160012-2012A EXPANSION VALVE 71R8301	1
716907-0610A DRYER	1
78R536078R5360M 2PK FILTER AIR COND	1
RD-5-7063-OP07-2618A A/C DRIER 7155	1

Workorder: V62216

In Date: 11/22/2013

Close Date: 12/16/2013

**Meter Reading:** 210,652.60

Problem?

A inspection

Task performed:

A INSP.

Parts	Quantity
322502BULB PATIENT GH22	2
S448GAUGE TIRE TREAD DEPTH	1



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V61061

In Date: 10/07/2013

Close Date: 12/17/2013

**Problem?** 

B inspection SR13

Task performed:

B INSPECTION OIL CHANGE SERVICES

Vendor? OIL CHANGE SERVICES

Workorder: V62620

In Date: 12/10/2013

Close Date: 12/18/2013

Problem?

Close Date: Problem?

Repair broken body door handle.

Task performed:

TRAVEL TO ST-15 SIDE DOOR HANDLE BROKEN PULL DOOR APAR R&R OUTLET HANDLE AND ADJUST LATCHES TEST OK.

Meter Reading:

Meter Reading:

Meter Reading:

209,511.60

211,232.80

212.248.60

Workorder: V63015

In Date: 12/30/2013

12/31/2013

R32 in spare got in an accident

Task performed:

ACCIDENTS, HIT AT INTERSECTION, TOWED TO SHOP AND

SWAPPED OUT.

Parts

000090155133634 FUEL FILTER WIX MERCEDES 1
00018017090IL FILTER 03 57215 WIX MERCEDES 1
R90PFILTER FUEL 33231 1

**Parts** 

**Parts** 

HND5948TM22676-02 HANDLE DOOR ENTRY

Quantity

Quantity

Quantity



\* ADVANCED LIFE SUPPORT VEHICLE

22-49905-000CABLE HEATER

Workorder: V62748

In Date: 12/16/2013 Close Date:

01/02/2014

Meter Reading:

211,232.80

**Problem?** 

A-inspection

Task performed:

1. TOPPED OFF ENGINE OIL, P/S FLUID COOLANT AND WASHER FLUID. REPLACED. 2. A-INSPECTION/ COMPLETED A-INSPECTION. 3 HEATER INOP/BROKEN/REPLACED HEATER CABLE. 4. NADAR PIN COVER/BROKEN/REPLACED COVER.

Workorder: V64226

In Date: 02/14/2014 Close Date:

02/18/2014

Meter Reading:

212,248.60

Problem?

No start

Task performed:

CHECK FOR NO START RECHARGE BATTERIES AND LET RUN FOR WHILE TO ENGINE CHARGING SYSTEM OK.

**Parts** 

**Parts** 

Quantity

Quantity



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V66376

In Date: 05/10/2014 Meter Reading: 80,746.00

Close Date: 06/16/2014

Problem?

A inspection SR13, accident damage repaired, take a good test drive to ensure unit drives properly

#### Task performed:

1) A srevice. 2) vehicle ran out of diesel fuel, fuel tank from another vehicle, bleaded system of air , drive to fuel dack fuel truck. 3) water in fuel light on removed filter cleaned blow replaced sonsor reinstalled and fill wit fresh fuel tested ok. 4) replaced left side siren frame and speaker installed all connectors 5) diagnoise rear a/c warm.air found small leak at schrader value pump down replaced scharder value vac and charged system ok. 6) patient compt, drawer slides bad replaced slider trackesand adj, ok. 7) repaired cabinet door latchs not working adj, ok 8) diagnoise frt, a/c warm. found a/c compressor bad pump down and replace a/c compressor vac and charge system ok. 9) replaced dryer also two bad bolts in momt, to compressor need to be replaced. installed belts, repaired wires to compressor ran system ok. 10) left low beam out & right high beam out replaced both head lights. 11) inlstall protective loom on fuel line & secured. 12) low coolant found leaks at clamps cut off old spring clamp replaced clamps with new one fill and tested system ok. 13) oil level over full drain oil to proper level. 14) diagnoise fauld in node 1 pin I code logged fron left head light high beam ok after head lights replaced. 15) replaced batteries all.

Parts	Quantity			
16-31438915 VALVE CORE A/C 3544706C1	1	$\neg$		
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER B/	4			
HP-31DBATTERY 950CCA HP-31D	4			
RAIRK30880N122WSKI 4000 SENSOR WATER IN FU	1			



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V67311

In Date: 06/18/2014 **Close Date:** 

06/23/2014

Meter Reading:

89,822.00

213,751.20

**Problem?** 

Wipers inop

Task performed:

TRAVEL TO ST-39 CHECK WIRES INOP SWITCH BAD DIDN'T HAVE SWITCH, GO TO SHOP FOR SWITCH RETURN R&R SWITCH TEST OF

Meter Reading:

Quantity 064615900006-46159-001 SWITCH WIPER

Workorder: V68342

In Date: 08/01/2014

Close Date: 08/05/2014

Problem?

A inspection SR13

Task performed:

A inspection repair sharps drawer park units in lot rear brakes making popping sound Truck due for C ser, new ticket made

**Parts** Quantity

3744BRAKE DRUM REAR	2
5632-1010 IN DRAWER SLIDES PR	1
A1834388002MOLD L/H	1
A1834388003MOLD R/H	1
KSMA3124710QKSMA3124710QP REAR BRAKE SHC	2
MA15425CHAMBER 24/30	2
R802446AUTO SLACK ADJ	1
R802447AUTO SLACK ADJ	1

**Parts** 



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V68798

In Date: 08/19/2014 Close Date:

08/21/2014

Problem?

Replace rear tires

Task performed: Replace rear tires.

Vendor? ELPEX

Workorder: V68384

In Date: 08/04/2014

09/15/2014

Close Date:

Problem?

C inspection SR13

### Task performed:

1."C" Inspection 2.Repairs 3.Remove and replace breaks. Slack adjusters , chambers, shoes and springs. 4. Service air dryer. 5-6. Training on diassembly and complete set up of all componets and reassembly. Adjustments etc. 7-8. Training on rear air brake diagnosis, teardown, assembly, installation and adjustment. 9.Re-install tires. Remove and replace belt. Install new tires on front. Rear dump swtich. Test drove. Clea up bay. 10. Quality check inspection. (SCBA bracket L-2 loose, Fire ext. strap missing, Inside door panels loose, Grip tape worn on right patient door, Insulate Exh. pipe on right side by step) 11. Repair items from Kevins QA list.

Meter Reading:

Meter Reading:

213,751.20

213,751.20

	Parts									Quai	ntity	
_		 		 	 			 		 		_

**NO PARTS USED** 

Quantity **Parts** 

000090155133634 FUEL FILTER WIX **MERCEDES** 0001801709OIL FILTER 03 57215 WIX MERCEDES 0127110042BELT MERCEDES MOTORS 107796DRYER KIT AD9 -NEW 107800VALVE CHECK AD9 26 15W40BSYN OIL BULK QTS 29526898 29548988 TRANS FILTER ALLISON 6807200575HANDLE DOOR 78R536078R5360M 2PK FILTER AIR COND 800405PURGE VALVE KIT 9425BELT MERCEDES RESCUE 12.5X1075 OE CA8193AIR FILTER 46744 WIX R90PFILTER FUEL 33231 6 TRANSYNDALLISON TRANS FLUID GAL



Workorder: V69135

09/03/2014

In Date:

## **Palm Beach County Fire Rescue Fleet Maintenance Asset History**

10156657

\* ADVANCED LIFE SUPPORT VEHICLE

In Date: Close Date: Problem?	09/03/2014 09/19/2014	Meter Reading:	214,057.00								
stretcher i	nop			Parts Quanti							
Task performed series	r <b>med:</b> stretcher and adj	justed latch.		NO PARTS USED							
Workorder	: V69283										
In Date: Close Date: Problem?	09/10/2014 09/19/2014	Meter Reading:									

**Parts** 

Task performed:

AC is broken R36

RAN A/C AND TESTED OK.

**NO PARTS USED** 

Quantity

Workorder: V69217

In Date: 09/07/2014

09/29/2014

Meter Reading: 115,570.00

Close Date: Problem?

no cab a/c **Parts** Quantity

Task performed:

RECHARGED A/C AND CLEANED CONDENCER FANS AND CK, FOR

LEAKS.



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V70097

In Date: 10/13/2014 **Close Date:** 

10/30/2014

Meter Reading: 210,011.00

Problem?

install power point for triptix

Travel to 28 repaired connection for triptix

**Parts** Quantity

2 56415CIG. LIGHTER ACCES.

Workorder: V70213

Task performed:

In Date: 10/16/2014

Close Date: 11/03/2014

Front A/C blowing hot, R28

Problem?

**Parts** Quantity

Task performed:

Travel to 28, checked A/C cleaned out condensers

NO PARTS USED

Workorder: V70431

In Date: 10/24/2014

Close Date: 11/03/2014

Meter Reading:

Meter Reading:

215,598.60

Problem?

A inspection SR13

Quantity **Parts** 

Task performed:

1. "A" Inspection 2. Install wiper blades and set tire pressures

52-24WIPER BLADES ANCO 24

2



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V70753

11/06/2014 In Date: 11/06/2014

Meter Reading: 215,763.60

Close Date:

Problem?

engine overheats at idle, SR-13

### Task performed:

check for overheating, check fan operation, found fan not comming on. check air supply to fan ok, remove coolant, hoses, fan shroud, and fan hub install new hub and reinstall all above, refill coolant run engine to operating temp, fan comes on, road test ok

**Parts** Quantity

HOR/991450HT 650 FAN ASY.

284358GOVERNOR D-2

Quantity

Workorder: V70772

In Date: 11/07/2014

11/13/2014

Meter Reading: 215,763.60

Close Date: Problem?

> **Parts** air not building

### Task performed:

Air not building above 50 PSI, replaced air governer air still not building compressor possibly faulty. Swapped into spare unit

Workorder: V70866

In Date: 11/12/2014 Close Date: 11/14/2014

Meter Reading: 147,184.80

Problem?

air leak

Quantity **Parts** 

### Task performed:

1. Travel to 21. Found bad Humphrey valve and bad stretcher latch. R & F valve and latch. 2. Travel to 21. Repaired air leak in airbag circuit.

090-0278STRECHER BAR NEW SU68088VALVE DUMP 310 HUMPHREY



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

800405PURGE VALVE KIT

Workorder: V70818

In Date: 11/10/2014 Close Date: 11/21/2014

**Meter Reading:** 215,763.60

Problem?

won't build air

Task performed:

Trace out no air-replace purge valve air lines to dryer. Trace out d-2 gov, hook up air line wrong. Check compressor by pass hook up wrong repair all get work with out have to replace compressor ok

Workorder: V71378

In Date: 12/03/2014 Meter Reading: 216,280.00

Close Date: 12/03/2014

Problem?

air horns inop, Spare Rescue at 46

Task performed:

air horns need adjusting, remove air horn ends and clean threads on cap to be able to adjust, ok

Parts

**Parts** 

Quantity

Quantity



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V69791

In Date: 09/30/2014 Close Date: 12/12/2014

Meter Reading: 210,011.00

Problem?

repair light bar

.

#### Task performed:

1. a & b. Light bar detached. Reattach light bar and reattach spot light. Seal roof top and size new lenses for light bar. 2. Install new drawer slides

- ballbearings falling out.

Parts	Quantity
9UCAPCC9UCAPCC END CAP CLEAR	1
9ULENSCCLEAR LENS FREEDOM BAR	1
LGHGO-2020GOLIGHT MODEL 2020 SEARCH LIGHT	1
MAKJ29ADJ. LIGHT BAR MOUNT	1
PRMISCONLA PIERCER 2 DUAL STROBE	1
SLD5366HT4932-16 DRAWER SLIDE 16	1

Workorder: V71221

In Date: 11/26/2014

Close Date: 01/02/2015

**Meter Reading:** 216,280.00

Problem?

A inspection SR13

Task performed:

1. "A" inspection 2. Adjust air horns 3. Tighten all comp door brackets

Parts	Quantity Quantity
S153BLOW GUN	1
S777COUPLING NIPPLE	1



10156657

\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V72528

In Date: 01/22/2015 Meter Reading:

Close Date: 01/23/2015

Problem?

A-inspection

#### Task performed:

1. A Inspection. 2. Patient compartment a/c inoperable. Check system and found low on freon. Check for leak and found hi side line leaking. Remove freon. Remove charging point fitting and install new fitting. Vacuum to charge system. Operate and cooling to 25 degrees F. 3. Cab rear a/c filter damaged. Remove and install new filter. 4. Slow crank/no start. Found uni shoreline charger 110V breaker tripped. Reset and check system working normally.

216,813.00

Parts	Quantity	
493170HOSE & FITTING	1	
78R536078R5360M 2PK FILTER AIR COND	1	

Workorder: V73427

In Date: 02/25/2015 Meter Reading: 218,426.10 **Close Date:** 03/20/2015

**Problem?** 

Air leak

### Task performed:

1. Find and repair air leaks in dashboard air switches, 2. Fix all electric over air switches in dash for warning systems.

**Parts** Quantity FSC17491121AIR SWITCH



\* ADVANCED LIFE SUPPORT VEHICLE

Workorder: V74159

In Date: 03/25/2015

03/26/2015

Close Date: Problem?

Meter Reading:

Cab AC is not working. @48

Task performed:

travel to sta-44, check a/c found low on Freon, top off so r-44 crew can

21,871.20

swap into it. travel back to s/shop

Workorder: V74229

In Date: 03/27/2015 Meter Reading:

04/29/2015

Close Date: 04/2

A/C inop @ 44

**Problem?** 

Task performed:

1. Went from ST 42 with EDO to check A/C on SR-13 charbe cab A/C and drop EDO off at south shop when went back to cent. shop.

NO PARTS USED

**Parts** 

**Parts** 

s \_\_\_\_\_ Quantity

Quantity

NO PARTS USED

316