

1/2/2018
12:17:28PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10161701 2005 JOHN DEERE 673 Roto-Tiller,6'Pull-Behind

Workorder: 553481 **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts
In Date: 08/18/2005	Hours	Description
Close Date: 08/18/2005		Quantity
- Pre-Delivery Inspection	2.00	
Parts Charge: 0.00	Labor Charge: 100.00	

Workorder: 1111068 **Problem:** gear box

Meter Reading: 0	Labor	Parts
In Date: 10/18/2011	Hours	Description
Close Date: 11/18/2011		Quantity
- Rebuild Damged Gear Box And Service Side Chain Box	6.00	SHOP SUPPLIES 1.00
- Weld Repair And Support Leg Bracket		85/140 GEAR OIL GEAR LUBE 4.00
- Shop Supplies		SEAL 1.00
		BEARING 1.00
		BEARING 1.00
		SHIM 1.00
		GASKET KIT 1.00
Parts Charge: 184.26	Labor Charge: 360.00	

Workorder: 1710256 **Problem:** Onsite Lube

Meter Reading: 0	Labor	Parts
In Date: 10/19/2017	Hours	Description
Close Date: 10/19/2017		Quantity
- Onsite Lube	1.00	SHOP SUPPLIES 1.00
- Shop Supplies		
Parts Charge: 2.00	Labor Charge: 60.00	

Workorder: 1710800 **Problem:** Transition Prep Charge

Meter Reading: 0	Labor	Parts
In Date: 11/01/2017	Hours	Description
Close Date: 11/01/2017		Quantity
- Transition Prep Charge	2.00	
Parts Charge: 0.00	Labor Charge: 0.00	

Total Parts Charges:	186.26	Total Labor Charges:	520.00	Total Comm. Charges:	0.00
----------------------	---------------	----------------------	---------------	----------------------	-------------