

1/2/2018
12:18:03PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166620 2006 ROTA DAIRON RD130 Soil Renovator

Workorder: 644546 **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts	Quantity
In Date: 08/23/2006	Hours	Description	
- Pre-Delivery Inspection	2.00		
Parts Charge:	0.00	Labor Charge:	100.00

Workorder: 941629 **Problem:** 9950

Meter Reading: 0	Labor	Parts	Quantity
In Date: 08/04/2009	Hours	Description	
- On Site Lube	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 1012312 **Problem:** 9950

Meter Reading: 0	Labor	Parts	Quantity
In Date: 11/02/2010	Hours	Description	
- On Site Lube	1.50	SHOP SUPPLIES	1.00
- Replace Missing Grease Fittings			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	90.00

Workorder: 1113187 **Problem:** 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 0	Labor	Parts	Quantity
In Date: 12/14/2011	Hours	Description	
- 1 - Detail Vehicle Wash Ticket(S) Issued			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	97.92

Workorder: 1401843 **Problem:** 9950

Meter Reading: 0	Labor	Parts	Quantity
In Date: 02/26/2014	Hours	Description	
- Onsite Lube	1.00	GREASE NLGI 2	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	9.23	Labor Charge:	60.00

1/2/2018
12:18:03PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10166620 2006 ROTA DAIRON RD130 Soil Renovator

Workorder: 1603063

Problem: input shaft bearing failure/ see notes

Meter Reading: 0	Labor	Parts			
In Date: 03/23/2016	Hours	Quantity			
Close Date: 04/29/2016	Description				
- Diagnose Pto Bearing Failer Dissemble Transmission From Tiller Replace Transmission And Driveshaft Cover Fill With Gear Oil	5.00	1QT SYNGEAR OIL 75-90 SHOP SUPPLIES GEAR BOX PTO COVER O RING Freight Charge	2.00 1.00 1.00 1.00 1.00 1.00		
- Shop Supplies					
Parts Charge:	1,558.27	Labor Charge:	300.00		
Total Parts Charges:	1,571.50	Total Labor Charges:	610.00	Total Comm. Charges:	97.92