10169434 2008 FORD F250 Pickup, 3/4 Ton, Ext Cab, 4X4

Workorder: Problem:	741237 PRE-DELIVER	Meter: Y INSPE				In Date:	07/11/2007	Closed:	07/11/20	07
- Pre-delivery	Inspection									
	Hours :	2.00		Labor:	110.00	Parts:	0.00	Total:	110.00	
Workorder: Problem:	741554 FLOOR MATS	Meter:	369			In Date:	07/17/2007	Closed:	08/30/20	07
- Order & Inst	all Floor Mats.				Parts Li	st				Qty
- Install Nerf E	Bars With Brack	ets Install	2 Spot Mirrors	S.	Shop Su	upplies				1.00
- Shop Suppli	es				7039d S	Spot Mirror V	elvac 723060/)		2.00
					8c3z261	3300b Floo	r Mat Set			1.00
						lerf Bar Set				1.00
	Hours :	3.50		Labor:	192.50	Parts:	906.19	Total:	1,098.69	
Workorder: Problem:	745553 P.M SERVICE,	Meter: SEE NO	4860 TE			In Date:	10/15/2007	Closed:	10/17/20	07
	repl Air Filter Wi	iper Blade	es,fire Ext Fue	I	Parts Li	st				Qty
Additive, rotate		- Ft l	:alata Mandal NI	-4	Shop Su					1.00
	be Light Sys,dia Test.remv Both					Air Filter				1.00
Light Bulbs,rep					1372 O		Ph2 Wix 51:	372		1.00
- Hi Speed Ba	alance On All 4	Γires.				ngine Oil	D 11 D			7.00
- Shop Suppli	es					-	ner Don't Red	order		1.00
						/iper Blades	d Fire Extings	hore		2.00
							b For Kit S66			1.00
							lb For Kit S66			1.00
	Hours	4.75		Labor:	285.00		134.22		419.22	1.00
Mantantan	:	N	2			In Data	44/40/0007	011	44/00/00	.07
Workorder: Problem:	747627 001 WASH TIC	Meter: CKET ISS	0 UED OUT 11	/16/07		In Date:	11/16/2007	Closed:	11/20/20	07
	icket Issued Out									
- 001 Wasii I	Hours) (Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	833578 P.M SERVICE	Meter:	9966			In Date:	02/01/2008	Closed:	02/06/20	08
- Pm Service					Parts Li	st				Qty
	Balance All Four	Tires.nitr	o Fill Tires.		Shop Su					1.00
- Shop Suppli					•	• •	Ph2 Wix 51:	372		1.00
					3243 Fu	el Filter Use	Mtc Fg1083			1.00
						ngine Oil				7.00
					10020 Ir	njector Clea	ner Don't Rec	order		1.00
					31-20 W	/iper Blades	20" Blade			2.00
	Hours :	3.75		Labor:	225.00	Parts:	43.44	Total:	268.44	

Workorder:	835518	Meter:	0			In Date:	02/29/2008	Closed:	03/13/2008
Problem:	002 WA	SH TICKETS IS	SUED OUT ()2/29/08					
- 002 Wash T	ickets Iss	ued Out 02/29/	08						
		Hours 0.00 :		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	837246 P.M SEF	Meter: RVICE	14453			In Date:	04/18/2008	Closed:	04/22/2008
- Pm Service					Parts L	ist			Qty
		ration,diag Frt S			Shop St	upplies			1.00
		placed 2 Defect		•	Ca1026	2 Air Filter N	/Itc Fa1883 W	/ix 49883	1.00
		Repl Defective			1372 O	il Filter Frm	Ph2 Wix 513	372	1.00
	•	ance All 4 Tires	s.nitrofill Tires.		G10166	Fuel Filter I	Mtc Fg1083 V	Vix 33243	1.00
- Shop Suppli	ies				5w20 E	ngine Oil			7.00
					1066 W	/hite Lithium	(crc 05037)		1.00
					31-20 W	/iper Blades	20" Blade		2.00
					Used Fi	rex Refurbe	d Fire Extings	hers	1.00
					Custom	5lb Bracket	Firex Stock #	£340060300	1.00
							lb For Kit S66	Осссс	2.00
		Hours 5.25 :		Labor:	315.00	Parts:	176.93	Total:	491.93
Workorder:	837387	Meter:	0			In Date:	04/21/2008	Closed:	04/23/2008
Problem:	001 DET	AIL VEHICLE	04/21/08	3					
- 001 Detail V	ehicle	04/21/08							
001 2010 1	010.0	Hours 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
		:							
Workorder:	838923	Meter:	16710	ONDET		In Date:	05/23/2008	Closed:	05/28/2008
Problem:	NO POV	VER,CHECK E	NGINE LIGHT	ON,DE I	AIL				
		le Miss Fire Co			Parts L	ist			Qty
		d Retest.defect	•		Shop St	upplies			1.00
Repairs To F	Replace F	And From Deal uel Pump.	er For Warran	ty	G10166	Fuel Filter I	VItc Fg1083 V	Vix 33243	1.00
- Shop Suppli	ies								
		Hours 3.20		Labor:	192.00	Parts:	19.15	Total:	211.15
Workorder: Problem:	839245	Meter:	0 05/27/08	3		In Date:	05/27/2008	Closed:	05/30/2008
	OOTDET	, all vernole							
- 001 Detail V		05/27/08							
- 001 Detail V				Labor:	0.00	Parts:	0.00	Total:	0.00

Workorder: Problem:	841270 P.M SEI	Meter: RVICE,DETAIL	19257			In Date:	07/11/2008	Closed:	07/21/20	800
- Pm Service					Parts Li	ist				Qty
		ts.diagnosed Le	ft Front,check	ed	Shop Su	upplies				1.00
Circuit, Replac					1372 O	il Filter Frm	Ph2 Wix 513	372		1.00
	•	alance 4 Tires/			G10166	Fuel Filter	Mtc Fg1083 W	/ix 33243		1.00
- Shop Suppli	es				5w20 Er	ngine Oil				7.00
					31-20 W	/iper Blades	20" Blade			2.00
					S30hac	Strobe Bulb	use S30hac	p)		1.00
					S30hac	Strobe Bulb	use S30hac	p)		-1.00
					S30hac	p Strobe Bu	lb For Kit S66	Осссс		1.00
		Hours 4.25 :		Labor:	255.00	Parts:	85.22	Total:	340.22	
Workorder: Problem:	841526 001 DE	Meter: TAIL VEHICLE	0 07/14/08	3		In Date:	07/14/2008	Closed:	07/16/2	800
- 001 Detail V	ehicle	07/14/08								
		Hours 0.00 :		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	843972 LEFT AI	Meter: LLEY LAMP ANI	22207 D DOME LAW	IP OUT		In Date:	09/10/2008	Closed:	09/16/2	800
	nd Dome	ome Lamp Bulbs Lamp Bulbs Wit			Shop St					Qty 1.00 2.00
		Hours 1.50 :		Labor:	90.00	Parts:	17.45	Total:	107.45	
Workorder: Problem:	846164 P.M SEI	Meter: RVICE,DETAIL	24712			In Date:	10/24/2008	Closed:	10/29/2	800
- Pm Service					Parts Li	ist				Qty
		Circuit,remv R/f	Headlamp To	Access	Shop Su	upplies				1.00
& R&r Defecti					Ca1026	2 Air Filter N	Mtc Fa1883 W	ix 49883		1.00
- Service Trar	,				1372 O	il Filter Frm	Ph2 Wix 513	372		1.00
`	•	Balance 4 Tires	,nitro Fill To S	Spec.	G10166	Fuel Filter	Mtc Fg1083 W	/ix 33243		1.00
- Shop Suppli	es				5w20 Er	ngine Oil				7.00
					Syn/atf	Trans Fluid	Synthetic			12.00
					31-20 W	/iper Blades	20" Blade			2.00
					Used Fi	rex Refurbe	d Fire Extings	hers		1.00
					S30hac	Strobe Bulb	use S30hac	p)		1.00
		Hours 6.25		Labor:	375.00	Parts:	176.46	Total:	551.46	
Workorder: Problem:	846310 001 DE	Meter: TAIL VEHICLE	0 10/28/08	3		In Date:	10/28/2008	Closed:	10/29/20	800
- 001 Detail V	ehicle	10/28/08								
		Hours 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	

Workorder: 934271 Problem: P.M. SI	ERVICE	Meter: .DETAIL	29809			In Date:	02/20/2009	Closed:	02/25/20	009
- Pm Service					Parts Lis	st				Qty
- Replace Both Defect	ive Fror	nt Strobe	Bulbs.		Shop Su	pplies				1.00
- Mount And Balance	4 New 1	Tires Nitro	o Fill.		1372 Oi	 I Filter Frm	n Ph2 Wix 513	372		1.00
- Complete Front End	Alignme	ent.test D	rive.		5w20 En	gine Oil				7.00
- Shop Supplies					31-20 W	iper Blades	s 20" Blade			2.00
					S30hacp	Strobe Bu	lb For Kit S66	Осссс		2.00
					Tire Disp	osal Fee				4.00
					Tr416 Va	alve Stem				4.00
					7485351	89 265/70	r17 Wrg Slt A	rmour E		4.00
	Hours :	8.25		Labor:	495.00	Parts:	922.64	Total:	1,417.6	4
Workorder: 934577 Problem: 001 DE		Meter: EHICLE	0 02/26	6/09		In Date:	02/26/2009	Closed:	02/27/20	009
- 001 Detail Vehicle	02/	26/09								
	Hours	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Problem: PM SE - Pm Service	RVICE,	ALSO SE	E NOTES	ON SIGNAL	S & HEA					Qty
- Diag Light Sys,r&r R	/f Head	Lamp Bu	ılb r&r l /r 9	Signal Bulb	Shop Su					1.00
& Repair Loose Conne				- · g. · · · · · · · ·	•	• •	Mtc Fa1883 W	ix 49883		1.00
- Rotate And Hi Speed	d Baland	ce All 4 T	ires. Nitro	Fill To	1372 Oi	l Filter Frm	n Ph2 Wix 513	372		1.00
Specs					5w20 En	gine Oil				7.00
- Shop Supplies					Used Fir	ex Refurbe	d Fire Extings	hers		1.00
					H6054 S	ealed Bear	m			1.00
					3157 Tai	I Light Bulb	os			1.00
	Hours :	5.25		Labor:	315.00	Parts:	45.81	Total:	360.81	
Workorder: 940489 Problem: Flat tire		Meter:	36290			In Date:	07/08/2009	Closed:	07/08/20	009
- Repair L/r tire					Parts Lis	st				Qty
- Shop Supplies					Shop Su	pplies				1.00
	Hours	1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: 942858		Meter:	39174			In Date:	09/02/2009	Closed:	09/03/20	009
Problem: Check	ights.									
		f turn sia	nal.		Parts Lis	st				Qtv
- Check all lights & re		f turn sig	nal.		Parts Lis					Qty
		f turn sig	nal.		Shop Su					Qty 1.00

Workorder: Problem:	943111 P.M. Service	Meter:	39711			In Date:	09/10/2009	Closed:	09/15/200	9
- P.m service.					Parts L	ist				Qty
- Test & repla	ce both front	strobe bulbs	S.		Shop St	upplies			1	1.00
- Perform air i & test drive.	nduction syst	em cleaning	j. Flush fue	l injectors	L17301a Blend)	a Engine Fo	g Kit Hard Ca	rbon (smart	1	1.00
- Test & repla	ce 3rd brake	lamp bulb.			L17040	Inject Clear	ner One Part (smart Blend) 1	1.00
- Rotate & bal	ance all four	tires.			G10166	Fuel Filter I	Mtc Fg1083 V	Vix 33243	1	1.00
- Shop Suppli	es				1372 O	il Filter Frm	Ph2 Wix 51	372	1	1.00
					5w20 E	ngine Oil			7	7.00
					31-20 W	Viper Blades	20" Blade		2	2.00
						•	lb For Kit S66			2.00
	Hou	urs 7.55		Labor:	453.00	Parts:	200.67	Total:	653.67	
Workorder: Problem:	1000735 P.M service,	Meter: nail in L/R t	45206 tire.			In Date:	01/20/2010	Closed:	01/26/201	0
- P.m service.					Parts L	ist				Qty
- Replace tail	gate protecto	r cap. repla	ce worn bra	ake pedal	Shop St	upplies			1	1.00
pad.			_		1372 O	il Filter Frm	Ph2 Wix 51	372	1	1.00
- Repair L/r tir		alance all fou	ur tires.		5w20 E	ngine Oil			7	7.00
- Shop Suppli	es				D3tz245	57b Brake P	edal Pad		1	1.00
					Tail Gat	e Cap / 8c3	z9940602aa		1	1.00
	Hou :	urs 5.25		Labor:	315.00	Parts:	63.76	Total:	378.76	
Workorder: Problem:	1001094 Install custor	Meter: mers DMI.	45582			In Date:	01/29/2010	Closed:	02/02/201	0
- Fabricate &	install Dmi sy	stem & wire	harness		Parts L	ist				Qty
- Shop Suppli	es				Shop St	upplies			1	1.00
	Hou	urs 4.00		Labor:	240.00	Parts:	2.00	Total:	242.00	
Workorder: Problem:	1001432 1 - Wash tick	Meter: ket(s) issued	45735			In Date:	02/09/2010	Closed:	02/09/201	0
- 1 - Wash ticl	ket(s) issued									
	, ,	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1001451 1 - Wash tick	Meter: ket(s) issued	45735			In Date:	02/09/2010	Closed:	02/09/201	0
- 1 - Wash ticl	ket(s) issued									
	Hou	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	

Workorder: Problem:	1001591 Replace fron	Meter: t tires.	46218		lr	n Date:	02/12/2010	Closed:	02/16/2	010
- Mount, bala	ance & nitro fill	two new fro	ont tires.		Parts List					Qty
- Shop Suppl	lies				Shop Supp	olies				1.00
					179535492	2 Lt265/7	0r17 Wrangle	r Sr-a E		2.00
					Tire Dispos	sal Fee				2.00
	Hou :	ırs 1.50		Labor:	90.00	Parts:	378.33	Total:	468.33	
Workorder: Problem:	1004500 P.M service,	Meter: noise in rea	50173 ar over bump	s, Detail.	Ir	n Date:	05/03/2010	Closed:	05/04/2	010
- P.m service	Э.				Parts List					Qty
	light system, r	emove L/f I	neadlamp ass	sembly &	Shop Supp	olies				1.00
replace strobe					1372 Oil F	ilter Frm	n Ph2 Wix 513	372		1.00
	new tires, rotat				Ca10262 A	Air Filter I	Vitc Fa1883 W	ix 49883		1.00
- Pressure te coolant.	est & inspect co	oung syste	m, nusn & fer	iew			Mtc Fg1083 W	/ix 33243		1.00
- Shop Suppl	lies				5w20 Engi		0011 D1 1			7.00
					31-20 Wipe			hara		2.00
							d Fire Extings Ib For Kit S66			1.00
					•		All Makes (pea			2.00
							0r17 Wranglei	•		2.00
					Tire Dispos		J			2.00
	Hou	ırs 7.45		Labor:	447.00	Parts:	504.77	Total:	951.77	
Manlagadan										
	1004589 : 1 - Detail Vel ehicle Wash Ti Hou		, ,	ued Labor:		Date: Parts:	05/03/2010	Closed:	05/03/2	010
Problem: - 1 - Detail Vo Workorder:	: 1 - Detail Vel	hicle Wash	Ticket(s) Issu		0.00					
Problem: - 1 - Detail Vo Workorder: Problem:	ehicle Wash Ti Hou : 1013929 : Pm service.	hicle Wash icket(s) Issu urs 0.00	Ticket(s) Issuued		0.00	Parts:	0.00	Total:	0.00	010
Problem: - 1 - Detail Vo Workorder: Problem: - Perform pm	ehicle Wash Ti Hou : 1013929 : Pm service.	hicle Wash icket(s) Issu urs 0.00 Meter:	Ticket(s) Issuued 61297	Labor:	0.00	Parts:	0.00	Total:	0.00	
Problem: - 1 - Detail Vo Workorder: Problem: - Perform pm - Test and renew.	ehicle Wash Ti Hou : 1013929 : Pm service. n service.	hicle Wash icket(s) Issu urs 0.00 Meter:	Ticket(s) Issuued 61297 bbe lamp bulb	Labor:	0.00 Ir Parts List Shop Supp	Parts: Date:	0.00	Total:	0.00	010 Qty
Problem: - 1 - Detail Vo Workorder: Problem: - Perform pm - Test and re new Install new	ehicle Wash Ti Hou : 1013929 : Pm service. eplace failed rig	hicle Wash icket(s) Issuurs 0.00 Meter: The front strong and results and results in the control of the contro	Ticket(s) Issuued 61297 bbe lamp bulb	Labor:	0.00 Ir Parts List Shop Supp	Parts: Date: Dilies Filter Frm	0.00 12/17/2010 n Ph2 Wix 513	Total:	0.00	010 Qty 1.00
Problem: - 1 - Detail Vo Workorder: Problem: - Perform pm - Test and re new Install new rotors.service	ehicle Wash Ti Hou : 1013929 : Pm service. eplace failed rig	hicle Wash licket(s) Issu urs 0.00 Meter: The front strong the s	Ticket(s) Issuued 61297 bbe lamp bulb rface two fromke fluid flush.	Labor: with	0.00 Parts List Shop Supp 1372 Oil F	Parts: Date: Dilies Tilter Frm ake Clear	0.00 12/17/2010 n Ph2 Wix 513	Total:	0.00	010 Qty 1.00 1.00
Problem: - 1 - Detail Vo Workorder: Problem: - Perform pm - Test and re new Install new rotors.service	tehicle Wash Ti Hou : 1013929 : Pm service. In service. In service failed right brake pace and percent brake pace	hicle Wash licket(s) Issu urs 0.00 Meter: The front strong the s	Ticket(s) Issuued 61297 bbe lamp bulb rface two fromke fluid flush.	Labor: with	0.00 Parts List Shop Supp 1372 Oil F 09997 Bra Front Pads 5w20 Engin	Parts: Date: Diles Filter Frm Rec Clear Companies Companies	0.00 12/17/2010 n Ph2 Wix 513	Total:	0.00	010 Qty 1.00 1.00 1.00 7.00
Problem: - 1 - Detail Vo Workorder: Problem: - Perform pm - Test and re new Install new rotors.service - Install two re balance all fo - Test starting	tehicle Wash Ti Hou : 1013929 : Pm service. eplace failed right front brake pace calipers and prew tires to the four. g and charging	hicle Wash icket(s) Issuurs 0.00 Meter: The front strong and resurber or brain front wheels system.ba	Ticket(s) Issued 61297 bbe lamp bulbourface two from the fluid flush. Ils.nitrogen fillottery failed locations.	Labor: with at	0.00 Parts List Shop Supp 1372 Oil F 09997 Bra Front Pads 5w20 Engin	Parts: Date: Diles Filter Frm Re Clear Companies The Oil The Fluid E	0.00 12/17/2010 In Ph2 Wix 513 In Brake Fluid	Total: Closed:	0.00	010 Qty 1.00 1.00 1.00 1.00 7.00 2.00
Problem: - 1 - Detail Vo Workorder: Problem: - Perform pm - Test and re new Install new rotors.service - Install two r balance all fo - Test starting after recharge	tehicle Wash Ti Hou : 1013929 : Pm service. replace failed right front brake pace calipers and proper tires to the pur. g and charging e.replace failed	hicle Wash licket(s) Issu urs 0.00 Meter: The front strong ds and result berform brace front wheelers I system.bace battery with	Ticket(s) Issued 61297 bbe lamp bulbourface two from the fluid flush. Ils.nitrogen fillottery failed locations.	Labor: with at	0.00 Parts List Shop Supp 1372 Oil F 09997 Bra Front Pads 5w20 Engin 1401 Brak Used Firex	Parts: Date: Dilies Cilter Frm Re Clear Companies Companies	0.00 12/17/2010 1 Ph2 Wix 513	Total: Closed:	0.00	010 Qty 1.00 1.00 1.00 7.00 2.00 1.00
Problem: - 1 - Detail Vo Workorder: Problem: - Perform pm - Test and re new Install new rotors.service - Install two re balance all fo - Test starting after recharge - Perform when	tehicle Wash Ti Hou : 1013929 : Pm service. replace failed right front brake pace calipers and prew tires to the four. g and charging e.replace failed right reel alignment	hicle Wash licket(s) Issu urs 0.00 Meter: The front strong ds and result berform brace front wheelers I system.bace battery with	Ticket(s) Issued 61297 bbe lamp bulbourface two from the fluid flush. Ils.nitrogen fillottery failed locations.	Labor: with at	0.00 Parts List Shop Supp 1372 Oil F 09997 Bra Front Pads 5w20 Engin 1401 Brak Used Firex 31-20 Wipe	Parts: Date: Diles Filter Frm Re Clear Re Fluid E Refurbe Refurbe Rer Blades	0.00 12/17/2010 1 Ph2 Wix 513 Brake Fluid Id Fire Extings 20" Blade	Total: Closed: 372	0.00	010 Qty 1.00 1.00 1.00 7.00 2.00 1.00 2.00
Problem: - 1 - Detail Vo Workorder: Problem: - Perform pm - Test and re new Install new rotors.service - Install two r balance all fo - Test starting after recharge	tehicle Wash Ti Hou : 1013929 : Pm service. replace failed right front brake pace calipers and prew tires to the four. g and charging e.replace failed right reel alignment	hicle Wash licket(s) Issu urs 0.00 Meter: The front strong ds and result berform brace front wheelers I system.bace battery with	Ticket(s) Issued 61297 bbe lamp bulbourface two from the fluid flush. Ils.nitrogen fillottery failed locations.	Labor: with at	0.00 Parts List Shop Supp 1372 Oil F 09997 Bra Front Pads 5w20 Engin 1401 Brak Used Firex 31-20 Wipe S30hacp S	Parts: Date: Diles Cilter Frm Re Clear Cane Oil Cane Fluid Ear Refurbe Car Blades Carrobe Bu	0.00 12/17/2010 1 Ph2 Wix 513 Brake Fluid ad Fire Extings 20" Blade alb For Kit S66	Total: Closed: 372 hers	0.00	010 Qty 1.00 1.00 1.00 7.00 2.00 1.00 2.00 1.00
Problem: - 1 - Detail Vo Workorder: Problem: - Perform pm - Test and re new Install new rotors.service - Install two re balance all fo - Test starting after recharge - Perform when	tehicle Wash Ti Hou : 1013929 : Pm service. replace failed right front brake pace calipers and prew tires to the four. g and charging e.replace failed right reel alignment	hicle Wash licket(s) Issu urs 0.00 Meter: The front strong ds and result berform brace front wheelers I system.bace battery with	Ticket(s) Issued 61297 bbe lamp bulbourface two from the fluid flush. Ils.nitrogen fillottery failed locations.	Labor: with at	0.00 Parts List Shop Supp 1372 Oil F 09997 Bra Front Pads 5w20 Engin 1401 Brak Used Firex 31-20 Wipe S30hacp S Group 65 E	Parts: Date: Diles Filter Frm Re Clear Re Fluid E Refurbe Re Blades Strobe Bu Battery (r	0.00 12/17/2010 1 Ph2 Wix 513 Brake Fluid Id Fire Extings 20" Blade Ilb For Kit S66 Into Bxt-65-850	Total: Closed: 372 hers 0cccc	0.00	010 Qty 1.00 1.00 1.00 7.00 2.00 1.00 2.00
Problem: - 1 - Detail Vo Workorder: Problem: - Perform pm - Test and re new Install new rotors.service - Install two re balance all fo - Test starting after recharge - Perform when	tehicle Wash Ti Hou : 1013929 : Pm service. replace failed right front brake pace calipers and prew tires to the four. g and charging e.replace failed right reel alignment	hicle Wash licket(s) Issu urs 0.00 Meter: The front strong ds and result berform brace front wheelers I system.bace battery with	Ticket(s) Issued 61297 bbe lamp bulbourface two from the fluid flush. Ils.nitrogen fillottery failed locations.	Labor: with at	0.00 Parts List Shop Supp 1372 Oil F 09997 Bra Front Pads 5w20 Engin 1401 Brak Used Firex 31-20 Wipe S30hacp S Group 65 E	Parts: Date: Diles Filter Frm Re Clear Re Fluid E Refurbe Refurbe Battery (r	0.00 12/17/2010 1 Ph2 Wix 513 Brake Fluid ad Fire Extings 20" Blade alb For Kit S66	Total: Closed: 372 hers 0cccc	0.00	010 Qty 1.00 1.00 1.00 7.00 2.00 1.00 2.00 1.00
Problem: - 1 - Detail Vo Workorder: Problem: - Perform pm - Test and renew Install new rotors.service - Install two repalance all food after recharged - Perform who	tehicle Wash Ti Hou : 1013929 : Pm service. replace failed right front brake pace calipers and prew tires to the four. g and charging e.replace failed right reel alignment	hicle Wash licket(s) Issu urs 0.00 Meter: The front strong ds and result berform brace front wheelers I system.bace battery with	Ticket(s) Issued 61297 bbe lamp bulbourface two from the fluid flush. Ils.nitrogen fillottery failed locations.	Labor: with at	0.00 Parts List Shop Supp 1372 Oil F 09997 Bra Front Pads 5w20 Engin 1401 Brak Used Firex 31-20 Wipe S30hacp S Group 65 E 179535492	Parts: Date: Date: Diles Filter Frm Re Clear Refurbe Refurbe Refurbe Refurbe Retrobe Bu Battery (re Lt265/7 Re Stem	0.00 12/17/2010 1 Ph2 Wix 513 Brake Fluid Id Fire Extings 20" Blade Ilb For Kit S66 Into Bxt-65-850	Total: Closed: 372 hers 0cccc	0.00	010 Qty 1.00 1.00 1.00 7.00 2.00 1.00 2.00 1.00 2.00

.

	1802 Meter :	67491		In Date:	05/05/2011	Closed:	05/10/20)11
Problem: Pm	service,see notes on	tires and detail vehi	ele.					
- Perform pm servi	ce.		Parts Lis	st				Qty
	lamp.test and repla	ce failed left front	Shop Su	pplies				1.00
strobe lamp bulb wi			1372 Oil	Filter Frm	n Ph2 Wix 51	372		1.00
- Perform transfer			G10166	Fuel Filter	Mtc Fg1083 V	Vix 33243		1.00
	rake pads and resur ers add perform brak		Ca10262	Air Filter N	Mtc Fa1883 W	/ix 49883		1.00
	ed hydralic system		Rear Pag	ds				1.00
	es to the front wheel	s.nitrogen fill and	09997 B	rake Clear	1			1.00
balance all four.					Fluid (motor	rcraft)		2.00
- Shop Supplies			5w20 En	•				7.00
			-		llb For Kit S66			1.00
					0r17 Wrangle	r Sr-a E		2.00
			Tire Disp					2.00
	Hours 10.00	Labor	600.00	Parts:	542.96	Total:	1,142.96	6
Workorder: 1104		67291		In Date:	05/09/2011	Closed:	05/09/20)11
Problem: 1 - D	etail Vehicle Wash	Ticket(s) Issued						
- 1 - Detail Vehicle	Wash Ticket(s) Issu	ed						
	Hours 0.00 :	Labor	0.00	Parts:	0.00	Total:	0.00	
	7212 Meter: k shakes at 45 mph.	68307		In Date:	07/08/2011	Closed:	07/13/20)11
- Diagnose for vibra	ation.replace two wa	rp tires with new and	Parts Lis	st				Qty
	ont wheels.nitrogen	fill and balance all	Shop Su	nnlina				-
t∩lir			Shop Su	pplies				1.00
four.					0r17 Wrangle	r Sr-a E		1.00 2.00
- Shop Supplies				92 Lt265/7	0r17 Wrangle	r Sr-a E		
	Hours 2.00 :	Labor	1795354	92 Lt265/7 oosal Fee	0r17 Wrangle 385.04		505.04	2.00
	: 2258 Meter:	Labor 70111	1795354 Tire Disp	92 Lt265/7 oosal Fee			505.04	2.00
- Shop Supplies Workorder: 1112 Problem: P.M.	: 2258 Meter: service.		1795354 Tire Disp	92 Lt265/7 posal Fee Parts:	385.04	Total:		2.00 2.00
- Shop Supplies Workorder: 1112	: 2258 Meter: service.		1795354 Tire Disp 120.00 Parts Lis	92 Lt265/7 cosal Fee Parts: In Date:	385.04	Total:		2.00
- Shop Supplies Workorder: 1112 Problem: P.M Perform pm service	: 2258 Meter: service.		1795354 Tire Disp 120.00 Parts Lis Shop Su	92 Lt265/7 posal Fee Parts: In Date: st pplies	385.04	Total:		2.00 2.00
- Shop Supplies Workorder: 1112 Problem: P.M Perform pm service - Rotate and balance	: 2258 Meter: service.		1795354 Tire Disp 120.00 Parts Lis Shop Su	92 Lt265/7 cosal Fee Parts: In Date: st pplies I Filter Frm	385.04	Total:		2.00 2.00 011 Qty 1.00
- Shop Supplies Workorder: 1112 Problem: P.M Perform pm service - Rotate and balance	: 2258 Meter: service.		1795354 Tire Disp 120.00 Parts Lis Shop Su 1372 Oil 5w20 En	92 Lt265/7 posal Fee Parts: In Date: st pplies I Filter Frm gine Oil	385.04	Total: Closed:		2.00 2.00 011 Qty 1.00 1.00
- Shop Supplies Workorder: 1112 Problem: P.M Perform pm service - Rotate and balance	: 2258 Meter: service.		1795354 Tire Disp 120.00 Parts Lis Shop Su 1372 Oil 5w20 En 7090blk	92 Lt265/7 cosal Fee Parts: In Date: st pplies I Filter Frm gine Oil Frt Floor M	385.04 11/16/2011 n Ph2 Wix 51	Total: Closed: 372 ueen)		2.00 2.00 011 Qty 1.00 1.00 7.00
- Shop Supplies Workorder: 1112 Problem: P.M Perform pm service - Rotate and balance	: 2258 Meter: service.		1795354 Tire Disp 120.00 Parts Lis Shop Su 1372 Oil 5w20 En 7090blk	92 Lt265/7 posal Fee Parts: In Date: st pplies I Filter Frm gine Oil Frt Floor M ex Refurbe	385.04 11/16/2011 n Ph2 Wix 51 lats (rubber Q	Total: Closed: 372 ueen)		2.00 2.00 2.11 Qty 1.00 1.00 7.00 1.00
- Shop Supplies Workorder: 1112 Problem: P.M Perform pm service - Rotate and balance	: 2258 Meter: service.	70111	1795354 Tire Disp 120.00 Parts Lis Shop Su 1372 Oil 5w20 En 7090blk	92 Lt265/7 posal Fee Parts: In Date: st pplies I Filter Frm gine Oil Frt Floor M ex Refurbe	385.04 11/16/2011 The Ph2 Wix 51stats (rubber Qued Fire Extings)	Total: Closed: 372 ueen) shers		2.00 2.00 2.11 211 211 1.00 1.00 1.00 1.
- Shop Supplies Workorder: 1112 Problem: P.M Perform pm service - Rotate and balance - Shop Supplies Workorder: 1202	: 2258 Meter: service. ce. ce all four tires. Hours 3.75	70111 Labor	1795354 Tire Disp 120.00 Parts Lis Shop Su 1372 Oil 5w20 En 7090blk Used Fire 31-20 Wi	92 Lt265/7 posal Fee Parts: In Date: st pplies I Filter Frm gine Oil Frt Floor M ex Refurbe	385.04 11/16/2011 1 Ph2 Wix 51: lats (rubber Qued Fire Extings a 20" Blade	Total: Closed: 372 ueen) shers	11/21/20	2.00 2.00 2.00 011 Qty 1.00 1.00 1.00 1.00 2.00
- Shop Supplies Workorder: 1112 Problem: P.M Perform pm service - Rotate and balance - Shop Supplies Workorder: 1202 Problem: 1 - D	: 2258 Meter: service. ce. ce all four tires. Hours 3.75 : Meter:	70111 Labor 70514 Ticket(s) Issued	1795354 Tire Disp 120.00 Parts Lis Shop Su 1372 Oil 5w20 En 7090blk Used Fire 31-20 Wi	92 Lt265/7 posal Fee Parts: In Date: st pplies I Filter Frm gine Oil Frt Floor M ex Refurbe iper Blades Parts:	385.04 11/16/2011 The Ph2 Wix 51: lats (rubber Qued Fire Extings as 20" Blade 87.23	Total: Closed: 372 ueen) shers Total:	11/21/20 312.23	2.00 2.00 2.00 011 Qty 1.00 1.00 1.00 1.00 2.00

Workorder:	1204981	Meter:	73635			In Date:	05/30/2012	Closed:	06/11/20	012
		rice and DMI. in	op and check e	engine l	ight on rur					-
- Perform pm	service.				Parts Lis	st				Qty
			light on and run		Ka8a Th	rottle Body/	Up Engine S	ervice Kit		1.00
codes with sca			ugs with new.cl	ear	408 Fuel	Injection C	leaner			1.00
			e lamp bulb with	h	Shop Su	pplies				1.00
		nead lamp asse			1372 Oil	Filter Frm	Ph2 Wix 51	372		1.00
		oricate and repa orted fuse with				Fuel Filter I eering Fluid	Mtc Fg1083 V	Vix 33243		1.00 1.00
- Perform ind	uction serv	rice and clean g	jummed up trott	tle	5w20 En	gine Oil				7.00
body.power flu with scan tool			uel lines.clear co	odes	31-20 Wi	iper Blades	20" Blade			2.00
- Rotate and I	balance all	l tires.			Spark Plu	J	L F			8.00
- Shop Suppli	ies				•		b For Kit S66			1.00
							mperial 8086			1.00
		Hours 11.75		Labor:	705.00	Parts:	277.98	Total:	982.98	
Workorder: Problem:	1205655 DMI is inc	Meter:	73829			In Date:	06/14/2012	Closed:	06/21/20	012
- Diagnose in recalibrate.	op Dmi.rep	place defective	interface modul	le and	Parts Lis					Qty
	ioc				Shop Su	pplies				1.00
- Shop Suppli		Hours 1.50	,	Labor:	00.00	Parts:	2.00	Total	92.00	
		:	'	Laboi.	90.00	raits.	2.00	TOtal.	92.00	
Workorder: Problem:	1301371 Right fror	Meter: nt strobe lamp in	79380 nop and P.M. se	ervice.		In Date:	02/07/2013	Closed:	02/21/20	013
Problem:	Right fror	nt strobe lamp in	nop and P.M. se		Parts Lis		02/07/2013	Closed:	02/21/20	
Problem:	Right fror	nt strobe lamp in				st		Closed:	02/21/20	Qty
Problem: - Remove rigi	Right fror ht headlam mp bulb wi	nt strobe lamp in	nop and P.M. se		S30hacp	st Strobe Bul		Closed:	02/21/20	Qty 1.00
Problem: - Remove rigit front strobe la	Right fror ht headlam mp bulb wi service.	nt strobe lamp in to acess and ith new.	nop and P.M. se		S30hacp 5w20 En	st Strobe Bul gine Oil		Closed:	02/21/20	Qty 1.00 7.00
Problem: - Remove right front strobe later - Perform pm	Right fron ht headlam mp bulb wi service. balance all	nt strobe lamp in to acess and ith new.	nop and P.M. se		S30hacp 5w20 En 1372 Oil	st Strobe Bul gine Oil Filter	b F	Closed:	02/21/20	Qty 1.00 7.00 1.00
Problem: - Remove right front strobe late - Perform pm - Rotate and late	Right fron ht headlam mp bulb wi service. balance all	nt strobe lamp in to acess and ith new.	nop and P.M. se		\$30hacp 5w20 En 1372 Oil 31-20 Wi	st Strobe Bul gine Oil Filter iper Blades	b F 20	Closed:	02/21/20	Qty 1.00 7.00 1.00 2.00
Problem: - Remove right front strobe late - Perform pm - Rotate and late	Right fron ht headlam mp bulb wi service. balance all	nt strobe lamp in to acess and ith new.	nop and P.M. se		S30hacp 5w20 En 1372 Oil 31-20 Wi	st Strobe Bul gine Oil Filter iper Blades ex Refurbe	b F 20	Closed:	02/21/20	Qty 1.00 7.00 1.00 2.00 1.00
Problem: - Remove right front strobe la - Perform pm - Rotate and	Right fron ht headlam mp bulb wi service. balance all ies	nt strobe lamp in to acess and ith new.	nop and P.M. se	ight	\$30hacp 5w20 En 1372 Oil 31-20 Wi	st Strobe Bul gine Oil Filter iper Blades ex Refurbed	b F 20		02/21/20	Qty 1.00 7.00 1.00 2.00
Problem: - Remove rightfront strobe late - Perform pmter - Rotate and leter - Shop Supplied	Right from the headlam mp bulb wing service. balance all ies	nt strobe lamp in the strobe lamp in the strobe lamp in the strong in th	nop and P.M. se	ight Labor:	S30hacp 5w20 En 1372 Oil 31-20 Wi Used Fire Shop Su 255.00	st Strobe Bulgine Oil Filter iper Blades ex Refurber pplies Parts:	b F 20 d F			Qty 1.00 7.00 1.00 2.00 1.00 1.00
Problem: - Remove right front strobe late - Perform pmthere - Rotate and late - Shop Supplied - Shop Supplied - Shop Supplied - Problem:	Right from the headlam mp bulb with service. balance all ties 1302842 Remove	nt strobe lamp in the strobe lamp in the strobe lamp in the strong in th	replace failed ri	ight Labor:	S30hacp 5w20 En 1372 Oil 31-20 Wi Used Fire Shop Su 255.00	st Strobe Bulgine Oil Filter iper Blades ex Refurber pplies Parts: In Date:	b F 20 d F 107.95	Total:	362.95	Qty 1.00 7.00 1.00 2.00 1.00 1.00
Problem: - Remove right front strobe late - Perform pm - Rotate and late - Shop Supplied - Shop Supplied - Problem: - Remove Dm	Right from the headlam mp bulb with service. balance all ies 1302842 Remove	nt strobe lamp in the strobe lamp in the strobe lamp in the strong properties and ith new. I four tires. Hours 4.25 Meter: DMI from unit a	replace failed ri	ight Labor:	\$30hacp 5w20 En 1372 Oil 31-20 Wi Used Fire Shop Sul 255.00 10169406 Parts Lis	st Strobe Bulgine Oil Filter iper Blades ex Refurber pplies Parts: In Date:	b F 20 d F 107.95	Total:	362.95	Qty 1.00 7.00 1.00 2.00 1.00 1.00
Problem: - Remove right front strobe late - Perform pmthere - Rotate and late - Shop Supplied - Shop Supplied - Shop Supplied - Problem:	Right from the headlam imp bulb with service. balance all ties 1302842 Remove to ini.secure at ties	nt strobe lamp in the strobe lamp in the strobe lamp in the strong properties and ith new. I four tires. Hours 4.25 Meter: DMI from unit a	replace failed rieplace failed	ight Labor:	S30hacp 5w20 En 1372 Oil 31-20 Wi Used Fire Shop Su 255.00	st Strobe Bulgine Oil Filter iper Blades ex Refurber pplies Parts: In Date:	b F 20 d F 107.95 03/22/2013	Total:	362.95	Qty 1.00 7.00 1.00 2.00 1.00 1.00
Problem: - Remove right front strobe late - Perform pm - Rotate and late - Shop Supplied - Shop Supplied - Remove Dm - Shop Supplied - Shop Su	Right from the headlam mp bulb will service. balance all ies 1302842 Remove Ini.secure a ies 1303042	nt strobe lamp in the strobe lamp in the strobe lamp in the strong property of the strong p	replace failed rieplace failed	Labor:	S30hacp 5w20 En 1372 Oil 31-20 Wi Used Fire Shop Su 255.00	st Strobe Bulgine Oil Filter iper Blades ex Refurber pplies Parts: In Date: st pplies	b F 20 d F 107.95 03/22/2013	Total:	362.95	Qty 1.00 7.00 1.00 2.00 1.00 1.00 013 Qty 1.00
Problem: - Remove right front strobe late - Perform pm - Rotate and late - Shop Supplied - Shop Supplied - Remove Dm - Shop Supplied - Shop Supplied - Shop Supplied - Problem: - Problem:	Right from the headlam mp bulb will service. balance all ies 1302842 Remove Ini.secure a ies 1303042 Transition	nt strobe lamp in his problem to acess and his new. I four tires. Hours 4.25 Meter: DMI from unit a his insulate wire thours 1.50 Meter: n Prep Charge	nop and P.M. se replace failed ri 80559 nd install into as e harness.	Labor:	S30hacp 5w20 En 1372 Oil 31-20 Wi Used Fire Shop Su 255.00	st Strobe Bulgine Oil Filter iper Blades ex Refurber pplies Parts: In Date: st pplies Parts:	20 d F 107.95 03/22/2013	Total:	362.95 03/28/20 92.00	Qty 1.00 7.00 1.00 2.00 1.00 1.00 013 Qty 1.00
Problem: - Remove right front strobe late - Perform pm - Rotate and late - Shop Supplied - Shop Supplied - Remove Dm - Shop Supplied - Shop Su	Right from the headlam mp bulb with service. balance all ties 1302842 Remove Ini.secure at ties 1303042 Transition Prep Charge	nt strobe lamp in his problem to acess and his new. I four tires. Hours 4.25 Meter: DMI from unit a his insulate wire thours 1.50 Meter: n Prep Charge	nop and P.M. sereplace failed riverse failed rivers	Labor:	S30hacp 5w20 En 1372 Oil 31-20 Wi Used Fire Shop Su 255.00	st Strobe Bulgine Oil Filter iper Blades ex Refurber pplies Parts: In Date: st pplies Parts:	20 d F 107.95 03/22/2013 2.00 03/28/2013	Total: Total: Closed:	362.95 03/28/20 92.00	Qty 1.00 7.00 1.00 2.00 1.00 1.00 013 Qty 1.00

Hitch Pin Lock											
Hitch Pin Lock				80792			In Date:	03/28/2013	Closed:	03/29/20	013
Hitch Pin Lock	- Parts Only					Parts L	ist				Qty
Workorder: 1303309 Meter: 80820 In Date: 04/04/2013 Closed: 04/04/2010 Problem: 1 - Wash ticket(s) issued	,					Hitch Pi	n Lock				1.00
Problem: 1 - Wash ticket(s) issued Hours 0.00		Hours	0.00		Labor:	0.00	Parts:	13.56	Total:	13.56	
Problem: 1 - Wash ticket(s) issued Hours 0.00	Workorder:	1303309	Meter:	80820			In Date:	04/04/2013	Closed:	04/04/20	013
Hours 0.00				d							
Service 1307496 Meter: 83446 In Date: 07/26/2013 Closed: 07/31/2013 Closed: 07/31	- 1 - Wash tic	ket(s) issued									
Problem: pm/ brake light out/ see notes - pm service - left brk light and turn signal inop, replace bulb		Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
- left brik light and turn signal inop, replace bulb - adjusted tool box							In Date:	07/26/2013	Closed:	07/31/20	013
- adjusted tool box	- pm service					Parts L	ist				Qty
Washer Fluid Concentr 1 Napagold Fuel Filter 1 1 Napagold Filter 1 Napago	- left brk light	and turn signal i	nop, repl	ace bulb		Napa Q	uart 5w20				7.00
Napagold Fuel Filter 1 1 1 1 1 1 1 1 1	- adjusted too	l box				Napago	ld Oil Filter				1.00
Hours 3.75 Labor: 225.00 Parts: 38.76 Total: 263.76						Washer	Fluid Conce	entr			1.00
Hours 3.75 Labor: 225.00 Parts: 38.76 Total: 263.76						Napago	ld Fuel Filte	r			1.00
Workorder: 1312398 Meter: 86346 In Date: 12/12/2013 Closed: 12/12/2013 Problem: 1 - Wash ticket(s) issued						Bulb					1.00
Problem: 1 - Wash ticket(s) issued Hours 0.00 EMOrkorder: 1400345 Problem: pm service Parts List Service rear differential Service rear differenti		Hours :	3.75		Labor:	225.00	Parts:	38.76	Total:	263.76	
Service Parts List	Problem:	1 - Wash ticket					In Date:	12/12/2013	Closed:	12/12/20	013
Problem: pm service - Pm Service - Service frt differential - Service rear differential - Service rear differential - Service rear differential - Napa Quart 5w20 - Replace I/front head lamp - Repalce 3rd brake lamp bulb - To and from dealer for Catalyst Convertor Warranty - To and from dealer fo		Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
- Service frt differential Napagold Oil Filter 1 - Service rear differential Napa Quart 5w20 7 - Replace I/front head lamp Wiper Blade 2 - Repalce 3rd brake lamp bulb 12345841 Gear Oil Syn 1 - To and from dealer for Catalyst Convertor Warranty 75w140 Gear Lube Synt 4 - Halogen Lamp 1 - Friction Modifier 1 - Ptex Ultra Grey 3oz 1 - Hours 7.75 Labor: 465.00 Parts: 175.08 Total: 640.08 - Workorder: 1404503 Meter: 89744 In Date: 04/22/2014 Closed: 05/08/2014 - Problem: damage to frt bumper			Meter:	86820			In Date:	01/10/2014	Closed:	01/27/20	014
- Service rear differential Replace l/front head lamp Wiper Blade Repalce 3rd brake lamp bulb To and from dealer for Catalyst Convertor Warranty Halogen Lamp Friction Modifier Ptex Ultra Grey 3oz Hours 7.75 Labor: 465.00 Parts: 175.08 Total: 640.08 Workorder: 1404503 Meter: 89744 Problem: damage to frt bumper Mapa Quart 5w20 7 Wiper Blade 2 7 Sw140 Gear Lube Synt Halogen Lamp Friction Modifier Ptex Ultra Grey 3oz 1 In Date: 04/22/2014 Closed: 05/08/2014	- Pm Service					Parts L	ist				Qty
Replace I/front head lamp Repalce 3rd brake lamp bulb To and from dealer for Catalyst Convertor Warranty To and from dealer for Catalyst Convertor Warranty Halogen Lamp Friction Modifier Ptex Ultra Grey 3oz Hours 7.75 Labor: 465.00 Parts: 175.08 Total: 640.08 Norkorder: 1404503 Meter: 89744 Problem: damage to frt bumper damage to frt bumper	- Service frt d	ifferential				Napago	ld Oil Filter				1.00
- Repalce 3rd brake lamp bulb - To and from dealer for Catalyst Convertor Warranty - To and from dealer for Catalyst Convertor Catalyst Convertor Warranty - To and from dealer for Catalyst Co	- Service rear	differential				Napa Q	uart 5w20				7.00
- To and from dealer for Catalyst Convertor Warranty - To and from dealer for Catalyst Convertor Warranty Halogen Lamp Friction Modifier Ptex Ultra Grey 3oz Hours 7.75 Labor: 465.00 Parts: 175.08 Total: 640.08 Workorder: 1404503 Meter: 89744 Problem: damage to frt bumper - damage to frt bumper	- Replace I/fro	ont head lamp				Wiper B	slade				2.00
Halogen Lamp Friction Modifier Ptex Ultra Grey 3oz Hours 7.75 Labor: 465.00 Parts: 175.08 Total: 640.08 Workorder: 1404503 Meter: 89744 Problem: damage to frt bumper In Date: 04/22/2014 Closed: 05/08/2014 In Date: 04/22/2014 Closed: 05/08/2014	- Repalce 3rd	brake lamp bull	0			123458	41 Gear Oil	Syn			1.00
Friction Modifier Ptex Ultra Grey 3oz Hours 7.75 Labor: 465.00 Parts: 175.08 Total: 640.08 Workorder: 1404503 Meter: 89744 Problem: damage to frt bumper - damage to frt bumper	- To and from	dealer for Catal	lyst Conv	ertor Warranty		75w140	Gear Lube	Synt			4.00
Ptex Ultra Grey 3oz						Haloger	n Lamp				1.00
Hours 7.75 Labor: 465.00 Parts: 175.08 Total: 640.08 Workorder: 1404503 Meter: 89744 In Date: 04/22/2014 Closed: 05/08/2014 Problem: damage to frt bumper - damage to frt bumper						Friction	Modifier				1.00
: Workorder: 1404503 Meter: 89744 In Date: 04/22/2014 Closed: 05/08/2014 Problem: damage to frt bumper - damage to frt bumper						Ptex Ult	ra Grey 3oz				1.00
Problem: damage to frt bumper - damage to frt bumper		Hours :	7.75		Labor:	465.00	Parts:	175.08	Total:	640.08	
				89744			In Date:	04/22/2014	Closed:	05/08/20	014
Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00	- damage to f	rt bumper									
·		Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	

Workorder: Problem:	1404892 pm/ check tires	Meter:	90199			In Date:	05/19/2014	Closed:	05/28/20	014
- Pm					Parts Li	st				Qty
- Mount and E	Balance 2 frt tire	:S			Napagol	d Oil Filter				1.00
- Wash Vehic	le				10w30 M					7.00
- Fuel Loaner	-					92 Lt265-7	0r17			2.00
						osal Fee				2.00
	Hours	5.75		Labor:	345.00		545.55	Total:	890.55	2.00
Workorder: Problem:	1407143 damage to rgt	Meter: frt fender	91640 & door			In Date:	07/08/2014	Closed:	07/21/20	014
- damage to r	gt frt fender & d	oor								
	Hours :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1407909 Nail on Tire on	Meter: the Left/F	92291 Rear			In Date:	08/11/2014	Closed:	08/20/20	014
- Replace 2 R	ear Tires Moun	t And Bala	ance Nitro Fill		Parts Li	st				Qty
					Lt265/70	r17 Tire E				2.00
					Tire Disp	osal Fee				2.00
	Hours	s 1.50		Labor:	-		643.48	Total:	733.48	
Workorder: Problem:	1500859 pm service	Meter:	96155			In Date:	01/26/2015	Closed:	01/30/20	015
- Pm					Parts Li	st				Qty
- Load test an	d check battery	r/r batter	у		Napagol	d Oil Filter				1.00
	·	•			Napa Qu	uart 5w20				7.00
					Wiper Bl					2.00
					-	d Air Filter				1.00
					Battery					1.00
	Hours	3.75		Labor:	225.00		167.06	Total:	392.06	
Workorder: Problem:	1502587 light out	Meter:	96999			In Date:	03/12/2015	Closed:	03/18/20	015
- Replace bull	o front left turn				Parts Li	st				Qty
					Signal S	top Lamp				1.00
	Hours	s 0.50		Labor:	30.00	Parts:	1.76	Total:	31.76	
	:						04/04/0045	<u> </u>	04/07/0	715
Workorder: Problem:	1504148 check for front	Meter: end shim	97906 my			In Date:	04/21/2015	Closed:	04/27/20	J13
Problem: - Remove who	check for front eel crawler to a	end shim	my	. r&r	Parts Li		04/21/2015	Closed:	04/27/20	
Problem: - Remove who moutns two in	check for front eel crawler to a front and two ir	end shim ccess fror center	my It body mounts		Parts Li	st	04/21/2015	Closed:	04/27/20	Qty
Problem: - Remove who mouths two in - Remove rea	check for front eel crawler to a front and two ir r back seat to a	end shim ccess fror center	my It body mounts		Body Mo	st	04/21/2015	Closed:	04/27/20	Qty 4.00 1.00
Problem: - Remove who moutns two in	check for front eel crawler to a front and two ir r back seat to a	end shim ccess fror center	my It body mounts		Body Mo	st ount Kit Penetrant	04/21/2015	Closed:	04/27/20	Qty 4.00

Workorder: Problem:	1505846 pm service	Meter:	98727			In Date:	06/11/2015	Closed:	06/17/2015
- Pm					Parts L	ist			Qt
- Wash Vehic	le					ld Oil Filter			1.0
774011 701110	.0				. •	Motor Oil			7.0
					Wiper B				2.0
					Brake C				1.0
					Drain Pl				1.0
	Hou	rs 3.75		Labor:	225.00	Parts:	37.43	Total:	262.43
Workorder: Problem:	1505995 1 - Wash tick	Meter: et(s) issued	98719 d			In Date:	06/16/2015	Closed:	06/16/2015
- 1 - Wash tic	` '								
	Hou :	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder:	1508661	Meter:	100947			In Date:	08/31/2015	Closed:	09/03/2015
Problem:	third light mal	function							
- Bed light inc	p replace bulb	•			Parts L	ist			Qt
					Rpl Bulk)			1.0
	Hou :	rs 0.50		Labor:	30.00	Parts:	0.80	Total:	30.80
Workorder:	1508853	Meter:	100947			In Date:	09/02/2015	Closed:	09/02/2015
Problem:	1 - Wash tick	et(s) issued	b						
- 1 - Wash tic	ket(s) issued								
	Hou :	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder:	1511635	Meter:	103098			In Date:	11/13/2015	Closed:	11/20/2015
Problem:	pm service								
- Pm					Parts L	ist			Qt
- Replace left	front turn sign	al bulb and	l left parking l	light bulb	Napa Q	uart 5w20			7.0
- Carwash					Napago	ld Oil Filter			1.0
					Brake C	leaner			1.0
					1401 B	rake Fluid B	ra		1.0
					Signal S	Stop Lamp			1.0
					Bulb				1.0
	Hou :	rs 4.75		Labor:	285.00	Parts:	40.52	Total:	325.52
Workorder:	1511714	Meter:	103098			In Date:	11/16/2015	Closed:	11/16/2015
Problem:	1 - Wash tick	et(s) issued	d						
- 1 - Wash tic	ket(s) issued								
	Hou :	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
	•								

Workorder:	1604193	Meter:	105440			In Date:	04/21/2016	Closed:	04/26/2016
Problem:	pm service								
- Pm					Parts L	ist			Qty
- Carwash					Napa Q	uart 5w20			7.00
					Napago	ld Oil Filter			1.00
					Brake C	leaner			1.00
					20" Wip	er Blade			2.00
					Napago	ld Air Filter			1.00
	Hou :	rs 3.75		Labor:	225.00	Parts:	47.94	Total:	272.94
Workorder:	1604324	Meter:	105440			In Date:	04/25/2016	Closed:	04/25/2016
Problem:	1 - Wash tick	et(s) issued	d						
- 1 - Wash tic	ket(s) issued								
	Hou :	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder:	1607848	Meter:	107069			In Date:	08/01/2016	Closed:	08/01/2016
Problem:	1 - Wash tick	et(s) issued	d						
- 1 - Wash tic		· /							
	` '	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder:	1608691	Meter:	107560			In Date:	08/22/2016	Closed:	08/24/2016
Problem:	clips missing	on tailgate	trim/ part in	truck					
- Repair back	tailgate trim								
	Hou :	rs 1.00		Labor:	60.00	Parts:	0.00	Total:	60.00
Workorder:	1610048	Meter:	108582			In Date:	09/26/2016	Closed:	09/28/2016
Problem:	pm service								
- Pm					Parts L	ist			Qty
- Wash Vehi					Wd40 1	6oz Aero Ca	an		1.00
					10w30 l	Motor Oil			7.00
					Napago	ld Oil Filter			1.00
					Non-chl	or Brake Clr	nr		1.00
					20" Wip	er Blade			2.00
	Hou	rs 3.75		Labor:	225.00	Parts:	44.60	Total:	269.60
Workorder:	1610284	Meter:	108582			In Date:	09/30/2016	Closed:	09/30/2016
Problem:	1 - Wash tick	et(s) issued	d						
- 1 - Wash tic	ket(s) issued								
	Hou	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00

Workorder:	1702442	Meter:	112043			In Date:	03/09/2017	Closed:	03/15/2017
Problem:	pm service								
- Pm					Parts Li	ist			Qty
- Replace 2 tires, balance 4					Napa Quart 5w20				7.00
					Napago	ld Oil Filter			1.00
					20" Wip	er Blade			2.00
					Non-chl	or Brake Clr	nr		1.00
					179535492 Lt265-70r17				2.00
					Tr416 V	alve Stem			2.00
				Tire Disposal Fee					2.00
	Hou	rs 4.75		Labor:	285.00	Parts:	574.54	Total:	859.54
Workorder:	1705922	Meter:	113786			In Date:	06/14/2017	Closed:	06/16/2017
Problem:	ac inop								
	on to Verify ref n, check gap. F								
	Hou	rs 1.50		Labor:	90.00	Parts:	0.00	Total:	90.00
Workorder:	1706061	Meter:	113786			In Date:	06/19/2017	Closed:	06/19/2017
Problem:	1 - Wash tick	et(s) issued	d						
- 1 - Wash tic	ket(s) issued								
	Hou	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder:	1707161	Meter:	114614			In Date:	07/21/2017	Closed:	07/27/2017
Problem:	flat tire & burr	n smell fror	n Ift rear whe	el					
- repair rr tire	check all								
•	brakes, temp.	test drive n	o problem fo	und					
,	•	rs 2.00	•		120.00	Parts:	0.00	Total:	120.00
Workorder:	1707163	Meter:	114298			In Date:	07/18/2017	Closed:	07/21/2017
Problem:	Flat tire and 1	There is als	so a burnina s	smell comi	ng from t	he driver sid	de rear tire are	ea (Shed tov	v for AM)
					g c (,
Tow From:	INN \/ \n+ / ` \ \	nound was	ot cide at trail	or #0 To.					
- Tow From: Se shop	Ipp Maint Com	pound wes	st side of trail	er#8 To:					
		pound wes	st side of trail	er#8 To: Labor:	0.00	Parts:	0.00	Total:	0.00

Workorder:	1709118	Meter:	115900			In Date:	09/21/2017	Closed:	09/29/2017
Problem:	pm/ set up fo	or no tow							
- Pm - Remove trailer plug, lock out hitch and install "no tow" message on tailgate					Parts List Napagold Oil Filter Napa Quart 5w20 20" Wiper Blade Napagold Air Filter				Qty 1.00 7.00 2.00 1.00
	Hou :	ırs 3.75		Labor:	225.00	Parts:	46.04	Total:	271.04
Workorder:	1711678	Meter:	117559			In Date:	11/29/2017	Closed:	12/08/2017
Problem:	possible sho	ck issue							
- Replace rea	erse and brak	turn signal	bulbs on bo		Parts Li Reflex T Bulb Rpl Bulb 150.00	ruck Shock	134.64	Total:	Qty 2.00 2.00 2.00 284.64
Workorder:	1800524		119062			In Date:	01/17/2018		01/22/2018
	tail light out	Meter:				in Date.	01/11/2010	Closed:	01/22/2010
en all lighte		irs 0.50		Labor:	30.00	Parts:	0.00	Total:	30.00
Workorder:	1802661	Meter:	120379			In Date:	03/12/2018	Closed:	03/16/2018
Problem:	pm/ brake lig	ht on/ turn :	signal						
- pm service	Hou	ırs 2.75		Labor:		ld Oil Filter uart 5w20	37.55	Total:	1.00 7.00 2.00 202.55
Workorder:	1804258	Meter:	121161			In Date:	04/24/2018	Closed:	04/30/2018
Problem:	runs very rou	ıgh							
- check vehicl	le, random mis	ssfires dete	cted						
	Hou	ırs 1.00		Labor:	60.00	Parts:	0.00	Total:	60.00
Workorder:	1805443	Meter:	121161			In Date:	05/29/2018	Closed:	05/29/2018
	Transition Pr	ep Charge							
- Transition P		ırs 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00