| r robietti.  | 843274<br>PRE-DELIVE  |   |   |                     |  | In Date:   | 08/25/2008   | Closed:               | 08/25/2           | 800   |
|--|---|---|---|---------------------|--|--|--|-----------------------|-------------------|---|
|  |   |   | CHON  |                     |  |  |  |                       |                   |   |
| - Pre-delivery   | •   |   |   | Labari              | 240.00   | Dorto  | 0.00   | Totali                | 040.00            |   |
|  | HOL<br>:  | urs 4.00  |   | Labor:              | 240.00   | Parts:   | 0.00   | i otai:               | 240.00            |   |
| Workorder:<br>Problem:   | 843447<br>001 KEY ISS   | Meter:<br>SUED OUT  | 0 08/28   | 3/08                |  | In Date:   | 08/28/2008   | Closed:               | 09/10/2           | 008   |
| - 001 Key Issu   | Jed Out   | 08/28/08  |   |                     | Parts Li   | st   |  |                       |                   | Qty   |
|  |   |   |   |                     | Duplicat   | e Vehicle K  | eys  |                       |                   | 1.00  |
|  | Hou<br>:  | urs 0.20  |   | Labor:              | 12.00  | Parts:   | 3.00   | Total:                | 15.00             |   |
| Workorder:<br>Problem:   | 845720<br>LOW BRAKE   | Meter:<br>E FLUID ME  | 843<br>SSAGE OI                                 | N DASH              |  | In Date:   | 10/15/2008   | Closed:               | 10/21/2           | 008   |
| - Complaint:b  |   |   |   |                     | Parts Li   | st   |  |                       |                   | Qty   |
| Springshackle<br>Caliper.flush 8   |   |   | Brk Line T                                      | o Rr                | Shop Su  | ipplies  |  |                       |                   | 1.00  |
| - Shop Suppli  |   | ys.   |   |                     | 3/16"x 4   |  | 1.00   |                       |                   |   |
|  | 00  |   |   |                     | 3/16"x 5   |  | 1.00   |                       |                   |   |
|  |   |   |   |                     |  | ake Fluid B  | rake Fluid   |                       |                   | 2.00  |
|  | Hou<br>:  | urs 2.00  |   | Labor:              | 120.00   | Parts:   | 17.49  | Total:                | 137.49            |   |
| Workorder:<br>Problem:   | 933905<br>P.M SERVIC  | Meter:<br>CE,WIRE ST  | 3574<br>ROBES TO                                | ) BATT PO           | WER  | In Date:   | 02/11/2009   | Closed:               | 03/03/2           | 009   |
| - Pm Service   |   |   |   |                     | Parts Li   | st   |  |                       |                   | Qty   |
|  |   |   |   |                     | Shop Supplies  |  |  |                       |                   | 1.00  |
| - Diag No Parking Lights.blown Fuse.pinpoint Test Locate<br>Shortwire.repl Right Center Marker Light And Repair  |   |   |   | air                 | 7312 O   |  | 1.00   |                       |                   |   |
| Harnocc Donl   |   | or Strobe Li  | ahte liahter                                    | Switch To           | Cs10263  |  | 1.00   |                       |                   |   |
| Harness. Repl  | Fabricate New Harness For Strobe Lights, lighted Switch To Allow For Uses W/ Truck Off.                                       |   |   |                     | L0135-063 Lubriplate Chain&cable<br>Lube,03050crc                        |  |  |                       |                   |   |
| - Fabricate Ne<br>Allow For Us   | es W/ Truck C   |   | <b>J</b> <sup>12</sup> , <b>J</b> <sup>12</sup> |                     |  |  | te Chain&cab   | le                    |                   | 1.00  |
| <ul> <li>Fabricate Net Allow For Us</li> <li>Nitro Service</li> </ul>  | es W/ Truck C<br>e All 6 Tires  | Off.  |   |                     |  | 050crc   | te Chain&cad   | le                    |                   | 1.00<br>15.00                               |
| <ul> <li>Fabricate Ne<br/>Allow For Us</li> <li>Nitro Service</li> <li>Service Crain</li> </ul>  | es W/ Truck C<br>e All 6 Tires<br>ne.inspect,lub  | Off.<br>be And Test   | Operation                                       |                     | Lube,03<br>15/40 C   | 050crc<br>Dil  | it 4" Rect Yell  |                       |                   |   |
| <ul> <li>Fabricate Ne<br/>Allow For Us</li> <li>Nitro Service</li> <li>Service Cran</li> <li>Transport To</li> </ul>   | es W/ Truck (<br>e All 6 Tires<br>ne.inspect,lub<br>o Dealer For F  | Off.<br>be And Test   | Operation                                       |                     | Lube,03<br>15/40 C<br>19006y   | 050crc<br>)il<br>Marker Ligh   |  | ow Led                |                   | 15.00                                       |
| <ul> <li>Fabricate Ne<br/>Allow For Us</li> <li>Nitro Service</li> <li>Service Crain</li> </ul>  | es W/ Truck (<br>e All 6 Tires<br>ne.inspect,lub<br>o Dealer For F  | Off.<br>be And Test   | Operation                                       |                     | Lube,03<br>15/40 C<br>19006y<br>84863 R                                  | 050crc<br>Dil<br>Marker Ligh<br>Locker Swite   | it 4" Rect Yell  | ow Led                |                   | 15.00<br>1.00                               |
| <ul> <li>Fabricate Ne<br/>Allow For Us</li> <li>Nitro Service</li> <li>Service Cran</li> <li>Transport To</li> </ul>   | es W/ Truck (<br>e All 6 Tires<br>ne.inspect,lub<br>o Dealer For F<br>es  | Off.<br>be And Test   | Operation                                       |                     | Lube,03<br>15/40 C<br>19006y<br>84863 R<br>80865 F                       | 050crc<br>Dil<br>Marker Ligh<br>cocker Swite<br>useholder l  | it 4" Rect Yell  | ow Led                | 810.46            | 15.00<br>1.00<br>1.00                       |
| <ul> <li>Fabricate Ne<br/>Allow For Us</li> <li>Nitro Service</li> <li>Service Cran</li> <li>Transport To</li> <li>Shop Suppli</li> </ul>  | es W/ Truck (<br>e All 6 Tires<br>ne.inspect,lub<br>o Dealer For F<br>es  | Off.<br>De And Test<br>Recalls #08<br>urs 11.00<br><b>Meter:</b>              | Operation                                       | Of Crane.           | Lube,03<br>15/40 C<br>19006y<br>84863 R<br>80865 F                       | 050crc<br>Dil<br>Marker Ligh<br>cocker Swite<br>useholder l  | ut 4" Rect Yell<br>ch (motormite)<br>mperial 80865           | ow Led                | 810.46<br>04/20/2 | 15.00<br>1.00<br>1.00<br>1.00               |
| <ul> <li>Fabricate Ne<br/>Allow For Us</li> <li>Nitro Service</li> <li>Service Cran</li> <li>Transport To</li> <li>Shop Suppli</li> </ul>  | es W/ Truck (<br>e All 6 Tires<br>ne.inspect,lub<br>o Dealer For F<br>es<br>Hou<br>:<br>934544<br>INSTALL BE                  | Off.<br>he And Test<br>Recalls #08<br>urs 11.00<br><b>Meter:</b><br>ED COVER. | Operation (<br>b06 08b07                        | Of Crane.<br>Labor: | Lube,03<br>15/40 C<br>19006y<br>84863 R<br>80865 F                       | 050crc<br>Marker Ligh<br>cocker Switc<br>useholder I<br>Parts:<br>In Date:                         | nt 4" Rect Yell<br>ch (motormite)<br>mperial 80865<br>150.46 | ow Led<br>5<br>Total: |                   | 15.00<br>1.00<br>1.00<br>1.00               |
| <ul> <li>Fabricate Ne Allow For Us</li> <li>Nitro Service</li> <li>Service Cran</li> <li>Transport To</li> <li>Shop Suppli</li> <li>Workorder:<br/>Problem:</li> <li>To/from Ray<br/>Bed Cover.</li> </ul> | es W/ Truck C<br>e All 6 Tires<br>ne.inspect,lub<br>o Dealer For F<br>es<br>Hou<br>:<br>934544<br>INSTALL BE<br>rside T&t And | Off.<br>he And Test<br>Recalls #08<br>urs 11.00<br><b>Meter:</b><br>ED COVER. | Operation (<br>b06 08b07                        | Of Crane.<br>Labor: | Lube,03<br>15/40 C<br>19006y<br>84863 R<br>80865 F<br>660.00             | 050crc<br>Dil<br>Marker Ligh<br>cocker Switc<br>useholder I<br>Parts:<br>In Date:                  | nt 4" Rect Yell<br>ch (motormite)<br>mperial 80865<br>150.46 | ow Led<br>5<br>Total: |                   | 15.00<br>1.00<br>1.00<br>1.00               |
| <ul> <li>Fabricate Ne Allow For Us</li> <li>Nitro Service</li> <li>Service Craition</li> <li>Transport To</li> <li>Shop Supplition</li> <li>Workorder:<br/>Problem:</li> <li>To/from Ray</li> </ul>        | es W/ Truck C<br>e All 6 Tires<br>ne.inspect,lub<br>o Dealer For F<br>es<br>Hou<br>:<br>934544<br>INSTALL BE<br>rside T&t And | Off.<br>he And Test<br>Recalls #08<br>urs 11.00<br><b>Meter:</b><br>ED COVER. | Operation (<br>b06 08b07                        | Of Crane.<br>Labor: | Lube,03<br>15/40 C<br>19006y<br>84863 R<br>80865 F<br>660.00<br>Parts Li | 050crc<br>Dil<br>Marker Ligh<br>Locker Switc<br>useholder I<br>Parts:<br>In Date:<br>st<br>upplies | nt 4" Rect Yell<br>ch (motormite)<br>mperial 80865<br>150.46 | ow Led<br>5<br>Total: |                   | 15.00<br>1.00<br>1.00<br>1.00<br>009<br>Qty |

| Workorder:<br>Problem:   | 942157<br>P.M service  | Meter:<br>e, check cran         | 8242<br>e wiring, de | tail.      |   | In Date:  | 08/17/2009   | Closed:                        | 09/21/2009  |
|--|--|---------------------------------|----------------------|------------|---|---|--|--------------------------------|---|
| - P.m service  |  |                                 |                      |            | Parts Li  | st  |  |                                | Qt  |
| - Service & in   | spect electric   | c crane, repla                  | ace damage           | ed/cracked | Shop Su   | upplies   |  |                                | 1.00  |
| electric motor.  | •  | •                               | Ū                    |            | ,<br>7312 O   | il Filterfrm C  | Ch9549 Wix 5   | 7312                           | 1.00  |
| - Rotate & ba  | lance all six t  | tires.                          |                      |            | Cs1026  | 3 Fuel Filter   | (use Cs1026  | 3a)                            | 1.00  |
| - Shop Suppl   | ies  |                                 |                      |            | Ca1027  | 0 Air Filter N  | Mtc Fa1886 W   | ix 49886                       | 1.00  |
|  |  |                                 |                      |            | 15/40 C   | Dil   |  |                                | 15.00   |
|  |  |                                 |                      |            | Used Fi   | rex Refurbe   | d Fire Extings   | hers                           | 1.00  |
|  |  |                                 |                      |            | 31-20 W   | /iper Blades  | 20" Blade  |                                | 2.00  |
|  |  |                                 |                      |            | Crane M   | lotor   |  |                                | 1.00  |
|  | Hc<br>:  | ours 8.50                       |                      | Labor:     | 510.00  | Parts:  | 938.49   | Total:                         | 1,448.49  |
| Workorder:<br>Problem:   | 944188<br>1 - Detail Ve  | Meter:<br>ehicle Wash           | 8242<br>Ticket(s) Is | sued       |   | In Date:  | 10/05/2009   | Closed:                        | 10/05/2009  |
| - 1 - Detail Ve  | ehicle Wash  | Ticket(s) Issu                  | ied                  |            |   |   |  |                                |   |
|  | Hc<br>:  | ours 0.00                       |                      | Labor:     | 0.00  | Parts:  | 0.00   | Total:                         | 0.00  |
| Workorder:<br>Problem:   | 944493<br>damage to  | Meter:<br>rear bumper           | 8242                 |            |   | In Date:  | 09/21/2009   | Closed:                        | 10/21/2009  |
| - damage to r  | rear bumper  |                                 |                      |            |   |   |  |                                |   |
|  | Ho   | ours 0.00                       |                      | Labor:     | 0.00  | Parts:  | 0.00   | Total:                         | 0.00  |
| Workorder:<br>Problem:   | 1001560<br>Nail in R/R   | Meter:<br>outer tire.           | 11746                |            |   | In Date:  | 02/11/2010   | Closed:                        | 02/11/2010  |
| - Repair R/r o   | outer tire.  |                                 |                      |            | Parts Li  | st  |  |                                | Qt  |
| - Shop Suppl   |  |                                 |                      |            | Shop Su   | upplies   |  |                                | 1.00  |
|  |  | ours 1.00                       |                      | Labor:     |   | Parts:  | 2.00   | Total:                         | 62.00   |
|  |  |                                 |                      |            |   |   |  |                                |   |
|  | 1003095<br>PM service  | Meter:<br>also see not          | 13560<br>es on tires |            |   | In Date:  | 03/26/2010   | Closed:                        | 04/06/2010  |
|  | PM service   |                                 |                      |            | Parts Li  |   | 03/26/2010   | Closed:                        | 04/06/2010<br>Qt                                    |
| Problem:   | PM service   | also see not                    | es on tires          |            | Parts Li<br>Shop Su   | st  | 03/26/2010   | Closed:                        |   |
| Problem:<br>- P.m service<br>- Mount, bala<br>- Fabricate ne   | PM service<br>.nce & nitro fil<br>ew grounds fo                  | also see not<br>Il six new tire | es on tires<br>s.    | tag lamp   | Shop Su<br>8c3z9a3  | <b>st</b><br>upplies<br>343a Seal ł   | Kit Fuel Filter  | (ford)                         | <b>Qt</b><br>1.00<br>1.00                           |
| Problem:<br>- P.m service<br>- Mount, bala<br>- Fabricate ne<br>on utility body  | PM service<br>.nce & nitro fil<br>ew grounds fo                  | also see not<br>Il six new tire | es on tires<br>s.    | tag lamp   | Shop Su<br>8c3z9a3<br>7312 O  | <b>st</b><br>upplies<br>343a Seal F<br>il Filterfrm C                                       | Kit Fuel Filter<br>Ch9549 Wix 5                                  | (ford)<br>7312                 | <b>Qt</b><br>1.00<br>1.00                           |
| Problem:<br>- P.m service<br>- Mount, bala<br>- Fabricate ne<br>on utility body<br>- Alignment.  | PM service<br>.nce & nitro fil<br>ew grounds fo                  | also see not<br>Il six new tire | es on tires<br>s.    | tag lamp   | Shop Su<br>8c3z9a3<br>7312 O<br>Cs1026                                  | <b>st</b><br>upplies<br>343a Seal F<br>il Filterfrm (<br>3 Fuel Filter                      | Kit Fuel Filter  | (ford)<br>7312                 | <b>Qt</b><br>1.00<br>1.00                           |
| Problem:<br>- P.m service<br>- Mount, bala<br>- Fabricate ne<br>on utility body<br>- Alignment.<br>- Inspect & se                            | PM service<br>.nce & nitro fil<br>ew grounds fo<br>ervice crane. | also see not<br>Il six new tire | es on tires<br>s.    | tag lamp   | Shop Su<br>8c3z9a3<br>7312 O  | <b>st</b><br>upplies<br>343a Seal F<br>il Filterfrm (<br>3 Fuel Filter                      | Kit Fuel Filter<br>Ch9549 Wix 5                                  | (ford)<br>7312                 | <b>Qt</b><br>1.00<br>1.00                           |
| Problem:<br>- P.m service<br>- Mount, bala<br>- Fabricate ne<br>on utility body<br>- Alignment.  | PM service<br>.nce & nitro fil<br>ew grounds fo<br>ervice crane. | also see not<br>Il six new tire | es on tires<br>s.    | tag lamp   | Shop Su<br>8c3z9a3<br>7312 O<br>Cs1026<br>15/40 O                       | <b>st</b><br>upplies<br>343a Seal H<br>il Filterfrm (<br>3 Fuel Filter<br>Dil               | Kit Fuel Filter<br>Ch9549 Wix 5                                  | (ford)<br>7312<br>3a )         | <b>Qt</b><br>1.00<br>1.00<br>1.00                   |
| <ul> <li>P.m service</li> <li>Mount, bala</li> <li>Fabricate ne<br/>on utility body</li> <li>Alignment.</li> <li>Inspect &amp; se</li> </ul> | PM service<br>.nce & nitro fil<br>ew grounds fo<br>ervice crane. | also see not<br>Il six new tire | es on tires<br>s.    | tag lamp   | Shop Su<br>8c3z9a3<br>7312 O<br>Cs1026<br>15/40 O<br>Used Fi            | <b>st</b><br>upplies<br>343a Seal ł<br>3 Fuel Filter<br>3 Fuel Filter<br>Dil<br>rex Refurbe | Kit Fuel Filter<br>Ch9549 Wix 5<br>(use Cs1026                   | (ford)<br>7312<br>3a )<br>hers | <b>Qt</b><br>1.00<br>1.00<br>1.00<br>1.00<br>15.00  |
| Problem:<br>- P.m service<br>- Mount, bala<br>- Fabricate ne<br>on utility body<br>- Alignment.<br>- Inspect & se                            | PM service<br>.nce & nitro fil<br>ew grounds fo<br>ervice crane. | also see not<br>Il six new tire | es on tires<br>s.    | tag lamp   | Shop Su<br>8c3z9a3<br>7312 O<br>Cs1026<br>15/40 C<br>Used Fi<br>1796364 | <b>st</b><br>upplies<br>343a Seal ł<br>3 Fuel Filter<br>3 Fuel Filter<br>Dil<br>rex Refurbe | Kit Fuel Filter<br>Ch9549 Wix 5<br>(use Cs1026<br>d Fire Extings | (ford)<br>7312<br>3a )<br>hers | Qt<br>1.00<br>1.00<br>1.00<br>1.00<br>15.00<br>1.00 |

| Workorder: 1010550 Meter: 18073  | c and tim |                     | In Date:    | 09/24/2010                                | Closed:    | 10/20/2010       |
|--|-----------|---------------------|-------------|---|------------|------------------|
| <b>Problem:</b> pm service, also see notes on filler neck  | k and tir | e.                  |             |   |            |                  |
| - Perform pm service.  |           | Parts Lis           | st          |   |            | Qty              |
| <ul> <li>Inspect and service eleciric crane.</li> </ul>  |           | Shop Sup            | oplies      |   |            | 1.00             |
| - Repair two flat tires.rotate and balance all six.  |           | 7312 Oil            | Filterfrm C | Ch9549 Wix 5                              | 7312       | 1.00             |
| - Fabricate and secure rear fuel filler neck and hoses a<br>from leaf spring shackle.  | away      |                     |             | <sup>.</sup> (use Cs1026<br>/Itc Fa1886 W |            | 1.00<br>1.00     |
| <ul> <li>Diagnose short circuit and repair wiring in utility box u<br/>crane to correct clearance lights concern.</li> </ul> | under     |                     | rake Clear  |   | 17 40000   | 1.00             |
| - Transport vehicle to and from dealer for replacing ca  | rpet      | 15/40 Oi            | I           |   |            | 15.00            |
| under factory warranty.remove and install fire entinguis<br>and bracket to enable new carpet installiation.                  |           |                     |             | ະ 20" Blade<br>ats (rubber Qເ             | ueen)      | 2.00<br>1.00     |
| - Shop Supplies  |           |                     |             |   |            |                  |
| Hours 12.00  | Labor:    | 720.00              | Parts:      | 193.58                                    | Total:     | 913.58           |
| Workorder: 1103089 Meter: 21124  |           |                     | In Date:    | 03/22/2011                                | Closed:    | 03/29/2011       |
| <b>Problem:</b> P.M. service and crane stops working a   | nd spar   | ks at time          | S.          |   |            |                  |
| - Perform pm service.  |           | Parts Lis           | st          |   |            | Qty              |
| - Install one new tire.nitrogen fill.rotate and balance all  | l six.    | Shop Sup            | oplies      |   |            | 1.00             |
| - Inspect and perform electric crane service.secure gro  | ound      | 7312 Oil            | Filterfrm C | Ch9549 Wix 5                              | 7312       | 1.00             |
| cable.   |           | Cs10263             | Fuel Filter | (use Cs1026                               | 3a)        | 1.00             |
| - Shop Supplies  |           | 15/40 Oi            | I           |   |            | 15.00            |
|  |           | Used Fire           | ex Refurbe  | d Fire Extings                            | hers       | 1.00             |
|  |           | 31-20 Wi            | per Blades  | 20" Blade                                 |            | 2.00             |
|  |           | 17963649            | 92 Lt245/7  | 5r17 Wranglei                             | r Sr-a E   | 1.00             |
|  |           | Tire Disp           | osal Fee    |   |            | 1.00             |
|  |           | Tr416 Va            | lve Stem    |   |            | 1.00             |
| Hours 7.50<br>:  | Labor:    | 450.00              | Parts:      | 300.17                                    | Total:     | 750.17           |
| Workorder: 1109055 Meter: 27216<br>Problem: Pm service.  |           |                     | In Date:    | 08/26/2011                                | Closed:    | 09/07/2011       |
| - Perform pm service.  |           | Parts Lis           | st          |   |            | Qty              |
| - Test starting and charging system both batteries faile   |           | Shop Sup            | oplies      |   |            | 1.00             |
| loadtest after recharge.replace both failed batteries with   |           | 7312 Oil            | Filterfrm C | Ch9549 Wix 5                              | 7312       | 1.00             |
| - Install two new tires to the front wheels.repair flat left tire.nitrogen fill and balance all six.                         | rear      | 3963 Fu<br>15/40 Oi | Wix 33963   | 1.00<br>15.00                             |            |                  |
| - Diagnose for water leak.remove and reseal third brak   | ke        |                     |             | 20" Blada                                 |            | 2.00             |
| lamp.  |           |                     |             | 20" Blade                                 | n)         | 2.00             |
| - Inspect and perform electric crane service.  |           |                     | ar Silicone | ntc Bxt-65-850                            | <i>י</i> ) | 2.00             |
| - Shop Supplies  |           |                     |             | 5r17 \N/ranala                            |            | 2.00             |
|  |           |                     |             | 5r17 Wranglei                             | 31-a E     | 2.00             |
| Hours 10.75  | Labor:    | Tire Disp<br>645.00 |             | 737.87                                    | Total:     | 2.00<br>1,382.87 |
| :  |           |                     |             |   |            |                  |

| Problem:  | 1200697<br>Pm service a   | Meter:<br>and request            | 29193<br>for detail veh | nicle. |   | In Date:  | 01/23/2012  | Closed:                                     | 02/03/2012  |
|---|---|----------------------------------|-------------------------|--------|---|---|---|---|---|
| - P.m. Service  |   | ·                                |                         |        | Parts Li  | st  |   |   | Qty   |
|   | rear tail lamp  |                                  |                         |        | Shop St   |   |   |   | 1.00  |
| <ul> <li>Replace three tires,roatate and balnce all six.</li> <li>Complete front end alignment.test drive.</li> <li>Inspect and service crane.</li> </ul> |   |                                  |                         |        | •   |   | Ch9549 Wix 5  | 7312  | 1.00  |
|   |   |                                  |                         |        | Wix 33963   | 1.00  |   |   |   |
|   |   |                                  |                         |        | 15/40 C   |   |   |   | 15.00   |
| - Shop Suppli   |   |                                  |                         |        | 31-20 W   | /iper Blades  | 20" Blade   |   | 2.00  |
|   |   |                                  |                         |        | 44202r <sup>-</sup>   | Tail Light 4"   | Red 42 Led  |   | 1.00  |
|   |   |                                  |                         |        |   | •   | 5r17 Wrangle  | r Sr-a E                                    | 3.00  |
|   |   |                                  |                         |        | Tire Dis  | posal Fee   | -   |   | 3.00  |
|   | Hou   | urs 11.00                        |                         | Labor: | 660.00  | Parts:  | 718.84  | Total:                                      | 1,378.84  |
| Workorder:<br>Problem:  | 1201168<br>1 - Detail Ve  | Meter:<br>hicle Wash             | 29034<br>Ticket(s) Issu | ued    |   | In Date:  | 02/03/2012  | Closed:                                     | 02/03/2012  |
| - 1 - Detail Ve   | ehicle Wash T   | icket(s) Issu                    | ied                     |        |   |   |   |   |   |
|   | Hou   | urs 0.00                         |                         | Labor: | 0.00  | Parts:  | 0.00  | Total:                                      | 0.00  |
| Workorder:<br>Problem:  | 1207193<br>Pm service a   | Meter:<br>and request            | 34042<br>for detail veh | nicle. |   | In Date:  | 08/01/2012  | Closed:                                     | 08/17/2012  |
| - P.m. Service  | э.  |                                  |                         |        | Parts Li  | st  |   |   | Qty   |
| - Inspect and   | - Inspect and service crane.                                    |                                  |                         |        |   |   |   |   |   |
| - Rotate and balance all tires.   |   |                                  |                         |        | Shop Su   | upplies   |   |   | 1.00  |
| - Rotate and I  |   |                                  |                         |        | -   |   | iesel Fuel (m/  | craft)                                      | 1.00<br>1.00  |
| - Rotate and I<br>- Shop Suppli   | balance all tire  |                                  |                         |        | Pm-22-a   | a Additive D  | iesel Fuel (m/<br>Ch9549 Wix 5  | ,   |   |
|   | balance all tire  |                                  |                         |        | Pm-22-a<br>7312 O   | a Additive D<br>il Filterfrm C  |   | 7312  | 1.00  |
|   | balance all tire  |                                  |                         |        | Pm-22-a<br>7312 O<br>3963 Fi<br>15/40 O   | a Additive D<br>il Filterfrm C<br>uel Filter Fr<br>Dil  | Ch9549 Wix 5<br>m Cs10263a  | 7312<br>Wix 33963                           | 1.00<br>1.00  |
|   | balance all tire  |                                  |                         |        | Pm-22-a<br>7312 O<br>3963 Fi<br>15/40 O   | a Additive D<br>il Filterfrm C<br>uel Filter Fr<br>Dil  | Ch9549 Wix 5  | 7312<br>Wix 33963                           | 1.00<br>1.00<br>1.00<br>15.00<br>1.00                           |
|   | balance all tire  |                                  |                         |        | Pm-22-a<br>7312 O<br>3963 Fu<br>15/40 C<br>Wd40 S<br>1066 W                       | a Additive D<br>il Filterfrm C<br>uel Filter Fr<br>Dil<br>pray Lube S<br>/hite Lithium  | Ch9549 Wix 5<br>m Cs10263a<br>Stock# 405540<br>n (crc 05037)  | 7312<br>Wix 33963<br>0002                   | 1.00<br>1.00<br>1.00<br>15.00<br>1.00<br>1.00                   |
|   | balance all tire  |                                  |                         |        | Pm-22-a<br>7312 O<br>3963 Fr<br>15/40 O<br>Wd40 S<br>1066 W<br>Used Fi            | a Additive D<br>il Filterfrm C<br>uel Filter Fr<br>Dil<br>pray Lube S<br>/hite Lithium<br>rex Refurbe                           | Ch9549 Wix 5<br>m Cs10263a<br>Stock# 405540<br>n (crc 05037)<br>d Fire Extings                      | 7312<br>Wix 33963<br>0002                   | 1.00<br>1.00<br>1.00<br>15.00<br>1.00<br>1.00<br>1.00           |
|   | balance all tire  | es.                              |                         |        | Pm-22-a<br>7312 O<br>3963 Fr<br>15/40 C<br>Wd40 S<br>1066 W<br>Used Fi<br>31-20 W | a Additive D<br>il Filterfrm C<br>uel Filter Fr<br>Dil<br>pray Lube S<br>/hite Lithium<br>rex Refurbe<br>/iper Blades           | Ch9549 Wix 5<br>m Cs10263a<br>Stock# 405540<br>n (crc 05037)<br>d Fire Extings<br>s 20" Blade       | 7312<br>Wix 33963<br>0002<br>hers           | 1.00<br>1.00<br>15.00<br>1.00<br>1.00<br>1.00<br>2.00           |
|   | balance all tire  |                                  |                         | Labor: | Pm-22-a<br>7312 O<br>3963 Fr<br>15/40 O<br>Wd40 S<br>1066 W<br>Used Fi            | a Additive D<br>il Filterfrm C<br>uel Filter Fr<br>Dil<br>pray Lube S<br>/hite Lithium<br>rex Refurbe<br>/iper Blades           | Ch9549 Wix 5<br>m Cs10263a<br>Stock# 405540<br>n (crc 05037)<br>d Fire Extings                      | 7312<br>Wix 33963<br>0002<br>hers           | 1.00<br>1.00<br>1.00<br>15.00<br>1.00<br>1.00<br>1.00           |
| - Shop Suppli   | balance all tire  | es.<br>urs 6.50<br>Meter:        | 33869<br>Ticket(s) Issi |        | Pm-22-a<br>7312 O<br>3963 Fr<br>15/40 C<br>Wd40 S<br>1066 W<br>Used Fi<br>31-20 W | a Additive D<br>il Filterfrm C<br>uel Filter Fr<br>Dil<br>pray Lube S<br>/hite Lithium<br>rex Refurbe<br>/iper Blades           | Ch9549 Wix 5<br>m Cs10263a<br>Stock# 405540<br>n (crc 05037)<br>d Fire Extings<br>s 20" Blade       | 7312<br>Wix 33963<br>0002<br>hers           | 1.00<br>1.00<br>15.00<br>1.00<br>1.00<br>1.00<br>2.00           |
| - Shop Suppli   | balance all tire<br>ies<br>Hou<br>:<br>1207611<br>1 - Detail Ve | urs 6.50<br>Meter:<br>hicle Wash | Ticket(s) Iss           |        | Pm-22-a<br>7312 O<br>3963 Fr<br>15/40 C<br>Wd40 S<br>1066 W<br>Used Fi<br>31-20 W | a Additive D<br>il Filterfrm C<br>uel Filter Fr<br>Dil<br>pray Lube S<br>/hite Lithium<br>rex Refurbe<br>/iper Blades<br>Parts: | Ch9549 Wix 5<br>m Cs10263a<br>Stock# 405540<br>(crc 05037)<br>d Fire Extings<br>20" Blade<br>141.84 | 7312<br>Wix 33963<br>0002<br>hers<br>Total: | 1.00<br>1.00<br>15.00<br>1.00<br>1.00<br>1.00<br>2.00<br>531.84 |

|   | 1301144<br>P.M. service.              | Meter:       | 36565          |            | In [   | Date:   | 01/31/2013              | Closed:  | 02/20/2013  |
|---|---------------------------------------|--------------|----------------|------------|--|---|-------------------------|----------|---|
| - P.m. Service  | ).                                    |              |                |            | Parts List   |   |                         |          | Q   |
| - Pressure tes  | and inspect co                        | ooling syste | em.replace le  | eaking     | 15-40 Oil  |   |                         |          | 15.0  |
| upper and lower radiator hoses.flush and refill cooling system. |                                       |              |                |            | Oil Filter   |   |                         |          | 1.0   |
|   |                                       |              |                |            | Napagold Fu  | uel Filte   | r                       |          | 1.0   |
|   | rear tire,rotate a                    | and balance  | e all six.     |            | Air Filter   |   |                         |          | 1.0   |
| - Inspect and service crane.                                    |                                       |              |                |            | Radiator Hos   | se  |                         |          | 1.0   |
| - Shop Supplie  | es                                    |              |                |            | Radiator Hos   | se  |                         |          | 1.(   |
|   |                                       |              |                |            | lower hose   |   |                         |          | 1.(   |
|   |                                       |              |                |            | Vc7b Coolan  | nt Moto   | rcra                    |          | 2.0   |
|   |                                       |              |                |            | Shop Supplie   | es  |                         |          | 1.(   |
|   | Hours                                 | s 11.00      |                | Labor:     | 660.00   | Parts:  | 401.30                  | Total:   | 1,061.30  |
| Workorder:  | . 1307880                             |              | 41344          |            |  | Date:   | 08/07/2013              | Closed:  | 09/09/2013  |
| Problem:  | Pm service and                        | d rear brake | e noisy witho  | out brakin | g.   |   |                         |          |   |
| - Perform pm  |                                       |              |                |            | Parts List   |   |                         |          | Q   |
|   | r noise in rear.ir                    |              |                |            | Bearing Cup  |   |                         |          | 1.  |
| rear rear whee<br>gear lube.                                    | el bearings and                       | seals with r | new and top    | off with   | Bearing Con  | e R   |                         |          | 1.  |
| 5   | replace failed w                      | vindshield w | asher nozzl    | es with    | Bearing Con  | е   |                         |          | 1.  |
| new and adjus   |                                       |              |                |            | Bearing Cup  |   |                         |          | 1.  |
| - Install two ne  | ew tires to the fr                    | ront wheels  | .nitrogen fill | and        | Seal   |   |                         |          | 1.  |
| balance all six.  |                                       |              |                |            | Axle Gasket  |   |                         |          | 1.  |
|   | ear brake pads                        |              |                |            | Rear Axle No   | 1.  |                         |          |   |
|   | calipers and flue<br>om with scan too |              |                |            | 15-40 Oil  |   |                         |          | 15.   |
|   | el alignment co                       |              |                |            | Napagold Oi  | 1.  |                         |          |   |
|   | service electric                      |              |                |            | Napagold Fu  | 1.  |                         |          |   |
|   |                                       |              |                |            | Used Fire X  | Refurb  | ished                   |          | 1.  |
| - Shop Supplie  | 50                                    |              |                |            | 31-20 Wiper  | Blades  | 20                      |          | 2.  |
| - Shop Supplie  |                                       |              |                |            |  |   |                         |          | 1.  |
| - Shop Suppli   |                                       |              |                |            | Pm-22-a Add  | ditive D  | les                     |          |   |
| - Shop Supplie  |                                       |              |                |            | Pm-22-a Add<br>179636492 L   |   |                         |          | 2.  |
| - Shop Suppli   |                                       |              |                |            |  | _t245-7   |                         |          |   |
| - Shop Suppli   |                                       |              |                |            | 179636492 L  | _t245-7   |                         |          | 2.  |
| - Shop Suppli   |                                       |              |                |            | 179636492 L<br>Washer Noz<br>Rear Pads   | _t245-7<br>zle  |                         | nt Wheel | 2.0<br>1.0  |
| - Shop Suppli   |                                       |              |                |            | 179636492 L<br>Washer Noz<br>Rear Pads   | _t245-7<br>zle<br>ng Con  | 5r17                    | nt Wheel | 2.0<br>1.0<br>1.0   |
| - Shop Suppli   |                                       |              |                |            | 179636492 L<br>Washer Noz<br>Rear Pads<br>Wheel Bearin   | _t245-7<br>zle<br>ng Con<br>g Cup                                     | 5r17<br>e - Inner - Fro | nt Wheel | 2.0<br>1.0<br>1.0<br>1.0  |
| - Shop Suppli   |                                       |              |                |            | 179636492 L<br>Washer Noz<br>Rear Pads<br>Wheel Bearin<br>Napa Bearin  | _t245-7<br>zle<br>ng Con<br>g Cup<br>g Cone                           | 5r17<br>e - Inner - Fro | nt Wheel | 2.0<br>1.0<br>1.0<br>1.0<br>1.0   |
| - Shop Suppli   |                                       |              |                |            | 179636492 L<br>Washer Noz<br>Rear Pads<br>Wheel Bearin<br>Napa Bearin<br>Napa Bearin   | _t245-7<br>zle<br>ng Con<br>g Cup<br>g Cone<br>g Cup                  | 5r17<br>e - Inner - Fro | nt Wheel | 2.<br>1.<br>1.<br>1.<br>1.<br>1.  |
| - Shop Suppli   |                                       |              |                |            | 179636492 L<br>Washer Noz<br>Rear Pads<br>Wheel Bearin<br>Napa Bearin<br>Napa Bearin<br>Napa Bearin                                | _t245-7<br>zle<br>ng Con<br>g Cup<br>g Cone<br>g Cup                  | 5r17<br>e - Inner - Fro | nt Wheel | 2.0<br>1.0<br>1.0<br>1.0<br>1.0<br>1.0<br>1.0                             |
| - Shop Suppli   |                                       |              |                |            | 179636492 L<br>Washer Noz<br>Rear Pads<br>Wheel Bearin<br>Napa Bearin<br>Napa Bearin<br>Napa Bearin<br>Wheel Seal -                | _t245-7<br>zle<br>ng Con<br>g Cup<br>g Cone<br>g Cup<br>- Front       | 5r17<br>e - Inner - Fro | nt Wheel | 2.0<br>2.0<br>1.0<br>1.0<br>1.0<br>1.0<br>1.0<br>1.0<br>1.0<br>1.0<br>1.0 |
| - Shop Suppli   |                                       |              |                |            | 179636492 L<br>Washer Noz<br>Rear Pads<br>Wheel Bearin<br>Napa Bearin<br>Napa Bearin<br>Napa Bearin<br>Wheel Seal -<br>Spindle Nut | _t245-7<br>zle<br>ng Con<br>g Cup<br>g Cone<br>g Cup<br>- Front<br>es | 5r17<br>e - Inner - Fro | nt Wheel | 2.0<br>1.0<br>1.0<br>1.0<br>1.0<br>1.0<br>1.0<br>1.0                      |

| Workorder: 140  | 1157                | Meter:             | 43957                   |            |                    | In Date:     | 02/04/2014         | Closed: | 02/25/2014       |
|---|---------------------|--------------------|-------------------------|------------|--------------------|--------------|--------------------|---------|------------------|
| Problem: P.M  | . service an        | d switch           | for strobe bro          | ken and    | check crar         | ne wiring a  | nd request de      | tail.   |                  |
| - P.m. Service.   |                     |                    |                         |            | Parts Lis          | st           |                    |         | Qty              |
| - Replace four tires  | ,rotate and         | balance            | all six.                |            | 15-40 Oi           | I            |                    |         | 15.00            |
| <ul> <li>Test batteries and charging system.replace both bad batteries.</li> <li>Replace strobe light switch.replace right brake lamp and missing pintle pin.repair side side utility box door lock .</li> <li>Inspect and service crane</li> </ul> |                     |                    |                         | ad         | Napagolo           |              | 1.00               |         |                  |
|   |                     |                    |                         |            | Fuel Filte         | r Ford Onl   | у                  |         | 1.00             |
|   |                     |                    |                         |            | Wiper Bla          | ade          |                    |         | 2.00<br>4.00     |
|   |                     |                    |                         | · ·        | 17963649           | 92 Lt245-7   | 5r17               |         |                  |
| <ul> <li>Inspect and service crane.</li> <li>Complete wheel alignment.test drive.</li> </ul>  |                     |                    |                         |            | Tr416 Va           | lve Stem     |                    |         | 4.00             |
| - Shop Supplies   | angriment.te        | st unve.           |                         |            | Battery 6          | 5            |                    |         | 2.00             |
| - Shop Supplies   |                     |                    |                         |            | Led Sup            | Mdl 44 42    | Dio                |         | 1.00             |
|   |                     |                    |                         |            | Universa           | Switch       |                    |         | 1.00             |
|   |                     |                    |                         |            | Pintle Pir         | W/chain      |                    |         | 1.00             |
|   |                     |                    |                         |            | Switch             |              |                    |         | 1.00             |
|   |                     |                    |                         |            | Shop Sup           | oplies       |                    |         | 1.00             |
|   |                     |                    |                         |            | Tire Disp          | osal Fee     |                    |         | 4.00             |
|   | Hours               | 14.50              |                         | Labor:     | 870.00             | Parts:       | 1,501.23           | Total:  | 2,371.23         |
| Workorder: 140  | :<br>1507           | Meter:             | 43773                   |            |                    | In Date:     | 02/14/2014         | Closed: | 02/14/2014       |
| - 1 - Detail Vehicle  | Wash Ticke<br>Hours | . ,                | led                     | Labor:     | 0.00               | Parts:       | 0.00               | Total:  | 0.00             |
| Workorder: 140 <sup>°</sup><br>Problem: Pm  |                     | Meter:<br>eck over | 49841<br>for noise wher | n put in d |                    | In Date:     | 08/12/2014<br>aps. | Closed: | 09/08/2014       |
| - Pm service.   |                     |                    |                         |            | Parts Lis          |              |                    |         | Qty              |
| - Right rear axle se  | al leaking r        | enlace ri          | aht rear ayle s         | seal       | left door o        |              | 1.00               |         |                  |
| - Inspect and servi   | -                   | •                  | -                       |            | 15-40 Oi           | •            |                    |         | 15.00            |
| - Remove driver do  |                     |                    |                         | •          |                    | I Oil Filter |                    |         | 1.00             |
| - Rotate and balan  |                     | •                  |                         | op.        |                    | r Ford Onl   | V                  |         | 1.00             |
| - Shop Supplies   |                     |                    |                         |            | Mac Wite           |              | 1.00               |         |                  |
|   |                     |                    |                         |            |                    | X Refurb     |                    |         | 1.00             |
|   |                     |                    |                         |            | Wiper Bla          |              |                    |         | 2.00             |
|   |                     |                    |                         |            | Napa Oil           |              |                    |         | 1.00             |
|   |                     |                    |                         |            | -                  | able Fabric  | ation              |         | 1.00             |
|   |                     |                    |                         |            |                    |              |                    |         | 3.00             |
|   |                     |                    |                         |            | Crane St           | rap          |                    |         |                  |
|   |                     |                    |                         |            | Crane St           | •            |                    |         |                  |
|   | Hours               | 10.50              |                         | Labor:     | Shop Sup<br>630.00 | oplies       | 470.14             | Total:  | 1.00<br>1,100.14 |

| Workorder: 1501461 Meter: 52292  | In Date: 02/09/2015 Closed: 02/19/2015       |
|--|--|
| Problem: Pm service.Cleaning exhaust filter message on                                       | dash.  |
| - Pm service.  | Parts List Qty                               |
| - Replace front brake pads and both front brake  | 15-40 Oil 15.00                              |
| calipers.resurface both front brake rotors.flush and bleed brake system.                     | Napagold Oil Filter 1.00                     |
| - Inspect and service crane.   | Fuel Filter Ford Only1.00                    |
| - Rotate and balance all six tires.  | Wiper Blade2.00                              |
| - Shop Supplies  | Seal Kit 1.00                                |
|  | Reman Brake Caliper 1.00                     |
|  | Reman Brake Caliper 1.00                     |
|  | 1401 Brake Fluid Bra2.00                     |
|  | Brake Cleaner 1.00                           |
|  | Napagold Air Filter 1.00                     |
|  | Brake Pads 1.00                              |
|  | Shop Supplies 1.00                           |
| Hours 11.50 Labor:   | 690.00 Parts: 479.32 Total: 1,169.32         |
| Workorder: 1501913 Meter: 52861<br>Problem: Pulls to left when braking.Check steering and u  | In Date: 02/23/2015 Closed: 03/16/2015       |
| Froment. Fulls to left when braking. Check steering and u                                    |  |
| - Diagnose and replace defective left front brake caliper with                               | Parts List Qty                               |
| warranty part and bleed the brake system.  | Led Sup MdI 44 42 Dio 1.00                   |
| - Test and replace defective Left Led brake lamp.  | Reman Brake Caliper 1.00                     |
| - Shop Supplies  | Shop Supplies 1.00                           |
| Hours 2.00 Labor:  | 120.00 Parts: 130.55 Total: 250.55           |
| Workorder: 1508224 Meter: 56581  | In Date: 08/17/2015 Closed: 08/31/2015       |
| Problem: Pm service.Right side mirror loose.Front end vi                                     | prates at 65 MPH.                            |
| - Pm service.  | Parts List Qty                               |
| - Inspect and replace both left and right side worn upper and                                | 15-40 Oil 15.00                              |
| lower ball joints.   | Napagold Oil Filter 1.00                     |
| - Replace two front and four rear defective body mounts.replace both broken rear bump stops. | Fuel Filter Ford Only 1.00                   |
| - Inspect and service transmission.replace filter.flush and                                  | Wiper Blade2.00                              |
| refill fluid.  | Used Fire X Refurbished 1.00                 |
| - Replace two tires.rotate and balance all six.  | Upper Ball Joint 2.00                        |
| - Inspect and service crane.replace missing safety pin.                                      | Body Mount Kit 2.00                          |
| - Complete front end alignment.  | Body Mount Kit 4.00                          |
| - Shop Supplies  | Syn-atf Trans Fluid S 24.00                  |
|  | Platinum Filter Kit 1.00                     |
|  | 179636492 Lt245-75r17 2.00                   |
|  | Lower Ball Joint 2.00                        |
|  | Bumper 2.00                                  |
|  | Hitch Pin 1.00                               |
|  | Atp Filter 1.00                              |
|  | Shop Supplies 1.00                           |
|  | Tire Disposal Fee2.00                        |
| Hours 25.00 Labor:   | 1,500.0 Parts: 1,595.43 Total: 3,095.43<br>0 |

| Workorder:1601177Meter:59238Problem:Pm service.  | In Date: 02/03/2016 Closed: 02/18/2016               |
|--|--|
| - Pm service.  | Parts List Qty                                       |
| - Check and inspect voltages at right rear brake lamp and  | 15-40 Oil 15.00                                      |
| body markers.replace right brake lamp and two red body   | Napagold Oil Filter 1.00                             |
| marker lamps.  | Fuel Filter Ford Only 1.00                           |
| - Replace four tires.rotate and balance all six.   | 20" Wiper Blade 2.00                                 |
| <ul> <li>Inspect worn drive shaft center bearing.r&amp;r drive shaft an<br/>replace defective center bearing.</li> </ul> | Washer Fluid Concentr 1.00                           |
| - Inspect and service electrical crane.  | Macs Battery Cleaner 1.00                            |
| - Shop Supplies  | Led Sup Mdl 44 42 Dio 1.00                           |
| ench extense   | Led M C Lamp 1.00                                    |
|  | 179636492 Lt245-75r17 4.00                           |
|  | M C Lamp 1.00  |
|  | Support 1.00   |
|  | Ptex Thrd Lck Red Sm 1.00                            |
|  | Shop Supplies 1.00                                   |
|  | Tire Disposal Fee 4.00                               |
| Hours 10.50 Labo   | : 630.00 Parts: 1,323.46 Total: 1,953.46             |
| Workorder:1602595Meter:59600Problem:Check engine light on.Whistle on acceleration  | <b>In Date:</b> 03/11/2016 <b>Closed:</b> 04/29/2016 |
| - Transport vehicle to dealer for high pressure fuel pump  | Parts List Qty                                       |
| replacement.   | Shop Supplies 1.00                                   |
| - Shop Supplies<br>Hours 1.00 Labo   | : 60.00 Parts: 2.00 Total: 62.00                     |
| :  |  |
| Workorder:1609205Meter:64326Problem:P.M. service and headl lights dim .  | In Date: 09/02/2016 Closed: 09/20/2016               |
| - P.m. Service.  | Parts List Qty                                       |
| - Rrotate and balance all six tires.   | Napagold Oil Filter 1.00                             |
| - Inspect and service crane.   | Fuel Filter Ford Only 1.00                           |
| - Replace two cargo door strut.retorque four loose body  | 15-40 Oil 15.00                                      |
| bolts.   | Macs Chain Cable Lube 1.00                           |
| - Replace two cab light marker bulbs.replace both  | 20" Wiper Blade 2.00                                 |
| headlamps Inspect and service rear differential.   | Washer Fluid Concentr 1.00                           |
| - Test both batteries and charging system.replace both   | Used Fire X Refurbished 1.00                         |
| batteries.   | Halogen Lamp 2.00                                    |
| - Shop Supplies  | Bulb 2.00  |
|  | 1qt Syngear Oil 75-904.00                            |
|  | Non-chlor Brake Clnr 1.00                            |
|  | Support 2.00   |
|  | Led M C Lamp 1.00                                    |
|  |  |
|  | Battery 2.00   |
|  | •  |

| Workorder:1611816Meter:64676Problem:Crane pedestal broken.       | In Date: 11/16/2016 Closed: 11/29/2016              | 6    |
|--|---|------|
| - Transport vehicle to Total Truck for crane repairs.            | Parts List 0  | Qty  |
| - Shop Supplies  | Weld Pin To Base 1                                  | .00  |
|  | Shop Supplies 1                                     | .00  |
| Hours 2.00 Labor:  | 120.00 Parts: 316.55 Total: 436.55                  |      |
| <b>Workorder:</b> 1701162 <b>Meter:</b> 66648                    | In Date: 02/03/2017 Closed: 03/27/2017              | 7    |
| <b>Problem:</b> P.M. service , ignition cylinder came apart,belt | noise, fuel leak on rear tank,white smoke bad smell |      |
| - P.m. Service.  | Parts List 0  | Qty  |
| - Check for fuel leak.replace rear fuel tank filler neck         | Fuel Filter Ford Only1                              | .00  |
| hose.replace fuel cap.   | 20" Wiper Blade 2                                   | 2.00 |
| - Replace and re-key ignition cylinder.                          | Mac Wite Lithium Gres 1                             | .00  |
| - Replace belt tensioner,a/c belt and serpentine belt.           | Serpentine Belt 1                                   | .00  |
| - Replace leaking hydro-booster.flush and bleed system.          | Serpentine Belt 1                                   | .00  |
| - Clean induction system,flush injectors.                        | Tensioner-heavy Duty 1                              | .00  |
| - R&r Dpf and pressure clean.                                    | Reman Brake Booster 1                               | .00  |
| - Inspect and service crane.                                     | Syn-atf Trans Fluid S 2                             | 2.00 |
| - Diagnose check engine light.,stuck Egr valve.r&r Egr           | Diesel Fuel Injection Service Kit 1                 | .00  |
| valve.remove broken plunger.clean carbon build up from passage.  | Diesel Egr Induction Service Kit 1                  | .00  |
| - Shop Supplies  | Exha 1  | .00  |
| end eddine   | Fuel Cap 2  | 2.00 |
|  | Hose Clamp 2  | 2.00 |
|  | Hose Clamp 4  | 1.00 |
|  | Ingition Lock 1                                     | .00  |
|  | Napagold Oil Filter 1                               | .00  |
|  | 15-40 Oil 15  | 5.00 |
|  | Fuel Hose 1   | .00  |
|  |   | .00  |
|  | -   | .00  |
|  | 5   | .00  |
| Hours 28.50 Labor:   | 1,710.0 Parts: 1,522.22 Total: 3,232.22<br>0        |      |

| Workorder:1708834Meter:71802Problem:P.M. Service.   | In Date: 09/14/2017 Closed: 09/21/  | 2017  |
|---|---|-------|
| - P.m. service.   | Parts List  | Qty   |
| - Replace two failed led red tail lamps and dome lamp bulb                                | . 15-40 Oil   | 15.00 |
| - Replace corroded trailer plug socket.repair wiring as                                   | Napagold Oil Filter   | 1.00  |
| needed.   | Fuel Filter Ford Only   | 1.00  |
| - Replace two worn tires.put on front .rotate and balance siz tires.nitro fill.           | <sup>x</sup> Napagold Air Filter  | 1.00  |
| - Inspect and service crane.  | 20" Wiper Blade   | 2.00  |
| - Shop Supplies   | Used Fire X Refurbished   | 1.00  |
| - Shop Supplies   | Stg Wheel Cov - Ford  | 1.00  |
|   | Pedal Pad   | 1.00  |
|   | Led Sup Mdl 44 42 Dio   | 3.00  |
|   | Bulb  | 1.00  |
|   | trailer plug  | 1.00  |
|   | 179636492 Lt245-75r17   | 2.00  |
|   | Tr416 Valve Stem  | 2.00  |
|   | Shop Supplies   | 1.00  |
|   | Tire Disposal Fee   | 2.00  |
| Hours 9.75 Labo   | or: 585.00 Parts: 891.27 Total: 1,476.  | 27    |
| Workorder: 1712473 Meter: 73304<br>Problem: Battery light on and noise in front over bump | In Date: 12/19/2017 Closed:<br>s, Exhaust smell and smoke, check crane ground wire. |       |
| Hours 0.00 Labo   | or: 0.00 Parts: 0.00 Total: 0.00  |       |
| Workorder:1805449Meter:73304Problem:Transition Prep Charge                                | In Date: 05/29/2018 Closed: 05/29/  | 2018  |
| - Transition Prep Charge  |   |       |
| . 2   | or: 120.00 Parts: 0.00 Total: 120.00  | )     |