

10/17/2016
9:22:19AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172356 2008 CHEVROLET MALIBU Car, Intermediate, Hybrid

Workorder: 841172 **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts
In Date: 07/10/2008	Hours	Description
Close Date: 07/10/2008	Quantity	
- Pre-Delivery Inspection	2.00	
Parts Charge: 0.00	Labor Charge: 120.00	

Workorder: 847651 **Problem:** P.M SERVICE,TIRE LIGHT ON

Meter Reading: 5570	Labor	Parts
In Date: 12/03/2008	Hours	Description
Close Date: 12/09/2008	Quantity	
- Pm Service	3.00	OIL FILTER 1.00
- Balance 4 Tires. Nitro Fill.Check All Tires.Retrain Tpms.		SHOP SUPPLIES 1.00
- Shop Supplies		5W30 OIL 5.00
Parts Charge: 20.53	Labor Charge: 60.00	

Workorder: 847809 **Problem:** CANCEIVER/PROGRAM

Meter Reading: 5570	Labor	Parts
In Date: 12/08/2008	Hours	Description
Close Date: 12/09/2008	Quantity	
- Program Canceiver	0.50	
Parts Charge: 0.00	Labor Charge: 30.00	

Workorder: 937234 **Problem:** P.M SERVICE

Meter Reading: 11120	Labor	Parts
In Date: 04/30/2009	Hours	Description
Close Date: 05/07/2009	Quantity	
- Pm Service	4.00	10W30 MOTOR OIL 5.00
- Replace 2 Tires.Put On Front. High Speed Balance 4		CH9018 OIL FILTER ACD PF457G WIX 57082 1.00
Tires. Fill W/Nitrogen.		TIRE DISPOSAL FEE 2.00
- Shop Supplies		413009507 215/60R16 ASSUR COMF TRD 94T 2.00
		SHOP SUPPLIES 1.00
Parts Charge: 217.91	Labor Charge: 240.00	

10/17/2016
9:22:19AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172356 2008 CHEVROLET MALIBU Car, Intermediate, Hybrid

Workorder: 937451 **Problem:** 001 WASH TICKET ISSUED OUT 05/05/09

Meter Reading: 0	Labor	Parts	
In Date: 05/05/2009	Hours	Description	Quantity
- 001 Wash Ticket Issued Out 05/05/09			
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 8.34	

Workorder: 941203 **Problem:** right rear tire flat

Meter Reading: 14580	Labor	Parts	
In Date: 07/24/2009	Hours	Description	Quantity
- Repair R/R Tire.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00	Labor Charge: 60.00		

Workorder: 943125 **Problem:** P.M service, tire light on.

Meter Reading: 16643	Labor	Parts	
In Date: 09/11/2009	Hours	Description	Quantity
- P.M Service.	6.50	SHOP SUPPLIES	1.00
- Mount Two New Tires, Rotate & Balance All Four Tires.		CA9492 AIR FILTER ACD A1627C WIX 46092	1.00
- Alignment.		CH9018 OIL FILTER ACD PF457G WIX 57082	1.00
- Shop Supplies		5W30 OIL	5.00
		413009507 215/60R16 ASSUR COMF TRD 94T	2.00
		TIRE DISPOSAL FEE	2.00
Parts Charge: 223.95	Labor Charge: 390.00		

Workorder: 947089 **Problem:** Wiper blades comming apart

Meter Reading: 19980	Labor	Parts	
In Date: 12/16/2009	Hours	Description	Quantity
- Replace Wiper Blades.	0.30	19187382 WIPER BLADE R/HAND (ACD 8-992115)	1.00
- Shop Supplies		19187383 WIPER BLADE L/HAND (ACD 8-992415)	1.00
		SHOP SUPPLIES	1.00
Parts Charge: 43.25	Labor Charge: 36.00		

10/17/2016
9:22:19AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172356 2008 CHEVROLET MALIBU Car, Intermediate, Hybrid

Workorder: 947209

Problem: Tire light on.

Meter Reading: 20204	Labor	Parts	
In Date: 12/21/2009	Hours	Description	Quantity
- Inspect All Tires, Reset Tire Pressures, Reset Tire Light.	0.50		
Parts Charge: 0.00	Labor Charge: 60.00		

Workorder: 1001607

Problem: P.M service.

Meter Reading: 22259	Labor	Parts	
In Date: 02/16/2010	Hours	Description	Quantity
- P.M Service.	3.00	10W30 MOTOR OIL	6.00
- Rotate & Balance All Four Tires.		CH9018 OIL FILTER ACD PF457G WIX 57082	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge: 22.68	Labor Charge: 180.00		

Workorder: 1005324

Problem: P.M service.

Meter Reading: 27244	Labor	Parts	
In Date: 05/24/2010	Hours	Description	Quantity
- P.M Service.	2.00	SHOP SUPPLIES	1.00
- Shop Supplies		CH9018 OIL FILTER ACD PF457G WIX 57082	1.00
		10W30 MOTOR OIL	5.00
Parts Charge: 19.78	Labor Charge: 120.00		

Workorder: 1006605

Problem: Service hybrid and check engine light on.

Meter Reading: 28563	Labor	Parts	
In Date: 06/23/2010	Hours	Description	Quantity
- Service Hybrid Sys. And Check Engine Light On.Transport To Dealer For Defective Hybrid Battery Pack.	2.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00	Labor Charge: 60.00		

10/17/2016
9:22:19AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172356 2008 CHEVROLET MALIBU Car, Intermediate, Hybrid

Workorder: 1006738 **Problem:** canceiver reflash

Meter Reading: 28563	Labor	Parts	Quantity
In Date: 06/28/2010	Hours	Description	Quantity
- Reflash Canceiver	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00		Labor Charge: 60.00	

Workorder: 1007302 **Problem:** Right rear tire flat.

Meter Reading: 29048	Labor	Parts	Quantity
In Date: 07/12/2010	Hours	Description	Quantity
- Install Four New Tires.Nitrogen Fill And Balance All Four.	4.50	738276571 215/60R16 ASSURANCE FUEL MAX 94H	4.00
- Perform Wheel Alignment Complete.		TIRE DISPOSAL FEE	4.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge: 397.96		Labor Charge: 270.00	

Workorder: 1008971 **Problem:** Towed in no start.

Meter Reading: 30588	Labor	Parts	Quantity
In Date: 08/19/2010	Hours	Description	Quantity
- Transport Vehicle To And From Dealer For Replacing 12 Volt Battery Under Factory Warranty.	2.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 2.00		Labor Charge: 60.00	

Workorder: 1009004 **Problem:** WON'T START

Meter Reading: 30174	Labor	Parts	Quantity
In Date: 08/19/2010	Hours	Description	Quantity
- From: Silver Bell Cres To: L.V.Shop At 2601-To Be Paid By Schumacher			
Parts Charge: 0.00		Labor Charge: 0.00	
		Commercial Charge: 102.00	

10/17/2016
9:22:19AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172356 2008 CHEVROLET MALIBU Car, Intermediate, Hybrid

Workorder: 1009284 **Problem:** FLASH CANCEIVER

Meter Reading: 30368	Labor	Parts			
In Date: 08/26/2010	Hours	Description	Quantity		
- Flash Canceiver	1.00	SHOP SUPPLIES	1.00		
- Shop Supplies					
Parts Charge:	2.00	Labor Charge:	60.00		

Workorder: 1010458 **Problem:** wont start

Meter Reading: 31252	Labor	Parts			
In Date: 09/23/2010	Hours	Description	Quantity		
- From: 114 Silver Bell Cresant To: Lv Shop				Commercial Charge:	102.00
Parts Charge:	0.00	Labor Charge:	0.00		

Workorder: 1010472 **Problem:** Towed in ,no start.

Meter Reading: 31489	Labor	Parts			
In Date: 09/23/2010	Hours	Description	Quantity		
- Transport Vehicle To And From Dealer For Factory Warranty Repairs,Adjusting Shifter Cable For No Start In Park.	2.00	SHOP SUPPLIES	1.00		
- Shop Supplies					
Parts Charge:	2.00	Labor Charge:	60.00		

Workorder: 1011898 **Problem:** P.M. service and humming noise while driving.

Meter Reading: 32539	Labor	Parts			
In Date: 10/25/2010	Hours	Description	Quantity		
- Perform Pm Service.	5.00	CA9492 AIR FILTER ACD A1627C WIX 46092	1.00		
- Rotate And Balance All Four Tires.		CH9018 OIL FILTER ACD PF457G WIX 57082	1.00		
- Transport Vehicle To And From Dealer For Replacing Failed Belt Tensioner Under Warranty		WIPER BLADE	1.00		
- Shop Supplies		SHOP SUPPLIES	1.00		
		10W30 MOTOR OIL	5.00		
		05023 BATTERY CLEANER	1.00		
		WIPER BLADE	1.00		
Parts Charge:	68.48	Labor Charge:	240.00		

10/17/2016
9:22:19AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172356 2008 CHEVROLET MALIBU Car, Intermediate, Hybrid

Workorder: 1100769 **Problem:** damage to rear bumper

Meter Reading: 34455	Labor	Parts			
In Date: 01/07/2011	Hours	Description	Quantity		
- Damage To Rear Bumper					
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge:	210.00

Workorder: 1104050 **Problem:** P.M. service.

Meter Reading: 37746	Labor	Parts			
In Date: 04/13/2011	Hours	Description	Quantity		
- P.M. Service.					
- Rotate And Balance All Tires.					
- Shop Supplies					
Parts Charge:	116.22	Labor Charge:	180.00		

Workorder: 1108578 **Problem:** P.M. Service.Canciever inop,water leak passenger rear.

Meter Reading: 42781	Labor	Parts			
In Date: 08/15/2011	Hours	Description	Quantity		
- Perform Pm Service.					
- Install Two New Tires To The Front Wheels.Nitrogen Fill					
And Balance All Four.					
- Perform Wheel Alignment Complete.					
- Diagnose For Water In Right Front And Rear Floor Carpet					
Also Mold Odor.Remove Seats And Carpet.Wet Vacume					
And Sun Dry Carpet Then Perform Tsb# 09-01-37-002D To					
Clean And Reseal Ac Evaporator Drain					
- Shop Supplies					
Parts Charge:	254.80	Labor Charge:	660.00		

10/17/2016
9:22:19AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172356 2008 CHEVROLET MALIBU Car, Intermediate, Hybrid

Workorder: 1109280

Problem: canceiver inop spot 175

Meter Reading: 42483	Labor	Parts	
In Date: 08/31/2011	Hours	Description	Quantity
- Fix Canceiver Wires-Reprogram And Test	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 1111185

Problem: Service hybrid/traction warning light on and check tires.

Meter Reading: 45332	Labor	Parts	
In Date: 10/21/2011	Hours	Description	Quantity
- Perform Induction Service And Clean Trottle Body.Power Flush All Fuel Injectors And Clear Codes With Scan Tool.	6.75	SHOP SUPPLIES	1.00
		TIRE DISPOSAL FEE	2.00
- Computer Diagnose For Misfire.Test And Replace All Four Failed Spark Plugs With New.		408 FUEL INJECTION CLEANER	1.00
		KA8A THROTTLE BODY/ UP ENGINE SERVICE KIT	1.00
- Install Two New Tires To The Rear Wheels.Nitrogen Fill And Balance All Four.		SPARK PLUGS	4.00
		738571571 P215/60R16 ASSURANCE FUEL MAX 95V	2.00
- Diagnose For Noise In Front End.Perform Tsb#06-02-32-0076 To Lube Steering Intermediate Shaft.			
- Shop Supplies			
Parts Charge:	338.45	Labor Charge:	405.00

Workorder: 1112915

Problem: Service hybrid and service traction warning light on.

Meter Reading: 45529	Labor	Parts	
In Date: 12/06/2011	Hours	Description	Quantity
- Transport Vehicle To Dealer For Warning Lights Staying On.Replaced Cam Solenoid.	2.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	120.00

10/17/2016
9:22:19AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172356 2008 CHEVROLET MALIBU Car, Intermediate, Hybrid

Workorder: 1201526

Problem: P.M. service and detail.

Meter Reading: 46342	Labor	Parts	
In Date: 02/15/2012	Hours	Description	Quantity
- P.M. Service.	3.00	WIPER BLADE	1.00
- Rotate And Balance All Tires.		CH9018 OIL FILTER ACD PF457G WIX 57082	1.00
- Shop Supplies		WIPER BLADE	1.00
		5W30 OIL	5.00
		SHOP SUPPLIES	1.00
Parts Charge:	61.34	Labor Charge:	180.00

Workorder: 1201915

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 46088	Labor	Parts	
In Date: 02/27/2012	Hours	Description	Quantity
- 1 - Detail Vehicle Wash Ticket(S) Issued			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	90.00

Workorder: 1203761

Problem: left rear tire flat.

Meter Reading: 48722	Labor	Parts	
In Date: 04/20/2012	Hours	Description	Quantity
- Repair And Balance Left Rear Tire.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 1204348

Problem: Right rear tail light out.

Meter Reading: 49437	Labor	Parts	
In Date: 05/08/2012	Hours	Description	Quantity
- Replace Both Tail Marker Light Bulbs.	0.50	3157 TAIL LIGHT BULBS	2.00
Parts Charge:	1.20	Labor Charge:	30.00

10/17/2016
9:22:19AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172356 2008 CHEVROLET MALIBU Car, Intermediate, Hybrid

Workorder: 1204686

Problem: Right front tire flat.

Meter Reading: 50053	Labor	Parts	
In Date: 05/17/2012	Hours	Description	Quantity
- Repair Right Front Tire Flat.Nitrogen Fill And Balance Same.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 1204924

Problem: Pm service and canceiver problem.

Meter Reading: 50598	Labor	Parts	
In Date: 05/29/2012	Hours	Description	Quantity
- P.M. Service.	3.00	5W30 OIL	5.00
- Rotate And Balance All Tires.		CH9018 OIL FILTER ACD PF457G WIX 57082	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	20.69	Labor Charge:	180.00

Workorder: 1205104

Problem: canceiver issue

Meter Reading: 50603	Labor	Parts	
In Date: 05/31/2012	Hours	Description	Quantity
- Test And Remove Defective Canceiver	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 1205180

Problem: Replace key fob.

Meter Reading: 51654	Labor	Parts	
In Date: 06/04/2012	Hours	Description	Quantity
- Test And Replace Failed Door Lock Remote Key Fob With New And Reprogram With Scan Tool.	1.75	SHOP SUPPLIES	1.00
		BATTERY	1.00
- Test Battery And Charging System.Replace Bad Battery.		REMOTE TRANSMITTER	1.00
- Shop Supplies			
Parts Charge:	178.73	Labor Charge:	105.00

10/17/2016
9:22:19AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172356 2008 CHEVROLET MALIBU Car, Intermediate, Hybrid

Workorder: 1304045 **Problem:** Right headlamp inop.

Meter Reading: 62221 **Labor**

In Date: 04/24/2013 **Hours** **Description** **Parts** **Quantity**

- Remove Front Bumper Cover And Headlamp Assembly To	1.50	SHOP SUPPLIES		1.00
Access And Replace Failed Right Head Lamp Bulb And		HARNES		1.00
Harness With New.		CAPSULE		1.00
- Shop Supplies				
Parts Charge:		47.56		
		Labor Charge:	90.00	

Workorder: 1308485 **Problem:** P.M. service and check tire edge wear.

Meter Reading: 67412 **Labor**

In Date: 08/22/2013 **Hours** **Description** **Parts** **Quantity**

- Perform Pm Service.	6.50	Wiper Blade - AccuFit - Passenger's Side		1.00
- Install Four New Tires To Wheels.Nitrogen Fill And		738571571 P215-60R16		4.00
Balance All Four.		NAPA QUART 5W30		5.00
- Perform Wheel Alignment Complete.		SHOP SUPPLIES		1.00
- Shop Supplies		NAPAGOLD OIL FILTER		1.00
		TIRE DISPOSAL FEE		4.00
		ACCUFIT BEAM		1.00
Parts Charge:		615.70		
		Labor Charge:	390.00	

Workorder: 1401183 **Problem:** Pm service.Low tire pressure warning light on and check for message on radio

Meter Reading: 73770 **Labor**

In Date: 02/04/2014 **Hours** **Description** **Parts** **Quantity**

- P.M. Service.	7.50	NAPAGOLD OIL FILTER		1.00
- Diagnose And Replace Defective Left Tpms .Rotate And		Wiper Blade - AccuFit - Passenger's Side		1.00
Balance All Four Tires And Reprogram Sensor.		PAD SET, REAR DISC		1.00
- Resurface Rear Brake Rotors,Replace Rear Brake		SHOP SUPPLIES		1.00
Pads.Service And Lube Rear Brake Calipers.Flush And		BRAKE CLEANER		1.00
Bleed System.		ACCUFIT BEAM		1.00
- Shop Supplies		NAPA QUART 5W30		5.00
		Tire pressure sensor		1.00
Parts Charge:		179.60		
		Labor Charge:	450.00	

10/17/2016
9:22:19AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172356 2008 CHEVROLET MALIBU Car, Intermediate, Hybrid

Workorder: 1406410

Problem: P.M. Service.Recall #14116(steering assist.)

Meter Reading: 78712		Labor		Parts	
In Date: 06/30/2014	Close Date: 07/14/2014	Hours	Description		Quantity
-	Perform Pm Service.	4.00	SHOP SUPPLIES		1.00
-	Test Starting And Charging System.Battery Failed		BATTERY		1.00
	Loadtest After Recharge.Replace Failed Battery With New.		NAPAGOLD OIL FILTER		1.00
			NAPA QUART 5W30		5.00
-	Rotate And Balance All Four Tires.				
-	Shop Supplies				
Parts Charge:		146.01	Labor Charge:	240.00	

Workorder: 1407610

Problem: Service traction control light on.

Meter Reading: 79650		Labor		Parts	
In Date: 08/01/2014	Close Date: 08/22/2014	Hours	Description		Quantity
-	Computer Diagnose For Traction Control Light	4.00	EXHAUST ACTUATOR SOLENOID VALVE		1.00
	On.P0014,P0Aa2And C0561.Pinpoint Test And Replace		FAB LOOM-SPLIT POLY		2.00
	Exhaust Camshaft Valve Solenoid And Connector		SHOP SUPPLIES		1.00
	Harness.Clear Codes And Road Test.		SOLENOID VALVE CONNECTOR		1.00
-	Shop Supplies				
Parts Charge:		98.04	Labor Charge:	240.00	

Workorder: 1412565

Problem: Pm service.Check tires.Safety recall #13036

Meter Reading: 83466		Labor		Parts	
In Date: 12/16/2014	Close Date: 01/06/2015	Hours	Description		Quantity
-	Pm Service.	6.50	NAPA QUART 5W30		5.00
-	Replace Hood Strut Support.		NAPAGOLD OIL FILTER		1.00
-	Replace Two Tires.Rotate And Balance All Four.		ACCUFIT BEAM		1.00
-	Transport Vehicle To And From Dealer For Safety Recalls #13036 And #14116		FLOOR MAT		1.00
			HOOD STRUT		1.00
-	Shop Supplies		TIRE DISPOSAL FEE		2.00
			HOOD LIFT		2.00
			Wiper Blade - AccuFit - Passenger's Side		1.00
			738571571 P215-60R16		2.00
			SHOP SUPPLIES		1.00
Parts Charge:		398.40	Labor Charge:	390.00	

10/17/2016
9:22:19AM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172356 2008 CHEVROLET MALIBU Car, Intermediate, Hybrid

Workorder: 1505929

Problem: Pm service.

Meter Reading: 88442		Labor		Parts	
In Date: 06/15/2015	Close Date: 06/22/2015	Hours	Description	Quantity	
- Pm Service.		9.50	738571571 P215-60R16		2.00
- Replace Front Brake Pads And Two Front Brake Rotors.Bleed Brake System.			FRONT BRAKE ROTOR		2.00
			NAPAGOLD OIL FILTER		1.00
- Replace Two Tires.Rotate And Balance All Four.			TIRE DISPOSAL FEE		2.00
- Complete Front End Alignment And Test Drive.			NAPA QUART 5W30		5.00
- Shop Supplies			FRONT BRAKE PAD		1.00
			Wiper Blade - AccuFit - Passenger's Side		1.00
			SHOP SUPPLIES		1.00
			ACCUFIT BEAM		1.00
			NAPAGOLD AIR FILTER		1.00
Parts Charge: 505.23		Labor Charge: 570.00			

Workorder: 1511680

Problem: P.M. service and tire pressure low light on.

Meter Reading: 92709		Labor		Parts	
In Date: 11/16/2015	Close Date: 11/24/2015	Hours	Description	Quantity	
- Pm Service.		3.00	WD40 16OZ		1.00
- Rotate And Balance All Four Tires.			NAPA QUART 5W30		5.00
- Shop Supplies			SHOP SUPPLIES		1.00
			NAPAGOLD OIL FILTER		1.00
			ACCUFIT BEAM		1.00
			Wiper Blade - AccuFit - Passenger's Side		1.00
Parts Charge: 64.35		Labor Charge: 180.00			

Workorder: 1600781

Problem: Nail in left front tire.

Meter Reading: 93500		Labor		Parts	
In Date: 01/25/2016	Close Date: 01/29/2016	Hours	Description	Quantity	
- Repair And Balance Left Front Tire.		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 60.00			

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10172356 2008 CHEVROLET MALIBU Car, Intermediate, Hybrid

Workorder: 1604657 **Problem:** P.M. service and transmission has hard shifts and traction control light comes on.

Meter Reading: 94033	Labor	Parts		
In Date: 05/03/2016	Hours	Description	Quantity	
- P.M. Service.	4.50	NAPA QUART 5W30	5.00	
- Test Drive For Hard Shifting Concern.Scan For Codes, None Present.Reset Transmission Shift Parameters.		NAPAGOLD OIL FILTER	1.00	
		ACCUFIT BEAM	1.00	
		Wiper Blade - AccuFit - Passenger's Side	1.00	
- Rotate And Balance All Tires.		WASHER FLUID CONCENTR	1.00	
- Shop Supplies		SHOP SUPPLIES	1.00	
Parts Charge:	56.93	Labor Charge:	270.00	

Workorder: 1605749 **Problem:** Check engine light on and oil burning smell.

Meter Reading: 94153	Labor	Parts		
In Date: 06/03/2016	Hours	Description	Quantity	
- Diagnose Check Engine Light.P0010.Perform Pinpoint Test.Replace Defective Intake Cam Position Sensor.Replace Leaking Vave Cover Gasket.Clear Codes.	3.50	SEALANT	1.00	
		CAMSHAFT SOLENOID	1.00	
		SHOP SUPPLIES	1.00	
- Shop Supplies		GASKET	1.00	
Parts Charge:	109.82	Labor Charge:	210.00	

Workorder: 1607739 **Problem:** Transition Prep Charge

Meter Reading: 94924	Labor	Parts		
In Date: 07/29/2016	Hours	Description	Quantity	
- Transition Prep Charge	2.00			
Parts Charge:	0.00	Labor Charge:	0.00	

Total Parts Charges:	4,796.28	Total Labor Charges:	8,121.00	Total Comm. Charges:	616.49
----------------------	-----------------	----------------------	-----------------	----------------------	---------------