



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V35845

In Date: 10/22/2010
Close Date: 12/07/2010

Meter Reading: 1,305.00

Problem?

Install bracket for third airpack. It is just sitting on a shelf now...unsecured. R41-1

Task performed:

1. installed air pack brkt in R-1 compt.
2. Readj compt mnt in cab. j

Parts	Quantity
101-124-000CRASH RESTRAINT STRAPS	1
FHLP-6TANK CLIP	2
KD-UN-5-SFUSE 6-SF BRACKET	1

Workorder: V36693

In Date: 11/28/2010
Close Date: 12/22/2010

Meter Reading: 49,903.00

Problem?

The side door in the patient compartment of the R41B truck has no hydraulic arm to prevent it from hitting the officer side door, an possibly breaking; glass, mirrors, and other doors. r41

Task performed:

- (1) TRAVELED TO ST41 TO REPLACE DOOR PISTON ON SIDE DOOR THAT WAS MISSING ON R41. DONE.
- (2) READJUSTED REAR AIR BAGS, ROAD TESTED OK. J.W.

Parts	Quantity
10009821DOOR SHOCK	1

Workorder: V36447

In Date: 11/15/2010
Close Date: 01/03/2011

Meter Reading: 3,148.00

Problem?

side cab entry door swings freely when opened position. r41

Task performed:

- (1) TRAVELED TO ST-41 TO REPAIR DOOR THAT SWINGS FREELY WHEN OPEN. REMOVED BROKEN SPRING AND INSTALLED NEW ONE. J.W.

Parts	Quantity
NO PARTS USED	

Workorder: V38564

In Date: 02/16/2011
Close Date: 02/23/2011

Meter Reading: 8,157.00

Problem?

no emergency lights r41 (on-call)

Task performed:

- Call stn to confirm fault; was notified that problem was solved; opr error; cancelled call out. j

Parts	Quantity
NO PARTS USED	



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V38059

In Date: 01/26/2011
Close Date: 03/08/2011

Meter Reading: 8,157.00

Problem?

black corrugated pass through window gasket between cab and "the box" is leaking during rain storm r41

Task performed:

rep rear window gskt that was falling off. j

Parts

NO PARTS USED

Quantity

Workorder: V39268

In Date: 03/17/2011
Close Date: 03/30/2011

Meter Reading: 12,491.00

Problem?

Driver Rear Airbag/ truck is leaning to driver side. Suspension is very bouncy, station 41.

Task performed:

1. Travel to stn; chk unit; needs valves for air bags.
2. Fnd X-member___ for leveling valves brkn; rem air lines, tanks, mnt plate, wiring & both brkn cornr brkts; welded brkts; reassem all parts; adj ck valves; ck ok.
3. Assist w/leveling valves & remntng air tanks. j

Parts

NO PARTS USED

Quantity

Workorder: V40003

In Date: 04/19/2011
Close Date: 04/27/2011

Meter Reading: 15,019.00

Problem?

move air pack bracket or shelf 6 or 8 inches up, sta41.

Task performed:

Move air pack brkt - stn request; needs air pack off of shelf & relocated. j

Parts

FHLP-6TANK CLIP

Quantity

2

Workorder: V39620

In Date: 04/01/2011
Close Date: 05/05/2011

Meter Reading: 14,181.00

Problem?

R411 siren wail function is not working on the manual dial, pressing the horn in emergency response brings up wail function but c not cycle R41

Task performed:

Replcd siren head. j

Parts

295SLSA1SIREN

Quantity

1



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V39913

In Date: 04/13/2011
Close Date: 05/13/2011

Meter Reading: 14,181.00

Problem?

Siren is malfunctioning R411

Task performed:

siren inop; R/R siren. j

Parts

295SLSA1SIREN

Quantity

1

Workorder: V40467

In Date: 05/08/2011
Close Date: 06/03/2011

Meter Reading: 16,992.00

Problem?

Pt compartment door has seals that are coming off R411

Task performed:

Reinstalled rubber seal on doors. j

Parts

NO PARTS USED

Quantity

Workorder: V40469

In Date: 05/08/2011
Close Date: 06/03/2011

Meter Reading: 16,992.00

Problem?

Shore line AC fan is making strange noises when the unit is plugged in R41

Task performed:

1. 110 A/C making noise; rep A/C fan for condensor.
2. Readj stretcher latch & tested. j

Parts

NO PARTS USED

Quantity

Workorder: V40889

In Date: 05/26/2011
Close Date: 06/09/2011

Meter Reading: 18,152.00

Problem?

The scba in the pt compartment does not sit flush in the bracket because it hangs off the base. Sta 41.

Task performed:

Rep strap on bottle holder. j

Parts

FHLP-6TANK CLIP

KD-UN-5-SFUSE 6-SF BRACKET

Quantity

4

2



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V41276

In Date: 06/12/2011
Close Date: 07/01/2011

Meter Reading: 18,318.00

Problem?

R411 entire electrical system malfunctioned. Truck had to be shut down twice before truck operated properly

Task performed:

Chkd sys & all tested ok. j

Parts

Quantity

NO PARTS USED

Workorder: V42093

In Date: 07/18/2011
Close Date: 07/18/2011

Meter Reading: 21,441.00

Problem?

Fuel smell in cab.

Task performed:

R411 FUEL SMELL IN CAP VERY BAD NO FUEL LEAK FOUND LOOK LIKE ENG WENT INTO REGEN AND TRUCK WAS IDLING AND STOP ENG OK NO SMELL AT THIS TIME AK

Parts

Quantity

NO PARTS USED

Workorder: V42506

In Date: 08/03/2011
Close Date: 08/05/2011

Meter Reading: 22,725.00

Problem?

back up camera/monitor not working R 41

Task performed:

Contacted horton for WARRANTY repair. j

Parts

Quantity

NO PARTS USED

Workorder: V42488

In Date: 08/02/2011
Close Date: 08/16/2011

Meter Reading: 22,725.00

Problem?

replace all tires r 41

Task performed:

outside agency replace all tires r 41

Parts

Quantity

NO PARTS USED

Vendor? BOULEVARD



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V42603

In Date: 08/06/2011
Close Date: 08/30/2011

Meter Reading: 22,881.00

Problem?

Left rear hub cap came off vehicle. R 41

Task performed:

Rem other side of wheel

j

Parts

Quantity

NO PARTS USED

Workorder: V43194

In Date: 08/31/2011
Close Date: 09/02/2011

Meter Reading: 24,223.00

Problem?

The gasket between the box and the cab leaks severely. R 41

Task performed:

Contacted Hallmark for WARRANTY repair

j

Parts

Quantity

NO PARTS USED

Workorder: V43195

In Date: 08/31/2011
Close Date: 09/19/2011

Meter Reading: 24,486.00

Problem?

Check engine light come for about 10 secondss intermittently then goes off. R 41

Task performed:

found no code but low on coolant

Parts

Quantity

NO PARTS USED

Workorder: V43821

In Date: 09/21/2011
Close Date: 10/03/2011

Meter Reading: 25,727.00

Problem?

Check charging system. Sta 41.

Task performed:

checked charging system and tested ok

Parts

Quantity

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V44003

In Date: 09/29/2011
Close Date: 10/03/2011

Meter Reading: 26,246.00

Problem?

Air horns not working.

Task performed:

Parts

Quantity

checked air horns found that diaphragm busted replaced
checked ok

NO PARTS USED

Workorder: V43861

In Date: 09/23/2011
Close Date: 10/07/2011

Meter Reading: 25,883.00

Problem?

Alarm going off in cab.

Task performed:

Parts

Quantity

checked for alarm going off no alarm going off

NO PARTS USED

Workorder: V44322

In Date: 10/12/2011
Close Date: 10/17/2011

Meter Reading: 26,719.00

Problem?

battery box troubleshooting.

Task performed:

Parts

Quantity

SEALED BATTERY BOX CHECKED BATTERIES AND
CHARGER FOR GASESS

NO PARTS USED

Workorder: V44161

In Date: 10/05/2011
Close Date: 10/20/2011

Meter Reading: 26,719.00

Problem?

The air bag dump is constantly leaking, Sta 41.

Task performed:

Parts

Quantity

repairs one on wo 44193

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V44200

In Date: 10/06/2011
Close Date: 10/28/2011

Meter Reading: 26,719.00

Problem?

wont start r 41

Task performed:

found truck wont start, ck injector control press, troubleshoot system, found faulty high pressure oil pump, removed fuel lines, filter housing and pump, replced pump, reassembled ck ok

found air compressor leaking oil into air system, removed ps pump pat ac comp and air compressor, replaced air comp, reassembled all parts ran and ck ok

found oil in air govenor and air dryer, r&r air gov., r&r dryer cartridge filter and purge valve, ck ok

Parts

Quantity

065624AD-IP DRIER	1
1812348C1FUEL LINE SLEEVE INT	2
1830070C1GEAR AIR COMPRESSOR	1
1836235C1COMP MOUNT GASKET	1
1882259C931882259C94 HIGH PRESSURE OIL PUMP	1
284358GOVERNOR D-2	1
3663597C91USE BX5014144X AIR COMPRESSOR	1
591597C2PS GASKET	1
CORECORE CHARGE	1
K022105PURGE VALVE AD-IP-IS	1

Workorder: V44372

In Date: 10/13/2011
Close Date: 10/28/2011

Meter Reading: 26,719.00

Problem?

replace body mounts R411

Task performed:

replaced body mounts, removed stairchair compartment, removed air tanks and condenssor assembly, r&r all mounts

Parts

Quantity

388863HOSE KIT	2
----------------	---

Workorder: V44521

In Date: 10/19/2011
Close Date: 10/28/2011

Meter Reading: 26,719.00

Problem?

replace bushings in torque arm

Task performed:

Replace bushings in torque arm - Total Truck j

Parts

Quantity

NO PARTS USED	
---------------	--

Vendor? TOTAL TRUC K



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V44193

In Date: 10/06/2011

Meter Reading: 26,731.00

Close Date: 11/07/2011

Problem?

C inspection and repairs as needed R411

Task performed:

1. Chk btry cables; rerouted/insulated cables - ck ok.
2. Fnd btry compt door won't open - opened door; rem inside panel; diss latch & linages; rep/reassem; ck opn - grease.
3. Fnd rear torsion bar bushings bad; rem shocks, air level valve rods & bar; tagged bar for bushing replacement.
4. Fnd leveling valves leaking air; R/R lines/valves; adjusted.
5. "C" svc; truck did not run; finished when truck was driveable.
6. Coolant line shut off valve install.
7. Torq all axle u-bolts; rem rear axle "S" cab lcn plates; ck ok.
8. R/R lower king pin grease fittings; greased pins.
9. Ck/coolant leak; ran eng at hi-idler; fnd clmps loose beh turbo; rem air clnr & air tubes; tightened clmps; ran/ck ok; reassem.
10. Ck LRO tire monitor sensor; reinflate tire; reinstalled seal ring on sensor; ck ok.
11. Fnd pat compt door catches - loose; tighten all screws; remntd SCBA brkt in L-2; ck ok.
12. Replc pat A/C filters; no filters in stock; rem/clnd; replc/mod mnt screws.
13. Quality check - j. George.
14. Ck for EGR coolers leaking internally; topped off cooling sys; went for test drive, press test & run coolant level; ck ok.
15. Cln work area - scrub floor. j

Parts

Quantity

1878042C91FUEL FILTER 2008 HORTON	1
2505183C91LEVELING VALVE	2
2506656C124316 WIX CAB A/C FILTER	1
5774457744XD OIL FILTER	1
91-22WIPER BLADE	2
F6DZ-8100-A9C3Z8101B RADIATOR CAP 10238 STANT	1

Workorder: V44937

In Date: 11/03/2011

Meter Reading:

Close Date: 12/02/2011

Problem?

Empty bracket behind the driver side front wheel in the engine compartment. sta 41.

Task performed:

truck missing rumbler, will need to order new one

Parts

Quantity

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V45290

In Date: 11/18/2011
Close Date: 12/02/2011

Meter Reading:

Problem?

Airhorn on LT side is not working and the Driver side airhorn is loose.

Task performed:

adjusted air horn

Parts

NO PARTS USED

Quantity

Workorder: V45492

In Date: 11/29/2011
Close Date: 12/02/2011

Meter Reading:

Problem?

drivers side headlight is out. sta 41

Task performed:

replaced head light and repaired wires

Parts

9007H9007 BULB ASSY

Quantity

2

Workorder: V45472

In Date: 11/29/2011
Close Date: 12/12/2011

Meter Reading:

Problem?

DRIVER'S SIDE HEADLIGHT IS OUT. NO BULBS IN THE STATION TO REPLACE IT. ALSO, CHECK ENGINE LIGHT HAS BEI FLASHING UPON VEHICLE START-UP. Sta 41

Task performed:

replaced led lights

Parts

60R00FRR600 SERIES RED LED W/O FLANGE

Quantity

2

Workorder: V45570

In Date: 12/02/2011
Close Date: 12/16/2011

Meter Reading:

Problem?

The gagrage door openeris damage and falling apart so we are unable to open or close the bay doors. Sta 41

Task performed:

THE GARAGE DOOR OPERNER IS DAMAGE AND FALLING APART SO WE ARE UNABLE TO OPEN OR CLOSE THE BAY DOORS. STA 41.

Parts

NO PARTS USED

Quantity

GAVE TO BUILDING MAINTENANCE.



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V45774

In Date: 12/09/2011

Meter Reading: 30,429.00

Close Date: 01/13/2012

Problem?

Driver side airhorn is not working R41

Task performed:

ADJUSTED AIR HORN.

Parts

3579984C1DOOR SWITCH

Quantity

2

Workorder: V46208

In Date: 01/02/2012

Meter Reading: 32,225.00

Close Date: 01/13/2012

Problem?

passenger side headlight not working R41

Task performed:

1. REPAIRED REAR A/C THAT WAS MAKING NOISE.

Parts

9007H9007 BULB ASSY

Quantity

2

2. REPLACED HEAD LIGHT.

Workorder: V46404

In Date: 01/08/2012

Meter Reading: 32,691.00

Close Date: 01/13/2012

Problem?

air horn, Sta 41

Task performed:

REPLACED SOLENOID ON AIR HORN.

Parts

NO PARTS USED

Quantity

Workorder: V46448

In Date: 01/09/2012

Meter Reading: 32,691.00

Close Date: 01/13/2012

Problem?

engine warning light/upside down triangle/solid. Level 3. Occured while driving to the station, still on. r 41

Task performed:

ROAD TESTED, NO LIGHT COMING ON.

Parts

WL2000WLA200-A00 WATER TANKVISION OLD FERR # 35

Quantity

1



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V46561

In Date: 01/13/2012 Meter Reading: 33,110.00
Close Date: 01/23/2012

Problem?

rear driver's wheel center cap is missing, fell off??? Sta 41

Task performed:	Parts	Quantity
REMOVED ALL CROME COVERS.	NO PARTS USED	

Workorder: V46656

In Date: 01/18/2012 Meter Reading: 33,531.00
Close Date: 01/23/2012

Problem?

Rear a/c inop. Sta 41

Task performed:	Parts	Quantity
REPAIRED RELAY FOR CONDENSER FANS.	NO PARTS USED	

Workorder: V46753

In Date: 01/22/2012 Meter Reading:
Close Date: 01/26/2012

Problem?

SIDE PT COMPARTMENT DOOR. THE DOOR STRUT IS LOOSE. OUT OF SOCKET, Sta 41

Task performed:	Parts	Quantity
repairs made on w/o # 46803	NO PARTS USED	

Workorder: V46777

In Date: 01/23/2012 Meter Reading: 3,818.00
Close Date: 01/26/2012

Problem?

replace tire

Task performed:	Parts	Quantity
REPLACE TIRE.	NO PARTS USED	

Vendor? BOULEVARD TIRE CENTE



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V46803

In Date: 01/24/2012
Close Date: 01/31/2012

Meter Reading: 34,096.00

Problem?

B INSPECTION R411

Task performed:

1. B inspection
2. r/r amber lite has water in it, remove lens clean water out and reseal gasket
3. ground lite under driver door inop, program and replace lite
4. r/side black rubber rub rail missing, install new rub rail and end cap
5. side entry door strut broken, replace strut
6. r/side chrome hub cover missing, had a DNI cover at s/shop, install on r/wheel
7. ground lite under side entry door inop, program and replace lite
8. top pull out draw slides broken in pat compt. replace slides and shim draw to new slides.
9. replace cracked plexi glass in pat. compt. door
10. replace a/c filters in pat. compt, replace missing screws for filter holders
11. invertor inop, check wiring and fuses, found plug not connected repair plug for invertor in I-1 compt. turn on and run invertor. check outlets all ok
12. update ECM to latest version

Parts

Quantity

02840400END CAP	1
04320004RUBBER EXTRUSION	12
10009821DOOR SHOCK	1
1501450007750USE 0775145	2
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
5632-1212 IN PAIR DRAWER SLIDES	2
5774457744XD OIL FILTER	1
607141-05USE 61H01 COPMPARTMENT LIGHT	3
AY-9400-040H20 LED	2
DOOR 822 7/8 X 7 1/2 DOOR HORTONS	1

Workorder: V47551

In Date: 02/24/2012
Close Date: 02/27/2012

Meter Reading: 36,208.00

Problem?

repair flat tire

Task performed:

REPAIR FLAT TIRE.

Parts

Quantity

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V47197

In Date: 02/09/2012
Close Date: 02/28/2012

Meter Reading: 34,853.00

Problem?

R411 needs 1 large (on side) and 1 small (rear) plate indicating unit number

Task performed:

REMOVED OLD HOLDERS AND INSTALLED ALL NEW HOLDERS AND PLATES.

Parts

Quantity

L PLACARD INSERTLARGE PLACARD INSERT CARD
S PLACARD INSERTFRONT AND BACK INSERT CARD

1
2

Workorder: V47834

In Date: 03/09/2012
Close Date: 03/16/2012

Meter Reading: 37,531.00

Problem?

A/C in the cab/ front is not working at all, Sta 41

Task performed:

FOUND BAD CONNECTION FOR BLOWER MOTOR/REPLACED MOTOR.

Parts

Quantity

3674285C1BLOWER MOTOR

1

Workorder: V48077

In Date: 03/20/2012
Close Date: 03/27/2012

Meter Reading: 38,417.00

Problem?

REPLACE REAR TIRES R41

Task performed:

REPLACE REAR TIRES R41

Parts

Quantity

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE

Workorder: V48007

In Date: 03/16/2012
Close Date: 04/02/2012

Meter Reading: 38,188.00

Problem?

o2 line pressure is low. main o2 has 900psi. R41

Task performed:

CHECKED FOR LEAK AND REPAIRED.

Parts

Quantity

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V48035

In Date: 03/17/2012 Meter Reading: 38,349.00
Close Date: 04/02/2012

Problem?

LR outside tire, no treads R41

Task performed:

1. ALL FOUR REAR TIRES WILL BE REPLACED.
2. ADJUSTED STRETCHER LATCH.

Parts

Quantity

NO PARTS USED

Workorder: V48528

In Date: 04/09/2012 Meter Reading: 40,023.00
Close Date: 04/16/2012

Problem?

Headlight needs to be replaced

Task performed:

REPLACED HEADLIGHT AND REPAIRED CONNECTION.

Parts

Quantity

9007H9007 BULB ASSY

2

Workorder: V48503

In Date: 04/07/2012 Meter Reading: 40,023.00
Close Date: 04/20/2012

Problem?

LCD SCREEN ON STEREO IS CRACKED.

Task performed:

NOT REPAIRING AT THIS TIME.

Parts

Quantity

3519807TURBO GASKET

1

3678603SEAL O RING

1

38188233818823 CAPSCREWS

4

3818824TURBO NUT

4

39013563901356 EXH.GASKET

1

3922794SEAL O RING

1

3937477MANIFOLD EXHAUST

1

39374795269779 EXHAUST GASKET C

6

3943841EXHAUST MANIFOLD

1

3944593EXH. MAN. BOLT

12

39446553944655 EXH. MAN. BOLT

1

3945252SPACER EXH. MAN.

12

5264569DRAIN GASKET 3937706

1



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V48511

In Date: 04/07/2012
Close Date: 04/20/2012

Meter Reading: 40,023.00

Problem?

LT (passenger) side headlight is out

Task performed:

REPLACED HEAD LIGHT.

Parts

NO PARTS USED

Quantity

Workorder: V49304

In Date: 05/12/2012
Close Date: 05/18/2012

Meter Reading: 42,457.00

Problem?

Drivers seat is loose and has a slight wiggle to it. R41

Task performed:

REPAIRED SEAT BASE, AND TESTED.

Parts

NO PARTS USED

Quantity

Workorder: V49439

In Date: 05/17/2012
Close Date: 06/01/2012

Meter Reading:

Problem?

r411 needs front tires

Task performed:

tires replaced on c inspection

Parts

NO PARTS USED

Quantity

Workorder: V49796

In Date: 06/01/2012
Close Date: 06/13/2012

Meter Reading: 42,840.00

Problem?

REPLACE FRONT TIRES / SERVICE CALL

Task performed:

REPLACE FRONT TIRES/SERVICE CALL.

Parts

NO PARTS USED

Quantity

Vendor? BOULEVARD TIRE CENTE



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V49144

In Date: 05/07/2012

Meter Reading: 42,990.00

Close Date: 06/18/2012

Problem?

C INSPECTION R 411

Task performed:

1. C insp.
2. update ECM
3. replace wiper blades
4. rear entry door striker plates loose, remove and add lock-tite to screws
5. r/rear door strut falling off, tighten all screws
6. install velcro on seat belt latches on front of squad bench, (tripping hazard)
7. replace 2 cabinet strut's on cabinet above action area
8. replace all a/c filters in pat. compt
9. 110v thermostat in pat. compt. inop, replace battery's
10. replace non skid tape on side entry and rear entry door floor
11. tire pressure monitor inop, install tire extension kit and replace with new style tire sensors on all wheels
12. replace 3 r/side ground lites, 1/2 lite up
13. replace 3 l/side ground lite 1/2 lite up
14. replace rear entry door ground lite, lite inop,
15. air leak, spray air system down with soap and water, found air line leaking on equalizer valve, replace air fitting, recheck for air leak, found l/side front brake chamber top fitting loose, remove brake hose and tightn fitting, replace hose and recheck for leaks, no more found at this time
16. service transmission
17. service power steering
18. service air drier
19. replace engine fan belt and a/c belt
20. power steering hose's leaking on bottom of resevor, replace both hoses (1 was a heater hose) and flush systemto remove ATF and refill with power steering fluid
21. remove rear wheels and drums, replace rear brake shoes, brake hardware and drums, adjust brakes and road test
22. replace front shocks
23. replace rear shocks
24. vanner battery charger indicator on l/side of vehicle broken, replace indicator
25. replace battery's
26. move radio mike clip from dash board to MDT plate bracket per on duty officer

Parts

Quantity

065624AD-IP DRIER	1
10009956STATUS PANEL CHARGER VANNER	1
15-40B15W40 MOTOR OIL NON SYN	30
1501450007750USE 0775145	4
1847727C1BELT	1
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
2507061C1PS RESV GASKET	1
29526898 29548988 TRANS FILTER ALLISON	1
3553628C3SHOCK REAR WPB	2
3555201C1PS HOSE NAVISTAR	1
3578105C2FRONT SHOCKS	2
3757REAR DRUMS 3757X 3647X	2
5774457744XD OIL FILTER	1
607141-05USE 61H01 COPMPARTMENT LIGHT	7
91-22WIPER BLADE	2
AMH-1AMH-1 VALVE EXTENSION	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	3
GSS1717UL1717UL0270N 343/09 GAS SHOCK 60 LB	2
HP-31DBATTERY 950CCA HP-31D	3
K022105PURGE VALVE AD-IP-IS	1
K060695BELT	1
K060705BELT HORTON	1
RWTG1234LED PRESSURE CAP	6
TRANSYNDALLISON TRANS FLUID GAL	5
VML/T1808D2503221C1 FILTER POWER STEERING	1
XK4034707QPMHD SHOE KIT 3/8 BEAM	2



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V51509

In Date: 08/10/2012
Close Date: 08/13/2012

Meter Reading: 47,471.00

Problem?

AIR IS LEAKING FROM THE REAR OF R411. AIRBAGS BOTTOM OUT AFTER IT SITS FOR A WHILE.

Task performed:

TRAVEL TO 41 CHECKED FOR AIR LEAK FOUND LR
AIR BAG TORN AND LEAKING SENT TO SHOP.

Parts

NO PARTS USED

Quantity

Workorder: V51517

In Date: 08/10/2012
Close Date: 08/13/2012

Meter Reading: 47,471.00

Problem?

Air dump valve is stuck to dump r41

Task performed:

R&R BOTH AIR BAGS, REPLACE REAR SCENE
LIGHT.

Parts

GUI1R11216GY1R11216 AIR BAG INT.
H35SN12BULB

Quantity

2
1

Workorder: V52350

In Date: 09/13/2012
Close Date: 09/13/2012

Meter Reading:

Problem?

R411 Siern stopped working.

Task performed:

1. check siren control head for power, check siren
speakers, remove center console, found siren control
head n/g, replace control head reassemble center
console....

Parts

295SLSA1SIREN

Quantity

2

Workorder: V52428

In Date: 09/17/2012
Close Date: 09/17/2012

Meter Reading: 50,668.00

Problem?

rear dump not working properly, R-411

Task performed:

1. check rear dump system, found r/side leveling valve
leaking, replace both leveling valves and adjust, road test
and recheck for leaks. ok

Parts

2505183C91LEVELING VALVE

Quantity

2

* had to replace these valves on the ground due to E-51
in for service and unable to move off lift..



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V52425

In Date: 09/17/2012

Meter Reading: 50,668.00

Close Date: 09/19/2012

Problem?

REAR DUMP NOT WORKING PROPERLEY R 411

Task performed:

Parts

Quantity

AIR LEAK/ KNEL MODULE GOING BAD/
INTERMITTENT PROB W/ MODULE WORKING
PROPERLY AT THIS TIME DID NOT HAVE PART ON
TRUCK NOTICIFIED SHOP TO GET NEW MODULE.

NO PARTS USED

Workorder: V51510

In Date: 08/10/2012

Meter Reading:

Close Date: 09/21/2012

Problem?

LEFT REAR SCENE LIGHT IS OUT. R411

Task performed:

Parts

Quantity

REPAIRED ON W/O 51517

NO PARTS USED

Workorder: V51531

In Date: 08/11/2012

Meter Reading:

Close Date: 09/21/2012

Problem?

REAR SCENE LIGHT IN BAR NOT WORKING R41

Task performed:

Parts

Quantity

REPAIRED ON W/O # 51517

NO PARTS USED

Workorder: V52250

In Date: 09/07/2012

Meter Reading:

Close Date: 09/21/2012

Problem?

LEFT-REAR SCENE LIGHT IS OUT. R41

Task performed:

Parts

Quantity

REAR SCENE LIGHT OUT REPAIRED MELTED
WIRES. REPLACED LENS SIDE.

Z8012062C-02LENS CLEAR 9 X 7 FLUTED

2



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V52103

In Date: 09/03/2012

Meter Reading:

Close Date: 10/01/2012

Problem?

The oxygen sensor connected to the main tank continuously goes off; even with a full oxygen tank. The sensor has to be continuously reset throughout each call we run. R 41

Task performed:

REPLACED SENSOR FOR OZ.

Parts

Quantity

10004858O2 SENSOR HORTON 0-3000

1

35103HANGAR EXHAUST

2

Workorder: V52951

In Date: 10/09/2012

Meter Reading:

52,210.00

Close Date: 10/19/2012

Problem?

B INSPECTION AND NEEDED REPAIRS

Task performed:

1. B-INSPECTION.
2. TRY TO ADJUST REAR LEVELING VALVES - WOULDN'T STOP LEAKING. REPLACE VALVES AND ADJUST.
3. CHECK FOR AIR LEAKS.
4. REPLACE REAR SCENE LIGHT.
5. CHECK STEERING PULL. TEST DRIVE PULL CAUSED BY TIRES.
6. FILL AIR SYSTEM TO 120 AND SIT OVER NIGHT.

Parts

Quantity

15-40B15W40 MOTOR OIL NON SYN

30

1878042C91FUEL FILTER 2008 HORTON

1

2505183C91LEVELING VALVE

2

2506656C124316 WIX CAB A/C FILTER

1

5774457744XD OIL FILTER

1

H35SN12BULB

1

RWTG1234LED PRESSURE CAP

2

Workorder: V53394

In Date: 10/30/2012

Meter Reading:

Close Date: 11/16/2012

Problem?

Back up sensor alarm not working. R41

Task performed:

1. BACK UP LIGHTS INOP, REPAIRED BACK UP ALARM THAT HAD BAD GROUND.
2. AIR LEAKS, CHEACKED FOR AIR LEAKS FOUND NONE AT THIS TIME.

Parts

Quantity

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V53441

In Date: 11/01/2012

Meter Reading:

Close Date: 11/16/2012

Problem?

back up alarm isnt working. R 41

Task performed:

1. BACK UP ALARM, REPAIRED UNIT.
2. ADJUSTED REAR BACK DOORS THAT WERE HARD TO OPEN.

Parts

Quantity

575BACKUP ALARM ECCO 107 DEC

1

Workorder: V54524

In Date: 12/19/2012

Meter Reading:

Close Date: 12/19/2012

Problem?

brake noise on R411

Task performed:

1. check for brake noise, check brakes, front wear at 70% and rear at 50% noticed drums glazed, road test vehicle no problem with stopping.

Parts

Quantity

NO PARTS USED

* noticed 4 rear tires down to wear bars, called c/shop for tires

Workorder: V54541

In Date: 12/20/2012

Meter Reading: 57,347.00

Close Date: 12/21/2012

Problem?

REPLACE REAR TIRES

Task performed:

REPLACE REAR TIRES

Parts

Quantity

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE

Workorder: V54419

In Date: 12/13/2012

Meter Reading:

Close Date: 01/03/2013

Problem?

back step missing washer and bolt to hold black bumper r41

Task performed:

REPAIRED STRECHER LATCH AND TESTED.
REPAIRED AIR LEAK IN REAR.

Parts

Quantity

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V55579

In Date: 02/06/2013

Meter Reading: 61,189.00

Close Date: 02/07/2013

Problem?

REPLACE FRONT TIRES

Task performed:

REPLACE FRONT TIRES

Parts

NO PARTS USED

Quantity

Vendor? BOULEVARD TIRE CENTE

Workorder: V55369

In Date: 01/29/2013

Meter Reading: 61,189.00

Close Date: 02/13/2013

Problem?

C insp. and repairs as needed, R-411

Task performed:

1. C insp.
2. driver seat cushion falling off, install new screws
3. r/rear entry lite inop, remove lite bar lens and install bulb.
4. replace pat. a/c filters
5. replace wiper blades
6. found fuel leak, remove filter housing, remove fuel line from fuel pump and replace fuel line grommets, reinstall filter housing and check for leaks. ok
7. found coolant level low, pressure test, found hose clamps loose under turbo, tighten clamps, found clamps under egr cooler loose, tighten clamps, remove egr valve and cross over tube check for coolant in system, none found. pressure test system again with engine at high idle, found another leak under cooler hose, tighten clamps, retest system, no more leaks found. top off coolant level and mark.
8. air system will not hold air overnight, check for leaks, found fitting inside l/side frame rail leaking, replace fitting, recheck for leaks, ok
9. remove rear wheels, drums, brakes, install new brake shoes, brake hardware, and drums, reinstall wheels, adjust brakes, road test.
10. steering wheel cover falling off, rescure cover to whe
11. driver side cab grab rail loose, tighten all cab grab hand rails
12. rear entry door stiker plate cover broken, drill holes in new plate and install
13. hook up laptop and updater international chassis ecm to newest version

Parts

- 15-40B15W40 MOTOR OIL NON SYN
- 1501450007750USE 0775145
- 1812348C1FUEL LINE SLEEVE INT
- 1878042C91FUEL FILTER 2008 HORTON
- 2506656C124316 WIX CAB A/C FILTER
- 3757REAR DRUMS 3757X 3647X
- 5774457744XD OIL FILTER
- 91-22WIPER BLADE
- XK4034707QPMHD SHOE KIT 3/8 BEAM

Quantity

- 30
- 2
- 1
- 1
- 1
- 4
- 1
- 2
- 2



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V56068

In Date: 02/28/2013
Close Date: 03/15/2013

Meter Reading: 63,149.00

Problem?

R411. O2 SENSOR ALARM IS ALWAYS ON. POSSIBLE LEAK

Task performed:

CHECKED FOR LEAKS AND FOUND NO LEAK.

Parts

NO PARTS USED

Quantity

Workorder: V48738

In Date: 04/18/2012
Close Date: 04/04/2013

Meter Reading: 40,545.00

Problem?

stretcher malfunction asset #10136385 stretcher swapped at st 42 for spare.

Task performed:

CONTACTED ENSAR FOR STRETCHER REPAIR.

Parts

NO PARTS USED

Quantity

Workorder: V50266

In Date: 06/20/2012
Close Date: 04/08/2013

Meter Reading:

Problem?

Puddle of water in overhead compartment of passenger side. Water pours out on turns. Dried it with towels but water returns rapid. Only happens when its rains, like today. R 41

Task performed:

Parts

NO PARTS USED

Quantity

Workorder: V49792

In Date: 06/01/2012
Close Date: 04/09/2013

Meter Reading: 42,840.00

Problem?

REPLACE FRONT TIRES

Task performed:

work done on 49796

Parts

NO PARTS USED

Quantity



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V56275

In Date: 03/08/2013

Meter Reading: 64,829.00

Close Date: 04/10/2013

Problem?

There's a leak some where in the main 02 system which is emptying an "m" tank in 2-3 shifts.

Task performed:

REPAIRED OZ LEAK AT REGULATOR.

Parts

NO PARTS USED

Quantity

Workorder: V57091

In Date: 04/17/2013

Meter Reading: 68,106.00

Close Date: 04/19/2013

Problem?

Rear a/c inop R-411

Task performed:

CLEANED CONDENSER FANS AND TESTED SYSTEM AND TESTED OK - AND ALSO FOUND BAD CONNECTION ON RELAY.

Parts

NO PARTS USED

Quantity

Workorder: V56910

In Date: 04/09/2013

Meter Reading: 67,470.00

Close Date: 04/26/2013

Problem?

R41 driver window switch not working

Task performed:

REPAIRED WINDOW SWITCH AND TESTED.

Parts

NO PARTS USED

Quantity



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V57131

In Date: 04/18/2013

Close Date: 04/30/2013

Meter Reading: 68,106.00

Problem?

B inspection R411

Task performed:

Parts

Quantity



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

1-2. B INSP.

3. SET UP VEHICLE ON STANDS AND SWITCH FRONT TIRES FROM SIDE TO SIDE.

4. R/SIDE REAR LOAD/ SCENE L1-INOP. DISASSEMBLE RIGHT SIDE OF LT BAR FOR ACCESS TO LOAD/SCENE LT. REPLACE LT ASSEMBLY-REASSEMBLE LT BAR.

5. REAR TIRES INFLATION- TWO TIRES WOULD NOT TAKE AIR AND TOO WOULD LEAK THROUGH VALVE CORE- INSTALL NEW VALVE CORES AND REPLACE FLEX HOSES AND INFLATION FIT BRACKETS.

6. REPLACE WIPER BLADES.

7-11. SEVERE AIR LEAK AIR UP VEHICLE AND START CHECKING FOR LEAKS- THERE ARE SO MANY LEAKS I STARTED FROM UNDER HOOD AND WORKED TO THE REAR- CHANGING OUT SEVERAL PUSH/IN FITTINGS- REAR AIR BAG LEVELING VALVES LEAKING - CHANGE THEM OUT AND ADJUST RIDE HEIGHTKEEP CHECKING DIFFERENT AREAS- I KEEP FINDING MORE LEAKS AND MAKING MORE REPAIRS- MAKE UP SPECIAL GUAGESAND FILL LINE TO SEPERATE EAACH SYSTEM- THEN TRACE DOWN LEAKS IN EACH SYSTEM FOR REAR AIR BAG SYSTEM.

12. REAR BUMPER- RUBBERS-(ONE MISSING AND THE OTHER BARELY HELD ON BY ONE BOLT- ALL HOLES TRIPPED OUT OVERSIZE DRILL AND TAP ALL HOLES AND INSTALL ONE NEW BUMPER AND NEW BOLTS.

15. ENG RUNS ROUGH WHEN FIRST STARTED PULL VALVE COVER AND CHECK FOR OIL LEAKING AT INJECTORS #6 AND 4 WERE SPRAYING- REMOVE OIL HIGH PRESSURE MANIFOLD AND REPLACE ALL INJECTOR TUBE O RINGS AND REINSTALL MANIFOLD- START ENG AND RECHECK LEAKAGE-NOTE STILL HAD LEAKING BUT LESSER AMOUNTS AND STILL STARTED ROUGH- FINISH INSTALL AND TAKE VEHICLE FOR LONG RIDE- SHUT OFF AND LET SIT AWHILE- RESTART- ENG STILL MISSES LIKE ON 5 CYLINDER- DISASSEMBLE ENG AND FOUND EXCESSIVE OIL COMING FROM OUTSIDE TUBE AREA- PRESSURE MANIFOLD- MAKE UP TEMPRARY PUCK REMOVAL AND INSTALLL TOOLS- REPLACE ALL PUCKS- REASSEMBLE ENG- START AND RECHECK LEAAGE- NOW HAS PROPER AMOUNT AND ENG HAS NO MISSING OR ROUGH RUNNING-FINISH ENG ASSEMBLING- TAKE FOR LONG RAOD TEST- SHUT OFF AND LET SIT AWILE AND RESTART-CHECK STARTING AND ROUGH ENG.

02-0383709-10700 SERIES SCENE	1
04320014DOCK BUMPER HORTON	1
1822135C1 214 ORING BREATHER INT.	1
1841923C97INJ PUCK ADAPTER	6
1842626C951842626C96 OIL RAIL MANIFOLD SEALS	1
1875784C921875784C93 ICP SENSOR	1
1878042C91FUEL FILTER 2008 HORTON	1
223-485V91-8301 85 PSI CLOSED 67 OPEN PREESURE PF	1
2505183C91LEVELING VALVE	2
2506656C124316 WIX CAB A/C FILTER	1
2506712C91SOLENOID AIR DUMP INT	2
2507385C1CAB AIR LEVEL VALVE INT	1
3584247C1CHECK VALVE INT	1
388863HOSE KIT	1
435 VALVE CAP	6
481-00-225334-751 VALVE HEIGHT CONTROL	1
5006816NSYNCHRO VALVE	1
5774457744XD OIL FILTER	1
800373SC-3 CHECK VALVE 5003525	1
91-22WIPER BLADE	2
ACX-84534LUG NUT COVER PK10	2
H35SN12BULB	1



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V57828

In Date: 05/18/2013
Close Date: 05/20/2013

Meter Reading: 69,728.00

Problem?

R411 pat a/c inop

Task performed:

PASS A/C IMOP- CHECK CHANGE ON FREON GOOD- NO COMPT EVAP FAN, CORE PASSENGER REINSTALLED AND RECHARGE NO IMPROVEMENT RESTINCTION IN SYSTEM. TRAVEL TO STOP. SWAP INTO SR-4 10142532.

Parts

NO PARTS USED

Quantity

Workorder: V57837

In Date: 05/20/2013
Close Date: 05/28/2013

Meter Reading: 69,728.00

Problem?

R411 pat a/c inop

Task performed:

1. A/C PRESSURE LOW 18-15 PSI HIGH 150 PSI- SHUTTING DOWN- VACUUM SYSTEM CHECK FOR LEAK, CHECK FOR CONTAMINANTS NONE FOUND, RECHARGE SYSTEM- REMOVE RELAY INSTALL NEW RELAY- INSTALL NEW SWITCH SYSTEM; WORKING AT NORMAL TEMP.
2. REMOVE BROKEN AM/FM RADIO- INSTALL NEW RADIO.
3. ASSIST IN DIAGNOSING ELECTRICAL PROBLEM WITH MULTIPLEX.

Parts

- 1261A/C RELAY
- 1512BINARY SWITCH 22-36474
- 3825124P91PP105222 RADIO AM/FM/WB
- 75908SWITCH BATTERY MASTER 300A

Quantity

- 1
- 1
- 1
- 1

Workorder: V58278

In Date: 06/09/2013
Close Date: 06/21/2013

Meter Reading: 26,340.00

Problem?

R411 pt compartment a/c no working

Task performed:

1. REPAIRED CONDENCER FANS AND CLEANED AND TESTED.
2. REINSTALLED AIR PACK BRACKET IN L-1 COMPARTMENT.

Parts

NO PARTS USED

Quantity



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V58288

In Date: 06/10/2013
Close Date: 06/21/2013

Meter Reading: 70,958.00

Problem?

R411. PT COMPARTMENT A/C IS NOT WORKING

Task performed:

REMOVED BLOWER MOTOR AND INSTALLED NEW ONE, TESTED SYSTEM.

Parts

Quantity

2284075MOTOR BLW PRO AIR MEDTEC/HORTON

1

Workorder: V58486

In Date: 06/17/2013
Close Date: 06/24/2013

Meter Reading: 71,421.00

Problem?

scba bracket fell off on d/s compartment

Task performed:

1. REINSTALLED AIR BOTTLE HOLDER.
2. SUCTION UNIT INOP- REPAIRED SUCTION UNIT AND TESTED.

Parts

Quantity

NO PARTS USED

Workorder: V58701

In Date: 06/26/2013
Close Date: 06/27/2013

Meter Reading: 72,012.00

Problem?

Check eng light and DPF light on R411

Task performed:

UNIT SHUT OFF - CODES DPF AND ICP WILL NOT START PULL TO STATION 47 - BRING CREW TO SHOP FOR SPARE UNIT. SWAP INTO SR-4 10142532.

Parts

Quantity

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V58841

In Date: 07/03/2013

Meter Reading: 72,012.00

Close Date: 07/25/2013

Problem?

C INSPECTION R 411 CHECK ENG LT ON

Task performed:

1. Replace upper radiator hose, refill with coolant, pressure test, ok.
2. C-Inspection.
3. C-Inspection.
4. Finish C-Inspection.
5. R&R wiper blades and air filter.
6. Replace all a/c filters.
7. Service Diff.
8. Service air dryer.
9. Remove driver's door panel, reconnect broken wire for LED working light.
10. Adjust air bags.
11. Adjust all patient compartment cabinet latches.
12. Check for air leaks, replace ad quick connect fittings
13. Remove rear wheels, clean and adjust brakes, replace tires.
14. Remove front wheels brakes and hubs convert over to oil both bearings.
15. Install officer's set and cushion.
16. Adjust air horns.
17. Tighten all power steering lines.
18. Tighten mirrors.
19. Test drive truck, hook up lap top check for codes ok.
20. Q. & A. Vehicle.
21. Tighten all door hold open mounts.
22. Resecure rear bumper diamond plate.

Parts

Quantity

065624AD-IP DRIER	1
12854DOME LIGHT BULBS	2
1501450007750USE 0775145	3
1878042C91FUEL FILTER 2008 HORTON	1
211-2BULB	2
2505201C1CONTAINER	1
2506656C124316 WIX CAB A/C FILTER	1
2594129C1GASKET DPF 2 DOOR	2
370001ASEAL 35066	2
46870AIR FILTER	1
5774457744XD OIL FILTER	1
75W90GEAR OIL SYN QT	12
91-22WIPER BLADE	2
98034R98034R REFLECTOR RED	1
ANTICOOLANT ANTIFREEZE GAL	12
CHR1612340-4024 HUB COVER - FRONT AXLE 2004 RESC	4
CLEAN AND TESTCOOLER/RADIATOR	1
GPX13ULTRA VIOLET LIGHT SHORT	1
K022105PURGE VALVE AD-IP-IS	1
S448GAUGE TIRE TREAD DEPTH	1
S777COUPLING NIPPLE	2

Workorder: V59713

In Date: 08/09/2013

Meter Reading: 73,405.00

Close Date: 08/19/2013

Problem?

Driver side headlight is out. R41

Task performed:

REMOVED AND REPLACED HEADLIGHT.

Parts

Quantity

9007H9007 BULB ASSY	2
---------------------	---



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V60913

In Date: 10/01/2013

Meter Reading:

Close Date: 10/10/2013

Problem?

The lock to the driver side scba bottle compartment fell off. R41

Task performed:

REPLACED BROKEN LOCK ON AIR BOTTLE DOOR.

Parts

HA49102C2-32-15 LATCH NON LOCKING

Quantity

2

Workorder: V60960

In Date: 10/03/2013

Meter Reading: 77,885.00

Close Date: 10/10/2013

Problem?

rear a/c inop

Task performed:

REPAIRED REAR A/C THAT WAS NO WORKING
FOUND BAD CONNECTION ON FAN.

Parts

NO PARTS USED

Quantity

Workorder: V61215

In Date: 10/12/2013

Meter Reading: 78,741.00

Close Date: 10/22/2013

Problem?

TRUCK READING LOW COOLANT, TRUCK HAS COOLANT, ITS JUST AT THE ADD LEVEL. NO COOLANT AT THE STATION
R41

Task performed:

REPLACED COOLANTS IN RESEVOIR. FOUND FAN
CLUTCH STAYING ENGAGED. OIL LEVEL OVER
FULL. NEEDS TO BE DRAINED.

Parts

NO PARTS USED

Quantity

Workorder: V61347

In Date: 10/17/2013

Meter Reading: 78,888.00

Close Date: 10/22/2013

Problem?

Front a/c blowing hot R41

Task performed:

1. CHECK A/C - A/C BLOWING COLD - TEST DROVE -
INSTALLED GAUGES CHECK A/C COMPRESSOR -
CHECKOK - FOUND DISCHARGE SHRODERS AND
O??? THERMISTATS LEAKING - FOUND OIL OVER
FULL WITH FUEL - MUST SWAPT TRUCK.
2. CHANGE OIL ON MOTOR OIL DELUDED WITH
FUEL JUST CHANGED LAST WEEK.

Parts

15-40B15W40 MOTOR OIL NON SYN

Quantity

25



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V61143

In Date: 10/09/2013
Close Date: 10/23/2013

Meter Reading: 77,885.00

Problem?
A/c inop

Task performed:

A/C INOP - REPLACED BLOWER MOTOR AND TESTED.

Parts

3674285C1BLOWER MOTOR

Quantity

1

Workorder: V61470

In Date: 10/23/2013
Close Date: 10/30/2013

Meter Reading: 79,173.00

Problem?
EGR coolers

Task performed:

INSTALLED NEW COOLER GASKETS AND COOLANT CHANGE DPF FILTER.

Parts

1878918C2EGR VALVE

4307362R91KIT EGR COOLER COLD SIDE OLD 1876262C

7090595C91COOLER EGR KIT 330MM EXH SIDE OLD 1876262C

DPFCLEANED UNIT

Quantity

1

1

1

1

Workorder: V61570

In Date: 10/28/2013
Close Date: 10/31/2013

Meter Reading: 79,173.00

Problem?
b inspection r41

Task performed:

1. B INSP.
2. B INSP.
3. INSTALLED NEW REAR BRAKE SHOES AND DRUMS.
4. INSTALLED NEW COMPARTMENT LIGHT IN L-1.
5. TIGHTENED DOOR HOLD OPEN RODS.
6. DIAGNOSE ELECTRICAL PROBLEM WITH A/C AND FAN CONTROL.
7. INSTALL NEW YORK HOOK HOLDERS IN L-1.

Parts

10007758STRIP LIGHT HORTON 69"

1878042C91FUEL FILTER 2008 HORTON

2506656C124316 WIX CAB A/C FILTER

3757REAR DRUMS 3757X 3647X

5269LPVM-5 SM MOUNT

5774457744XD OIL FILTER

XK4034707QPMHD SHOE KIT 3/8 BEAM

Quantity

1

1

1

2

2

1

2



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V59829

In Date: 08/15/2013

Meter Reading:

Close Date: 01/06/2014

Problem?

the stretcher is not locking properly.

Task performed:

Parts

Quantity

PERFORMED BY ENSAR.

NO PARTS USED

Workorder: V59843

In Date: 08/16/2013

Meter Reading:

Close Date: 01/06/2014

Problem?

r411 Stretcher 10-7, won't lock. Bad stretcher is at 42, tagged.

Task performed:

Parts

Quantity

REPAIRED BY ENSAR.

NO PARTS USED

Workorder: V60658

In Date: 09/21/2013

Meter Reading:

Close Date: 01/06/2014

Problem?

AC goes in and out... r41

Task performed:

Parts

Quantity

REPAIRED ON V61143.

NO PARTS USED

Workorder: V60832

In Date: 09/27/2013

Meter Reading:

Close Date: 01/13/2014

Problem?

r411 stretcher broken. Tagged and in bays at station 42

Task performed:

Parts

Quantity

REPAIRED BY ENSAR.

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V62365

In Date: 12/01/2013
Close Date: 01/24/2014

Meter Reading: 81,654.00

Problem?

R411 PASSENGER SIDE AIR HORN NOT WORKING

Task performed:

1. INSTALLED NEW AIR HORN ON RIGHT SIDE.
2. READJUSTED REAR AIR BAGS THAT WERE LEANING - TO THE LEFT.

Parts

Quantity

1094KIT-AIR HORN-GROVER

2

HRN6681HORN AIR 24" GROVER P/N-1510

1

Workorder: V63889

In Date: 01/31/2014
Close Date: 02/04/2014

Meter Reading: 87,091.00

Problem?

replace all tires

Task performed:

REPLACE ALL TIRES.

Parts

Quantity

NO PARTS USED

Vendor? BOULEVARD TIRE

Workorder: V63591

In Date: 01/21/2014
Close Date: 02/05/2014

Meter Reading:

Problem?

R411 front tires need replacement. Ware bar showing. Also noted driver side air horn bracket missing. Not sure if itsnew, or there previous entry.

Task performed:

1. replace l/side air horn bracket

Parts

Quantity

GRV1720244770R1 HORN SUPPORT BRKT

1

Workorder: V63912

In Date: 02/02/2014
Close Date: 02/05/2014

Meter Reading:

Problem?

ac in front cad blows warm R41

Task performed:

see w/o#63972

Parts

Quantity

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V63972

In Date: 02/04/2014

Meter Reading:

Close Date: 02/05/2014

Problem?

front cab a/c is blowing hot

Task performed:

1. driver stated a/c blows warm intermittently, remove freon, check thermistors and replace both thermistors, refill freon, found leak on high side schrader valve replace valve, recharge again, run a/c found outside air blend door not closing, remove and replace vent actuator, remove dash check other vent actuator's found another one cracked for blend door, replace it, remove and install new a/c control head, run a/c cools down to 28 deg, in cab, check fan clutch comes on ok, road test unit, a/c stayed cold during road test

2. remove and adjust stretcher release handle for new stryker stretcher, (had ferno). install hook for stryker in rear of rescue

Parts

Quantity

3542606C12611234C1 VENT ACTUATOR	2
3545543C23545543C5 HEATER AC CONTROL	1
3622764C32606229C92 THERMISTER	1

Workorder: V64020

In Date: 02/06/2014

Meter Reading:

Close Date: 02/06/2014

Problem?

a/c still having intermittent cold/hot cycling r411

Task performed:

1. check out cab a/c, with truck idling a/c blows out at 24deg, road test vehicle on turnpike, a/c started to blow warm then went cold again, travel to c/shop had Steve R hook up laptop and drove truck around, found high pressure switch was giving different readings while driving, return to c/shop and replace high pressure switch, road test vehicle again, readings were normal for high pressure switch, drive truck back to s/shop, a/c was cold....

Parts

Quantity

3542575C2VENT MOT0R	2
3546241C1SWITCH A/C PRESSURE INT.	1
3557857C1CLAMPS	1

Workorder: V63629

In Date: 01/22/2014

Meter Reading: 86,391.00

Close Date: 02/12/2014

Problem?

repair coolant leak R41

Task performed:

TRUCK BROKE DOWN, REMOVED HEATER VALVES AND INSTALLED NEW ONES, REFILLED WITH COOLANT.

Parts

Quantity

746148211237 HEATER VALVE	1
---------------------------	---



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V64202

In Date: 02/13/2014

Meter Reading:

Close Date: 02/13/2014

Problem?

the front a/c is blowing hot

Task performed:

1. crew showed up at shop stated cab a/c blows warm, started truck up and a/c was blowing cold, this has been an on going problem, check freon, check actuators, all ok, call steve R, was told to reset blend doors, remove control and reset, cab a/c still blows cold, ????????

Parts

Quantity

NO PARTS USED

Workorder: V64329

In Date: 02/19/2014

Meter Reading:

Close Date: 02/28/2014

Problem?

AC not working on R411

Task performed:

1. A/C LEAK- VACUUMED SYSTEM AND FILLED NITROGEN TO FIND LEAK.
2. PRESSURE TEST AND FOUND COOLANT LEAK AT RADIATOR HOSE FROM THERMASTAT HOUSING TIGHTEN CLAMP.
3. BACK UP ALARM WORKED SOMETIMES FOUND A LOOSE GROUND CHANGED LOCATION OF GROUND AND CLEANED UP SURFACES.
4. ASSIST NORRIS WITH ABOVE A/C REPAIR.

Parts

Quantity

16-31438915 VALVE CORE A/C 3544706C1

1

16-31498925 VALVE CORE

1

8201L17-3428 ESTER OIL E7

1

Workorder: V64021

In Date: 02/06/2014

Meter Reading:

Close Date: 03/05/2014

Problem?

brand new tires instsalled last week. OUT OF BALANCE. at 60 MPH truck bopunces and shakes badly. tires need balancing.

Task performed:

1. ROAD TESTED TRUCK TESTED OK AT THIS TIME.
2. REPAIRED STRETCHER LATCH AND TESTED.

Parts

Quantity

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V64435

In Date: 02/21/2014

Meter Reading: 88,961.00

Close Date: 03/12/2014

Problem?

A/C inop R41

Task performed:

TRACED OUT PROBLEM WITH A/C SHUTTING OFF.

Parts

3674285C1BLOWER MOTOR

Quantity

1

Workorder: V64582

In Date: 02/27/2014

Meter Reading: 89,597.00

Close Date: 03/13/2014

Problem?

C inspection R411

Task performed:

1. C-INSP.
2. REPLACE BATTS- FAIL LOAD TEST.
3. TIGHTEN DOWN BOLT ON COMPRESSOR- LOOSE BOLT AT COMPRESSOR MOUNTING.
4. REPLACE VIPER BLADES.
5. SCBA BRACKET LOOSE- REPLACED BOLTS AND FASTEN DOWN.
6. L2 COMPARTMENT HOLD OPEN LOOSE- TIGHTEN DOWN BRACKET AND SHOCK.
7. ALL PAT A/C INLET FILTERS DIRTY- R&R ALL A/C INLET FILTERS.
8. REAR DOOR STRIKERS LOOSE- TIGHTEN STRIKERS.
9. 02 WRENCH VELCRO MISSING- REPLACE VELCRO.
10. R/REAR FLOOD LIGHT INOP- R&R BULB/ ENTRY DOOR LIGHT INOP R&R BULB.
11. INVERTER INOP-RESET.
12. REMOVED WHEEL AND DRUM TO CHECK BRAKES- BRAKES STILL GOOD REINSTALLED WHEEL AND DRUM AND ADJUSTED BRAKES.
13. PRESSURE TEST SYSTEM FOR LEAK AND CHECK EGR LOOKED FOR FAILURE. COOLANT LEAK AT THERMOSTAT HOUSING REPLACE THERMOSTAT AND REFILLED SYSTEM.

Parts

15-40B15W40 MOTOR OIL NON SYN

1842130C11842130C3 THERMOSTAT DT466

1846481C92SENSOR MAP

1875838C91SENSOR MANIFOLD AIR TEMP MAT

1878042C91FUEL FILTER 2008 HORTON

194BULB

2506656C124316 WIX CAB A/C FILTER

5774457744XD OIL FILTER

91-22WIPER BLADE

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER

GPX13ULTRA VIOLET LIGHT SHORT

HP-31DBATTERY 950CCA HP-31D

Quantity

30

1

1

1

1

1

1

1

2

3

1

3



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V65185

In Date: 03/25/2014
Close Date: 03/26/2014

Meter Reading: 91,735.00

Problem?
c/e light

Task performed:

Parts

Quantity

CHECKED FOR CODES FOUND CODES FOR AFTER TREATMENT FILTER- CLEANED TUBES AND SENSOR ROAD TESTED LIGHT WENT OUT.

NO PARTS USED

Workorder: V65160

In Date: 03/24/2014
Close Date: 04/08/2014

Meter Reading:

Problem?
R-411 does not shift out of first gear. (intromitten)

Task performed:

Parts

Quantity

ROAD TESTED AND TESTED OK FOUND NO CODES

NO PARTS USED

Workorder: V64219

In Date: 02/13/2014
Close Date: 04/25/2014

Meter Reading:

Problem?
Front A/C not working, moving air but not cooling. Fixed earlier at station 42 but not working again.

Task performed:

Parts

Quantity

REPAIRED ON V64329.

NO PARTS USED

Workorder: V64237

In Date: 02/14/2014
Close Date: 04/25/2014

Meter Reading:

Problem?
AC in the cab is out. This has been an ongoing problem for 3 days. Thank you

Task performed:

Parts

Quantity

AC in the cab is out.

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V65918

In Date: 04/23/2014
Close Date: 04/25/2014

Meter Reading: 94,643.00

Problem?

A/c inop intermittent

Task performed:

1. DETERMINED WHICH HVAC ACTIVATOR IS BAD. R&R R/R R/S DASH R&R MODE DOOR ACTIVATOR. RESET SYSTEM MEMORY.
2. CHK CODES- CHK OK CLEAR OLD CODES- TEST DROVE POSSIBLE LOW ON FREON- BLOWS COLD THEN WARMER.
3. VACUUM SYSTEM CHARGER SCHRADER VALVE LEAK TEST CHARGE- ROAD TEST OK.

Parts

Quantity

3542606C12611234C1 VENT ACTUATOR

1

Workorder: V65885

In Date: 04/22/2014
Close Date: 05/09/2014

Meter Reading:

Problem?

air conditioning not working in the cab of the truck

Task performed:

TRACED OUT PROBLEM WITH A/C FOUND HIGH- CLEANED FANS TESTED.

Parts

Quantity

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V66069

In Date: 04/29/2014

Meter Reading:

Close Date: 05/23/2014

Problem?

the a/c in the front cab is blowing hot air

Task performed:

1. A/C INOP CLEANED CONDENSER FANS AND TESTED/WILL MONITOR SYSTEM.
2. REPAIRED REAR LIGHT BAR THAT WAS NOT WORKING FOUND BAD GROUND.
3. CHECK CAB A/C CLUTCH ENGAGING CHK BODY CONTROLLER CODES- \$2609.16 HVAC HIGH PRESS AND PROTECTION SENSOR.
4. CHK CAB A/C CONT TROUBLESHOOT A/C SYSTEM- COMPRESSOR DAMAGED AND GROUND TERMINAL CIRCUIT FOR TRANS OVER READING VOLTAGE.
5. REPAIR CAB A/C REMOVED KICK PANEL TRACED AND TROUBLESHOOT WIRING REPAIR-BROKEN GROUND R&R TERMINAL PLUG.
6. REPAIR A/C CONT REMOVED BELTS, LINES AND COMPARRISON- ADJ OIL LEVEL REPLACED COMPRESSOR- INSTALLED BELT.
7. REPAIR A/C COT REPLACED EXP. VALVE EXP VALVE BOLTS DAMAGED R&R BOLTS-RAN ACCUM/ DRIER -VAC AND CHARGE.
8. REPAIR A/C CON; RAN UNIT RECOVER FREON.
9. REPAIR A/C CONT. R&R SHRADER CORES- LEAK TEST- CHK OK VAC AND CHARGE SYSTEM CHK OK

Parts

Quantity

16-31438915 VALVE CORE A/C 3544706C1	2
2501105C1HARNES ICP MAP	1
3544706C1SCHRADER VALVE INT.	2
3546241C1SWITCH A/C PRESSURE INT.	1
3611894C9103-0805 A/C COMPRESSOR 4347	1
3660853C22512331C1 EXP VALVE NAV	1
3670134C1ACCUMULATOR ASSY INT.	1
9007H9007 BULB ASSY	1

Workorder: V66242

In Date: 05/05/2014

Meter Reading: 95,821.00

Close Date: 05/23/2014

Problem?

cab a/c inop

Task performed:

RAN A/C FOUND UNIT WORKING FOUND NO CODES CLEANED CONDENSER FANS.

Parts

Quantity

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V66525

In Date: 05/16/2014

Meter Reading: 95,956.00

Close Date: 05/23/2014

Problem?

B inspection R411

Task performed:

1. B SERVICE. R&R ENG OIL AND FILTER- PRESS TEST COOLING SYSTEM R&R RAD CAP.
2. B SERVICE.
3. B SERVICE.
4. FOUND PAT COMPARTMENT GROUNDS HAVE STAR WASHERS REMOVED AND CLEANED FRAME AND CONNECTIONS FOR GROUNDS.
5. REPAIR GROUNDS- REMOVED STAR WASHERS AND CLEANED GROUND CONTACTS.
6. FOUND CRANK BREATHER LEAKING- REMOVED AIR CLEANER AIR TUBES, CRANK- BREATHER TUBE AND FILTER ASSEMBLY- DISASSEMBLE AND CLEANED RESEALED BREATHER. REASSEMBLED ALL PARTS- CHK OK.
7. FOUND BATT HOLD DOWN LOOSE- REASSEMBLED ADJUSTED AND REPLACED MISSING BOLTS- CHK OK.
8. FOUND CAB DOOR SWITCHES DAMAGED- R&R DOOR SWITCHES CHO OK.
9. FOUND L-2 COMPARTMENT DOOR LOOSE- TIGHTENED HINGE MOUNT BOLTS- CHK ALL OTHER DOORS-CHK OK.

Parts

Quantity

1875880C2SEAL	1
1876922C91SEAL KIT	1
1878042C91FUEL FILTER 2008 HORTON	1
3579984C1DOOR SWITCH	2
46870AIR FILTER	1
5774457744XD OIL FILTER	1
91-22WIPER BLADE	2
F6DZ-8100-A9C3Z8101B RADIATOR CAP 10238 STANT	1



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V66616

In Date: 05/20/2014
Close Date: 05/23/2014

Meter Reading: 95,956.00

Problem?

engine running rough

Task performed:

1. CHK CODES-FOUND #6 CYL INBALANCE, REMOVED AIR CLEANER AND VALVE COVER- RAN ENGINE- #6 INJ PUCK LEAKING- NEED TO REPLACE #6 PUCK ALL OTHER INJ SEAL AND INJECTORS.
2. CHK ENG CONT; REMOVED INJECTION HARNESS AND OIL RAIL ASSEMBLY- REMOVED INJECTORS AND #6 INJ TUBE.
3. CHK ENG CONT- R&R INJECTOR TUBE O-RINGS R&R #6 INJ TUBE, R&R 6 INJECTORS- INSTALLED OIL RAIL AND VALVE COVER HARNESS VALVE COVRES.
4. CHK ENG CONT- TEST DROVE- CHK ENG CODES
5. CHK ENG CONT RAN ENG TESTS CHK OK- RAN PARK REGEN- CHK OK.

Parts

Quantity

1841923C97INJ PUCK ADAPTER	1
1842626C951842626C96 OIL RAIL MANIFOLD SEALS	1
1875784C921875784C93 ICP SENSOR	1
5010561R925010561R93 INJECTOR	6

Workorder: V64529

In Date: 05/30/2014
Close Date: 06/09/2014

Meter Reading: 89,597.00

Problem?

Coolant leak

Task performed:

Coolant Leak/ Hose to egr cooler. Travel to shop for part replaced hose test ok

Parts

Quantity

NO PARTS USED

Workorder: V66992

In Date: 06/05/2014
Close Date: 07/03/2014

Meter Reading:

Problem?

Rescue 411 is leaking oil !!! Thank you !!

Task performed:

CLEANED UP OIL AND UNDER ENGINE WILL MONITOR OIL LEAK.

Parts

Quantity

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V65696

In Date: 04/14/2014

Meter Reading:

Close Date: 07/07/2014

Problem?

front a/c is not working on R411

Task performed:

Parts

Quantity

REPAIRS DONE AT SHOP ON TICKET V65918

NO PARTS USED

Workorder: V67708

In Date: 07/06/2014

Meter Reading:

Close Date: 07/07/2014

Problem?

R411 air horn has been working intermintantly and is not as loud as it should be when it does work.

Task performed:

Parts

Quantity

remove air horns and clean, adjust both air horns

NO PARTS USED

Workorder: V67828

In Date: 07/10/2014

Meter Reading:

Close Date: 07/18/2014

Problem?

Air horn not working properly, possible air leak.

Task performed:

Parts

Quantity

ck, and test air horns ck, for air leaks all tested ok at this time.

NO PARTS USED

Workorder: V68541

In Date: 08/09/2014

Meter Reading:

Close Date: 08/12/2014

Problem?

Right headlight does not wook andneeds to be replaced R41

Task performed:

Parts

Quantity

headlights inop truck out on call sta, captain will install new light left with sta,

9007H9007 BULB ASSY

1



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V68222

In Date: 07/28/2014
Close Date: 08/28/2014

Meter Reading:

Problem?

Front compartment radio hooks needs to be repaired. Back compartment side bench seat belt needs to be repaired.

Task performed:

repaired on w/o#68819

Parts

Quantity

NO PARTS USED

Workorder: V68469

In Date: 08/06/2014
Close Date: 08/28/2014

Meter Reading:

Problem?

Cigarette lighter in front cab not functioning. Unable to charge the TripTix.

Task performed:

repaired on w/o#68819

Parts

Quantity

NO PARTS USED

Workorder: V68542

In Date: 08/09/2014
Close Date: 08/28/2014

Meter Reading:

Problem?

cigarette lighter in the front cab does not work, this is pivotal for charging the triptix tablet R41

Task performed:

repaired on w/o#68819

Parts

Quantity

NO PARTS USED

Workorder: V69053

In Date: 08/29/2014
Close Date: 09/03/2014

Meter Reading: 103,358.00

Problem?

replace rear tires

Task performed:

Replace rear tires.

Parts

Quantity

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V68730

In Date: 08/21/2014
Close Date: 09/09/2014

Meter Reading: 93,190.60

Problem?

a/c is pulsating.still blowing cold but sounds like it's about to stop working. R41

Task performed:

1. run a/c on max for 1 hour could not reproduce problem, a/c blows ice cold ???

Parts

NO PARTS USED

Quantity

Workorder: V58930

In Date: 07/08/2013
Close Date: 09/11/2014

Meter Reading: 72,012.00

Problem?

high pressure pump bad

Task performed:

work was complete parts on ticket no future issues with truck.

Parts

1812348C1FUEL LINE SLEEVE INT 4
1846481C92SENSOR MAP 1
1875838C91SENSOR MANIFOLD AIR TEMP MAT 1
1882259C931882259C94 HIGH PRESSURE OIL PUMP 1
3533425C3FUEL LINE FITTING INT. 1
3591094C1FUEL FITTING 1
CORECORE CHARGE 1

Quantity

Workorder: V69203

In Date: 09/06/2014
Close Date: 09/26/2014

Meter Reading:

Problem?

Back up camera not working R41

Task performed:

REPAIRS COMPLETE ON W/O 69221

Parts

NO PARTS USED

Quantity

Workorder: V69221

In Date: 09/07/2014
Close Date: 09/26/2014

Meter Reading:

Problem?

R411 back up camera insiee of the cab stoped working while enrout to the hospital tonight. Will not turn on.

Task performed:

REPAIRED BAD CONNECTION ON REAR CAMERA AND TESTED OK.

Parts

NO PARTS USED

Quantity



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V69288

In Date: 09/11/2014

Meter Reading: 104,361.00

Close Date: 09/26/2014

Problem?

cab a/c inop

Task performed:

1. Ran A/C and tested OK.
2. Lug nut fell off - Checked all lug nuts and checked OK
- Tighten all lugs nuts.
3. Repaired headlight that was full of water. Replaced bulb.

Parts

Quantity

2586872C1LOCK RING HEADLITE

1

2587313C1SPRING WASHER HEADLITE

1

9007H9007 BULB ASSY

1

Workorder: V69447

In Date: 09/17/2014

Meter Reading: 104,692.00

Close Date: 10/29/2014

Problem?

interior front cab compartment a/c is not working as well as back up camera R41

Task performed:

1. Repaired cab A/C installed and wired 30 amp breaker
2. Repaired bad connection on rear back up camera
3. Installed new headlight bezel

Parts

Quantity

10010552MONITOR VOYAGER 10008120

1

3574387C934020383C91 LH HEADLITE ASSY

1

3574388C93RH HEADLIGHT HARNESS 4020384C91

1

Workorder: V69547

In Date: 09/20/2014

Meter Reading: 105,143.00

Close Date: 10/30/2014

Problem?

charger outlet not working correctly. R41

Task performed:

1. Repaired connection on 12voh charger

Parts

Quantity

NO PARTS USED

Workorder: V70964

In Date: 11/16/2014

Meter Reading: 110,199.00

Close Date: 11/19/2014

Problem?

Air Bag (suspension) on the driver side has a significant air leak. R41

Task performed:

1. Found air bag leaking. R & R both air bags and fittings. Ran and checked. OK.

Parts

Quantity

GUI1R11216GY1R11216 AIR BAG INT.

2



6/25/2018

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V68819

In Date: 08/20/2014

Meter Reading: 103,497.00

Close Date: 12/03/2014

Problem?

C inspection R411

Task performed:

1. C insp
2. l/side dash a/c vent broken, replace
3. replace wiper blades
4. latch broken on compt, door behind emt seat
5. remove emt seat cushion and send out for repair
6. replace pat. compt. a/c filters
7. service air dryer
8. remove wheels, drums, brakes and replace brake shoes, hardware, and brake drums,
9. rear leaf springs make rattle noise, put rubber inbetween spring and secure with hose clamps
10. map light broken, repace lite
11. repair wiring for 12v lighter in cab
12. replace driver side door cup
13. replace broken seat belt on squad bench
14. install radio mike clip in cab

Parts

Quantity

065624AD-IP DRIER	1
0775145PANEL FILTER	3
15W40BSYN OIL BULK QTS	30
1878042C91FUEL FILTER 2008 HORTON	1
2505201C1CONTAINER	1
2506656C124316 WIX CAB A/C FILTER	1
3598043C2LOUVER DASH INT.	1
3757REAR DRUMS 3757X 3647X	2
5774457744XD OIL FILTER	1
K022105PURGE VALVE AD-IP-IS	1
LF18TS-LEDMAP LIGHT LED 18 IN	1
XK4034707QPMHD SHOE KIT 3/8 BEAM	2

Workorder: V71302

In Date: 12/01/2014

Meter Reading: 111,594.00

Close Date: 12/05/2014

Problem?

Window stuck

Task performed:

Window stuck. Fluid delivered on other w/o.

Parts

Quantity

NO PARTS USED

Workorder: V71136

In Date: 11/23/2014

Meter Reading: 110,933.00

Close Date: 12/15/2014

Problem?

replace driver front tire. tread at wear bar R41

Task performed:

Will monitor tires at this time

Parts

Quantity

NO PARTS USED



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V71261

In Date: 11/29/2014
Close Date: 12/15/2014

Meter Reading:

Problem?

There is no power to the officers door/window. The window is stuck half way in the down position.

Task performed:

Parts

Quantity

Removed and reset breaker for power windows

NO PARTS USED

Workorder: V71342

In Date: 12/02/2014
Close Date: 12/23/2014

Meter Reading: 111,594.00

Problem?

Needs new front tires Check engine light came on then went off when we turned off/on the battery. Truck was sluggish while chec engine light on.

Task performed:

Parts

Quantity

Truck was swapped out and sent to shop

NO PARTS USED

Workorder: V71839

In Date: 12/23/2014
Close Date: 12/23/2014

Meter Reading: 11,777.00

Problem?

repaired seat armrest

Task performed:

Parts

Quantity

repaired arm rest

NO PARTS USED

Vendor? CENTRAL

Workorder: V71858

In Date: 12/24/2014
Close Date: 12/30/2014

Meter Reading: 112,060.00

Problem?

replace front tires

Task performed:

Parts

Quantity

Replace tires

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V70254

In Date: 10/19/2014
Close Date: 01/05/2015

Meter Reading:

Problem?

Door handle is broken in half and does not work. Door actually opened while driving down the road to a call.

Task performed:

Drive to station
Patient side door inop/handle broken. Replaced outer door handle.

Parts

NO PARTS USED

Quantity

Workorder: V71990

In Date: 01/02/2015
Close Date: 01/20/2015

Meter Reading:

Problem?

Coolant leak in engine, no coolant at station R41

Task performed:

Swapped out. Sent to shop.

Parts

NO PARTS USED

Quantity

Workorder: V72106

In Date: 01/07/2015
Close Date: 01/20/2015

Meter Reading: 112,874.00

Problem?

EGR coolers

Task performed:

- 1.travel to c/shop to pick up unit, pick up egr coolers, jump start in yard, travel back to s/shop
2. replace egr coolers
3. charge battery's and test, n/g, replace battery's

Parts

1878918C2EGR VALVE 1
 3688514C1TUBE AIR INTAKE COLD SIDE 1
 4307362R91KIT EGR COOLER COLD SIDE OLD 1876262C 1
 7090595C91COOLER EGR KIT 330MM EXH SIDE OLD 1876 1
 ANTICOO LANT ANTIFREEZE GAL 8
 BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER 3
 HP-31DBATTERY 950CCA HP-31D 3

Quantity



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V72515

In Date: 01/21/2015
Close Date: 02/05/2015

Meter Reading:

Problem?

the hydraulic hing on the side door of the box is broken. the hing threads are striped.

Task performed:

Removed and replaced door piston on side door.

Parts

10009821DOOR SHOCK

Quantity

1

Workorder: V72754

In Date: 01/30/2015
Close Date: 02/20/2015

Meter Reading:

Problem?

on R411 the truck radio, county radio, ACC are intermittent while the truck is moving. also transmission slips from drive to neutral. also one rear flood light is out

Task performed:

Traced all connections. Found none loose. Road test.

Parts

NO PARTS USED

Quantity

Workorder: V74100

In Date: 03/23/2015
Close Date: 03/31/2015

Meter Reading: 119,146.00

Problem?

Coolant leak

Task performed:

1. COOLANT LEAK. ENGINE BELT & PULLY BROKE OFF. INSTALL NEW BELT, PULLY & ADD 3 GALL OF COOLANT. CHECK & CLEAR ALL COOLANT CODES. RAN ENGINE.

Parts

1822018C1IDLER PULLEY BOLT

1832771C1PULLEY BUSHING

1832784C1IDLER DUST COVER

1841930C1IDLER PULLEY

Quantity

1

1

1

1



6/25/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10183586

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V71367

In Date: 12/03/2014
Close Date: 04/14/2015

Meter Reading: 111,777.00

Problem?

B inspection R411

Task performed:

1. Dead inyard-jump start unit
2. B-inspection and road test
3. No start-transmission code abn ecu-none
out-remove ecu install new flash allison tran ecu.
4. Oil leak-pressure watch engine and transmisson, no
leak at this time found.
5. Cap air line remove officers seat for upholstery
6. Front tires worn-outside vender repair
7. Check for engine codes none-active
8. Check for transmission codes non active
9. PA speake on right bumper falling off-replace missing
nut and bolt
10. QA inspection

Parts

Quantity

15-40B15W40 MOTOR OIL NON SYN	27
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
5774457744XD OIL FILTER	1

Workorder: V74483

In Date: 04/07/2015
Close Date: 07/07/2015

Meter Reading:

Problem?

replace dc power port in dash as its loose and triptix power cord doesnt charge.

Task performed:

Parts

Quantity

NO PARTS USED



Palm Beach County Fire Rescue

Fleet Maintenance Asset History

Asset: (10183586) 2010 - HORTON 4400 Advanced Life Support Vehicle 2Dr

10183586

CSHOP-2015-1113

Comments: **C INSPECTION R241**

Date Opened 6-10-2015

Date Finished 6-19-2015

Meter 1 Reading: 125,190

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

1	FILTER; FUEL FILTER 2008 HORTON
30	MOTOR; 15W40 MOTOR OIL NON SYN
1	FILTER; 24316 WIX CAB A/C FILTER
1	FILTER; 57744XD OIL FILTER

CSHOP-2015-1114

Comments: **R241 REPAIRS FROM PM**

Date Opened 6-10-2015

Date Finished 6-22-2015

Meter 1 Reading: 125,190

110 V A/C NOT WORKING

TASKS PERFORMED

Q PARTS

WIPER BLADES

2 WIPER; WIPER BLADE

OIL

1 SENSOR; OIL PRESSURE SENSOR

LIGHTING SYSTEM

1 BULB; BULB

BATTERY

1 LIGHT; CLEAR UTILITY LED

INVERTER

3 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY

TIRES ALL

3 BATTERY; BATTERY 950CCA HP-31D

REAR TIRES

2 BRAKE; HD SHOE KIT 3/8 BEAM

REAR BRAKE PADS-SHOES

2 BRAKE; REAR DRUMS 3757X 3647X

FRONT BRAKE PADS-SHOES

2 BRAKE; BRAKE DRUM RUMPER FRONT

AIR SYSTEM

2 BRAKE; FRONTBRAKE KIT RUMPER AND 4DR RESCUE

FIRE EXTINGUISHER

2 STRAP; STRAP

DOOR HANDLES INSIDE-OUTSIDE

1 INTERNATIONAL; CONTAINER

SEAT BELTS

1 BRAKE; BRK PEDAL PAD

DOOR PANEL

1 NONSTOCK; A/C VENT

UPHOLSTERY

1 FILTER; PANEL FILTER

CAB-INTERIOR ACCESSORIES

1 FILTER; PANEL FILTER

DASH CONTROLS

1 GAUGE; SPMGC23 GAUGE

A/C FILTER SCREENS

1 SENSOR; O2 SENSOR HORTON 0-3000

QUALITY CHECK-REPAIRS

AIR CONDITIONING

CSHOP-2015-1457

Comments: **MAIN O2 LEAKS AT THE VALVE WHERE IT CONNECTS TO THE RESCUE R241**

Date Opened 6-29-2015

Date Finished 7-6-2015

Meter 1 Reading: 125,200

TASKS PERFORMED

NO PARTS USED

CAB-INTERIOR ACCESSORIES

Asset Work Order History 10183586

CSHOP-2015-2498

Comments: **OFFICERS DOOR STICKS WHEN TRYING TO OPEN E41**
Date Opened 8-24-2015 Date Finished 9-10-2015 Meter 1 Reading: 125,200

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
BODY EXTERIOR

CSHOP-2015-2979

Comments: **REPLACE DASH CIG LIGHTER POWER OUTLET R241 DRIVERS SIDE FLOOD LIGHT OUT**
Date Opened 9-18-2015 Date Finished 10-9-2015 Meter 1 Reading: 133,746

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
LIGHTING SYSTEM
INSTRUMENTS-GAUGES-WARNING &
AIR CONDITIONING

3 BULB; BULB

CSHOP-2015-3124

Comments: **B INSPECTION R241 BY OCS**
Date Opened 9-28-2015 Date Finished 10-14-2015 Meter 1 Reading: 134,180

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 FILTER; FUEL FILTER 2008 HORTON
1 FILTER; 57744XD OIL FILTER
1 FILTER; 24316 WIX CAB A/C FILTER

VENDOR? OIL CHANGE SERVICES

CSHOP-2015-3417

Comments: **R41**
Date Opened 10-14-2015 Date Finished 11-3-2015 Meter 1 Reading: 135,622

TASKS PERFORMED

Q PARTS

STARTER

1 STARTER; 6808 38MT 12T STARTER

Service Requests:

10/14/2015 SERVICE REQUEST / 19: LOOSE / REPAIR
HARD START

Asset Work Order History 10183586

CSHOP-2015-3505

Comments: **R41 REVERSE ALARM NOT WORKING**

Date Opened 10-20-2015 Date Finished 10-30-2015 Meter 1 Reading: 135,321

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
ELECTRICAL
INSTRUMENTS-GAUGES-WARNING &
AIR CONDITIONING

1 ALARM; BACKUP ALARM ECCO 107 DEC
1 SHOCK; DOOR SHOCK

Service Requests:

10/20/2015 ALARMS / 18: LEAKING / REPAIR
REVERSE ALARM NOT WORKING

CSHOP-2015-3722

Comments: **R241 HARD STARTING ALL THE TIME**

Date Opened 11-2-2015 Date Finished 11-2-2015 Meter 1 Reading: 135,529

TASKS PERFORMED

NO PARTS USED

CRANKING SYSTEM

Service Requests:

11/02/2015 ENGINE / 19: LOOSE / REPAIR
HARD STARTING ALL THE TIME ON R241

CSHOP-2015-3909

Comments: **R41**

Date Opened 11-12-2015 Date Finished 12-15-2015 Meter 1 Reading: 138,801

TASKS PERFORMED

NO PARTS USED

FRONT TIRES

VENDOR? ELPEX TIRE TIRESOLES

CSHOP-2015-3953

Comments: **R41**

Date Opened 11-13-2015 Date Finished 11-25-2015 Meter 1 Reading: 136,999

TASKS PERFORMED

Q PARTS

AIR SYSTEM
INSTRUMENTS-GAUGES-WARNING &

1 LIGHT; AMBER QUAD LIGHT

Asset Work Order History 10183586

CSHOP-2015-4090

Comments: **R41 LEFT TIRE WORN AND EMER LIGHTS ON REAR OF BOX LEFT SIDE MALFUNCTIONING**
Date Opened 11-23-2015 Date Finished 12-14-2015 Meter 1 Reading: 138,717

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
COOLING SYSTEM
ENGINE AND ACCESSORIES
LIGHTING SYSTEM

6 FLUID; 50-50 EXTENDED LIFE COOLANT GAL

Service Requests:

11/21/2015 TIRES / 19: LOOSE / REPAIR
LEFT FRONT TIRE IS WORN TO WEAR INDICATOR BAR, INDICATING THAT IT NEEDS REPLACED. RIGHT FRONT IS WORN ALMOST TO INDICATOR BAR. BOTH FRONT TIRES ARE WEARING UNEVENLY, CUPPING ON THE OUTSIDE.

11/21/2015 LIGHTS / 19: LOOSE / REPAIR
EMERGENCY LIGHT ON REAR OF BOX ON LEFT SIDE IS MALFUNCTIONING. 1/4 OF THE LIGHT DOES NOT WORK.

CSHOP-2015-4677

Date Opened 12-28-2015 Date Finished 2-2-2016 Meter 1 Reading: 140,147

TASKS PERFORMED

Q PARTS

FUEL SYSTEM
COOLING SYSTEM
SERPENTINE BELT
INTAKE MANIFOLD

1 PUMP; 1882259C94 HIGH PRESSURE OIL PUMP
4 SLEEVE; FUEL LINE SLEEVE INT
1 VALVE; DRAIN VALVE RADIATOR NAV
1 BELT; BELT
1 BELT; BELT
1 TUBE; TUBE AIR INTAKE COLD SIDE

CSHOP-2016-1629

Date Opened 4-6-2016 Date Finished 4-6-2016 Meter 1 Reading: 145,858

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR CONDITIONING

Asset Work Order History 10183586

CSHOP-2016-1710

Comments: **R41**

Date Opened 4-11-2016

Date Finished 4-29-2016

Meter 1 Reading: 147,995

REAR TIRES WERE ORDERED ON 04/19

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
WIPERS-WASHER
FUEL SYSTEM
REAR TIRES

1 CAP; 431008 FUEL CAP

Service Requests:

04/11/2016 SERVICE REQUEST / 18: LEAKING / Q
WINDOW WASHER FLUID LEAKING

04/19/2016 TIRES / 19: WORN / REPLCED REAR TIRES
REAR OUTSIDE TIRES ARE AT THE WEAR BAR. THE REAR INSIDE TIRES ARE CLOSE TO THE WEAR BAR.

CSHOP-2016-1876

Comments: **R241**

Date Opened 4-21-2016

Date Finished 4-27-2016

Meter 1 Reading: 147,831

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FUEL SYSTEM
AIR CONDITIONING

Service Requests:

04/21/2016 SERVICE REQUEST / 19: LOOSE / Z
THE GAS CAP ON THE DRIVERS SIDE DOOR WILL NOT COME UNDONE.

CSHOP-2016-217

Comments: **C INSPECTION R241**

Date Opened 1-19-2016

Date Finished 1-25-2016

Meter 1 Reading: 139,688

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

30 MOTOR; 15W40 MOTOR OIL NON SYN
1 FILTER; FUEL FILTER 2008 HORTON
1 FILTER; 24316 WIX CAB A/C FILTER
1 FILTER; 57744XD OIL FILTER

Asset Work Order History 10183586

CSHOP-2016-2502

Comments: **R41**

Date Opened 5-24-2016

Date Finished

8-13-2016

Meter 1 Reading:

155,481

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
MIRRORS
AIR CONDITIONING

1 BRACKET; MIRROR BRACKET UPPER R/H
3 A/C; FREON LB

Service Requests:

05/24/2016

MIRROR / 12: BROKEN / REPAIR

OFFICER SIDE DOWN MIRROR IS LOOSE AND WILL NOT TIGHTEN TO THE PROPER POSITION . ALSO THE MIRROR IS CRACKED.

CSHOP-2016-259

Comments: **PM FOLLOW UPS**

Date Opened 1-19-2016

Date Finished

2-4-2016

Meter 1 Reading:

140,315

TASKS PERFORMED

Q PARTS

EQUIPMENT MOUNTING BRACKETS
SIDE COMPARTMENT BODY
OXYGEN SENSOR
ENGINE AND ACCESSORIES
PARK-CLEARANCE LIGHTS
LIGHTING SYSTEM
ELECTRICAL
TRANSMISSION
TIRES & WHEELS
REPAIR FROM PM - BELTS
STEERING
REPAIR FROM PM - DECALS/CLEANLINESS
AIR SYSTEM
AIR BAG SYSTEM
SIREN
AIR HORN
SAFTEY-EMERGENCY EQUIPMENT
DOOR WEATHER MOLDING
DOOR HINGE-PINS-BUSHINGS
CAB-INTERIOR ACCESSORIES
BLOWER RESISTER
A/C CONDENSER FAN
A/C FILTER SCREENS

1 MOUNT; LPVM-5 SM MOUNT
1 NEWPART; DRAWER LATCH
1 OXYGEN; OXM1757-01 OXYGEN WRENCH
1 HELMET HOOK
2 ORING; ORING
4 FLUID; SYN OIL BULK QTS
1 NEWPART; OIL COOLER ASSY
1 VALVE; VALVE COVER GASKET INT.
1 BULB; BULB
1 LIGHT; HEADLITE KIT WITH SEALER
1 COVER; OVAL AUTO EJECT COVER
6 FLUID; ALLISON TRANS FLUID GAL
1 FILTER; 29548988 TRANS FILTER ALLISON
2 FLUID; P/S FLUID
1 GASKET; PS RESV GASKET
1 FILTER; 2503221C1 FILTER POWER STEERING
1 VALVE; PURGE VALVE AD-IP-IS
1 DRYER; AD-IP DRIER
2 BRAKE; GY1R11216 AIR BAG INT.
1 VENT; BEZEL AC
1 FAN; FAN KIT DANHARD CONDENSER
3 FILTER; PANEL FILTER

CSHOP-2016-2596

Date Opened 5-31-2016

Date Finished

6-7-2016

Meter 1 Reading:

150,936

TASKS PERFORMED

Q PARTS

WINDSHIELD

2 WIPER; WIPER BLADE

Service Requests:

05/29/2016

BODY / 18: LEAKING / E

BROKEN RIGHT SIDE WINDSHIELD WIPER.

Asset Work Order History 10183586

CSHOP-2016-2950

Date Opened 6-20-2016 Date Finished 9-6-2016 Meter 1 Reading: 156,953

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
HEADLIGHTS LOW BEAM 2 BULB; H9007 BULB ASSY
CAB-INTERIOR ACCESSORIES 2 SWITCH; DOOR SWITCH
AIR CONDITIONING

Service Requests:

08/31/2016 LIGHTS / 18: LEAKING / REPAIR
VEHICLE DRIVER SIDE HEADLIGHT NOT WORKING, EMERGENCY LIGHTS FULLY FUNCTIONING

06/20/2016 ALARMS / 19: LOOSE / REPAIR
CAB OPEN DOOR LIGHTS ARE INTERMITTENT AND FLASH ON AND OFF WHILE DRIVING.

06/20/2016 STEERING / 19: LOOSE / REPAIR
STEERING WHEEL COVER IS LOOSE AND COMING OFF OF STEERING WHEEL.

CSHOP-2016-3080

Date Opened 6-27-2016 Date Finished 8-13-2016 Meter 1 Reading: 155,481

TASKS PERFORMED

Q PARTS

BODY EXTERIOR 3 A/C; FREON LB
AIR CONDITIONING

Service Requests:

06/25/2016 ALARMS / 49: CAN NOT DUPLICATE CONCERN / INSPECT
THE DOOR OPEN RED LIGHT FLASHES RANDOMLY.

CSHOP-2016-4487

Comments: R41

Date Opened 9-14-2016 Date Finished 10-25-2016 Meter 1 Reading: 160,623

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM 1 LIGHT; LIGHT AMBER QUADRA FLARE FEDERAL SIGNAL
AIR CONDITIONING 1 LIGHT; AMBER QUAD LIGHT

Service Requests:

09/12/2016 LIGHTS / 19: LOOSE / REPAIR
2 OF THE REAR LED WARNING LIGHTHEADS NEED REPLACEMENT (HALF THE LED DIODES ARE BURNT OUT ON THE 2 REAR-FACING AMBER FEDERAL SIGNAL QUADRAFLARE 9X7 LIGHTHEADS)

Asset Work Order History 10183586

CSHOP-2016-4828

Comments: **R-241 AC CAUSES O2 ALARM TO GO OFF??**

Date Opened 10-11-2016 Date Finished 10-31-2016 Meter 1 Reading: 160,913

TASKS PERFORMED

Q PARTS

BODY EXTERIOR
AIR CONDITIONING

1 HANDLE; HANDLE LH HORTON

Service Requests:

10/08/2016 A/C / 19: LOOSE / REPAIR
A/C ISSUE WHEN TRUCK AC IS PLUGGED IN AT STATION IT SETS OFF THE CO MONITOR IN THE PT COMPARTMENT.

CSHOP-2016-5002

Date Opened 10-20-2016 Date Finished 10-20-2016 Meter 1 Reading: 160,453

TASKS PERFORMED

NO PARTS USED

BODY EXTERIOR

CSHOP-2016-5055

Comments: **R-241 CHECK BATTERIES**

Date Opened 10-24-2016 Date Finished 11-17-2016 Meter 1 Reading: 160,913

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL

Service Requests:

10/24/2016 SERVICE REQUEST / 18: LEAKING / REPAIR
SERVICE REQUEST FOR R241, WHILE TRYING TO RESPOND TO A CALL LAST NIGHT THE RESCUE WOULD NOT START. PUT TRUCK OUT OF SERVICE AND PLACED THE BATTERY CHARGER ON BATTERIES. AFTER 20 MINUTES OF CHARGE ENGINE STARTED AND R241 PLACED BACK INTO SERVICE. R241 CURRENTLY PLUGGED INTO SHORELINE AND BATTERY CHARGER. BATTERIES AND RESCUE SHORELINE PLUG NEED TO BE EVALUATED. THANK YOU.

CSHOP-2016-5331

Date Opened 11-14-2016 Date Finished 12-5-2016 Meter 1 Reading: 161,032

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

30 MOTOR; 15W40 MOTOR OIL NON SYN
2 FILTER; 57744XD OIL FILTER
1 FILTER; 24316 WIX CAB A/C FILTER
1 FILTER; AIR FILTER
1 FILTER; FUEL FILTER 2008 HORTON

Asset Work Order History 10183586

CSHOP-2016-5378

Comments: **PM FOLLOW UPS**

Date Opened 11-17-2016 Date Finished 12-20-2016 Meter 1 Reading: 162,383

TASKS PERFORMED

Q PARTS

RADIO	2	FERRARA; NOZZLE KIT
WASHER PUMP	1	THERMOSTAT; 1842130C3 THERMOSTAT DT466
THERMOSTAT	1	WASHER; WASHER PUMP W/GROMMET
ENGINE AND ACCESSORIES	3	BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
BATTERY	3	BATTERY; BATTERY 950CCA HP-31D
STEERING COLUMN-SHAFT-BOOT	2	BRAKE; HD SHOE KIT 3/8 BEAM
REAR BRAKE PADS-SHOES	2	BRAKES; CLEVIS KIT
AIR SYSTEM	2	BRAKE; NT3030ELS-80 LONG CHAMBER 30/30
LIGHT BAR	2	BRAKE; REAR DRUMS 3757X 3647X
AIR CONDITIONING	1	LENS; LENS 4500 BAR CLEAR
	1	NEWPART; SUB ASSY BRACKET 4500SERIES
	2	NEWPART; LENS CLEAR 4500 ADVANTAGE
	2	NEWPART; DIVIDER 4500 SERIES

CSHOP-2016-5843

Comments: **R241**

Date Opened 12-14-2016 Date Finished 12-15-2016 Meter 1 Reading: 161,929

TASKS PERFORMED

NO PARTS USED

BRAKES

Service Requests:

12/14/2016 BRAKES / 19: LOOSE / REPAIR
BRAKE SQUEAKING ON R241 AND PULLING VERY HARD TO THE RIGHT.

CSHOP-2016-5882

Comments: **CHECK BELTS AND TIRES.**

Date Opened 12-16-2016 Date Finished 12-21-2016 Meter 1 Reading: 162,515

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM
INSTRUMENTS-GAUGES-WARNING &

Service Requests:

12/15/2016 SERVICE REQUEST / 19: LOOSE / REPAIR
SERVICE REQUEST

12/15/2016 TIRES / 19: LOOSE / REPAIR
BAD TIRES THE DRIVER SIDE, REAR, INNER DUAL TIRE IS BEGINNING TO WEAR ON THE INSIDE.

Asset Work Order History 10183586

CSHOP-2016-5988

Comments: **R-241 BACK UP LIGHT OUT**

Date Opened 12-27-2016 Date Finished 1-12-2017 Meter 1 Reading: 164,521

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM

2 BULB; BULB

CSHOP-2016-5989

Comments: **R-241 BACK UP LIGHT OUT NOTE BACK UP LIGHT WAS REPAIRED ON ANOTHER TICKET**

Date Opened 12-27-2016 Date Finished 1-3-2017 Meter 1 Reading: 163,627

TASKS PERFORMED

NO PARTS USED

AIR CONDITIONING

Service Requests:

12/26/2016 SERVICE REQUEST / 19: LOOSE / REPAIR
SERVICE REQUEST.....REAR PASSENGER BACK-UP LIGHT OUT

CSHOP-2016-901

Comments: **R41 BOULEVARD REPAIRED TIRE 1-22**

Date Opened 2-25-2016 Date Finished 3-9-2016 Meter 1 Reading: 143,671

TASKS PERFORMED

NO PARTS USED

FIRE APPARATUS
TIRES & WHEELS

Service Requests:

02/25/2016 SERVICE REQUEST / 19: LOOSE / REPAIR
AIR HORN NOT WORKING PROPERLY.

CSHOP-2017-1108

Date Opened 2-22-2017 Date Finished 2-22-2017 Meter 1 Reading: 168,388

TASKS PERFORMED

NO PARTS USED

FUEL SYSTEM

Asset Work Order History 10183586

CSHOP-2017-1368

Comments: **TIRES NOT DONE TRUCK WAS NOT IN STATION WHEN TIRE GUY WAS THERE**
Date Opened 3-6-2017 Date Finished 3-23-2017 Meter 1 Reading: 171,286

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM
REAR TIRES
HOSES-LINES & FITTINGS

Service Requests:

03/06/2017 RADIATOR / 18: LEAKING / REPAIR
RADIATOR IS LOW ON COOLANT

03/06/2017 TIRES / 18: LEAKING / REPAIR
BAD TIRES ON REAR OUTSIDE STILL BAD

03/06/2017 STEERING / 18: LEAKING / REPAIR
POWER STEERING FLUID LOW

03/17/2017 TIRES / 18: LEAKING / REPAIR
BAD TIRES

CSHOP-2017-138

Comments: **R-241 PLEASE CHECK OUT TIRE REPORTED AS HAVING A NAIL IN IT.**
Date Opened 1-6-2017 Date Finished 1-9-2017 Meter 1 Reading: 164,209

TASKS PERFORMED

NO PARTS USED

AIR CONDITIONING

Service Requests:

01/06/2017 TIRES / 19: LOOSE / REPAIR
NAIL FOUND IN LEFT REAR OUTER TIRE.

CSHOP-2017-1726

Date Opened 3-21-2017 Date Finished 4-25-2017 Meter 1 Reading: 174,224

TASKS PERFORMED

Q PARTS

AIR SYSTEM
AIR HORN

1	9IP; KIT-AIR HORN-GROVER
1	9IP; HORN AIR 24" GROVER P/N-1510
1	2FL; PEDESTAL HORN MOUNT

Service Requests:

03/20/2017 HAZARD / 18: LEAKING / REPAIR
10183586 (R-241) AIR HORN NOT WORKING PROPERLY. HORN IS VERY WEAK, POSSIBLY DUE TO AN AIR LEAK.

Asset Work Order History 10183586

CSHOP-2017-1751

Comments: **CALLED CALLAGHAN 3-22-17**

Date Opened 3-22-2017 Date Finished 3-28-2017 Meter 1 Reading: 171,739

TASKS PERFORMED

NO PARTS USED

REAR TIRES

VENDOR? DAN CALLAGHAN ENTERPRISES

Service Requests:

03/22/2017 TIRES / 44: WORN / EXCHANGE - NEW
BAD TIRES.... WEAR BAR IN ALL 4 REAR TIRES. REQUEST 4 NEW FIRESTONE FS560 255/70R 22.5

CSHOP-2017-1911

Date Opened 3-31-2017 Date Finished 4-10-2017 Meter 1 Reading: 172,981

TASKS PERFORMED

NO PARTS USED

CAB-INTERIOR ACCESSORIES

Service Requests:

03/30/2017 BODY / 18: LEAKING / REPAIR
RESCUE 241 DRIVER SCBA MOUNT IN SIDE COMPARTMENT BROKE OFF AND IS NOW LOOSE

CSHOP-2017-2011

Date Opened 4-5-2017 Date Finished 4-10-2017 Meter 1 Reading: 172,981

TASKS PERFORMED

NO PARTS USED

AIR CONDITIONING

Service Requests:

04/05/2017 ENGINE / 18: LEAKING / REPAIR
ENGINE- OIL LEAK,

CSHOP-2017-2045

Date Opened 4-7-2017 Date Finished 5-17-2017 Meter 1 Reading: 176,206

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM

2 1WL; 1WL

Service Requests:

04/07/2017 LIGHTS / 18: LEAKING / REPAIR
VEHICLE LIGHTS NOT WORKING. 3 OF THE LED FLASHING LIGHTS ON THE RESCUE ARE NOT WORKING PROPERLY:
2 OF THE REAR LED WARNING LIGHTHEADS (AMBER FEDERAL SIGNAL QUADRAFLARE 9X7 LIGHTS) ARE HALF BURNT
OUT, AND 1 RED LIGHT (FEDERAL SIGNAL QUADRAFLARE 9X7) ON THE DRIVERS SIDE IS PARTIALLY BURNT OUT.

Asset Work Order History 10183586

CSHOP-2017-2088

Comments: **LEAKING OIL AT TURBO**

Date Opened 4-10-2017 Date Finished 4-10-2017 Meter 1 Reading: 172,981

TASKS PERFORMED

Q PARTS

ENGINE AND ACCESSORIES

1 2IH; 2IH
1 2IH; TUBRO KIT MOUNT

CSHOP-2017-2094

Date Opened 4-10-2017 Date Finished 4-10-2017 Meter 1 Reading: 172,981

TASKS PERFORMED

Q PARTS

PM SERVICE B

1 2IH; FUEL FILTER
28 9OC; SYN 15W40
1 FILTER; AIR FILTER
1 9IP; OIL FILTER 06 INTERNATIONAL WPB

CSHOP-2017-2267

Date Opened 4-18-2017 Date Finished 4-21-2017 Meter 1 Reading: 173,960

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM
BODY EXTERIOR

1 LIGHT; 700 SER LED STOP LIGHT

Service Requests:

04/18/2017 DOOR / 18: LEAKING / REPAIR
REAR STAIR CHAIR COMPARTMENT ON R 241 LOCKING MECHANISM NOT WORKING CORRECTLY. DOOR WILL NOT LATCH CLOSED

04/18/2017 LIGHTS / 18: LEAKING / REPAIR
REAR PT. LOAD LIGHTS NOT WORKING ON R 241

CSHOP-2017-2269

Date Opened 4-18-2017 Date Finished 6-13-2017 Meter 1 Reading: 178,605

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
CAB-INTERIOR ACCESSORIES

Service Requests:

04/29/2017 A/C / 18: LEAKING / REPAIR
REAR PT. COMPARTMENT (AC UNIT UNDER CAPTAINS CHAIR) NEEDS NEW AC FILTER AND THE METAL GRATING/COVER FOR THE FITLER NEEDS TO BE REPLACED.

04/29/2017 LIGHTS / 18: LEAKING / REPAIR
2 REAR SCENE LIGHTS NEED TO BE REPLACED: THE 2 HALOGEN WHELEN 700 SERIES REAR SCENE LIGHTS (INSIDE THE WHELEN 4500 PLUS SERIES LIGHTBAR) ARE BURNT OUT AND NEED TO BE REPLACED.

Asset Work Order History 10183586

CSHOP-2017-2681

Date Opened 5-8-2017 Date Finished 5-8-2017 Meter 1 Reading: 175,409

TASKS PERFORMED

NO PARTS USED

DIAGNOSE ELECTRICAL

Service Requests:

05/07/2017 ENGINE / 18: LEAKING / REPAIR
ENGINE IS SLOW TO TURNOVER WHEN TRYING TO START IT (YOU NEED TO HOLD THE KEY FOR ~10 SECS BEFORE IT WILL TURN ON)

CSHOP-2017-2993

Date Opened 5-22-2017 Date Finished 5-22-2017 Meter 1 Reading: 176,659

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
BODY EXTERIOR
AIR CONDITIONING

Service Requests:

05/21/2017 SERVICE REQUEST / 18: LEAKING / REPAIR
PATIENT CAB AREA HAS A GLASS WINDOW THAT IS MISSING A BOLT AND IS SWINGING OPEN AND CLOSE AS THE VEHICLE IS MOVING.

CSHOP-2017-3848

Date Opened 6-29-2017 Date Finished 7-27-2017 Meter 1 Reading: 180,613

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

1 2IH; FUEL FILTER
1 FIL; NAPAGOLD OIL FILTER
1 FIL; NAPA CABIN AIR FILTER

Asset Work Order History 10183586

CSHOP-2017-3880

Date Opened 6-30-2017 Date Finished 8-18-2017 Meter 1 Reading: 181,258

TASKS PERFORMED

Q PARTS

SIDE COMPARTMENT BODY	1	9IP; C2-32-15 LATCH NON LOCKING
EXHAUST PIPE	2	2IH; CLAMP EXHUAST
REPAIR FROM PM - POWER STEERING	1	FIL; POWER STEERING FILTER
SHORELINE CHRAGER	2	9IP; COVER
TRANSMISSION	5	9IP; GAL CONTAINER TRANS FLUID
REPAIR FROM PM - BELTS	1	FIL; NAPA TRANS FILTER
SUSPENSION	1	9IP; BELT
AIR SYSTEM	1	NBH; V-RIBBED BELT
REPAIR FROM PM - BRAKES	2	2IH; SPRING AIR
AIR HORN	1	TWD; REP/CART
SEAT BELTS	1	TWD; AD-IP AD-IS PURGE VLV
AIR CONDITIONING	2	2TP; BRAKE SHOES
	2	MBI; GRIP/KIT
	2	TWD; BRAKE DRUM
	2	8GR; FILTER

CSHOP-2017-4300

Date Opened 7-24-2017 Date Finished 7-25-2017 Meter 1 Reading: 180,468

TASKS PERFORMED

Q PARTS

LIGHTING SYSTEM	2	LIT; BULB
-----------------	---	-----------

Service Requests:

07/24/2017 LIGHTS / 18: LEAKING / REPAIR
REAR LOADING LIGHTS OOS. DOES NOT TURN ON WHEN YOU PRESS BUTTON IN THE CONTROL PANEL OR WHEN YOU OPEN BACK DOORS.

CSHOP-2017-4559

Date Opened 8-7-2017 Date Finished 8-7-2017 Meter 1 Reading: 181,259

TASKS PERFORMED

NO PARTS USED

AIR CONDITIONING

CSHOP-2017-52

Comments: **R-241 BRAKES**

Date Opened 1-3-2017 Date Finished 1-3-2017 Meter 1 Reading: 163,627

TASKS PERFORMED

NO PARTS USED

BRAKES

Service Requests:

01/01/2017 BRAKES / 19: LOOSE / REPAIR
BRAKES ARE SQUEAKING AND IT TAKES A VERY LONG TIME TO COME TO AN ACTUAL STOP.

Asset Work Order History 10183586

CSHOP-2017-61

Comments: **R-241 SHARPS DRAWER TRACK IS BROKEN**

Date Opened 1-4-2017 Date Finished 1-30-2017 Meter 1 Reading: 166,141

TASKS PERFORMED

Q PARTS

CAB-INTERIOR ACCESSORIES
AIR CONDITIONING

2 9IP; 9IP

Service Requests:

01/03/2017 SERVICE REQUEST / 19: LOOSE / REPAIR
SERVICE REQUEST R241 BIOHAZARD DRAWER TRACK SYSTEM IS BROKEN.

CSHOP-2017-784

Date Opened 2-7-2017 Date Finished 2-13-2017 Meter 1 Reading: 167,485

COOLANT LEAK

TASKS PERFORMED

Q PARTS

ANTIFREEZE

1 9IP; WATER PUMP DT570
8 9OC; 9OC

RADIO-2017-369

Date Opened 6-30-2017 Date Finished 6-30-2017 Meter 1 Reading: 179,795

TASKS PERFORMED

NO PARTS USED

RADIO

Service Requests:

06/30/2017 RADIO / /
REMOVED RADIO 10188243 S/N:500CKM2666 AND INSTALLED RADIO 10204372 S/N:681CTH0767 INTO R241.