

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

#### Workorder: V26114

In Date: Close Date: 09/08/2009 Meter Reading:

1,425.00

Close Date: 09/24/2009 Problem?

b inspection set up new vehicle R45

| Task performed:   | Parts                                 | Quantity |
|---|---------------------------------------|----------|
| 1. Assemble new style SCBA air pack brkts; (uses two);                    | 101-124-000CRASH RESTRAINT STRAPS     | 1        |
| install one on L-q compt left door & the other on the back                | 14-7014HGR-1 HELMET HOOK              | 8        |
| eqpt mntng wall; also in L-1 compt.<br>2. Finished setting up new rescue. | 1878042C91FUEL FILTER 2008 HORTON     | 1        |
| 3. B-Inspection   | 5269LPVM-5 SM MOUNT                   | 6        |
| 4. Rem air horns for decals to be put on.                                 | 680-10LAMERICAN FLAG W UV CLEAR LEFT  | 1        |
| 5. Chk in new trucks.   | 680-10RAMERICAN FLAG W UV CLEAR RIGHT | 1        |
| 6. Finish B-Inspection.<br>7. installed decals.                           | KD-UN-5-SFUSE 6-SF BRACKET            | 2        |
| 8. installed drip edges.  | LPVM-7LG MOUNT                        | 1        |
| 9. Installed eqmpt holders in compts.                                     | UMVS162511STRAP                       | 3        |
|   | UMVS254411STRAP 46 IN                 | 1        |

#### Workorder: V26878

| In Date:<br>Close Date:    | 10/14/2009<br>11/05/2009 | Meter Reading: | 1,425.00 |
|----------------------------|--------------------------|----------------|----------|
| Problem?<br>install # plat | tes and remove s         | scba brakets   |          |

| Task performed:  | Parts   | Quantity |  |
|--|---|----------|--|
| <ol> <li>Mk up # plates &amp; install on trk; install all 005 stickers.</li> <li>Rem SCBA brkts from seats; box up for shipping.</li> <li>Set up new SCBA brkt for Spearon pack; isntall in trk;<br/>adj; C/O to send to 45.</li> <li>Btry dead charge up in lot. j</li> </ol> | 101-124-000CRASH RESTRAINT STRAPS<br>KD-UN-5-SFUSE 6-SF BRACKET | 1<br>1   |  |
| Workorder: V27195<br>In Date: 10/27/2009 Meter Reading:<br>Close Date: 11/05/2009<br>Problem?<br>Patient compartment rear door stopper. The screws are s   | 77.00<br>stripped and it is starting to fall off. r45           |          |  |
| Task performed:  | Parts   | Quantity |  |
| Rear door hold opens loose & msng screws; rep hold opens, new screws & threads. j  | NO PARTS USED   |          |  |



10188443

| Workorder:                          | V27325                                |  |   |                  |
|-------------------------------------|---------------------------------------|--|---|------------------|
| In Date:<br>Close Date:<br>Problem? | 11/02/2009<br>12/09/2009              | -  | 1,908.00  |                  |
| door opene                          | r battery peg bro                     | ken R45                                  |   |                  |
| Task perforr                        | ned:                                  |  | Parts   | Quantity         |
| 1. Replc door<br>2. Readj stret     | peg in btry tray.<br>cher latch.      | j  | NO PARTS USED   |                  |
| Workorder:                          | V27334                                |  |   |                  |
| In Date:<br>Close Date:<br>Problem? | 11/02/2009<br>12/09/2009              | Meter Reading:                           | 376.40  |                  |
|                                     | station placard fe                    | ell off, needs new tape to b             | e put back on. The old tape is not sticking anymore. r4 | 5                |
| Task perforr                        | ned:                                  |  | Parts   | Quantity         |
| 1. Replcd rea                       | r number plate ir<br>ep leaks where r |  | NO PARTS USED   |                  |
| Workorder:                          | V27384                                |  |   |                  |
| In Date:<br>Close Date:<br>Problem? | 11/03/2009<br>12/09/2009              | Meter Reading:                           | 376.40  |                  |
|                                     |                                       | ocked and is unable to be u              | unlocked by key. ( Driver side rear bottom compartmer   | nt ) r45 St 45   |
| Task perforr                        | ned:                                  |  | Parts   | Quantity         |
|                                     | er plate fell off; r<br>door not oper | einstalled.<br>ning; rep side door latch | NO PARTS USED   |                  |
| Workorder:                          | V29434                                |  |   |                  |
| In Date:<br>Close Date:<br>Problem? | 01/25/2010<br>02/11/2010              | Meter Reading:                           | 492.00  |                  |
|                                     | ner rubber strippi                    | ng between the cab and th                | ne Pt Compartment is coming apart. Needs to be fixed    | or replaced. R45 |
|                                     |                                       |  |   |                  |
| Task perforr                        | ned:                                  |  | Parts   | Quantity         |



10188443

| Workorder:                                       | V28483                              |  |             |                                   |          |
|--|-------------------------------------|--|-------------|-----------------------------------|----------|
| In Date:<br>Close Date:<br>Problem?              | 12/18/2009<br>02/22/2010            | Meter Reading:                               | 309         | 9.00                              |          |
| the weather                                      | r seal between tl                   | ne box and the cab                           | comes loose | and leaks badly when it rains R45 |          |
|  |                                     |  |             |                                   |          |
| Task perforr                                     |                                     |  |             | Parts                             | Quantity |
| Resealed sea                                     | al for second tim                   | e. j   |             | NO PARTS USED                     |          |
| Workorder:                                       | V28851                              |  |             |                                   |          |
| In Date:<br>Close Date:<br>Problem?              | 01/06/2010<br>02/22/2010            | Meter Reading:                               | 4,398       | 3.00                              |          |
|  | cement headligh                     | t for R45Ait was o                           | changed yes | sterday.                          |          |
| Task perforr                                     | ned:                                |  |             | Parts                             | Quantity |
| Air leak dia; f                                  | nd one at dryer                     | & rep. j                                     |             | NO PARTS USED                     |          |
| Workorder:                                       | V29739                              |  |             |                                   |          |
| In Date:<br>Close Date:<br>Problem?              | 02/05/2010<br>03/02/2010            | Meter Reading:                               | 5,822       | 2.00                              |          |
| flat repair R                                    | 45 (outside Age                     | ncy-Boulevard tire)                          |             |                                   |          |
| Task perforr                                     | ned:                                |  |             | Parts                             | Quantity |
| Flat repair R4                                   | 15 - Boulevard T                    | ire j  |             | NO PARTS USED                     |          |
| Vendor? E  | BOULEVARD TH                        | RE   |             |                                   |          |
| Workorder:                                       | V30256                              |  |             |                                   |          |
| In Date:<br>Close Date:<br>Problem?<br>SIREN INO | 02/25/2010<br>03/10/2010<br>P, R-45 | Meter Reading:                               | 6,579       | 0.00                              |          |
| Task perforr                                     | ned:                                |  |             | Parts                             | Quantity |
|  |                                     | ter console cvr; fn<br>connect; install cons |             | NO PARTS USED                     |          |



10188443

| Workorder:                          | V29609                           |   |            |   |                           |
|-------------------------------------|----------------------------------|---|------------|---|---------------------------|
| In Date:<br>Close Date:<br>Problem? | 02/02/2010<br>03/19/2010         | Meter Reading:                                    | 53         | 38.00   |                           |
| wheather s                          |                                  |   |            | keeps falling down letting rain into the cab abo<br>y make a loud popping sound R45 | ove radio equip. Also whe |
| Task perfor                         | med:                             |   |            | Parts   | Quantity                  |
| Reinstalled v                       | weather stripping                | in cab. j   |            | NO PARTS USED   |                           |
| Workorder:                          | V29665                           |   |            |   |                           |
| In Date:<br>Close Date:<br>Problem? | 02/03/2010<br>03/19/2010         | Meter Reading:                                    | 5,82       | 22.00   |                           |
| th weather                          | stripping is fallin              | g down again and ha                               | s a potint | ial to get the radio equipment wet. r45   |                           |
| Task perfor                         | med:                             |   |            | Parts   | Quantity                  |
| 1. Resealed<br>2. Rep cab 8         | top of roof where<br>& box seal. | e needed.<br>j                                    |            | NO PARTS USED   |                           |
| Workorder:                          | V30156                           |   |            |   |                           |
| In Date:<br>Close Date:<br>Problem? | 02/23/2010<br>03/26/2010         | Meter Reading:                                    | 6,57       | 79.00   |                           |
|                                     | OOF LEAK R45                     |   |            |   |                           |
| Task perfor                         | med:                             |   |            | Parts   | Quantity                  |
| Resealed top                        | p of roof; will mo               | nitor for leaks. j                                |            | NO PARTS USED   |                           |
| Workorder:                          | V30202                           |   |            |   |                           |
| In Date:<br>Close Date:<br>Problem? | 02/24/2010<br>03/26/2010         | Meter Reading:                                    | 6,57       | 79.00   |                           |
|                                     | arm Going Off 2)                 | Outside Lock Mechar                               | nism Malf  | unction 3) Privacy Windows Malfunction R45  |                           |
| Task perfor                         | med:                             |   |            | Parts   | Quantity                  |
| Hallmark; wa                        |                                  | no alarm going off;<br>nect privacy window m<br>j |            | NO PARTS USED   |                           |
| rep door swi                        | -                                | door open alarm goir                              | ng off;    |   |                           |
|                                     |                                  | p.<br>brkn wire on window.                        | j          |   |                           |



10188443

| Workorder:  | V30279                                      |                                     |   |                                      |
|---|---|-------------------------------------|---|--------------------------------------|
| In Date:<br>Close Date:<br>Problem?                 | 02/26/2010<br>03/26/2010                    | Meter Reading:                      | 6,579.00                                    |                                      |
| level 1 exha  | aust filter regene                          | eration required                    |   |                                      |
| Task perforr  | ned:  |                                     | Parts                                       | Quantity                             |
| Regen lite on                                       | ; performed reg                             | en & tested ok. j                   | NO PARTS USED                               |                                      |
| Workorder:  | V31092                                      |                                     |   |                                      |
| In Date:<br>Close Date:<br>Problem?<br>privacy wind | 03/28/2010<br>04/20/2010<br>dows stuck in b | Meter Reading:<br>lock position R45 | 3,062.00                                    |                                      |
| Task perforr  | ned:  |                                     | Parts                                       | Quantity                             |
| -   | em that Hallma                              | ark is working on window            |   |                                      |
| Workorder:  | V31094                                      |                                     |   |                                      |
| In Date:<br>Close Date:<br>Problem?                 | 03/28/2010<br>04/20/2010                    | Meter Reading:                      | 3,062.00                                    |                                      |
| open door s   | sensor for the co<br>the open door a        |                                     | door is broken and unable to drive vehicle  | safely at night due to flashing inte |
| Task perforr  | ned:  |                                     | Parts                                       | Quantity                             |
| Restuck the this time.                              | magnet on rea<br>j                          | r door for alarm; chk ok a          | NO PARTS USED                               |                                      |
| Workorder:  | V31095                                      |                                     |   |                                      |
| In Date:<br>Close Date:<br>Problem?                 | 03/28/2010<br>04/20/2010                    | Meter Reading:                      | 3,062.00                                    |                                      |
| med jdoor a<br>R45                                  | and iv supply jdo                           | oor will not stay closed whe        | n the brakes are applied jdoors come flying | g open could cause potential injur   |
| Task perform  | ned:  |                                     | Parts                                       | Quantity                             |
|   | dj slides/latch o<br>n; ok at this time     | n top of door; replc missing<br>. j | NO PARTS USED                               |                                      |



|   | l   |                          |  |          |
|---|---|--------------------------|--|----------|
| Workorder:  | V30580                                      |                          |  |          |
| In Date:<br>Close Date:<br>Problem?               | 03/09/2010<br>04/21/2010                    | Meter Reading:           | 6,917.00   |          |
| scba storaç                                       | ge door in pass                             | enger side(lieutenant)ii | n R45-B sticks and will not pop open when activate | ed.      |
| Task perfor                                       | med:  |                          | Parts  | Quantity |
| rep air bottle                                    | door. j                                     |                          | NO PARTS USED                                      |          |
| Workorder:  | V31618                                      |                          |  |          |
| In Date:<br>Close Date:<br>Problem?<br>Door alarm | 04/19/2010<br>04/29/2010<br>on (on-call) R4 | Meter Reading:           | 8,343.00   |          |
|   |   |                          |  |          |
| Task perform                                      | med:  |                          | Parts  | Quantity |
| Alarm gooing                                      | g off in cab; rep                           | rear door switch. j      | NO PARTS USED                                      |          |
| Workorder:  | V31524                                      |                          |  |          |
| In Date:<br>Close Date:<br>Problem?               | 04/14/2010<br>05/01/2010                    | Meter Reading:           | 8,343.00   |          |
| Install mou                                       | lding around so                             | reen r45                 |  |          |
| Task perfor                                       | med:  |                          | Parts  | Quantity |
| 1. installed m<br>2. Relocated                    | olding.<br>radio mic & sir                  | en mic. j                | NO PARTS USED                                      |          |



10188443

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

#### Workorder: V31141

| In Date:    | 03/30/2010 |
|-------------|------------|
| Close Date: | 05/03/2010 |
| Problem?    |            |

03/30/2010 Meter Reading: 05/03/2010 8,343.00

Douto

C inspection and repairs as needed R45

#### Task performed:

1. Svc trans filter & fluid first time 8000 miles.

2. Torque u-bolts for first time frnt/rear.

3. C-Inspection

4. Torque (4) lugs on each wheel; fnd 3 out 4 loose on back wheel torque; all lugs on reg axle.

5. Test/cln all btrys.

6. Street horn did not work; fnd both horns bad; R/R both horns; fnd horn on w/key off & btry swtch off; started look for wire problem.

7. Look thru cab wire harness & console for problem; fnd nothing; called Anthony at Hallmark; he said they had that problme in door lock ckt board in compt on plug 03 on wire 30 & 30A; rewired that plug; stopped horn all tog; Hallmark was going to send tech to help w/problem on Monday.

8. Scott for Hallmark & we went thru wires again; fnd problem in door lockpanel plug J3; Horton eng said ckt board will not work w/electo spike to put relay on wire 30 & 30A; SAcott installed relay & we fnd no power at horn; after tracers horn ckt, fnd bad plug so I replc plug; everything is ok. j

| Quantity |
|----------|
| 1        |
| 30       |
| 1        |
| 1        |
| 1        |
| 1        |
| 1        |
| 1        |
| 1        |
| 1        |
|          |

Our and its

| Workorder:                          | V32006                   |                |               |          |
|-------------------------------------|--------------------------|----------------|---------------|----------|
| In Date:<br>Close Date:             | 05/05/2010<br>06/04/2010 | Meter Reading: | 9,339.00      |          |
| Problem?<br>Siren T1 or             | n dial not workin        | g R45          |               |          |
| Task perfor                         | med:                     |                | Parts         | Quantity |
| Tested siren                        | & tested ok.             | j              | NO PARTS USED |          |
| Workorder:                          | V32491                   |                |               |          |
| In Date:<br>Close Date:<br>Problem? | 05/28/2010<br>06/28/2010 | Meter Reading: | 9,339.00      |          |
| MOVE AIR                            | PACKS R45                |                |               |          |
| Task perfor                         | med:                     |                | Parts         | Quantity |
| Relocated air                       | r packs in rear c        | ompt. j        | NO PARTS USED |          |



|                                     | V32606                   |   |          |   |            |
|-------------------------------------|--------------------------|---|----------|---|------------|
| In Date:<br>Close Date:<br>Problem? | 06/02/2010<br>06/29/2010 | Meter Reading:  | 9,339    | 9.00  |            |
|                                     | tcher latch is sti       | icking and not allowing th  | e streto | ther to be secured inside the rescue                      |            |
|                                     |                          |   |          |   |            |
| Task perforr                        | med:                     |   |          | Parts   | Quantity   |
| Adj stretcher                       | latch. j                 |   |          | NO PARTS USED   |            |
| Workorder:                          | V33309                   |   |          |   |            |
| In Date:<br>Close Date:<br>Problem? | 07/02/2010<br>08/02/2010 | Meter Reading:  | 12,07    | 5.00  |            |
| r45 bravo. v                        |                          | s put in reverse the backu<br>is put in reverse.R45                             | up cam   | is not automatically switching to backup cam and the beep | ing is not |
| Task perforr                        | ned:                     |   |          | Parts   | Quantity   |
| out when rev                        | erse is selected         | n does change frm inside<br>; no backup alarm; suspe<br>above rear comp; Hallma | ect      | NO PARTS USED   |            |
| Workorder:                          | V34526                   |   |          |   |            |
| In Date:<br>Close Date:             | 08/26/2010<br>09/02/2010 | Meter Reading:  | 12,867   | 7.00  |            |
| Problem?<br>ON CALL F               | PAITENT A/C 10           | )-7 R45   |          |   |            |
| Task perforr                        | ned:                     |   |          | Parts   | Quantity   |
| Pat compt A/<br>relay unit run      |                          | ans inop; jump sys; bypa  | SS       | NO PARTS USED   |            |
| Workorder:                          | V33622                   |   |          |   |            |
| In Date:<br>Close Date:<br>Problem? | 07/19/2010<br>09/08/2010 | Meter Reading:  | 12,07    | 5.00  |            |
|                                     | R45 (on-call)            |   |          |   |            |
| Task perforr                        | ned:                     |   |          | Parts   | Quantity   |
| -                                   | /C & tested; rep         | leaks. j  |          | NO PARTS USED   |            |



10188443

| Workorder:                          | V33867                   |   |            |                            |          |
|-------------------------------------|--------------------------|---|------------|----------------------------|----------|
| In Date:<br>Close Date:             | 07/28/2010<br>09/09/2010 | Meter Reading:  | 12,867     | 7.00                       |          |
| Problem?<br>Placard ho              | lders not install        | ed on R45B. please in   | stall. r45 |                            |          |
|                                     |                          |   |            |                            |          |
| Task perfor                         | med:                     |   |            | Parts                      | Quantity |
| Installed sigr                      | ns on rescue.            | j   |            | NO PARTS USED              |          |
| Workorder:                          | V34504                   |   |            |                            |          |
| In Date:<br>Close Date:<br>Problem? | 08/25/2010<br>09/10/2010 | Meter Reading:  | 12,867     | 7.00                       |          |
| replace all                         | tires boulevard          | r45   |            |                            |          |
| Task perfor                         | med:                     |   |            | Parts                      | Quantity |
| Replc all tire                      | s - Boulevard R          | 45 j  |            | NO PARTS USED              |          |
| Vendor?                             | BOULEVARD T              | ÎRE   |            |                            |          |
| Workorder:                          | V33871                   |   |            |                            |          |
| In Date:<br>Close Date:             | 07/29/2010<br>09/17/2010 | Meter Reading:  | 12,867     | 7.00                       |          |
| Problem?<br>WINDOW                  | 10-7 R45                 |   |            |                            |          |
| Task perfor                         | med:                     |   |            | Parts                      | Quantity |
| MODULE O<br>WORKING.<br>MOTOR RE    | N DRIVERS S<br>REMOVE DO | DRIVERS SIDE R<br>DE WINDOW STILL<br>OR PANEL NO PO<br>MOTOR CHECK WIN<br>PANEL | NOT<br>WER | 2505420C91L/H WINDOW MOTOR | 1        |



10188443

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

#### Workorder: V34919

| In Date:    |  |
|-------------|--|
| Close Date: |  |

09/13/2010 Meter Reading: 09/29/2010

14,484.00

Problem?

**B INSPECTION AND REPAIRS AS NEEDED R45** 

| Task performed:   | Parts  | Quantity               |
|---|--|------------------------|
| <ol> <li>B inspection</li> <li>I/rear entry lite inop, remove lite bar lens and replace<br/>bulb</li> <li>water in rear LED lites, remove lens and remove wate<br/>4.reverse lite and back up alarm inop, check horton<br/>multiplex system, trace wiring found bad connector in<br/>wiring harness above electrical compartment</li> <li>pat. compt. a/c fans inop, trace wiring found loose<br/>connector on wire strip in center console.</li> </ol> | 15W40BSYN OIL BULK QTS<br>1878042C91FUEL FILTER 2008 HORTON<br>2506656C124316 WIX CAB A/C FILTER<br>5774457744XD OIL FILTER<br>H50SN12BULB | 30<br>1<br>1<br>1<br>1 |
| Workorder: V33078   |  |                        |
| In Date: 06/23/2010 Meter Reading: 11,3<br>Close Date: 10/04/2010<br>Problem?<br>Rear pt compartment door on passenger side holder is b<br>compartment stretcher release handle is cracked but still  |  | vs from manufac.       |
| Task performed:   | Parts  | Quantity               |
| Rep hold open brkt for door. j  | NO PARTS USED  |                        |
| Workorder: V35365   |  |                        |
| In Date: 10/04/2010 Meter Reading: 14,7<br>Close Date: 10/04/2010<br>Problem?<br>ON CALL PAITENT A/C 10-7 R45   | 795.00   |                        |
| Task performed:   | Parts  | Quantity               |
| No pat A/C; traced problem; fnd conensor fans not<br>working; fnd bad connection on ckt brkr; rem wire<br>connector & installed new one & chkd opn of unit &<br>tested ok. j  | NO PARTS USED  |                        |



10188443

| Workorder:   | V30911                                  |                          |              |  |          |
|--|---|--------------------------|--------------|--|----------|
| In Date:<br>Close Date:<br>Problem?  | 03/21/2010<br>10/19/2010                | Meter Reading:           | 7,397        | 2.00                                   |          |
| Computer s   | creen is develo                         | oping cracks in the hing | jes R45      |  |          |
| Task perforr   | ned:                                    |                          |              | Parts                                  | Quantity |
| Completed  | j                                       |                          |              | NO PARTS USED                          |          |
| Workorder:   | V31362                                  |                          |              |  |          |
| In Date:<br>Close Date:<br>Problem?<br>install filter  | 04/08/2010<br>10/19/2010<br>for a/c r45 | Meter Reading:           | 8,343        | 3.00                                   |          |
|  |   |                          |              |  |          |
| Task perforr   | ned:                                    |                          |              | Parts                                  | Quantity |
| Completed  | j                                       |                          |              | NO PARTS USED                          |          |
| Workorder:   | V34435                                  |                          |              |  |          |
| In Date:<br>Close Date:<br>Problem?  | 08/22/2010<br>10/20/2010                | Meter Reading:           | 12,867       | 7.00                                   |          |
| The cord th  | at plug's into th                       | e rescue was frayed so   | o it was rei | moved because someone got shocked. R45 |          |
| Task perforr   | ned:                                    |                          |              | Parts                                  | Quantity |
| Rep 110 cord   | l. j                                    |                          |              | NO PARTS USED                          |          |
| Workorder:   | V34434                                  |                          |              |  |          |
| In Date:<br>Close Date:<br>Problem?  | 08/22/2010<br>10/21/2010                | Meter Reading:           | 12,867       |  |          |
| The compu  | ter stand broke                         | The screw that hold's    | the stand    | up snapped in half.                    |          |
| Task perforr   | ned:                                    |                          |              | Parts                                  | Quantity |
| <ol> <li>remove computer stand, install new bolts and reinstall computer stand. jab</li> </ol> |   |                          |              | NO PARTS USED                          |          |



10188443

| Workorder:                          | V36013                                      |                                      |            |   |            |
|-------------------------------------|---|--------------------------------------|------------|---|------------|
| In Date:<br>Close Date:<br>Problem? | 10/28/2010<br>10/28/2010                    | Meter Reading:                       | 15,397     | 7.00  |            |
|                                     | e mirror bracket,                           | , R-45                               |            |   |            |
| Task perfori                        | med:  |                                      |            | Parts   | Quantity   |
| 1. repair drive                     | er side upper bra                           | acket                                |            | NO PARTS USED   |            |
| Workorder:                          | V35521                                      |                                      |            |   |            |
| In Date:<br>Close Date:<br>Problem? | 10/08/2010<br>12/22/2010                    | Meter Reading:                       | 14,795     | 5.00  |            |
| tire pressur                        | e monitor alarm                             | sounding for no sigr                 | 1al R45    |   |            |
| Task perfor                         | med:  |                                      |            | Parts   | Quantity   |
| FOR NO SI                           |   | tor Alarm Soui<br>Reprogramed<br>J.W | ) TIRE     | NO PARTS USED   |            |
| Workorder:                          | V35602                                      |                                      |            |   |            |
| In Date:<br>Close Date:<br>Problem? | 10/12/2010<br>12/22/2010                    | Meter Reading:                       | 14,795     | 5.00  |            |
|                                     |   | N THE FRONT CAB                      | DOES NOT   | TURN ON. THERE IS NO AIR BLOWING AT ALL. R45              |            |
| Task perfori                        | med:  |                                      |            | Parts   | Quantity   |
| FOUNE                               | AB OF R45 DOE<br>) BAD CONNE(<br>TESTED OK. | SN'T RUN.<br>CTION AT THE SV<br>J.W. | VITCH.     | NO PARTS USED   |            |
| Workorder:                          | V37253                                      |                                      |            |   |            |
| In Date:<br>Close Date:<br>Problem? | 12/18/2010<br>01/05/2011                    | Meter Reading:                       | 18,361     | .00   |            |
| R451 - reve                         | erse lights and w<br>le horn. R451          | rarning tone will not o              | come on wh | en vehicle is in reverse siren will not change modes with | the manual |
| Task perfor                         | med:  |                                      |            | Parts   | Quantity   |
| Replcd siren                        | head & tested.                              | j                                    |            | NO PARTS USED   |            |



10188443

| Workorder:<br>In Date:<br>Close Date:<br>Problem?<br>Back up ala | 12/13/2010<br>01/11/2011               | Meter Reading:<br>lights inoperable. r45 | 17,886   | 5.00   |          |
|--|--|--|----------|--|----------|
| Task perforr   | ned:                                   |  |          | Parts  | Quantity |
| Fnd backup a<br>j  | alarm & backup                         | lights working at this tim               | ne.      | NO PARTS USED                                |          |
| Workorder:   | V37693                                 |  |          |  |          |
| In Date:<br>Close Date:<br>Problem?                              | 01/09/2011<br>02/08/2011               | Meter Reading:                           | 19,225   |  |          |
| reverse war  | ming tone not we                       | orking unable to change                  | Siren ii | odes passenger side seatbelt mount loose R45 |          |
| Task perforr   | ned:                                   |  |          | Parts  | Quantity |
| •  | n head & tested.<br>belt that was loos | se. j                                    |          | NO PARTS USED                                |          |
| Workorder:   | V38456                                 |  |          |  |          |
| In Date:<br>Close Date:<br>Problem?                              | 02/12/2011<br>02/24/2011               | Meter Reading:                           | 20,964   | 4.00   |          |
|  | the audible warr                       | ning sound and white rev                 | erse lig | hts are not operational.R45                  |          |
| Task perforr   | modi                                   |  |          | Parts  | Quantity |
| 1. Reset brkr  | for back-up alar                       | m.<br>brkt on stretcher. j               |          | NO PARTS USED                                | <u></u>  |
| Workorder:   | V38687                                 |  |          |  |          |
| In Date:<br>Close Date:<br>Problem?                              | 02/22/2011<br>02/25/2011               | Meter Reading:                           | 21,688   | 3.00   |          |
| ON CALL B  | BIOHAZARD DR.                          | AWER 10-7 R45                            |          |  |          |
| Task perforr   | ned:                                   |  |          | Parts  | Quantity |
| -  |  | h - latch screws strippe                 | ed;      | NO PARTS USED                                | ^        |



10188443

| Workorder:                                       | V38317                                   |  |         |   |          |
|--|--|--|---------|---|----------|
| In Date:<br>Close Date:<br>Problem?              | 02/07/2011<br>03/09/2011                 | Meter Reading:                                       | 1,234   | 4.00  |          |
| Back up lig                                      | hts not working a                        | again R45  |         |   |          |
| Task perforr                                     | med:                                     |  |         | Parts                                       | Quantity |
|  | for backup light<br>d small fitting le   | s & tested.<br>aking on rear tank. j                 |         | NO PARTS USED                               |          |
| Workorder:                                       | V38319                                   |  |         |   |          |
| In Date:<br>Close Date:<br>Problem?              | 02/07/2011<br>03/09/2011                 | Meter Reading:                                       | 1,234   | 4.00  |          |
| front headli                                     | ght out, no spar                         | es at station. r45                                   |         |   |          |
| Task perforr                                     | med:                                     |  |         | Parts                                       | Quantity |
| Replc headlig                                    |  |  |         | NO PARTS USED                               |          |
| Workorder:                                       | V38677                                   |  |         |   |          |
| In Date:<br>Close Date:<br>Problem?              | 02/22/2011<br>03/24/2011                 | Meter Reading:                                       | 21,688  | 3.00  |          |
|  | I O2 TANK REG                            | ULATOR BROKEN (M-                                    | TANK) I | PSI NEEDLE BROKEN UNABLE TO READ AMOUNT O2. |          |
| Took porfor                                      | madu                                     |  |         | Parts                                       | Quantity |
| Task perforn<br>Replcd O2 gu                     | uage & adj brkt.                         | i  |         | NO PARTS USED                               | Quantity |
|  |  | -  |         |   |          |
| Workorder:                                       | V39279                                   |  |         |   |          |
| In Date:<br>Close Date:<br>Problem?<br>ON CALL A | 03/18/2011<br>03/24/2011<br>VC 10-7 R 45 | Meter Reading:                                       | 22,64   | 5.00  |          |
|  |  |  |         |   |          |
| Task perform                                     |  |  |         | Parts                                       | Quantity |
|  |  | freon, vac sys - no vac lo<br>specs 27 degrees; suct |         | 16-3444CAP R134A - RED 5575/5557            | 1        |
|  | er valve was oi                          | lyp no Schrader on tru                               |         | 16-3445CAP-BLACK 134A 5579 KOOL TEMP        | 1        |



10188443

|  | V39289<br>03/19/2011<br>03/24/2011<br>ING COOLANT<br>ATH TRUCK. R4  | . LEVEL JUST ABOVE FI | 22,799.00<br>LL LINE. L | ARGE AMOUNT OF COOLANT ON GRO | OUND IN BAY |
|--|---|-----------------------|-------------------------|-------------------------------|-------------|
| Task performed:   Parts   Quantity   |   |                       |                         |                               |             |
| swapout unit.<br>2. Swap into  | <ol> <li>Coolant leak; fnd wtr pump leaking; travel to shop;<br/>swapout unit.</li> <li>Swap into SR - 10142534, miles 90676, hrs 6320.</li> <li>L/lower strobe activate on brake application.</li> </ol> |                       |                         |                               |             |
| Workorder:   |   |                       |                         |                               |             |
| In Date:<br>Close Date:<br>Problem?<br>water pump  | V39318<br>03/21/2011<br>03/24/2011<br>10-7 r 45   | Meter Reading: 2      | 22,799.00               |                               |             |
| Task perforr   | ned:  |                       | Part                    | <b>i</b>                      | Quantity    |
| R/R fluid & R/R wtr pump; reinstall belt; fill up coolant sys; chk for leak - ok; ready for svc. j |   |                       | nt 1842                 | 665C92WATER PUMP DT570        | 1           |



10188443

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

#### Workorder: V38818

In Date: 02/28/2011 Close Date:

Meter Reading: 03/29/2011

22,355.00

**Problem?** C INSPECTION AND REPAIRS AS NEEDED R 45

#### Task performed:

Chk tire monitor; looks to be ok; C/O rest of truck for completion - ok. j3/29/11

2. C-Service

- 3. Chk rear shoreline A/C; fnd displace not working; rep/replace (2) btrys; A/C working cold & display works at this time.
- 4. R/R dryer asy & purge valve.
- 5. Rep cable to wrench on OX sys.
- 6. Svc P/S unit & filter.
- 7. Tightene all heater hose clamps to valve.
- 8. Installed new wiper blades & add fluid.
- 9. Tighten grab rail on side of truck.
- 9a. Chk/replc R/rear scene light; working ok at this time. 10. T-shoot backup alarm & backup light; rep light socket on L/rear back door marker light.
- 11. C/O tires doran sys w/Jeff & myself to try to get to work; tried to reprogram; need to chk further.
- 12. Tried to program tire monitor sys.

13. Rep stair chair compt door switch - all brkn off; installed diff switch & magnet on rear door; drill/fit to work.

14. R/R both eng belts, A/C belt.

15. Torque all wheel/flange bolts on all wheels.

16. Chk volts at btry at 14.14 - good; dash guage reads wrong; hookup laptop to chk & set guagges w/Eddie.

j4/8/11

#### Workorder: V39431

| In Date:<br>Close Date:<br>Problem? | 03/25/2011<br>04/05/2011 | Meter Reading:        | 22,799 | 9.00          |          |
|-------------------------------------|--------------------------|-----------------------|--------|---------------|----------|
| back up ala                         | rm doesn't work          | on R451 (2) door R45  |        |               |          |
| Task perfori                        | ned:                     |                       |        | Parts         | Quantity |
| Traced out p                        | roblem; fnd blow         | n fuse; replc/tested. | j      | NO PARTS USED |          |

| Parts                                     | Quantity |
|---|----------|
| 065624AD-IP DRIER                         | 1        |
| 10006527WINDOW INVERTOR                   | 1        |
| 10048011712407 DOOR PROX SWITCH 2418/2407 | 1        |
| 1004803PROX MAGNET                        | 1        |
| 15W40BSYN OIL BULK QTS                    | 30       |
| 1847727C1BELT                             | 1        |
| 1878042C91FUEL FILTER 2008 HORTON         | 1        |
| 2506656C124316 WIX CAB A/C FILTER         | 1        |
| 2507061C1PS RESV GASKET                   | 1        |
| 404-100 VALVE CORE                        | 2        |
| 46870AIR FILTER                           | 1        |
| 5774457744XD OIL FILTER                   | 1        |
| 91-22WIPER BLADE                          | 2        |
| H35SN12BULB                               | 1        |
| K022105PURGE VALVE AD-IP-IS               | 1        |
| K060695BELT                               | 1        |
| VML/T1808D2503221C1 FILTER POWER STEERING | 1        |
|   |          |



10188443

| Workorder: V39432<br>In Date: 03/25/2011 Meter Reading: 22,7<br>Close Date: 04/05/2011<br>Problem?<br>rear side, lower right, flashing LED brake light not working   | 799.00<br>g on R451 (2) door R45  |          |
|--|-----------------------------------|----------|
| Task performed:  | Parts                             | Quantity |
| <ol> <li>Replcd rear led light.</li> <li>Rep rear stretcher latch. j</li> </ol>  | NO PARTS USED                     |          |
| Workorder: V39433  |                                   |          |
| In Date: 03/25/2011 Meter Reading: 22,7<br>Close Date: 04/05/2011<br>Problem?<br>vibration felt and noise heard on steering wheel possibly   | 799.00<br>from power steering R45 |          |
| Task performed:  | Parts                             | Quantity |
| <ol> <li>Road tested; fnd no vibration in wheel.</li> <li>A/C inop; tested sys &amp; tested ok. j</li> </ol>   | 9007H9007 BULB ASSY               | 1        |
| Workorder: V40533  |                                   |          |
| In Date: 05/10/2011 Meter Reading: 25,1<br>Close Date: 05/10/2011<br>Problem?<br>pat. a/c inop, R-451  | 16.00                             |          |
| Task performed:  | Parts                             | Quantity |
| 1.check pat. a/c, recover freon from a/c system, only pulled 12oz of freon, evacuate system and recharge. check for leaks, found valve on high side compressor leaking, tighten shradeer valve and recheck, ok | NO PARTS USED                     |          |
| Workorder: V40585  |                                   |          |
| In Date: 05/13/2011 Meter Reading: 25,1<br>Close Date: 05/16/2011<br>Problem?<br>Open door alarm   | 16.00                             |          |
| Task performed:  | Parts                             | Quantity |
| Low on freon; recycle/chk for leak; no leak; fnd, charge & operate; unit cooling to specs; stair chair comp alarm; temp repair door open alarm. j  | NO PARTS USED                     |          |



10188443

| Workorder:   | V/40007                  |                       |                    |                                    |                     |
|--|--------------------------|-----------------------|--------------------|------------------------------------|---------------------|
| In Date:<br>Close Date:<br>Problem?  | 05/27/2011<br>05/27/2011 | Meter Reading:        | 25,69 <sup>-</sup> | 1.00                               |                     |
|  |                          | GHT INTERMITTENT      | LY FLASH           | HES AND BEEPS WHILE DRIVING. FRONT | CAB A/C DOES NOT BL |
| Task perforr   | ned:                     |                       |                    | Parts                              | Quantity            |
| 1. check a/c, blower motor inop, trace wiring found connector not crimped properly, cut connector out and recrimp new connector, |                          |                       |                    | NO PARTS USED                      |                     |
| Sent unit to s   | hop for brake lig        | ht problem            |                    |                                    |                     |
| Workorder:   | V40931                   |                       |                    |                                    |                     |
| In Date:<br>Close Date:<br>Problem?  | 05/27/2011<br>06/08/2011 | Meter Reading:        | 25,69 <sup>-</sup> | 1.00                               |                     |
| Replace all  | 6 tires, normal v        | wear. at Sta 45.      |                    |                                    |                     |
| Took porform   | madu                     |                       |                    | Porto                              | Quantity            |
| Task perform   | 6) tires at Stn45        | - Boulevard j         |                    |                                    | Quantity            |
|  | BOULEVARD                | Joanovara             |                    | NO PARTS USED                      |                     |
| Workorder:   | V40586                   |                       |                    |                                    |                     |
| In Date:<br>Close Date:<br>Problem?  | 05/13/2011<br>06/09/2011 | Meter Reading:        | 25,116             | 5.00                               |                     |
|  | artment door ne          | eds to be readjusted. |                    |                                    |                     |
| Task perforr   | madu                     |                       |                    | Parts                              | Quantity            |
| -  | pors that were ha        | ard to open. j        |                    | NO PARTS USED                      |                     |
| Workorder:   | V40738                   |                       |                    |                                    |                     |
| In Date:<br>Close Date:<br>Problem?  | 05/19/2011<br>06/09/2011 | Meter Reading:        | 25,116             | 5.00                               |                     |
|  | iver side tire has       | a nail, Sta 45.       |                    |                                    |                     |
| Task perforr   | ned:                     |                       |                    | Parts                              | Quantity            |
| -  | tire; no leaks.          | j                     |                    |                                    | <b></b>             |



| Morkordoru   | V/40700                            |                           |            |  |          |
|--|------------------------------------|---------------------------|------------|--|----------|
| Workorder:<br>In Date:<br>Close Date:<br>Problem?  | V40782<br>05/23/2011<br>06/09/2011 | Meter Reading:            | 25,691     |  |          |
| the stretche                                       | er is leaning to the               | he rt side. the stretcher | locks into | place and works but the bed part is crooked. Sta 45. |          |
| Task perforr                                       | ned:                               |                           |            | Parts  | Quantity |
| •  | pare stretcher f                   | rom 42. j                 |            | NO PARTS USED  |          |
| Workorder:   | V41644                             |                           |            |  |          |
| In Date:<br>Close Date:<br>Problem?<br>No cab a/c. | 06/28/2011<br>07/05/2011           | Meter Reading:            | 26,846     | 6.00   |          |
| Task perform                                       | ned:                               |                           |            | Parts  | Quantity |
|  | LONER MOTO                         | OR STICKING ABLE<br>AN AK | то         | NO PARTS USED  |          |
| Workorder:   | V41945                             |                           |            |  |          |
| In Date:<br>Close Date:<br>Problem?                | 07/12/2011<br>07/12/2011           | Meter Reading:            | 27,761     | .00  |          |
|  | ning not cooling                   | in pt compartment. Sta    | 45.        |  |          |
| Task perforn                                       | ned:                               |                           |            | Parts  | Quantity |
| 1. check a/c e<br>did not find a                   |                                    | echarge a/c, check for le | eaks       | NO PARTS USED  |          |
| Workorder:   | V41602                             |                           |            |  |          |
| In Date:<br>Close Date:<br>Problem?                | 06/25/2011<br>07/19/2011           | Meter Reading:            | 26,846     | 5.00   |          |
| NEED 451   | PLATE ON SID                       | E OF RESCUE, BACK         | LEFT RE    | EVERSE LIGHT OUT ON R451                             |          |
| Task perform                                       | ned:                               |                           |            | Parts  | Quantity |
| REPARIED<br>CONNECTIO                              |                                    | REAR THAT HAD E           | BAD        | L PLACARD INSERTLARGE PLACARD INSERT CARD            | 2        |



| Workorder:<br>In Date:<br>Close Date:<br>Problem?<br>Blower mote | V41650<br>06/28/2011<br>07/19/2011<br>or intermitant. | Meter Reading:          | 26,846    | 5.00  |          |
|--|---|-------------------------|-----------|---|----------|
| Task perforr   | med:  |                         |           | Parts   | Quantity |
| installed blow   | ver motor & teste                                     | ed. j                   |           | 3626414C1BLOWER MOTOR RESISTOR<br>3674285C1BLOWER MOTOR | 1<br>1   |
| Workorder:   | V41689  |                         |           |   |          |
| In Date:<br>Close Date:<br>Problem?<br>need numb                 | 06/30/2011<br>07/19/2011<br>er plate, sta 45.         | Meter Reading:          | 26,846    | 5.00  |          |
| Task perforr   | ned:  |                         |           | Parts   | Quantity |
|  | R LOST NUME<br>REINSTALLED                            | BER PLATE AT ST<br>AK   | ATION     | 101-124-000CRASH RESTRAINT STRAPS                       | 2        |
| Workorder:   | V42002  |                         |           |   |          |
| In Date:<br>Close Date:<br>Problem?<br>rear L scene              | 07/13/2011<br>08/08/2011<br>e light inop R451         | Meter Reading:          | 27,761    | .00   |          |
| Task perforr   | ned:  |                         |           | Parts   | Quantity |
| -  | scene lights tah                                      | t were out              |           | NO PARTS USED   |          |
| repaired rear  | door latch taht v                                     | vas hard to open        |           |   |          |
| Workorder:   | V42840  |                         |           |   |          |
| In Date:<br>Close Date:<br>Problem?                              | 08/16/2011<br>08/16/2011<br>ar lens cracked,          | Meter Reading:<br>R-451 | 29,222    | 2.00  |          |
| Task perforr   | ned:  |                         |           | Parts   | Quantity |
| 1. travel to sta<br>back to s/sho                                | •   | ken rear lite bar lens  | s, travel | 68-3983813-30LENS 4500 BAR CLEAR                        |          |



10188443

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

#### Workorder: V42615

| In Date:    | 08/07/2011 |
|-------------|------------|
| Close Date: | 08/25/2011 |
| Problem?    |            |

28,866.00

R451 RIGHT HEADLAMP IS OUT. OFFICER SIDE. BULB 9004 IS NEEDED.

Meter Reading:

Task performed:

Parts

Quantity

replaced headlight

NO PARTS USED



10188443

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

#### Workorder: V42990

| In Date:<br>Close Date: | 08/23/2011<br>09/09/2011 | Meter Reading: | 29,659.00 |
|-------------------------|--------------------------|----------------|-----------|
| Problem?                |                          |                |           |
| B INSPEC                | TION AND REP             | AIRS R 45      |           |

Task performed:

Parts

Quantity



**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

#### **B INSPECTION**

DRIVER SINDOW REGULATION MOUNT BROKEN -REMOVE ASSEMBLY FROM DOOR - INSTALL NEW WINDOW REGULATION - TO CORRECT ELECTRICAL SHORT IN CONNECTION

AIR DRYER SERVICE - CHECK VALVE SERVICE - AIR DRYER VALVE INOP REMOVE ASSEMBLY, FILL WITH WATER, CLEAN AND REPLACE NEW CHECK VAVLE AND FILTER

AIR BAS RUBBING TO - ON SUPPORT FRAME-REMOVE AIR BAGS TO INSALL NEW ONES

ASSIST WITH DOOR AND COMPUTER TROUBLE SHOOTING

ASSIST WITH TESTS

REAR ENTRANCE LIGHT 10-7 REMOVE BLOWN BULB AND INSTALL NEW BULB

FRAME SUPPORTBRACKET BROKEN - REMOVE BROKEN PART INSTALL NEW ASSEMBLE FRAME SECURE ALL NUTS AND BOLTS

AIR LEAKES FOUND AIR LINE FITTINGS LEAKING REMOVE TO INSTALL NEW FITTINGS AND RETEST NO LEAKS FOUND

TIRE PSI MONITOR INOP REMOVE CHECK PSI TO AIR UP TO 110PSI INSTALL NEW LED PSI INDICATO

LEVELING VALVES NEED ADJUSTING REPLACE ONE DAMAGE ROD ADJUST AIR VALVE LEVELING POSTION

L2 AX HOLDER BROKEN REMOVE AND INSTALL NEW REPLACEMENT AX HOLDER

PATIENT COMPARTMENT A/C FILTER DIRTY AND VOER MISSING ---REPLACE FILTER AND INSTALL NEW HOLD DOWN SCREWS FOR COVER

HEATER LINE NEEDS SHUT OFF VALVE INSTALL NEW SHUT OFF VALVES IN HEATER LINE

BATTERY SWITCH LOOSE REMOVE FUEL TANK COVER/STEMS SECURE LOOSE BATTERY SWITCH TO CABLE REINSTALL FUEL TANK COVER STEP QA INSPECTION

| 065624AD-IP DRIER                   | 1  |
|-------------------------------------|----|
| 1878042C91FUEL FILTER 2008 HORTON   | 1  |
| 2506656C124316 WIX CAB A/C FILTER   | 1  |
| 3576482C1BEZEL DOOR HANDLE          | 1  |
| 3610441C98WINDOW REGULATOR ASSY L/H | 1  |
| 366555GTL6 13 X 19 FILTER           | 1  |
| 3856953C1BRACKET CROSSMEMBER        | 1  |
| 388863HOSE KIT                      | 2  |
| 5774457744XD OIL FILTER             | 1  |
| FREIGHTSHIPPING CHARGES             | 65 |
| GUI1R11216GY1R11216 AIR BAG INT.    | 2  |
| H50SN12BULB                         | 1  |
| K022105PURGE VALVE AD-IP-IS         | 1  |
| RWTG1234LED PRESSURE CAP            | 6  |



suspension as best as poss; levelling valves shid be replcd; no parts on truck or at shop; will be ok to use until we get the valves. (Hadley valves - cld not find any.

i

#### Palm Beach County Fire Rescue Fleet Maintenance Asset History 10188443

| Workorder:   | V42229                   |                         |  |  |          |  |  |
|--|--------------------------|-------------------------|--|--|----------|--|--|
| In Date:<br>Close Date:  | 07/22/2011<br>09/21/2011 | Meter Reading:          | 28,260   | 0.00   |          |  |  |
| Problem?<br>R-451 stretcher on 7/21/2011 came out of<br>service/evaluation. Sta 45.                                    |                          |                         | the load position on its own twice, during pt loading into the rescue. The stret |  |          |  |  |
| Task perfor  | med:                     |                         |  | Parts  | Quantity |  |  |
| swaped out s   | stretcher for rep        | pair                    |  | NO PARTS USED                                    |          |  |  |
| Workorder:   | V43804                   |                         |  |  |          |  |  |
| In Date:<br>Close Date:<br>Problem?  | 09/20/2011<br>09/21/2011 | Meter Reading:          | 30,162   | 2.00   |          |  |  |
|  | noxide warning           | going off.              |  |  |          |  |  |
| Task perfor  | med:                     |                         |  | Parts  | Quantity |  |  |
| carbon mono<br>shorline  | oxide warning (          | going off when plugged  | d into   | NO PARTS USED                                    |          |  |  |
| Workorder:   | V43805                   |                         |  |  |          |  |  |
| In Date:<br>Close Date:<br>Problem?  | 09/20/2011<br>09/21/2011 | Meter Reading:          | 30,162   | 2.00   |          |  |  |
|  | noxide warning           | , air suspension bag ov | verfull.   |  |          |  |  |
| Task perfor  | med:                     |                         |  | Parts  | Quantity |  |  |
|  |                          | ngsounding; btrys in c  |  | 82000878200433 39MT STARTER 6815                 | 1        |  |  |
| causing alarm to go off; chkd for exh leak; tightened all clamps; inspected; exh all ok; fnd cargon monoxide           |                          |                         |  | BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF | 3        |  |  |
| sensing btrys off casing; rplcd btrys; alarm not going off.<br>2. Air suspension ari bag over full: R/R empty L/R: adi |                          |                         | ng off.  | HP-31DBATTERY 950CCA HP-31D                      | 3        |  |  |



10188443

| Workorder:<br>In Date:<br>Close Date:<br>Problem?<br>leveling valv        | V43755<br>09/19/2011<br>09/28/2011<br>ves replace, co a                  | Meter Reading:<br>larm going off.   | 30,162                      | 2.00                     |          |
|---|--|---|-----------------------------|--------------------------|----------|
| Task perforn  | ned:   |   |                             | Parts                    | Quantity |
| Work w/SO34<br>much CO & it<br>test shoreline<br>rem charger<br>properly. | to find out how<br>is entering pat<br>charger; Charg<br>to test & reinst | & trim down rods to<br>v btrys are producing<br>compt; try & seal com<br>ger putting out high an<br>all charger; now wor<br>explain & price out n | too<br>pt &<br>nps;<br>king | 2505183C91LEVELING VALVE | 2        |
| Workorder:  | V43661   |   |                             |                          |          |
| In Date:<br>Close Date:<br><b>Problem?</b><br>Power door                  | 09/14/2011<br>10/03/2011<br>lock failure R45                             | Meter Reading:  | 29,987                      | 7.00                     |          |
| Task perforn  | ned:   |   |                             | Parts                    | Quantity |
| •   | door lock that wa  | as jammed   |                             | NO PARTS USED            |          |
| Workorder:  | V43134   |   |                             |                          |          |
| In Date:<br>Close Date:<br><b>Problem?</b><br>replace bod                 | 08/29/2011<br>10/04/2011<br>y mounts r 45                                | Meter Reading:  | 29,636                      | 5.00                     |          |
| Task perforn  | ned:   |   |                             | Parts                    | Quantity |
| body mount re<br>secondary air<br>body mounts                             | eplacement remo<br>tanks remove t  | ove stair chair primary<br>body mounts reinstall<br>primary and secondar<br>nd cables   | new                         | NO PARTS USED            |          |



10188443

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

| Workorder:  | V42730   |  |                         |   |          |
|---|--|--|-------------------------|---|----------|
| In Date:<br>Close Date:<br>Problem?<br>pat. a/c inop                                | 08/10/2011<br>10/06/2011<br>R-451                                    | Meter Reading:   | 28,866                  | 6.00  |          |
|   |  |  |                         |   |          |
| Task perform  | ned:   |  |                         | Parts                                       | Quantity |
| leaks found<br>leaking, (insta<br>both high sid                                     | high side and<br>alled new high<br>le and low side<br>recharge, chec | charge system check<br>low side schrader va<br>side a month ago) rep<br>scharder valves, evo<br>k for leaks seems ol | alves<br>blace<br>cuate | NO PARTS USED                               |          |
| Workorder:  | V44550   |  |                         |   |          |
| In Date:<br>Close Date:<br><b>Problem?</b><br>hallmark Re                           | 10/20/2011<br>01/17/2012<br>work doors. Sta                          | Meter Reading:<br>a 45.  | 30,283                  | 3.00  |          |
| Task perform  | ned:   |  |                         | Parts                                       | Quantity |
|   |  |  |                         | NO PARTS USED                               |          |
| Vendor? H   | IALL MARK FIR  | E APPAR  |                         |   |          |
| Workorder:  | V46443   |  |                         |   |          |
| In Date:<br>Close Date:<br>Problem?   | 01/09/2012<br>02/03/2012   | Meter Reading:   | 30,283                  | 3.00  |          |
|   | TION / CAB A/C   | 10-7 / POWER WIND  | OWS 10-                 | 7 R 451                                     |          |
| Task perform  | ned:   |  |                         | Parts                                       | Quantity |
| 1. A-Inspecti   |  |  |                         | 298435298435 VENT-AIR                       | 1        |
|   |  | op. Hook up a/c mac  |                         | 3542606C12611234C1 VENT ACTUATOR            | 1        |
| o.k. Hook up lap top code for fresh air door, R&R fresh air door actruter, cracked. |  |  |                         | 3544934C6DOOR POD 2 DOOR RESCUE DRIVER DOOR | 1        |

3. Tighten all comp door shock mounting brackets.

4. Check patient a/c, low on freon, check for leak, replaced o-rings on a/c lines going to condensor, recharge and check o.k.

5. Check for Air Leaks, replace fitting on air compressor governors.

|   | Quantity |
|---|----------|
| 298435298435 VENT-AIR                       | 1        |
| 3542606C12611234C1 VENT ACTUATOR            | 1        |
| 3544934C6DOOR POD 2 DOOR RESCUE DRIVER DOOR | 1        |
| 3544935C6DOOR POD L/H NAV                   | 1        |
| 516592MINI 10 AMP CB211-10 CIRCUIT BREAKER  | 1        |
| 91-22WIPER BLADE                            | 2        |
|   |          |



10188443

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

| Workorder:   | V47491                                |                                    |       |                                |          |
|--|---------------------------------------|------------------------------------|-------|--------------------------------|----------|
| In Date:<br>Close Date:<br>Problem?<br>WONT STA    | 02/22/2012<br>02/27/2012<br>ART R 451 | Meter Reading:                     | 32,47 | 6.00                           |          |
| Task perforr                                       | ned:                                  |                                    |       | Parts                          | Quantity |
|  |                                       | CALL TOW TRUCK G<br>136378 NO ICP. | GO TO | NO PARTS USED                  |          |
| Workorder:   | V47381                                |                                    |       |                                |          |
| In Date:<br>Close Date:<br>Problem?<br>Fuel system | 02/17/2012<br>02/28/2012<br>n repair. | Meter Reading:                     | 32,47 | 6.00                           |          |
| Task perforr                                       | ned:                                  |                                    |       | Parts                          | Quantity |
| 1. TOWN IN   | TO SHOP/WA                            | S TOWED TO SHOP/A                  | AIRED | 1873910C91FUEL STRAINER HORTON | 1        |

UP PARKING BRAKE AND TOWED INTO SHOP. 2. REPLACE HI PRESSURE OIL PUMP/NOT BUILDING PROPER PRESSURE/REPLACED HI PRESSURE OIL PUMP. 3. TRAVEL TO RECHTEIN TO PICK UP PUMP.

TRAVEL TO RECHTEIN TO PICK UP PUMP.
 HARD STARTING NEXT MORNING/AIR IN SYSTEM

TOOK FOR 1 HOUR ROAD TEST.

5. A-INSPECTION

6. ADJ TIRE PRESSURE/LEAKING DURING INSPECTION/REPLACED LEAKING VALVE CORES ADJUSTED TIRE PRESSURES AND INSTALLED EXTENTIONS FOR LED INDICATORS.

7. R/R LOWER WARNING LED INOP/WIRE PULLED OUT/REPAIRED WIRING.

8. METAL TRIM LOOSE BELOW CAB/SCREWS STRIPPED/REPAIRED THREADS AND TIGHTEN .

| Parts                                       | Quantity |
|---|----------|
| 1873910C91FUEL STRAINER HORTON              | 1        |
| 1878042C91FUEL FILTER 2008 HORTON           | 1        |
| 1882259C931882259C94 HIGH PRESSURE OIL PUMP | 1        |
| CORECORE CHARGE                             | 1        |



10188443

| Workorder:  | V47526   |  |                            |          |
|---|--|--|----------------------------|----------|
| In Date:<br>Close Date:<br>Problem?<br>vibration wh   | 02/23/2012<br>02/28/2012<br>en veh is driver   | Meter Reading:<br>over 55 mph, Sta 45  |                            |          |
|   |  |  |                            |          |
| Task perform  | ned:   |  | Parts                      | Quantity |
| pressure fittin<br>pressure fittir<br>pump, test dr<br>cam is bad, ha<br>at s/shop, veh   | ng on oil pump,<br>ng, replace o rin<br>ive vehicle, eng<br>ave crew swap o<br>nicle will be towe  | th oil comming out of hig<br>remove lift pump, remov<br>ngs reinstall fitting and li<br>ine runs rough seems lik<br>out into spare 2 door rescu<br>ed to dealer<br>lie O with repairs      | e<br>ft<br>.e              |          |
| Workorder:  | V47791   |  |                            |          |
| In Date:<br>Close Date:<br>Problem?<br>A INSPECT  | 03/06/2012<br>03/08/2012<br>TON R451   | Meter Reading:   | 33,000.00                  |          |
| Task perform  | ned:   |  | Parts                      | Quantity |
| REMOVE SE<br>FILL COOLAI<br>2. AIR SUPF<br>REMOVE AII<br>INSTALL ADA<br>3. DIAGNO<br>DRIVING REA<br>- ROAD TE<br>INSPECTION<br>OUT OF ALIA<br>REINSTALL<br>ROAD TEST<br>4. A-INSPEC | CTION CUT AI<br>NT SYSTEM AN<br>PLY FROM AIR<br>R FILTER HOU<br>APTER AND RE<br>SING EXCESS<br>AR - TEST DRIV<br>EST - STILL<br>I FOUND DIFF<br>GNMENT - WH<br>AFTER TOW -<br>- FAULT CORR<br>CTION. | FILTER TUBE BROKEN<br>SING TAP INTO TUBE<br>ASSEMBLE.<br>IVE VIBRATION WHOL<br>'E - INSTALL 4 REAR TIR<br>VIBRATE - FURTHE<br>'ERENTAL - UNIVERSA<br>EN DROVE SHAFT WA<br>CORRECT FAULT AN | E<br>E<br>R<br>L<br>S<br>D | 2        |
| Workorder:  |  |  |                            |          |
| In Date:<br>Close Date:<br>Problem?<br>A inspection   | 09/20/2011<br>03/09/2012<br>1.   | Meter Reading:   | 30,162.00                  |          |
| Task perform  | ned:   |  | Parts                      | Quantity |



10188443

| Workorder:                          | V47876                    |   |        |               |          |
|-------------------------------------|---------------------------|---|--------|---------------|----------|
| In Date:<br>Close Date:<br>Problem? | 03/10/2012<br>03/12/2012  | Meter Reading:                          | 33,000 | 0.00          |          |
| leaking mas                         | ssive amouts of c         | bil R45                                 |        |               |          |
|                                     |                           |   |        |               |          |
| Task perform                        | ned:                      |   |        | Parts         | Quantity |
| OIL LEAK<br>FITTING/SW              | /HI PRESSUI<br>APPED OUT. | RE OIL LINE (                           | OR     | NO PARTS USED |          |
| Workorder:                          | V46522                    |   |        |               |          |
| In Date:<br>Close Date:<br>Problem? | 01/11/2012<br>03/15/2012  | Meter Reading:                          | 30,283 | 3.00          |          |
| DOOR LOC                            | CKS 10-7                  |   |        |               |          |
|                                     |                           |   |        |               |          |
| Task perform                        | med:                      |   |        | Parts         | Quantity |
|                                     |                           | oor locks inop. Al<br>Entry power loc   |        | NO PARTS USED |          |
| 2. CONTIN                           |                           | HOOT LOCKS, FOU                         |        |               |          |
|                                     |                           | ES TOP, OF SIDE ENT<br>BOARD DRIVERS DO |        |               |          |
| ,                                   |                           | COMPARTMENT DO                          |        |               |          |
| LOCK ACTR                           |                           |   |        |               |          |
| 3. ASSIST W<br>PROBLDM.             | ITH TROUBLES              | HOOTING DOOR LOC                        | CK     |               |          |
| -                                   | C BOARD DISC              | ONNECT AND SECU                         | RE     |               |          |
| WIRING AND                          | 2 DOOR LOCK               | S.                                      |        |               |          |
|                                     | ON DOOR LOC               |   | то     |               |          |
|                                     |                           | PANEL, REMOVE<br>ATS. INSTALL PRIVA     |        |               |          |
|                                     | ID ASSEMBLE.              |   | 01     |               |          |
|                                     |                           | OOR LOCK ACTUAT                         |        |               |          |
|                                     | ACTUATOR HAI              | D TO DRILL NEW HOL                      | ES     |               |          |
| TO INSTALL                          | UF DATED FAR              | 1.                                      |        |               |          |



10188443

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

#### Workorder: V47998

| In Date:    | C |
|-------------|---|
| Close Date: | 0 |

03/15/2012 Meter Reading: 03/28/2012

33,000.00

#### **Problem? C INSPECTION R 451**

#### Task performed:

| Task performed:   | Parts   | Quantity                               |
|---|---|--|
| <ol> <li>C-INSPECTION.</li> <li>REPLACE U-JOINT STRAPS AND BOLTS REMOVE<br/>STRIPPED BOLTS.</li> <li>REMOVE ALL STRIP TAPE ON BOTH PATIENT<br/>DOORS AND INSTALL NEW.</li> <li>INSTALL ENGINE AIR FILTER.</li> <li>TORQUE U-BOLTS.</li> <li>INSTALL PATIENT A/C FILTERS.</li> <li>INSTALL WIPER BLADES.</li> <li>INSTALL BOTH ENGINE BELTS.</li> <li>REMOVE SQUAD BENCH SEND TO BE<br/>RECOVERED.</li> <li>REMOVE REAR WHEEL COVERS AND<br/>BRACKETS.</li> <li>INSTALL SQUAT BENCH SEAT - STRAIGHTEN<br/>SEAT FRAME.</li> </ol> | Parts         1501450007750USE 0775145         1847727C1BELT         1873217C2BELT TENSONER         1878042C91FUEL FILTER 2008 HORTON         2506656C124316 WIX CAB A/C FILTER         366555GTL6 13 X 19 FILTER         46870AIR FILTER         5774457744XD OIL FILTER         91-22WIPER BLADE         K060705BELT HORTON | Quantity 1 1 1 1 1 1 1 1 1 1 1 1 2 1 1 |
| 12. TIGHTEN ALL DOOR OPEN MOUNT SCREWS AND INSIDE DOOR PANELS.  |   |  |

13. Q.A. INSPECTION.

#### Workorder: V48498

In Date: 04/07/2012 Meter Reading: Close Date: 04/10/2012 **Problem?** 

A/C in the cab not working. Blowing hot air. R451

#### Task performed:

1. check cab a/c, comp. kicks on and off, remove freon, had the correct amount in it, refill system put 12v to comp. low side gauge was 90 psi and high side was 100 psi, remove air filter, remove fan belt, remove comp. and install new comp. check oil ok, install new o rings and gaskets, r&r drier, remove expansion valve, had to cut drier line to be able to remove bolt (stripped) on exp. valve. install new exp. valve and o rings, evecaute and charge system, went to remove high side a/c gauge line and schareder valve leaking, evecaute system and replace schareder valve recharge system recheck cab a/c cooling to 29 deg. check for leaks none found at this time.

| Parts                                 | Quantity |
|---------------------------------------|----------|
| 16-31498925 VALVE CORE                | 1        |
| 3611894C9103-0805 A/C COMPRESSOR 4347 | 1        |
| 3660853C22512331C1 EXP VALVE NAV      | 1        |
| 3670134C1ACCUMULATOR ASSY INT.        | 1        |



10188443

| workorder:   | V4/896   |                              |                                |  |                            |
|--|--|------------------------------|--------------------------------|--|----------------------------|
| In Date:<br>Close Date:<br>Problem?<br>Repair oil le   | 03/12/2012<br>04/20/2012<br>eak.                       | Meter Reading:               | 33,00                          | 0.00   |                            |
| Task perfori   | med:   |                              |                                | Parts  | Quantity                   |
| <ol> <li>REMOVE POWER STEERING RESERVOIR, FUEL<br/>FILTER HOUSING REPLACE HIGH PRESSURE OIL<br/>HOSE AND FITTINGS. HAD TO REMOVE TRANSFER<br/>PUMP TO REMOVE FITTINGS INSTALL NEW FITTING<br/>AND HOSE.</li> <li>R&amp;R FUEL FILTER HOUSING REPLACE FUEL<br/>TRANSFER PUMP.</li> <li>REMOVE HIGH PRESSURE OIL PUMP.</li> <li>INSTALL HIGH PRESSURE OIL PUMP TEST DRIVE<br/>AND CLEAN ENGINE.</li> </ol> |  |                              | e oil<br>Sfer<br>Iting<br>Fuel | 1812348C1FUEL LINE SLEEVE INT<br>1876108C922511369C91 FUEL PUMP LOW PRESS<br>1882259C931882259C94 HIGH PRESSURE OIL PUMP<br>1893940C911893940C93 OIL LINE HIGH PRESS PUMP<br>2500673C91KIT U-JOINT STRAP<br>3591094C1FUEL FITTING<br>CORECORE CHARGE | 3<br>1<br>1<br>1<br>1<br>1 |
| Workorder:<br>In Date:<br>Close Date:<br>Problem?<br>Head light of   | V49343<br>05/14/2012<br>05/25/2012<br>out on drivers s | Meter Reading:<br>ide. R-451 | 55,74                          | 9.00   |                            |
| Task perfori   | med:   |                              |                                | Parts  | Quantity                   |
| REPLACED   | HEAD LIGHT   |                              |                                | NO PARTS USED  |                            |
| Workorder:<br>In Date:<br>Close Date:<br>Problem?  | 05/16/2012<br>05/25/2012                               | Meter Reading:               | 35,96                          | 5.00   |                            |
| Task perform   | headleight out<br>med:                                 | 0111401                      |                                | Parts  | Quantity                   |
| REPLACED.  |  |                              |                                | 9007H9007 BULB ASSY  | 1                          |



10188443

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

#### Workorder: V51147

| In Date:    | 07/27/2012 |
|-------------|------------|
| Close Date: | 08/29/2012 |

Meter Reading:

#### **Problem?**

the CO monitor on the stretcher reading 36ppm after the shoreline being plugged in for a couple hours. Similar to the problem previously with the batteries off gassing into the patient compartment. R451

| Task performed:          | Parts         | Quantity |
|--------------------------|---------------|----------|
| repairs made on w/o 1578 | NO PARTS USED |          |

#### Workorder: V51578

In Date: 08/14/2012 Close Date: 08/29/2012 Problem? B INSPECTION R 45 Meter Reading:

39,925.00

#### Task performed:

1. B inspection

2. 110v outlets in pat. compt. inop. check wiring and circuit breakers, found inverter plug wiring terminals loose, tighten terminals

3. left rear entry door scene lite inop, remove lite bar lens and replace bulb

4. driver door panel falling off, secure door panel

5. compt. struts over work station, bench seat, and seat inop, replace struts

6. privacy windows inop, check inverter, remove window and check voltage, found windows inop, replace all 3 windows.

7. found upper radiator hose collapsed during inspection, drain coolant, replace upper hose and refill coolant, let run

8. replace rear brakes, brake hardware and drums, adjust brakes and road test

9. service air dryer

10. replace pat. compt. a/c filters

11. pat. compt, a/c blows cool, found low on freon, top off and check for leaks, found hose crimp on high side of compressor leaking, and low side schrader valve leaking, evecaute system install new crimp and scharder valve recharge system and recheck for leaks.

12. r/side cab step entry lite inop, replace lite

- 13. I/side cab step entry lite inop, replace lite
- 14. hook up laptop and update International modules

15. windshield washer tank leaking, remove tank found rubber groment leaking, reseal groment and reintall tank, refill fill with fluid

| Parts                                 | Quantity |
|---------------------------------------|----------|
| 065624AD-IP DRIER                     | 1        |
| 10007599WINDOW HORTON                 | 3        |
| 15-40B15W40 MOTOR OIL NON SYN         | 30       |
| 1501450007750USE 0775145              | 4        |
| 1878042C91FUEL FILTER 2008 HORTON     | 1        |
| 2506656C124316 WIX CAB A/C FILTER     | 1        |
| 3610318C2RADIATOR HOSE                | 1        |
| 3757REAR DRUMS 3757X 3647X            | 2        |
| 4DA2545W LAMP                         | 1        |
| 5774457744XD OIL FILTER               | 1        |
| 607141-05USE 61H01 COPMPARTMENT LIGHT | 2        |
| ANTICOOLANT ANTIFREEZE GAL            | 4        |
| HLD3999GSS1715UV 30LB STRUT GAS       | 6        |
| K022105PURGE VALVE AD-IP-IS           | 1        |
| XK4034707QPMHD SHOE KIT 3/8 BEAM      | 2        |
|                                       |          |



10188443

| Workorder:<br>In Date:<br>Close Date:<br>Problem?<br>Rear scene | V51656<br>08/16/2012<br>08/29/2012<br>light on left side | Meter Reading:   |   |                                |
|---|--|--|---|--------------------------------|
| Task perforr  | ned:   |  | Parts   | Quantity                       |
| repairs made  | on w/o 51578   |  | NO PARTS USED                                       |                                |
| Workorder:  | V51657   |  |   |                                |
| In Date:<br>Close Date:<br>Problem?<br>Front left tir           | 08/16/2012<br>08/29/2012<br>e is wearing une             | Meter Reading:   | than all the other tires on the vehicle. May need t | o be replaced soon.            |
|   |  |  |   |                                |
| Task perforr<br>repairs made                                    | <b>ned:</b><br>on w/o 51578                              |  | Parts   | Quantity                       |
| Workorder:  | V51969   |  |   |                                |
| In Date:<br>Close Date:<br>Problem?<br>REPLACE                  | 08/29/2012<br>09/13/2012<br>FRONT TIRES                  | Meter Reading:   | 39,815.00   |                                |
| Task perforr  | ned:   |  | Parts   | Quantity                       |
| REPLACE FF  | RT TIRES   |  | NO PARTS USED                                       |                                |
| Vendor? B   | OULEVARD TIF   | RE   |   |                                |
|   | 07/30/2012<br>09/14/2012<br>eaking oil. it was           | Meter Reading:<br>s passed down to me th<br>started to leak again. | at r451 was taken over to the shop a few days ac    | go and was fixed. the offgoing |
| Task perforr  | ned:   |  | Parts   | Quantity                       |
|   | T OIL LEAK FO<br>ND TESTED.                              | OUND SENDER LEAKI  | NG 1839415C910IL PRESSURE SENSOR                    | 1                              |



10188443

| Workorder:  | V51545                                      |  |                                     |          |
|---|---|--|-------------------------------------|----------|
| In Date:<br>Close Date:<br>Problem?               | 08/12/2012<br>09/17/2012<br>nsor is broken. | Meter Reading:   |                                     |          |
|   | nsor is broken.                             |  |                                     |          |
| Task perforr                                      | ned:  |  | Parts                               | Quantity |
| -   |   | ER AND CALABRATED OZ<br>CK DOOR THAT WAS HARD  | 10004858O2 SENSOR HORTON 0-3000     | 1        |
| Workorder:  | V51609                                      |  |                                     |          |
| In Date:<br>Close Date:<br>Problem?               | 08/15/2012<br>09/17/2012                    | Meter Reading:   |                                     |          |
|   | cab not workir                              | ng, no air coming out. R451  |                                     |          |
| Task perforr                                      | ned:  |  | Parts                               | Quantity |
|   | OUT PROB                                    |  | 3536182C1RESET BREAKERS NEW HORTONS | 2        |
| Workorder:  | V52426                                      |  |                                     |          |
| In Date:<br>Close Date:<br>Problem?               | 09/17/2012<br>09/19/2012                    | Meter Reading: 40,70   | 03.00                               |          |
| BLOWER N  | NOTOR NOT V                                 | VORKING R 451  |                                     |          |
| Task perforr                                      | med:  |  | Parts                               | Quantity |
| BAD/CHKD F<br>TESTED FO<br>BLOWER DI<br>SPEED ORD | FOR CASE TIC<br>R HIGH CUR<br>RAWING EXC    | B/ A/C BLOWER GOING<br>GHTENED ALL BUSS BARS<br>RENT DRAW FOUND A/C<br>CESSIVE AMPS ON HIGH<br>MOTOR, ROAD TECT WILL | NO PARTS USED                       |          |
| INSTALL.  | V50407                                      |  |                                     |          |
| In Date:<br>Close Date:<br>Problem?               | 09/17/2012<br>09/25/2012                    | Meter Reading: 40,70   | 03.00                               |          |
|   | OWER BURNI                                  | NG SMELL IN CAB R 451  |                                     |          |
| Task perforr                                      | ned:  |  | Parts                               | Quantity |
| -   | NEW BREAKE                                  | ER AND REPAIRED WIRES  | 3536182C1RESET BREAKERS NEW HORTONS | 3        |



10188443

| Workorder:  | V53153  |   |   |            |
|---|---|---|---|------------|
| In Date:<br>Close Date:<br>Problem?   | 10/17/2012<br>10/17/2012  | Meter Reading:  |   |            |
| R451 A/C II   | n the PT compa  | rtment is not working   |   |            |
| Task perfori  | ned:  |   | Parts   | Quantity   |
| only had 10 or<br>scharder valv<br>and vacunm<br>ok cools to 29<br>2. while perfo | oz in system, fill<br>ve on high side f<br>system down an<br>9deg.<br>orming a/c repair | ws cool, evecaute system,<br>and check for leaks found<br>fitting leaking replace valve<br>d recharge, check for leaks,<br>, head air leak at foot valve,<br>valve recheck ok | NO PARTS USED   |            |
| Workorder:  | V53085  |   |   |            |
| In Date:<br>Close Date:<br>Problem?   | 10/15/2012<br>11/09/2012  | Meter Reading:  |   |            |
| noise comir   | ng from transpor  | t compartment. unkn origin R4   | .5  |            |
| Task perfori  | med:  |   | Parts   | Quantity   |
| ROAD TEST   | ED FOUND NO   | NOISE IN REAR.  | NO PARTS USED   |            |
| Workorder:  | V53401  |   |   |            |
| In Date:<br>Close Date:<br>Problem?   | 10/30/2012<br>11/16/2012  | Meter Reading:  |   |            |
| Issue has b   |   |   | the rescue dumps air to below 60 psi, while parked with the<br>ned out at the start of each call R 45 | engine off |
| Task perfori  | med:  |   | Parts   | Quantity   |
| CHECKED F   |   | , FOUND AND REPAIRED  | NO PARTS USED   |            |
| Workorder:  | V53737  |   |   |            |
| In Date:<br>Close Date:<br>Problem?   | 11/13/2012<br>12/14/2012  | Meter Reading:  |   |            |
|   | 1 air dump leakii   | ng! Air bags are compleatly em  | npty when the rescue is parked and the ignition is off.   |            |
| Task perfori  | med:  |   | Parts   | Quantity   |
| TRACED OU   | IT AIR LEAK AN  | ID REPAIRED.  | NO PARTS USED   |            |



10188443

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

| W | ork | ord | er: | V | 54 | 41 | 4 |
|---|-----|-----|-----|---|----|----|---|
|   |     |     |     |   |    |    |   |

| In Date:    | 12/13/2012 | Meter Reading: |
|-------------|------------|----------------|
| Close Date: | 01/14/2013 |                |

**Problem?** 

Air leak to rear of rescue is getting worse. The unit is bottoming out all the way until they get to the call. The suspension and rear i taking a beating. Needs to be fixed. R45

| Task performed:  | Parts   | Quantity |
|--|---|----------|
| TRACED OUT AIR LEAKS AND REPAIRED.   | NO PARTS USED                                     |          |
| Workorder: V55304  |   |          |
| In Date: 01/25/2013 Meter Reading:<br>Close Date: 02/05/2013<br>Problem?<br>Replace rear tires @ south shop                | 46,613.00   |          |
| Task performed:  | Parts   | Quantity |
| REPLACE REAR TIRES @ SOUTH SHOP.   | NO PARTS USED                                     |          |
| Vendor? BOULEVARD TIRE CENTE   |   |          |
| Workorder: V54588  |   |          |
| In Date: 12/24/2012 Meter Reading:<br>Close Date: 02/13/2013<br>Problem?<br>the regulator on the onboard o2 is not working | g properly. the sensor is working correctly. r451 |          |
| Task performed:  | Parts   | Quantity |
| see w/o#54954 for repairs  | NO PARTS USED                                     |          |
| Workorder: V54914  |   |          |
| In Date: 01/07/2013 Meter Reading:<br>Close Date: 02/13/2013<br>Problem?<br>Rescue unit has a leak in the air system and t | the back-up camera does not function r45.         |          |
| Task performed:  | Parts   | Quantity |
| see w/o#54954 for repairs  |   |          |



10188443

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

#### Workorder: V54954

 In Date:
 01/09/2013

 Close Date:
 02/13/2013

 Problem?
 C INSPECTION R45

Meter Reading:

46,777.00

Task performed:

Parts

Quantity



**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

#### 1. C insp.

2. found air leak overnight, trace out air leak. found muplitible air leaks. replace cab air ride level valve, replace governor, repalce air fitting in frame rail to drier, replace air tank bleeder, recheck for air leaks no more found holds air overnight

3. back up camera inop, replace monitor in cab w/wiring harness, test, works ok but rear camara had water in it. (blurry) replace rear camara

4. onboard o2 reg. broken, replace gauge

5. spotlight on cab roof inop, check light. replace spotlight assy.

6. driver side door panel broken and falling off, replace complete door assy. remove and install red LED lite on new door panel

7. replace wiper blades

8. cab interior light above back up camara falling down, resecure lite to headliner

9, r/side rear rubber bumper falling off, rescure to rear step

10. replace non skid tape on rear and side entry door's

11. replace pat. a/c filters

12. I/side rear comt. door back up lite inop, remove and replace bulb

13. found 6 ground lites inop. or half lite, replace 6 ground lites

14. officer seat belt, female side loose on floor, tighten bolts for all floor attached seat belts

15. radio speaker fell off of mount, install new screws to hold speaker

16. found low on coolant, pressure test, remove air filter housing, replace hose clamps on cross over hose below turbo. tighten hose clamps below egr cooler on l/side, remove cooler cross over pipe and solnoid and check for coolant in system none found. pressure test and recheck for leaks with engine running on high idle, found another hose clamp leaking on r/side under cooler, tighten clamps and recheck for leaks. no more found

17. update ECM for latest version

18. service air drier

19. pat. 110volt a/c inop, check freon, found low, check for leaks found line leaking at compressor, install new fitting. recharge system and recheck for leaks, replace battery's in thermostat

20. replace front shocks

21. road test vehicle

| 04320014DOCK BUMPER HORTON            | 1  |
|---------------------------------------|----|
| 065624AD-IP DRIER                     | 2  |
| 10010552MONITOR VOYAGER 10008120      | 1  |
| 15-40B15W40 MOTOR OIL NON SYN         | 30 |
| 1501450007750USE 0775145              | 1  |
| 1878042C91FUEL FILTER 2008 HORTON     | 1  |
| 2506656C124316 WIX CAB A/C FILTER     | 1  |
| 2507385C1CAB AIR LEVEL VALVE INT      | 1  |
| 284358GOVERNOR D-2                    | 1  |
| 3578105C2FRONT SHOCKS                 | 2  |
| 3612550C92DOOR PANEL                  | 1  |
| 4DA2545W LAMP                         | 1  |
| 5774457744XD OIL FILTER               | 1  |
| 607141-05USE 61H01 COPMPARTMENT LIGHT | 6  |
| 91-22WIPER BLADE                      | 2  |
| K022105PURGE VALVE AD-IP-IS           | 1  |
| MG-C23SPMGC23 GAUGE                   | 1  |
| SPT6008146SL LIGHT-REMOTE SPOT        | 1  |
| VCCS150VOYAGER CAMERA                 | 1  |



10188443

| Workorder:<br>In Date:                           | 03/04/2013                 | Meter Reading:  | 48,371 | .00           |          |
|--|----------------------------|---|--------|---------------|----------|
| Close Date:<br>Problem?<br>ON CALL V             | 03/04/2013<br>VONT START R | 451   |        |               |          |
| Task perforr                                     | ned:                       |   |        | Parts         | Quantity |
| RECHARGEI<br>ROAD TEST                           |                            | AND RAN TRUCK AN                                      | ND     | NO PARTS USED |          |
| Workorder:                                       | V56638                     |   |        |               |          |
| In Date:<br>Close Date:<br><b>Problem?</b>       | 03/25/2013<br>03/25/2013   | Meter Reading:  |        |               |          |
|  | PT cab is not blo          | wing cold R45   |        |               |          |
| Task perforr                                     | ned:                       |   |        | Parts         | Quantity |
| 1. check pat.                                    | a/c, found low o           | n freon top off unit, run a<br>one found at this time | a/c    | NO PARTS USED |          |
| Workorder:                                       | V47380                     |   |        |               |          |
| In Date:<br>Close Date:<br>Problem?<br>no start. | 02/17/2012<br>04/04/2013   | Meter Reading:  | 32,476 | 3.00          |          |
| Task perforr                                     | med:                       |   |        | Parts         | Quantity |
| •  | ORDER v47491.              |   |        | NO PARTS USED |          |
| Workorder:                                       | V54965                     |   |        |               |          |
| In Date:<br>Close Date:<br>Problem?              | 01/09/2013<br>04/18/2013   | Meter Reading:  |        |               |          |
|  | ılb is out. Needs          | replacement.  |        |               |          |
| Task perforr                                     | ned:                       |   |        | Parts         | Quantity |
| Periori  |                            |   |        | NO PARTS USED |          |



10188443

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

é

| Workorder:  | V57525                                       |   |            |   |                |
|---|--|---|------------|---|----------------|
| In Date:<br>Close Date:<br>Problem?<br>hard startin       | 05/06/2013<br>05/06/2013<br>g, R-451         | Meter Reading:  | 57,76      | 5.00  |                |
| Task perforr  | ned:   |   |            | Parts   | Quantity       |
| load test batt  | tery's, found 2 b                            | emove battery cables<br>attery's failed test. rep<br>g system all ok, starts o            | blace      | BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER<br>HP-31DBATTERY 950CCA HP-31D | 4<br>4         |
| Workorder:  | V57573                                       |   |            |   |                |
| In Date:<br>Close Date:<br>Problem?                       | 05/08/2013<br>05/09/2013                     | Meter Reading:  |            |   |                |
|   |  | placed recently, vehicle<br>proper starting procedu                                       |            | mely sluggish and difficult to start. Took numerous attempts<br>5               | ; to start for |
| Task perform  | ned:   |   |            | Parts   | Quantity       |
| battery charg<br>starter. due to                          | ger,all ok. remo                             | recheck batery's, c<br>ve starter. found wate<br>and flooding in Batt-4 a<br>er starts ok | er in      | 82000056808 38MT 12T STARTER<br>HEV-13964DRAIN PAN                              | 1<br>1         |
| Workorder:  | V57213                                       |   |            |   |                |
| In Date:<br>Close Date:<br><b>Problem?</b><br>A/C leaking | 04/23/2013<br>05/29/2013<br>inside right gea | Meter Reading:  | officer si | de.   |                |
| Task perforr  | med:   |   |            | Parts   | Quantity       |
| REPAIRED C  | ON ANOTHER V                                 | VO#.  |            | NO PARTS USED   |                |
| Workorder:  | V58025                                       |   |            |   |                |
| In Date:<br>Close Date:<br>Problem?<br>power steer        | 05/29/2013<br>05/30/2013<br>ring locking up  | Meter Reading:  | 53,04      | 4.00  |                |
| Task perforr  | med:   |   |            | Parts   | Quantity       |
| ROAD TESTI<br>OUT UNIT.                                   | ED FOUND UNI                                 | T HARD STEER- SWA   | PED        | NO PARTS USED   |                |
|   |  |   |            |   |                |



10188443

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

#### Workorder: V58184

| In Date:<br>Close Date: | 06/04/2013<br>06/04/2013 | Meter Reading: | 53,263.00 |  |
|-------------------------|--------------------------|----------------|-----------|--|
|                         |                          |                |           |  |

**Problem?** 

Driver side rear door won't open up. Unable to retrieve the stretcher from the rescue truck. Appears the door is stuck from the bott latch where it connects and locks to the floor.

**Parts** 

#### Task performed:

REMOVED REAR DOOR PANEL AND REPAIRED NO PARTS USED DOOR LINKAGE.

#### Workorder: V58005

| In Date:    | 05/28/2013    | Meter Reading:   | 53.044.00 |
|-------------|---------------|------------------|-----------|
| Close Date: | 06/11/2013    | inotor reducingi |           |
| Problem?    |               |                  |           |
| stooring lo | cking up P451 |                  |           |

steering locking up, R451

#### Task performed:

1. check seering for locking up, take pressure's for pump, replace p/s filter and gakket, refill fluid, retest. still tight ,found u joint on steering column tight grease fitting, road test ok.

2. front grill led lite cover broken, when crew was swapping out the bay door came down on front grill braking led lite, remove grill assy. replace lite assy. reinstall grill

| Workorder: | V58030 |
|------------|--------|
| workorder: | VJOUJU |

In Date: 05/29/2013 Close Date: 06/11/2013 Problem? B inspection R-451

Meter Reading:

53,044.00

#### Task performed:

1. b inspection

2. work with john murray and check steering locking up, remove steering shaft assy, found u joint was tight, grease u joint, reinstall steering shaft road test vehicle, bring back into shop to align steering wheel, road test all ok

3. found return steering hose leaking, drain system and install new clamps, refill fill and test for leak, ok

4. service transmission

5. r/side rear entry lite inop, remove lite bar lens and replace  $\ensuremath{\mathsf{bulb}}$ 

| Parts                                  | Quantity |
|--|----------|
| 1878042C91FUEL FILTER 2008 HORTON      | 1        |
| 2506656C124316 WIX CAB A/C FILTER      | 1        |
| 29526898 29548988 TRANS FILTER ALLISON | 1        |
| 5774457744XD OIL FILTER                | 1        |
| H35SN12BULB                            | 1        |

| Parts                                     | Quantity |
|---|----------|
| 2507061C1PS RESV GASKET                   | 1        |
| 68118358130600 SER OPTIC CLEAR            | 1        |
| VML/T1808D2503221C1 FILTER POWER STEERING | 1        |

Quantity



10188443

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

#### Workorder: V58340

| In Date:    | 06/11/2013 | Meter Reading: |
|-------------|------------|----------------|
| Close Date: | 06/12/2013 |                |
| Problem?    |            |                |

The truck takes 2-3 attempts to start. R451

#### Task performed:

1. check for no start, driver stated last shift that the truck would turn over but not start, hook up laptop, no codes, batterys are new and starter is new, could not reproduce problem, vehicle starts every time, replace run relay and start relay,

| Parts                                     | Quantity |
|---|----------|
| 1219360123-11276-041 RELAY VF28-35F14-Z05 | 2        |

#### Workorder: V58442 In Date: 06/15/2013 Meter Reading: Close Date: 06/17/2013 Problem?

R451 is having problem starting, its taking a while to start. Need attention ASAP.

| Task performed:   | Parts  | Quantity |
|---|--|----------|
| REMOVED AND REPLACED STARTE   | R. 82000056808 38MT 12T STARTER                      | 1        |
| Workorder: V59318   |  |          |
| In Date: 07/24/2013 Meter Re<br>Close Date: 07/24/2013<br>Problem?<br>pat. compt. a/c inop, R-451 | ading: 55,723.00                                     |          |
| Task performed:   | Parts  | Quantity |
| 1. check pat. a/c, blows cool, add 7 check for leaks.   | oz of freon and NO PARTS USED                        |          |
| Workorder: V59427   |  |          |
| In Date: 07/29/2013 Meter Re<br>Close Date: 08/12/2013<br>Problem?                                | ading: 56,012.00                                     |          |
| need to get brackets install for the new  | v stretcher.   |          |
| Task performed:   | Parts  | Quantity |
| INSTALLED NEW STRETCHER.  | 090-0278STRECHER BAR NEW<br>6092036018J HOOK STRYKER | 1<br>1   |



10188443

| Workorder:  | V59006  |   |                             |               |          |
|---|---|---|-----------------------------|---------------|----------|
| In Date:<br>Close Date:<br><mark>Problem?</mark>  | 07/11/2013<br>08/19/2013<br>/c drain pan leak   | Meter Reading:  | 54,98                       | 1.00          |          |
|   |   | J   |                             |               |          |
| Task perforn  | ned:  |   |                             | Parts         | Quantity |
| MONITOR LE  | EAK.  | E THAT FELL OFF   | WILL                        | NO PARTS USED |          |
|   |   |   |                             |               |          |
| Workorder:<br>In Date:<br>Close Date:<br>Problem?<br>A/C in the P                                   | 09/06/2013<br>09/18/2013  | Meter Reading:<br>nt is not working. R4   | 51                          |               |          |
| Task perforn  | ned:  |   |                             | Parts         | Quantity |
| 1. check pat.<br>a/c and chec<br>crimp on low<br>crimp fitting,<br>leaking at crin<br>2. a/c inop - | a/c, evecaute sy<br>k for leaks, only<br>side schrader va<br>vac. system dow<br>np anymore. | stem, low on freon, o<br>y leak found was at<br>alve connection, insta<br>wn and recharge, wa<br>a/c and all tested of<br>ne. | t hose<br>all new<br>as not | NO PARTS USED |          |
| Workorder:  | V60702  |   |                             |               |          |
| In Date:<br>Close Date:<br>Problem?<br>Replace from   | 09/23/2013<br>09/24/2013<br>nt tires  | Meter Reading:  | 58,51                       | 8.00          |          |
| Task perforn  | ned:  |   |                             | Parts         | Quantity |
| REPLACE FF  |   |   |                             | NO PARTS USED |          |
| Vendor? B   | OULEVARD TIF  | RE CENTE  |                             |               |          |
| Workorder:  | V60362  |   |                             |               |          |
| In Date:<br>Close Date:<br>Problem?<br>Small screw  | 09/07/2013<br>10/01/2013<br>/ in front left tire.   | Meter Reading:<br>Wear bars are also  | 57,913<br>exposed. F        |               |          |
|   |   |   |                             |               |          |
| Task perforn  | ned:  |   |                             | Parts         | Quantity |
| CHECKED (<br>INSTALLED.   | ON TIRES, W   | ILL HAVE NEW <sup>-</sup>   | TIRES                       | NO PARTS USED |          |



10188443

| Problem?     | V61985<br>11/11/2013<br>11/18/2013<br>REAR TIRES R4 | Meter Reading:<br>451 | 60,172.00     |          |
|--------------|---|-----------------------|---------------|----------|
| Task perform |   |                       | Parts         | Quantity |
| REPLACE RE   | EAR TIRES R45                                       | 51                    | NO PARTS USED |          |
| Vendor? B    | OULEVARD TIF  | RE                    |               |          |



10188443

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

#### Workorder: V61412

In Date: 10/21/2013 Close Date: 11/19/2013 Problem? C inspection R451 Meter Reading:

59,953.00

Parts

Quantity

Task performed:



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

1. C INSP.

2. REPLACE KING PIN GREASE FITIINGS.

3. PASSENGER WINDOW INOP COMPLAIN-OPERATE CONTROLERS UNABLE TO MAKE WINDOW MOTOR FAIL AT THIS TIME.

4. HEATER HOSE RUBBING ON ALTERNATOR FAN-HOSE CUT- CUT HOSE AND SPIDER HOSE-REROUTE HOSE AND SECURE.

5. COOLANT LEAK A EGR VLAVE- PRESSURE TEST COOLANT SYSTEM FOUND NO LEAK.

6. FRONT BRAKES- REMOVE WHEEL AND DRUM DISASSEMBLE BRAKES, INSTALL NEW BRAKE SHOES, REASSEMBLE AND ADJUST BRAKE SLACK ADJUSTER.

7. RADIO SHOP REPAIR SPEAKER PROBLEM.

8. WINDSHIELD WIPER BLADE AND TOP OFF FLUID RESEVOIR.

9. R-1 COMP PANNEL MOUNT START LOOSE.

10. BATTERY TRAY SLIDE LOCK BROKEN-FABRICATED AND INSTALL TRAY SUPPORT LOCK STAMP.

11. NATAR PIN COVER BROKEN- REMOVE AND INSTALL NEW NATAT PIN COVER.

12. PACENT REAR DOOR NOW- SKID STRIP PEELING OFF-REMOVE CLEAN AREA AND INSTALL NEW SECTION OF NONSKID.

13. PACENT COMPT 2 A/C FILTERS- REMOVE ACCESS SCREEN AND REMOVE OLD FILTER-INSTALL AND SECURE 2 NEW FILTERS.

14. PACENT SIDE DOOR STROUT AND STROUT SUPPORT LOOSE- REMOVE STROUT REMP SUPPORT HOLE, REINSTALL STROUT AND SECURE SUPPORT AND STROUT.

15. ACCREDITATION DECAL- REMOVE DECAL, CLEAN AND POLISH AREA.

16. REAR ENTRANCE SCENE LIGHT INOP- REMOVE BLOWN BULB AND INSTALL NEW BULB.

17. L-2 COMP 2 BOX LIGHT CHANGER TABS BROKEN- REMOVE CHARGERS AND HANDWIRE 2 WIRE 2 NEW REPLACEMENT AND SECURE.

18. L-2 DOOR SHOCK L-2 CONT LOCK L-2 DOOR SHOCK L-1 O2 WRENCH MISSING- SECURE SHOCK-MOUNTS AND SUPPORT REPLACE O2 WRENCH ASSEMBLE SUPPORT STRAP FOR 02 WIRED AND INSTALL.

19. 110 A/C OUTLET INOP- CHECK 110 A/C RESET BREAKER PLUG IN/ OUT SIDE OUTLET WIRED BACK BOARD AND GROUND TAB BURNT, DISASSMBLE UNIT. PART ON ORDER.

20. POWER STEERING SYSTEM LEAK- REMOVE SUPPLY HOSE LINE SPLICED IN 3 LOCATION DRAIN OIL, INSTALL NEW HOSE, REMOVE FILTER SERVICE INSTALL NEW AND POWER STEERING FILLED. CLEAN OFF PUMP.

| 03920056SOCKET                               | 1 |
|--|---|
| 03990221RECP COVER                           | 1 |
| 101-124-000CRASH RESTRAINT STRAPS            | 1 |
| 14-565697LATCH EBERHARD                      | 1 |
| 1875880C2SEAL                                | 1 |
| 1876922C91SEAL KIT                           | 1 |
| 1878042C91FUEL FILTER 2008 HORTON            | 1 |
| 2506656C124316 WIX CAB A/C FILTER            | 1 |
| 2507061C1PS RESV GASKET                      | 1 |
| 2594129C1GASKET DPF 2 DOOR                   | 2 |
| 3555201C1PS HOSE NAVISTAR                    | 1 |
| 5-20PH1PGK4 CONNECTOR 120V 20A FEMALE        | 1 |
| 5774457744XD OIL FILTER                      | 1 |
| 91-22WIPER BLADE                             | 2 |
| AMH-1AMH-1 VALVE EXTENSION                   | 1 |
| DPF-22594131C91 DPF V8                       | 1 |
| KSMA2124703QFRONTBRAKE KIT RUMPER AND 4DR RE | 2 |
| RWTG1234LED PRESSURE CAP                     | 2 |
| TH5220D1003WALL THERMOSTATE HORTON           | 1 |
| TRW-L24VC0109DRAG LINK BOOT                  | 2 |
| VML/T1808D2503221C1 FILTER POWER STEERING    | 1 |



**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

21. CRANK CASE VENT FILTER HOUSING EXCESSIVE OIL- REMOVE DISASSEMBLE CLEAN UNIT, INSTALL NEW O-RINGS AND REASSEMBLE AND INSTALL.

22. INSTALL VALVE STEM EXTENSION ON REAR TIRES. TIRE SENSORS REAR R/I AND FRONT RIGHT 23. DRAG LINK BOOTH (BOTH) TORN- REMOVE DRAG LING KNOCK OFF GREASE BOOTH INSTALL (2) NEW GREASE BOOTH, REINSTALL AND SECURE DRAG LINK- GREASE BOOTHS.

24. CHECK TIRE PRESSURES- INSTALL LED AIR GUARD AND ADJUST TO TIME SPECS PRESSURE. 25. COMPLAIN CRACKING ON STARTUP. PERFORM AIR MANEGMENT TEST, STANDARD TEST PASS.

26. OPERATE UNITS NORMAL TEMP- COLANT TANK FULL- CHECK PIPE BEHIND WATER PUMP- EGR HOSE FITTING AND COMPRESSOR WHERE WATER MARKERS ARE NO LEAK AT THIS POINT.

27. PACENT SIDE DOOR PANEL LOOSE- PANNEL SCREW HOLES WORN, DRILL AND RETAP INSTALL NEW SCREWS AND SECURE.

28. MEDICAL BASJET SLIDES LOOSE- SECURE LOOSE SLIDES AND MISSING SUPPORT NUT AND BOLT FASTNER.

29. INVENTER INOP- POWER IN UNIT OVER TEMP TRIPPING- REMOVE INSTALL REPLACEMENT UNIT, REWIRE AND SECURE.

30. INTERMITTING CITY HORN- STEERING COLUMN GROUND LOOSE- CORRECT CONNECTION PROBLEM.

31. LONG CRACKING COMPLAIN- CHECK CODES NONE ACTIVE- START UNIT COLD- CRANK TIME ACCEPTABLE AFTER INITIAL WATER TO STARK CYCLE OF EGR.

32. 110V A/C CONTROLLER DIGITAL SCREWS PARTIAL OPERATION- REMOVE AND INSTALL NEW CONTROLLER REWIRE TO OPERATE A/C UNIT.

#### Workorder: V62192

In Date: 11/21/2013 Meter Reading: Close Date: 11/27/2013

#### Problem?

Air conditioner drains water into the lowest shelf in the exterior compartment on the officer side of the truck. Equipment and gear is being damaged from the water.

#### Task performed:

Parts

Quantity

| NEEDS | NEW    | DRAIN   | RAN-WILL | NEED | ТΟ | INSTALL |
|-------|--------|---------|----------|------|----|---------|
| NEW O | NE- WI | ILL ORD | ER.      |      |    |         |

NO PARTS USED



10188443

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

ANTICOOLANT ANTIFREEZE GAL

S986AIR GAUGE 160 PSI

Quantity 3

1

1

#### Workorder: V62236

| In Date:    | 1 |
|-------------|---|
| Close Date: | 1 |

**Problem?** 

 1/24/2013
 Meter Reading:

 2/10/2013

Truck leaking red fluid onto bay floor R451

#### Task performed:

1. vehicle was sent to the s/shop per. Tommy,check for red fluid leak, pressure test cooling system, found coolant hose under EGR valve has hoile in it. remove cross over pipe and replace hose and clamps, refill with coolant and pressure test system again, no leaks found.

#### \* had hose in stock Workorder: V62384 In Date: 12/01/2013 Meter Reading: 12/31/2013 Close Date: **Problem?** Emergency light cover on rear driver side of vehicle Task performed: **Parts** Quantity COOLANT LEAK- REPLACED HOSE CLAMPS ON NO PARTS USED HOSES. Workorder: V62692 In Date: 12/13/2013 Meter Reading: 12/31/2013 Close Date: **Problem?** Cover missing for emergency light on rear of vehicle. AC continues to leak water into the gear compartment on the officer side of truck, damaging medical and firefighting gear. R451 Task performed: **Parts** Quantity RESEALED LIGHT AND INSTALLED NEW LENS. 1 6811813493LENS CLEAR 68-1181349-3 Workorder: V61250 10/14/2013 In Date: Meter Reading: Close Date: 01/06/2014 **Problem?** Rear scene lamp inop. Passenger side power window inop. Task performed: Parts Quantity REPAIRED ON V61412. 1 AS758070XM1757-01 OXYGEN WRENCH

H35SN12BULB

**Parts** 



10188443

| Workorder:   | V63382  |  |                      |          |
|--|---|--|----------------------|----------|
| In Date:<br>Close Date:<br>Problem?<br>Patient a/c | 01/14/2014<br>01/15/2014<br>inop              | Meter Reading:   | 64,184.00            |          |
| Task perfor  | med:  |  | Parts                | Quantity |
| FREON- RE<br>WITH NITE<br>SYSTEM, NO<br>FREON, CH  | ECOVER 8 ON<br>ROGEN NO<br>O OIL VISABL       | IECK SYSTEM, LOV<br>ICES. CHECK FOR<br>LEAK FOUND, VAO<br>E, CHANGE SYSTEM<br>ATION, AND PRESS<br>DEGREES. | LEAK<br>CUUM<br>1 29 |          |
| Workorder:   | V63482  |  |                      |          |
| In Date:<br>Close Date:<br>Problem?<br>high water  | 01/17/2014<br>01/22/2014<br>- water in com    | Meter Reading:   | 64,474.00            |          |
| Task perfor  | med:  |  | Parts                | Quantity |
| HIGH WATE  | R PROBLEMS                                    |  | NO PARTS USED        |          |
| Workorder:   | V63530  |  |                      |          |
| In Date:<br>Close Date:<br>Problem?<br>R-front hea | 01/19/2014<br>01/22/2014<br>ad light is out R | Meter Reading:   |                      |          |
| Task perfor  | med:  |  | Parts                | Quantity |
| 1. replace r/s                                     | side headlight                                |  | 9007H9007 BUILB ASSY | 1        |



10188443

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

#### Workorder: V63554

| In Date:    | 01/20/2014 |
|-------------|------------|
| Close Date: | 01/22/2014 |

Meter Reading:

Problem?

R451 front compartment a/c not blowing cold needs repair.

| Task performed:   | Parts Quantity   |
|---|--|
| 1. check cab a/c, compressor not comming on, check<br>for power, check freon, hook up laptop, found codes for<br>thermisitors, control head, and vent door motor. remove<br>freon, replace both thermisitors, refill freon, replace a/c<br>control head, replace vent motor on evapotor box, (upper<br>motor), recheck a/c blows 29deg. | 3542606C12611234C1 VENT ACTUATOR       1         3545543C23545543C5 HEATER AC CONTROL       1         3622764C32606229C92 THERMISTER       2 |
| Workorder: V57572   |  |
| In Date: 05/07/2013 Meter Reading: 61,7<br>Close Date: 01/24/2014<br>Problem?   | 54.00  |
| 3 or 4 pods of the LED lights on the rear light bar appear  | not to be working.   |
| Task performed:   | Parts Quantity   |
| VERIFIED COMPLAINT. WORK COMPLETED ON<br>ANOTHER WORK ORDER.  | NO PARTS USED  |
| Workorder: V62896   |  |
| Close Date: 01/27/2014  | 05.00  |
| Problem?<br>Cirarette power source in front of cab does not work for ta   | ablet charger.   |
| Task performed:   | Parts Quantity   |
| 1. REPAIRED POWER TO 12 VOLT CHARGER AND TESTED.  |  |
| 2. READJUSTED STRETCHER LATCH AND TESTED.   |  |
| Workorder: V63130   |  |
| Close Date: 01/27/2014  | 27.00  |
| <b>Problem?</b><br>front AC power does not work for tablet power cord, thern<br>continues to leak water into outside compartment on offic   | nostat has fallen off the wall in the patient compartment and the AC<br>er side of truck, damaging EMS eqpt. E45                             |
| Task performed:   | Parts Quantity   |
| REPAIRED REAR DOOR HANDLE THAT WOULD NOT OPEN DOOR.   | NO PARTS USED  |



10188443

|  | L                                 |   |                       |                                 |          |
|--|-----------------------------------|---|-----------------------|---------------------------------|----------|
| Workorder:<br>In Date:<br>Close Date:<br>Problem?<br>lighter outle | 01/11/2014<br>01/27/2014          | Meter Reading:<br>Irtment not working. una  | 64,079<br>able to plu |                                 |          |
|  |                                   |   |                       |                                 |          |
| Task perfor  | med:                              |   |                       | Parts                           | Quantity |
|  |                                   | ARGER AND TESTED.<br>RED COOLANT LEAK.  |                       | NO PARTS USED                   |          |
| Workorder:   | V63323                            |   |                       |                                 |          |
| In Date:<br>Close Date:  | 01/11/2014<br>01/27/2014          | Meter Reading:  | 64,079                | 9.00                            |          |
| Problem?<br>R451 was o   | driven in very h                  | igh water.  |                       |                                 |          |
| Task perfor  | med:                              |   |                       | Parts                           | Quantity |
| CHECKED A  | LL FLUIDS AN                      | ID DRAINED FUEL FIL   | TER                   | NO PARTS USED                   |          |
| Workorder:   | V65072                            |   |                       |                                 |          |
| In Date:<br>Close Date:<br>Problem?                                | 03/20/2014<br>03/24/2014          | Meter Reading:  |                       |                                 |          |
|  | tch does not tu                   | rn system off. Batteries  | stay on.              |                                 |          |
| Task perfor  | med:                              |   |                       | Parts                           | Quantity |
| power to pat<br>install new t                                      | . compt. disco<br>pattery switch. | ound inop, will not shu<br>nnect batterys, remove<br>drill out eyelets on ba<br>tuds on new battery swi | and                   | 75908SWITCH BATTERY MASTER 300A | 1        |



10188443

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

#### Workorder: V64972

In Date: 0 Close Date: 0

03/17/2014 Meter Reading: 04/01/2014

68,488.00

Problem? B Inspection R451

Task performed:

 travel to sta-45 with pick up truck, drop off and pick up R-451 travel back to s/shop
 B insp.

3. remove 110v a/c and repair drain pan, leakin into r-1 compt.

4. coolant leak, found EGR cooler and hoses leaking, drain coolant, remove air filter, turbo hoses, remove wiring harness and hoses to get to EGR coolers, remove intake and exhaust coolers, install new map, ebp, and air temp sensors, install new coolers, and EGR valve, install all new coolant hoses, install new upper radiator hose, refill coolant and reassamble harness and air filter, turbo hoses, etc.etc. check for leaks..

5. service air drier, bolt stipped for drier, had to chisel off old bolt and install new bolt touqre to 70 ft lbs

6. replace pat. compt. a/c filters

7. replace both a/c and fan belts

8. replace wiper blades

9. adjust tire air pressure and install air sensors

10. replace struts on bench seat in pat. compt

11. inverter inop, found breaker tripped reset and run inverter,  $\ensuremath{\mathsf{ok}}$ 

12. remove and install new DPF filter and gaskets, road test vehicle get to operating temp, no check engine lite or DPF lite came on..

13. would not hold air overnight for rear tank, use soap and water, trace out air leaks on frame rail and foot valve, replace fittings, recheck for air leaks, holds overnight.14. rear entry door will not open from inside, remove door panel and adjust linkage for door latchs

15. found outside 110v outlet missing, on order

#### Workorder: V64898

| In Date:    |  |
|-------------|--|
| Close Date: |  |
| Problem?    |  |

Meter Reading:

ate: 04/11/2014

03/12/2014

The AC unit continues to leak water into the right exterior compartment, damaging gear and medical equipment. This is an ongoin problem that has been reported for over a year. Your assistance is requested.

#### Task performed:

Parts

Quantity

1. remove cover's and filter assy, for 110v a/c. found drain broken on pan, the one sent to me was wrong,

A63275M1183SLACK ADJ. FRONT M2

2

#### **Parts** Quantity 1 065624AD-IP DRIER 1 102D-158EHOSE GAUGE 1 109498BOLT KIT CARTRIDGE ADIP 30 15-40B15W40 MOTOR OIL NON SYN 1 1846480C2SENSOR EBP 1 1846481C92SENSOR MAP 1 1847727C1BELT 1 1875838C91SENSOR MANIFOLD AIR TEMP MAT 1 1878042C91FUEL FILTER 2008 HORTON 1 1878918C2EGR VALVE 1 2506656C124316 WIX CAB A/C FILTER 2 2594129C1GASKET DPF 2 DOOR 1 3610318C2RADIATOR HOSE 1 366555GTL6 13 X 19 FILTER 1 4307362R91KIT EGR COOLER COLD SIDE OLD 1876262C 1 46870AIR FILTER 1 5-20PH1PGK4 CONNECTOR 120V 20A FEMALE 1 5774457744XD OIL FILTER 1 7090595C91COOLER EGR KIT 330MM EXH SIDE OLD 187( 2 91-22WIPER BLADE 7 ANTICOOLANT ANTIFREEZE GAL 1 **DPFCLEANED UNIT** 2 EAA-8350-60UGSS6557UP STRUT-LIFT 1 K022105PURGE VALVE AD-IP-IS 1 K060695BELT 4 RWTG1234LED PRESSURE CAP



10188443

| Workorder:   | V65641                         |                          |           |   |          |
|--|--------------------------------|--------------------------|-----------|---|----------|
| In Date:<br>Close Date:<br>Problem?<br>Cab a/c inc | 04/11/2014<br>05/13/2014<br>pp | Meter Reading:           | 69,352    | 2.00  |          |
| Task perfor  | med:                           |                          |           | Parts   | Quantity |
| REPAIRED (<br>BLOWER M(                            |                                | ID BAD CONNECTION        | ON        | NO PARTS USED                                   |          |
| Workorder:   | V66317                         |                          |           |   |          |
| In Date:<br>Close Date:<br>Problem?                | 05/07/2014<br>05/13/2014       | Meter Reading:           |           |   |          |
|  | side headlight is              | not working. R45         |           |   |          |
| Task perfor  | med:                           |                          |           | Parts   | Quantity |
| replace head                                       | llight                         |                          |           | 9007H9007 BULB ASSY                             | 1        |
| Workorder:   | V66435                         |                          |           |   |          |
| In Date:<br>Close Date:<br>Problem?                | 05/13/2014<br>05/13/2014       | Meter Reading:           |           |   |          |
|  | hasnothing sec                 | uring the cushion to the | seat frar | ne. There are no screws mounting the seat down. |          |
| Task perfor  | med:                           |                          |           | Parts   | Quantity |
| repaired on v                                      | v/o# 66460                     |                          |           | NO PARTS USED                                   |          |
| Workorder:   | V66460                         |                          |           |   |          |
| In Date:<br>Close Date:<br>Problem?                | 05/13/2014<br>05/13/2014       | Meter Reading:           | 71,697    | 2.00  |          |
|  | missing bolts, R               | 2-451                    |           |   |          |
| Task perfor  | med:                           |                          |           | Parts   | Quantity |
| -  |                                | er seat                  |           | NO PARTS USED                                   |          |



10188443

| Workorder:  | V66476  |   |          |               |          |
|---|---|---|----------|---------------|----------|
| In Date:<br>Close Date:<br>Problem?<br>Fuel leak            | 05/14/2014<br>05/14/2014                      | Meter Reading:                              | 71,749   | .00           |          |
| Task perfori  | med:  |   |          | Parts         | Quantity |
| Removed<br>Manifold I<br>2. CHK Fue<br>Air Mainfo           | AIR TUBE TES<br>EAKING AT HE<br>L LEAK CONT.  | . TIGHTENED LINES AN<br>HK ERASE ENG. CODE  | IR<br>ND | NO PARTS USED |          |
| Workorder:  | V66623  |   |          |               |          |
| In Date:<br>Close Date:<br>Problem?<br>R451 Rear            | 05/20/2014<br>05/21/2014<br>a/c inop          | Meter Reading:                              | 72,026   | .00           |          |
| Task perfori  | med:  |   |          | Parts         | Quantity |
|   | N CAB FOUNE<br>EPAIRED AND                    | D BLEND DOOR STUC<br>TESTED.                | СК       | NO PARTS USED |          |
| Workorder:  | V66536  |   |          |               |          |
| In Date:<br>Close Date:<br><b>Problem?</b><br>Flashlight is | 05/16/2014<br>06/10/2014<br>s not working. It | Meter Reading:<br>needs to be repaired or r | eplaced  | I             |          |
|   |   |   |          |               |          |
| Task perfor   | med:  |   |          | Parts         | Quantity |
| repaired flash  | nlight charger th                             | at was not working.                         |          | NO PARTS USED |          |
| Workorder:  | V66750  |   |          |               |          |
| In Date:<br>Close Date:<br>Problem?                         | 05/26/2014<br>06/12/2014                      | Meter Reading:                              |          |               |          |
| Cab AC in   | R451 is not worl                              | king sporadically.                          |          |               |          |
| Task perfor   | med:  |   |          | Parts         | Quantity |
| checked a/c<br>was working                                  |   | r codes found on codes a                    | a/c      | NO PARTS USED |          |



10188443

| Workorder:<br>In Date:<br>Close Date:<br>Problem?<br>Patient a/c | 06/10/2014<br>06/17/2014     | Meter Reading:              | 73,322 | 2.00  |          |
|--|------------------------------|-----------------------------|--------|---|----------|
| Task perfor  | med:                         |                             |        | Parts   | Quantity |
|  | C INOP. A/C C<br>ONDENSER TE | CONDENSOR CLOGGEI<br>ST OK. | D.     | NO PARTS USED   |          |
| Workorder:   | V66938                       |                             |        |   |          |
| In Date:<br>Close Date:<br><b>Problem?</b><br>No start           | 06/03/2014<br>06/18/2014     | Meter Reading:              | 72,688 | 3.00  |          |
| Task perfor  | med:                         |                             |        | Parts   | Quantity |
| no start, batt   | eries shorted rep            | laced all batteries.        |        | BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF<br>HP-31DBATTERY 950CCA HP-31D | 3<br>3   |
| Workorder:   | V67251                       |                             |        |   |          |
| In Date:<br>Close Date:<br>Problem?                              | 06/16/2014<br>06/23/2014     | Meter Reading:              |        |   |          |
| left front tire  | e tread low                  |                             |        |   |          |
| Task perfor  | med:                         |                             |        | Parts   | Quantity |
| will montator  | tires at this time.          |                             |        | NO PARTS USED   |          |
| Workorder:   | V67372                       |                             |        |   |          |
| In Date:<br>Close Date:<br>Problem?                              | 06/22/2014<br>06/24/2014     | Meter Reading:              |        |   |          |
| Front drive  | r tire has low trea          | ad. R45                     |        |   |          |
| Task perfor  | modi                         |                             |        | Parts   | Quantity |
| -  |                              | TO REPLACE TIRES.           |        | NO PARTS USED   | Quantity |
| · · · · · · ·  |                              |                             |        |   |          |



| Workorder:<br>In Date:<br>Close Date:<br>Problem?<br>Replace from    | V67428<br>06/24/2014<br>06/26/2014<br>nt tires | Meter Reading:  | 73,959.   | 00   |             |
|--|--|---|-----------|--|-------------|
| Task perforn   | ned:   |   | ļ         | Parts  | Quantity    |
|  |  |   |           | NO PARTS USED  |             |
| Vendor? E  | LPEX TIRES                                     |   |           |  |             |
| Workorder:   | V65789   |   |           |  |             |
|  | 04/17/2014<br>07/02/2014                       | Meter Reading:  |           |  |             |
|  |  | tinues to leak water into ance is requested in corre  |           | om shelf of officer side rear compartment, damaging med<br>is issue. | cal equipme |
| Task perforn   | ned:   |   | ļ         | Parts  | Quantity    |
|  |  |   |           | NO PARTS USED  |             |
| Workorder:   | V66520   |   |           |  |             |
| In Date:<br>Close Date:<br>Problem?<br>On R451 the<br>firefighting g |  | Meter Reading:<br>continues to leak water   | in the ex | xterior cabinet on the officer's side, damaging medical equ          | uipment and |
| Task perforn   | ned:   |   | ļ         | Parts  | Quantity    |
| l/side drain bro<br>remove 110v                                      | oken, remove filte<br>a/c system, inst         | v a/c, remove cover four<br>er housing, remove panel<br>all new drain pan, reinsta<br>no water leak found | ls,       | 50-1100DRAIN PAN PLASTIC<br>FRT27146FREIGHT                          | 1<br>1      |
| Workorder:   | V66910   |   |           |  |             |
| In Date:<br>Close Date:<br>Problem?                                  | 06/01/2014<br>07/02/2014                       | Meter Reading:  |           |  |             |
|  |  | Also, AC unit continues t   | o leak w  | ater into exterior compartment, damaging EMS equipmer                | it and      |
| Task perforn   | ned:   |   | ļ         | Parts  | Quantity    |
|  |  |   |           | NO PARTS USED  |             |



10188443

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

#### Workorder: V67459

| In Date:    | 06/25/2014      | Meter Reading: | 74.084.00 |
|-------------|-----------------|----------------|-----------|
| Close Date: | 07/02/2014      |                | ,         |
| Problem?    |                 |                |           |
| check engi  | ne lite and DPF | lite on, R-451 |           |

#### Task performed:

1. hook up laptop and check for codes, found 1 for #4 cylinder injector, erase code but whent active again, check DPF do a regen cleaning but was aborted to much ash in filter, have crew swap out. order parts

2. R&R DPF filter

3. remove air filter, hoses, wiring, valve cover, remove and install new fuel injector's, install new nylon washers and o rings on fuel rail, tourque all bolts, reinstall all above and run engine, road test, recheck for codes no codes found

| Parts  | Quantity |
|--|----------|
| 1842626C951842626C96 OIL RAIL MANIFOLD SEALS | 1        |
| 1875784C921875784C93 ICP SENSOR              | 1        |
| 2594129C1GASKET DPF 2 DOOR                   | 2        |
| 5010561R925010561R93 INJECTOR                | 6        |
| 516TIRE INFLATOR                             | 1        |
| DPF-22594131C91 DPF V8                       | 1        |
| S153BLOW GUN                                 | 1        |
| S448GAUGE TIRE TREAD DEPTH                   | 1        |

#### Workorder: V67373

| In Date:    | 07/29/2014 |
|-------------|------------|
| Close Date: | 07/30/2014 |
| Problem?    |            |
| Patient a/c | inop       |

Meter Reading:

Task performed:

patient a/c inop low refrigent add 1lb of freon did not fine leak will bring to shop.

#### Workorder: V68547

| In Date:    | 08/09/2014       |
|-------------|------------------|
| Close Date: | 08/11/2014       |
| Problem?    |                  |
| Air look in | the rear avenage |

Meter Reading:

Air leak in the rear suspension R45

Task performed:

repairs made on w/o#68557

Parts \_\_\_\_\_

Quantity

Quantity

NO PARTS USED

Parts

NO PARTS USED



10188443

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

#### Workorder: V68557

| In Date:    | 08/10/2014 |
|-------------|------------|
| Close Date: | 08/11/2014 |

Meter Reading:

Meter Reading:

#### **Problem?**

Air bags in rear leak guickly after the truck is turned off. Very rough start to calls when the air is charging back up. very rough ride the patient compartment. R45

#### Task performed:

**Parts** Quantity 2 1. travel to sta-45 check for air leak found rear bag GUI1R11216GY1R11216 AIR BAG INT. leaking bring to s/shop and repair 2.check for air leaks found l/side air bag had holes, replace both air bags, recheck for leaks none found

#### Workorder: V68558

| In Date:       | 08/10/2014 |  |
|----------------|------------|--|
| Close Date:    | 08/11/2014 |  |
| Des la la seco |            |  |

#### **Problem?**

Shoreline AC continues to leak water into the officer-side exterior compartment, damaging expensive EMS equipment and rirefighting gear. This problem has been ongoing for over one year and the compartment smells of mold. R45

| Task performed:   | Parts                            | Quantity |
|---|----------------------------------|----------|
| run 110v a/c for a couple of hours, found a/c drains ok, bring outside and use hose on compt. found water | 10008146HND5948 HANDLE RH HORTON | 1        |
| leaking into compt from top of door, order new door seal  |                                  |          |

#### Workorder: V68559

In Date: 08/10/2014 Meter Reading: 08/11/2014 Close Date:

#### **Problem?**

Vendor?

Broken latch to side patient compartment door. Door to compartment opened while driving a patient to the hospital. Very unsafe. Crews have been instructed not to use the door. Door has been locked closed.

NO PARTS USED

#### Task performed:

Parts

Quantity

remove r/side entry door window, remove door panel. remove door handle assy, replace door handle and adjust, reinstall window and door panel

**BOULEVARD TIRE CENTE** 

\* handle charged out on w/o#68558

| Workorder:<br>In Date:<br>Close Date:<br>Problem?<br>replace 4 re | V69338<br>01/01/1900<br>09/15/2014<br>ear tires | Meter Reading: | 123,206.90 |          |
|---|---|----------------|------------|----------|
| Task perforr<br>Replace 4 rea                                     |   |                | Parts      | Quantity |



10188443

| Workorder:<br>In Date:<br>Close Date:<br>Problem?<br>water leak   | V68769<br>08/18/2014<br>09/23/2014<br>in r/side outer o | Meter Reading:<br>compt. R-451   | 76,51 | 10.00   |              |
|---|---|--|-------|---|--------------|
| Task perfor   | med:  |  |       | Parts   | Quantity     |
| 1. check for water leak into exterior r/side compt. it is not<br>comming from 110v a/c it is from door weather seal,<br>hosed down door with water and found leak at top of<br>door, order door seal will install when comes in |   |  | seal, | 0434001304340008 SEAL DOOR COMPARTMENT HORTON                                     | 25           |
| Workorder:  | V68987  |  |       |   |              |
| In Date:<br>Close Date:<br>Problem?   | 08/27/2014<br>09/23/2014                                | Meter Reading:   |       |   |              |
|   |   | tinues to leak water intended in the second se |       | cer-side compartment, damaging EMS equipment and firefig<br>s without a solution. | jhting gear. |
| Task perfor   | med:  |  |       | Parts   | Quantity     |
|   |   |  |       | NO PARTS USED   |              |



10188443

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

#### Workorder: V69054

In Date: 08/29/2014 Close Date: 09/23/2014

<sup>4</sup> Meter Reading: 4 77,034.00

Douto

Problem? C inspection R451

#### Task performed:

1. C insp

2. am/fm radio face broken, install new radio that was given to me by tommy he had on service truck, radio will not turn on trace out wiring to fuse panel, found fuse holder pins burnt, install fuse holder on panel. radio now works

3. abs lite on, hook up laptop, found code for l/front sensor, replace both front wheel abs sensors,

4. found code for outside fresh air door, replace door acuator motor, reset blend door motors, erease code5. replace wiper blades

6. washer fluid lite on, found washer tank leaking, install new tank and fill with washer fluid

7. cab dome lite inop, repair wire connectors

8. r/side and l/side amber marke lites in headlight assy. inop. replace bulbs

9. 110 inverter inop, found plugs falling out of recepticale 10. service p/s

11. remove rear wheels, drums and brakes, install new abs sensors, brake shoes, brake hardware and drums, adjust brakes and raod test, recheck brake adjustment

12. make up pitman arm puller for steering box, travel to s/shop assist eddie o with install of new power steering box, refill fluid, set steering poppet valve, test steering, travel back to c/shop

13. driver side door cup missing, found on floor in rear of vehicle, reinstall

14. r/s r-1 compt has water leaking into it, driver says it is from 110v a/c, run a/c no leaks, found water comming in from door seal, install new compt door seal

15. water still comming in from a/c, work with Karl to find out where water is comming from, when going around turn water over flows from drain pan, remove 110v a/c unit and drain pan, order new drain pan, send to c/shop to be repaired

16. road test vehicle

| Parts                                     | Quantity |
|---|----------|
| 15-40B15W40 MOTOR OIL NON SYN             | 30       |
| 1878042C91FUEL FILTER 2008 HORTON         | 1        |
| 194-ABULB                                 | 10       |
| 2506656C124316 WIX CAB A/C FILTER         | 1        |
| 2507061C1PS RESV GASKET                   | 1        |
| 3542606C12611234C1 VENT ACTUATOR          | 1        |
| 355059C98RESERVOIR TANK WINDSHIELD WASHER | 1        |
| 3757REAR DRUMS 3757X 3647X                | 2        |
| 50-1100DRAIN PAN PLASTIC                  | 1        |
| 5774457744XD OIL FILTER                   | 1        |
| 91-22WIPER BLADE                          | 4        |
| BX801551ABS SENSOR REAR INT.              | 2        |
| BX801553ABS SENSOR BENDIX STRAIGHT        | 2        |
| FRT 66425FREIGHT CHARGE                   | 1        |
| VML/T1808D2503221C1 FILTER POWER STEERING | 1        |
| XK4034707QPMHD SHOE KIT 3/8 BEAM          | 2        |
| ZRXM100PMTSTEERING GEAR NAV 3554373C91    | 1        |
|   |          |

Ouromatite.



10188443

| Workorder: V69588   |                         |                 |
|---|-------------------------|-----------------|
| Close Date: 09/24/2014<br>Problem?  | 123,695.10              |                 |
| a/c leaking in paitent compt. R451  |                         |                 |
| Task performed:   | Parts (                 | Quantity        |
| <ol> <li>INSTALLED NEW DRIP PAN IN COMPARTMENT R-<br/>OF PATIENT 110V A/C.</li> <li>FAB, RIAER FOR EVAP, HOUSEING AND DRA<br/>PAN TO DRAN DOWN HILL SO WATER WOOD NC<br/>DRAN IN REAR COMPARTMENT. REINSTALLED AL<br/>TRIM WORK AND PARTS REMOVE FOR WORK.</li> <li>TEST DRIVE UNIT TO SEE IF DRAIN SYSTE<br/>WORKING PROPERLY ALL WORKING AT THIS TIM</li> </ol> | AN<br>DT<br>LL          | 1               |
| Workorder: V69985   |                         |                 |
| In Date: 10/08/2014 Meter Reading:<br>Close Date: 10/31/2014<br>Problem?<br>door to compartment 6 opening on its own when hitti   | 77,985.00               |                 |
| Task performed:   | Parts (                 | Quantity        |
| Readjusted door latch and tested door   | NO PARTS USED           |                 |
| Workorder: V70631   |                         |                 |
| In Date: 11/01/2014 Meter Reading:<br>Close Date: 11/18/2014<br>Problem?  |                         |                 |
| Rear right scene light inop (4th light from right of top  | lightbar) R45           |                 |
| Task performed:   | Parts                   | Quantity        |
| Repaired connection in rear scene light   | NO PARTS USED           |                 |
| Workorder: V71216   |                         |                 |
| In Date: 11/26/2014 Meter Reading:<br>Close Date: 12/15/2014<br>Problem?<br>Patient compartment A/C system blows room tempter   | 7,982.00<br>erature air |                 |
| Task performed:   | Parts                   | Quantity        |
| <ol> <li>Traced out A/C problem, recharge system and blowir cold at this time</li> <li>Repaired rear doors that were hard to open</li> </ol>  |                         | <u>xuantity</u> |



10188443

|   | V72637  |   |  |                     |
|---|---|---|--|---------------------|
| In Date:<br>Close Date:<br>Problem?   | 01/27/2015<br>02/09/2015  | Meter Reading:  |  |                     |
| stop engine   | e alarm with ste  | am from under the hood, coola   | nt leak  |                     |
| Task perform  | ned:  |   | Parts  | Quantity            |
|   |   | Removed and replaced hose<br>Refilled with coolant.                     | ALA00350-50 EXTENDED LIFE COOLANT GAL                  | 6                   |
| Workorder:  | V73340  |   |  |                     |
| In Date:<br>Close Date:<br>Problem?   | 02/22/2015<br>03/02/2015  | Meter Reading:  |  |                     |
|   | -   | nce of moisture in light(mold), F<br><sub>l</sub> uires replacemet. R45 | Front scene light "cap" is broken and needs replacemer | nt. Back reflective |
| Task perform  | ned:  |   | Parts  | Quantity            |
|   |   |   | NO PARTS USED  |                     |
| Workorder:  | V73559  |   |  |                     |
| In Date:<br>Close Date:<br>Problem?   | 03/02/2015<br>03/02/2015  | Meter Reading:  |  |                     |
| front right h   | ead light out. A  | Iso rear right scene light missin                                       | ig plastic cover.                                      |                     |
| Task perform  | ned:  |   | Parts  | Quantity            |
| •   | sy, and re-wire   | ater in lite assy. install new<br>, tighten aide and rear entry         | NO PARTS USED  |                     |
|   | ssy, was given  | to me off of tommy's truck  |  |                     |
| * headlight as  |   |   |  |                     |
|   | V73672  |   |  |                     |
| * headlight as<br>Workorder:<br>In Date:<br>Close Date:<br>Problem?<br>B inspection                             | 03/05/2015<br>04/22/2015  | Meter Reading: 87,1   | 52.00  |                     |
| Workorder:<br>In Date:<br>Close Date:<br>Problem?   | 03/05/2015<br>04/22/2015<br>n R451                                      | Meter Reading: 87,1   | 52.00 Parts  | Quantity            |
| Workorder:<br>In Date:<br>Close Date:<br>Problem?<br>B inspection<br>Task perform<br>B inspection               | 03/05/2015<br>04/22/2015<br>n R451<br>med:<br>R451 OUTSID               | E VENDOR  |  | Quantity1           |
| Workorder:<br>In Date:<br>Close Date:<br>Problem?<br>B inspection<br>Task perforr<br>B inspection<br>1. R/FRONT | 03/05/2015<br>04/22/2015<br>n R451<br>med:<br>R451 OUTSID<br>BRAKE SHOE | E VENDOR  | Parts  | Quantity1<br>1<br>1 |



10188443

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

#### Workorder: V73959

| In Date:<br>Close Date: | 03/17/2015<br>05/04/2015 | Meter Reading: | 87,589.00 |
|-------------------------|--------------------------|----------------|-----------|
| Problem?                |                          |                |           |
| FRONT B                 | RAKES REF W/             | O 73672        |           |

#### Task performed:

**Parts** 

NO PARTS USED

Quantity

1. R/FRONT BRAKE SHOE CRACKED(LOWER) 2. R/REAR FLOOD LIGHT LENS COVER MISSING 3. put vehicle on lift, check r/front brake shoe found small

heat crack on bottom shoe, e-maile pic to steve r, will

monitor, road test no complaints from driver

4. Replaced light cover.

5. Sent to shop for brake problem.

#### Workorder: V73983

| In Date:              | 03/18/2015 | Meter Reading: | 87,589.00 |
|-----------------------|------------|----------------|-----------|
| Close Date:           | 05/21/2015 |                |           |
| Problem?<br>Check a/c |            |                |           |
| One on are            |            |                |           |

#### Task performed:

1. Check A/C on cab, found no freeon in system, charged with nitrogen, found condencer leaking and a crack in compress and it was locked up so I removed the compress dryer expension valve and condencer then I flush all hose and evpator, installed new part vacuum system charger system.

2. Check patient compartment, found system low on Freon and the high side line leaking. Remove compressor, check oil in unit found it was clean low so I put 402 in compressor. Put compressor back on and fixed hose with new fitting vacuum system and charged, worked replaced filter in compartment.

3. Ran cab A/C and pressure was very low and dryer was freezing up. Recover system and replace dryer and exp. valve vacuum system and charged it and it works good. 4. Found radiator hose was flat spring was bad in hose. R&R radiator hose.

| Parts                                 | Quantity |
|---------------------------------------|----------|
| 071601A07-0602A DRIER A/C 7118        | 1        |
| 08-6932QAC FITTING                    | 1        |
| 16-31438915 VALVE CORE A/C 3544706C1  | 1        |
| 16-31455533 CAP LOW SIDE BLUE         | 2        |
| 16-3445CAP-BLACK 134A 5579 KOOL TEMP  | 2        |
| 1693981C1CAP A/C INTERNATIONAL        | 1        |
| 2593329C91CONDNSER                    | 1        |
| 3544705C1CAP A/C INTERNATIONAL        | 1        |
| 3544706C1SCHRADER VALVE INT.          | 1        |
| 3610318C2RADIATOR HOSE                | 1        |
| 3611894C9103-0805 A/C COMPRESSOR 4347 | 1        |
| 3622764C32606229C92 THERMISTER        | 1        |
| 3660853C22512331C1 EXP VALVE NAV      | 2        |
| 366555GTL6 13 X 19 FILTER             | 1        |
| 3670134C1ACCUMULATOR ASSY INT.        | 2        |
| 8201L17-3428 ESTER OIL E7             | 1        |



10188443

**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

| W | or | kord | er: | V7 | 387· | 4 |
|---|----|------|-----|----|------|---|
|   |    |      |     |    |      |   |

| In Date:             | 03/14/2015 | Meter Reading |
|----------------------|------------|---------------|
| Close Date:          | 05/26/2015 |               |
| Design of the second |            |               |

Problem?

| AC in cab is not blowing cold. | Burning smell coming | from engine com | partment R45 |
|--------------------------------|----------------------|-----------------|--------------|
|--------------------------------|----------------------|-----------------|--------------|

| Task performed:  |  | Parts  | Quantity |
|--|--|--|----------|
| 1. Drove from headquarters to<br>Got to ST found patient A/C<br>system pressure were good a<br>small leak on hose on com<br>through the weekend, driver<br>working so I put gayge on it a<br>I tried to change it but they go<br>2. Driver on R45 said the true<br>and off so I put gauge on the<br>good and couldn't see empty<br>so they took the call and wer<br>3. Got home. | low on freon, so I charge<br>and A/C was cool. Found a<br>pressor but it should go<br>said the cab A/C was not<br>nd found system empty, so<br>ot a call so they left.<br>ck cab A/C was working on<br>the truck and pressure was<br>problem and they got a call | NO PARTS USED  |          |
| Workorder: V28493  |  |  |          |
| In Date: 12/20/2009<br>Close Date: 06/04/2015<br>Problem?<br>water leaking in pass throug  | Meter Reading:<br>gh R45   | 309.00   |          |
| Task performed:  |  | Parts  | Quantity |
| Rep leak in rear; resealed.  | j  | NO PARTS USED  |          |
| Workorder: V73876  |  |  |          |
| In Date:         03/14/2015           Close Date:         06/30/2015           Problem?  | Meter Reading:   |  |          |
|  | A/C is blowing cold. The pa  | atient compartment is very uncomfortable. Thank you. R45 |          |
| Task performed:  |  | Parts  | Quantity |
|  |  | NO PARTS USED  |          |
|  |  |  |          |



**INTERNATIONAL 4400 ADVANCED LIFE SUPPORT** 

#### Workorder: V73540

| In Date:    | 03/01/2015 | Meter |
|-------------|------------|-------|
| Close Date: | 07/07/2015 |       |

Reading:

#### **Problem?**

Stryker power stretcher goes up on its own without touching buttons This stretcher did get wet a few days in a row. Both these power stretchers are out of service at STATION 42

| Task performed:  |                          |                | Parts         | Quantity |
|--|--------------------------|----------------|---------------|----------|
|  |                          |                | NO PARTS USED |          |
| Workorder:   | V74669                   |                |               |          |
| In Date:<br>Close Date:<br><b>Problem?</b><br>a/c inop | 04/15/2015<br>09/08/2015 | Meter Reading: | 89,139.00     |          |
| Task perfori   | ned:                     |                | Parts         | Quantity |
|  |                          |                | NO PARTS USED |          |



Asset: (10188443) 2010 - HORTON 4400 Advanced Life Support Vehicle 2Dr

| 10188443<br>CSHOP-2015-113<br>Comments: R45 A/C INOP<br>Date Opened 4-17-2015 Date Finished<br>TASKS PERFORMED<br>AIR CONDITIONING                                   | 4-21-2015 Meter 1 Reading: 88,810<br>NO PARTS USED   |
|--|--|
| CSHOP-2015-1165<br>Comments: R-245 FREON LEAKING FROM AC TUBE<br>Date Opened 6-15-2015 Date Finished<br>TASKS PERFORMED<br>DRYER-ACCUMULATOR                         | 6-15-2015Meter 1 Reading:92,411QPARTS4A/C; FREON LB1ASSEMBLY; ACCUMULATOR ASSY INT.  |
| CSHOP-2015-1699<br>Comments: R245 SMOKING ALSO HAS FLUID LEAK<br>Date Opened 7-13-2015 Date Finished<br>TASKS PERFORMED<br>DEF FLUID                                 | 7-13-2015 Meter 1 Reading: 92,450 <b>NO PARTS USED</b>   |
| CSHOP-2015-1749<br>Comments: BROKEN DOOR LATCH<br>Date Opened 7-14-2015 Date Finished<br>TASKS PERFORMED<br>TRAVEL TO BE CHARGED TO WORK ORDER<br>BODY EXTERIOR      | 7-14-2015 Meter 1 Reading: 92,500 NO PARTS USED  |
| CSHOP-2015-1790<br>Comments: CAB AC NOT COLD R45<br>Date Opened 7-16-2015 Date Finished<br>TASKS PERFORMED<br>TRAVEL TO BE CHARGED TO WORK ORDER<br>AIR CONDITIONING | 7-17-2015       Meter 1 Reading:       92,600         Q       PARTS         1       INTERNATIONAL;       2606229C92 THERMISTER |

| Asset Work Order History 10188443<br>CSHOP-2015-1802<br>Comments: R45 O2 COMPARTMENT WONT OPEN<br>Date Opened 7-17-2015 Date Finished | 7-27-2015 Meter 1 Reading: 94,346  |
|---|--|
| TASKS PERFORMED   | Q PARTS  |
| TRAVEL TO BE CHARGED TO WORK ORDER<br>DOOR HANDLES INSIDE-OUTSIDE<br>AIR CONDITIONING   | <ol> <li>HANDLE; TM22676-02 HANDLE DOOR ENTRY</li> <li>HANDLE; TM22676-02 HANDLE DOOR ENTRY</li> <li>HANDLE; HANDLE LH HORTON</li> <li>HANDLE; HANDLE LH HORTON</li> </ol>   |
| CSHOP-2015-1961<br>Comments: CAB AC INOP R45<br>Date Opened 7-27-2015 Date Finished<br>THERMISTORS BAD                                | 8-4-2015 Meter 1 Reading: 94,346   |
| TASKS PERFORMED   | Q PARTS  |
| AIR CONDITIONING  | 1 INTERNATIONAL; 2606229C92 THERMISTER   |
| CSHOP-2015-2328<br>Comments: R245 NO A/C<br>Date Opened 8-14-2015 Date Finished<br>TASKS PERFORMED<br>AIR CONDITIONING                | 8-18-2015 Meter 1 Reading: 94,346<br>NO PARTS USED   |
| CSHOP-2015-2380<br>Date Opened 8-18-2015 Date Finished<br>TASKS PERFORMED<br>PM SERVICE C RESCUE                                      | 8-19-2015 Meter 1 Reading: 95,432<br>NO PARTS USED   |
| CSHOP-2015-2381<br>Comments: R245 REPAIRS FROM INSPECTION<br>Date Opened 8-18-2015 Date Finished<br>TASKS PERFORMED                   | 9-2-2015 Meter 1 Reading: 95,432<br>Q PARTS  |
| FLASHER<br>REAR TIRES<br>AIR SYSTEM<br>SEAT BELTS<br>CAB-INTERIOR ACCESSORIES<br>A/C FILTER SCREENS                                   | <ol> <li>BULB; BULB</li> <li>FILTER; PANEL FILTER</li> <li>BELT; SEAT BELT ASSY</li> <li>BELT; 80075 SEAT BELT</li> <li>BELT; 80075 SEAT BELT</li> <li>HORN; ELECTRIC HORN LOW</li> <li>HORN: FLECTRIC HORN HIL</li> </ol> |

1 HORN; ELECTRIC HORN HI

| Asset Work Order History 10188443  |          |                        |  |                  |   |
|--|----------|------------------------|--|------------------|---|
| CSHOP-2015-2547  |          |                        |  |                  |   |
| Comments: O2 SENSOR ON M TANK IS OUT OF SERV.<br>Date Opened 8-26-2015 Date Finished               |          | 5-2015                 | Meter 1 Reading:                         | 95,432           |   |
| TASKS PERFORMED  | Q        | PARTS                  |  |                  |   |
| SAFTEY-EMERGENCY EQUIPMENT<br>AIR CONDITIONING   | 1        | LINE; TR               | ANSDUCER LINE PI                         | RESSURE HORTON   |   |
| CSHOP-2015-3061  |          |                        |  |                  |   |
| Comments: CAB AC INOP R@45<br>Date Opened 9-24-2015 Date Finished                                  | 9-28     | 3-2015                 | Meter 1 Reading:                         | 96,902           |   |
| TASKS PERFORMED  | Q        | PARTS                  |  |                  |   |
|  |          |                        |  |                  |   |
| AIR CONDITIONING   | 1        | INTERNA                | TIONAL; 2606229C                         | 92 THERMISTER    |   |
| CSHOP-2015-3388  |          |                        |  |                  |   |
| Comments: R245 CHECK PAT A/C CONDENSER FANS<br>Date Opened 10-13-2015 Date Finished                | 10-1     | 3-2015                 | Meter 1 Reading:                         | 97,749           |   |
| TASKS PERFORMED  |          | ARTS USED              |  |                  |   |
| TRAVEL TO BE CHARGED TO WORK ORDER   |          |                        |  |                  | • |
| AIR CONDITIONING   |          |                        |  |                  |   |
| Service Requests:  |          |                        |  |                  |   |
| 10/10/2015 A/C / 19: LOOSE / REPAIR<br>R245 TWO FANS BELOW PATIENT COMPARTM                        | ENT MAK  | ING NOISE. SOL         | INDS LIKE BAD BEARINGS.                  |                  |   |
| CSHOP-2015-3643  |          |                        |  |                  |   |
| Comments: R245 TRANS NOT SHIFTING PROPERLY<br>Date Opened 10-28-2015 Date Finished                 | 11 1     | 2-2015                 | Matau 1 Dag diago                        | 98,477           |   |
| TASKS PERFORMED  |          | PARTS                  | Meter 1 Reading:                         | 90,477           |   |
|  | <u>u</u> | FARTS                  |  |                  |   |
| TOWING HITCH<br>TRANSMISSION<br>QUALITY CHECK-REPAIRS  | 1        | INTERNA                | TIONAL; CONTAINE                         | ER               |   |
| VENDOR? SISTERS TOWING   |          |                        |  |                  |   |
|  |          |                        |  |                  |   |
| CSHOP-2015-415<br>Comments: R-45 EMERGENCY LIGHT NOT WORKING<br>Date Opened 5-4-2015 Date Finished |          | HT SIDE FROM<br>2-2015 | NT GRILLE. NEEDS REP<br>Meter 1 Reading: | LACED.<br>90,741 |   |
| TASKS PERFORMED  | NO P     | ARTS USED              |  |                  |   |
| LIGHTING SYSTEM  |          |                        |  |                  |   |

| Asset Work Orde  |  |   |  |   |   |  |                 |
|--|--|---|--|---|---|--|-----------------|
| CSHOP-2015-434   |  | 12-7-2015   | Date Finished  | 12.2  | 1 2015  | Mahau 1 Daadhaas   | 100 647         |
|  |  | 12-7-2015   | Date Finished  | _   | 1-2015  | Meter 1 Reading:   | 100,647         |
| TASKS PERFORM  | ED   |   |  | <u>Q</u>  | PARTS   |  |                 |
| TRAVEL TO BE (<br>ELECTRICAL<br>AIR CONDITION  |  | GED TO WOF  | RKORDER  | 1   | BULB; H   | 9007 BULB ASSY   |                 |
| Service Requests:  |  |   |  |   |   |  |                 |
| 12/06/2015   | R245 H/  |   |  |   |   | IR HORN IS USED. WHEN 1  | THE RESCUE SITS |
| 12/07/2015   |  | S / 19: LOOSE<br>R SIDE HEADLIGH  |  |   |   |  |                 |
| CSHOP-2015-445   |  |   |  |   |   |  |                 |
|  |  | IN CAB HOT<br>12-14-2015  | Date Finished  | 1-4-  | 2016  | Meter 1 Reading:   | 101,232         |
| TASKS PERFORM  | -  | 0.0   | Dute Thisney   |   | ARTS USED   |  | 101,232         |
|  |  |   |  |   |   |  |                 |
|  |  |   |  |   |   |  |                 |
| AIR CONDITION  | ING  |   |  |   |   |  |                 |
|  | ING  |   |  |   |   |  |                 |
| Service Requests:  |  |   |  |   |   |  |                 |
|  | <br>A/C / 1  | I9: LOOSE / RI  | EPAIR<br>ARTMENT BLOWING I   |   |   |  |                 |
| Service Requests:  | A/C / 1<br>A/C IN 1  |   |  | HOT AIR.  |   |  |                 |
| Service Requests:<br>12/13/2015<br>CSHOP-2015-464<br>Comments: R <sup>2</sup>  | — —<br>A/C / 1<br>А/С IN Т<br>А/С IN Т<br>3<br>3<br>45 SEN                               | THE FRONT COMP.   | ARTMENT BLOWING I  | )HN MOI   |   |  | 104.026         |
| Service Requests:<br>12/13/2015<br>CSHOP-2015-464<br>Comments: R <sup>2</sup><br>Date O  | A/C / 1<br>A/C IN 1<br>A/C IN 1<br>3<br>45 SEN<br>Ipened                                 | HE FRONT COMP   | ARTMENT BLOWING I  | )HN MOI<br>2-23   | -2016   | ISTALL<br>Meter 1 Reading:                                       | 104,026         |
| Service Requests:<br>12/13/2015<br>CSHOP-2015-464<br>Comments: R <sup>2</sup>  | A/C / 1<br>A/C IN 1<br>A/C IN 1<br>3<br>45 SEN<br>Ipened                                 | THE FRONT COMP.   | ARTMENT BLOWING I  | )HN MOI   |   |  | 104,026         |
| Service Requests:<br>12/13/2015<br>CSHOP-2015-464<br>Comments: R <sup>2</sup><br>Date O  | A/C / 1<br>A/C IN 1<br>3<br>45 SEN<br>ppened<br>IED<br>CHAR(                             | THE FRONT COMP,   | ARTMENT BLOWING I  | )HN MOI<br>2-23   | -2016<br><b>PARTS</b>   |  | 104,026         |
| Service Requests:<br>12/13/2015<br>CSHOP-2015-464<br>Comments: R <sup>2</sup><br>Date O<br>TASKS PERFORM<br>TRAVEL TO BE O<br>WIPER BLADES   | A/C / 1<br>A/C IN 1<br>3<br>45 SEN<br>ppened<br>IED<br>CHAR(                             | THE FRONT COMP,   | ARTMENT BLOWING I  | 0HN MOI<br>2-23<br>Q  | -2016<br><b>PARTS</b>   | Meter 1 Reading:   | 104,026         |
| Service Requests:<br>12/13/2015<br>CSHOP-2015-464<br>Comments: R4<br>Date O<br>TASKS PERFORM<br>TRAVEL TO BE (<br>WIPER BLADES<br>AIR CONDITION  | A/C / 1<br>A/C IN 1<br>3<br>45 SEN<br>pened<br>IED<br>CHAR(<br>ING<br>A/C / 1            | THE FRONT COMP.   | ARTMENT BLOWING I<br>TO STATION JC<br>Date Finished<br>RK ORDER<br>EPAIR   | 2-23<br>Q<br>2  | -2016<br><b>PARTS</b><br>WIPER; \                               | Meter 1 Reading:   |                 |
| Service Requests:<br>12/13/2015<br>CSHOP-2015-464<br>Comments: R <sup>2</sup><br>Date O<br>TASKS PERFORM<br>TRAVEL TO BE O<br>WIPER BLADES<br>AIR CONDITION<br>Service Requests:<br>12/24/2015   | A/C / 1<br>A/C IN 1<br>3<br>45 SEN<br>pened<br>IED<br>CHAR(<br>ING<br>A/C / 1<br>A/C BLC | THE FRONT COMP.   | ARTMENT BLOWING I<br>TO STATION JC<br>Date Finished<br>RK ORDER<br>EPAIR   | 2-23<br>Q<br>2  | -2016<br><b>PARTS</b><br>WIPER; \                               | Meter 1 Reading:   |                 |
| Service Requests:<br>12/13/2015<br>CSHOP-2015-464<br>Comments: R <sup>2</sup><br>Date O<br>TASKS PERFORM<br>TRAVEL TO BE O<br>WIPER BLADES<br>AIR CONDITION<br>Service Requests:<br>12/24/2015<br>CSHOP-2015-554<br>Comments: R <sup>2</sup> | A/C / 1<br>A/C IN 1<br>3<br>45 SEN<br>pened<br>IED<br>CHAR(<br>ING<br>A/C / 1<br>A/C BLC | THE FRONT COMP,<br>T WIPER BLADE<br>12-28-2015<br>GED TO WOF<br>GED TO WOF<br>19: LOOSE / RI<br>DWS WARM AIR AF<br>INTERMITTENT | ARTMENT BLOWING I<br>TEN STATION JC<br>Date Finished<br>ARK ORDER<br>EPAIR<br>TER RUNNING FOR A<br>TCAB AND PATIEN | 2<br>COUPLE   | -2016<br>PARTS<br>WIPER; \<br><br>MINUTES. IT BI<br>PARTMENT R. | Meter 1 Reading:   |                 |
| Service Requests:<br>12/13/2015<br>CSHOP-2015-464<br>Comments: R <sup>2</sup><br>Date O<br>TASKS PERFORM<br>TRAVEL TO BE O<br>WIPER BLADES<br>AIR CONDITION<br>Service Requests:<br>12/24/2015<br>CSHOP-2015-554<br>Comments: R <sup>2</sup> | A/C / 1<br>A/C IN 1<br>3<br>45 SEN<br>pened<br>IED<br>CHAR(<br>ING<br>A/C / 1<br>A/C BLC | THE FRONT COMP,<br>T WIPER BLADE<br>12-28-2015<br>GED TO WOF<br>GED TO WOF<br>19: LOOSE / RI<br>DWS WARM AIR AF                 | ARTMENT BLOWING I<br>S TO STATION JC<br>Date Finished<br>RK ORDER<br>EPAIR<br>TER RUNNING FOR A                    | 2<br>2<br>2<br>0<br>2<br>0<br>2<br>0<br>0<br>2<br>0<br>0<br>2<br>0<br>0<br>2<br>0<br>0<br>2<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0<br>0 | -2016<br>PARTS<br>WIPER; \<br>                                  | Meter 1 Reading:<br>WIPER BLADE WIPER BLADE UNUS COLD WHEN RESTA |                 |

| Asset Work Order History 10188443                              |      |                                       |                   |               |  |
|--|------|---------------------------------------|-------------------|---------------|--|
| CSHOP-2015-574<br>Comments: R-45 PATIENT AIR CONDITIONER NOT W |      |                                       |                   |               |  |
| Date Opened 5-11-2015 Date Finished                            |      | 1-2015                                | Meter 1 Reading:  | 90,841        |  |
| TASKS PERFORMED  | Q    | PARTS                                 |                   |               |  |
| AIR CONDITIONING   |      |                                       |                   |               |  |
| AIR CONDITIONING   | 2    |                                       | RY48 RELAY        |               |  |
|  | 1    |                                       | ; SWITCH A/C PRES |               |  |
|  | 2    | INTERNA                               | ATIONAL; 2606229C | 92 THERMISTER |  |
| CSHOP-2015-579   |      |                                       |                   |               |  |
| Comments: PATIENT AC NOT WORKING R245                          |      |                                       |                   |               |  |
| Date Opened 5-11-2015 Date Finished                            | 5-11 | L-2015                                | Meter 1 Reading:  | 90,641        |  |
| TASKS PERFORMED  | NO P | ARTS USED                             |                   |               |  |
| AIR CONDITIONING   |      |                                       |                   |               |  |
|  |      |                                       |                   |               |  |
| CSHOP-2015-875   |      |                                       |                   |               |  |
| Comments: PATIENT AC INOP R245                                 |      |                                       |                   |               |  |
| Date Opened 5-29-2015 Date Finished                            | 5-29 | 9-2015                                | Meter 1 Reading:  | 91,622        |  |
| TASKS PERFORMED  | NO P | ARTS USED                             |                   |               |  |
| A/C CONDENSER FAN  |      |                                       |                   |               |  |
|  |      |                                       |                   |               |  |
| CSHOP-2016-1063  |      |                                       |                   |               |  |
| Comments: B INSPECTION   |      |                                       |                   |               |  |
| Date Opened 3-7-2016 Date Finished                             | 3-8- | -2016                                 | Meter 1 Reading:  | 104,067       |  |
| TASKS PERFORMED  | Q    | PARTS                                 |                   |               |  |
|  |      |                                       |                   |               |  |
| PM SERVICE B   | 30   | MOTOR                                 | R; 15W40 MOTOR O  | L NON SYN     |  |
|  | 1    | · · · · · · · · · · · · · · · · · · · | FUEL FILTER 2008  |               |  |
|  | 1    |                                       | 57744XD OIL FILTE |               |  |
|  | 1    | FILTER;                               | 24316 WIX CAB A/C | FILTER        |  |
|  |      |                                       |                   |               |  |

CSHOP-2016-1162 Comments: **REPAIRS FROM PM** Date Opened 3-10-2016 Date Finished 3-29-2016 Meter 1 Reading: 104,648 TASKS PERFORMED Q PARTS THERMOSTAT 1 THERMOSTAT: 1842130C3 THERMOSTAT DT466 HOSE UPPER 2 BRAKE; HD SHOE KIT 3/8 BEAM DOME LIGHTS 2 BRAKE; REAR DRUMS 3757X 3647X **INVERTER** 1 FAN; FAN KIT DANHARD CONDENSER KNUCKLE 2 BRAKE; GY1R11216 AIR BAG INT. **REAR BRAKE PADS-SHOES** SEAL; DOOR SEAL F 1 **REAR BRAKE DRUMS REPAIR FROM PM - DECALS/CLEANLINESS** AIR SYSTEM AIR BAG SYSTEM DOOR WEATHER MOLDING DOOR PANEL GLOVE BOX A/C CONDENSER FAN CSHOP-2016-1749 Date Opened 4-13-2016 Date Finished 4-19-2016 Meter 1 Reading: 105,902 **TASKS PERFORMED NO PARTS USED** TRAVEL TO BE CHARGED TO WORK ORDER AIR CONDITIONING CSHOP-2016-2032 Date Opened 4-28-2016 5-29-2016 107,993 Date Finished Meter 1 Reading: **TASKS PERFORMED** PARTS Q **ELECTRICAL** 1 SLIDE; 3320-18 DRAWER SLIDE **AIR CONDITIONING** 

#### CSHOP-2016-2315

| Comments: ON-CALL R245 NO STAF<br>Date Opened 5-14-2016 | T<br>Date Finished | 5-14-2016     | Meter 1 Reading: | 107,272 |
|---|--------------------|---------------|------------------|---------|
| TASKS PERFORMED   |                    | NO PARTS USED |                  |         |
| ENGINE AND ACCESSORIES                                  |                    |               |                  |         |
| CSHOP-2016-2558<br>Date Opened 5-27-2016                | Date Finished      | 5-27-2016     | Meter 1 Reading: | 107,879 |
| TASKS PERFORMED   |                    | NO PARTS USED |                  |         |
| FAULT CODE  |                    |               |                  |         |

| Asset Work Ord                                 |               | <u>ory 10188443</u>             | <u>i</u>                       |                           |                   |                   |
|--|---------------|---------------------------------|--------------------------------|---------------------------|-------------------|-------------------|
|  | 245           | 6 2 2016                        | Data Fisishad                  | C 0 2010                  |                   | 100 472           |
| Date (<br>TASKS PERFORN                        |               | 6-3-2016                        | Date Finished                  | 6-8-2016<br>NO PARTS USED | Meter 1 Reading:  | 108,472           |
| TASKS PERFORM                                  |               |                                 |                                | NU PARTS USED             |                   |                   |
| TRAVEL TO BE<br>LIGHTING SYST<br>AIR CONDITION | ГЕМ           | GED TO WOF                      | RK ORDER                       |                           |                   |                   |
| Service Requests:                              |               |                                 |                                |                           |                   |                   |
| 06/03/2016                                     | -             | S / 18: LEAKII                  | NG / R<br>BIDE) HEADLIGHT IS C | DUT                       |                   |                   |
| CSHOP-2016-27                                  |               |                                 |                                |                           |                   |                   |
|  | 245<br>Opened | 6-9-2016                        | Date Finished                  | 6-9-2016                  | Meter 1 Reading:  | 108,472           |
| TASKS PERFORM                                  | <u>1ED</u>    |                                 |                                | NO PARTS USED             |                   |                   |
| Service Requests:<br>06/08/2016                |               |                                 |                                |                           |                   |                   |
| 00/00/2010                                     | -             | SIVE OIL LEEK                   | REFAIR                         |                           |                   |                   |
| CSHOP-2016-300<br>Comments: C                  |               | NGINE FOR CO                    | OLANT AND OIL LI               | FAKS                      |                   |                   |
|  |               | 6-21-2016                       | Date Finished                  | 6-29-2016                 | Meter 1 Reading:  | 108,472           |
| TASKS PERFORM                                  | <u>1ED</u>    |                                 |                                | Q PARTS                   |                   |                   |
| OIL PUMP                                       |               |                                 |                                | 1 PUMP; 18                | 93940C93 OIL LIN  | E HIGH PRESS PUMP |
|  | N-CALL        | . <mark>R245</mark><br>7-5-2016 | Date Finished                  | 7-5-2016                  | Meter 1 Reading:  | 108,711           |
| TASKS PERFORM                                  | -             | •                               | Jaconinoned                    | NO PARTS USED             | ricter i reduing. |                   |
| TRANSMISSION                                   |               |                                 |                                |                           |                   |                   |

| Asset Work Order Histo  | ory 10188443                          |                            |                |                      |                  |         |  |
|---|---------------------------------------|----------------------------|----------------|----------------------|------------------|---------|--|
| CSHOP-2016-323<br>Date Opened   | 1-25-2016                             | Date Finished              | 2-2-2          | 2016                 | Meter 1 Reading: | 103,112 |  |
| TASKS PERFORMED   |                                       |                            | Q              | PARTS                |                  |         |  |
| TRAVEL TO BE CHAR<br>DIAGNOSE ELECTRIC<br>AIR SYSTEM<br>AIR CONDITIONING                                      |                                       | K ORDER                    | 2              | DOOR; D              | OOR MAGNETS      |         |  |
| Service Requests:   |                                       |                            |                |                      |                  |         |  |
|   | R / 19: LOOSE /<br>ISOR STAIR CHAIR ( | REPAIR<br>COMPARTMENT SENS | SOR MAL        | FUNCTIONING          |                  |         |  |
| CSHOP-2016-3337<br>Comments: FREON C<br>Date Opened<br>TASKS PERFORMED  |                                       | Date Finished              | 7-27-<br>Q     | 2016<br><b>PARTS</b> | Meter 1 Reading: | 109,600 |  |
| AIR CONDITIONING  |                                       |                            | 3              | A/C; FRE             | ON LB            |         |  |
| CSHOP-2016-3589<br>Date Opened<br>TASKS PERFORMED   | 7-27-2016                             | Date Finished              | 8-6-2<br>NO PA | 2016<br>ARTS USED    | Meter 1 Reading: | 110,017 |  |
| AIR CONDITIONING  |                                       |                            |                |                      |                  |         |  |
| Service Requests:   |                                       |                            |                |                      |                  |         |  |
|   | 19: LOOSE / EX<br>BLE A/C BLOWER MA   | CHANGE - NEW               |                |                      |                  |         |  |
| CSHOP-2016-3714<br>Comments: R245 STF<br>Date Opened<br>TASKS PERFORMED<br>TIRES & WHEELS<br>POWER SEAT MOTOR |                                       | Date Finished              | 8-6-2<br>NO PA | 2016<br>ARTS USED    | Meter 1 Reading: | 110,017 |  |
|   |                                       |                            |                |                      |                  |         |  |
| CSHOP-2016-4215<br>Date Opened  | 8-26-2016                             | Date Finished              | 8-26-<br>NO PA | 2016<br>ARTS USED    | Meter 1 Reading: | 110,791 |  |
| TRAVEL TO BE CHAR   | GED TO WORI                           | K ORDER                    |                |                      |                  |         |  |

#### CSHOP-2016-4292

Comments: ON-CALL R245 COOLANT LEAK

Date Opened 8-31-2016 Date Finished

TASKS PERFORMED

Meter 1 Reading:

111,071

NO PARTS USED

ENGINE COOLANT TEMPERATURE SE

| CSHOP-2016-4431<br>Date Opened | 9-12-2016  | Date Finished                        | 11-8-   | 2016        | Meter 1 Reading:                   | 111,869                 |
|--------------------------------|--|--------------------------------------|---|-------------|------------------------------------|-------------------------|
| TASKS PERFORMED                |  |                                      | Q   | PARTS       | ricci i riccanigi                  |                         |
|                                |  |                                      |   |             |                                    |                         |
| WIPER BLADES                   |  |                                      | 2   | WIPER; V    | VIPER BLADE                        |                         |
| AIR FILTER                     | R FILTER<br>(HAUST MANIFOLD<br>ERPENTINE BELT<br>IGINE AND ACCESSORIES |                                      |   |             | AIR FILTER                         |                         |
|                                |  |                                      |   | BELT; BE    |                                    |                         |
|                                |  |                                      |   | BELT; BE    |                                    |                         |
| LIGHTING SYSTEM                |  |                                      | 1   |             | PULLEY BUSHING                     | -                       |
| OIL COOLER-HEAT EXC            |  |                                      | 1 PULLEY; IDLER PULLEY BOLT<br>1 PULLEY; IDLER PULLEY |             |                                    |                         |
| TRANSMISSION                   |  |                                      | 1   |             | LT HORTON                          |                         |
| HOSES-LINES & FITTIN           |  |                                      | 1   |             | DLER DUST COVE                     | 2                       |
| FRONT BRAKE PADS-S             | HOES   |                                      | 1   |             | LT TENSONER                        |                         |
| AIR DRIER<br>BODY EXTERIOR     |  |                                      | 1   |             |                                    | ORTON ADD ON A/C        |
| CAB-INTERIOR ACCESS            |  |                                      | 1   | BELT; BE    | LT                                 |                         |
| A/C COMPRESSOR                 | SOINES   |                                      | 1   |             |                                    | ED COMPRESSOR INT.      |
|                                |  |                                      | 2   |             | T; BOLTS EGR COO                   |                         |
|                                |  |                                      | 1   |             | T; KIT SEAL OIL CO                 |                         |
|                                |  |                                      | 1   |             | AL KIT OIL COOLE                   |                         |
|                                |  |                                      | 1<br>2  |             | 29548988 TRANS F<br>BRAKE DRUM RUM |                         |
|                                |  |                                      | 2   |             |                                    | RUMPER AND 4DR RESCUE   |
|                                |  |                                      | 1   |             | AD-IP DRIER                        |                         |
|                                |  |                                      | 1   |             | URGE VALVE AD-IF                   | P-IS                    |
|                                |  |                                      | 1   |             | 320-20 DRAWER SL                   |                         |
|                                |  |                                      | 20  | NEWPA       | RT; BOOT CAB 2DC                   | OR HORTON               |
|                                |  |                                      | 1   |             | 07-0602A DRIER A/0                 |                         |
|                                |  |                                      | 2   | PORT; 08    | -6932BS 90 DEGRE                   | E FEMALE W/SERVICE PORT |
| Service Requests:              |  |                                      |   |             |                                    |                         |
|                                | REQUEST WHEN   | 12: BROKEN / F<br>IT RAINS, LARGE AM |   | WATER COLLE | CTS ON UNIT FLOOR BETV             | VEEN CAB AND PT         |
| CSHOP-2016-4586                |  |                                      |   |             |                                    |                         |
|                                | /C INOP R245   |                                      |   |             |                                    |                         |
| Date Opened                    | 9-20-2016  | Date Finished                        | 10-21   | -2016       | Meter 1 Reading:                   | 111,869                 |
| TASKS PERFORMED                |  |                                      | NO PA   | ARTS USED   |                                    |                         |
| AIR CONDITIONING               |  |                                      |   |             |                                    |                         |
|                                |  |                                      |   |             |                                    |                         |

8-31-2016

| Asset Work Orde          | r Histo                       | <u>ry 10188443</u>                      |  |             |                      |  |                                   |
|--------------------------|-------------------------------|---|--|-------------|----------------------|--|-----------------------------------|
| CSHOP-2016-466<br>Date O |                               | 9-27-2016                               | Date Finished  | 10-3        | 1-2016               | Meter 1 Reading:   | 111,869                           |
| TASKS PERFORM            | <u>ED</u>                     |   |  | Q           | PARTS                |  |                                   |
| PM SERVICE C I           | RESCU                         | E                                       |  | 1<br>1<br>1 | FILTER;              | FUEL FILTER 2008<br>57744XD OIL FILTE<br>24316 WIX CAB A/C | R                                 |
|                          | HANGE E                       | BATTERIES<br>11-17-2016                 | Date Finished  | 11-1        | 7-2016               | Meter 1 Reading:   | 111,869                           |
| TASKS PERFORM            | ED                            |   |  | Q           | PARTS                |  |                                   |
| BATTERY                  |                               |   |  | 3<br>3      |                      | Y; BATTERY EPA T.<br>Y; BATTERY 950CC                      | AX \$1.50 PER BATTERY<br>A HP-31D |
|                          | 45 FROI<br>pened<br><u>ED</u> | <mark>NT A/C NOT B</mark> I<br>2-3-2016 | LOWING COLD.<br>Date Finished                                |             | 2-2016<br>PARTS USED | Meter 1 Reading:   | 103,585                           |
| Service Requests:        |                               |   |  |             |                      |  |                                   |
| 02/03/2016               |                               | 9: LOOSE / R                            |  |             |                      |  |                                   |
|                          | N-CALL I                      | <mark>२२४५</mark><br>11-25-2016         | Date Finished  | 12-1        | 2-2016               | Meter 1 Reading:   | 113,097                           |
| TASKS PERFORM            | <u>ED</u>                     |   |  | NO P        | ARTS USED            |  |                                   |
| TRANSMISSION             |                               |   |  | _           |                      |  |                                   |
| Service Requests:        |                               |   |  |             |                      |  |                                   |
| 11/25/2016               | TRANSM                        | ISSION BAD LEA                          | : LOOSE / REPAI<br>K. WITHIN A HOUR OF<br>IN BOTH THE DRIVER | BEING F     |                      | RTS TO MAKE A PUDDLE                                       | UNDER THE BUMPER                  |

| Asset Work Ord   | er History 1018844                            | <u>3</u>                                   |  |  |   |  |
|--|---|--|--|--|---|--|
| CSHOP-2016-563   | <b>30</b><br>Dpened 12-2-2016                 | Date Finished                              | 12 5   | -2016  | Matar 1 Danding                             | 112,854  |
|  |   | Date Fillistieu                            | _  |  | Meter 1 Reading:                            | 112,034  |
| TASKS PERFORM  |   |  | Q  | PARTS  |   |  |
| SIREN<br>AIR CONDITION   | NNG   |  | 1  | SIREN; S   | SIREN                                       |  |
| Service Requests:  |   |  |  |  |   |  |
| 12/02/2016   | SERVICE REQUES<br>SERVICE REQUEST FOR<br>USE. |  |  | ITSELF, AND DO   | DES NOT STAY IN ONE SET                     | TING WHILE IN  |
| CSHOP-2016-574<br>Date C   | <b>15</b><br>Dpened 12-9-2016                 | Date Finished                              | 12-9   | -2016  | Meter 1 Reading:                            | 113,029  |
| TASKS PERFORM  | <u>1ED</u>                                    |  | NO P   | ARTS USED  |   |  |
| SIREN  |   |  |  |  |   |  |
| Service Requests:  |   |  |  |  |   |  |
| 12/09/2016<br><b>CSHOP-2016-69</b><br>Comments: R  | LEFT ALONE. HOWEVER                           | R R245 SIREN REOCC<br>, THE SIREN CAN STIL | URRING I<br>L BE OPE                             | RATED DURING   | HICH THE SIREN WILL TUR<br>EMERGENCY CALLS. | IN ON BY ITSELF IF   |
| Date (   | Opened 2-12-2016                              | Date Finished                              | 3-8-   | -2016  | Meter 1 Reading:                            | 104,026  |
| TASKS PERFORM  | <u>1ED</u>                                    |  | Q  | PARTS  |   |  |
| FUEL SYSTEM<br>EXHAUST SYST<br>COOLING SYST<br>HOSES-LINES &<br>FRONT TIRES<br>CAB-INTERIOR<br>AIR CONDITION | TEM<br>& FITTINGS<br>ACCESSORIES              |  | 1<br>2<br>1<br>1<br>1<br>1<br>876<br>1<br>1<br>1 | GASKET<br>VALVE; I<br>TANK; S<br>COOLEF<br>COOLEF<br>261C98<br>NEWPAF<br>BRAKE;<br>INTERN/ |   | OOR<br>R COLD SIDE OLD 1876262C96<br>KIT 330MM EXH SIDE OLD<br>G<br>C92 THERMISTER |
| Service Requests:  |   |  |  |  |   |  |
| 02/11/2016   | A/C / 19: LOOSE / N<br>THE AC IN THE CAB DOB  |  |  | ) INSTALLED  | NEW THERMISTOR                              | S CHECKED FOR ACT  |
| 02/18/2016   | TIRES / 44: WORN<br>DRIVER FRONT TIRE BA      |  | W  |  |   |  |

| SHOP-2017-13  |  |   |   |                     |                |                                 |                    |  |
|---|--|---|---|---------------------|----------------|---------------------------------|--------------------|--|
|   | R-245 OX<br>Opened   |   | WONT OPEN WILL<br>Date Finished   | NEED OXYO<br>1-6-20 |                | Meter 1 Reading:                | 114,503            |  |
| TASKS PERFOR  | MED  |   |   | NO PAR              | TS USED        |                                 |                    |  |
| BODY EXTERI   | OR   |   |   |                     |                |                                 |                    |  |
| Service Requests  | <u> </u>   |   |   |                     |                |                                 |                    |  |
| 01/06/2017  | VEHICLE  |   |   |                     |                | EVEN WHEN UNLOCKED<br>TIME.     | . OXYGEN LEVEL WAS |  |
| SHOP-2017-16<br>Date  |  | 3-16-2017   | Date Finished   | 3-24-20             | )17            | Meter 1 Reading:                | 119,306            |  |
| TASKS PERFOR  | MED  |   |   | Q                   | PARTS          |                                 |                    |  |
| ELECTRICAL<br>AIR CONDITIO  | NING   |   |   | 1                   | AVB; CAF       | PSULE                           |                    |  |
| Service Requests  |  |   |   |                     |                |                                 |                    |  |
| 03/16/2017  | -  |   | T / 18: LEAKING /<br>GHT HEAD LIGHT OUT   | REPAIR              |                |                                 |                    |  |
|   | Opened   | 4-3-2017  | Date Finished   | 4-4-20              |                | Meter 1 Reading:                | 120,030            |  |
| Date<br>TASKS PERFOR  | Opened   | 4-3-2017  | Date Finished   | -                   | 17<br>TS USED  | Meter 1 Reading:                | 120,030            |  |
| Date  | Opened<br>RMED<br>STEM   | 4-3-2017  | Date Finished   | -                   |                | Meter 1 Reading:                | 120,030            |  |
| Date<br><b>TASKS PERFOR</b><br>LIGHTING SYS   | Opened<br>RMED<br>STEM<br>RM   | 4-3-2017  | Date Finished   | -                   |                | Meter 1 Reading:                | 120,030            |  |
| Date<br>TASKS PERFOR<br>LIGHTING SYS<br>BACK-UP ALAI  | Opened<br><b>RMED</b><br>STEM<br>RM<br><u>-</u><br>LIGHT   | <br>S / 18: LEAK  | Date Finished   | <u>NO PAR</u>       | <u>TS USED</u> |                                 | 120,030            |  |
| Date<br>TASKS PERFOR<br>LIGHTING SYS<br>BACK-UP ALA<br>Service Requests   | Copened<br>CMED<br>STEM<br>RM<br>LIGHT<br>REAR LO<br>TIRES   | — — — — — — — — — — — — — — — — — — —   | — — — — — —<br>ING / REPAIR   | NO PAR              | TS USED        | ON R245                         | 120,030            |  |
| Date<br>TASKS PERFOR<br>LIGHTING SYS<br>BACK-UP ALA<br>Service Requests<br>04/03/2017   | COpened<br>CMED<br>STEM<br>RM<br>LIGHT<br>REAR LO<br>TIRES<br>TIRE TR<br>ALARM   | S / 18: LEAK<br>DAD LIGHT ON F<br>/ 18: LEAKIN<br>EAD ALMOST TO<br>// 18: LEAI                | ING / REPAIR  | NO PAR              | TS USED        | ON R245<br>RESCUE 245           | 120,030            |  |
| Date<br>TASKS PERFOR<br>LIGHTING SYS<br>BACK-UP ALA<br>Service Requests<br>04/03/2017<br>04/03/2017<br>04/03/2017<br>SHOP-2017-19                         | Copened<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COP | S / 18: LEAK<br>DAD LIGHT ON F<br>/ 18: LEAKIN<br>EAD ALMOST TO<br>// 18: LEAI<br>ALARM AND C | ING / REPAIR<br>REAR OF RESCUE DRIV<br>NG / REPAIR<br>O WEAR BAR ON DRIVI<br>KING / REPAIR                      | NO PAR              | TS USED        | ON R245<br>RESCUE 245           |                    |  |
| Date<br>TASKS PERFOR<br>LIGHTING SYS<br>BACK-UP ALA<br>Service Requests<br>04/03/2017<br>04/03/2017<br>04/03/2017<br>SHOP-2017-19<br>Date                 | Copened<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COP | S / 18: LEAK<br>DAD LIGHT ON F<br>/ 18: LEAKIN<br>EAD ALMOST TO<br>// 18: LEAI<br>ALARM AND C | ING / REPAIR<br>REAR OF RESCUE DRIV<br>NG / REPAIR<br>O WEAR BAR ON DRIVI<br>KING / REPAIR                      | NO PAR              | DIT WORKING    | ON R245<br>RESCUE 245           | 120,030            |  |
| Date<br>TASKS PERFOR<br>LIGHTING SYS<br>BACK-UP ALA<br>Service Requests<br>04/03/2017<br>04/03/2017<br>04/03/2017<br>SHOP-2017-19                         | Copened<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COP | S / 18: LEAK<br>DAD LIGHT ON F<br>/ 18: LEAKIN<br>EAD ALMOST TO<br>// 18: LEAI<br>ALARM AND C | ING / REPAIR<br>REAR OF RESCUE DRIV<br>NG / REPAIR<br>O WEAR BAR ON DRIVI<br>KING / REPAIR<br>AMERA NOT WORKING | NO PAR              | DNT TIRE ON    | ON R245<br>RESCUE 245<br>EVERSE |                    |  |
| Date<br>TASKS PERFOR<br>LIGHTING SYS<br>BACK-UP ALA<br>Service Requests<br>04/03/2017<br>04/03/2017<br>04/03/2017<br>SHOP-2017-19<br>Date                 | Copened<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COPENER<br>COP | S / 18: LEAK<br>DAD LIGHT ON F<br>/ 18: LEAKIN<br>EAD ALMOST TO<br>// 18: LEAI<br>ALARM AND C | ING / REPAIR<br>REAR OF RESCUE DRIV<br>NG / REPAIR<br>O WEAR BAR ON DRIVI<br>KING / REPAIR<br>AMERA NOT WORKING | NO PAR              | DIT WORKING    | ON R245<br>RESCUE 245<br>EVERSE |                    |  |
| Date<br>TASKS PERFOR<br>LIGHTING SYS<br>BACK-UP ALA<br>Service Requests<br>04/03/2017<br>04/03/2017<br>04/03/2017<br>SHOP-2017-1S<br>Date<br>TASKS PERFOR | Copened<br>Copened<br>CTEM<br>RM<br>LIGHT<br>REAR LO<br>TIRES<br>TIRE TR<br>ALARN<br>BACK UI<br>COpened<br>COPENED   | S / 18: LEAK<br>DAD LIGHT ON F<br>/ 18: LEAKIN<br>EAD ALMOST TO<br>// 18: LEAI<br>ALARM AND C | ING / REPAIR<br>REAR OF RESCUE DRIV<br>NG / REPAIR<br>O WEAR BAR ON DRIVI<br>KING / REPAIR<br>AMERA NOT WORKING | NO PAR              | DIT WORKING    | ON R245<br>RESCUE 245<br>EVERSE |                    |  |

| Asset Work Order History 10188443  |                       |                   |   |              |
|--|-----------------------|-------------------|---|--------------|
| CSHOP-2017-2124<br>Date Opened 4-12-2017 Date Finished   | 5-5-                  | 2017              | Meter 1 Reading:  | 121,417      |
| TASKS PERFORMED  | Q                     | PARTS             | Pieter i Redding.   |              |
| EXHAUST SYSTEM<br>FRONT TIRES<br>AIR SYSTEM  | 1                     | FREIGHT           | LINER; BOS622208  | 4001 KIT AIR |
| Service Requests:  |                       |                   |   |              |
| 04/11/2017 BODY / 12: BROKEN / REPAIR<br>BODY ISSUE: DRIVER SIDE SCBA AIR CYLINDE                                      | R COMPA               | RTMENT DOOF       | UN SECURE.  |              |
| CSHOP-2017-239<br>Comments: R245 SIREN TURNS ON BY ITS SELF.<br>Date Opened 1-11-2017 Date Finished<br>TASKS PERFORMED |                       | 2017<br>ARTS USED | Meter 1 Reading:  | 116,021      |
| REAR TIRES<br>SIREN<br>VENDOR? ELPEX TIRE TIRESOLES  |                       |                   |   |              |
| Service Requests:  |                       |                   |   |              |
| 01/11/2017 ALARMS / 19: LOOSE / REPAIR<br>ALARM SIGNALS, SIREN SHORTS AND TURNS<br>POSITION.                           | ON PERIC              | DICALLY BY IT     | SELF. WORKS FINE WHEN                                       | USED IN ON   |
| CSHOP-2017-2570<br>Date Opened 5-2-2017 Date Finished  | 5-16                  | -2017             | Meter 1 Reading:  | 121,661      |
| TASKS PERFORMED  | Q                     | PARTS             | Meter I Reduing:  | 121,001      |
|  | <u>~</u>              | TARTO             |   |              |
| PM SERVICE B   | 1<br>2<br>1<br>3<br>1 | 9AP; WA           | AGOLD AIR FILTEF<br>SHER SOLVENT<br>AGOLD OIL FILTER<br>TER |              |

| <u> </u>  |           |                              |                        |               |  |  |  |  |
|---|-----------|------------------------------|------------------------|---------------|--|--|--|--|
| CSHOP-2017-2571<br>Comments: REPAIRS FROM PM              |           |                              |                        |               |  |  |  |  |
| Date Opened 5-2-2017 Date Finished                        | 1 5-19    | -2017                        | Meter 1 Reading:       | 121,875       |  |  |  |  |
| TASKS PERFORMED   | Q         | PARTS                        |                        |               |  |  |  |  |
|   |           |                              |                        |               |  |  |  |  |
| PUMP ENGINE BELTS   | 1         | NBH: V-I                     | RIBBED BELT            |               |  |  |  |  |
|   | 1         |                              | ELT HORTON             |               |  |  |  |  |
| TOUCH TAPE-SENSITIVE EDGE<br>WIPER BLADES                 | 1         | 8HD; 8H                      | D                      |               |  |  |  |  |
| ENGINE AND ACCESSORIES                                    | 1         |                              |                        |               |  |  |  |  |
| REPAIR FROM PM - POWER STEERING                           | 1         | 1 FIL; NAPA CABIN AIR FILTER |                        |               |  |  |  |  |
| BACK-UP ALARM-LIGHT SWITCH                                | 2         | 1AN; WI                      |                        |               |  |  |  |  |
| CROSS MEMBER  | 6         | 2IH; INJE                    |                        |               |  |  |  |  |
| AIR BAG SYSTEM  | 1         | 2IH; SEA<br>2IH; SEA         |                        |               |  |  |  |  |
|   | 1<br>1    | 21H; SEA                     |                        |               |  |  |  |  |
|   | 1         |                              |                        | TFR           |  |  |  |  |
|   | 3         |                              | VER STEERING FLU       |               |  |  |  |  |
|   | 1         |                              | GLE ASM                |               |  |  |  |  |
|   | 2         |                              | RINGAIR                |               |  |  |  |  |
|   |           |                              |                        |               |  |  |  |  |
| CSHOP-2017-2922   |           |                              |                        |               |  |  |  |  |
| Date Opened 5-17-2017 Date Finished                       | d 6-15    | -2017                        | Meter 1 Reading:       | 122,278       |  |  |  |  |
| TASKS PERFORMED   | Q         | PARTS                        |                        |               |  |  |  |  |
| TRAVEL TO BE CHARGED TO WORK ORDER                        |           |                              |                        |               |  |  |  |  |
| GRILLE  | 6         |                              | CO RATCHET STRA        | PS            |  |  |  |  |
| SEAT BELTS  | 1         |                              | WIPER ARM M2           |               |  |  |  |  |
| CAB-INTERIOR ACCESSORIES                                  | 2         | TVVL; BA                     | CKUP LIGHT             |               |  |  |  |  |
| AIR CONDITIONING  |           |                              |                        |               |  |  |  |  |
| Service Requests:   |           |                              |                        |               |  |  |  |  |
| 05/17/2017 ALARMS / 12: BROKEN / EXCHANC                  | GE - NEW  |                              |                        |               |  |  |  |  |
| REVERSE ALARM SIGNAL AND REVERSE CA<br>TURNED ON MANUALLY | AMERA NOT | WORKING. RE                  | /ERSE CAMERA STILL WOF | RKS HAS TO BE |  |  |  |  |
|   |           |                              |                        |               |  |  |  |  |
| CSHOP-2017-2977   |           |                              |                        |               |  |  |  |  |
| Date Opened 5-19-2017 Date Finished                       |           | -2017                        |                        | 121,875       |  |  |  |  |
| TASKS PERFORMED   | NO P      | ARTS USED                    | )                      |               |  |  |  |  |
| SUSPENSION  |           |                              |                        |               |  |  |  |  |
| CSHOP-2017-33   |           |                              |                        |               |  |  |  |  |
| Comments: R-245 POWER STEERING                            |           |                              |                        |               |  |  |  |  |
| Date Opened 1-3-2017 Date Finished                        | 1-3-      | -2017                        | Meter 1 Reading:       | 114,349       |  |  |  |  |
| TASKS PERFORMED   |           | ARTS USED                    |                        |               |  |  |  |  |
|   |           |                              |                        |               |  |  |  |  |
| POWER STEERING PUMP                                       |           |                              |                        |               |  |  |  |  |

| CSHOP-2017-3534<br>Date Ope<br>TASKS PERFORMEN<br>CRANKING SYSTE |          | 6-14-2017                 |  |                                    |                   |                       |                   |
|--|----------|---------------------------|--|------------------------------------|-------------------|-----------------------|-------------------|
| TASKS PERFORME   |          | 6-14-2017                 |  |                                    |                   |                       |                   |
|  |          | 6-14-2017                 | Date Finished                          | 6-15-2017 Meter 1 Reading: 122,278 |                   | 122,278               |                   |
| CRANKING SYSTE   | <u>)</u> |                           |  | NO PARTS USED                      |                   |                       |                   |
|  | ΞM       |                           |  |                                    |                   |                       |                   |
| CSHOP-2017-420   |          |                           |  |                                    |                   |                       |                   |
|  |          | OR HANDLE BR<br>1-19-2017 | OKEN<br>Date Finished                  | 2-16-                              | 2017              | Meter 1 Reading:      | 117,213           |
| TASKS PERFORME   |          |                           |  | Q                                  | PARTS             |                       | , -               |
|  | _        |                           |  |                                    |                   |                       |                   |
| LIGHTING SYSTEM<br>BODY EXTERIOR                                 |          |                           |  | 1<br>1                             | NONSTO<br>1WL; 1W | CK; FREIGHT CHA       | RGE               |
|  |          |                           |  | 1                                  |                   | DLE LH HORTON         |                   |
| Service Requests:  |          |                           |  |                                    |                   |                       |                   |
| 01/19/2017 B   | ODY      | / 19: LOOSE               | <br>/ REPAIR                           |                                    |                   |                       |                   |
| В  | DDY IS   | SUE. REAR DOO             | R HANDLE BROKEN O                      |                                    |                   | ED NEW LATCH, METAL H | IANDLE HAS        |
| SI   | =PARA    | ATED. DOOR OPE            | RATES NORMALLY BY                      | OPENING                            | FROM THE INS      | SIDE.                 |                   |
|  |          |                           |  |                                    |                   |                       |                   |
| CSHOP-2017-4307<br>Date Ope                                      | ned      | 7-24-2017                 | Date Finished                          | 8-14-                              | 2017              | Meter 1 Reading:      | 124,765           |
| TASKS PERFORMED  | <u>)</u> |                           |  | Q                                  | PARTS             |                       |                   |
|  |          |                           |  |                                    |                   |                       |                   |
| TRANSMISSION<br>SUSPENSION                                       |          |                           |  | 1                                  | 2IH; TRA          |                       |                   |
| AIR SYSTEM   |          |                           |  | 1                                  |                   | SE FITTINGS           |                   |
| SIREN  |          |                           |  | 1                                  |                   | SSURE PROTECT         | VLV               |
| AIR CONDITIONIN  | G        |                           |  | 2                                  | 2IH; VAL          |                       |                   |
|  | •        |                           |  | 2                                  |                   | /E PRESURE            |                   |
|  |          |                           |  | 3                                  |                   | COCK DRAIN            |                   |
|  |          |                           |  | 6                                  |                   | NECTOR                |                   |
|  |          |                           |  | 2                                  |                   | ECTRICAL TAPE         |                   |
|  |          |                           |  | 1                                  | 2IH; THE          | RMISTORS              |                   |
| Service Requests:  |          |                           |  |                                    |                   |                       |                   |
| SI   | REN IS   |                           | / 19: LOOSE / RE<br>NG. SIREN WORKS IN |                                    | NT IN SOME SE     | TTINGS AND AUTOMATIC. | ALLY SWITCH MODES |
|  |          |                           |  |                                    |                   |                       |                   |
| CSHOP-2017-4802<br>Date Ope                                      | ned      | 8-16-2017                 | Date Finished                          | 8-25-                              | 2017              | Meter 1 Reading:      | 124,765           |
| TASKS PERFORMED  |          |                           |  | NO PARTS USED                      |                   |                       |                   |
| DPFE SENSOR  |          |                           |  |                                    |                   |                       |                   |
| Service Requests:  |          |                           |  |                                    |                   |                       |                   |
|  |          |                           | <br>OKEN / EXCHANG                     |                                    |                   |                       |                   |
|  |          | ORK ORDER                 | UNLIN / LAUHAING                       |                                    | v                 |                       |                   |

| Asset Work Order History 10188443  |   |
|--|---|
| CSHOP-2017-4935<br>Date Opened 8-23-2017 Date Finishe  | ed 8-23-2017 Meter 1 Reading: 124,765                       |
| TASKS PERFORMED  | NO PARTS USED   |
| CRANKING SYSTEM  |   |
| CSHOP-2017-5229  |   |
| Date Opened 9-6-2017 Date Finishe  | ed 9-19-2017 Meter 1 Reading: 124,765<br>NO PARTS USED      |
| CRANKING SYSTEM  |   |
| CSHOP-2017-529   |   |
| Date Opened 1-24-2017 Date Finishe   |   |
| TASKS PERFORMED  | NO PARTS USED   |
| INSTRUMENTS-GAUGES-WARNING &   |   |
| Service Requests:         01/24/2017       LIGHTS / 18: LEAKING / REPAIR         LEFT REAR LOADING LIGHT 10-7 THIS WAY | — — — — — — — — — — — — — — — — — — —                       |
| CSHOP-2017-5773<br>Date Opened 10-4-2017 Date Finishe  |   |
| TASKS PERFORMED<br>CRANKING SYSTEM   | NO PARTS USED   |
| CSHOP-2017-5940<br>Date Opened 10-16-2017 Date Finishe   |   |
| TASKS PERFORMED  | Q PARTS   |
| SAFTEY-EMERGENCY EQUIPMENT   | 1 9AP; STRYKER BAR  |
| Service Requests:  |   |
| 10/16/2017 DOOR / 18: LEAKING / REPAIR<br>VEHICLE DOORS SAFETY COVER OVER TO<br>STATION 56 (R256).                     | HE REAR (PT COMPARTMENT) DOOR IS BROKEN OFF. SPARE TRUCK AT |
| CSHOP-2017-6085<br>Date Opened 10-21-2017 Date Finishe   | ed 10-27-2017 Meter 1 Reading: 125,467                      |
| TASKS PERFORMED  | Q PARTS   |
| BATTERY  |   |

#### RADIO-2017-170

Comments:CT3 PROGRAMMED AND TESTED A REPLACEMENT PAGER. GIVEN TO CT4 FOR DELIVERY TO FS45.Date Opened3-27-2017Date Finished3-28-2017Meter 1 Reading:119,549

#### TASKS PERFORMED

### NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER RADIO

#### Service Requests:

| 03/26/2017 | OTHER / /   |
|------------|---|
|            | LIEUTENANT PAGER ON RESCUE 245 DISPLAY NOT WORKING PROPERLY, UNABLE TO READ MESSAGES ON DISPLAY |